

R0246

STELLAR ENVIRONMENTAL SOLUTIONS, INC.  
2198 SIXTH STREET, BERKELEY, CA 94710  
TEL: 510.644.3123 ★ FAX: 510.644.3859

RECEIVED

FEB 23 2006

Alameda County  
FEB 24 2006  
Environmental Health

|   |  |  |  |
|---|--|--|--|
| TRANSMITTAL MEMORANDUM  |  | ENVIRONMENTAL HEALTH SERVICES                      |  |
| TO: ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY<br>DEPT. OF ENVIRONMENTAL HEALTH<br>HAZARDOUS MATERIALS DIVISION<br>1131 HARBOR BAY PKWY, SUITE 250<br>ALAMEDA, CA 94502 |  | DATE: FEBRUARY 22, 2006                            |  |
| ATTENTION: MR. JERRY WICKHAM  |  | FILE: SES-2005-66                                  |  |
| SUBJECT: REDWOOD REGIONAL PARK FUEL LEAK SITE<br>FUEL LEAK CASE NO. RO0000246   |  |  |  |
| WE ARE SENDING: <input checked="" type="checkbox"/> HEREWITH  |  | <input type="checkbox"/> UNDER SEPARATE COVER      |  |
| <input checked="" type="checkbox"/> VIA MAIL  |  | <input type="checkbox"/> VIA                       |  |
| THE FOLLOWING: BIOVENTING SYSTEM INSTALLATION AND STARTUP REPORT<br>(DATED FEBRUARY 21, 2006)   |  |  |  |
| <input type="checkbox"/> AS REQUESTED   |  | <input type="checkbox"/> FOR YOUR APPROVAL         |  |
| <input type="checkbox"/> FOR REVIEW   |  | <input checked="" type="checkbox"/> FOR YOUR USE   |  |
| <input type="checkbox"/> FOR SIGNATURE  |  | <input checked="" type="checkbox"/> FOR YOUR FILES |  |
| COPIES TO: N. FUJITA (EBRPD)<br>C. WILCOX (CA FISH & GAME)  |  | BY: <u>Bruce Rucker</u>                            |  |
|   |  |  |  |

February 21, 2006

Mr. Jerry Wickham, P.G.  
Hazardous Materials Specialist  
Alameda County Department of Environmental Health  
1131 Harbor Bay Parkway, Suite 250  
Alameda, California 94502

Subject: Bioventing Installation and Startup Report  
Redwood Regional Park Service Yard Site – Oakland, California

Dear Mr. Wickham:

This report discusses the installation and startup of a bioventing corrective action system at the Redwood Regional Park Service Yard, located at 7867 Redwood Road, Oakland, California. This project is being conducted for the East Bay Regional Park District, and follows previous site investigation and remediation activities (conducted since 1993). The key regulatory agencies for this investigation are the Alameda County Department of Environmental Health, the Regional Water Quality Control Board, and the California Department of Fish and Game. I declare, under penalty of perjury, that the information and/or recommendations contained in the attached document or report is true and correct to the best of my knowledge.

If you have any questions regarding this report, please contact Mr. Neal Fujita of the East Bay Regional Park District, or contact us directly at (510) 644-3123.

Sincerely,



Bruce M. Rucker, R.G., R.E.A.  
Project Manager



Richard S. Makdisi, R.G., R.E.A.  
Principal Geochemist

cc: Carl Wilcox (California Department of Fish and Game); Cherie McCalou (Regional Water Quality Control Board); Neal Fujita (East Bay Regional Park District)

**BIOVENTING SYSTEM  
INSTALLATION AND STARTUP  
REPORT**

Alameda County  
FEB 24 2006  
Environmental Health

**REDWOOD REGIONAL PARK  
SERVICE YARD  
OAKLAND, CALIFORNIA**

*Prepared for:*

**EAST BAY REGIONAL PARK DISTRICT  
P.O. BOX 5381  
OAKLAND, CALIFORNIA 94605**

*Prepared by:*

**STELLAR ENVIRONMENTAL SOLUTIONS  
2198 SIXTH STREET, SUITE 201  
BERKELEY, CALIFORNIA 94710**

**February 21, 2006**

Project No. 2005-66

# TABLE OF CONTENTS

---

| Section   | Page |
|---|------|
| 1.0 PROJECT DESCRIPTION AND SITE HISTORY.....             | 1    |
| Project Description.....                                  | 1    |
| Site Description.....                                     | 2    |
| Site History and Contamination.....                       | 2    |
| Site Geology and Hydrogeology.....                        | 5    |
| Site Conceptual Model and Contaminant Mass Estimate.....  | 6    |
| Regulatory Status and Data Reporting.....                 | 6    |
| 2.0 BIOVENTING SYSTEM INSTALLATION.....                   | 8    |
| Rationale for Well Location and Construction.....         | 8    |
| Vent Well Installation Activities.....                    | 9    |
| Vapor Monitoring Point Installation Activities.....       | 11   |
| 3.0 SOIL VAPOR SAMPLING ACTIVITIES.....                   | 16   |
| Soil Vapor Sampling and Analysis.....                     | 16   |
| Soil Vapor Sampling Results.....                          | 17   |
| 4.0 SYSTEM STARTUP AND AIR FLOW OPTIMIZATION.....         | 19   |
| System Operation and Maintenance.....                     | 19   |
| 5.0 EVALUATION OF RESULTS.....                            | 27   |
| Blower Operation and Air Flow in Distribution Piping..... | 27   |
| Hydrogeologic Conditions Affecting Air Injection.....     | 27   |
| Baseline Conditions.....                                  | 28   |
| 6.0 SUMMARY, CONCLUSIONS, AND PROPOSED ACTIONS.....       | 29   |
| Summary and Conclusions.....                              | 29   |
| Proposed Actions.....                                     | 29   |
| 6.0 REFERENCES.....                                       | 31   |

## Appendices

|            |  |
|------------|--|
| Appendix A | Photodocumentation   |
| Appendix B | Well Permits, Geologic Logs, and Well Completion Forms               |
| Appendix C | Certified Analytical Laboratory Reports and Chain-of-Custody Records |
| Appendix D | Waste Soil Disposal Documentation                                    |

## TABLES AND FIGURES

---

| <b>Tables</b>   | <b>Page</b> |
|---|-------------|
| Table 1 Bioventing Well Construction Data<br>Redwood Regional Park Service Yard, Oakland, California .....                      | 9           |
| Table 2 Baseline Soil Vapor Sampling Results, December 2005<br>Redwood Regional Park Service Yard, Oakland, California .....    | 18          |
| Table 3 Bioventing System Measurements - Blower and Vent Wells<br>Redwood Regional Park Service Yard, Oakland, California ..... | 20          |
| Table 4 Bioventing Vapor Monitoring Points Data<br>Redwood Regional Park Service Yard, Oakland, California .....                | 23          |

| <b>Figure</b>  | <b>Page</b> |
|--|-------------|
| Figure 1 Site Location on USGS Topographic Map .....                   | 3           |
| Figure 2 Full Scale Bioventing System Site Plan .....                  | 4           |
| Figure 3 As-Built Vent Well Construction Details For VW-2 & VW-3 ..... | 10          |
| Figure 4 As-Built Vapor Monitoring Point Construction Details .....    | 12          |
| Figure 5 Bioventing Process Flow and Instrumentation Diagram .....     | 15          |

## **1.0 PROJECT DESCRIPTION AND SITE HISTORY**

---

### **PROJECT DESCRIPTION**

The subject property is the East Bay Regional Park District (EBRPD) Redwood Regional Park Service Yard, located at 7867 Redwood Road in Oakland, Alameda County, California. The site has undergone site investigations and remediation since 1993 to address subsurface contamination caused by leakage from one or both of two former underground fuel storage tanks (UFSTs) that contained gasoline and diesel fuel. The Alameda County Health Care Services Agency, Department of Environmental Health (Alameda County Health) has provided regulatory oversight of the investigation since its inception. Other regulatory agencies with historical involvement in site review include the Regional Water Quality Control Board – San Francisco Bay Region (Water Board) and the California Department of Fish and Game (CDFG).

This report documents the installation and startup of a soil bioventing system at the site. Bioventing was selected as an appropriate corrective action to mitigate residual petroleum contamination, based on site conditions, residual contaminant distribution, and results from a previously conducted bioventing pilot test in 2004. The bioventing system installation and startup activities were conducted in December 2005 and January 2006, and consisted of: installing two additional vent wells (VW) and one additional vapor monitoring point (VMP); installing a bioventing blower; installing air distribution piping to convey air from the blower to the vent wells; conducting baseline soil vapor sampling from unsaturated bioventing well screens; and a 1-month period of air flow optimization. These activities are described in detail in Sections 2.0 through 4.0.

This work follows a bioventing pilot test conducted in 2004. The pilot test consisted of: installing one VW and three VMPs; conducting an in situ respiration (ISR) test; and evaluating soil air permeability and the likely radius of influence for a full-scale bioventing system (SES, 2004b). The evaluation report recommended the installation of operation of a full-scale bioventing system, which was approved by Alameda County Health (Alameda County Health, 2005b).

## SITE DESCRIPTION

Figure 1 shows the location of the project site. A site plan showing the full-scale bioventing system is presented on Figure 2.

The site slopes to the west, from an elevation of approximately 564 feet above mean sea level (amsl) at the eastern edge of the service yard to approximately 545 feet amsl at Redwood Creek, which defines the approximate western edge of the project site with regard to this investigation. From east to west, the study area consists of:


- Flat, paved EBRPD service yard with several permanent and temporary buildings/sheds (former UFST excavation area);
- Steep slope (approximately 45 degrees) between the western edge of the service yard and the park entrance road (immediately west of MW-2);
- Hummocky terrain with low vegetation (between MW-8 and MW-11), including a large EBRPD-designated sycamore tree (adjacent to MW-8 and VMP-2);
- Flat, unpaved parking lot (between MW-11 and MW-7); and
- Steep slope (approximately 45 degrees) to Redwood Creek (immediately west of MW-12, MW-7, and MW-9).

## SITE HISTORY AND CONTAMINATION

Contaminant corrective actions and investigations have been conducted at the site since 1993. General phases of work previously included:

- Removal of UFSTs and contaminated soil;
- Installation and quarterly monitoring of groundwater monitoring wells;
- Several phases of remedial investigation-oriented exploratory borehole drilling and sampling;
- A correction action feasibility study;
- Two phases of ORC™ injection; and
- An evaluation of bioventing feasibility as a corrective action, which included a bioventing pilot test.





3-D TopoQuest Copyright © 1999 DeLorme, Yarmouth, ME 04896 Source Data: USGS 1:25,000 Scale: 1:25,000 Detail: 13-0 Datum: WGS84




**SITE LOCATION ON U.S.G.S. TOPOGRAPHIC MAP**

|   |         |            |  |
|---|---------|------------|--|
| Redwood Reg. Park Service Yard<br>Oakland, CA | By: MJC | APRIL 2004 | ★ Stellar Environmental Solutions, Inc.<br>Geoscience & Engineering Consulting |
|---|---------|------------|--|

**Figure 1**

2004-02-01





**FULL-SCALE BIOVENTING SYSTEM**  
**7867 Redwood Rd, Oakland, CA**

**Figure 2**

by: MJC

DECEMBER 2005

2005-09-08

As discussed in detail in previous SES reports, the available data support the following conclusions:

- The saturated zone overlies laterally-extensive bedrock, which limits downward migration of groundwater contamination.
- The unsaturated zone varies in thickness due to seasonal water level fluctuations of several feet.
- Site chemicals of concern include total petroleum hydrocarbons (TPH)—specifically as gasoline (TPHg) and diesel (TPHd); benzene, toluene, ethylbenzene, and xylenes (BTEX); and methyl *tertiary*-butyl ether (MTBE).
- Residual soil contaminant mass in the unsaturated zone is acting as a long-term source of groundwater contamination; the maximum thickness of the residual soil contamination (during lowest water level periods) is approximately 10 feet.
- Previous ORC™ injection programs resulted in apparent permanent reductions at the peripheral plume margins, but was followed by rebound to pre-injection conditions within the central portions of the plume, corroborating the conceptual model that remaining unsaturated zone soil contamination is continuing to impact groundwater.
- Site conditions appear favorable for bioventing as a corrective action to reduce unsaturated zone soil contamination, especially in the near-source area that is inaccessible to other methods due to the hilly topography.

## SITE GEOLOGY AND HYDROGEOLOGY

Previous reports by SES (SES, 2004a; SES, 2004b) have detailed site subsurface lithology through a series of constructed cross sections. Shallow soil stratigraphy consists of a surficial 3- to 10-foot-thick clayey silt unit underlain by a 5- to 15-foot-thick silty clay unit. In the majority of boreholes, a 5- to 10-foot-thick clayey coarse-grained sand and clayey gravel unit that laterally grades to a clay or silty clay was encountered. This unit overlies a weathered siltstone at the base of the observed soil profile. The top of this bedrock varies in elevation by several feet in the area of contamination, and likely is a fundamental control on local groundwater flow (on the order of several feet). The soils beneath Redwood Creek appear to be a thin clayey unit with large cobbles in the creek bed, underlain by sandy and gravelly soils to an unknown depth. Soils in the vicinity of MW-1 are inferred to be landslide debris (loose matrix of poorly-sorted material and steep groundwater gradient).

Groundwater at the site occurs under unconfined and semi-confined conditions, generally within the clayey, silty, sand-gravel zone. The top of this zone varies between approximately 12 and 19



- “Field Point IDs” – names of bioventing wells
- “GeoMap” – site plan showing bioventing wells and air distribution piping
- “GeoBore” – borehole geologic logs for bioventing wells
- “Geo Report” – electronic format of the Bioventing Pilot Test Results Report (SES, 2004f) and this report.
- Electronic Data Deliverable (EDD) – analytical laboratory report for the December 2005 soil vapor sampling event.

The site is also subject to Alameda County Environmental Health’s separate file transfer protocol (ftp) electronic system, which also requires the uploading of site technical reports. Uploads to the ftp system have been made for both the Bioventing Pilot Test Results Report (SES, 2004b) and this current report, and Alameda County Health has been notified of the uploads via email.

## **2.0 BIOVENTING SYSTEM INSTALLATION**

---

This section discusses the installation of the full-scale bioventing system, which includes: two additional VWs; one additional VMP; air distribution piping; and a blower. Photos of the bioventing system installation are included in Appendix A. Figure 2 shows the full-scale bioventing system site plan.

### **RATIONALE FOR WELL LOCATION AND CONSTRUCTION**

Bioventing typically has an effective radius of influence between 10 and 50 feet, depending on soil type. As part of the October 2004 pilot test, a single vent well (VW-1) was installed in the central portion of the contaminated area, and three VMPs (VMP-1, VMP-2, and VMP-3) were installed at distances of approximately 10, 20, and 35 feet from the vent well to allow for an evaluation of the radius of influence due to air injection at VW-1. The pilot test data indicated a likely radius of influence of 30 feet.

Two additional VWs (VW-2 and VW-3) and one additional VMP (VMP-4) were installed in November/December 2005 to supplement the existing bioventing well network. As shown on Figure 2, the design radii of the three VWs encompass the entire area of residual unsaturated zone soil contamination. The VWs were screened from 6 to 16 feet bgs (VW-1) and 8 to 18 feet bgs (VW-2 and VW-3) to incorporate the full thickness of the residual soil contamination zone.

Two "nested" casings/screens were installed in each of the four VMP boreholes (total of eight VMP screens available for monitoring). The VMP screened intervals in each borehole correspond to the top of unsaturated zone soil contamination at each location, and at depths coincident with VW screened intervals, and provide two separate monitoring depths.

Table 1 summarizes bioventing VW and VMP construction data.

**Table 1**  
**Bioventing Well Construction Data**  
**Redwood Regional Park Service Yard, Oakland, California**

| Well  | Screen Interval Depth (feet) | Filter Pack Sand Depth Interval (feet) |
|-------|------------------------------|--|
| VW-1  | 6-16                         | 4-16                                   |
| VW-2  | 8-18                         | 6-18                                   |
| VW-3  | 8-18                         | 6-18                                   |
| VMP-1 | 10-11.5                      | 9.5-12                                 |
|       | 14-15.5                      | 13.5-16                                |
| VMP-2 | 10-11.5                      | 9.5-12                                 |
|       | 14-15.5                      | 13.5-16                                |
| VMP-3 | 10-11.5                      | 9.5-12                                 |
|       | 12.5-14                      | 12-14.5                                |
| VMP-4 | 15.5-17                      | 15-17.5                                |
|       | 20.5-22                      | 20-20.5                                |

Note:

All depths are in feet below top of well box (approximately ground surface).


**VENT WELL INSTALLATION ACTIVITIES**

The wells were installed on November 28-30, 2005 by HEW Drilling (East Palo Alto, CA) under the direct supervision of Bruce Rucker, the SES California Registered Geologist. Prior to installation, well installation permits were obtained from Alameda County Public Works Agency (ACPWA). Well boreholes were drilled with 8-inch-diameter truck-mounted, hollow-stem augers. Appendix B contains copies of the well installation permits and geologic logs.

Figure 3 shows the as-built construction details for VW-2 and VW-3. The total depth of both boreholes was 18 feet bgs. Both VWs were constructed of 2.0-inch inner diameter (ID), Schedule 40 PVC casing, and screened from 8 to 18 feet bgs (0.020-inch slot size). Flush-threaded PVC casing and screen was used, with no organic solvents or glues. Annular filter pack material was placed across and 2 feet above the well screen.

The well specification called for 8x16 ("8 Mesh) filter pack sand; however, a field oversight resulted in using 8x20 (#3) sand, which is a slightly finer-grained sand. In our professional opinion, this variance should not result in a significant adverse impact to the operation of the





NOT TO SCALE  
 (well casing is actually  
 centered in borehole)

Note: All connections threaded  
 with gasket or teflon tape.  
 No glues used.

**AS-BUILT VENT WELL CONSTRUCTION DETAILS FOR VW-2 & VW-3**

Redwood Regional Park  
 Oakland, CA

By: MJC

DECEMBER 2005

**Figure 3**



2005-06-08

system because: 1) the grain size of the sand used is appropriate for (larger than) the well screen size (i.e., the sand grains will not enter the well through the screen); and 2) the small difference in grain size will not appreciably reduce effective porosity (for air transmission).

A 3-foot-thick layer of hydrated bentonite pellets was then placed above the filter pack, followed by a bentonite/cement grout annular pollution seal to surface. A metal well box was installed at the surface to protect the well, with cut openings in the east side (VW-2) and north side (VW-3) to accommodate air distribution piping.

### **VAPOR MONITORING POINT INSTALLATION ACTIVITIES**

Figure 4 shows the as-built construction details for VMP-4. The total depth of the VMP-4 borehole was 22 feet bgs. Two isolated, nested screened intervals were installed in each VMP; each screened interval was constructed with a 1.5-foot-long, 1.0-inch ID Schedule 80 PVC slotted well screen (0.020-inch slot size). The upper screened interval was from 15.5 to 17.0 feet bgs. The lower screened interval was from 20.5 to 22.0 feet bgs. Riser casing (from top of screened interval to surface) was 0.5-inch ID Schedule 80 PVC.


Annular filter pack (#8/16) sand was placed across and 0.5 feet above and below the well screen. A bentonite seal (2 to 3 feet thick) was placed between each filter pack to isolate the individual well screens/filter packs within the borehole. Above the shallowest filter pack, a cement grout annular pollution seal was installed to ground surface. The two nested casings are contained in the same traffic-rated, Christy-type well box. Individual air sampling valves were installed on each VMP casing at the ground surface for purging and sampling.

Each nested VMP screened interval was assigned a unique name, corresponding to the top of the 1.5-foot-long screened interval (e.g., VMP-4-15.5 refers to the screened interval between 15.5 and 17.0 feet in VMP-4).

In accordance with ACPWA requirements, SES submitted Well Completion Forms for the wells, including one form for each of the nested VMP-4 casings and one for each of VW-2 and VW-3. Copies of the Well Completion Forms are included in Appendix B.


### **Waste Soil Disposal**

Waste soil from drilling activities was placed in seven labeled, 55-gallon steel drums temporarily stored onsite with four drums of waste soil from the installation of the pilot test wells in September 2004. Following all drilling, a composite sample ("Soil Drum Comp.") from the



Not To Scale

Note: Depts shown are applicable to VMP-1 and VMP-2. Depth in VMP-3 and VMP-4 vary.



**AS-BUILT VAPOR MONITORING POINT CONSTRUCTION DETAILS**

Redwood Regional Park  
Oakland, CA

By: MJC

JUNE 2005

**Figure 4**



2005-06-10

drums was collected for laboratory analysis, to profile the soil for disposal. Appendix C contains the certified analytical laboratory report and chain-of-custody record for that sample. The analytical results demonstrated that the soil is non-hazardous, and amenable for disposal at a permitted Class III or II landfill. All 11 drums of waste soil were profiled and hauled offsite as non-hazardous waste on December 12, 2005 by Morgan Environmental (U.S. Environmental Protection Agency [EPA] ID No. CAT080013428) and disposed of at D/K Environmental in Vernon, California. A copy of the waste transport documentation is included in Appendix D.

### **Air Distribution Piping Installation**

All air distribution piping was Schedule 80, 2-inch outside diameter PVC.

On December 2, 2005, SES began the installation of the aboveground component of the air distribution piping. Aboveground piping was installed in areas of minimal foot/vehicle traffic, as shown on Figure 2: up the hill from the service road, and along the western side of the service yard. Aboveground piping was secured in place by driving U-shaped pieces of iron rebar into the ground. Piping lengths were connected with either Schedule 80 PVC slip couplings or with rubber screw-tight Fernco™ couplings.

On December 5, 2005, the belowground portion of the air distribution piping was installed. The belowground portions of the distribution piping were installed in areas of potential foot/vehicle traffic, as shown on Figure 2, and included all piping to the west of and across the service road, as well as the approximately 25 feet adjacent to the blower shed. This piping was laid in a trench approximately 1 foot deep; the fittings were secured with glued Schedule 80 slip-type couplings; and the trenches were backfilled with the excavated soil.

While only three VWs were installed, a fourth air distribution line was installed from the blower manifold to the edge of the temporary storage container. This fourth line was installed in anticipation of possible future use with a fourth vent well (which would be designated VW-4); this piping is currently capped and is accessible from the ground surface.

### **Blower System**

For ease of setup and operation, the blower system consists of a new, pre-packaged blower system constructed by Environmental Instruments (Concord, CA), and contains the following components and specifications:


- 2.0-horsepower Rotron EN 505M regenerative-type blower
- 230-volt starter

- Outlet air bleed valve (for controlling air flow)
- Integral vacuum gauge (inlet) and pressure gauge (outlet)
- In-line particulate air filter
- Maximum free air flow: 160 standard cubic feet per minute (scfm)
- Maximum operating pressure: 62 inches water (H<sub>2</sub>O)
- Air flow at 20 inches H<sub>2</sub>O: 140 scfm
- Explosion-proof motor and internal circuit breaker

Figure 5 is a flow instrumentation diagram for the blower and associated manifold. The blower is installed in a small shed on the west side of the service yard garage building. This blower system was selected based on the pilot test design specifications; namely, achieving a potential 30-foot radius of influence and a 40-scfm flow rate to individual vent wells under induced pressure conditions.

An air distribution piping manifold was constructed to connect the blower discharge to the vent well air distribution piping. The manifold was constructed wholly of Schedule 80 PVC, 2-inch-diameter piping with glued slip-type couplings. The blower discharge pipe was manifolded into four separate pipes (one to each existing VW and one to a potential fourth VW) that exit the blower shed and extend directly underground. Threaded metal flow measurement ports were installed at the following locations: in the blower discharge pipe (to measure total blower discharge); and in each of the four VW-specific manifold pipes (to measure individual air flows to each VW). A ball-type flow control valve was installed immediately downstream of each of the four VW-specific flow measurement ports, to allow for flow adjustment to individual VWs.

An air inlet pipe (1.5-inch-diameter Schedule 40 PVC) was run from the blower inlet to the exterior of the blower shed to draw in ambient air. A similar pipe was run from the blower bleed valve to the exterior of the shed. A small wooden enclosure was constructed adjacent to the blower shed to house the ends of the air inlet and blower bleed valve outlet pipes. This enclosure was constructed to minimize blower noise, and also to minimize intake of debris and moisture.



2005-66-07



### **3.0 SOIL VAPOR SAMPLING ACTIVITIES**

---

This section discusses the soil vapor sampling and analysis methods used to conduct the baseline sampling prior to bioventing system startup.

#### **SOIL VAPOR SAMPLING AND ANALYSIS**

The soil vapor sampling was conducted December 9, 2005 to establish baseline conditions for future evaluation of the impact of bioventing on residual soil contamination. At that time, all four VMPs showed shallow screens and all three VWs showed partially exposed (unsaturated) screens (see Section 4.0 for a discussion of water level depths relative to screened intervals). However, the shallow screen at VMP-4 could not be purged (or sampled), suggesting either that the annular filter pack around this screen was saturated during hydration of the bentonite seal during installation or that soils surrounding the screen are very tight and/or moderately-saturated due to the shallow water level.

Soil vapor samples were collected with a sample collection system that consisted of a small, portable vacuum pump, Tygon<sup>®</sup> tubing, and a vacuum chamber. The vacuum pump was used to purge the well and tubing. The purge times for each of the VMP depths was approximately 1 minute, and the purge time for VWs was approximately 5 minutes. These purge times were based on well construction and the flow rate of the pump to ensure that a representative sample was collected.

Once the wells were purged, soil vapor samples were collected in Tedlar<sup>®</sup> bags within the vacuum chamber for field analysis. All soil vapor samples were analyzed in the field using portable meters: a GasTech Model GT-408 for oxygen/carbon dioxide and a photoionization detector (PID) (*Mini-RAE Plus Classic*) for organic compounds. Meters were calibrated prior to field use according to manufacturer's specifications. Soil vapor samples were collected for laboratory analysis subsequent to purging and field screening by attaching an evacuated Summa<sup>®</sup> canister directly to the well.

All samples collected for laboratory analysis were analyzed for BTEX, MTBE, and total volatile hydrocarbons as gasoline (TVHg) using EPA Method TO-3. Laboratory analyses were

conducted by Columbia Analytical Services (Simi Valley, CA). Sample results are discussed below, and certified analytical results and chain-of-custody forms are provided in Appendix C.

## **SOIL VAPOR SAMPLING RESULTS**

### **Fuel Hydrocarbons**

Table 2 summarizes the baseline soil vapor sample analytical results, as well as field PID readings. Gasoline concentrations ranged from non-detect (VMP-1 and VMP-3) to 5,100 parts per million by volume (ppmv) (VMP-2). Note that the oxygen and carbon dioxide readings in VW-2 (discussed below) suggest that ambient air leakage may have occurred, and the contaminant concentrations in VW-2 likely is at a higher concentration than recorded. Sampling points with elevated gasoline concentrations also showed elevated BTEX concentrations. The only well with detected MTBE was VMP-2.

Maximum concentrations for all hydrocarbon compounds were measured at VMP-2. This result is consistent with previous findings that indicated the center of mass of groundwater and residual soil contamination is located in the area surrounding VMP-2. There was relatively good correlation between PID field readings and TVHg laboratory measurements, with higher PID readings associated with higher TVH readings.

### **Oxygen/Carbon Dioxide**

Oxygen concentrations below background concentration (usually 18 to 21 percent), and carbon dioxide concentrations above background (usually 0.05 percent) indicate that petroleum hydrocarbon contamination has induced native microbiological activity in soils. However, aerobic microbial activity is substantially limited below approximately 5 percent oxygen.

During baseline sampling, oxygen concentrations were depleted and carbon dioxide concentrations were elevated (as compared to ambient conditions) in all monitored points, with the exception of VW-2 (likely due to ambient air leakage). These results are consistent with the previous findings of residual soil contamination at these locations. At VW-2 (location of inferred maximum contamination), oxygen was not detected and carbon dioxide was at 19 percent, indicating a strong contaminant impact and significantly limiting conditions for aerobic microbial activity.

**Table 2**  
**Baseline Soil Vapor Sampling Results, December 2005**  
**Redwood Regional Park Service Yard, Oakland, California <sup>(a)</sup>**

| Location                                  | Depth (feet) | TVHg  | Benzene | Toluene | Ethyl Benzene | Xylenes | MTBE    | O <sub>2</sub> (%)  | CO <sub>2</sub> (%) | PID   |
|---|--------------|-------|---------|---------|---------------|---------|---------|---------------------|---------------------|-------|
| <b>December 9, 2005 Baseline Sampling</b> |              |       |         |         |               |         |         |                     |                     |       |
| VW-1                                      | 6-16         | 45    | < 0.058 | < 0.058 | < 0.058       | 0.058   | < 0.058 | 9.1                 | 9.3                 | 24.5  |
| VW-2 <sup>(b)</sup>                       | 8-18         | 2,500 | 2.8     | 3.3     | 2.5           | 1.5     | < 0.065 | 20.5 <sup>(c)</sup> | 0.4                 | 420   |
| VW-3                                      | 8-18         | 4,100 | 1.9     | 8.5     | < 0.073       | 7.9     | < 0.073 | 15.4                | 2.0                 | 675   |
| VMP-1-shallow                             | 10-11.5      | < 6.9 | < 0.068 | < 0.068 | < 0.068       | < 0.136 | < 0.068 | 10.0                | 9.5                 | < 0.1 |
| VMP-2-shallow                             | 10-11.5      | 5,100 | 61      | 28      | 80            | 316     | 21      | 0.0                 | 19.0                | 1,890 |
| VMP-3-shallow                             | 10-11.5      | < 7.1 | < 0.070 | < 0.070 | < 0.070       | < 0.070 | < 0.140 | 10.9                | 8.6                 | < 0.1 |

Notes:

- <sup>(a)</sup> All concentrations are in parts per million by volume (ppmv) unless otherwise indicated.  
<sup>(b)</sup> Contaminant and carbon dioxide results may be biased (low) due to ambient air leakage.  
<sup>(c)</sup> Results may be biased (high) due to ambient air leakage.

CO<sub>2</sub> = carbon dioxide  
 MTBE = methyl tertiary-butyl ether  
 O<sub>2</sub> = oxygen  
 PID = photoionization detector  
 TVHg = total volatile hydrocarbons as gasoline

## **4.0 SYSTEM STARTUP AND AIR FLOW OPTIMIZATION**

---

The purpose of the expanded full-scale bioventing system is to provide oxygen to stimulate aerobic biodegradation of the remaining soil contamination present at the site. Because at least several feet of exposed (unsaturated) VW screens was measured immediately following the VW installations (see Table 3), startup of the system was initiated on December 20, 2005. It is expected that the effectiveness of the bioventing system will be reduced as water levels rise during the rainy period, and then increase as water levels fall. The system will be shut down in the event that all VW screens become fully saturated, or if no flow is measured in any of the wells.

### **SYSTEM OPERATION AND MAINTENANCE**

#### **System Testing and Start-Up**

The final electrical service for the blower was installed on December 19, 2005. On December 20, 2005 (after the baseline soil vapor sampling event), the blower was started (with the bleed valve fully open and the VW flow control valves fully closed at the manifold) and total air flow was measured. The VW flow control valves at the manifold and at the well head were then opened (one VW at a time) to ensure that air was moving through the manifold piping to each wellhead. SES confirmed that air was moving from the blower and through each VW pipe and exiting at each wellhead, with flow rates of approximately 30 to 50 standard cubic feet per minute (scfm) per VW. Total blower airflow could not be measured as the limit of meter range was 100 scfm. The valve at each VW wellhead was then closed so that air flow was introduced into the subsurface at each VW. Airflow was measured using a thermal anemometer (TSI model 8345).

#### **Air Flow Optimization**

Initial system measurements were taken on December 21 and 22, 2005. Total and VW-specific air injection rates were optimized to ensure uniform flow rates to VWs and proper operation of the blower system. Total blower airflow was determined to be approximately 50 to 55 scfm, with all air flow going to VW-1. No air was being injected into either newly installed VW-2 or VW-3. In our opinion, the filter pack (sand) material in those two wells was saturated (as a result of well installation and/or high water level conditions). The blower bleed valve was therefore adjusted to maintain the design outlet pressure of 40 inches of water.

**Table 3  
Bioventing System Measurements - Blower and Vent Wells  
Redwood Regional Park Service Yard, Oakland, California**

| Location   | Blower Total Air Flow – before adjustment (scfm) | Blower Total Air Flow – after adjustment (scfm) | Blower Inlet Vacuum (inches H <sub>2</sub> O) <sup>(a)</sup> | Blower Pressure (inches H <sub>2</sub> O) <sup>(a)</sup> | Airflow to VW – before adjustment (scfm) | Airflow to VW – after adjustment (scfm) | Screened Interval Depth (feet) | Water Level (feet) |
|--|--|---|--|--|--|---|--------------------------------|--------------------|
| <b>December 9, 2005 (before bioventing system startup)</b>                 |  |   |  |  |  |   |                                |                    |
| Blower   | ---  | ---   | ---  | ---  |  |   |                                |                    |
| VW-1   |  |   |  |  | NM                                       | NM                                      | 5.6 – 15.6                     | 12.15              |
| VW-2   |  |   |  |  | NM                                       | NM                                      | 8.4 – 18.4                     | 10.27              |
| VW-3   |  |   |  |  | NM                                       | NM                                      | 8.8 – 18.8                     | 11.94              |
| <b>December 23, 2005 (first event following bioventing system startup)</b> |  |   |  |  |  |   |                                |                    |
| Blower   | 53   | NM  | 16   | 42   |  |   |                                |                    |
| VW-1   |  |   |  |  | 51                                       | NM                                      | 5.6 – 15.6                     | 11.0               |
| VW-2   |  |   |  |  | < 1                                      | NM                                      | 8.4 – 18.4                     | 10.9               |
| VW-3   |  |   |  |  | < 1                                      | NM                                      | 8.8 – 18.8                     | 14.1               |
| <b>December 29, 2005</b>   |  |   |  |  |  |   |                                |                    |
| Blower   | 29   | 28  | 14   | 49   |  |   |                                |                    |
| VW-1   |  |   |  |  | 34                                       | 30                                      | 5.6 – 15.6                     | 11.1               |
| VW-2   |  |   |  |  | < 1                                      | < 1                                     | 8.4 – 18.4                     | 7.2                |
| VW-3   |  |   |  |  | < 1                                      | < 1                                     | 8.8 – 18.8                     | 14.5               |
| <b>January 3, 2006<sup>(b)</sup></b>                                       |  |   |  |  |  |   |                                |                    |
| Blower   | NM   | NM  | 17   | 45   |  |   |                                |                    |
| VW-1   |  |   |  |  | NM                                       | NM                                      | 5.6 – 15.6                     | 6.0                |

Table 3 continued

| Location                | Blower Total Air Flow – before adjustment (scfm) | Blower Total Air Flow – after adjustment (scfm) | Blower Inlet Vacuum (inches H <sub>2</sub> O) <sup>(a)</sup> | Blower Pressure (inches H <sub>2</sub> O) <sup>(a)</sup> | Airflow to VW – before adjustment (scfm) | Airflow to VW – after adjustment (scfm) | Screened Interval Depth (feet) | Water Level (feet) |
|-------------------------|--|---|--|--|--|---|--------------------------------|--------------------|
| <b>January 6, 2006</b>  |  |   |  |  |  |   |                                |                    |
| Blower                  | 8.5  | 7.5   | 18   | 38   |  |   |                                |                    |
| VW-1                    |  |   |  |  | 8.0                                      | NM                                      | 5.6 – 15.6                     | 6.7                |
| VW-2                    |  |   |  |  | < 1                                      | < 1                                     | 8.4 – 18.4                     | 3.4                |
| VW-3                    |  |   |  |  | < 1                                      | < 1                                     | 8.8 – 18.8                     | 10.1               |
| <b>January 12, 2006</b> |  |   |  |  |  |   |                                |                    |
| Blower                  | NM   | 10.1  | 13   | 58   |  |   |                                |                    |
| VW-1                    |  |   |  |  | NM                                       | 9.8                                     | 5.6 – 15.6                     | 8.5                |
| VW-2                    |  |   |  |  | NM                                       | < 1                                     | 8.4 – 18.4                     | 6.5                |
| VW-3                    |  |   |  |  | NM                                       | < 1                                     | 8.8 – 18.8                     | 11.8               |
| <b>January 24, 2006</b> |  |   |  |  |  |   |                                |                    |
| Blower                  | NM   | NM  | 18   | 38   |  |   |                                |                    |
| VW-1                    |  |   |  |  | NM                                       | NM                                      | 5.6 – 15.6                     | 9.9                |
| VW-2                    |  |   |  |  | NM                                       | < 1 <sup>(c)</sup>                      | 8.4 – 18.4                     | 5.98               |
| VW-3                    |  |   |  |  | NM                                       | < 1 <sup>(c)</sup>                      | 8.8 – 18.8                     | 12.90              |

Notes:

- <sup>(a)</sup> Reading is prior to adjustment back to design operating parameters
- <sup>(b)</sup> Supplemental event to check on blower system after heavy precipitation event.
- <sup>(c)</sup> Qualitatively assessed by closing the VW-specific manifold valve and noting no change in blower outlet pressure.

H<sub>2</sub>O = water

NM = not measured

scfm = standard cubic feet per minute

Depths are in feet below top of well casing (TOC).



Water levels measured in this period confirmed that all deep VMP screens were fully saturated (such that purging and vapor sampling could not be conducted).

Following startup, four weekly system monitoring events were conducted designed to measure system operation and optimize air flows. The objective of the monitoring events was to ensure that the required flow rates are achieved and that oxygen concentrations increase in the VMPs as a result of air injection. As shown in Table 3 (Bioventing System Measurements – Blower and Vent Wells) and Table 4 (Bioventing Vapor Monitoring Points Data), the following measurements were made during each event (when conditions allowed):

- Water levels in VWs and VMPs.
- Blower inlet vacuum and outlet pressure.
- Airflow rates to each VW (including temperature during the air flow reading).
- Induced pressure in each non-saturated VMP well screen, using Dwyer magnehelic gauges (0- to 1-inch water range).
- Oxygen and carbon dioxide concentrations in each non-saturated VMP well screen (by purging and Tedlar bag sampling).

The following general sequence of procedures were followed for the weekly events.

- Initial (“before adjustments”) system measurements (blower inlet vacuum and outlet pressure) were made.
- The system was turned off and water level measurements were made.
- Induced pressures were measured.
- Well purging and Tedlar bag was conducted.
- The air flow system was returned to operating conditions, and air flows/blower outlet pressure were adjusted, and final (“after adjustment”) readings were made.

As discussed below, unfavorable bioventing conditions (high water levels) precluded collecting some of the desired measurements. Summaries of each of the weekly monitoring activities follow.

On December 29, 2005 (approximately 1 week after startup), total air flow to the VWs had declined to approximately 30 scfm, again with all the air flow going to VW-1 and no air flow into VW-2 or VW-3. Induced air pressure was measured at the shallow well screens of VMP-1, VMP-2, and VMP-3. Because vacuum conditions had previously been demonstrated in the shallow screen of VMP-4, neither induced pressure readings nor purging were conducted.

**Table 4**  
**Bioventing Vapor Monitoring Points Data**  
**Redwood Regional Park Service Yard, Oakland, California**

| Location   | Induced Pressure at VMP (inches H <sub>2</sub> O) | O <sub>2</sub> (%) | CO <sub>2</sub> (%) | PID   | Screened Interval Depth (feet) | Water Level (feet) |
|--|---|--------------------|---------------------|-------|--------------------------------|--------------------|
| <b>December 9, 2005 (before bioventing system startup)</b>       |   |                    |                     |       |                                |                    |
| VMP-1-10   | NA  | 10.0               | 9.5                 | < 0.1 | 9.3 – 10.8                     | dry (>10.8)        |
| VMP-1-14   | NA  | (a)                | (a)                 | (a)   | 13.4 – 14.9                    | 10.8               |
| VMP-2-10   | NA  | 0.0                | 19.0                | 1,890 | 9.5 – 11.0                     | dry (>11.0)        |
| VMP-2-14   | NA  | (a)                | (a)                 | (a)   | 13.9 – 15.4                    | 12.5               |
| VMP-3-10   | NA  | 10.9               | 8.6                 | < 0.1 | 9.8 – 11.3                     | 11.0               |
| VMP-3-12.5   | NA  | (a)                | (a)                 | (a)   | 12.0 – 13.5                    | 10.8               |
| VMP-4-15.5   | NA  | (a)                | (a)                 | (a)   | 15.1 – 16.6                    | dry (>16.6)        |
| VMP-4-20.5   | NA  | (a)                | (a)                 | (a)   | 20.8 – 22.3                    | 19.3               |
| <b>December 23, 2005 (first event bioventing system startup)</b> |   |                    |                     |       |                                |                    |
| VMP-1-10   | 0.50  | 16.9               | 6.6                 | NM    | 9.3 – 10.8                     | 10.9               |
| VMP-1-14   | (a)   | (a)                | (a)                 | (a)   | 13.4 – 14.9                    | NM                 |
| VMP-2-10   | 0.12  | 1.3                | 16.6                | NM    | 9.5 – 11.0                     | dry (>11.0)        |
| VMP-2-14   | (a)   | (a)                | (a)                 | (a)   | 13.9 – 15.4                    | NM                 |
| VMP-3-10   | 0.18  | (a)                | (a)                 | NM    | 9.8 – 11.3                     | 10.2               |
| VMP-3-12.5   | (a)   | (a)                | (a)                 | (a)   | 12.0 – 13.5                    | NM                 |
| VMP-4-15.5   | -0.13   | (a)                | (a)                 | NM    | 15.1 – 16.6                    | dry (>16.6)        |
| VMP-4-20.5   | (a)   | (a)                | (a)                 | (a)   | 20.8 – 22.3                    | NM                 |
| <b>December 29, 2005</b>   |   |                    |                     |       |                                |                    |
| VMP-1-10   | 0.34  | (a)                | (a)                 | NM    | 9.3 – 10.8                     | 10.14              |
| VMP-1-14   | (a)   | (a)                | (a)                 | (a)   | 13.4 – 14.9                    | NM                 |
| VMP-2-10   | 0.33  | (a)                | (a)                 | NM    | 9.5 – 11.0                     | 10.39              |
| VMP-2-14   | (a)   | (a)                | (a)                 | (a)   | 13.9 – 15.4                    | NM                 |
| VMP-3-10   | 0.50  | (a)                | (a)                 | NM    | 9.8 – 11.3                     | 10.12              |
| VMP-3-12.5   | (a)   | (a)                | (a)                 | (a)   | 12.0 – 13.5                    | NM                 |
| VMP-4-15.5   | (a)   | (a)                | (a)                 | NM    | 15.1 – 16.6                    | dry (>16.6)        |
| VMP-4-20.5   | (a)   | (a)                | (a)                 | (a)   | 20.8 – 22.3                    | NM                 |

Table 4 continued

| Location                | Induced Pressure at VMP (inches H <sub>2</sub> O) | O <sub>2</sub> (%) | CO <sub>2</sub> (%) | PID | Screened Interval Depth (feet) | Water Level (feet) |
|-------------------------|---|--------------------|---------------------|-----|--------------------------------|--------------------|
| <b>January 6, 2006</b>  |   |                    |                     |     |                                |                    |
| VMP-1-10                | (a)   | (a)                | (a)                 | NM  | 9.3 – 10.8                     | 9.9                |
| VMP-1-14                | (a)   | (a)                | (a)                 | (a) | 13.4 – 14.9                    | 7.9                |
| VMP-2-10                | (a)   | (a)                | (a)                 | NM  | 9.5 – 11.0                     | 9.9                |
| VMP-2-14                | (a)   | (a)                | (a)                 | (a) | 13.9 – 15.4                    | 6.4                |
| VMP-3-10                | (a)   | (a)                | (a)                 | NM  | 9.8 – 11.3                     | 9.2                |
| VMP-3-12.5              | (a)   | (a)                | (a)                 | (a) | 12.0 – 13.5                    | 5.9                |
| VMP-4-15.5              | (a)   | (a)                | (a)                 | NM  | 15.1 – 16.6                    | dry (>16.6)        |
| VMP-4-20.5              | (a)   | (a)                | (a)                 | (a) | 20.8 – 22.3                    | 15.6               |
| <b>January 12, 2006</b> |   |                    |                     |     |                                |                    |
| VMP-1-10                | -0.12   | (a)                | (a)                 | NM  | 9.3 – 10.8                     | 9.8                |
| VMP-1-14                | (a)   | (a)                | (a)                 | (a) | 13.4 – 14.9                    | 8.4                |
| VMP-2-10                | -0.20   | (a)                | (a)                 | NM  | 9.5 – 11.0                     | 7.5                |
| VMP-2-14                | (a)   | (a)                | (a)                 | (a) | 13.9 – 15.4                    | 7.2                |
| VMP-3-10                | -0.22   | (a)                | (a)                 | NM  | 9.8 – 11.3                     | 9.6                |
| VMP-3-12.5              | (a)   | (a)                | (a)                 | (a) | 12.0 – 13.5                    | 9.2                |
| VMP-4-15.5              | 0.0   | (a)                | (a)                 | NM  | 15.1 – 16.6                    | dry (>16.6)        |
| VMP-4-20.5              | (a)   | (a)                | (a)                 | (a) | 20.8 – 22.3                    | 15.8               |
| <b>January 24, 2006</b> |   |                    |                     |     |                                |                    |
| VMP-1-10                | NM  | (a)                | (a)                 | NM  | 9.3 – 10.8                     | 8.5                |
| VMP-1-14                | NM  | (a)                | (a)                 | (a) | 13.4 – 14.9                    | 8.7                |
| VMP-2-10                | NM  | (a)                | (a)                 | NM  | 9.5 – 11.0                     | 7.4                |
| VMP-2-14                | NM  | (a)                | (a)                 | (a) | 13.9 – 15.4                    | 7.5                |
| VMP-3-10                | NM  | (a)                | (a)                 | NM  | 9.8 – 11.3                     | 9.8                |
| VMP-3-12.5              | NM  | (a)                | (a)                 | (a) | 12.0 – 13.5                    | 9.4                |
| VMP-4-15.5              | NM  | (a)                | (a)                 | NM  | 15.1 – 16.6                    | dry (>16.6)        |
| VMP-4-20.5              | NM  | (a)                | (a)                 | (a) | 20.8 – 22.3                    | 15.8               |

Notes:

(a) Well screen saturated and/or tight soils exhibited high vacuum condition during (purging; sample could not be collected).

CO<sub>2</sub> = carbon dioxide

NM = not measured

H<sub>2</sub>O = water

O<sub>2</sub> = oxygen

NA = not applicable

PID = photoionization detector

Depths are in feet below top of well casing (TOC).

This event demonstrated that oxygen concentrations increased and carbon dioxide decreased measurably at VMP-1-10 and VMP-2-10. Also, the induced pressure numbers are somewhat higher than what was seen during the pilot test. Both of these results indicate that the blower injection and flow was having the desired effect, but that it was short-lived.

On January 3, 2006, it was observed that the blower had shut down. The blower was left off until the cause of the shut-down was confirmed. The EBRPD subsequently confirmed that the entire facility lost electrical power during the severe storms earlier in the week.

On January 6, 2006, the water level in VW-1 (as well as other VWs) had risen several additional feet in response to heavy rainfall earlier in the week. The blower (which had been off since January 3, 2006) was restarted. Total blower airflow had decreased to approximately 8 scfm, again with all of the air flow going to VW-1 and no air flow to VW-2 or VW-3. Water levels in the shallow screens of the VMPs were either above or nearly coincident with the top of the well screens. Induced air pressure was measured at the shallow well screens of all VMPs. Induced air pressures were either zero (VMP-3 and VMP-4) or negative (VMP-1 and VMP-2), indicating vacuum conditions in the well (typical of saturated conditions). No well purging, PID readings, or oxygen/carbon dioxide measurements were done because of the saturated well screen conditions.

On January 12, 2006, the water level in VW-1 (and in the other VWs) had dropped slightly, and a slight increase in airflow was observed. As with previous events, all airflow was to VW-1 and none to VW-2 or VW-3. Water levels in the shallow screens of the VMPs were either above or nearly coincident with the top of the well screens. Induced air pressure was measured at the shallow well screens of all VMPs. Induced air pressures were either zero (VMP-3 and VMP-4) or negative (VMP-1 and VMP-2), indicating saturated conditions. No well purging, PID readings, or oxygen/carbon dioxide measurements were done because of the saturated well screen conditions.

On January 24, 2006, the water level had risen in VW-2 (0.5 feet), and had dropped in VW-1 (1.4 feet) and VW-3 (1.1 feet). As with previous events, all airflow was to VW-1 and none to VW-2 or VW-3 (this was evaluated qualitatively by turning off the VW-specific manifold valves (for VW-2 and VW-3) and noting no change in blower outlet pressure. No well purging, PID readings, or oxygen/carbon dioxide measurements were done because of the saturated well screen conditions.

Following the January 24, 2006 (final) weekly event, all manifold valves were closed except VW-3. The objective of this was to concentrate all air flow into VW-3, in an attempt to dehydrate the annular pack material in that well. Planned monthly operation and maintenance events will include a qualitative evaluation of air flow into VW-3 (by closing the VW-3 manifold valve and looking for an increase in blower outlet pressure).

## **5.0 EVALUATION OF RESULTS**

---

This section discusses the findings of the full-scale bioventing system startup and first month of system monitoring.

### **BLOWER OPERATION AND AIR FLOW IN DISTRIBUTION PIPING**

The blower system is fully functional and operating within design parameters. The blower system has two safety mechanisms for automatic shut-off. First, for safety reasons, there is no automatic re-start of the blower. The first shut-off mechanism consists of 60-amp fuses in the external circuit breaker box. The second shut-off mechanism is an internal, time-delay variable amp shut-off (currently set at 22 amps); the shutdown occurs when the motor operates at unsafe amperage due to increased blower outlet pressure.

During the approximately 1-month startup period, the blower shut down twice. One shutdown occurred due to sitewide electrical service outage. The second shutdown was due to blower outlet pressure causing an exceedance of the internal shut-off amperage. These events demonstrate that the blower's automatic shut-off mechanisms are working and there is minimal risk associated with automatic operation.

Air flow is moving through the air distribution piping and reaching wellheads (when wellheads are open) at expected flow rates. No significant air leaks have been observed in the system.

### **HYDROGEOLOGIC CONDITIONS AFFECTING AIR INJECTION**

Water level monitoring has confirmed that water levels fluctuate in wells up to several feet over the year and can change rapidly over short periods of time following individual precipitation events, which will affect both total system flow rate and possibly the ratio between individual VWs.

#### **Vent Wells**

Water levels rose between 6 and 7 feet in VW-1 and VW-2 between December 9, 2005 and January 6, 2006, in response to two heavy precipitation events. Water levels subsequently dropped 2 to 3 feet in these wells within the next week. Slightly less variable water level changes were observed in downgradient VW-3.



Initial conditions showed several feet of exposed screen (relative to water level measurements in the well) in newly-installed VW-2 and VW-3. However, no air could be injected into these two new wells. Water level measurements have demonstrated that the well screens are open to groundwater entry; thus, there is no possibility that the wells screens were sealed during well installation. It is likely that the filter pack material in these wells was saturated as a result of installation activities (or possibly capillary action that filled pore spaces in the filter pack). Because the 3 weeks of blower operation did not result in any measurable air flow to these VWs, it appears likely that no appreciable air flow into VW-2 and VW-3 will occur until water levels drop and the filter pack material dehydrates.

### **Vapor Monitoring Points**

All deep screens at all VMPs were fully saturated from the time of the initial measurement through the final weekly event, and it is highly unlikely that the bioventing system has any positive effect on residual contamination at these depths, during the current high-water conditions.

Initial (system startup and first weekly monitoring event) induced pressures at the shallow screens of VMPs indicated that air injection at VW-1 did have a positive pressure effect on VMPs (except for VMP-4). Another indication that the blower system had a positive effect were the increase in oxygen and decrease in carbon dioxide in the shallow screens of VMP-1 and VMP-2. By the second week, induced pressures were either zero or negative (indicating a vacuum) at the VMPs. This suggests that pore spaces in the soil are filled with water (due to rising water levels) and that air is not flowing at these depths.

### **BASELINE CONDITIONS**

Baseline soil vapor sampling results confirm the general conditions observed in the 2004 bioventing pilot test. High petroleum concentrations were detected in soil vapor in the area of groundwater contamination, and depressed oxygen/elevated carbon dioxide levels demonstrate that aerobic microbial activity is occurring but is limited by oxygen supply. Baseline oxygen levels at VMP-2 (area of inferred maximum contamination) are below the level necessary to support sustained aerobic microbial activity.

Minimal air injection is occurring (and only at VW-1) due to high-water level conditions and/or filter pack saturation from well installation. As water levels drop (following the rainy season), it is likely that air injection rates and increases in oxygen concentrations will improve and potentially exceed those seen during the pilot test due to the expanded well network. This expectation will be confirmed by continued measurement of water levels, air injection rates, oxygen concentrations, and the proposed ISR test.

## **6.0 SUMMARY, CONCLUSIONS, AND PROPOSED ACTIONS**

This section presents the conclusions and proposed actions with regard to the installation and implementation of the full-scale bioventing remedial system at the Redwood Regional Park Service Yard.

### **SUMMARY AND CONCLUSIONS**

- The 2005 bioventing pilot test demonstrated a radius of bioventing influence of approximately 30 feet, greater than the minimum design criteria needed for cost-effective operations.
- The full-scale bioventing system was installed in November and December 2005. The full-scale system consists of: four vapor monitoring points, each with two nested screens; three vent wells; air distribution piping from the blower to the VWs; a blower and manifold system; and appurtenant gauges and sampling ports.
- Pre-startup (baseline) soil vapor sampling confirmed elevated petroleum concentrations in the majority of the VMPs (shallow screens) and VWs.
- Pre-startup (baseline) soil vapor sampling also confirmed depressed oxygen/elevated carbon dioxide levels, indicating that aerobic microbial activity is occurring but is limited by oxygen supply.
- Current high-water level conditions as a result of seasonal rains are currently impeding significant air flow into the VWs, and are resulting in tight soil conditions that preclude the sampling of all VMP screens (both deep and shallow).
- Current conditions (little to no air injection) will likely continue through the rainy season. Falling water levels should improve air injection rates and response at the VMPs.

### **PROPOSED ACTIONS**

EBRPD proposes to implement the following actions with regard to the bioventing program:

- Operate and maintain the full-scale bioventing system until in situ respiration testing data (i.e., oxygen utilization rates) and soil vapor sampling data at the VMPs indicate that residual soil contamination has been significantly reduced and that biodegradation is no longer oxygen-limited.

- Conduct monthly operation and maintenance of the bioventing system, including air flow optimization when water level changes and/or air injection rates warrant.
- Conduct an ISR test, including air permeability and system radius of influence, at such time as water levels drop sufficiently to evaluate at least the shallow VMP screens.
- Report on bioventing system progress/activities in quarterly progress reports, and prepare an annual summary report (approximately 1 year after the system begins operation).

## 6.0 REFERENCES

---

Alameda County Health, 2005a. Letter regarding Alameda County Health's review of SES Bioventing Pilot Test Report. May 25.

Alameda County Health, 2005b. Letter approving installation and implementation of bioventing full-scale system. June 24.

Stellar Environmental Solutions, Inc. (SES), 2004a. Bioventing Feasibility Letter Report – Redwood Regional Park Service Yard, Oakland, California. February 6.

Stellar Environmental Solutions, Inc. (SES), 2004b. Bioventing Pilot Tests Result Report, Redwood Regional Park Service Yard, Oakland, California. October 29.

Stellar Environmental Solutions, Inc. (SES), 2003. Letter to Alameda County Health Care Services Agency proposing bioventing as a corrective action remedy at Redwood Regional Park Service Yard, Oakland, California. November 6.



Subject: Drilling borehole for vent well VW-3, looking to the northwest from the park service road.

Site: 7867 Redwood Road, Oakland, Alameda County, California

Date Taken: November 28, 2005

Project No.: SES 2005-66

Photographer: Bruce Rucker

Photo No.: 01



Subject: Drilling borehole for vent well VW-2, looking to the south, down the park entrance road.

Site: 7867 Redwood Road, Oakland, Alameda County, California

Date Taken: November 28, 2005

Project No.: SES 2005-66

Photographer: Bruce Rucker

Photo No.: 02



Subject: Drilling borehole for vapor monitoring point VMP-4, looking to the west from the service yard parking lot.

Site: 7867 Redwood Road, Oakland, Alameda County, California

Date Taken: November 29, 2005

Project No.: SES 2005-66

Photographer: Bruce Rucker

Photo No.: 03



Subject: Trenching for bioventing underground piping, looking to the north from VW-3.

Site: 7867 Redwood Road, Oakland, Alameda County, California

Date Taken: December 5, 2005

Project No.: SES 2005-66

Photographer: Bruce Rucker

Photo No.: 04



Subject: Below-grade piping connected to VW-3 (before backfilling), looking to the north.

Site: 7867 Redwood Road, Oakland, Alameda County, California

Date Taken: December 5, 2005

Project No.: SES 2005-66

Photographer: Bruce Rucker

Photo No.: 05



Subject: Surface completion at vent well VW-3 showing ball valve (red handle) and sampling port (top of well).

Site: 7867 Redwood Road, Oakland, Alameda County, California

Date Taken: December 5, 2005

Project No.: SES 2005-66

Photographer: Bruce Rucker

Photo No.: 06





Subject: Bioventing piping going underground (before backfilling), looking to the north.

Site: 7867 Redwood Road, Oakland, Alameda County, California

Date Taken: December 5, 2005

Project No.: SES 2005-66

Photographer: Bruce Rucker

Photo No.: 07



Subject: Bioventing piping going underground (before backfilling), looking to the south.

Site: 7867 Redwood Road, Oakland, Alameda County, California

Date Taken: December 5, 2005

Project No.: SES 2005-66

Photographer: Bruce Rucker

Photo No.: 08





Subject: Bioventing piping coming from blower shed (before backfilling), looking to the southeast.

Site: 7867 Redwood Road, Oakland, Alameda County, California

Date Taken: December 5, 2005

Project No.: SES 2005-66

Photographer: Bruce Rucker

Photo No.: 09



Subject: Bioventing blower (left) and piping manifold (right) in the blower shed (before installing flow measurement ports on the manifold).

Site: 7867 Redwood Road, Oakland, Alameda County, California

Date Taken: December 5, 2005

Project No.: SES 2005-66

Photographer: Bruce Rucker

Photo No.: 10

# Alameda County Public Works Agency - Water Resources Well Permit



399 Elmhurst Street  
Hayward, CA 94544-1395  
Telephone: (510)670-6633 Fax:(510)782-1939

**Application Approved on:** 10/31/2005 **By jamesy**  
**Permits Issued:** W2005-1069 to W2005-1073

**Receipt Number:** WR2005-2171  
**Permits Valid from** 11/28/2005 **to** 11/30/2005

**Application Id:** 1130791965828  
**Site Location:** 7867 Redwood Road, Oakland, 94546  
(Redwood Park Service Yard)  
**Project Start Date:** 11/28/2005

**City of Project Site:** Oakland

**Completion Date:** 11/30/2005

**Applicant:** Stellar Environmental Solutions - Bruce Rucker  
2198 6th St, Berkeley, CA 94710

**Phone:** 510-644-3123

**Property Owner:** East Bay Regional Park District  
PO Box 5382, Oakland, CA 94605

**Phone:** 510-649-3313

**Client:** \*\* same as Property Owner \*\*

|                           |                     |
|---------------------------|---------------------|
| <b>Total Due:</b>         | \$1200.00           |
| <b>Total Amount Paid:</b> | \$1200.00           |
| <b>Paid By:</b> CHECK     | <b>PAID IN FULL</b> |

**Works Requesting Permits:**

Well Construction-Monitoring-Monitoring - 1 Wells  
Driller: HEW Drilling - Lic #: 604987 - Method: auger

**Work Total: \$300.00**

**Specifications**

| Permit #   | Issued Date | Expire Date | Owner Well Id | Hole Diam. | Casing Diam. | Seal Depth | Max. Depth |
|------------|-------------|-------------|---------------|------------|--------------|------------|------------|
| W2005-1069 | 10/31/2005  | 02/26/2006  | MW-12         | 8.00 in.   | 0.00 in.     | 0.00 ft    | 26.00 ft   |

**Specific Work Permit Conditions**

1. Permittee shall assume entire responsibility for all activities and uses under this permit and shall indemnify, defend and save the Alameda County Public Works Agency, its officers, agents, and employees free and harmless from any and all expense, cost, liability in connection with or resulting from the exercise of this Permit including, but not limited to, properly damage, personal injury and wrongful death.
2. Permitte, permittee's contractors, consultants or agents shall be responsible to assure that all material or waters generated during drilling, boring destruction, and/or other activities associated with this Permit will be safely handled, properly managed, and disposed of according to all applicable federal, state, and local statutes regulating such. In no case shall these materials and/or waters be allowed to enter, or potentially enter, on or off-site storm sewers, dry wells, or waterways or be allowed to move off the property where work is being completed.
3. Prior to any drilling activities, it shall be the applicant's responsibility to contact and coordinate an Underground Service Alert (USA), obtain encroachment permit(s), excavation permit(s) or any other permits or agreements required for that Federal, State, County or City, and follow all City or County Ordinances. No work shall begin until all the permits and requirements have been approved or obtained.
4. Compliance with the well-sealing specifications shall not exempt the well-sealing contractor from complying with appropriate State reporting-requirements related to well destruction (Sections 13750 through 13755 (Division 7, Chapter 10, Article 3) of the California Water Code). Contractor must complete State DWR Form 188 and mail original to the Alameda County Public Works Agency, Water Resources Section, within 60 days. Including permit number and site map.

# Alameda County Public Works Agency - Water Resources Well Permit

5. Applicant shall contact James Yoo for an inspection time at 510-670-6633 at least five (5) working days prior to starting, once the permit has been approved. Confirm the scheduled date(s) at least 24 hours prior to drilling.
6. Wells shall have a Christy box or similar structure with a locking cap or cover. Well(s) shall be kept locked at all times. Well(s) that become damaged by traffic or construction shall be repaired in a timely manner or destroyed immediately (through permit process). No well(s) shall be left in a manner to act as a conduit at any time.
7. Minimum surface seal thickness is two inches of cement grout placed by tremie
8. Minimum seal depth for monitoring wells is 5 feet below ground surface(BGS) or the maximum depth practicable or 20 feet.
9. Copy of approved drilling permit must be on site at all times. Failure to present or show proof of the approved permit application on site shall result in a fine of \$500.00.

---

## Well Destruction-Monitoring - 1 Wells

Driller: HEW Drilling - Lic #: 604987 - Method: auger

Work Total: \$300.00

### Specifications

| Permit #   | Issued Date | Expire Date | Owner Well Id | Hole Diam. | Casing Diam. | Seal Depth | Max. Depth | State Well # | Orig. Permit # | DWR # |
|------------|-------------|-------------|---------------|------------|--------------|------------|------------|--------------|----------------|-------|
| W2005-1070 | 10/31/2005  | 02/26/2006  | MW-4          | 8.00 in.   | 0.00 in.     | 0.00 ft    | 26.00 ft   |              |                |       |

### Specific Work Permit Conditions

1. Drilling Permit(s) can be voided/ cancelled only in writing. It is the applicant's responsibility to notify Alameda County Public Works Agency, Water Resources Section in writing for an extension or to cancel the drilling permit application. No drilling permit application(s) shall be extended beyond ninety (90) days from the original start date. Applicants may not cancel a drilling permit application after the completion date of the permit issued has passed.
2. Compliance with the well-sealing specifications shall not exempt the well-sealing contractor from complying with appropriate State reporting-requirements related to well destruction (Sections 13750 through 13755 (Division 7, Chapter 10, Article 3) of the California Water Code). Contractor must complete State DWR Form 188 and mail original to the Alameda County Public Works Agency, Water Resources Section, within 60 days. Including permit number and site map.
3. Permittee shall assume entire responsibility for all activities and uses under this permit and shall indemnify, defend and save the Alameda County Public Works Agency, its officers, agents, and employees free and harmless from any and all expense, cost and liability in connection with or resulting from the exercise of this Permit including, but not limited to, property damage, personal injury and wrongful death.
4. Applicant shall contact James Yoo for an inspection time at 510-670-6633 at least five (5) working days prior to starting, once the permit has been approved. Confirm the scheduled date(s) at least 24 hours prior to drilling.
5. Permittee, permittee's contractors, consultants or agents shall be responsible to assure that all material or waters generated during drilling, boring destruction, and/or other activities associated with this Permit will be safely handled, properly managed, and disposed of according to all applicable federal, state, and local statutes regulating such. In no case shall these materials and/or waters be allowed to enter, or potentially enter, on or off-site storm sewers, dry wells, or waterways or be allowed to move off the property where work is being completed.

# Alameda County Public Works Agency - Water Resources Well Permit

6. Copy of approved drilling permit must be on site at all times. Failure to present or show proof of the approved permit application on site shall result in a fine of \$500.00.

7. Drill out & Replace with New Well

---

Remedial Well Construction-Injection - 1 Wells

Driller: HEW Drilling - Lic #: 604987 - Method: auger

**Work Total: \$200.00**

## Specifications

| Permit #   | Issued Date | Expire Date | Owner Well Id | Hole Diam. | Casing Diam. | Seal Depth | Max. Depth |
|------------|-------------|-------------|---------------|------------|--------------|------------|------------|
| W2005-1071 | 10/31/2005  | 02/26/2006  | VMP-4         | 8.00 in.   | 0.00 in.     | 0.00 ft    | 22.00 ft   |

## Specific Work Permit Conditions

1. Applicant shall contact James Yoo for an inspection time at 510-670-6633 at least five (5) working days prior to starting, once the permit has been approved. Confirm the scheduled date(s) at least 24 hours prior to drilling.
2. Minimum seal depth is 2 feet below ground surface (BGS).
3. Minimum surface seal thickness is two inches of cement grout placed by tremie
4. Copy of approved drilling permit must be on site at all times. Failure to present or show proof of the approved permit application on site shall result in a fine of \$500.00.
5. Compliance with the above well-sealing specifications shall not exempt the well-sealing contractor from complying with appropriate state reporting-requirements related to well destruction (Sections 13750 through 13755 (Division 7, Chapter 10, Article 3) of the California Water Code). Contractor must complete State DWR Form 188 and mail original to the Alameda County Public Works Agency, Water Resources Section, within 60 days. Including permit number and site map.
6. Permittee shall assume entire responsibility for all activities and uses under this permit and shall indemnify, defend and save the Alameda County Public Works Agency, its officers, agents, and employees free and harmless from any and all expense, cost, liability in connection with or resulting from the exercise of this Permit including, but not limited to, property damage, personal injury and wrongful death.
7. Prior to any drilling activities, it shall be the applicant's responsibility to contact and coordinate an Underground Service Alert (USA), obtain encroachment permit(s), excavation permit(s) or any other permits or agreements required for that Federal, State, County or City, and follow all City or County Ordinances. No work shall begin until all the permits and requirements have been approved or obtained.
8. Permittee, permittee's contractors, consultants or agents shall be responsible to assure that all material or waters generated during drilling, boring destruction, and/or other activities associated with this Permit will be safely handled, properly managed, and disposed of according to all applicable federal, state, and local statutes regulating such. In no case shall these materials and/or waters be allowed to enter, or potentially enter, on or off-site storm sewers, dry wells, or waterways or be allowed to move off the property where work is being completed.

---

Remedial Well Construction-Extraction - 1 Wells

Driller: HEW Drilling - Lic #: 604987 - Method: auger

**Work Total: \$200.00**

# Alameda County Public Works Agency - Water Resources Well Permit

## Specifications

| Permit #   | Issued Date | Expire Date | Owner Well Id | Hole Diam. | Casing Diam. | Seal Depth | Max. Depth |
|------------|-------------|-------------|---------------|------------|--------------|------------|------------|
| W2005-1072 | 10/31/2005  | 02/26/2006  | VW-2          | 8.00 in.   | 0.00 in.     | 0.00 ft    | 18.00 ft   |

## Specific Work Permit Conditions

1. Permittee shall assume entire responsibility for all activities and uses under this permit and shall indemnify, defend and save the Alameda County Public Works Agency, its officers, agents, and employees free and harmless from any and all expense, cost, liability in connection with or resulting from the exercise of this Permit including, but not limited to, properly damage, personal injury and wrongful death.
2. Permittee, permittee's contractors, consultants or agents shall be responsible to assure that all material or waters generated during drilling, boring destruction, and/or other activities associated with this Permit will be safely handled, properly managed, and disposed of according to all applicable federal, state, and local statutes regulating such. In no case shall these materials and/or waters be allowed to enter, or potentially enter, on or off-site storm sewers, dry wells, or waterways or be allowed to move off the property where work is being completed.
3. Compliance with the well-sealing specifications shall not exempt the well-sealing contractor from complying with appropriate State reporting-requirements related to well destruction (Sections 13750 through 13755 (Division 7, Chapter 10, Article 3) of the California Water Code). Contractor must complete State DWR Form 188 and mail original to the Alameda County Public Works Agency, Water Resources Section, within 60 days. Including permit number and site map.
4. Applicant shall contact James Yoo for an inspection time at 510-670-6633 at least five (5) working days prior to starting, once the permit has been approved. Confirm the scheduled date(s) at least 24 hours prior to drilling.
5. Minimum seal depth is 2 feet below ground surface (BGS).
6. Minimum surface seal thickness is two inches of cement grout placed by tremie
7. Copy of approved drilling permit must be on site at all times. Failure to present or show proof of the approved permit application on site shall result in a fine of \$500.00.

Remediation Well Construction-Extraction - 1 Wells

Driller: HEW Drilling - Lic #: 604987 - Method: auger

Work Total: \$200.00

## Specifications

| Permit #   | Issued Date | Expire Date | Owner Well Id | Hole Diam. | Casing Diam. | Seal Depth | Max. Depth |
|------------|-------------|-------------|---------------|------------|--------------|------------|------------|
| W2005-1073 | 10/31/2005  | 02/26/2006  | VW-3          | 8.00 in.   | 0.00 in.     | 0.00 ft    | 18.00 ft   |

## Specific Work Permit Conditions

1. Permittee shall assume entire responsibility for all activities and uses under this permit and shall indemnify, defend and save the Alameda County Public Works Agency, its officers, agents, and employees free and harmless from any and all expense, cost, liability in connection with or resulting from the exercise of this Permit including, but not limited to, properly damage, personal injury and wrongful death.
2. Permittee, permittee's contractors, consultants or agents shall be responsible to assure that all material or waters generated during drilling, boring destruction, and/or other activities associated with this Permit will be safely handled,

## Alameda County Public Works Agency - Water Resources Well Permit

properly managed, and disposed of according to all applicable federal, state, and local statutes regulating such. In no case shall these materials and/or waters be allowed to enter, or potentially enter, on or off-site storm sewers, dry wells, or waterways or be allowed to move off the property where work is being completed.

3. Compliance with the well-sealing specifications shall not exempt the well-sealing contractor from complying with appropriate State reporting-requirements related to well destruction (Sections 13750 through 13755 (Division 7, Chapter 10, Article 3) of the California Water Code). Contractor must complete State DWR Form 188 and mail original to the Alameda County Public Works Agency, Water Resources Section, within 60 days. Including permit number and site map.
  4. Applicant shall contact James Yoo for an inspection time at 510-670-6633 at least five (5) working days prior to starting, once the permit has been approved. Confirm the scheduled date(s) at least 24 hours prior to drilling.
  5. Minimum seal depth is 2 feet below ground surface (BGS).
  6. Minimum surface seal thickness is two inches of cement grout placed by tremie
  7. Copy of approved drilling permit must be on site at all times. Failure to present or show proof of the approved permit application on site shall result in a fine of \$500.00.
-

BORING NUMBER VW-2 Page 1 of 1

PROJECT Redwood Park Service Yard OWNER East Bay Regional Park District



LOCATION 7867 Redwood Road, Oakland, CA PROJECT NUMBER 2005-66

TOTAL DEPTH 18 feet bgs BOREHOLE DIA. 8 inch

SURFACE ELEV. -550' amsl WATER FIRST ENCOUNTERED 17'




DRILLING COMPANY HEW Drilling DRILLING METHOD Hollow Stem Auger

DRILLER Manuel GEOLOGIST B. Rucker DATE DRILLED 11/28/2005

| DEPTH (feet) | GRAPHIC LOG  | DESCRIPTION/SOIL CLASSIFICATION   | REMARKS  |
|--------------|--|---|--|
| 0            |      | Dark brown clayey silt (ML), moist, sl. stiff, cohesive, friable                    |  |
| 2            |  |   |  |
| 4            |  | 4.5' Iron staining and organics   |  |
| 6            |  | 6' Becomes mod. stiff, friable, mod. cohesive, sl. moist                            |  |
| 8            |  |   | Petroleum odor begins at 8.5'  |
| 10           |  |  | Dark brown silty clay (CL), mod. stiff, cohesive, sl. friable, sl. moist |
| 12           | 10' Blue-grey discoloration, sl. stiff, moist  |   |  |
| 14           | 13' Mod. stiff, minor fine-medium sand, mostly dark brown with some blue-grey mottling |   | Petroleum odor slight at 13.5'   |
| 16           | 13.5' Sl. stiff, no visible sand, sticky, moist  |   | Petroleum odor absent at 14.5'   |
| 18           | 14.5' Minor fine sand  |   |  |
| 20           | 17' Sl.-mod. stiff, v. moist<br>17.5' Minor small gravel                               |   |  |
|              |  | Bottom of borehole = 18'  |  |

BORING NUMBER VW-3 Page 1 of 1

PROJECT Redwood Park Service Yard OWNER East Bay Regional Park District  
 LOCATION 7867 Redwood Road, Oakland, CA PROJECT NUMBER 2005-66  
 TOTAL DEPTH 19 feet bgs BOREHOLE DIA. 8 inch  
 SURFACE ELEV. -547' amsl WATER FIRST ENCOUNTERED 17'  
 DRILLING COMPANY HEW Drilling DRILLING METHOD Hollow Stem Auger  
 DRILLER Manuel GEOLOGIST B. Rucker DATE DRILLED 11/28/2005

| DEPTH (feet) | GRAPHIC LOG   | DESCRIPTION/SOIL CLASSIFICATION   | REMARKS               |  |
|--------------|---|---|-----------------------|--|
| 0            |   | Dark brown clayey silt (ML), friable, no cohesion, stiff, dense                     |                       |  |
| 2            |   |   |                       |  |
| 4            |   | 4' Mod. cohesive, sl. stiff, sl. moist  |                       |  |
| 5            |   | 5' No cohesion, mod. stiff  |                       |  |
| 6            |   |   |                       |  |
| 7.5          |   | 7.5' Very stiff   |                       |  |
| 9            |   | 9' Mod. cohesion, friable   |                       |  |
| 10.5         |   | 10.5' Minor fine sand, occasional cobbles   |                       |  |
| 12           |   |  |                       | Light brown sandy, gravelly clay (CL), sand is fine, gravel is small, mod. stiff, friable, sl. cohesive, sl. moist |
| 13.5         |   |   |                       | 13.5' Gravel very minor, sand absent, v. stiff, friable  |
| 14           | 14' Blue-grey silty clay (CL), sl. stiff, v. cohesive, moist                        |   | Petroleum odor at 14' |  |
| 15           | 15' Very moist  |   |                       |  |
| 16           | 16' Gravelly (~30%), small-medium size  |   |                       |  |
| 17           | 17' Blue-grey, no gravel, sl. sandy, sl. stiff, v. cohesive, v. moist               | Petroleum odor ends at 17.5'  |                       |  |
| 18           |  | Light brown clayey silty (ML), med. stiff, v. moist                                 |                       |  |
| 20           |   | Bottom of borehole = 19'  |                       |  |

2005-66-03



BORING NUMBER VWP-4 Page 1 of 1

PROJECT Redwood Park Service Yard OWNER East Bay Regional Park District



LOCATION 7867 Redwood Road, Oakland, CA PROJECT NUMBER 2005-66

TOTAL DEPTH 21 feet bgs BOREHOLE DIA. 8 inch

SURFACE ELEV. -564' amsl WATER FIRST ENCOUNTERED -20'

DRILLING COMPANY HEW Drilling DRILLING METHOD Hollow Stem Auger

DRILLER Manuel GEOLOGIST B. Rucker DATE DRILLED 11/29/2005

| DEPTH (feet) | GRAPHIC LOG   | DESCRIPTION/SOIL CLASSIFICATION  | REMARKS |
|--------------|---|--|---------|
| 0            |   | Brown gravelly silty clay (UFST backfill material)<br>dry, fully friable, sl. cohesive   |         |
| 2            |   |  |         |
| 4            |   |  |         |
| 6            |   |  |         |
| 8            |   |  |         |
| 10           |   |  |         |
| 12           |   |  |         |
| 14           |  | Dark brown silty clay (CL), sl. moist, sl. plastic,<br>slight petroleum odor, cohesive   |         |
| 16           |   |  |         |
| 18           |   |  |         |
| 20           |  | Red-brown clayey silty (ML), minor small gravel,<br>sl. moist, mod. stiff, mod. cohesive |         |
|              |   | Bottom of borehole = 21'   |         |

2005-66-04

**CONFIDENTIAL**

STATE OF CALIFORNIA DWR  
WELL COMPLETION REPORT  
(WELL LOGS)

**REMOVED**

**CONFIDENTIAL**

STATE OF CALIFORNIA DWR  
WELL COMPLETION REPORT  
(WELL LOGS)

**REMOVED**

**CONFIDENTIAL**

STATE OF CALIFORNIA DWR  
WELL COMPLETION REPORT  
(WELL LOGS)

**REMOVED**

**CONFIDENTIAL**

STATE OF CALIFORNIA DWR  
WELL COMPLETION REPORT  
(WELL LOGS)

**REMOVED**

---

**Waste Soil Disposal Profile Sample**







Batch QC Report

**Curtis & Tompkins Laboratories Analytical Report**

|   |                        |
|---|------------------------|
| Lab #: 183495                           | Location: Redwood Park |
| Client: Stellar Environmental Solutions | Prep: EPA 5030B        |
| Project#: STANDARD                      | Analysis: EPA 8021B    |
| Type: LCS                               | Basis: as received     |
| Lab ID: QC319348                        | Diln Fac: 1.000        |
| Matrix: Soil                            | Batch#: 108288         |
| Units: ug/Kg                            | Analyzed: 12/01/05     |

| Analyte      | Spiked | Result | %REC | Limits |
|--------------|--------|--------|------|--------|
| MTBE         | 100.0  | 109.9  | 110  | 71-130 |
| Benzene      | 100.0  | 107.4  | 107  | 80-120 |
| Toluene      | 100.0  | 100.6  | 101  | 80-120 |
| Ethylbenzene | 100.0  | 103.6  | 104  | 80-120 |
| m,p-Xylenes  | 100.0  | 103.2  | 103  | 80-120 |
| o-Xylene     | 100.0  | 105.0  | 105  | 80-120 |

| Surrogate                | %REC | Limits |
|--------------------------|------|--------|
| Trifluorotoluene (PID)   | 98   | 63-125 |
| Bromofluorobenzene (PID) | 110  | 71-129 |

## Batch QC Report

**Curtis & Tompkins Laboratories Analytical Report**

|           |                                 |           |              |
|-----------|---------------------------------|-----------|--------------|
| Lab #:    | 183495                          | Location: | Redwood Park |
| Client:   | Stellar Environmental Solutions | Prep:     | EPA 5030B    |
| Project#: | STANDARD                        | Analysis: | EPA 8015B    |
| Type:     | LCS                             | Basis:    | as received  |
| Lab ID:   | QC319349                        | Diln Fac: | 1.000        |
| Matrix:   | Soil                            | Batch#:   | 108288       |
| Units:    | mg/Kg                           | Analyzed: | 12/01/05     |

| Analyte         | Spiked | Result | %REC | Limits |
|-----------------|--------|--------|------|--------|
| Gasoline C7-C12 | 10.00  | 10.66  | 107  | 80-120 |

| Surrogate                | %REC | Limits |
|--------------------------|------|--------|
| Trifluorotoluene (FID)   | 123  | 59-140 |
| Bromofluorobenzene (FID) | 118  | 62-149 |

Batch QC Report

**Curtis & Tompkins Laboratories Analytical Report**

|             |                                 |           |              |
|-------------|---------------------------------|-----------|--------------|
| Lab #:      | 183495                          | Location: | Redwood Park |
| Client:     | Stellar Environmental Solutions | Prep:     | EPA 5030B    |
| Project#:   | STANDARD                        | Analysis: | EPA 8015B    |
| Field ID:   | SOIL DRUM COMP                  | Diln Fac: | 1.000        |
| MSS Lab ID: | 183495-001                      | Batch#:   | 108288       |
| Matrix:     | Soil                            | Sampled:  | 11/30/05     |
| Units:      | mg/Kg                           | Received: | 11/30/05     |
| Basis:      | as received                     | Analyzed: | 12/02/05     |

Type: MS Lab ID: QC319350

| Analyte         | MSS Result | Spiked | Result | %REC | Limits |
|-----------------|------------|--------|--------|------|--------|
| Gasoline C7-C12 | 2.570      | 10.53  | 13.06  | 100  | 44-120 |

| Surrogate                | %REC | Limits |
|--------------------------|------|--------|
| Trifluorotoluene (FID)   | 118  | 59-140 |
| Bromofluorobenzene (FID) | 115  | 62-149 |

Type: MSD Lab ID: QC319351

| Analyte         | Spiked | Result | %REC | Limits | RPD | Lim |
|-----------------|--------|--------|------|--------|-----|-----|
| Gasoline C7-C12 | 10.99  | 11.60  | 82   | 44-120 | 15  | 23  |

| Surrogate                | %REC | Limits |
|--------------------------|------|--------|
| Trifluorotoluene (FID)   | 113  | 59-140 |
| Bromofluorobenzene (FID) | 111  | 62-149 |



Batch QC Report

**Total Extractable Hydrocarbons**

|           |                                 |           |              |
|-----------|---------------------------------|-----------|--------------|
| Lab #:    | 183495                          | Location: | Redwood Park |
| Client:   | Stellar Environmental Solutions | Prep:     | SHAKER TABLE |
| Project#: | STANDARD                        | Analysis: | EPA 8015B    |
| Type:     | LCS                             | Diln Fac: | 1.000        |
| Lab ID:   | QC319373                        | Batch#:   | 108295       |
| Matrix:   | Soil                            | Prepared: | 12/01/05     |
| Units:    | mg/Kg                           | Analyzed: | 12/02/05     |
| Basis:    | as received                     |           |              |

Cleanup Method: EPA 3630C

| Analyte        | Spiked | Result | %REC | Limits |
|----------------|--------|--------|------|--------|
| Diesel C10-C24 | 49.58  | 46.64  | 94   | 54-137 |

| Surrogate  | %REC | Limits |
|------------|------|--------|
| Hexacosane | 96   | 48-132 |



---

**December 2005 Soil Vapor Samples**

December 28, 2005

Mr. Bruce Rucker  
Stellar Environmental Solutions, Inc.  
2198 Sixth Street #201  
Berkeley, CA 94710

**RE: P2503094**  
**Redwood Bioventing/2005-02**

Dear Mr. Rucker:

Enclosed are the results of the sample(s) submitted to our laboratory on December 12, 2005.  
For your reference, these analyses have been assigned our service request number P2503094.

All analyses were performed in accordance with our laboratory's quality assurance program. Results are intended to be considered in their entirety and apply only to the samples analyzed. Columbia Analytical Services is not responsible for use of less than the complete report. Your report contains 13 pages.

Columbia Analytical Services is certified by the California Department of Health Services, Certificate No. 2380; Arizona Department of Health Services, Certificate No. AZ0550; New Jersey Department of Environmental Protection, NELAP Laboratory Certification ID #CA009; New York State Department of Health, NELAP NY Lab ID No: 11221; Oregon Environmental Laboratory Accreditation Program, NELAP ID: CA20007; The American Industrial Hygiene Association, Laboratory #101661. Please contact me for specific method(s) and analyte(s) corresponding to a particular certification.

If you have any questions, please call me at (805) 526-7161.

Respectfully submitted,

**Columbia Analytical Services, Inc.**



Kate Aguilera  
Project Manager



## LABORATORY REPORT

|          |                                       |                 |          |
|----------|---------------------------------------|-----------------|----------|
| Client:  | Stellar Environmental Solutions, Inc. | Date of Report: | 12/28/05 |
| Address: | 2198 Sixth Street #201                | Date Received:  | 12/12/05 |
|          | Berkeley, CA 94710                    | CAS Project No: | P2503094 |
| Contact: | Mr. Bruce Rucker                      | Purchase Order: | 2005-02  |

Client Project ID: Redwood Bioventing/2005-02

Six (6) Stainless Steel Summa Canisters labeled:

|                 |                 |                 |
|-----------------|-----------------|-----------------|
| "VMP-1-Shallow" | "VMP-2-Shallow" | "VMP-3-Shallow" |
| "VW-1"          | "VW-3"          | "VW-2"          |

The samples were received at the laboratory under chain of custody on December 12, 2005. The samples were received intact. Please refer to the sample acceptance check form for additional information. The results reported herein are applicable only to the condition of the samples at the time that they were received at the laboratory.

### Total Petroleum Hydrocarbons as Gasoline Analysis


The samples were analyzed for total petroleum hydrocarbons as gasoline per modified EPA Method TO-3 using a gas chromatograph equipped with a flame ionization detector (FID).

Reviewed and Approved:



Regan Lau  
Analytical Chemist  
Air Quality Laboratory

Reviewed and Approved:



Wade Henton  
GC-VOA Team Leader  
Air Quality Laboratory

CAS Project No: P2503094

### BTEX/MTBE Analysis

The samples were also analyzed for methyl tert-butyl ether, benzene, toluene, ethylbenzene, and xylenes according to modified CARB Method 410. This method is based on the separation of a gas mixture using dual column high resolution gas chromatographic column followed by measurement of the separated components with dual photoionization detectors (PID). One of the columns serves as the quantitation column and the other the confirmation column. The retention times of each separated component are compared with those of known compounds under identical conditions on the respective column. Only components that contain a peak on both the quantitation column and the confirmation column in the proper retention time window are positively confirmed.

The concentration for each analyte is calculated from each column and compared by relative percent difference. If the RPD is within acceptable limits the lower of the two concentrations is reported; however if the result exceeds the criteria, the lower value is reported with a matrix interference qualifier.

The results of analyses are given on the attached data sheets. All results are intended to be considered in their entirety, and Columbia Analytical Services, Inc. (CAS) is not responsible for utilization of less than the complete report.

**COLUMBIA ANALYTICAL SERVICES, INC.**

RESULTS OF ANALYSIS

Page 1 of 1

**Client:** Stellar Environmental Solutions, Inc.  
**Client Project ID:** Redwood Bioventing/2005-02

CAS Project ID: P2503094

**Total Petroleum Hydrocarbons (TPH) as Gasoline**

**Test Code:** EPA TO-3 Modified  
**Instrument ID:** HP5890 II/GC11/FID  
**Analyst:** Regan Lau  
**Sampling Media:** Summa Canister(s)  
**Test Notes:**

**Date Collected:** 12/9/05  
**Date Received:** 12/12/05  
**Date Analyzed:** 12/16/05  
**Volume(s) Analyzed:** 1.00 ml  
 0.50 ml  
 0.10 ml

| Client Sample ID | CAS Sample ID | D. F. | Total Petroleum Hydrocarbons (TPH) as Gasoline |                          |                |             | Data Qualifier |
|------------------|---------------|-------|--|--------------------------|----------------|-------------|----------------|
|                  |               |       | Result<br>mg/m <sup>3</sup>                    | MRL<br>mg/m <sup>3</sup> | Result<br>ppmV | MRL<br>ppmV |                |
| VMP-1-Shallow    | P2503094-001  | 1.36  | ND   | 24                       | ND             | 6.9         |                |
| VMP-2-Shallow    | P2503094-002  | 1.26  | 18,000   | 230                      | 5,100          | 64          |                |
| VMP-3-Shallow    | P2503094-003  | 1.39  | ND   | 25                       | ND             | 7.1         |                |
| VW-1             | P2503094-004  | 1.15  | 160  | 21                       | 45             | 5.9         | G              |
| VW-3             | P2503094-005  | 1.46  | 8,700  | 26                       | 2,500          | 7.5         | G              |
| VW-2             | P2503094-006  | 1.31  | 14,000   | 47                       | 4,100          | 13          | G              |
| Method Blank     | P051216-MB    | 1.00  | ND   | 18                       | ND             | 5.1         |                |

Parts Per Million Results Are Based on a Molecular Weight of 86.18

ND = Compound was analyzed for, but not detected above the laboratory reporting limit.

MRL = Method Reporting Limit - The minimum quantity of a target analyte that can be confidently determined by the referenced method.

G = Quantitated using fuel calibration, but pattern does not match current gasoline standard.

**COLUMBIA ANALYTICAL SERVICES, INC.**

RESULTS OF ANALYSIS

Page 1 of 1

Client: **Stellar Environmental Solutions, Inc.**

Client Sample ID: **VMP-1-Shallow**

CAS Project ID: **P2503094**

Client Project ID: **Redwood Bioventing/2005-02**

CAS Sample ID: **P2503094-001**

Test Code: **CARB 410 Modified**

Date Collected: **12/9/05**

Instrument ID: **HP5890A/GC2/PID**

Date Received: **12/12/05**

Analyst: **Regan Lau**

Date Analyzed: **12/16/05**

Sampling Media: **Summa Canister**

Volume(s) Analyzed: **1.00 ml**

Test Notes:

Container ID : **1SC00087**

Pi 1 = -2.6

Pf 1 = 1.8

D.F. = 1.36

| CAS #       | Compound                | Result            | MRL               | Result | MRL   | Data Qualifier |
|-------------|-------------------------|-------------------|-------------------|--------|-------|----------------|
|             |                         | mg/m <sup>3</sup> | mg/m <sup>3</sup> | ppmV   | ppmV  |                |
| 1634-04-4   | Methyl tert-Butyl Ether | ND                | 0.25              | ND     | 0.068 |                |
| 71-43-2     | Benzene                 | ND                | 0.22              | ND     | 0.068 |                |
| 108-88-3    | Toluene                 | ND                | 0.26              | ND     | 0.068 |                |
| 100-41-4    | Ethylbenzene            | ND                | 0.30              | ND     | 0.068 |                |
| 136777-61-2 | <i>m,p</i> -Xylenes     | ND                | 0.30              | ND     | 0.068 |                |
| 95-47-6     | <i>o</i> -Xylene        | ND                | 0.30              | ND     | 0.068 |                |

ND = Compound was analyzed for, but not detected above the laboratory reporting limit.

MRL = Method Reporting Limit - The minimum quantity of a target analyte that can be confidently determined by the referenced method.

**COLUMBIA ANALYTICAL SERVICES, INC.**

RESULTS OF ANALYSIS

Page 1 of 1

**Client:** Stellar Environmental Solutions, Inc.  
**Client Sample ID:** VMP-2-Shallow  
**Client Project ID:** Redwood Bioventing/2005-02

**CAS Project ID:** P2503094  
**CAS Sample ID:** P2503094-002

**Test Code:** CARB 410 Modified  
**Instrument ID:** HP5890A/GC2/PID  
**Analyst:** Regan Lau  
**Sampling Media:** Summa Canister  
**Test Notes:**  
**Container ID :** 1SC00037

**Date Collected:** 12/9/05  
**Date Received:** 12/12/05  
**Date Analyzed:** 12/16/05  
**Volume(s) Analyzed:** 1.00 ml

Pi 1 = -1.5

Pf 1 = 1.9

D.F. = 1.26

| CAS #       | Compound                | Result            | MRL               | Result | MRL   | Data Qualifier |
|-------------|-------------------------|-------------------|-------------------|--------|-------|----------------|
|             |                         | mg/m <sup>3</sup> | mg/m <sup>3</sup> | ppmV   | ppmV  |                |
| 1634-04-4   | Methyl tert-Butyl Ether | 77                | 0.23              | 21     | 0.063 | PI             |
| 71-43-2     | Benzene                 | 190               | 0.20              | 61     | 0.063 | PI             |
| 108-88-3    | Toluene                 | 110               | 0.24              | 28     | 0.063 |                |
| 100-41-4    | Ethylbenzene            | 350               | 0.27              | 80     | 0.063 |                |
| 136777-61-2 | <i>m,p</i> -Xylenes     | 1,200             | 0.27              | 280    | 0.063 |                |
| 95-47-6     | <i>o</i> -Xylene        | 160               | 0.27              | 36     | 0.063 | PI             |

ND = Compound was analyzed for, but not detected above the laboratory reporting limit.

MRL = Method Reporting Limit - The minimum quantity of a target analyte that can be confidently determined by the referenced method.

PI = Possible/Probable Interference and/or Analyte whose concentration has a greater than 25% difference for detected concentrations between the GC primary and confirmation columns.

**COLUMBIA ANALYTICAL SERVICES, INC.**

RESULTS OF ANALYSIS

Page 1 of 1

Client: **Stellar Environmental Solutions, Inc.**

Client Sample ID: **VMP-3-Shallow**

Client Project ID: **Redwood Bioventing/2005-02**

CAS Project ID: **P2503094**

CAS Sample ID: **P2503094-003**

Test Code: **CARB 410 Modified**

Instrument ID: **HP5890A/GC2/PID**

Analyst: **Regan Lau**

Sampling Media: **Summa Canister**

Test Notes:

Container ID : **1SC00027**

Date Collected: **12/9/05**

Date Received: **12/12/05**

Date Analyzed: **12/16/05**

Volume(s) Analyzed: **1.00 ml**

Pi 1 = **-3.2**

Pf 1 = **1.3**

D.F. = **1.39**

| CAS #       | Compound                | Result            | MRL               | Result | MRL   | Data Qualifier |
|-------------|-------------------------|-------------------|-------------------|--------|-------|----------------|
|             |                         | mg/m <sup>3</sup> | mg/m <sup>3</sup> | ppmV   | ppmV  |                |
| 1634-04-4   | Methyl tert-Butyl Ether | ND                | 0.25              | ND     | 0.070 |                |
| 71-43-2     | Benzene                 | ND                | 0.22              | ND     | 0.070 |                |
| 108-88-3    | Toluene                 | ND                | 0.26              | ND     | 0.070 |                |
| 100-41-4    | Ethylbenzene            | ND                | 0.30              | ND     | 0.070 |                |
| 136777-61-2 | <i>m,p</i> -Xylenes     | ND                | 0.30              | ND     | 0.070 |                |
| 95-47-6     | <i>o</i> -Xylene        | ND                | 0.30              | ND     | 0.070 |                |

ND = Compound was analyzed for, but not detected above the laboratory reporting limit.

MRL = Method Reporting Limit - The minimum quantity of a target analyte that can be confidently determined by the referenced method.

**COLUMBIA ANALYTICAL SERVICES, INC.**

RESULTS OF ANALYSIS

Page 1 of 1

**Client:** Stellar Environmental Solutions, Inc.  
**Client Sample ID:** VW-1  
**Client Project ID:** Redwood Bioventing/2005-02

**CAS Project ID:** P2503094  
**CAS Sample ID:** P2503094-004

**Test Code:** CARB 410 Modified  
**Instrument ID:** HP5890A/GC2/PID  
**Analyst:** Regan Lau  
**Sampling Media:** Summa Canister  
**Test Notes:**  
**Container ID :** 1SC00048

**Date Collected:** 12/9/05  
**Date Received:** 12/12/05  
**Date Analyzed:** 12/16/05  
**Volume(s) Analyzed:** 1.00 ml

Pi 1 = -1.0

Pf 1 = 1.1

D.F. = 1.15

| CAS #       | Compound                | Result            | MRL               | Result | MRL   | Data Qualifier |
|-------------|-------------------------|-------------------|-------------------|--------|-------|----------------|
|             |                         | mg/m <sup>3</sup> | mg/m <sup>3</sup> | ppmV   | ppmV  |                |
| 1634-04-4   | Methyl tert-Butyl Ether | ND                | 0.21              | ND     | 0.058 |                |
| 71-43-2     | Benzene                 | ND                | 0.18              | ND     | 0.058 |                |
| 108-88-3    | Toluene                 | ND                | 0.22              | ND     | 0.058 |                |
| 100-41-4    | Ethylbenzene            | ND                | 0.25              | ND     | 0.058 |                |
| 136777-61-2 | <i>m,p</i> -Xylenes     | 0.25              | 0.25              | 0.058  | 0.058 | NX, PI         |
| 95-47-6     | <i>o</i> -Xylene        | ND                | 0.25              | ND     | 0.058 |                |

ND = Compound was analyzed for, but not detected above the laboratory reporting limit.

MRL = Method Reporting Limit - The minimum quantity of a target analyte that can be confidently determined by the referenced method.

PI = Possible/Probable Interference and/or Analyte whose concentration has a greater than 25% difference for detected concentrations between the GC primary and confirmation columns.

NX = Chromatogram does not resemble Xylene

**COLUMBIA ANALYTICAL SERVICES, INC.**

RESULTS OF ANALYSIS

Page 1 of 1

Client: **Stellar Environmental Solutions, Inc.**  
 Client Sample ID: **VW-3**  
 Client Project ID: **Redwood Bioventing/2005-02**

CAS Project ID: **P2503094**  
 CAS Sample ID: **P2503094-005**

Test Code: **CARB 410 Modified**  
 Instrument ID: **HP5890A/GC2/PID**  
 Analyst: **Regan Lau**  
 Sampling Media: **Summa Canister**  
 Test Notes:  
 Container ID : **1SC00089**

Date Collected: **12/9/05**  
 Date Received: **12/12/05**  
 Date Analyzed: **12/16/05**  
 Volume(s) Analyzed: **1.00 ml**

Pi 1 = -3.7                      Pf 1 = 1.4

D.F. = 1.46

| CAS #       | Compound                | Result            | MRL               | Result | MRL   | Data Qualifier |
|-------------|-------------------------|-------------------|-------------------|--------|-------|----------------|
|             |                         | mg/m <sup>3</sup> | mg/m <sup>3</sup> | ppmV   | ppmV  |                |
| 1634-04-4   | Methyl tert-Butyl Ether | ND                | 0.26              | ND     | 0.073 |                |
| 71-43-2     | Benzene                 | 6.1               | 0.23              | 1.9    | 0.073 | NX, PI         |
| 108-88-3    | Toluene                 | 32                | 0.28              | 8.5    | 0.073 |                |
| 100-41-4    | Ethylbenzene            | ND                | 0.32              | ND     | 0.073 |                |
| 136777-61-2 | <i>m,p</i> -Xylenes     | 34                | 0.32              | 7.9    | 0.073 | NX             |
| 95-47-6     | <i>o</i> -Xylene        | ND                | 0.32              | ND     | 0.073 |                |

ND = Compound was analyzed for, but not detected above the laboratory reporting limit.

MRL = Method Reporting Limit - The minimum quantity of a target analyte that can be confidently determined by the referenced method.

PI = Possible/Probable Interference and/or Analyte whose concentration has a greater than 25% difference for detected concentrations between the GC primary and confirmation columns.

NX = Chromatogram does not resemble benzene and xylene



**COLUMBIA ANALYTICAL SERVICES, INC.**

RESULTS OF ANALYSIS

Page 1 of 1

**Client:** Stellar Environmental Solutions, Inc.  
**Client Sample ID:** VW-2  
**Client Project ID:** Redwood Bioventing/2005-02

**CAS Project ID:** P2503094  
**CAS Sample ID:** P2503094-006

**Test Code:** CARB 410 Modified  
**Instrument ID:** HP5890A/GC2/PID  
**Analyst:** Regan Lau  
**Sampling Media:** Summa Canister  
**Test Notes:**  
**Container ID :** 1SC00034

**Date Collected:** 12/9/05  
**Date Received:** 12/12/05  
**Date Analyzed:** 12/16/05  
**Volume(s) Analyzed:** 1.00 ml

Pi 1 = -2.7

Pf 1 = 1.0

D.F. = 1.31

| CAS #       | Compound                | Result            | MRL               | Result | MRL   | Data Qualifier |
|-------------|-------------------------|-------------------|-------------------|--------|-------|----------------|
|             |                         | mg/m <sup>3</sup> | mg/m <sup>3</sup> | ppmV   | ppmV  |                |
| 1634-04-4   | Methyl tert-Butyl Ether | ND                | 0.24              | ND     | 0.065 |                |
| 71-43-2     | Benzene                 | 9.1               | 0.21              | 2.8    | 0.065 | NX, PI         |
| 108-88-3    | Toluene                 | 12                | 0.25              | 3.3    | 0.065 |                |
| 100-41-4    | Ethylbenzene            | 11                | 0.28              | 2.5    | 0.065 | PI             |
| 136777-61-2 | <i>m,p</i> -Xylenes     | 6.6               | 0.28              | 1.5    | 0.065 | NX, PI         |
| 95-47-6     | <i>o</i> -Xylene        | ND                | 0.28              | ND     | 0.065 |                |

ND = Compound was analyzed for, but not detected above the laboratory reporting limit.

MRL = Method Reporting Limit - The minimum quantity of a target analyte that can be confidently determined by the referenced method.

PI = Possible/Probable Interference and/or Analyte whose concentration has a greater than 25% difference for detected concentrations between the GC primary and confirmation columns.

NX = Chromatogram does not resemble benzene and xylene

**COLUMBIA ANALYTICAL SERVICES, INC.**

RESULTS OF ANALYSIS

Page 1 of 1

**Client:** Stellar Environmental Solutions, Inc.

**Client Sample ID:** Method Blank

CAS Project ID: P2503094

**Client Project ID:** Redwood Bioventing/2005-02

CAS Sample ID: P051216-MB

**Test Code:** CARB 410 Modified

Date Collected: NA

**Instrument ID:** HP5890A/GC2/PID

Date Received: NA

**Analyst:** Regan Lau

Date Analyzed: 12/16/05

**Sampling Media:** Summa Canister

Volume(s) Analyzed: 1.00 ml

**Test Notes:**

D.F. = 1.00

| CAS #       | Compound                | Result            | MRL               | Result | MRL   | Data Qualifier |
|-------------|-------------------------|-------------------|-------------------|--------|-------|----------------|
|             |                         | mg/m <sup>3</sup> | mg/m <sup>3</sup> | ppmV   | ppmV  |                |
| 1634-04-4   | Methyl tert-Butyl Ether | ND                | 0.18              | ND     | 0.050 |                |
| 71-43-2     | Benzene                 | ND                | 0.16              | ND     | 0.050 |                |
| 108-88-3    | Toluene                 | ND                | 0.19              | ND     | 0.050 |                |
| 100-41-4    | Ethylbenzene            | ND                | 0.22              | ND     | 0.050 |                |
| 136777-61-2 | <i>m,p</i> -Xylenes     | ND                | 0.22              | ND     | 0.050 |                |
| 95-47-6     | <i>o</i> -Xylene        | ND                | 0.22              | ND     | 0.050 |                |

ND = Compound was analyzed for, but not detected above the laboratory reporting limit.

MRL = Method Reporting Limit - The minimum quantity of a target analyte that can be confidently determined by the referenced method.

**Columbia Analytical Services, Inc.**  
**Sample Acceptance Check Form**

Client: Stellar Environmental Solutions, Inc.

Work order:

P2503094

Project: Redwood Bioventing/2005-02

Sample(s) received on: 12/12/05

Date opened: 12/12/05

by: MZ

*Note:* This form is used for all samples received by CAS. The use of this form for custody seals is strictly meant to indicate presence/absence and not as an indication of compliance or nonconformity. Thermal preservation and pH will only be evaluated either at the request of the client or as required by the method/SOP.

|    |   | <u>Yes</u>                          | <u>No</u>                           | <u>N/A</u>                          |
|----|---|-------------------------------------|-------------------------------------|-------------------------------------|
| 1  | Were <b>custody seals</b> on outside of cooler/Box?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |
|    | Location of seal(s)? _____ Sealing Lid?   | <input type="checkbox"/>            | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |
|    | Were signature and date included?   | <input type="checkbox"/>            | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |
|    | Were seals intact?  | <input type="checkbox"/>            | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |
|    | Were custody seals on outside of sample container?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |
|    | Location of seal(s)? _____ Sealing Lid?   | <input type="checkbox"/>            | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |
|    | Were signature and date included?   | <input type="checkbox"/>            | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |
|    | Were seals intact?  | <input type="checkbox"/>            | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |
| 2  | Were <b>sample containers</b> properly marked with client sample ID?                                      | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/>            |
| 3  | Did <b>sample containers</b> arrive in good condition?  | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/>            |
| 4  | Were <b>chain-of-custody</b> papers used and filled out?  | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/>            |
| 5  | Did <b>sample container labels</b> and/or tags agree with custody papers?                                 | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/>            |
| 6  | Was <b>sample volume</b> received adequate for analysis?  | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/>            |
| 7  | Are samples within specified holding times?   | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/>            |
| 8  | Was proper <b>temperature</b> (thermal preservation) of cooler at receipt adhered to?                     | <input type="checkbox"/>            | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |
|    | Cooler Temperature <u>NA</u> °C   |                                     |                                     |                                     |
|    | Blank Temperature <u>NA</u> °C  |                                     |                                     |                                     |
| 9  | Is pH (acid) <b>preservation</b> necessary, according to method/SOP or Client specified information?      | <input type="checkbox"/>            | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |
|    | Is there a client indication that the submitted samples are <b>pH</b> (acid) preserved?                   | <input type="checkbox"/>            | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |
|    | Were <b>VOA vials</b> checked for presence/absence of air bubbles?  | <input type="checkbox"/>            | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |
|    | Does the client/method/SOP require that the analyst check the sample pH and <u>if necessary</u> alter it? | <input type="checkbox"/>            | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |
| 10 | <b>Tubes:</b> Are the tubes capped and intact?  | <input type="checkbox"/>            | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |
|    | Do they contain moisture?   | <input type="checkbox"/>            | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |
| 11 | <b>Badges:</b> Are the badges properly capped and intact?   | <input type="checkbox"/>            | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |
|    | Are dual bed badges separated and individually capped and intact?   | <input type="checkbox"/>            | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |

| Lab Sample ID | Required pH<br>(as received, if required) | pH<br>(as received, if required) | VOA Headspace<br>(Presence/Absence) | Receipt / Preservation<br>Comments |
|---------------|---|----------------------------------|-------------------------------------|------------------------------------|
| P2503094-001  |   |                                  | NA                                  |                                    |
| P2503094-002  |   |                                  | NA                                  |                                    |
| P2503094-003  |   |                                  | NA                                  |                                    |
| P2503094-004  |   |                                  | NA                                  |                                    |
| P2503094-005  |   |                                  | NA                                  |                                    |
| P2503094-006  |   |                                  | NA                                  |                                    |
|               |   |                                  |                                     |                                    |
|               |   |                                  |                                     |                                    |
|               |   |                                  |                                     |                                    |

Explain any discrepancies: (include lab sample ID numbers): \_\_\_\_\_



**Air Quality Laboratory**  
 2665 Park Center Drive, Suite D  
 Simi Valley, California 93065  
 Phone (805) 526-7161  
 Fax (805) 526-7270

**Chain of Custody Record & Analytical Service Request**

**Requested Turnaround Time by Close of Business Day (Surcharges) Please Circle:**  
 1 Day (100%) 2 Day (75%) 3 Day (50%) 4 Day (35%) 5 Day (15%) 10 Day-Standard

CAS Project No. P2503044

**Reporting Information (Company Name & Address)**  
 Stellar Environmental Solutions, Inc  
 2148 Sixth St #201  
 Berkeley CA 94710  
 Attention: BRUCE RUCKER

Phone 510/644-3123 Fax 510/644-3159

Email Address for Result Reporting  
brucker@stellar-environmental.com

**P.O. # / Billing Information**  
2005-02

**Project Name**  
REDWOOD BIOMENTING

**Project Number**  
2005-02

**Sampler (Print & Sign)**  
JOSEPH DWAN Joseph Dwan

**CAS Contact:**  
Kate Aguilera

**Analysis Method and/or Analytes**

**Comments**  
 e.g. Preservative or specific instructions

| Client Sample ID         | Date Collected | Time Collected | Lab Sample No. | Sample Type (Air/Liquid/Solid/Tube) | Canister ID (Bar Code#) | Flow Controller (Bar Code #) | Sample Volume |                 |      |                      |
|--------------------------|----------------|----------------|----------------|-------------------------------------|-------------------------|------------------------------|---------------|-----------------|------|----------------------|
| VMP-1-shallow            | 12/9/05        | 1250           | (1)            | AIR                                 | 15C00087                | NA                           | 1L            | TO-3            | -5.2 |                      |
| VMP-2-shallow            |                | 1305           | (2)            |                                     | 15C00087                |                              |               | TO-3            | -3.1 |                      |
| VMP-3-shallow            |                | 1230           | (3)            |                                     | 15C00087                |                              |               | TO-3            | -6.5 |                      |
| <del>VMP-4-shallow</del> |                |                |                |                                     | <del>15C00034</del>     |                              |               | <del>TO-3</del> |      | Sample Not Collected |
| VW-1                     |                | 1455           | (4)            |                                     | 15C00048                |                              |               | TO-3            | -2.1 |                      |
| <del>VW-2</del>          |                |                |                |                                     | <del>15C00090</del>     |                              |               | <del>TO-3</del> |      | Do Not Analyze       |
| VW-3                     |                | 1430           | (5)            |                                     | 15C00089                |                              |               | TO-3            | -7.5 |                      |
| VW-2                     | 12/9/05        | 1600           | (6)            | AIR                                 | 15C00034                | NA                           | 1L            | TO-3            | -5.8 |                      |

**Report Tier Levels - please select**  
 Tier I - (default if not specified)   
 Tier II (QC forms) \_\_\_\_\_  
 Tier III (QC, Raw Data, Spectra) 10% Surcharge \_\_\_\_\_  
 Other \_\_\_\_\_

EDD required  Yes / No  
 Type: \_\_\_\_\_

**Project Requirements (MRLs, QAPP)**

|  |                      |                   |   |                       |                   |
|--|----------------------|-------------------|---|-----------------------|-------------------|
| Relinquished by: (Signature)<br><u>Joseph Dwan</u> | Date: <u>12/9/05</u> | Time: <u>1700</u> | Received by: (Signature)<br><u>TO FED EX</u>  | Date: <u>12/9/05</u>  | Time: <u>1700</u> |
| Relinquished by: (Signature)<br><u>Fedex</u>       | Date:                | Time:             | Received by: (Signature)<br><u>W. Truller</u> | Date: <u>12/10/05</u> | Time: <u>0900</u> |
| Relinquished by: (Signature)<br><u>W</u>           | Date:                | Time:             | Received by: (Signature)                      | Date:                 | Time:             |

Cooler / Blank Temperature \_\_\_\_\_ °C



**NON-HAZARDOUS WASTE MANIFEST**

1. Generator's US EPA ID No.

*Non-Applicable*

Manifest Doc. No.

*4380A*

2. Page 1

of 1

3. Generator's Name and Mailing Address

*East Bay Regional Park District  
P.O. Box 5381 - Oakland, Ca 94605-0381*

4. Generator's Phone

*(510) 649-3313*

5. Transporter 1 Company Name

*Morgan Environmental, Inc.*

6. US EPA ID Number  
*CAT 080013428*

A. Transporter's Phone

*510-267-0134*

7. Transporter 2 Company Name

8. US EPA ID Number

B. Transporter's Phone

9. Designated Facility Name and Site Address

~~ALTA MONT LANDFILL  
10840 ALTA MONT PASS RD  
LIVERMORE, CA 94550~~  
*DK Environmental  
3650 East 26th St  
Vernon, Ca 90023*

10. US EPA ID Number

~~CAT 080033681  
CAT 0801562132~~

C. Facility's Phone

~~523-268-5050  
(925) 419-8349~~

11. Waste Shipping Name and Description

a. *Non-Hazardous Waste Solid*

12. Containers

No. Type

13. Total Quantity

14. U

*211 DM 67700 P*

D. Additional Descriptions for Materials Listed Above

*A) Soil Cuttings*

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

PROFILE # \_\_\_\_\_

CUSTOMER NAME \_\_\_\_\_

*MFA 4380  
Site: 7867 Redwood Rd.  
Oakland, Ca.*

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name

*Joseph D. ... - Stelling Environmental*

Signature

*[Signature]*

Month Day Year  
*12 12 02*

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

*Warren A. Young*

Signature

*[Signature]*

Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature

Month Day Year

GENERATOR

TRANSPORTER

FACILITY