

10/7

Post-It™ brand fax transmittal memo 7671		# of pages ▶ 4
To Chris Carpenter	From Scott SEERY	
Co. DAS office	Co. ACDEH	
Dept.	Phone # 271-4530	
Fax # 569-0505	Fax #	

Chris -

Here is my evaluation of the GTI work plan.

This stage of the investigation is not necessarily the last stage of work to be completed here. For example, the results of this phase may indicate the need for further soil evaluation and additional wells once gradient has been determined. Further, lead (Pb) levels in the waste oil pit area are sufficiently high that a waste extraction test (WET) per 22 CCR is required, in the strictest sense. Consequently, hazardous waste levels of lead may actually be present in soil associated with the waste oil tank leak. However, I felt it important to get going on the ground water study now — The other stages can ~~also~~ come sequentially.

Scott

9/90 UST closures

- 10,000 gal w.o. tank
- obvious contamination noted above tank near fill tube
 - " " below UST in A11 - slab at bottom
 - holes observed in tank (several)
 - sample collected from SW end (near fill)
 - " " " E side (near service bays)
 - no samples from remote fill inside building
 - no samples from pipes leading into building
 - holes in several tanks
- oil tanks

REPORT 10/90 AEMC

.. All soil samples analyzed for: BTX5, TPH-D ~~5~~, TOC
 In addition, w.o. tank samples : TPH-E, VOC (8240), metals
 semi VOC's ? ? -

WP results:	TPH-D	787A	787B
G	5	200	1800
B	31	31	
T	ND	12	
E			
X			
Pb	360*	180*	
TOC	3200	2100	
Peak	82	7	
TCE	17	19	

7A - North end
 7B - South(?) "

* > 10x STEC for Pb (5.0 mg kg⁻¹)

oil UST results

TPH-D	320
TOC	600
E	0.013
X	0.014

} up to these values

11/90 AEMC proposal (11/2; revised 11/13/89)

- overexcavate UST excavation (which?)
- confirmatory samples (TPH-D, TOC)
- line and backfill excavation w/ pea gravel

11/15/90

new oil UST pits overexcavated, samples collected

1/4/91 - AEMC Prelim. report + assessment w.p.

- Phase I - ECP proposed; 15 ECP "soundings"
 " II - soil samples collected adjacent to soundings through standard borings (15); ECP used
 " III - ECP ("hydroprobe") used to collect GW samples; no metals?
 " IV - Report

USTs on both sides of bldg.

one side S - clean motor oil - moderate cont.

other side I - w. - extreme cont
Cl
metals
OG

also, former fuel USTs may have been former near corner; none have been discovered (AM-Env.)
- hydro fract
- borings

- went to front door of building, cont.
may go under building