


A Report Prepared for


City of Oakland  
Redevelopment Agency  
One City Hall Plaza  
Oakland, California 94612


INITIAL GASOLINE LEAK INVESTIGATION  
CHINATOWN REDEVELOPMENT PROJECT AREA  
OAKLAND, CALIFORNIA

HLA Job No. 9382,005.02

By

  
Gregory Sengleman  
Project Geologist

  
Donald G. Gray  
Civil Engineer



Harding Lawson Associates  
200 Rush Landing Road  
P.O. Box 578  
Novato, California 94948  
415/892-0821

June 19, 1987

## INTRODUCTION

This report summarizes the results of Harding Lawson Associates' (HLA) initial investigation of gasoline leakage from underground storage tanks located near 11th and Webster Streets in the Chinatown Redevelopment Project Area of Oakland. The purpose of our investigation was to evaluate the vertical extent of gasoline in soil below the former tank locations and whether leakage has impacted ground water. The scope of our services, as outlined in our revised proposal to the City of Oakland Department of Public Works, dated May 8, 1987, was to drill two test borings, complete one of the borings as a ground-water monitoring well, analyze soil samples for gasoline, and prepare a report summarizing our findings.

### Background

HLA provided observation, sampling, and chemical analysis services during removal of four underground storage tanks from below the sidewalk area on 11th Street just west of Webster Street (Plate 1). The results of observations, sampling, and chemical analysis during tank removal were summarized in our letter report dated May 8, 1987. The report concluded that there has been significant spillage or leakage into the material surrounding the tanks and that hydrocarbon materials have migrated into the native soils below the tank backfill. Concentrations of total petroleum hydrocarbons (TPH) as gasoline ranged from 3,200 to 11,000 parts per million (ppm) below the three tanks that contained gasoline. One of the tanks contained waste oil and concentrations of oil and grease measured as total oil and grease (TOG) were 5,700 ppm. Based on these observations and test results, we recommended that a ground-water monitoring well be installed to evaluate the

impact on water quality and that a test boring be drilled in the tank excavation to evaluate the vertical distribution of gasoline below the former tank location.

## FIELD INVESTIGATION

### Drilling and Sampling

We drilled two test borings at this site on May 26, 1987 (Plate 1). The borings were drilled with truck-mounted hollow-stem auger drilling equipment. Our geologist was present during drilling to log the soil conditions encountered and to obtain samples for lithologic classification and chemical analyses. Soil samples were obtained by driving a split-barrel sampler lined with stainless steel tubes into the soils. Soil samples were sealed in the tubes with aluminum foil, capped, labeled, and stored on ice in a cooler until delivery to the analytical laboratory. During drilling, we screened the soil samples for vapors using a Gastech Model 1314 portable gas analyzer. Soil conditions encountered in the borings, sample locations, and vapor readings are shown on the boring logs (Plates 2 and 3). The soils are classified in accordance with the Unified Soil Classification System (Plate 4).

Each boring was drilled with augers that had been steam cleaned before drilling. The soil sampler was washed in a solution of Alconox and rinsed in tap water prior to each sampling effort. Boring 1 was completed as a ground-water monitoring well, as described in the following section. Boring 2, which was drilled to the ground-water level, was grouted from the bottom to a depth of 9 feet below ground surface. The upper 9 feet was not grouted because old backfill in the upper 9 feet will subsequently be excavated and removed.

Monitoring Well Installation and Sampling

Boring 1, located south (and assumed to be downgradient) and within 10 feet of the former tank location, was completed as a 4-inch-diameter ground-water monitoring well. The well extended 15 feet into the ground water, as required by the Regional Water Quality Control Board (RWQCB) in their guidelines for addressing fuel leaks. Details of the well completion are shown on Plate 5, which indicates the screened interval, sand pack, bentonite pellet, and sanitary seal dimensions. The well was developed the day following installation. Prior to well development, the ground water was checked for floating product using a clear Lucite bailer. Development was performed by pumping 15 well-bore volumes with a submersible pump. During the development process, pH, specific conductance, and temperature of the discharge water were monitored. The water was discharged into 55 gallon drums and left on site. The water sample was obtained from the well after development using a laboratory-cleaned plastic bottle. The water was decanted into laboratory-prepared volatile organic analysis (VOA) bottles, labeled, and placed in a cooler on ice until delivery to the analytical laboratory.

Chemical Analyses

The soil and ground-water samples were transported in a cool ice chest under chain of custody to Wesco Laboratories in Novato for chemical analyses. The analyses were performed using methods approved by the Regional Water Quality Control Board and EPA as indicated on the laboratory test result forms (attached). Three soil samples from Boring 2 and one soil sample from Boring 1 were analyzed for TPH as gasoline and for benzene, toluene, and xylenes (BTX). Concentrations of TPH and BTX found in Borings 1 and 2 are noted on the boring

logs (Plates 2 and 3). The water sample was analyzed for TPH, BTX, and for purgeable halocarbons using EPA Method 601. The sample was analyzed by Method 601 because our geologist smelled a "sweet" odor during sampling that was uncharacteristic of gasoline. Concentrations of TPH, BTX, and other organic compounds that were detected in the ground-water sample are summarized on Table 1.

### SUBSURFACE CONDITIONS

#### Soil Conditions

Test borings encountered 4 to 9 feet of old fill underlain by natural sandy soils to the depths explored (39 feet). The deeper fill in Boring 2 consisted of temporary backfill placed in the former tank excavation. Sandy soils below the fill consist of slightly clayey and silty sands to a depth of about 22 feet, where clean sands were encountered. These subsurface conditions generally agree with the results of previous geotechnical test borings drilled in the parcel south of our investigation for a proposed high-rise building. Strong gasoline odors were detected in Boring 2, drilled at the former tank location, all the way to ground water. Light to moderate odors were detected in Boring 1 located south of the tank location.

Ground water was encountered in our test borings at 24 to 26 feet below ground surface. The depth of ground water stabilized in our monitoring well one day after installation at a depth of 26.4 feet below ground surface.

### Chemical Analyses

High concentrations of gasoline were detected in the soil samples from Boring 2 (Plate 3), with the highest concentrations encountered just above the ground-water level. The soil sample obtained from just above the water level in Boring 1 showed relatively low concentrations of gasoline (Plate 2). TPH measured as gasoline, typical gasoline indicators (BTX), purgeable halocarbons, and ethylene dibromide (EDB) were detected in the ground water. Some of these chemicals exceed state action levels for drinking water (Table 1).

### DISCUSSION AND CONCLUSIONS

The vertical extent of gasoline in the former tank excavation area confirms our previous conclusion that there has been significant leakage from one or more of the former tanks. The concentrations of gasoline detected exceed the RWQCB guideline of 1,000 ppm for soil removal or remediation. Although data are limited, the relatively low concentration of gasoline in the soil in Boring 1 and the relatively lower vapor reading suggest that migration of gasoline from the tanks has been largely downward with limited lateral migration in the unsaturated zone. This is to be expected, considering the relatively free-draining nature of the sands underneath the site.

Dissolved gasoline is present in the ground water, indicating that leakage from the tanks has impacted ground-water quality. The source of the other organic compounds detected in the water is unknown. The laboratory was asked to check the chromatographic records from the soil analysis in Boring 2 to see if there were indications that these organic compounds are present in the unsaturated zone. However, the high concentrations of gasoline present masked any lower

concentrations of other organics that might be present. The "sweet" odor noticed in the ground water was not noticed in the soil and previous analysis of the tank contents indicates that three of the tanks contained gasoline and one contained waste oil. Therefore, it is possible that the source of the organic compounds is upgradient. Additional ground-water investigations will be needed to evaluate the source of the organic compounds, the lateral extent of the gasoline, and the ground-water flow direction.

We recommend that an Underground Storage Tank Unauthorized Release/Contamination Site Report be filed as required by the RWQCB and that appropriate regulatory agencies be contacted regarding the scope for additional investigations. Also, the ground water should be resampled and analyzed using EPA method 624 to confirm the organic compounds initially detected.

Table 1. Compounds Detected in Ground Water from MW-1  
on May 28, 1987

<u>Compound</u>	<u>Concentration mg/l (ppm)</u>	<u>State Action Level<sup>1</sup></u>
Petroleum hydrocarbons (as gasoline)	66	N <sup>2</sup>
Benzene	4.9	.0007
Toluene	6.8	0.10
Xylenes	6.1	0.62
Chlorobenzene	0.051	N
1,2-Dichloroethane (1,2-DCA)	0.51	0.001
1,2-Dichloropropane	0.003	0.010
Ethylene dibromide (EDB)	0.18	0.00005
Trichloroethene (TCE)	0.036	0.005
1,1,2-Trichloroethane (1,1,2-TCA)	0.002	N

<sup>1</sup>Drinking water action level, ppm.

<sup>2</sup>No standard.



PLATES


Plate 1 - Boring Location Map

Plate 2 - Log of Boring 1

Plate 3 - Log of Boring 2

Plate 4 - Unified Soil Classification Chart

Plate 5 - Well Construction Detail for Monitoring Well 1



**Harding Lawson Associates**  
Engineers and Geoscientists

**Boring Location Map**  
Oakland Chinatown Tanks  
Oakland, California

PLATE

**1**

DRAWN  
MG


JOB NUMBER  
09382,005.02

APPROVED  
*D. Gray*

DATE  
6/87

REVISED

DATE



**Harding Lawson Associates**  
Engineers, Geologists  
& Geophysicists

**Log of Boring 1**  
Oakland Chinatown Tanks  
Oakland, California

PLATE

**2**

DRAWN


JOB NUMBER  
9382,005.02

APPROVED  
*D. Smith*

DATE  
6/87

REVISED

DATE



**Harding Lawson Associates**  
 Engineers, Geologists  
 & Geophysicists

**Log of Boring 2**  
 Oakland Chinatown Tanks  
 Oakland, California

PLATE

**3**

DRAWN

JOB NUMBER  
 9382.005.02

APPROVED  
*D. Day*

DATE  
 6/87

REVISED

DATE

MAJOR DIVISIONS				TYPICAL NAMES	
COARSE - GRAINED SOILS MORE THAN HALF IS LARGER THAN NO. 200 SIEVE	GRAVELS  MORE THAN HALF COARSE FRACTION IS LARGER THAN NO. 4 SIEVE SIZE	CLEAN GRAVELS WITH LITTLE OR NO FINES	GW		WELL-GRADED GRAVELS, GRAVEL-SAND MIXTURES
			GP		POORLY GRADED GRAVELS, GRAVEL-SAND MIXTURES
		GRAVELS WITH OVER 12% FINES	GM		SILTY GRAVELS, POORLY GRADED GRAVEL-SAND-SILT MIXTURES
			GC		CLAYEY GRAVELS, POORLY GRADED GRAVEL-SAND-CLAY MIXTURES
	SANDS  MORE THAN HALF COARSE FRACTION IS SMALLER THAN NO. 4 SIEVE SIZE	CLEAN SANDS WITH LITTLE OR NO FINES	SW		WELL-GRADED SANDS, GRAVELLY SANDS
			SP		POORLY GRADED SANDS, GRAVELLY SANDS
		SANDS WITH OVER 12% FINES	SM		SILTY SANDS, POORLY GRADED SAND-SILT MIXTURES
			SC		CLAYEY SANDS, POORLY GRADED SAND-CLAY MIXTURES
FINE - GRAINED SOILS MORE THAN HALF IS SMALLER THAN NO. 200 SIEVE	SILTS AND CLAYS  LIQUID LIMIT 50% OR LESS	ML		INORGANIC SILTS AND VERY FINE SANDS, ROCK FLOUR, SILTY OR CLAYEY FINE SANDS, OR CLAYEY SILTS WITH SLIGHT PLASTICITY	
		CL		INORGANIC CLAYS OF LOW TO MEDIUM PLASTICITY, GRAVELLY CLAYS, SANDY CLAYS, SILTY CLAYS, LEAN CLAYS	
		OL		ORGANIC CLAYS AND ORGANIC SILTY CLAYS OF LOW PLASTICITY	
	SILTS AND CLAYS  LIQUID LIMIT GREATER THAN 50%	MH		INORGANIC SILTS, MICACEOUS OR DIATOMACEOUS FINE SANDY OR SILTY SOILS, ELASTIC SILTS	
		CH		INORGANIC CLAYS OF HIGH PLASTICITY, FAT CLAYS	
		OH		ORGANIC CLAYS OF MEDIUM TO HIGH PLASTICITY, ORGANIC SILTS	
	HIGHLY ORGANIC SOILS		Pt		PEAT AND OTHER HIGHLY ORGANIC SOILS

UNIFIED SOIL CLASSIFICATION SYSTEM

Perm	—	Permeability	Shear Strength (psf)	↓	↓	Confining Pressure	
Consol	—	Consolidation	TxUU	3200	(2500)	—	Unconsolidated Undrained Triaxial Shear (field moisture or saturated)
LL	—	Liquid Limit (%)	(FM) or (S)				
PI	—	Plastic Index (%)	TxCU	3200	(2500)	—	Consolidated Undrained Triaxial Shear (with or without pore pressure measurement)
G <sub>s</sub>	—	Specific Gravity	(P)				
MA	—	Particle Size Analysis	TxCD	3200	(2500)	—	Consolidated Drained Triaxial Shear
■	—	"Undisturbed" Sample	SSCU	3200	(2500)	—	Simple Shear Consolidated Undrained (with or without pore pressure measurement)
☒	—	Bulk or Classification Sample	(P)				
			SSCD	3200	(2500)	—	Simple Shear Consolidated Drained
			DSCD	2700	(2000)	—	Consolidated Drained Direct Shear
			UC	470		—	Unconfined Compression
			LVS	700		—	Laboratory Vane Shear

KEY TO TEST DATA



**Harding Lawson Associates**  
Engineers, Geologists  
& Geophysicists

Unified Soil Classification Chart  
Oakland Chinatown Tanks  
Oakland, California

PLATE

**4**

DRAWN  
MG


JOB NUMBER  
09382,005.02

APPROVED  
*D. J. H. /*

DATE  
6/87

REVISED

DATE



Top of PVC Casing  
Elevation —

- 8 IN. DIAMETER STEEL WELL HOUSING WITH LOCKING COVER
- WELL CAP
- SURFACE CONE
- 10 IN. DIAMETER BORING
- CEMENT/BENTONITE SANITARY SEAL
- 4 IN. DIAMETER SCHEDULE 40 PVC WELL CASING
- BENTONITE PELLET SEAL
- SAND FILTER PACK (size: Monterey # 3)
- 4 IN. DIAMETER SCHEDULE 40 PVC WELL SCREEN (0.20" slot size)
- SILT TRAP
- BOTTOM CAP

NOT TO SCALE



**Harding Lawson Associates**  
Engineers, Geologists  
& Geophysicists

**Well Construction Detail for  
Monitoring Well 1  
Oakland Chinatown Tanks  
Oakland, California**

PLATE

**5**

DRAWN

JOB NUMBER  
9382.005.02

APPROVED

*D. Gray*

DATE  
6/87

REVISED

DATE

LABORATORY REPORTS



# WESCO Laboratories

HARDING LAWSON  
JUN 12 1987

Date: June 11, 1987

Client Job/P.O. #: 9382,005.02

Client: Harding Lawson Associates

Date Collected: May 26, 1987

Submitted by: Dave Hochmuth

Date Submitted: May 27, 1987

Report to: Dave Hochmuth

# & Type of Samples: 4 soils

WESCO Job#: HLA8733-L

Site: Oakland Chinatown

page 1 of 1

Lab No.	Client ID	Benzene mg/kg	Toluene mg/kg	Xylene mg/kg	Gasoline mg/kg
7-8481	MW04	0.012	<0.001	<0.001	0.43
7-8482	Boo2	9.8	22	74	3700
7-8483	Boo3	1.6	5.5	42	2400
7-8484	Boo4	48	110	190	16000

METHOD(S)      Note 1      Note 1      Note 1      Note 1

NOTES: Note 1: EPA 5020/8020/8015

*Michael Webb*

Analytical supervisor





Date: June 15, 1987 Client Job/P.O. #: 9382,005.02  
 Client: Harding Lawson Associates Date Collected: May 28, 1987  
 Submitted by: Greg Sengelmann Date Submitted: May 28, 1987  
 Report to: Dave Hochmuth # & Type of Samples: 2 waters  
 WESCO Job#: HLA 8735-L, 2nd EDIT Site: Oakland Chinatown Tanks

page 1 of 1

Lab No.	Client ID	Gasoline mg/l	Benzene mg/l	Toluene mg/l	Xylene mg/l	Ethylbenzene mg/l
7-8496	8721-0101	66	4.9	6.8	6.1	<0.005
	METHOD(S)	Note 1	Note 2	Note 2	Note 2	Note 2

Lab No.	Client ID	1,2-DCA	Trichloro- ethylene mg/l	1,2-dichloro- propane mg/l	1,1,2-tri- chloroethane mg/l	chloro- benzene mg/l
7-8497	8721-0101	0.51	0.036	0.003	0.002	0.051
	METHOD(S)	Note 3	Note 3	Note 3	Note 3	Note 3

Lab No.	Client ID	2-chloro ethyl vinyl ether mg/l	All other EPA 601 Compounds mg/l	dibromoethane (EDB)* mg/l	Freon 113 mg/l
7-8497	8721-0101	<0.005	<0.001	0.18	<0.001
	METHOD(S)	Note 3	Note 3	Note 3	Note 3

NOTES: Note 1: EPA Methods 5020/8015  
 Note 2: EPA Method 602  
 Note 3: EPA Method 601  
 \*: Confirmed by liquid/liquid extraction; second column, GC/ECD

*M. L. Webb*  
 Analytical supervisor

DISTRIBUTION

4 copies: City of Oakland,  
Department of Public Works,  
One City Hall Plaza,  
Oakland, California 94612

Attention: Mr. Randy Lum, P.E.,  
Principal Civil Engineer

1 copy: Job File

1 copy: QC/Bound Report File

DPH/DGG/ljc/B0662-R

QUALITY CONTROL REVIEWER



David P. Hochmuth  
Civil Engineer

