

HAZMAT

94 OCT 31 AM 10:42

**SUMMARY OF SITE CONDITIONS
ELECTRO-COATINGS, INC. FACILITY
1401 AND 1421 PARK AVENUE
EMERYVILLE, CALIFORNIA**

Prepared for:

ELECTRO-COATINGS, INC.

Also Prepared On Behalf of:


1421 PARK AVENUE ASSOCIATES
per the request of Electro-Coatings, Inc.

Prepared by:

ENTRIX, Inc.
590 Ygnacio Valley Road, Suite 200
Walnut Creek, California 94596

Project No. 376402

October 28, 1994



Steven F. Michelson

California Registered Geologist, No. 5165




TABLE OF CONTENTS

	Page
1.0 Introduction.....	1-1
1.1 Objectives	1-2
1.2 Structure of this Report.....	1-2
2.0 Site Description and History	2-1
2.1 Site Description.....	2-1
2.2 History of Site Operations	2-1
2.3 History of Environmental Investigations	2-2
2.4 Municipal Setting	2-3
2.5 Hydrogeologic Setting.....	2-4
3.0 Soil and Groundwater Quality.....	3-1
3.1 Potential Sources.....	3-1
3.1.1 Chromium Waste Storage Area.....	3-1
3.1.2 Vapor Degreaser and Solvent Above Ground Storage Tank.....	3-2
3.1.3 Gasoline Underground Storage Tank	3-2
3.1.4 Background Groundwater Quality.....	3-2
3.2 Soil Quality	3-3
3.3 Groundwater Quality.....	3-4
3.3.1 Chromium in Groundwater	3-4
3.3.2 Other Metals in Groundwater.....	3-5
3.3.3 Chlorinated Hydrocarbons in Groundwater	3-6

3.4	Summary of Current Environmental Conditions	3-7
4.0	Potential for Exposure to Released Compounds	4-1
5.0	Recommendations for Action	5-1
5.1	Known and Potential Source Areas.....	5-1
5.2	Other Areas With Contaminants in Soil.....	5-2
5.3	Groundwater	5-2
6.0	Reference List.....	6-1

Appendix A. Tables

- Table 1. Well Summary.
- Table 2. Chromium in Soil.
- Table 3. Total Chromium in Shallow Groundwater.
- Table 4. Hexavalent Chromium in Shallow Groundwater.
- Table 5. Total Chromium in Deep Groundwater.
- Table 6. Hexavalent Chromium in Deep Groundwater.
- Table 7. Purgeable Halocarbons in Shallow Groundwater.
- Table 8. Purgeable Halocarbons in Deep Groundwater.

Appendix B. Figures

- Figure 1. Site Location Map.
- Figure 2. Base Map.
- Figure 3. Soil Boring Locations.
- Figure 4. Total Chromium Over Time.
- Figure 5. Total Chromium - January and October 1981.
- Figure 6. Total Chromium - October and November 1991.
- Figure 7. Trichloroethylene Over Time.
- Figure 8. Trichloroethylene - February 1985.
- Figure 9. Trichloroethylene - October and November 1991.

Appendix C. Boring Logs and Cross-Sections

In 1963, Electro-Coatings, Incorporated (ECI) purchased the assets of a metal plating facility at 1401 and 1421 Park Avenue, Emeryville, California (Figure 1). Prior to 1963, Industrial Hard Chrome Plating Corporation operated the metal plating facility at the 1401 and 1421 Park Avenue address.

This report is in response to the 26 August 1994 letter from the Regional Water Quality Control Board (RWQCB). This letter outlines six specific items for inclusion in a technical report:

1. Discussion of investigations completed to date and inclusion of all relevant data.
2. Work plan to define the vertical and lateral extent of chlorinated solvents and chromium in soil and groundwater.
3. Proposed interim remedial measures to prevent the migration of the plumes to adjacent sites.
4. Documentation of the removal of the underground storage tanks.
5. Proposed remedial action to be implemented at the site to prevent migration and impact of the plumes.
6. Determination of potential health risks posed by the presence of the contaminant plumes to on-site workers and to occupants of adjacent sites.

1.1 OBJECTIVES

The objective of this report is to identify reasonable remediation actions based on current site conditions, risk to human health and the environment, and current and future use of the property including the soil and groundwater. While this report is in response to requests from the RWQCB, ECI has an ongoing program to identify and evaluate reasonable and appropriate remediation alternatives.

1.2 STRUCTURE OF THIS REPORT

This report is organized to address each of the above items described in the 26 August 1994 letter from the RWQCB:

- Section 2 describes the site and history of operations, summarizes environmental actions to date, and briefly describes the regional setting.
- Section 3 describes potential sources of chemicals to soil and groundwater, data collected to date, and interprets current environmental conditions at the site.
- Section 4 discusses exposure pathways and potential risk, but this section is not a formal risk assessment.
- Section 5 recommends a plan of action to mitigate further contribution of chemicals to soil and groundwater.

2.1 SITE DESCRIPTION

The 1.0 acre Electro-Coatings, Inc. (ECI) facility consists of two parcels of property. Four buildings are located on the premises. The facility began operation in 1952 under the ownership of Industrial Hard Chrome Plating Corporation. In 1963 the business was purchased by ECI. One of the parcels is owned by ECI and one is leased. The buildings abuts property lines along its northern and eastern borders and is surrounded by parking and paved areas to the south and west.

The facility is bounded to the north by Park Avenue. To the east is a dirt alley with buried railroad tracks which is reportedly scheduled to be improved in order to extend Holden Street from Park Avenue to 40th Street. A lumber yard and parking area are south and immediately adjacent to the facility. About 140 feet further south is the Southern Pacific Railroad right of way which is being reconstructed as an extension of 40th Street. A clothing outlet and a crematorium are immediately adjacent to the west of the facility. About 80 feet further west is Horton Street.

2.2 HISTORY OF SITE OPERATIONS

Chrome plating operations began at the site in 1952 by Industrial Hard Chrome Plating Corporation. Electroless nickel plating began in the late 1950s. In 1963, ECI purchased the assets of the facility. ECI ceased hard chrome plating in 1989 and now only performs nickel plating. The remaining nickel plating operation is slated for relocation sometime in the near future. All plating operations have and continue to be performed in vats constructed above the ground surface. All nickel plating operations have been performed on the 1421 Park Avenue parcel and all chrome plating operations have been performed on the 1401 Park Avenue parcel.

Trichloroethylene (TCE) was used at the facility to vapor degrease metal parts prior to nickel plating. Trichloroethylene (TCE) was in use prior to purchase by ECI in 1963. TCE use was discontinued in 1973 and 1,1,1-trichloroethane (TCA) was substituted in the vapor degreaser. Vapor degreasing was discontinued in 1992. Today, metal degreasing is performed using a liquid alkaline soak process. All metal degreasing operations were performed in the southwest portion of the facility on the 1421 Park Avenue parcel.

2.3 HISTORY OF ENVIRONMENTAL INVESTIGATIONS

In 1977 the California Regional Water Quality Control Board issued a Cleanup and Abatement Order (No. 77-011) which required ECI to investigate groundwater contamination emanating from the site. In response, ECI conducted a well survey and installed seven monitoring wells (wells MW-1, MW-2, MW-3A, MW-3B, MW-3C, MW-4 and MW-5) in 1977. The seven wells were sampled and analyzed for total chromium and hexavalent chromium in August 1977.

In 1978 three additional monitor wells (MW-6, MW-7 and MW-8) were installed. In 1980 five more monitor wells (MW-9, MW-10, MW-11, MW-12 and MW-13) were installed. Soil samples were also collected for analysis from the borings for these wells. All 15 wells were sampled in 1981, some more than once, and analyzed for total and hexavalent chromium.

In 1982 five additional monitor wells (MW-14, MW-15, MW-16, MW-17 and MW-18) were installed and one soil boring (B1) was conducted. Soil samples were also collected from the boring for monitor well 14. No data are available from the reported boring B1. In 1983 four additional wells (MW-18A, MW-19, MW-20 and MW-21) were installed and two soil borings, 22 and 23 were performed. In 1985, eight more soil borings were drilled and sampled, borings 24 through 31. Also, in 1985, 15 of the 24 wells were sampled and analyzed for total and hexavalent chromium and halogenated volatile compounds. It was during this round of sampling that TCE was encountered in the groundwater.

In 1991, 21 of the 24 monitor wells were sampled. Three could not be located. Groundwater was analyzed for total chromium, hexavalent chromium and VOCs. Again

in 1991, and in 1994, selected wells were sample and analyzed for total chromium, hexavalent chromium, and VOCs.

Water sample analyses from all sampling events are summarized in Tables 3 through 8. Soil sample analyses are summarized in Table 2.

2.4 MUNICIPAL SETTING

The ECI facility is located in a highly industrialized area north of Interstate 580-Highway 24 and just east of Interstate 80. The facility is roughly 2,500 feet to the east of San Francisco Bay. The area was developed in early 1900s and various areas became industrialized beginning in the 1920s. The area is currently in transition.

On 7 September 1994, the City of Emeryville Zoning Ordinance Revision Committee conducted a public workshop as part of the City's effort to update the land use policies and design guidelines for the creation of a Revitalization Strategy/Zoning Overlay District for five blocks along Park Avenue. The ECI facility at 1401 and 1421 Park Avenue are included in this district.

Since 7 September, ECI has met with the City's Community Development staff, including the Redevelopment Director, Mr. Kofi Bonner. ECI has submitted copies of all existing technical reports describing environmental conditions to the City. The City has expressed the intent to preserve the character of this district while allowing new uses by non-industrial commercial businesses. Many buildings in the area have served their useful economic life for industry and are now in transition to other uses. The City wants to find ways to address the environmental issues so that development can occur without posing unacceptable risk to humans. Mr. Bonner is willing to meet with the County of Alameda Department of Health Services and the RWQCB and the property owners to discuss possible ways to address the environmental issues of this site as it is converted to non-industrial use.

2.5 HYDROGEOLOGIC SETTING

The site is generally underlain by clays and silty clays to roughly 15 feet. Between about 15 to 30 feet, the sediments become coarser, consisting of layers of sand and gravel with varying silt and clay content. This coarser zone comprises the water bearing unit and shallow aquifer. While variations exist at each boring location, the lithology and hydrogeology of the site can be generally described by the boring logs and cross-sections (Appendix C). Monitor well construction details are summarized in Table 1.

The shallow aquifer is semi-confined to confined, with a potentiometric surface roughly 6 to 9 feet below ground surface, and a hydraulic gradient to the west and northwest. An aquifer test performed in the aquifer yielded permeability of $28 \text{ feet}^3/\text{day}/\text{foot}^2$ (units can also be expressed as feet/day, which is not indicative of groundwater velocity). This permeability is typical for sand and gravel aquifers.

Three monitor wells (3A, 18A, 20) are constructed below the shallow aquifer. Underlying the shallow aquifer is an extensive blue clay with small lenses of sand and gravel. These three monitor wells are screened in deeper water bearing units and data from the deeper wells are not used to interpret conditions in the shallow aquifer. The potentiometric surface in the deeper wells 3A and 18A reveal a slight vertically downward hydraulic head, whereas, monitor well 20 shows an upward vertical head of about 3 feet above the shallow potentiometric surface. This upward head indicates that contaminants are not likely to migrate below the shallow aquifer under natural conditions.

3.1 POTENTIAL SOURCES

There are three identified potential sources of contaminants to soil and/or groundwater. The following generally describes each potential source. Other potential sources of compounds to soil at the facility include general operations and maintenance, but based upon the data, these activities are not considered at this time to be significant. Background or upgradient activities by others is the only other known general source of contaminants to groundwater beneath the ECI facility. The remainder of this section describes historical environmental data and site conditions as described by the most recent set of data.

3.1.1 CHROMIUM WASTE STORAGE AREA

The southeast corner of the facility directly behind the 1401 Park Avenue building is identified as the likely source of contaminants to soil and groundwater. It is labeled as "chromium waste storage area" on Figures 2 through 8. A concrete vault or tank was located there and it was reported leaking sometime in either 1974 or 1977, the record is unclear. In 1977, the storage area was completely reconstructed with double lined concrete and steel tank. The southeast corner of the facility directly behind the 1401 Park Avenue building is identified as the likely source of contaminant to soil and groundwater. It is labeled "chromium waste storage area" on Figures 2 through 8. The groundwater quality data (described below) indicate that elevated chromium concentrations probably emanated from this area. The chromium waste storage area is no longer used, nor available for use.

3.1.2 VAPOR DEGREASER AND SOLVENT ABOVE GROUND STORAGE TANK

Metal parts for nickel plating were degreased in an operation performed in the southwest corner of the facility. The vapor degreaser was located inside the southwest corner of the 1421 Park Avenue building and an above ground tank located outside the building was used to gravity feed the solvent to the degreaser. Until 1973, TCE was the solvent used in the vapor degreasing operation, at which time 1,1,1-TCA was substituted as the degreasing chemical. In 1992, vapor degreasing was discontinued at the facility. Although no leaks or spills are reported in the record, elevated levels of TCE, above background, may have emanated from this area, as this is the only known potential on-site source.

3.1.3 GASOLINE UNDERGROUND STORAGE TANK

A 500 gallon gasoline underground storage tank (UST) is reportedly located to the west of the building at 1421 Park Avenue. No investigation has been performed to date to either locate or assess the integrity of this UST.

3.1.4 BACKGROUND GROUNDWATER QUALITY

While this report does not detail current or historical industrial activities in the area upgradient from the ECI facility, the long term industrialization of this area is known. Groundwater quality in the region has been affected as a consequence of industrialization of the area that began in the early part of this century. Groundwater background, or upgradient, to the ECI facility is to the east, southeast, and northeast and is described by monitor wells MW-1, 2, 8, and 21 (see Figure 2 for locations).

These wells show that background groundwater contains detectable concentrations of chromium and various chlorinated solvents. Although no statistical evaluation of upgradient water quality has been performed, we estimate that upgradient shallow groundwater quality can be generally described as containing up to:

- 1 µg/l 1,1-DCE
- 800 µg/l trans 1,2-DCE

- 2 µg/l 1,1-DCA
- 110 µg/l TCA
- 70 µg/l chromium
- 100 (MW-8) to 2,200 (MW-21) µg/l TCE
- 250 (MW-21) µg/l PCE

It is noted that none of the ECI wells have been analyzed for petroleum products and there is no reported use of perchloroethylene (PCE) at the facility.

3.2 SOIL QUALITY

Soil samples have been analyzed from 15 soil borings shown in Figure 3. Table 2 summarizes the analytical results. Most of the borings were located south of the ECI building, some near the former chromium waste storage area. Borings 9 through 14 are associated with monitor wells with the same identification. Soil has been analyzed for total and hexavalent chromium, but not for solvents nor petroleum products. The data show that background levels of total chromium ranges from about 30 to 60 mg/kg; this is common for soils derived from the Franciscan complex of rocks comprising the San Francisco Bay Area. Hexavalent chromium is not considered an ambient form of chromium and was not detected in soil samples interpreted as representing background conditions.

Some of the soil borings extending 9 feet or more below ground surface (bgs) show an increase in total chromium with depth, notably borings 13, 27, 30, and 31. Because the potentiometric surface of the shallow groundwater is between 6 and 9 feet bgs, this increase probably results from chromium migrating in groundwater.

Soil borings 24 and 25 reveal levels of chromium greater than 1,000 mg/kg in near surface soils with background levels at depth. Because borings 24 and 25 are located east of the facility and off the property, it is not known if this chromium is attributable to ECI. The soil data show that chromium concentrations decrease to background levels by 9 feet bgs in boring 24, and by 6 feet bgs in boring 25, and that background concentrations are maintained to total sampling depth of 11.5 feet bgs. These data are not indicative of a source of chromium to groundwater.

In contrast, soil boring 22, located near the chromium waste storage area, shows that chromium concentrations attenuate to 482 mg/kg at 8.5 feet bgs, which is above background levels. The highest level of chromium in soil below 5 feet bgs, was contained in soil boring 23 at 980 mg/kg at 8 feet bgs. These data are indicative of a source area, which has been consistently described as located in the southeast corner of the facility. Other borings in this area also reveal chromium above background levels in some samples.

3.3 GROUNDWATER QUALITY

Groundwater samples have been collected at various times from 24 monitor wells installed by ECI on and off-site. Tables 3 through 8 summarize 17 years of analytical results beginning with monitor well installation in 1977 and continuing through 1994. Groundwater, when sampled, has been consistently analyzed for total chromium and hexavalent chromium. In 1977 and 1981, selected wells were also analyzed for the metals arsenic, iron, nickel, and zinc, and also pH. In 1985, 1991, and 1994 groundwater from most of the wells (fewer wells in 1994) was analyzed for purgeable halocarbons, with results tabulated for the more common chlorinated compounds 1,1-DCE, trans 1,2-DCE, 1,1-DCA, TCE, TCA, methylene chloride, and vinyl chloride. The analytical results for chromium and TCE are interpreted graphically in Figures 4 through 8.

3.3.1 CHROMIUM IN GROUNDWATER

Figure 4 plots the total chromium concentrations at each monitoring well location for the years 1981, 1985, 1991, and 1994. Figures 5 and 6 depict the distribution of total chromium in shallow groundwater in 1981 and 1991. Several wells recorded highest concentrations in 1985, but as suggested in an earlier technical summary report, it is possible that samples were not filtered in the field. Nonetheless, several important conditions can be interpreted from the data and figures:

- The magnitude, or highest concentrations of the chromium plume, is decreasing over time, from 880,000 µg/l at MW-5 in 1981 to 510,000 µg/l at MW-13 in 1991.

- The size of the chromium plume is increasing over time to the west to northwest and parallel with the direction of the groundwater gradient.
- The center, or most concentrated portion of the chromium plume, is migrating at a rate slower than the less concentrated portions of the plume.
- Significant contributions of chromium to groundwater stopped sometime ago, possibly before 1981) because the center, or most concentrated portions of the plume, is about 100 feet downgradient of the probable chromium source area in 1981 and 200 feet in 1991.
- The data support the source of chromium to groundwater as located near the southeast corner of the ECI building, based on a 10 feet/year migration of the plume center (comparing 1981 and 1991 figures).
- The plume and some background wells exceed drinking water criteria based upon the California maximum contaminant level (MCL) for chromium in drinking water level (is 50 µg/l).
- Groundwater below the shallow aquifer contains detectable, but much lower, levels of chromium. It appears that the 1,300 µg/l chromium detected in deep well 20 in 1983 may have been a consequence of drilling because groundwater from this well was non detect for chromium in 1985; MW-20 was installed in 1983.

3.3.2 OTHER METALS IN GROUNDWATER

Detectable levels of arsenic, iron, nickel, and zinc were found in some of the wells sampled and analyzed for these metals. Most of the detected concentrations were near the detection limit. The MCL for arsenic is 50 µg/l and for nickel is 100 µg/l. Primary MCLs have not been promulgated for iron and zinc, secondary drinking water standards are 300 µg/l and 5,000 µg/l, respectively. From the data, only MW-5 had iron and nickel above standards, and only MW-11 had arsenic above standards.

3.3.3 CHLORINATED HYDROCARBONS IN GROUNDWATER

Purgeable halocarbons, which includes chlorinated solvents, were analyzed in selected wells in 1985, 1991, and 1994. Tables 7 and 8 summarize these data. Figure 7 plots TCE concentrations at each location for the years 1985, 1991, and 1994. Figures 8 and 9 depict the distribution of TCE in shallow groundwater in 1985 and 1991.

ECI reports using only the solvents TCE and 1,1,1-TCA at the facility. These solvents were used to degrease metal parts prior to plating. It is recognized that vinyl chloride and some forms of DCE and DCA are degradation products of TCE and TCA, and that TCE (and possibly TCA) is a degradation product of PCE. Because all of these compounds have been detected in ECI wells that monitor upgradient groundwater (see section 3.1.4), ECI is not the only source of these compounds to groundwater. While PCE is also detected in ECI wells, it is highest in background wells MW-1 (221 $\mu\text{g/l}$) in the northeast corner and MW-21 (380 $\mu\text{g/l}$) beyond the southern property line. Because PCE has no documented use at this facility and because background wells contain the highest concentrations, ECI is not interpreted to be a source of PCE.

The data and figures do show concentrations of TCE and TCA and their related degradation products DCE and DCA and vinyl chloride, above background levels downgradient from the southwest corner of the facility. This area housed the vapor degreaser with an outside above ground storage tank used to gravity feed TCE and later TCA. Several important conditions can be interpreted from the data and figures:

- The size of the TCE plume is increasing with time to the west to northwest and parallel with the direction of the groundwater gradient.
- The magnitude, or highest concentrations of the TCE plume, appears to be increasing over time, however, this may be due to the center of plume not intercepted by wells in 1985.
- The data support the source of TCE and TCA to groundwater as located near the southwest corner of the facility.
- The California maximum contaminant level (MCL) for TCE, TCA, and PCE in drinking water is 5 $\mu\text{g/l}$, 200 $\mu\text{g/l}$, and 5 $\mu\text{g/l}$, respectively. The

plume and most background wells exceed drinking water criteria for TCE and PCE. Only wells MW-10 and MW-16 exceed the MCL for TCA.

- Groundwater below the shallow aquifer has only been analyzed from well 18A, which contained low levels of TCE and methylene chloride in 1985.

3.4 SUMMARY OF CURRENT ENVIRONMENTAL CONDITIONS

The most recent comprehensive set of data describing groundwater is from 1991. These data are graphically depicted for total chromium in Figure 6 and for TCE in Figure 9. Both figures show that the most concentrated portions of the plumes are still located almost entirely on the ECI property. The figures also show the plume to extend to the west and northwest, parallel with groundwater flow direction. Background levels for both total chromium and TCE appear to be reached about 100 to 200 feet beyond MW-6. Based on the limited 1994 data, chromium and TCE concentrations appear to be decreasing. The plume does not extend into any areas known to be a source of drinking water supply.

Data describing soil were collected from 1980 to 1985. Because operations at the facility have remained similar or have decreased over the last several years, the extent of soil with chromium and TCE is not expected to be much different than described by the existing data.

POTENTIAL FOR EXPOSURE TO RELEASED COMPOUNDS

The purpose of this section is to generally describe the potential for exposure to contaminants at the ECI facility, notably chromium and TCE. Routes of human exposure to contaminated soil include dermal absorption, inhalation of particulates, and incidental ingestion. Routes of human exposure to contaminated groundwater include dermal absorption, inhalation of volatiles and water droplets, and ingestion of contaminated water supplies. Some of the following discussion is based on the *Site Inspection Prioritization* report dated 20 September 1993 and generated by Bechtel for the U.S. Environmental Protection Agency for the purpose of assessing "the relative threat associated with actual or potential releases of hazardous substances at the site."

EXPOSURE TO SOIL

Currently, the site is covered by either buildings or pavement; and the surrounding area is similarly developed. The known or inferred locations of contaminated soil are either beneath buildings, beneath pavement, or beneath several feet of uncontaminated soil. Under current conditions, exposure of on-site workers or workers at adjacent sites to contaminated subsurface soils is unlikely.

The one exception is the chromium detected in shallow soil to the east along the buried railroad tracks (soil borings 24 and 25). Because of the reported planned construction in this area, ECI has notified Catellus Development of the presence of elevated levels of chromium found in soil borings in 1985.

EXPOSURE TO GROUNDWATER

The water bearing unit at the site begins at about 15 feet below ground surface. The only routes of exposure to this groundwater would be via supply wells or excavation. Surveys of groundwater supply wells have been performed by previous consultants to ECI and by Bechtel, the contractor for the EPA in 1993. None of these surveys revealed groundwater supply wells that would be potentially impacted by the plume emanating from the ECI

facility. Under current conditions, exposure of on-site workers or workers at adjacent sites to shallow groundwater is unlikely.

POTENTIAL FUTURE EXPOSURE SCENARIOS

There are potential future scenarios that may result in exposure to contaminated media. If subsurface soils containing concentrations of contaminants above background levels are excavated, potential exposure pathways may include dermal adsorption, inhalation of particulates, and incidental ingestion. If excavation continues into the groundwater, then potential exposures may include inhalation and dermal adsorption. Use of the groundwater as source of drinking water is unlikely because the EBMUD supplies drinking water to the Emeryville area by importing surface water from the Central Valley of California, over 100 miles to the east.

This sections provides recommendations for action in response to known or inferred conditions regarding chromium and TCE in soil and groundwater at the site. These recommendations should be further discussed and developed, and then prioritized based on perceived need, regulatory criteria and request, cost effectiveness, financial abilities of ECI, future use, and potential effects on the redevelopment plan now underway by the City of Emeryville. This section is intended to serve as an outline for a work plan to be further developed following discussions with the regulatory agencies.

5.1 KNOWN AND POTENTIAL SOURCE AREAS

There are three known or potential sources that should be considered for investigation and remediation. They are the chromium waste storage area, the vapor degreasing operation and TCE above ground storage tank, and the gasoline UST.

- The chromium waste storage area should be further investigated. Soil containing elevated levels of chromium should be removed. Contaminated soil can as appropriate, be subject to building integrity serve as a secondary and long term source of compounds to groundwater long after the primary source has been removed. A cleanup level for chromium in soil should be developed one te extent is known.
- The vapor degreasing area should be investigated. Soil with elevated levels of TCE, or other contaminants, should be remediated, as appropriate subject to building integrity. Contaminated soil can serve as a secondary and long term source of compounds to groundwater long after the primary source has been removed. A cleanup level for TCE and other chlorinated hydrocarbons should be developed once the extent is known.

- The gasoline UST should be located and records describing the UST should be located and reviewed. As appropriate, and presuming the UST is not slated for future use, the UST should be removed or abandoned in place by filling with concrete. Soil samples and UST closure should be performed consistent with the RWQCB and County guidelines.

5.2 OTHER AREAS WITH CONTAMINANTS IN SOIL

Only one other area exists with known concentrations of chromium above background that is not associated with a known or potential source area. This is the shallow soil east of the facility adjacent to the buried railroad tracks. While it is not clear if ECI activities are responsible for this chromium, ECI is aware of its existence. As described above, ECI has recently notified Catellus Development of the presence of elevated levels of chromium. We recommend that ECI confirm this notification in writing and receive notification that this issue is being appropriately addressed if and when road construction is contemplated.

5.3 GROUNDWATER

One complete round of groundwater samples should be collected from all monitor wells except 3C. MW-3C is screened in a zone already screened by immediately adjacent well MW-3B. Groundwater from these wells should be analyzed for total chromium and purgeable halocarbons. The samples for chromium should be filtered in the field to exclude artifacts introduced by suspended sediment. In addition, an attempt should be made to determine which previous groundwater samples were submitted filtered or unfiltered for analysis. The results of the recommended groundwater sampling should be evaluated along with previous data for the purpose of developing an annual groundwater sampling program. Annual sampling is considered adequate based on a 17 year history of data and the reasonably predictable behavior of the groundwater plume.

Groundwater remediation is not recommended at this time because:

- Groundwater is not a source of drinking water downgradient of the site.

- There are no actual beneficial uses being impacted by the groundwater plume.
- EBMUD supplies all water to Emeryville, and exposure to, and use of, the groundwater is unlikely.
- There is a regional groundwater contamination problem that should be approached comprehensively with costs allocated accordingly.
- The only identifiable probable use of the groundwater is as discharge to the bay. Concentrations of compounds at this point of discharge are not yet predicted, but based on current data and rates of contaminant attenuation, the discharged concentrations are likely to be much lower than those detected at the ECI facility.

REFERENCE LIST

Bechtel Environmental, Inc., Site Inspection Prioritization, September 20, 1993.

American Environmental Management Corporation, Groundwater Monitoring Report for Electro-Coatings, Inc., Emeryville, California, January 27, 1992, pp 1-4, 12-17, 19-22.

Kleinfelder, Inc., Data Summary Report, Electro-Coatings Facility, 1421 Park Avenue, Emeryville, California, April 25, 1991, Tables 1,3,5,7, Plates 2-9.

Poling, Kathleen U., Electro-Coatings, Inc., Letter to Susan Hugo, county of Alameda, Department of Environmental Health Hazardous Materials Division, August 31, 1994.

**Table 1
WELL SUMMARY**

Well No.	Date of Installation	Depth of Well (feet)	Depth To Water 5 November 1991 (feet)	TOC Elevation (feet)	Water Elevation 5 November 1991 (feet)	Screen Interval (feet)	Depth of Well Seal (feet)	Well Dia. / Slot Size (inch)	Remarks from 5 November 1991 survey
1	08/18/77	29	6.4	15.19	8.79	21-29	14	4/na	New locking well cap, removed tubing from well
2	08/18/77	21	na	na	na	14-21	13	1.5/na	Could not locate
3A	08/15/77	65	7.75	16.1	8.35	57-61	55	1.5/na	7" well cover installed
3B	08/15/77	18	7.1	16.3	9.2	16-18	15	1.5/na	7" well cover installed
3C	08/15/77	15 *	6.825	16.21	9.38	11-14	10	1.5/na	7" well cover installed
4	08/15/77	20.5	6.6	14.29	7.69	16-20	14.5	1.5/na	7" well cover installed
5	08/15/77	15	7.55	15.87	8.32	11-15	10	1.5/na	7" well cover installed
6	02/21/78	18	3.675	9.24	5.56	13-17	11	1.5/na	7" well cover installed, found tubing in well
7	02/21/78	18	na	na	na	10-13	9	1.5/na	Could not locate
8	03/13/78	22	6.575	16.42	9.84	16-22	14	na/na	7" well cover installed, extend casing, found tubing in well
9	12/12/80	24.5	7.1	16.03	8.93	17.5-24.5	15.5	4/na	12" well cover installed, new locking well cap - soil boring
10	12/18/80	24.5	7.15	15.1	7.95	17.5-24.5	17	4/na	12" well cover installed, new locking well cap - soil boring
11	12/19/80	29	6.7	15.94	9.24	16-29	14.5	6/na	New locking well cap - soil boring
12	12/22/80	28.5	6.85	16.04	9.19	17.5-28.5	14.5	4/na	New locking well cap
13	04/13/82	25	7.125	15.37	8.24	10.5-15.5	9.5	6/na	12" well cover installed, new locking well cap - soil boring
14	04/13/82	25	7.075	15.49	8.41	15-25	na	4/0.01	New locking well cap - soil boring
15	04/13/82	25	8.35	17.26	8.91	15-25	na	4/0.01	New locking well cap
16	04/13/82	22	4.8	12.08	7.28	12-22	na	4/0.01	New locking well cap
17	04/13/82	25	5.075	12.76	7.68	10-20	na	4/0.01	New locking well cap
18	04/13/82	25	5.375	13.57	8.19	15-25	na	4/0.01	New locking well cap, new well cover lid
18A	1983	51.5	6.5	13.36	6.86	35-50	35	4/0.02	Repair casing, new locking well cap
19	06/10/83	25	na	na	na	10-25	6	4/0.02	Could not locate
20	1983	53	3.55	14.93	11.38	31-51	28	4/0.02	Repair casing, new locking cap, grout inside casing
21	06/08/83	0.5	na	na	na	10-25	7	4/0.02	Could not locate

Notes: na = not available

Table 2
CHROMIUM IN SOIL

Boring Number	Approximate Sample Date	Sample Depth (feet)	Total Chromium (mg/Kg)	Hexavalent Chromium (mg/Kg)
9	12/12/80	6-7	31	-
10	12/16/80	3.5-4.5	29	-
		5-7.5	52	-
11	12/18/80	3	39	-
		5.5	35	-
13	12/22/80	3	48	-
		8	305	-
14	04/13/82	5	33	-
		10	48.8	-
		15	40.2	-
		20	46	-
22	06/08/83	4-4.5	5,200	-
		8-8.5	482	-
23	06/83	2-2.5	38.4	-
		7.5-8	980	-
24	01/09/85	2.0-2.5	6,700	< 0.2
		4.0-4.5	727	-
		6.0-6.5	432	91
		9.0-9.5	41.5	-
		11.0-11.5	41.5	-
25	01/05/85	2.0-2.5	2,030	< 0.2
		4.0-4.5	503	< 0.2
		6.0-6.5	40.9	-
		9.0-9.5	44.9	-
		11.0-11.5	42.9	-
26	01/09/85	4.0-4.5	48.2	< 0.2
		6.0-6.5	39.9	-
		9.0-9.5	45.1	-
		11.0-11.5	66.1	-
27	01/09/85	2.0-2.5	95.3	-
		4.0-4.5	78.2	-
		6.0-6.5	102	-
		9.0-9.5	250	1.6
		11.0-11.5	51.7	-
28	01/09/85	2.0-2.5	52.2	-
		4.0-4.5	434	< 0.2
		6.0-6.5	4934	-
		9.0-9.5	49.5	-
		11.0-11.5	24.1	-
29	01/09/85	2.0-2.4	55.6	0.4
		4.0-4.5	46	-
		6.0-6.5	36.9	-
		9.0-9.5	47.6	-
30	01/09/85	2.0-2.5	45	-
		4.0-4.5	48.5	-
		6.0-6.5	36.1	-
		9.0-9.5	57.9	-
		11.0-11.5	110	44
31	01/09/85	2.0-2.5	60.8	-
		4.0-4.5	45.2	-
		6.0-6.5	37	< 0.2
		9.0-9.5	130	-
		11.0-11.5	73.7	-

Notes: Soil borings 9 through 14 correspond to monitor well locations.
- = no data

Table 3
TOTAL CHROMIUM IN SHALLOW GROUNDWATER

Well Number	Aug-77 (ug/l)	Jan-81 (ug/l)	Jul-81 (ug/l)	Sep-81 (ug/l)	Oct-81 (ug/l)	Nov-81 (ug/l)	Dec-81 (ug/l)	Jun-83 (ug/l)	Feb-85 (ug/l)	Jun-91 (ug/l)	Oct-91 (ug/l)	Jul-94 (ug/l)
1	200	-	-	<1	1	2.5	32	-	<20	-	<50	-
2	60	-	-	<1	4	1.1	2	-	-	-	-	-
3B	60	-	-	<1	480	2,000	190	-	-	-	110,000	-
3C	18,000	-	-	30,000	28,000	22,000	17,000	-	7,250	-	2,300	-
	7,100											
4	90,000	-	-	57,000	61,000	56,000	55,000	-	59,000	17,000	22,000	-
5	360,000	-	-	-	880,000	610,000	280,000	-	480,000	390,000	260,000	-
6	-	-	-	630	80	790	630	-	3,330	-	31,000	-
7	-	-	-	<1	<1	-	3	-	-	-	-	-
8	-	-	-	<1	2	2.5	70	-	<20	-	<50	-
9	-	258,000	-	-	-	-	-	-	892,000	-	140,000	-
10	-	17,000	-	-	-	-	-	-	746,000	-	490,000	-
11	-	129,000*	340	-	-	-	-	-	2,440	-	470	-
12	-	32,000	-	-	-	-	-	-	240,000	38,000	44,000	-
13	-	381,000*	-	-	-	-	-	-	676,000	-	510,000	230,000
14	-	-	-	-	-	-	-	-	654,000	-	320,000	-
15	-	-	-	-	-	-	-	-	<20	30	<50	-
16	-	-	-	-	-	-	-	-	460,000	-	240,000	120,000
17	-	-	-	-	-	-	-	-	90,000	-	250,000	190,000
18	-	-	-	-	-	-	-	-	60,500	-	31,000	-
19	-	-	-	-	-	-	-	<20	20	-	-	-
21	-	-	-	-	-	-	-	20	40	-	-	-

Notes: October 1991 data also includes November 1991 data

* Data represents the average of 8 sequential samples collected hourly during a pumping test.

< 20 = less than detection limit

- = no data

Table 4
HEXAVALENT CHROMIUM IN SHALLOW GROUNDWATER

Well Number	Aug-77 (ug/l)	Jan-81 (ug/l)	Jul-81 (ug/l)	Sep-81 (ug/l)	Oct-81 (ug/l)	Nov-81 (ug/l)	Dec-81 (ug/l)	Jun-83 (ug/l)	Feb-85 (ug/l)	Jun-91 (ug/l)	Oct-91 (ug/l)	Jul-94 (ug/l)
1	-	-	-	-	-	-	-	-	<20	-	50	-
2	-	-	-	-	-	-	-	-	-	-	-	-
3B	-	-	-	-	-	-	-	-	-	-	100,000	-
3C	12,000	-	-	-	-	-	-	-	6,300	-	1,600	-
	6,700	-	-	-	-	-	-	-	-	-	-	-
4	67,000	-	-	-	-	-	-	-	59,000	17,800	22,000	6,300
5	295,000	-	-	-	2,240	-	-	-	480,000	-	250,000	454,000
6	-	-	-	-	-	-	-	-	3,300	-	25,000	4,800
7	-	-	-	-	-	-	-	-	-	-	-	-
8	-	-	-	-	-	-	-	-	<20	-	<10	-
9	-	185,000	-	-	-	-	-	-	877,000	-	130,000	-
10	-	14,000	-	-	-	-	-	-	740,000	-	450,000	-
11	-	115,500*	34	-	-	-	-	-	2,410	-	410	-
12	-	12,000	-	-	-	-	-	-	240,000	29,700	39,000	-
13	-	325,000	-	-	-	-	-	-	676,000	-	430,000	130,000
14	-	-	-	-	-	-	-	-	632,000	-	310,000	-
15	-	-	-	-	-	-	-	-	<20	-	<10	<10
16	-	-	-	-	-	-	-	-	460,000	-	290,000	320,000
17	-	-	-	-	-	-	-	-	38,200	-	300,000	200,000
18	-	-	-	-	-	-	-	-	55,000	-	24,000	-
19	-	-	-	-	-	-	-	<20	20	-	-	-
21	-	-	-	-	-	-	-	<20	<20	-	-	-

Notes: October 1991 data also includes November 1991 data

* Data represents the average of 8 sequential samples collected hourly during a pumping test.

< 20 = less than detection limit

- = no data

Table 5
TOTAL CHROMIUM IN DEEP GROUNDWATER

Well Number	Aug-77 (ug/l)	Jan-81 (ug/l)	Jul-81 (ug/l)	Sep-81 (ug/l)	Oct-81 (ug/l)	Nov-81 (ug/l)	Dec-81 (ug/l)	Jun-83 (ug/l)	Aug-83 (ug/l)	Feb-85 (ug/l)	Oct-91 (ug/l)	Jul-94 (ug/l)
3A	50	-	-	<1	<1	230	14	-	-	770	130	-
18A	-	-	-	-	-	-	-	20	-	<20	<50	-
20	-	-	-	-	-	-	-	1,300	90	<20	<50	-
								1,300				

Notes: October 1991 data also includes November 1991 data

* Data represents the average of 8 sequential samples collected hourly during a pumping test.

< 20 = less than detection limit

- = no data

Table 6
HEXAVALENT CHROMIUM IN DEEP GROUNDWATER

Well Number	Aug-77 (ug/l)	Jan-81 (ug/l)	Jul-81 (ug/l)	Sep-81 (ug/l)	Oct-81 (ug/l)	Nov-81 (ug/l)	Dec-81 (ug/l)	Jun-83 (ug/l)	Aug-83 (ug/l)	Feb-85 (ug/l)	Oct-91 (ug/l)	Jul-94 (ug/l)
3A	-	-	-	-	-	-	-	-	-	80	<500	-
18A	-	-	-	-	-	-	-	<20	-	<20	<10	-
20	-	-	-	-	-	-	-	1200	40	<20	14	-
								530				

Notes: October 1991 data also includes November 1991 data

* Data represents the average of 8 sequential samples collected hourly during a pumping test.

< 20 = less than detection limit

- = no data

Table 7
PURGEABLE HALOCARBONS IN SHALLOW GROUNDWATER

Well Number	Date	1,1-DCE (ug/l)	Trans 1,2-DCE (ug/l)	1,1-DCA (ug/l)	TCE (ug/l)	TCA (ug/l)	PCE (ug/l)	Methylen Chloride (ug/l)	Vinyl Chloride (ug/l)
1	3/21/85	<0.5	<0.5	<0.5	33	<0.5	21	<0.5	<0.5
	11/15/91	0.5	4.8	1.6	11	<0.5	0.6	<0.5	<1
2	NS	-	-	-	-	-	-	-	-
3B	10/29/91	13	45	1.2	650	<0.5	6.8	<0.5	6.4
3C	6/11/85	<0.5	23	<0.5	150	2.4	1.7	<0.5	<0.5
	10/29/91	61	46	5.4	180	34	1.7	<0.5	18
4	11/4/91	<5	260	<5	2,100	<5	31	<5	10
	7/28/94	-	-	-	6,500	-	-	-	-
5	11/4/91	4.2	120	42	410	1.3	8.9	<0.5	54
6	6/11/85	<5	54	<5	220	3.9	<5	<5	<5
	11/5/91	29	78	<0.5	420	6.4	5.9	<0.5	19
	7/28/94	-	-	-	790	-	-	-	-
8	6/10/85	<1	19	1	46	<1	18	<1	3
	6/11/85	1	32	1	93	<0.5	35	<5	-
	11/5/91	0.8	23	1.8	38	<0.5	35	<0.5	4.9
9	6/13/85	<5	31	<5	700	<5	26	<50	<5
	10/30/91	<0.5	13	1.3	200	<0.5	11	<0.5	<1
10	6/12/85	<50	<50	<50	5,100	<50	81	<20	<50
	6/12/85	<50	600	<50	12,000	<50	<50	<500	-
	11/7/91	3,800	640	<50	14,000	6,500	<50	<50	<100
11	6/12/85	<0.5	3.4	<0.5	19	1.3	5.3	7.6	<0.5
	11/15/91	<0.5	3.1	<0.5	10	<0.5	1.5	<0.5	<1
12	11/11/91	3.3	9	1.3	130	4.6	10	<1	<2
13	11/8/91	6.8	89	15	630	<5	8.9	<5	20
	7/28/94	-	-	-	770	-	-	-	-
14	3/21/85	<0.5	<0.5	<0.5	580	<0.5	26	<0.5	<0.5
	11/11/91	13	150	19	4,300	17	13	<5	30
15	6/13/85	<50	410	<50	1,200	<50	<50	<50	<50
	11/12/91	<5	220	<5	650	<5	<5	<5	<10
16	3/21/85	<0.5	<0.5	<0.5	360	<0.5	42	<0.5	<0.5
	11/19/91	1,200	2,200	<5	19,000	1300	<5	<5	420
	7/28/94	-	-	-	22,000	-	-	-	-
17	6/13/85	46	23	<5	200	22	18	<5	<5
	11/19/91	54	54	7.8	460	30	8.9	<5	420
	7/28/94	-	-	-	780	-	-	-	-
18	6/12/85	<0.5	140	<0.5	430	52	32	<0.5	<0.5
	6/12/85	<50	<50	<50	340	66	<50	<500	-
	11/19/91	<5	160	<5	560	23	11	<5	30
19	3/21/85	<0.5	<0.5	<0.5	91	<0.5	23	<0.5	<0.5
21	6/13/85	<50	800	<50	2,200	110	<50	380	<50

Notes: - = No data
<5 = Not detected above reported detection limit

**Table 8
PURGEABLE HALOCARBONS IN DEEP GROUNDWATER**

Well Number	Date	Trans		1,1-DCA (ug/l)	TCE (ug/l)	TCA (ug/l)	PCE (ug/l)	Methylen Chloride (ug/l)	Vinyl Chloride (ug/l)
		1,1-DCE (ug/l)	1,2-DCE (ug/l)						
3A	10/29/91	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<1
18A	6/13/85	<0.5	<0.5	<0.5	10	<0.5	<0.5	2.4	<0.5
	11/19/91	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<1
20	11/15/91	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<1

Notes: - = No data
 <5 = Not detected above reported detection limit





Figure 1. Site of Electro-Coatings, Inc.



LEGEND


- Fence or brick wall
- Buildings
- Property Line
- Monitoring Wells (found 1991)
- Monitoring Wells (not found 1991)




**Figure 2. Base Map
1401 and 1421 Park Avenue - Emeryville**

Electro-Coatings, Inc.

Emeryville, California

Project: 376403	Draftsperson: RBL	
File Name: ECBASE2.DWG	Approval: SM	
Creation Date: 10/10/94	Sheet 1 of 1	
Revision Date: 10/28/94		
Revision Level: 1.1		





LEGEND
 Monitoring Well
 Soil Boring
 Building

Note: Soil borings 9 through 14 correspond to monitor well locations. Refer to Figure 2 for other monitor well locations.

Figure 3. Soil Boring Locations
Site Plan Detail Southeast Property Corner

Electro-Coatings Inc.
 Emeryville, California


Project: 376401	Draftsperson: MJR	 WALNUT CREEK CALIFORNIA
File Name: ECISOILDWG	Approval: SM	
Creation Date: 10/20/94	Sheet 1 of 1	
Revision Date: 10/18/94		
Revision Level: 1.1		




**Figure 4. Total Chromium Over Time
1401 and 1421 Park Avenue - Emeryville**

Electro-Coatings, Inc.
Emeryville, California

Project: 376402	Draftsperson: RBL	
File Name: ECBASE2.DWG	Approval: SM	
Creation Date: 10/10/94	Sheet 1 of 1	
Revision Date: 10/28/94	Revision Level: 1.1	







- LEGEND**
- x—x—x— Fence or brick wall
 - ▭ Buildings
 - - - - - Property Line
 - 100,000— Concentration Contour (ug/l)
 - ⊕ Monitoring Wells (found 1991)
 - ⊙ Monitoring Wells (not found 1991)

**Figure 6. Total Chromium - October and November 1991
1401 and 1421 Park Avenue - Emeryville**

Electro-Coatings, Inc. Emeryville, California	Project: 378402	Draftsperson: RBL	
	File Name: ECBASE2.DWG	Approval: SM	
	Creation Date: 10/10/94	Sheet 1 of 1	
	Revision Date: 10/28/94	Revision Level: 1.1	



Approximate Groundwater Gradient




LEGEND

- x-x-x- Fence or brick wall
 - ▭ Buildings
 - - - - - Property Line
 - ⊕ Monitoring Wells (found 1991)
 - ⊙ Monitoring Wells (not found 1991)
- | | |
|------------|---------------------|
| 230 - 1985 | } Trichloroethylene |
| 420 - 1991 | |
| 790 - 1994 | |

Catellus LP-10
700 - 1990
100 - 1997
(Approximate location)

**Figure 7. Trichloroethylene Over Time
1401 and 1421 Park Avenue - Emeryville**

Electro-Coatings, Inc. Emeryville, California	Project: 378402	Draftsperson: RBL	
	File Name: ECBASE.DWG	Approval: SIM	
	Creation Date: 10/10/94	Sheet: 1 of 1	
	Revision Date: 10/28/94	Revision Level: 1.1	





Approximate
Groundwater Gradient

LEGEND

- x — x — x — Fence or brick wall
- ▬ Buildings
- - - - - Property Line
- - 1,000 - - Concentration Contour (ug/l)
- ⊕ Monitoring Wells (found 1991)
- ⊕ Monitoring Wells (not found 1991)


Figure 8. Trichloroethylene - February 1985		1401 and 1421 Park Avenue - Emeryville	
Electro-Coatings, Inc.		Project: 378402	Draftsperson: RBL
Emeryville, California		File Name: ECBASE2.DWG	Approval: SIM
		Creation Date: 10/10/84	Sheet 1 of 1
		Revision Date: 10/28/84	
		Revision Level: 11	





LEGEND

WELL 4 Monitoring well number



A A' Cross-section designation


DESCRIPTION OF UNITS

- Fill material
- Clay and Silty Clay - little or no coarse fraction
- Zones of increased coarse material (Sands, Gravels) within Clay or Silty Clay matrix
- Zones of increased fine material (Clays and Silts) within a Sand or Gravel matrix
- Clean Sands and Gravels - little or no fine fraction

NOTE


Contacts between units are approximate only and are based on general soil descriptions provided in boring logs (Appendix A)

SCALE




	CROSS-SECTION A-A'	PLATE 4
	Electro-Coolings, Inc 1401 Park Avenue Emeryville, California	
DRAFTED BY K King	DATE 04/18/91	PROJECT NO 10-2200-01
CHECKED BY J. Romie	DATE 04/18/91	

Approximate Depth Below Ground Surface (feet)








LEGEND

WELL 5 Monitoring well number



A A' Cross section designation


DESCRIPTION OF UNITS


-  Fill material
-  Clay and Silty Clay - little or no coarse fraction
-  Zones of increased coarse material (Sands, Gravels) within Clay or Silty Clay matrix
-  Zones of increased fine material (Clays and Silts) within a Sand or Gravel matrix
-  Clean Sands and Gravels - little or no fine fraction

NOTE

Contacts between units are approximate only and are based on general soil descriptions provided in boring logs (Appendix A)

SCALE




 KLEINFELDER	CROSS-SECTION B-B'		PLATE 5
	Electro-Coatings, Inc 1401 Park Avenue Emeryville, California		
DRAFTED BY: F. King	DATE: 04/18/91	PROJECT NO: 10-2200-01	
CHECKED BY: J. Romie	DATE: 04/18/91		

LEGEND

- ELECTRO-COATINGS, INC., PROPERTY LINE
- 1 WELLS INSTALLED BY PREVIOUS INVESTIGATORS
- ⊕ 20 WELLS INSTALLED BY KLEINFELDER AS OF 1985
- 2 WELLS INSTALLED BY PREVIOUS INVESTIGATORS THAT COULD NOT BE LOCATED AS OF FEBRUARY 1991
- ⊕ 19 WELLS INSTALLED BY KLEINFELDER THAT COULD NOT BE LOCATED AS OF FEBRUARY 1991
- B1 ○ SOIL BORING
- (5.90) GROUND WATER SURFACE ELEVATION (feet)
- - - 6.5 GROUND WATER SURFACE ELEVATION CONTOUR (feet)

NOTE: Ground water elevations are based on an arbitrary survey datum.





	INFERRED PIEZOMETRIC SURFACE CONTOUR MAP FOR SHALLOW WATER BEARING ZONE, JANUARY 1981	PLATE 6
	ELECTRO-COATINGS, INC. 1401 PARK AVENUE EMERYVILLE, CALIFORNIA	
DRAFTED BY: L. Sue/L. Latman DATE: 4-17-91 CHECKED BY: J. Romle DATE: 4-23-91	PROJECT NO. 10-2200-01	

LEGEND

- ELECTRO-COATINGS, INC., PROPERTY LINE
- 1 WELLS INSTALLED BY PREVIOUS INVESTIGATORS
- ⊕ 20 WELLS INSTALLED BY KLEINFELDER AS OF 1985
- 2 WELLS INSTALLED BY PREVIOUS INVESTIGATORS THAT COULD NOT BE LOCATED AS OF FEBRUARY 1991
- ⊕ 19 WELLS INSTALLED BY KLEINFELDER THAT COULD NOT BE LOCATED AS OF FEBRUARY 1991
- B1 ○ SOIL BORING
- (93.4) GROUND WATER SURFACE ELEVATION (feet)
- - - - 93.5 GROUND WATER SURFACE ELEVATION CONTOUR (feet)

NOTE: Ground water elevations are based on an arbitrary survey datum.



	<p>INFERRED PIEZOMETRIC SURFACE CONTOUR MAP FOR SHALLOW WATER BEARING ZONE, FEBRUARY 21, 1991</p> <p>ELECTRO-COATINGS, INC. 1401 PARK AVENUE EMERYVILLE, CALIFORNIA</p>	<p>PLATE</p> <p style="font-size: 2em; font-weight: bold;">9</p>
<p>DRAFTED BY: L. Sue/L. Latman DATE: 4-17-91</p> <p>CHECKED BY: J. Romie DATE: 4-23-91</p>	<p>PROJECT NO. 10-2200-01</p>	

Project: ELECTRO COATINGS INC.
Emeryville, California

LOG OF WELL NO. 1


Date Drilled: August 18, 1977

Remarks:

Type of Boring: 6" Auger

Hammer Weight: ---

(See Legend Sheet for sampler sizes and hammer weights)



Project: ELECTRO COATINGS INC.
Emeryville, California

LOG OF WELL NO. 2


Date Drilled: August 18, 1977

Remarks:

Type of Boring: 6" Auger

Hammer Weight: ---

(See Legend Sheet for sampler sizes and hammer weights)

Depth, Ft.	Samples	Blows/Ft.	MATERIAL DESCRIPTION	WELL INSTALLATION DETAILS
				
Surface Elevation:				
			SILTY CLAY (CL) (FILL) Dense, dry, light gray-brown, with trash	PROTECTIVE CAP
			SILTY CLAY (CL): Stiff, moist, mottled dark brown & black & green (FILL)	
			SILTY CLAY (CL) Stiff, moist, black	1 1/2" PVC CASING
			↓ Becomes grayish brown	
			9-8-77 SILTY CLAY (CL) Stiff, moist, mottled green and gray, with trace of fine sand and gravel	GROUT SEAL
			SILTY GRAVEL (GM): Dense, damp, brown	
			CLAYEY SILT: Dense, damp, mottled gray and brown, with clay lenses	SAND FILTER
			SILTY CLAY (CL): Stiff, moist, grayish brown, trace of fine sand and small gravel Trace of water	
			Trace to some gravel	BENTONITE SEAL
			CLAYEY GRAVEL (GC) Dense, moist, brown	
			VERY SILTY CLAY (CL) Stiff, moist, gray-brown, with sand pockets	PERFORATIONS
			CLAYEY GRAVEL: Dense, wet, brown	
			VERY SILTY CLAY (CL) Very stiff, moist, brown	2' FALL-IN CAP
			↓ BOTTOM OF HOLE @ 23'	

Project: ELECTRO COATINGS INC.
Emeryville, California

LOG OF WELL NO. 3A

Date Drilled: August 15, 1977

Remarks:

Type of Boring: 4 7/8" ϕ Rotary

Hammer Weight: ---

(See Legend Sheet for sampler sizes and hammer weights)

Depth, Ft.	Samples	Blows/Ft.	MATERIAL DESCRIPTION	WELL INSTALLATION DETAILS
			Surface Elevation:	
			6" ASPHALT CONCRETE	
			SANDY CLAY FILL Stiff, moist, brown, with bricks & blue clay	
			CLAYEY SAND FILL (SC-SP) Dense, moist, bluish green to brown	
			GRAVEL LAYER: Dense, gray, with clay binder	
5			SILTY CLAY (CL-CH) (FILL) Very stiff, moist, black	
			9-8-77 ∇ ↓ Becomes gray, with trace of gravel	
			↓ Becomes bluish gray	
10			SILTY CLAY (CL) Stiff, moist, blue-gray	
15			SILTY CLAY (CL) Very stiff, moist, mottled gray and brown, with rust streaks	
20			SAND AND GRAVEL (GW-SW) Dense, wet, brown, with trace of clay	
30			VERY SILTY CLAY (CL-ML): Medium stiff, very moist, blue, with trace of fine gravel ↓ --No gravel	
				<p>1 1/2" PVC CASING</p> <p>PROTECTIVE CAP</p> <p>GROUT SEAL</p>

Project: ELECTRO COATINGS INC.
Emeryville, California

LOG OF WELL NO. 3A
(Continued)

Depth, Ft.	Samples	Blows/Ft.	MATERIAL DESCRIPTION	WELL INSTALLATION DETAILS
35			<p>} Sand lense: black and blue</p>	<p>GROUT SEAL</p> <p>1 1/2" PVC CASING</p>
45			<p>VERY SILTY CLAY (CL-ML)</p> <p>Stiff, moist, gray, possibly with thin sand lenses</p>	<p>BENTONITE SEAL</p>
55			<p>SILTY CLAY (CL)</p> <p>Stiff, moist, brown</p>	<p>SAND FILTER</p> <p>PERFORATIONS</p>
60			<p>SILTY SAND & GRAVEL (GM-SH)</p> <p>Dense, wet, reddish brown, gravel to ± 1" diameter</p>	<p>SAND FILTER</p>
65			<p>SILTY CLAY (CL)</p> <p>Stiff, moist, reddish brown</p> <p>BOTTOM OF HOLE @ 65'</p>	<p>CAP</p>

Project: ELECTRO COATINGS INC.
Emeryville, California

LOG OF WELL NO. 3B

Date Drilled: August 15, 1977


Remarks:

Type of Boring: 6" Auger

Hammer Weight: ---

(See Legend Sheet for sampler sizes and hammer weights)

Depth, Ft.	Samples	Blows/Ft.	MATERIAL DESCRIPTION	WELL INSTALLATION DETAILS
Surface Elevation:				
			6" ASPHALT CONCRETE	
			SANDY CLAY FILL: Stiff, moist, brown, with bricks	
			CLAYEY SAND (SC-SP): Medium dense, very moist, blue-green to brown	
			Gravel lense, (FILL)	
5			SILTY CLAY (CL): Very stiff, moist, black	
			9-8-77 Becomes gray, with organic material	
			Becomes mottled blue-gray, with trace of fine gravel	
10			SILTY CLAY (CL) Medium stiff, moist, gray-brown, trace of fine gravel and sand	
			VERY SILTY CLAY (CL) Very stiff, moist, mottled gray and brown	
15			Trace of water at time of drilling	
			SAND AND GRAVEL (SW-GW) Dense, wet, dark brown, with trace of clay	
20			Sand and gravel	
			BOTTOM OF HOLE @ 20'	
25				
30				



Project: ELECTRO COATINGS INC.
Emeryville, California

LOG OF WELL NO. 3C

Date Drilled: August 15, 1977


Remarks:

Type of Boring: 4 7/8" ϕ Rotary

Hammer Weight: ---

(See Legend Sheet for sampler sizes and hammer weights)

Depth, Ft.	Samples	Blows/Ft.	MATERIAL DESCRIPTION	WELL INSTALLATION DETAILS
Surface Elevation:				
			6" ASPHALT CONCRETE	
			SANDY CLAY FILL: Stiff, moist, brown, with bricks	
			CLAYEY SAND FILL (SC-SP) Dense, moist, blue green to brown	
			CLAYEY GRAVEL: Dense, damp, brown, angular to 1 1/2" in diameter (FILL)	
5			after drilling SILTY CLAY (CL-CH) Very stiff, moist, black	
			9-8-77 ↓ Becomes grayish blue, with organics, trace of fine gravel and hard nodules	
10			SILTY CLAY (CL): Stiff, moist, mottled brown and blue-gray, with trace of organic materials	
			SILTY CLAY (CL): Very stiff, moist, gray and brown and black mottled, with trace of fine gravel & sand	
15			SILTY CLAY (CL): Very stiff, moist, mottled gray and brown --- Trace of water	
			BOTTOM OF HOLE @ 15'	
20				
25				
30				



Project: ELECTRO COATINGS INC.
Emeryville, California

LOG OF WELL NO. 4

Date Drilled: August 15, 1977


Remarks: _____

Type of Boring: 6" Auger

Hammer Weight: ---

(See Legend Sheet for sampler sizes and hommer weights)

Depth, Ft.	Samples	Blows/Ft.	MATERIAL DESCRIPTION	WELL INSTALLATION DETAILS
Surface Elevation:				
			3" ASPHALT CONCRETE	
			SILTY CLAY (CL) Very stiff, moist, black	
5			after drilling 16'-17' 9-8-77 Becomes gray Trace of gravel	
10			SILTY CLAY (CL) Very stiff, moist, gray-brown, with trace of gravel and sand	
15			} Water inflow, possibly gravelly layer	
20			VERY CLAYEY SILT (ML-CL) Medium dense, moist, brown	
			BOTTOM OF HOLE @ 20.5'	
25				
30				



Project: ELECTRO COATINGS INC.
Emeryville, California

LOG OF WELL NO. 5

Date Drilled: August 15, 1977

Remarks:

Type of Boring: 6" Auger

Hammer Weight: ---

(See Legend Sheet for sampler sizes and hammer weights)

Depth, Ft.	Samples	Blows/Ft.	MATERIAL DESCRIPTION	WELL INSTALLATION DETAILS
			Surface Elevation:	
			3" ASPHALT CONCRETE	
			CLAYEY GRAVEL (GC): Dense, moist, gray to reddish brown	
			SILTY CLAY (CL-CH)	
			Very stiff, moist, black	
			<div style="display: flex; align-items: center;"> <div style="margin-right: 10px;"> ∇ 9-8-77 </div> <div style="border-left: 1px solid black; padding-left: 5px;"> Becomes bluish light gray, with trace of fine gravel </div> </div>	
			SILTY CLAY (CL): Very stiff, moist, mottled gray & brown	
			SILTY CLAY (CL): Very stiff, moist, brown, trace of fine gravel and sand	
			CLAYEY GRAVEL (GC): Dense, wet, brown	
			SILTY CLAY: Very stiff, moist, gray-brown, with trace of fine gravel	
			BOTTOM OF HOLE @ 15'	

Project: ELECTRO COATINGS INC.
Emeryville, California

LOG OF WELL NO. 6


Date Drilled: February 21, 1978

Remarks:

Type of Boring: 6" Auger

Hammer Weight: ---

(See Legend Sheet for sampler sizes and hammer weights)



Project: ELECTRO COATINGS INC.
Emeryville, California

LOG OF WELL NO. 7

Date Drilled: February 21, 1978
 Size of Boring: 6" Auger
 Hammer Weight: ---

Remarks: _____
 (See Legend Sheet for sampler sizes and hammer weights)

Depth, Ft.	Samples	Blows/Ft.	MATERIAL DESCRIPTION	WELL INSTALLATION DETAILS
Surface Elevation: 9.58				
5	2/24/78		<p>SILTY CLAY (CL) Medium stiff to stiff, moist, dark gray to black</p> <p>Trace of fine gravel</p> <p>Becomes stiff, dark bluish gray, with trace of brown</p> <p>Trace of lime nodules, bluish gray</p>	
10			<p>SILTY CLAY (CL-CH): Stiff to very stiff, moist to wet, light green</p> <p>SILTY CLAY (CL): Very stiff, moist, green and brown, some gravel and sand</p> <p>More sand and gravel (GC-CL) seep in bottom of hole</p>	
15			<p>CLAYEY SAND AND GRAVEL (SC-GC) Medium dense, wet, brown, gravel to 1"</p> <p>SILTY CLAY (CL) Stiff to very stiff, brown, trace of fine gravel</p> <p>Becomes brown and gray mottled</p>	
20			<p>BOTTOM OF HOLE @ 18'</p>	
25				
30				

Project: ELECTRO COATINGS INC.
Emeryville, California

LOG OF WELL NO. 8



Date Drilled: March 13, 1978

Remarks:

Type of Boring: 6" Auger

Hammer Weight: ---

(See Legend Sheet for sampler sizes and hammer weights)

Depth, Ft.	Samples	Blows/Ft.	MATERIAL DESCRIPTION	WELL INSTALLATION DETAILS
				
Surface Elevation:				
			4" ASPHALT CONCRETE	
			5" AGGREGATE BASE	
			CLAYEY SAND & GRAVEL FILL (SC-GC): Loose, moist, black	
			SILTY CLAY (CL-CH) (FILL): Medium stiff, moist, black, trace of wood	
			CLAYEY TO SANDY SILT (ML) (FILL) Loose, wet, black, trace of wood	
5			SILTY CLAY (CL-CH): Stiff, moist, dark gray	
			Grades to grayish blue, trace of lime nodules	
			SILTY CLAY (CL)	
			Stiff to very stiff, wet, bluish green, trace of lime nodules	
			Trace of fine gravel	
10			Becomes more silty, brown interbedded with dark gray	
			SILTY CLAY (CL): Stiff to very stiff, moist, reddish brown and gray marbled	
			Trace of fine sand, slightly greenish	
			With some sand	
15			CLAYEY SAND & FINE GRAVEL (SC) Medium dense, wet, reddish brown	
			VERY SILTY CLAY (CL): Medium stiff, wet, brown, trace of sand and fine gravel	
			With thin clayey and silty fine and coarse sand layers	
20			VERY SILTY CLAY (CL): Stiff to very stiff, brown marbled with gray	
25				
30				

BOTTOM OF HOLE @ 22'

Project: ELECTRO COATINGS INC.
Emeryville, California

Log of Boring No. 9

Date Drilled: 12/10/80 to 12/12/80

Remarks:

Type of Boring: 4 5/8" Pitcher Core Barrel

Hammer Weight:

(See Legend Sheet for sampler types and hammer weights)

Depth, Ft.	Samples	Ft. recovered/ Ft. cored	MATERIAL DESCRIPTION	WELL INSTALLATION DETAILS				
				PROTECTIVE CAP				
Surface Elevation:								
1			8" ASPHALT			<p>4" PVC CAP</p> <p>5 7/8" BOREHOLE</p> <p>4" PVC CASING</p> <p>GROUT SEAL</p> <p>BENTONITE SEAL (APPROXIMATE)</p> <p>SAND (APPROXIMATE)</p>		
2			GRAVEL FILL angular fragments (up to 1"), reddish-brown					
3								
4			CLAY medium hard, very dark gray					
5			lost sample in hole					
6		0 1						
7		2.15 2.5	CLAY firm to stiff, mottled, trace of coarse sand, fine gravel grading more sandy and softer					12/29/80 } Water Levels 1/14/81 }
8			CLAYEY SAND trace fine gravel, light green					
9		1.5 1.5	CLAYEY SILT-SILTY CLAY soft, wet, gray					
10			GRAVELLY SILTY SAND green, orange mottling					
11		1.1 2.5	SILTY SANDY GRAVEL crumbly, moist, gravel is subangular-subrounded (maximum size of gravel is 1"), mottled, greenish-reddish brown					
12			core loss					
13		1.7 2.5	SAND fine-medium sand, trace gravel and clay, mottled, light brown to light green transitional					
14			SANDY SILTY CLAY soft, light brown to light green					
15		1.0 1.0	SANDY GRAVEL					

Project: ELECTRO COATINGS INC.
Emeryville, California

Log of Boring No. 9

(Continued)

Depth, Ft.	Samples	Ft. recovered/ Ft. cored	MATERIAL DESCRIPTION	WELL INSTALLATION DETAILS
16			subrounded gravel, crumbly more clayey	
17		2.1 2.5	SANDY CLAY firm, light brown to light green	
18			CLAYEY SAND trace of fine gravel, firm, slightly moist, in places sandy clay	
19			core loss	
20		1.3 2.5	SANDY CLAY fine sand, firm, slightly moist, light brown to light green, reddish-brown and brown mottling	
21			SILTY CLAY moderately stiff, light brown to light green core loss	
22		1.5 2.5		
23			core loss	
24			more sandy orange mottling more common	
25		1.7 2.5	trace gravel near base	
26			SILTY CLAY firm, common orange mottles, blue core loss	
27		1.7 2.5	angular fine gravel more predominant with minor sandy zones	
29		2.3 2.5	SANDY CLAY fine sand, trace gravel, orange mottling, bluish-gray	
31			extensive orange mottling	
32		2.2 2.5	grading more sandy	

Proj. No. 14929A


Woodward-Clyde Consultants

Figure 2b

Project: ELECTRO COATINGS INC.
Emeryville, California

Log of Boring No. 9

(Continued)

Depth, Ft.	Samples	Ft. recovered/ Ft. cored	MATERIAL DESCRIPTION	WELL INSTALLATION DETAILS
33			as above Bottom of boring @ 33.5 feet	 <p>DRILL CUTTINGS</p> <p>4 5/8" BOREHOLE</p>


Project: ELECTRO COATINGS INC.
Emeryville, California

Log of Boring No. 10

Date Drilled: 12/12/80 to 12/16/80
Type of Boring: 4 5/8" Pitcher Core Barrel

Remarks: _____
(See Legend Sheet for sampler types and hammer weights)

Hammer Weight: _____



Proj. No. 14929A

Woodward-Clyde Consultants

Figure 3a

Depth, Ft.	Samples	Ft. recovered/ Ft. cored	MATERIAL DESCRIPTION	WELL INSTALLATION DETAILS
16		1.8 2.0		<p>The diagram shows a vertical well casing. At the top, there is a 'BENTONITE SEAL' above a layer of 'SAND'. Below the sand is another 'BENTONITE SEAL'. The casing is surrounded by 'PEA GRAVEL'. At the bottom of the casing, there is a '4" PERFORATED PVC' section and a '4" PVC CAP'. 'DRILL CUTTINGS' are shown at the very bottom of the well. Arrows point from the labels to the corresponding parts of the well.</p>
17			CLAYEY SAND gravelly, firm, wet, olive-brown	
18		2.8 3.0		
19			SANDY SILTY CLAY firm, moist, orange mottling, greenish-brown	
20				
21		2.4 3.0		
22			grading more brown	
23			core loss	
24		2.9 3.0		
25			SILTY CLAY trace sand, firm, blue	
26			grading more clayey	
27		2.3 2.5		
28			orange mottling predominant at base of core	
29			SILTY SANDY CLAY firm, orange mottling, blue	
30		2.2 2.5		
31			grading to clayey fine sand	
31			SILTY CLAY firm, reddish-orange mottling, blue	
32			Bottom of boring @ 31.0 feet	

Project: ELECTRO COATINGS INC.
Emeryville, California

Log of Boring No.11

Date Drilled: 12/16/80 to 12/18/80

Remarks:

Type of Boring: 4 5/8" Pitcher Core Barrel

Hammer Weight:


(See Legend Sheet for sampler types and hammer weights)

MATERIAL DESCRIPTION

WELL INSTALLATION DETAILS

PROTECTIVE CAP

Surface Elevation:



Project: ELECTRO COATINGS INC.
Emeryville, California

Log of Boring No. 11

(Continued)

Depth, Ft.	Samples	Ft. recovered/ Ft. cored	MATERIAL DESCRIPTION	WELL INSTALLATION DETAILS
16			GRAVELLY CLAYEY SAND fine sand, poor to moderate sorting, moist to wet	<p>PEA GRAVEL</p> <p>1" PERFORATED PVC</p> <p>6" PRE-SLOTTED CASING</p> <p>6" PVC CAP</p> <p>DRILL CUTTINGS</p>
17		2.2 2.5	GRAVELLY SANDY CLAY firm, wet, bright orange mottling, light brown	
18			GRAVELLY SAND gravel up to 25mm across, predominantly medium to coarse sand, poor sorting, minor clay, wet, loose, permeable, dark brown	
19		1.3 2.5		
20				
21		0 1	core loss	
22		2.2 2.5	CLAYEY GRAVELLY SAND pebble to cobble sizes, fine to coarse sand, poorly sorted, wet, orange mottling throughout, tan brown to light brown	
23			less clay, loose	
24			as above, with less cobble-sized gravel, better sorting	
25		2.0 2.5	gravel constituents: sandstone, chert, milky quartz, basalt gravel is angular	
26			core loss	
27		1.3 2.5	as above, less clay, moderately sorted, saturated appearance clayey gravelly sand near top and bottom of interval	
28			core loss	
29			SILTY SANDY CLAY trace fine angular gravel, moist, orange-dark brown mottling, green to light brown	
30		1.8 2.5	minor gravel lense	
31			SANDY CLAY-CLAYEY SAND firm, slightly moist, gray to olive-brown	
32		2.5 2.5		

CONTINUOUS CORING

Proj. No. 14929A


Woodward-Clyde Consultants

Figure 4b

Project: ELECTRO COATINGS INC.
Emeryville, California

Log of Boring No. 11

(Continued)

Depth, Ft.	Samples	Ft. recovered/ Ft. cored	MATERIAL DESCRIPTION	WELL INSTALLATION DETAILS
33			SILTY CLAY trace sand, orange mottling, some fat clay, bluish-gray	
34			Bottom of boring @ 34 feet	DRILL CUTTINGS

Project: ELECTRO COATINGS INC.
Emeryville, California

Log of Boring No.12

Date Drilled: 12/18/80 to 12/19/80

Remarks:

Type of Boring: 8" Rotary

(See Legend Sheet for sampler types and hammer weights)

Hammer Weight:

Depth, Ft.	Samples	Ft. recovered/ Ft. cored	MATERIAL DESCRIPTION	WELL INSTALLATION DETAILS	
				PROTECTIVE CAP	
Surface Elevation:				<p>4" PVC CAP</p> <p>8" BOREHOLE</p> <p>4" PVC CASING</p> <p>GROUT SEAL</p> <p>BENTONITE SEAL</p> <p>SAND</p>	
6" ASPHALT					
1			FINE SAND brown to gray with angular chips of gray gravel		
2					
3			fragments of granite (?) (very rough drilling)		
4			SAND brown		
5			grading to SILTY CLAY black		
6			12/29/81 } Water Levels 1/14/81 }		
7			SILTY CLAY gray		
8					
9			SILTY CLAY buff brown to blue-gray grading more brown		
10					
11			SANDY SILTY CLAY trace coarse sand and angular gravel, tan brown		
12			grading less gravel		
13					
14					
15					

Project: ELECTRO COATINGS INC.
Emeryville, California

Log of Boring No. 12

(Continued)

Depth, f.t.	Samples	Ft. recovered/ Ft. cored	MATERIAL DESCRIPTION	WELL INSTALLATION DETAILS
16				
17			SAND AND GRAVEL coarse sand, fine gravel, brown to gray	
18				
19				
20				
21				
22				
23			grading coarser	PEA GRAVEL
24				
25				
26				
27				
28			SILTY CLAY trace of fine sand, tan-brown	FALL-IN
29				
30			Bottom of boring @ 30 feet	4" PERFORATED PVC
31				
32				4" PVC CAP

Figure 5b

Project: ELECTRO COATING INC.
Emeryville, California

Log of Boring No. 13


Date Drilled: 12/22/80

Remarks:

Type of Boring: 4 5/8" Pitcher Core Barrel

Hammer Weight:

(See Legend Sheet for sampler types and hammer weights)



Proj. No. 14929A

Woodward-Clyde Consultants

Figure 6

DEPTH IN FEET

DEPTH IN FEET	DRY DENSITY lb/ft ³	MOISTURE CONTENT % DRY WEIGHT	BLOW COUNT	SAMPLE	USCS	DESCRIPTION
0						6" asphalt.
1						
2						
3						
4						
5			5	00001		Blue-gray clay, stiff, few quartz pebbles.
6			8	00002		
			13			
7						
8						
9						
10			4	00003		Blue-gray clay
11			8	00004		Brown sandy-silty clay, few pebbles dry
12			12			
13						

J. H. KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING



ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA
 LOG OF BORING NO. B-1

PLATE

A-2


PREPARED BY: RJZ DATE: 5/10/82

CHECKED BY: DCM DATE: 5/10/82

PROJECT NO. B-1132-3

DEPTH IN FEET	DRY DENSITY 16/113	MOISTURE CONTENT % DRY WEIGHT	BLOW COUNT	SAMPLE	USCS	DESCRIPTION
14						
15			6			
16			9	00005		Tan-green sandy-silty clay, stiff, balling up on auger.
17			12	00006		
18						
19						
20			5			Gravelly clay with water bearing stringers, very wet, yellow water.
21			6	00007		
22			6	00008		Brown sandy clay, fat, moist, stiff.
23						
24						Blue clay.
25			7			
26			8	00009		Brown gravelly clay, saturated.
27			10	00010	*	Blue silty clay.
						Bottom of boring at 26½ ft.
						Hole abandoned.

* Assumed base of shallow groundwater.

J.H. KLEINFELDER & ASSOCIATES 
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA

LOG OF BORING NO. B-1 (CONT)

PLATE

A-2.1

PREPARED BY: RJZ DATE: 5/10/82

CHECKED BY: DCM DATE: 5/10/82

PROJECT NO. B-1132-3

DEPTH IN FEET

DEPTH IN FEET	DRY DENSITY lb/ft ³	MOISTURE CONTENT % DRY WEIGHT	BLOW COUNT	SAMPLE	USCS	DESCRIPTION
0						6" asphalt
1						
2						
3						
4						
5			5			
6			8	00011		Brown silty sandy clay, dry
7			12	00012		Dark gray clay with pebbles, fat.
8						
9						
10			6			
11			11	00013		Brown silty clay, fat, moist.
12			17	00014		Brown clayey gravel, wet, oxidized (Fe ₂ O ₃).
13						

J.H. KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING



ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA
 LOG OF BORING NO. 14

PLATE

A-3

PREPARED BY: RJZ DATE: 5/10/82


CHECKED BY: DCM DATE: 5/10/82

PROJECT NO. B-1132-3

DEPTH IN FEET

DEPTH IN FEET	DRY DENSITY 16/113	MOISTURE CONTENT & DRY WEIGHT	BLOW COUNT	SAMPLE	USCS	DESCRIPTION
14						
15			5			
16			5	00015		Brown silty clay, fairly dry.
17			6	00016		Mottled brown clay with extensive oxidation, fat, moist.
18						
19						
20			4			
21			5	00017		Brown clay with pebbles.
22			9	00018		Green-gray clay.
23						
24						
25			7			
26			10	00019		
27			12	00020	*	Blue clay
						Bottom of boring at 26½ ft. Well construction: 0-15', blank 4" PVC 15-25', perforated 4" PVC

* Assumed base of shallow groundwater.

J.H. KLEINFELDER & ASSOCIATES 
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA
 LOG OF BORING NO. 14 (CONT)

PLATE


A-3.1


PREPARED BY: RJZ DATE: 5/10/82

CHECKED BY: DCM DATE: 5/10/82

PROJECT NO. B-1132-3

DEPTH IN FEET

DEPTH IN FEET	DRY DENSITY lb/ft ³	MOISTURE CONTENT % DRY WEIGHT	BLOW COUNT	SAMPLE	USCS	DESCRIPTION
0						4" asphalt, brown fill, fine grain and white crystalline material.
1						
2						
3						
4						Black clay
5			5			
6			7			
7			10	00021		4/16/82 Black clay with wood fragments.
8						
9						
10			6			
11			9			
12			12	00022		Brown-gray clay with decayed organics, some iron stain, some pebbles, fat.
13						

J.H. KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING 

PREPARED BY: RJZ DATE: 5/10/82

CHECKED BY: DCM DATE: 5/10/82

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA

LOG OF BORING NO. 15


PROJECT NO. B-1132-3

PLATE

A-4


DEPTH IN FEET	DRY DENSITY 1b/fc3	MOISTURE CONTENT & DRY WEIGHT	BLOW COUNT	SAMPLE	USCS	DESCRIPTION
14						
15			5			
16			6			
16			11	00023		Brown sandy-gravelly clay, fat.
17						
18						Light brown sandy clay, saturated.
19						
20			11			
21			14			
21			27	00024		Brown sandy gravel, saturated.
22						
23						
24						
25			9			
26			10			
26			14	00025	*	Brown clayey gravel, blue clay.
27						Bottom of boring at 26½ ft. Well construction: 0-15', blank 4" PVC 15-25', perforated 4" PVC

* Assumed base of shallow groundwater.

JH KLEINFELDER & ASSOCIATES GEOTECHNICAL CONSULTANTS • MATERIALS TESTING		ELECTRO-COATINGS INC. EMERYVILLE, CALIFORNIA	PLATE A-4.1
		LOG OF BORING NO. 15 (CONT)	
PREPARED BY: RJZ DATE: 5/10/82		PROJECT NO. B-1132-3	
CHECKED BY: DCM DATE: 5/10/82			

DEPTH IN FEET

DEPTH IN FEET	DRY DENSITY lb/ft ³	MOISTURE CONTENT % DRY WEIGHT	BLOW COUNT	SAMPLE	USES	DESCRIPTION
0						8" asphalt.
1						
2						
3						
4					▼ ▼	4/16/82 5/3/82
5						
6			3			
7			7			
8			10	00026		Gray clay with roots, fat.
9						
10			4			
11			8			
12			12	00027		Augers wet, brown pebbly clay, moist.
13						

J.H. KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING 

PREPARED BY: RJZ DATE: 5/10/82
 CHECKED BY: DCM DATE: 5/10/82

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA
 LOG OF BORING NO. 16


PROJECT NO. B-1132-3

PLATE
A-5

DEPTH IN FEET

DEPTH IN FEET	DRY DENSITY lb/ft ³	MOISTURE CONTENT % DRY WEIGHT	BLOW COUNT	SAMPLE	USCS	DESCRIPTION
14						
15			4			
16			5			
16			6	00028		Brown silty clay, saturated, yellow water.
17						
18						
19						
20			4			
21			7			
21			10	00029		Brown clay, fat.
22						
23						
24						
25			7			
26			9			
26			13	00030	*	Blue clay
27						Bottom of boring at 26½ ft. Well construction: 0-12', blank 4" PVC 12-22', perforated 4" PVC

* Assumed base of shallow groundwater.

J.H. KLEINFELDER & ASSOCIATES 
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING

PREPARED BY: RJZ DATE: 5/10/82

CHECKED BY: DCM DATE: 5/10/82

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA

LOG OF BORING NO. 16 (CONT)

PROJECT NO. B-1132-3

PLATE

A-5.1

DEPTH IN FEET

DEPTH IN FEET	DRY DENSITY lb/ft ³	MOISTURE CONTENT % DRY WEIGHT	BLOW COUNT	SAMPLE	USCS	DESCRIPTION
0						Asphalt
1						
2						
3					▼	4/16/82
4					▼	Static water level after drilling 10 ft - also on 5/3/82.
5			4			
6			6			
7			11	00031		Blue-green clay with sand and pebbles, fat
8						
9						
10			4			
11			5			
12			10	00032		Brown clay, saturated
13						

J.H. KLEINFELDER & ASSOCIATES 
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA
 LOG OF BORING NO. 17

PLATE

A-6


PREPARED BY: RJZ DATE: 5/10/82

CHECKED BY: DCM DATE: 5/10/82

PROJECT NO. B-1132-3

DEPTH IN FEET	DRY DENSITY lb/ft ³	MOISTURE CONTENT & DRY WEIGHT	BLOW COUNT	SAMPLE	USCS	DESCRIPTION
14						
15			6			
			9			
16			13	00033		Brown gravelly clay, iron stain.
17						
18						
19						
20			3			
			5			
21			8	00034		Brown silty clay
22						
23						
24						
25			6			
			10			
26			13	00035	*	Blue clay
27						Bottom of boring at 26½ ft. Well construction: 0-10', blank 4" PVC 10-20', perforated 4" PVC 20-25', blank 4" PVC

* Assumed base of shallow groundwater.

J.H. KLEINFELDER & ASSOCIATES GEOTECHNICAL CONSULTANTS • MATERIALS TESTING		ELECTRO-COATINGS INC. EMERYVILLE, CALIFORNIA	PLATE A-6.1
		LOG OF BORING NO. 17 (CONT)	
PREPARED BY: RJZ DATE: 5/10/82		PROJECT NO. B-1132-3	
CHECKED BY: DCM DATE: 5/10/82			

DEPTH IN FEET

BLOW COUNT	SAMPLE	USCS	DESCRIPTION	WELL CONST.
0			Asphalt	
		Fill	Subbase - gravel and sand	
2		CL/ CH	SILTY CLAY - black, moist, plastic, some sand	
4				
6		CL	GRAVELLY CLAY - bluish green, grey, moist, stiff	
8				
10		CL/ GC	SANDY GRAVELLY CLAY/CLAYEY GRAVEL - brown, moist	
12				
14				
16				
18				
20		CL	SILTY CLAY - brown, wet, soft	
22				
24				
26		CL	SILTY CLAY - mottled blue gray, brown, wet, plastic, moderately stiff	
28				

(1) 16" diameter hole drilled to 27', 10" casing set and annulus backfilled with bentonite/cement grout that was tremied in place.

JH KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING



ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA

LOG OF BORING NO. 18A

PLATE


7

PREPARED BY: AP DATE: 7/83

CHECKED BY: MLS DATE: 7/83

PROJECT NO. B-1132-4

DEPTH IN FEET	BLOW COUNT	SAMPLE	USES	DESCRIPTION	WELL CONDT.
28			CL	Silty clay as before	
30	53	1 2	SC	CLAYEY SAND - brown, blue gray, wet, dense, clay approx. 35%, silt approx. 10%, some fine gravel	
32			ML	SILT - blue gray, mottled brown, wet, moderately stiff, non-plastic, some clay increasing with depth	
34				grading into	
36	22	3 4			
38			CL	SILTY CLAY - blue gray, wet, very stiff, some sand and gravel	
40	53	5 6			
42			SM	SILTY SAND - flowing sands 3 feet of heave up auger	
44			CL	SILTY CLAY - light olive gray, wet, stiff, slightly plastic to plastic, some high silt content zones	
46					
48					
50	25	7 8			
52				Total depth of boring = 51.5 feet Logged by M. L. Siembieda	
54					

J H KLEINFELDER & ASSOCIATES 
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA

PLATE

LOG OF BORING NO. 18A

7A

PREPARED BY: AP DATE: 7/83

CHECKED BY: MLS DATE: 7/83

PROJECT NO. B-1132-4

DEPTH IN FEET

	DRY DENSITY lb/ft ³	MOISTURE CONTENT & DRY WEIGHT	BLOW COUNT	SAMPLE	USES	DESCRIPTION
28						
29						
30			4	00039		Brown clay.
31			12			
			26	00040		Brown clayey sand, dry.
32						Bottom of boring at 31½ ft.
33						Well construction: 0-15', blank 4" PVC 15-25', perforated 4" PVC
34						
35						
36						
37						
38						
39						
40						
41						

J.H. KLEINFELDER & ASSOCIATES 
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA
 LOG OF BORING NO. 18 (CONT)

PLATE

A-7.2

PREPARED BY: RJZ DATE: 5/10/82

CHECKED BY: DCM DATE: 5/10/82

PROJECT NO. B-1132-3

DEPTH IN FEET

DEPTH IN FEET	DRY DENSITY lb/ft ³	MOISTURE CONTENT & DRY WEIGHT	BLOW COUNT	SAMPLE	USCS	DESCRIPTION
0						Asphalt
1						
2						Gray silty clay.
3					▼	4/16/82
4					▼	5/3/82
5			3			
			7			
6			10	*		Black clay.
7						Brown clay.
8						
9						
10			10			Water on outside of Porter sampler.
			14			
11			19	*		Brown sandy clay, some iron stain, saturated.
12						
13						

J.H. KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING



ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA
 LOG OF BORING NO. 18

PLATE

A-7

PREPARED BY: RJZ DATE: 5/10/82

CHECKED BY: DCM DATE: 5/10/82

PROJECT NO. B-1132-3

DEPTH IN FEET

	DRY DENSITY lb/ft ³	MOISTURE CONTENT % DRY WEIGHT	BLOW COUNT	SAMPLE	USCS	DESCRIPTION
14						
15			8			
			16			
16			19	D0036		Brown sandy gravelly clay, fat, saturated.
17						
18						
19						Brown gravelly clay.
20			4			
			6			
21			8	D0037		Brown clay, saturated.
22						
23						
24						
25			4			
			6			
26			8	D0038		Brown clay, soft, plastic, wet.
27						

J.H. KLEINFELDER & ASSOCIATES 
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA
 LOG OF BORING NO. 18 (CONT)

PLATE

A-7.1

PREPARED BY: RJZ DATE: 5/10/82

CHECKED BY: DCM DATE: 5/10/82

PROJECT NO. B-1132-3

DEPTH IN FEET	BLOW COUNT	SAMPLE	USCS	DESCRIPTION	WELL CONST.
	0				Asphalt
			Fill	Subbase - sand & gravel	
2			CL	SILTY CLAY - black, moist, plastic, stiff	
4					
6	22	1 2		becoming very dark gray	
8					
10	17	3	SC	CLAYEY SAND - brown, saturated, moderately dense, well graded, some fine gravel, appreciable amount of fines	
12			CH	SILTY CLAY - brown, wet, stiff, highly plastic	
14			CL	SILTY CLAY - brownish gray, mottled brown, wet, moderately stiff, moderately plastic, trace sand and gravel, silt content approx. 30%	
16	15	4 5			
18					
20	13	6 7		sand and gravel increase	
22					
24				grading into	
26	17	8 9	CL	SILTY CLAY - bluish gray, gray, wet, plastic to slightly plastic, stiff	
28				Bottom of boring @ 26.5 ft. Logged by M. L. Siembieda 6/10/83	

J H KLEINFELDER & ASSOCIATES 
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA

PLATE

8

LOG OF BORING NO. 19

PREPARED BY: AP DATE: 7/83


CHECKED BY: MLS DATE: 7/83

PROJECT NO. B-1132-4

DEPTH IN FEET

BLOW COUNT	SAMPLE	USCS	DESCRIPTION	WELL CONST.
0			Asphalt	
2		CL	SILTY CLAY - black, moist, firm, plastic, some sand	
4				
6			Some wood material	
8		CL/ GC	GRAVELLY CLAY/CLAYEY GRAVEL - brown, moist, sandy, stiff	
10				
12				
14			Clay increasing	
16		CL	SILTY CLAY - grayish brown, stiff, plastic	
18				
20				
22				
24		CL	SILTY CLAY - bluish gray, mottled brown, wet, plastic, moderately stiff, high silt content (30-40%)	
26				
28				

(1) 16" diameter hole drilled to 26.5 feet, 10 foot casing set & annulus backfilled with bentonite/cement grout that was tremied in place.

J H KLEINFELDER & ASSOCIATES 
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA

LOG OF BORING NO. 20

PLATE

9

PREPARED BY: AP DATE: 7/83


CHECKED BY: MLS DATE: 7/83

PROJECT NO. B-1132-4

DEPTH IN FEET	BLOW COUNT	SAMPLE	USCS	DESCRIPTION	WELL CONST.
28			CL	Silty clay as before	
30		1			
32	25	2			
34					
36	21	3		Silt decreases to 20-10%, highly plastic	
38		4			
40					
42	35	5	SC	CLAYEY SANDS - brown, saturated, dense, well graded, fines approx. 20%, gravel to 1/2" max., mostly angular	
44		6			
46	19	7			
48			CL	GRAVELLY CLAY - gray, wet, stiff, plastic, gravel approx. 20% fine, well rounded	
50		8			
52	19	9			
54		10	SC	CLAYEY SAND - brown, saturated, moderately dense, high clay %, fine grained	
56			SP	Grading into SAND - brown, saturated, loose, poorly graded, medium grained, little fines	
58	19	11			
60		12	CL	GRAVELLY CLAY - dark gray, stiff, plastic, silty, gravel approx. 20%	
62					-1-
64		13			
66	30	14			


Bottom of boring @ 56.5 feet
 Logged by M.L. Siembieda

(1) 3.5 feet of slough in hole.

J.H. KLEINFELDER & ASSOCIATES <small>GEOTECHNICAL CONSULTANTS & MATERIALS TESTING</small> 	ELECTRO-COATINGS INC. EMERYVILLE, CALIFORNIA	PLATE 9A
	LOG OF BORING NO. 20	
PREPARED BY: AP DATE: 7/83	PROJECT NO. B-1132-4	
CHECKED BY: MLS DATE: 7/83		

DEPTH IN FEET	BLOW COUNT	SAMPLE	USCS	DESCRIPTION	WELL CONST.
0			Fill	Railroad Roadbed - sand, gravel and silt, loose, dry	
2					
4					
6	16	1	CH	SILTY CLAY - gray, moist, firm, highly plastic	
8					
10					
12	22	2	GW	SANDY GRAVEL - brown, saturated, dense, well graded, little fines, approx. 10%, gravel 1/2" max.	
14					
16	11	3	CL	SILTY CLAY - greenish gray, wet, plastic, stiff, high silt content, approx 35%	
18					
20					
22	44	4 5	GC	CLAYEY GRAVEL - brown, saturated, dense, well graded, gravel to 1" max.	
24					
26	24	6 7	CL	SILTY CLAY - olive gray, bluish gray, stiff, wet, plastic, few gravel	
28				Bottom of boring @ 26.5 feet Logged by M.L. Siembieda 6/8/83	

J H KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING



PREPARED BY: AP DATE: 7/83
 CHECKED BY: MLS DATE: 7/83

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA

LOG OF BORING NO. 21


PROJECT NO. B-1132-4

PLATE

10

DEPTH IN FEET

BLOW COUNT	SAMPLE	USES	DESCRIPTION	WELL CONST.
0			Asphalt	
2	14	1 2	CL SANDY SILTY CLAY (Fill) - blue gray, moist, slightly plastic, firm, sand approx. 35%	
4	18	3 4	GC CLAYEY GRAVEL (Fill) - black, dark greenish gray, brown, wet, wide range of materials	
6	16	*	CL SILTY CLAY - very dark gray, moist, stiff, plastic, sand 5-10% - sand increases, mottled color, irridescence - few gravel	
8	23	5 6	ML/CL SILTY CLAY - yellowish brown, moist, slightly plastic, firm, some fine sand & gravel	
10	12	7 8	CL Silt decreases - light yellowish gray, brown mottling, moderately plastic	
12			Bottom of boring 11.5 ft. Logged by M.L. Siembieda 6/8/83	
14				
16				
18				
20				
22				
24				
26				
28				

J H KLEINFELDER & ASSOCIATES 
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA
 LOG OF BORING NO. 22

PLATE
 11


PREPARED BY: AP DATE: 7/83

CHECKED BY: MLS DATE: 7/83

PROJECT NO. B-1132-4

DEPTH IN FEET

BLOW COUNT	SAMPLE	USCS	DESCRIPTION	WELL CONST.
0			Asphalt	
		Fill	Subbase - sand and gravel	
2	16	CL	SILTY CLAY - black, moist, stiff, plastic, trace fine sand	
4	15		- some sandy zones - at 4.5' wood	
8	18	CL	SILTY CLAY - greenish, bluish gray, moist, stiff, plastic, trace fine sand, some brown mottling	
10	19	ML	CLAYEY SILT - light olive gray, moist, stiff	
12			Bottom of boring @ 11.5 ft. Logged by M.L. Siembieda	
14				
16				
18				
20				
22				
24				
26				
28				

J H KLEINFELDER & ASSOCIATES 
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA

LOG OF BORING NO. 23

PLATE

12

PREPARED BY AP DATE: 7/83

CHECKED BY MLS DATE: 7/83

PROJECT NO. B-1132-4

Depth in feet

Blow/ Ft.	Sample No.	USCS	DESCRIPTION	WELL CONST
0				
1				
2	70	GM	SILTY GRAVEL -Brown -dry -serpentine gravels, angular to 2" diameter(fill) -very hard	
3	S-2.0 A24			
4		ML	CLAYEY SILT -Black -moist -stiff -medium permeability -low plasticity	
5	17		Serpentine gravels, angular to 1" diameter	
6				
7	24	CH	CLAY -Dark gray to olive gray -moist -stiff -low permeability -high plasticity	
8	S-6.0 A24			
9				
10	34	CL	SILTY CLAY -Blue/green with some brown mottles -moist -some silt -very stiff -low permeability -medium plasticity	
11	S-9.0 A24			
12	25		-some root holes	
13	S-11.0 A24			
14			NFWE TD of Boring 11.5' Logged by Mark Klaver 1/9/85	
15				

J H KLEINFELDER & ASSOCIATES 
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING

ELECTRO - COATINGS
 EMERYVILLE, CALIFORNIA
LOG OF BORING NO. 24

PROJECT NO.: B-1132-5

PLATE

Depth In Feet	Blow/ Ft.	Sample No.	USCS	DESCRIPTION	WELL CONST
0				Concrete	
1			CL	SILTY CLAY -Black -moist -hard	
2	44	S-2.0 A25		-trace subrounded gravels to 2" dia (fill) -trace fine sand (oxidized mottles) -low plasticity -medium permeability	
3			CL	CLAY -Black -moist -hard	
4	42	S-4.0 A25		-low permeability -high plasticity	
5			CL	CLAY -Dark gray -moist -firm	
6	20	S-6.0 A25		-Trace gravels subrounded to 1.5" diameter -low permeability -medium plasticity	
7					
8					
9	26	S-9.0 A25		SILTY CLAY -Blue/green w light brown mottling -moist -very firm -low permeability -medium plasticity	
10					
11	18	S-11.0 A25			
12				TD of boring 11.5' NFWE Logged by Mark Klaver 1/9/85	
13					
14					
15					

J. H. KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING



ELECTRO - COATINGS
 EMERYVILLE, CALIFORNIA
 LOG OF BORING NO. 25

PROJECT NO. B-1132-5

PLATE

Depth In Feet

Blow/ Fl.	Sample No.	USCS	DESCRIPTION	WELL CONST
0				
1			Abandoned clay gas pipe sand backfill	
2			-No sample recovery	
3				
4	17 S-4.0 A26	CL	SILTY CLAY -Black -moist -firm -trace gravels angular to 1" diameter	
5				
6	21 S-6.0 A26	CH	CLAY -Gray -moist -firm -trace angular gravel to 1/2" diameter -low permeability -high plasticity	
7				
8				
9	28 A-9.0 A26	CL	CLAY -Tan w/ gray mottling -moist -stiff -some silt stringers -low permeability -medium plasticity	
10				
11	24 S-11.0 A26			
12			TD of boring 11.5' Logged by Mark Klaver 1/9/85	
13				
14				
15				

J H KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING



ELECTRO - COATINGS
 EMERYVILLE, CALIFORNIA
 LOG OF BORING NO. 26

PLATE

PROJECT NO. B-1132-5

Depth In Feet	Blow/ Ft.	Sample No.	USCS	DESCRIPTION	WELL CONST
0					
1	13	S-2.0 A27	ML	CLAYEY SANDY SILT -Black -dry -soft/loose -some wood fragments	-medium permeability -some fine sand
3	30	S-4.0 A27	SM	SILTY SAND -Brown -moist -dense -fine to medium sand -some wood fragments -trace angular gravel to 3/4" diameter	
6	46	S-6.0 A27	CH	CLAY -Dark gray -moist -hard -redwood fragments (minor)-high plasticity	-some root holes
8	34	S-9.0 A27	CL	CLAYEY SILT -Gray w/tan mottling -moist -stiff -some fine sand -root holes -low permeability -medium plasticity	
11	34	S-11.0 A27		GRAVELLEY CLAYEY SILT -Gray w/orange and black mottling -moist -stiff -medium plasticity -medium permeability	
12				NFWE TD of boring 11.5' Logged by Mark Klaver 1/9/85	
13					
14					
15					

JH KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING



ELECTRO - COATINGS
 EMERYVILLE, CALIFORNIA
 LOG OF BORING NO. 27

PROJECT NO. B-1132-5

PLATE

Depth In Feet	Blow/ Ft.	Sample No.	USCS	DESCRIPTION	WELL CONST
0					
1			SM	SILTY SAND -Black w/green-gray sand -medium dense -moist -high permeability -low plasticity	
2	19	S-2.0 A28			
3					
4			SC	CLAYEY SAND -Upper 6" green sand -loose *Sampler refusal @ 4.5' hard rock	
5					
6	18	S-6.0 A28	CH	CLAY -Black -moist -firm -low permeability -high plasticity	
7					
8			ML	CLAYEY SILT -Gray w/some orange mottling -green sand stringer 9.0-9.3' -moist -firm -medium permeability -low plasticity	
9	19	S-9.0 A28			
10				SILTY CLAY -Gray -moist to wet -soft -low permeability - medium plasticity	
11	11	S-11.0 A28			
12				TD of Boring 11.5' Logged by Mark Klaver 1/9/85	
13					
14					
15					

JH KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING



ELECTRO - COATINGS
 EMERYVILLE, CALIFORNIA
 LOG OF BORING NO. 28

PLATE

PROJECT NO. B-1132-5

Depth : feet

Blow/ Ft.	Sample No.	USCS	DESCRIPTION	WELL CONST
0				
1			SAND -Green w/tan mottles -moist -medium dense -fine to medium sand -high permeability	
2	18	S-2.0 A29		
3			SILTY CLAY -Gray -moist -firm -trace fine sand -low permeability -medium plasticity	
4	19	S-4.0 A29		
5			CLAY -Black -moist -firm -trace fine sand -low permeability -high plasticity	
6	15	S-6.0 A29		
7				
8				
9	24	S-9.0 A29	CLAYEY SILT -Gray w/ orange mottling -moist -firm -medium permeability-low plasticity	
10			SANDY GRAVEL -Varicolored gravels w/ brown sand -angular gravels to 1/2" diameter -medium to coarse sand -medium dense -high permeability	
11	23	S-11.0 A29		
12			TD of boring 11.5' Logged by Mark Klaver 1/9/85	
13				
14				
15				

J H KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING



ELECTRO - COATINGS
 EMERYVILLE, CALIFORNIA
 LOG OF BORING NO. 29

PROJECT NO. B-1132-5

PLATE

Depth In Feet	Blow/ Ft.	Sample No.	USCS	DESCRIPTION	WELL CONST
0					
1			SP	SILTY SAND -Brown w/ green sand lenses -moist -loose -fine to medium sand -trace fine gravel -medium permeability	
2	17	S-2.0 A30			
3			ML	SANDY SILT -Greenish gray -moist -loose -medium permeability	
4					
5	19	S-4.0 A30			
6			CH	CLAY -Black -moist -soft -low permeability -high plasticity	
7					
8			CL	SILTY CLAY -Gray w/orange mottles -moist -slightly stiff -trace fine sand -low permeability -medium plasticity	
9					
10	21	S-9.0 A30			
11			ML	CLAYEY SILT -Gray -low permeability -moist -low plasticity -firm -trace root holes	
12	18	S-11.0 A30			
13				TD of Boring 11.5' Logged by Mark Klaver 1/9/85	
14					
15					

J H KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING

PROJECT NO. B-1132-5

ELECTRO - COATINGS
 EMERYVILLE, CALIFORNIA
 LOG OF BORING NO. 30

PLATE

Depth In feet

Blow/ Ft.	Sample No.	USCS	DESCRIPTION	WELL CONST
0			Concrete 4"	
1				
2	31	SW	GRAVELLEY CLAYEY SAND -Black w/green sand stringers -moist -dense -high permeability	
3	S-2.0 A31			
4	18	ML	SANDY SILT -Black w/green sand stringers -moist -loose to medium dense -medium - high permeability	
5	S-4.0 A31			
6	18	CL	CLAY -Black -moist -firm -trace fine sand -medium plasticity -low permeability	
7	S-6.0 A31			
8		ML	SANDY SILT -Light gray -slightly wet -firm -trace fine sand and fine gravels -medium permeability	
9	26			
10	S-9.0 A31			
11	15	CL	GRAVELLEY SILTY CLAY -Gray w/orange and black mottles -wet -firm -medium to high permeability -gravel lens at 10.5'-11.0'	
12			TD of Boring 11.5' Logged by Mark Klaver 1/9/85	
13				
14				
15				

J H. KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING



ELECTRO - COATINGS
 EMERYVILLE, CALIFORNIA
 LOG OF BORING NO. 31

PLATE

PROJECT NO. B-1132-5