

Prepared for: ELECTRO-COATINGS, INC.

David 9/18/84
SA

Progress Report

Electro-Coatings, Inc.

Emeryville, California

November, 1983

J. H. KLEINFELDER & ASSOCIATES
GEOTECHNICAL CONSULTANTS • MATERIALS TESTING
LAND AND WATER RESOURCES



J. H. KLEINFELDER & ASSOCIATES

GEOTECHNICAL CONSULTANTS • MATERIALS TESTING
LAND & WATER RESOURCES

1901 OLYMPIC BOULEVARD, SUITE 300
WALNUT CREEK, CA 94596-5063

(415) 938-5610

November 2, 1983

File: B-1132-4

Attention: Mr. William Moore

Electro-Coatings, Inc.
1605 School Street
Moraga, California 94556

Subject: Transmittal of Conclusions and Progress Report for
Emeryville, California Investigation

Dear Bill:

Enclosed is a discussion of Kleinfelder and Associates' conclusions regarding data generated to date at Electro-Coatings Emeryville plant. Also, attached is a report presenting an update of the investigative program conducted to date. Information collected during this latest phase of work has allowed us to address many of the Regional Water Quality Control Board concerns as presented in their December 16, 1982 letter. The following paragraphs present our discussion of each of the Regional Board's concerns:

1. HOW MANY WATER BEARING ZONES ARE AFFECTED?

Data generated from exploration of the upper two waterbearing zones in the vicinity of the Electro-Coatings plant indicates that only one water bearing zone, the aquifer above the blue clay, has been contaminated. The waterbearing materials beneath the clay continue to show low levels of both total and hexavalent chromium. Redevelopment and retesting of wells has shown a decrease in chromium levels, which suggests that what little chromium is being detected was introduced during monitoring well construction and is not indicative of aquifer degradation. As all areas drilled around the plant have encountered the blue clay, we believe this zone to be continuous and to be acting as a vertical barrier to contaminant movement.

2. WHAT IS THE LATERAL EXTENT OF CONTAMINATION IN EACH OF THESE ZONES?

Plates 4 and 5 in the attached report depict plumes representing the total hexavalent chromium levels in the shallow aquifer. As can be seen, the plumes are evaluated down to the drinking water standard of 0.05 mg/l for chromium. These plates reasonably show definition of the lateral extent of contamination.

OTHER OFFICES:

Sacramento • Stockton • Fresno • Fairfield • Merced • Berkeley • Reno • Las Vegas • St. George, Utah



Mr. William Moore
November 2, 1983
File: B-1132-4
Page 2

3. WHAT ARE THE POTENTIAL THREATS TO WATERS (BOTH SURFACE AND GROUNDWATERS) OF THE STATE (IS THERE POTENTIAL FOR LATERAL MIGRATION IN EACH AFFECTED ZONE, AND VERTICAL MIGRATION FROM AN AFFECTED ZONE TO A CLEAN UNDERLYING ZONE?)

In our November, 1981 proposal, we estimated a shallow aquifer contaminant flow velocity of 0.2-2.0 ft/day. Monitoring well 6, located in the center of the projected plume approximately 700 feet away from the sump area, has shown hexavalent chromium at a level of 0.33 mg/l in one analysis. This suggests that the leading edge of the plume may now be only 700 feet away from the source. Groundwater must therefore be moving much slower than the velocities estimated earlier. No refinement of the velocity calculations has been attempted. Assuming present environmental conditions are not altered, contaminated groundwater will continue to migrate in a west southwesterly direction in the shallow aquifer.

The clay layer beneath the upper aquifer appears to be retarding the movement of chromium downward. As indicated earlier, no significant contamination has been detected below the clay zone. Considering that over 20 borings have been drilled in the vicinity of the plant and those drilled deep enough have encountered what appears to be the same blue clay horizon, we must conclude that the clay is continuous. The continuity of the clay and the apparent low movement of the plume provide a strong indication that deeper usable groundwater is not being threatened.

4. WHAT ARE THE POTENTIAL USES OF THE AFFECTED ZONES?

A cursory well census was performed to ascertain whether water wells were present within about one mile of the plant and whether they might be utilizing the upper contaminated zone. Well logs found in the California Department of Water Resource files in Sacramento, all indicate substantial clay in the upper 20 to 40 feet. None of the wells found are perforated in the shallow zone. Hence, there do not appear to be any current uses of the shallow aquifer.

The water quality of the groundwater above and below the blue clay has been assessed. In general the quality of the shallow zone is satisfactory with the exceptions of the total dissolved solids (TDS) which exceed the drinking water standard of 1000 mg/l in many wells both up and downgradient from the site, the pH which fluctuates from a reported low of 2.7 to a high of 12.1, and the known presence of chromium along with the probable



Mr. William Moore
November 2, 1983
File: B-1132-4
Page 3

presence of other heavy metals from other industrial activities in the vicinity. These exceptions make the potential use of this shallow aquifer very questionable. The quality of the deep aquifer water exceeds only the secondary drinking water standard of 1600 micromhos specific conductivity. This water should therefore be considered potentially suitable as a potable water supply. Limiting factors affecting the practicability of utilizing this water source are the shallowness of the water relative to current sanitary seal well construction standards and the low permeability characteristics of the aquifer materials.

5. AT WHAT DEPTH DOES USABLE GROUNDWATER EXIST?

The groundwater below the blue clay zone would have to be considered usable as described in #4 above. However, the average total depth for the seven water wells known to have been drilled in the area is 250 feet, with the deepest being over 400 feet. Perforation data are absent so no definitive statement can be made about production zones. A cursory analysis of the well logs indicates that what water can be developed comes from sand stringers within the larger clay zones.

6. DOES THE LEVEL OF CONTAMINATION IN THE SOILS IN THE AREA OF THE FORMER SOURCE POSE A LONG-TERM THREAT TO WATER QUALITY?

The assumed major source of contamination is the sump at the northeast corner of the building. Wastes allegedly seeped out of a hole in the sump bottom and into the shallow aquifer. This hole was detected and subsequently repaired, which should eliminate any further contamination from this source. Several soil borings were drilled and sampled near the loading dock adjacent to the sump. Levels of chromium in this area ranged from 38.4 mg/kg, a probable background level, to 5200 mg/kg. Neither boring 22 or 23 encountered groundwater in the 11.5 feet drilled. Monitoring wells nearby have water levels shallower than 11.5 feet. This suggests the groundwater is locally confined and thus there may be a natural separation between the contaminated soil and the shallow aquifer. Further sampling and analysis will be necessary to determine how much contamination is present and whether this chromium can act as a future source.

The December 16, 1982 Regional Board letter also requests information regarding the direction of flow and gradient of the deeper aquifer. The three wells completed below the blue clay have water levels which suggest a groundwater flow in a northerly direction. While there are three wells for triangulation the lithology and the varying piezometric surfaces causes us to

J. H. KLEINFELDER & ASSOCIATES

Mr. William Moore
November 2, 1983
File: B-1132-4
Page 4


question the reliability of the direction. Similar water levels have been remeasured in these deeper wells to verify the initial measurements.

With the completion of this latest phase of work, Kleinfelder and Associates is pleased to note that the groundwater contamination has been substantially defined and the soil contamination should be assessed in the near future. We anticipate working with Electro-Coatings staff to prepare a plan to address the issues of groundwater and soil contamination.

We have enjoyed being of service to Flecto-Coatings, Inc., and look forward to finally resolving this issue. Should you have any questions regarding our interpretation of the data or our report, please contact us.

Very truly yours,

J. H. KLEINFELDER AND ASSOCIATES



David C. Mathy
Engineering Manager



Michael L. Siembieda
Project Geologist

DCM:lj



PROGRESS REPORT
ELECTRO-COATINGS, INC.
EMERYVILLE, CALIFORNIA

TABLE OF CONTENTS

	<u>PAGE</u>
I. INTRODUCTION	1
A. Purpose	1
B. Scope of Work	1
C. Authorization	2
II. FIELD ACTIVITIES	2
A. General	2
B. Deep Monitoring Wells	3
C. Shallow Monitoring Wells	3
D. Soil Borings	4
E. Well Installation	4
F. Well Development and Water Supply	5
G. Soil Sampling	6
H. Groundwater Elevations	6
I. Well Survey	6
III. ANALYTIC RESULTS	7
A. Groundwater Flow and Gradient - Shallow Aquifers ..	7
B. Groundwater Flow and Gradient - Deep Aquifers	7
C. Groundwater Chemistry - Shallow Aquifers	7
D. Groundwater Chemistry - Deep Aquifers	8
E. Soil Chemistry	8
IV. CONCLUSIONS	9
A. Introduction	9
B. Shallow Aquifers	9
C. Deep Aquifers	10
D. Soil Contamination	10
V. RECOMMENDATIONS FOR FUTURE WORK	11

Progress Report
Electro-Coatings, Inc.
Emeryville, California

I. Introduction

A. Purpose

The following progress report summarizes work performed to date by J. H. Kleinfelder and Associates at the Electro Coatings plant in Emeryville, California (see Plate 1).

This report expands and further defines the investigative work performed in earlier studies at the plant site. These reports are used as references to supplement the data and conclusions presented in this report. Refer to Table 1 for a list of prior reports. An abbreviated history of drilling activities at the plant is presented in Table 2.

B. Scope of Work

The scope of work performed by J. H. Kleinfelder and Associates in this phase of field investigation consisted of:

- Drilling, sampling and completion of two deep monitoring wells,
- Drilling sampling and completion of two shallow monitoring wells,
- Drilling and sampling of two on-site borings,
- Sampling and analyzing groundwater from four new monitoring wells for total chromium, hexavalent chromium and standard mineral. Trivalent chromium was obtained by the difference between total and hexavalent.

J. H. KLEINFELDER & ASSOCIATES

- Analyzing of selected soil samples for a total chromium,
- Surveying in relative elevations for new and existing monitoring wells,
- Measuring groundwater levels for new and existing monitoring wells,
- Conducting a well survey in the vicinity of Electro-Coatings Plant,
- Preparing a status report containing our findings and conclusions to date along with recommendations for further work.

C. Authorization

This work has been performed in accordance with the provisions of Purchase Order Number 2006.011 dated April 8, 1983, and Kleinfelders proposal dated January 20, 1983.

II. FIELD ACTIVITIES

A. General

Four monitoring wells (MW-18A through MW-21) and two soil borings (R-22 and B-23) were drilled, installed and sampled during this phase of work (Plate 2). These locations were selected to assist in defining the vertical and lateral extent of chromium in the groundwater and soil. Groundwater levels were measured and relative elevations of monitoring wells were surveyed to better evaluate the groundwater flows in both the shallow and deeper aquifers which are present beneath the site. Augers were cleaned between borings to prevent cross contamination.

B. Deep Monitoring Wells

Two deep monitoring wells (MW-18A and MW-20) were installed to evaluate if chromium is present below a layer of blue clay identified during earlier studies to be present beneath the site. These wells were drilled and completed within the general guidelines of the California Regional Water Control Board, Lower Aquifer Drilling Protocol.

On June 9, 1983, Malcom Drilling of South San Francisco, drilled two borings (18A and 20) with a Texoma 600 drill equipped with a 16" auger to a depth of approximately 27' below ground surface. The borings were visually logged to ensure that they penetrated into the blue clay confining layer. Unused 25 foot long, 10" diameter, 12 guage steel casings were then inserted into the borings. The annulus was then backfilled with a cement/bentonite grout, tremied in place with returns to the surface. A 12 hour period was allowed for the grout to harden. The interior fluid was then removed and the remainder of the borings completed using, J. H. Kleinfelder and Associates, Acker AD-II drill rig using a 8-1/4" hollow stem augers.

C. Shallow Monitoring Wells

Two additional shallow monitoring wells (MW-19 and MW-20) were drilled to help evaluate the lateral extent of chromium in the shallow aquifer above the blue clay. The wells were drilled and completed in general accordance with guide lines for Subsurface Investigation issued by the California Regional Water Control Board.

Monitoring wells 19 and 21 were drilled using J. H. Kleinfelder and Associates, CMF-55 drill rig with 8-1/4" hollow stem augers on June 10, 1983, and June 8, 1983 respectively. Each boring was advanced until it encountered the blue clay layer at a depth of approximately 25 feet.

D. Soil Borings

Two soil borings (B-22 and B-23) were drilled near the chromium waste pit area to evaluate if significant chromium was present in the soils above the saturated zone. The borings were drilled on July 8, 1983, using J. H. Kleinfelder and Associates, CME-55 drill rig equipped with 8-1/4" hollow stem augers. After completion of the borings, they were backfilled with native materials and capped with a concrete plug approximately one foot thick.

E. Well Installation

Monitoring wells were installed in MW-18A, 19, 20 and 21, after completion of the drilling. Four-inch diameter threaded PVC pipe, plugs and caps were used to construct the wells (see Boring Logs, Plates 7-12, for well construction details). No PVC glue or cement was used in the well construction. Perforated PVC pipe, slotted at 0.020-inch was used for the well screen section. After setting the well casing, the annulus was backfilled with 3-C mesh sand. In the deep wells, bentonite plugs were placed opposite low permeability clay layers to minimize the movement of water from the upper aquifer migrating down to the lower zones. In the shallow wells, bentonite plugs were placed on top of the sand pack to minimize surface infiltration. The wells were finished at the surface with a concrete Christy box, locking steel cap and threaded PVC plug.

Monitoring Well Construction Summary

Well No.	Total Depth From			
	Ground Surface Feet	Screen Sect. Feet	Bentonite Plug Location Ft.	10" Steel Casing Location Ft.
MW18A	51.5	35-50	28-35	2-27
MW19	26.5	10-25	1-6	N.A.*
MW20	56.5	31.5-51.5	25-28'	1.5-26.5
MW21	26.5	10-25	4-7	N.A.*

*N.A. - Not Applicable

F. Well Development and Water Sampling

All four monitoring wells installed during this phase of work were developed on June 21, 1983. The wells were developed by means of a peristaltic pump and/or a two inch air activated piston pump. In addition, on August 9, 1983, MW-20 was redeveloped by means of dual tube air lift pump, equipped with a check valve to prevent the introduction of air into the formation. All four monitoring wells were sampled on June 21, 1983, by means of a Bennett piston, submersible pump. The pump is constructed of stainless steel and teflon materials to minimize sorption affects. Water quality parameters consisting of pH, temperature and conductivity were measured during the purging of the wells to assist in determining when representative formation water samples could be obtained. The samples were collected in an acid rinsed, 250 ml. plastic container and placed in a refrigerated environment prior to delivery to the testing laboratories. Chain of custody forms accompanied all samples.

G. Soil Sampling

Soil samples for chemical analysis were collected from boring 22 and 23. See boring logs (Plate 11 and 12) for sample locations. Soil samples were collected by means of 2" Modified California Sampler specially fabricated to accommodate plastic liners. The sampler was thoroughly cleaned with tap water between sample locations and unused plastic liners were used. After the sampler was removed from the boring, the liners containing the soil samples were removed and capped with plastic caps prior to delivery to the laboratory. Chain of Custody forms accompanied all samples.

H. Groundwater Elevations

To better define the groundwater gradients at the site, a survey was performed on August 9, 1983, to establish a relative elevation between wells. MW-20 was assigned an arbitrary elevation of 100.00' and all other wells (new and old) were surveyed into this datum. Refer to Table 3 for a history of the drilling activities. Depths to groundwater were measured in all existing wells on August 9, 1983, except MW-2, 7 and 13 which could not be located (see Table 2). In addition, a limited remeasurement of groundwater depths was performed on September 2, 1983. Depths were measured to the nearest 10th of a foot using an electronic water level meter manufactured by Slope Indicator, Inc.

I. Well Survey

The well driller reports on file with the California Department of Water Resources were examined to determine if active water wells were present within approximately one mile of the plant. A total of seven water wells are on record. The wells vary from 54 to 408 feet in depth. None of the wells, if still operating, appear to be extracting water from the uppermost zones.

III. ANALYTIC RESULTS

A. Groundwater Flow and Gradient - Shallow Aquifers

A groundwater contour map in the shallow aquifer was prepared using water elevation data measured on August 9, 1983 (see Table 3 and Plate 2). Groundwater flow was determined to be in a west/southwesterly direction towards San Francisco Bay. The flow direction established in this report is in slightly different direction than the west direction presented in an earlier report (WCC-1981). A groundwater gradient of approximately one foot per 100 feet or 1% was computed. This gradient closely follows the elevation contours in the area.

It should be noted that the depth to groundwater measured during this phase of study are approximately 3 feet higher than that reported in 1981. Record winter rains for the last two years are assumed to be responsible for this rise.

B. Groundwater Flow and Gradient - Deep Aquifers

Groundwater elevations were measured in the three deep wells (MW-3, MW-18A and MW-20) open to the lower aquifers (see Table 2). The piezometric surface of MW-20 was approximately 3' higher, MW-18A essentially the same and MW-3A 6' lower than the piezometric surface of the upper aquifer. Examination of the lithology encountered in the deeper wells suggests that they may have penetrated different non-connecting aquifers and hence have different piezometric surfaces.

C. Groundwater Chemistry - Shallow Aquifers

Groundwater samples from MW-19 and MW-21 were tested for total and hexavalent chromium along with a standard mineral test. Total and hexavalent chromium were below the detection limits of 0.02 mg/l for the MW-19 sample. Total chromium was at the

detection limit and hexavalent was below the detection limit for MW-21. These levels are below the Federal and California drinking standard of 0.05 mg/l.

D. Groundwater Chemistry - Deep Aquifers

Groundwater samples from MW-18A and MW-20 were tested for total and hexavalent chromium along with a standard mineral analysis (see Appendix A). In addition, a duplicate sample from MW-20 was sent to a different laboratory as a quality control check. Results from MW-18A were at the detection limit for total chromium, (0.02 mg/l) and below the detection limit for hexavalent chromium. Initial results for MW-20 were 1.3 mg/l for total and 0.53 mg/l for hexavalent chromium. Because of the relatively high levels reported, the well was redeveloped and sampled again. Levels of 0.09 mg/l for total and 0.04 mg/l for hexavalent were reported. This is approximately a 10 to 15 times decrease in the level of chromium detected. Because of this large decrease, it is assumed that the chromium present was the result of cross contamination from the upper aquifer which possible occurred during well construction. The additional development apparently flushed out some of the chromium contamination. It is assumed that additional developing will further reduce the amount of chromium to below significant levels.

E. Soil Chemistry

Four soil samples from B-22 and P-23 were analyzed for total chromium (see Appendix A). A range from 38 to 5200 mg/l was reported.

IV. CONCLUSIONS

A. Introduction

The conclusions reached are a result of the information gathered during this phase of work along with information gathered from earlier studies. The major conclusions made are:

- Definition of the horizontal extent of chromium contamination in the shallow aquifer, (see Plates 4 and 5).
- The deep aquifers near the site do not contain significant amounts of chromium,
- Soil contamination by chromium exists in the area of the former waste storage pit,
- Shallow and deeper aquifers do not appear to be interconnected.

B. Shallow Aquifers

A shallow confined to semi-confined aquifer exists at the site. The aquifer exists at an approximate depth from 10 to 20 feet below ground surface and consists of a wide range of materials from clayey silts to clean sandy gravels. Results of groundwater measurements and pump test data indicate that the aquifer is interconnected within the study area. Chemical tests indicate that a well defined plume exists (see Plates 4 and 5) with the highest concentrations of chromium in the vicinity of the former chromium waste storage pit. The plume becomes more diffused as it moves down gradient with wells 1, 2, 6, 7, 8, 19 and 21 defining areas of uncontaminated waters.

C. Deep Aquifers

A number of confined, nonconnected aquifers exist below the layer of blue clay in the study area. Based on chemical analyses, chromium has not contaminated the lower aquifer(s). Concentrations measured in MW-20 appear to be the result of well construction cross contamination and should be considered as such.


D. Soil Contamination

Significant concentrations of chromium exist in soils in the vicinity of the former chromium waste storage pit. The lateral and vertical extent are not defined.


V. RECOMMENDATIONS FOR FUTURE WORK


- Drill and sample 6-8 borings in the vicinity of the former chromium waste pit with soil samples to be taken at 1, 3, 5, 8 and 10' and selected samples analyzed for total chromium to assess the extent of soil contamination,
- Redevelop and resample all existing monitoring wells for total and hexavalent chromium. Use field blanks and duplicates to separate laboratories for quality control.





J.H. KLEINFELDER & ASSOCIATES GEOTECHNICAL CONSULTANTS • MATERIALS TESTING	ELECTRO - COATINGS INC. EMERYVILLE, CALIFORNIA SITE PLAN	PLATE 2
PREPARED BY: ADP DATE:	PROJECT NO. B-1132-4	
CHECKED BY: MLS DATE:		






J.H. KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS - MATERIALS TESTING

PREPARED BY: ADP DATE: / /
 CHECKED BY: MLS DATE: / /


ELECTRO - COATINGS INC.
 EMERYVILLE, CALIFORNIA
**TOTAL CHROMIUM IN
 SHALLOW GROUNDWATER**

PROJECT NO. B-1132-4

PLATE
4



APPROXIMATE SCALE








LEGEND

- PREVIOUSLY DRILLED WELLS
 - PREVIOUSLY DRILLED WELLS NOT LOCATED IN THIS STUDY
 - ⊙ WELLS & BORINGS DRILLED & COMPLETED IN THIS STUDY
- 0.05--- HEXAVALENT CHROMIUM IN SHALLOW GROUNDWATER AT 0.05, 100 AND 500 M_g/L CONCENTRATIONS
- VALUES FOR MW-1 THROUGH MW-18 MEASURED AND REPORTED IN KLEINFELDER'S 1982 REPORT.
- VALUES FOR MW-18A THROUGH MW-21 MEASURED AND REPORTED IN THIS REPORT.

J.H. KLEINFELDER & ASSOCIATES GEOTECHNICAL CONSULTANTS • MATERIALS TESTING		ELECTRO - COATINGS INC. EMERYVILLE, CALIFORNIA HEXAVALENT CHROMIUM IN SHALLOW GROUNDWATER	PLATE
			5
PREPARED BY: ADP DATE:	CHECKED BY: MLS DATE:	PROJECT NO. B-1132-4	

UNIFIED SOIL CLASSIFICATION SYSTEM

MAJOR DIVISIONS		LTR	DESCRIPTION	MAJOR DIVISIONS		LTR	DESCRIPTION		
COARSE GRAINED SOILS	GRAVEL AND GRAVELLY SOILS	GW	Well-graded gravels or gravel sand mixtures, little or no fines.	FINE GRAINED SOILS	SILTS AND CLAYS LL<50	ML	Inorganic silts and very fine sands, rock flour, silty or clayey fine sands or clayey silts with slight plasticity.		
		GP	Poorly-graded gravels or gravel sand mixture, little or no fines.			CL	Inorganic clays of low to medium plasticity, gravelly clays, sandy clays, silty clays, lean clays.		
		GM	Silty gravels, gravel-sand-clay mixtures.			OL	Organic silts and organic silt-clays of low plasticity		
		GC	Clayey gravels, gravel-sand-clay mixtures.						
	SAND AND SANDY SOILS	SW	Well-graded sands or gravelly sands, little or no fines.		SILTS AND CLAYS LL>50	MH	Inorganic silts, micaceous or diatomaceous fine sandy or silty soils, elastic silts		
		SP	Poorly-graded sands or gravelly sands, little or no fines.			CH	Inorganic clays of high plasticity, fat clays.		
		SM	Silty sands, sand-silt mixtures.			OH	Organic clays of medium to high plasticity.		
		SC	Clayey sands, sand-clay mixtures.						
						HIGHLY ORGANIC SOILS		Pt	Peat and other highly organic soils.

-  Standard penetration split spoon sample
-  Modified California Sampler
-  Shelby tube sample
-  Water level observed in boring
-  No recovery
- NFWE No free water encountered

NOTE: Blow count represents the number of blows of a 140-pound hammer falling 30 inches per blow required to drive a sampler through the last 12 inches of an 18-inch penetration.

NOTE: The line separating strata on the logs represent approximate boundaries only. The actual transition may be gradual. No warranty is provided as to the continuity of soil strata between borings. Logs represent the soil section observed at the boring location on the date of drilling only.

J.H. KLEINFELDER & ASSOCIATES
GEOTECHNICAL CONSULTANTS • MATERIALS TESTING



ELECTRO-COATINGS INC.
EMERYVILLE, CALIFORNIA

BORING LOG LEGEND

PLATE

6

PREPARED BY:

DATE:

CHECKED BY:

DATE:

PROJECT NO. B-1132-4

DEPTH IN FEET

BLOW COUNT	SAMPLE	USCS	DESCRIPTION	WELL CONST.
0			Asphalt	
		Fill	Subbase - gravel and sand	
2		CL/CH	SILTY CLAY - black, moist, plastic, some sand	
4				
6		CL	GRAVELLY CLAY - bluish green, grey, moist, stiff	
8				
10		CL/GC	SANDY GRAVELLY CLAY/CLAYEY GRAVEL - brown, moist	
12				
14				
16				
18				
20		CL	SILTY CLAY - brown, wet, soft	
22				
24				
26		CL	SILTY CLAY - mottled blue gray, brown, wet, plastic, moderately stiff	
28				

(1) 16" diameter hole drilled to 27', 10" casing set and annulus backfilled with bentonite/cement grout that was tremied in place.

J.H. KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING



ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA

LOG OF BORING NO. 18A

PLATE

7

PREPARED BY: AP DATE: 7/83

CHECKED BY: MLS DATE: 7/83

PROJECT NO. B-1132-4

DEPTH IN FEET	BLOW COUNT	SAMPLE	USCS	DESCRIPTION	WELL CONST.
28			CL	Silty clay as before	
30	53	1 2	SC	CLAYEY SAND - brown, blue gray, wet, dense, clay approx. 35%, silt approx. 10%, some fine gravel	
32			ML	SILT - blue gray, mottled brown, wet, moderately stiff, non-plastic, some clay increasing with depth	
34					
36	22	3 4		grading into	
38			CL	SILTY CLAY - blue gray, wet, very stiff, some sand and gravel	
40	53	5 6			
42			SM	SILTY SAND - flowing sands 3 feet of heave up auger	
44			CL	SILTY CLAY - light olive gray, wet, stiff, slightly plastic to plastic, some high silt content zones	
46					
48					
50	25	7 8			
52				Total depth of boring = 51.5 feet Logged by M. L. Siembieda	
54					

J.H. KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING

PREPARED BY: AP DATE: 7/83
 CHECKED BY: MLS DATE: 7/83

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA

LOG OF BORING NO. 18A

PROJECT NO. B-1132-4

PLATE
7A

DEPTH IN FEET	BLOW COUNT	SAMPLE	USCS	DESCRIPTION	WELL CONST.
	0				Asphalt
			Fill	Subbase - sand & gravel	
2			CL	SILTY CLAY - black, moist, plastic, stiff	
4					
6	22	1 2		becoming very dark gray	
8					
10	17	3	SC	CLAYEY SAND - brown, saturated, moderately dense, well graded, some fine gravel, appreciable amount of fines	
12			CH	SILTY CLAY - brown, wet, stiff, highly plastic	
14			CL	SILTY CLAY - brownish gray, mottled brown, wet, moderately stiff, moderately plastic, trace sand and gravel, silt content approx. 30%	
16	15	4 5			
18					
20	13	6 7		sand and gravel increase	
22					
24				grading into	
26	17	8 9	CL	SILTY CLAY - bluish gray, gray, wet, plastic to slightly plastic, stiff	
28				Bottom of boring @ 26.5 ft. Logged by M. L. Siembieda 6/10/83	

J.H. KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING



ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA

LOG OF BORING NO. 19

PLATE

8


PREPARED BY: AP DATE: 7/83

CHECKED BY: MLS DATE: 7/83

PROJECT NO. B-1132-4

BLOW COUNT	SAMPLE	USCS	DESCRIPTION	WELL CONST.
0			Asphalt	
2		CL	SILTY CLAY - black, moist, firm, plastic, some sand	
4				
6			Some wood material	
8		CL/ GC	GRAVELLY CLAY/CLAYEY GRAVEL - brown, moist, sandy, stiff	
10				
12				
14		CL	Clay increasing SILTY CLAY - grayish brown, stiff, plastic	
16				
18				
20				
22				
24		CL	SILTY CLAY - bluish gray, mottled brown, wet, plastic, moderately stiff, high silt content (30-40%)	
26				
28				

(1) 16" diameter hole drilled to 26.5 feet, 10 foot casing set & annulus backfilled with bentonite/cement grout that was tremied in place.

J.H. KLEINFELDER & ASSOCIATES <small>GEO TECHNICAL CONSULTANTS • MATERIALS TESTING</small> 		ELECTRO-COATINGS INC. EMERYVILLE, CALIFORNIA LOG OF BORING NO. 20		PLATE 9
PREPARED BY: AP DATE: 7/83	PROJECT NO. B-1132-4			
CHECKED BY: MLS DATE: 7/83				

DEPTH IN FEET

BLOW COUNT	SAMPLE	USCS	DESCRIPTION	WELL CONST.
28		CL	Silty clay as before	
30	1			
25	2			
32				
34				
36	3		Silt decreases to 20-10%, highly plastic	
21	4			
38				
40	5			
35	6	SC	CLAYEY SANDS - brown, saturated, dense, well graded, fines approx. 20%, gravel to 1/2" max., mostly angular	
42	7			
44		CL	GRAVELLY CLAY - gray, wet, stiff, plastic, gravel approx. 20% fine, well rounded	
46	8			
19	9			
46	10	SC	CLAYEY SAND - brown, saturated, moderately dense, high clay %, fine grained	
48		SP	Grading into SAND - brown, saturated, loose, poorly graded, medium grained, little fines	
50	11			
19	12			
52		CL	GRAVELLY CLAY - dark gray, stiff, plastic, silty, gravel approx. 20%	
54				
56	13			
30	14			

Bottom of boring @ 56.5 feet
 Logged by M.L. Siembieda

(1) 3.5 feet of slough in hole.

J.H. KLEINFELDER & ASSOCIATES 
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA
 LOG OF BORING NO. 20

PLATE
9A


PREPARED BY: AP DATE: 7/83

CHECKED BY: MLS DATE: 7/83

PROJECT NO. B-1132-4

DEPTH IN FEET

BLOW COUNT	SAMPLE	USCS	DESCRIPTION	WELL CONST.
0		Fill	Railroad Roadbed - sand, gravel and silt, loose, dry	
2				
4				
6	1	CH	SILTY CLAY - gray, moist, firm, highly plastic	
8				
10				
12	2	GW	SANDY GRAVEL - brown, saturated, dense, well graded, little fines, approx. 10%, gravel 1/2" max.	
14				
16	3	CL	SILTY CLAY - greenish gray, wet, plastic, stiff, high silt content, approx 35%	
18				
20				
22	4 5	GC	CLAYEY GRAVEL - brown, saturated, dense, well graded, gravel to 1" max.	
24				
26	6 7	CL	SILTY CLAY - olive gray, bluish gray, stiff, wet, plastic, few gravel	
28			Bottom of boring @ 26.5 feet Logged by M.L. Siembieda 6/8/83	

J.H. KLEINFELDER & ASSOCIATES 
 GEOTECHNICAL CONSULTANTS - MATERIALS TESTING

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA
LOG OF BORING NO. 21

PLATE

10

PREPARED BY: AP DATE: 7/83


CHECKED BY: MLS DATE: 7/83

PROJECT NO. B-1132-4

DEPTH IN FEET

BLOW COUNT	SAMPLE	USCS	DESCRIPTION	WELL CONST.
0			Asphalt	
2	14	CL	SANDY SILTY CLAY (Fill) - blue gray, moist, slightly plastic, firm, sand approx. 35%	
4	18	GC	CLAYEY GRAVEL (Fill) - black, dark greenish gray, brown, wet, wide range of materials	
6	16	CL	SILTY CLAY - very dark gray, moist, stiff, plastic, sand 5-10%	
8			- sand increases, mottled color, irridescence	
			- few gravel	
10	23	ML/CL	SILTY CLAY - yellowish brown, moist, slightly plastic, firm, some fine sand & gravel	
12	12	CL	Silt decreases - light yellowish gray, brown mottling, moderately plastic	
14			Bottom of boring 11.5 ft. Logged by M.L. Siembieda 6/8/83	
16				
18				
20				
22				
24				
26				
28				

J.H. KLEINFELDER & ASSOCIATES
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING



PREPARED BY: AP DATE: 7/83
 CHECKED BY: MLS DATE: 7/83

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA

LOG OF BORING NO. 22

PROJECT NO. B-1132-4

PLATE

11

DEPTH IN FEET

BLOW COUNT	SAMPLE	USCS	DESCRIPTION	WELL CONST.
0			Asphalt	
		Fill	Subbase - sand and gravel	
16	1			
2	2	CL	SILTY CLAY - black, moist, stiff, plastic, trace fine sand	
			- some sandy zones	
4	3			
	4		- at 4.5' wood	
6				
18	5			
8	6	CL	SILTY CLAY - greenish, bluish gray, moist, stiff, plastic, trace fine sand, some brown mottling	
10				
19	7			
	8	ML	CLAYEY SILT - light olive gray, moist, stiff	
12			Bottom of boring @ 11.5 ft. Logged by M.L. Siembieda	
14				
16				
18				
20				
22				
24				
26				
28				

J.H. KLEINFELDER & ASSOCIATES 
 GEOTECHNICAL CONSULTANTS • MATERIALS TESTING

ELECTRO-COATINGS INC.
 EMERYVILLE, CALIFORNIA
LOG OF BORING NO. 23

PLATE

12

PREPARED BY: AP DATE: 7/83

CHECKED BY: MLS DATE: 7/83

PROJECT NO. B-1132-4



ANALYTICAL LABORATORY
A DIVISION OF DEWANTE & STOWELL

1914 S STREET, SACRAMENTO, CALIFORNIA 95814 • 916-447-2946

JULY 18, 1983
DATE SAMPLES REC'D: 6-22-83
REPORT #: 260982

KLEINFELDER & ASSOC.
1901 OLYMPIC BLVD.
WALNUT CREEK, CA 94596

ATTN: MIKE SIEMBIEDA

PAGE 1 OF 2

<u>ANALYSIS</u>	<u>W-MW18A-35¹</u>	<u>W-MW19-20¹</u>	<u>W-MW20-35¹</u>	<u>W-MW21-20¹</u>
	<u>82-2609-1</u>	<u>82-2609-2</u>	<u>82-2609-3</u>	<u>82-2609-4</u>
CHROMIUM, MG/L	0.02	<0.02	1.30	0.02
HEXAVALENT CHROMIUM, MG/L	<0.02	<0.02	0.53	<0.02
PH	12.1	7.9	7.9	2.7
ALKALINITY, MG/L AS CaCO ₃	552	356	98	< 1
SPEC. COND., UMHO	2400	840	520	3200
NITRATE, MG/L AS N	9.32	11.9	12.8	37.8
CHLORIDE, MG/L	30	20	30	69
SULFATE, MG/L	41	71	69	1100
CALCIUM, MG/L	186	60	42.4	222
MAGNESIUM, MG/L	<0.01	42.8	16.0	133
SODIUM, MG/L	54	72	42	96
POTASSIUM, MG/L	6.05	1.64	1.92	1.80

1 SAMPLES FILTERED THROUGH 0.45 MICRON FILTER PRIOR TO ANALYSIS.



ANALYTICAL LABORATORY
A DIVISION OF DEWANTE & STOWELL

1814 S STREET, SACRAMENTO, CALIFORNIA 95814 • 916-447-2946

JULY 18, 1983
REPORT #: 260982

KLEINFELDER & ASSOC.
ATTN: MIKE SIEMBIEDA

PAGE 2 OF 2


<u>SAMPLE DESCRIPTION</u>	<u>ANLAB ID #</u>	<u>CHROMIUM MG/KG</u>
S-B22-4-41/2 *	82-2609-5	5200
S-B22-81/2-9 *	82-2609-6	482
S-B23-2-21/2 *	82-2609-7	38.4
S-B23-71/2-8 *	82-2609-8	980

* WET WEIGHT.

DATA CERTIFIED BY Ken Namla
REPORT APPROVED BY Logan Elliott
ANLAB/T. IKESAKI

SS

GENERAL MINERAL ANALYSIS*



BROWN AND CALDWELL

CONSULTING ENGINEERS
ANALYTICAL SERVICES DIVISION
 1255 POWELL STREET
 EMERYVILLE, CA 94608
 PHONE (415) 428-2300

Log No. E83-6-191-1

Date Sampled 6-21-83
 Date Received 6-21-83
 Date Reported 7-5-83

Reported To: Mr. Michael Siembieda
 J.H. Kleinfelder & Associates
 1901 Olympic Boulevard, Suite 300
 Walnut Creek, California 94596

cc.

J. Hatfield
 Laboratory Director

Sample Description **JOB #B-1132-4: W-MW20-35**

Anions	Milligrams per liter	Milliequiv. per liter	Determination	Milligrams per liter	Determination	Milligrams per liter
Nitrate Nitrogen (as NO ₃)	47	0.76	Hydroxide Alkalinity (as CaCO ₃)	0	Chromium, hexavalent	1.2
Fluoride	37	1.04	Carbonate Alkalinity (as CaCO ₃)	0	Chromium, trivalent	0.1
Sulfate (as SO ₄)	85	1.77	Bicarbonate Alkalinity (as CaCO ₃)	90		
Bicarbonate (as HCO ₃)	110	1.80	Calcium Hardness (as CaCO ₃)	107		
Carbonate (as CO ₃)	0	0	Magnesium Hardness (as CaCO ₃)	57		
Total Milliequivalents per Liter		5.37	Total Hardness (as CaCO ₃)	164		
Cations	Milligrams per liter	Milliequiv. per liter	Iron	1.3		
Sodium	46	2.00	Manganese	0.03		
Potassium	2.0	0.05	Copper	< 0.01		
Calcium	43	2.15	Zinc	0.05		
Magnesium	14	1.15	Foaming Agents (MBAS)	----		
Total Milliequivalents per Liter		5.35	Dissolved Residue, Evaporated @ 180°C	355		
*Conforms to Title 22, California Administrative Code (California Domestic Water Quality and Monitoring Regulations)			Specific Conductance, micromhos @ 25°C	489	pH	8.2

mls



ANALYTICAL LABORATORY
A DIVISION OF DEWANTE & STOWELL

1914 S STREET, SACRAMENTO, CALIFORNIA 95814 • 916-447-2946

AUGUST 12, 1983
DATE SAMPLE REC'D: 8-11-83
REPORT #: 100108

KLEINFELDER & ASSOC.
1910 OLYMPIC BLVD.
WALNUT CREEK, CA 94596

ATTN: RICHARD ZIPP

B-1132-4
W-MW20-40
100108-1

ANALYSIS

TOTAL CHROMIUM, MG/L	0.09
HEXAVALENT CHROMIUM, MG/L	0.04

DATA CERTIFIED BY Ken Namla

REPORT APPROVED BY Roger Elliott

ANLAB/T. IKESAKI

SS