

REPORT OF FINDINGS  
UNDERGROUND STORAGE TANK REMOVAL

DUBLIN HONDA  
7099 AMADOR PLAZA ROAD  
DUBLIN, CALIFORNIA  
EPA #CAC000626120

PREPARED FOR:  
Mr. Dan Hill  
Dublin Honda  
7099 Amador Plaza Rd.  
Dublin, CA 94568

PREPARED BY:  
THE ENVIRONMENTAL CONSTRUCTION COMPANY  
775 Montague Expressway  
Milpitas, CA 95035

NOVEMBER 1991

## TABLE OF CONTENTS

<u>Topic</u>	<u>Page</u>
Introduction	1
Executive Summary	2
Risk	3
Site Background/Tank History	4
Excavation of Soils	4
Tank and Product Line Removal	4-5
Soil Sampling Protocol	5-6
Analytical Results	6-9
Findings and Recommendations	9-11
Limitations	11

### Figures

- Figure 1 - Site Location Map
- Figure 2 - Site Characterization Map
- Figure 3 - Sampling Location Map

### Appendices

- Appendix A - Tank Removal Permits
- Appendix B - Hazardous Waste Manifest/Certificate of Disposal
- Appendix C - Laboratory Report/Chain of Custody

Underground Storage Tank Removal  
Dublin Honda  
7099 Amador Plaza Road  
Dublin, California 94568  
EPA #CAC000626120

Dan Hill  
Dublin Honda  
7099 Amador Plaza Road  
Dublin, CA 94568

December 5, 1991

Dear Mr. Hill

On October 1, 1991, THE ENVIRONMENTAL CONSTRUCTION COMPANY (TECC) removed one 500-gallon underground storage tank from the subject property located at 7099 Amador Plaza Road, Dublin, California. The scope of our work included: Submitting the tank removal permits as required by the State of California Water Resources Control Board and the Dougherty Regional Fire Authority; excavating and removing the underground storage tank and associated product line; collecting appropriate soil samples and providing for their analyses; and properly disposing of the removed tank and product line.

This Report of Findings summarizes the history of the tank, the results of the visual inspection of the tank and product line, subsurface sampling methods, analytical results of the soil samples, and our findings and recommendations.

Should you have any questions or require additional information, please feel free to contact our office at (408) 957-7700 at your convenience. THE ENVIRONMENTAL CONSTRUCTION COMPANY is pleased to be of service to you on this project.

Respectfully,

*Brian Reddig*  
Brian Reddig  
Staff Geologist

## EXECUTIVE SUMMARY

On October 1, 1991, TECC personnel removed one 500-gallon, steel, single-walled underground storage tank that last contained waste oil from the subject property located at 7099 Amador Plaza Road, Dublin, California. The tank pit was approximately seven feet long by seven feet wide, with the base of the tank resting at a depth of seven feet below surface grade. The soil encountered in the pit was a grayish-brown, poorly sorted, gravelly sand which apparently was used as back-fill during the initial tank installation. Native soils excavated from along the walls of the pit predominantly were black, moderately plastic clays and silty clays. A slight to moderate oily odor was noted in some of the excavated soils. Groundwater was not encountered in the pit during the tank removal.

Visual inspection of the tank did not indicate any signs of rupture, puncture, cracking, or leakage. Slight rust scaling was noted on both the tank and the product line, although no through-going holes were discovered.

Two soil samples (DH-1 and DH-2) were collected from below the floor of the tank pit. Three soil stockpile samples (SP-1, SP-2, and SP-3) were collected from the soil stockpile for subsequent laboratory composition (SP-1,2,3\*). Each sample was analyzed for TPHg, TPHd, BTEX, TOG, Purgeable Halocarbons, and the five priority LUFT metals.

Each of the three samples contained elevated concentrations of TPHg, BTEX, TOG, and the Purgeable Halocarbon Tetrachloroethene. Two of the samples contained TOG in excess of 1000 ppm, which is the concentration used by the Department of Health Services to designate hazardous waste.

TECC recommends that two actions be considered. The first action involves the removal of contaminated soils from the vicinity of the removed waste oil tank in order to reduce the possibility of contaminants leaching into the groundwater and/or areas of clean soil. The second action, which may be required if the excavation of contaminated soils cannot be successfully accomplished, involves the determination of the lateral and vertical extent of soil contamination and to determine if the groundwater has been impacted by petroleum hydrocarbon contamination.

## RISK

The subject site presents a moderate risk to the environment based on the following site characteristics:

- TOG was detected at concentrations ranging from 3000 ppm to 820 ppm.
- TPHg was detected at concentrations ranging from 82 ppm to 2.6 ppm.
- Benzene was detected at concentrations ranging from 23 ppb to non-detectable.
- Toluene was detected at concentrations ranging from 34 ppb to non-detectable.
- Ethylbenzene was detected at concentrations ranging from 130 ppb to 16 ppb.
- Total Xylenes were detected at concentrations ranging from 670 ppb to 100 ppb.
- Tetrachloroethene was detected at concentrations ranging from 85 ppb to 20 ppb.

In addition, it is believed that the groundwater is encountered approximately 10 to 15 feet below surface grade in the vicinity of the site.

One beneficial condition characteristic of the site is the presence of subsurface low permeability clays and silty clays underlying the site.

## SITE BACKGROUND/TANK HISTORY

The site is currently a retail automobile sales and repair facility located at 7099 Amador Plaza Road, Dublin, California. The location of the site is shown in Figure 1, Site Location Map. The site is bound to the north by a parking lot and retail stores, to the west by Amador Plaza Road, to the south by an automobile dealership, and to the east by a small stream and Highway 580. The general layout of the site is shown in Figure 2, Site Characterization Map.

It was unknown to the client as to when the underground storage tank was initially installed. The 500-gallon, steel, single-walled underground storage tank was last used to store waste oil. The last date of tank usage also was unknown to the client. It appears that during the initial tank installation, the pit was back-filled with a gravelly sand and subsequently resurfaced with concrete and asphalt.

## EXCAVATION OF SOILS

Prior to the excavation of soils from above the underground storage tank, TECC personnel removed the concrete and asphalt patch from directly above the tank. Soils were then excavated from above and along the sides of the tank in order to expose the top and walls of the tank in preparation for its removal.

The soil encountered in the pit was a grayish-brown, poorly sorted gravelly sand, which apparently was used as back-fill material during the initial tank installation. Native soils excavated from along the walls of the pit predominantly were black, moderately plastic clays and silty clays. The top of the tank was encountered at a ~~depth of 3-1/2 feet below surface grade~~. The tank pit was enlarged to approximately seven feet long by seven feet wide, with the base of the tank resting at ~~seven feet below surface grade~~. Approximately ~~12 cubic yards~~ of soil was removed from the pit during the tank removal procedure. A slight to moderate oily odor was noted in some of the excavated soils. Groundwater was not encountered in the tank pit during the tank removal process.

## TANK AND PRODUCT LINE REMOVAL

On October 1, 1991, TECC personnel exposed the top and sides of the underground storage tank in preparation for its removal. Inspector Tom Hathcox of the Dougherty Regional Fire Authority was on site to witness the preparation and removal of the underground storage tank.

Before the tank was removed, approximately 150 pounds of dry ice was inserted into the tank in order to inert any residual contents within it. The probe of a GasTech Model 1314 Explosimeter was then lowered into the tank to measure the lower explosive limit (LEL) and oxygen level (OL). According to safety guidelines, the LEL and OL must be below 10% in order for the tank to be safely removed and transported. Readings below this level were measured; consequently the tank was prepared for removal. The tank was removed by attaching a heavy-duty steel chain around the middle of the tank and attaching this assembly to the bucket of the back-hoe. The back-hoe then lifted the tank out of the pit and placed it in a staging area for inspection.

The product line was removed initially by exposing the pipe with the back-hoe, and then cutting the pipe flush with the edge of the building using a sparkless saw. The end of the pipe was then capped and the remaining length of the pipe filled with cement.

A visual inspection of the tank indicated a minor amount of rust scaling, but no signs of through-going holes, cracks, or punctures were noted. The product line also appeared to be intact, with only a minor amount of rust scaling present.

After the visual inspection was completed, the tank and approximately ten feet of product line were loaded onto an H&H Ship Service transport truck (EPA #CAD004771168) and taken to Erickson, Inc., 255 Parr Blvd., Richmond, CA (EPA #CAD009466392). Copies of the Hazardous Waste Manifest and Certificate of Disposal are included in Appendix B.

#### SAMPLING PROTOCOL

On October 1, 1991, under the supervision of Hazardous Materials Specialist Ravi Arulanantham of the Alameda County Health Agency, TECC personnel collected two soil samples from the floor of the tank pit (DH-1 and DH-2) and three soil samples from the soil stockpile (SP-1, SP-2, and SP-3) for subsequent laboratory composition (SP-1,2,3\*). The locations from where these samples were collected are indicated in Figure 3, Sampling Location Map. Soil sample DH-1 was collected from native soils one foot below the fill-port (west) end of the tank (eight feet total depth). Soil sample DH-2 was collected from a similar depth below the east end of the tank. Soil samples SP-1, SP-2, and SP-3 were collected from random locations in the soil stockpile. A slight oily odor was noted in the pit floor samples DH-1 and DH-2. A slight to moderate oily odor was noted in stockpile samples SP-1, SP-2, and SP-3.

The "grab sample" method was used to collect pit floor samples DH-1 and DH-2. With this technique, a clean 2-inch outside diameter, 4-inch long brass sampling tube was hand-driven into the excavated soils in the bucket of the back-hoe. Care was taken in recovering the sample at locations away from the walls of the bucket in order to reduce the possibility of contamination from the bucket. Before the samples were collected, the outer foot of soils in the bucket were scraped away in order to allow for the collection of a more representative sample.

Soil stockpile samples SP-1, SP-2, and SP-3 were collected by hand-driving a clean 2-inch OD, 4-inch long, brass sampling tube into the excavated soil stockpile at random locations. Before collecting the samples, a small pit was shovel-dug into the stockpile in order to allow for the collection of a more representative sample. These three soil samples were collected for subsequent laboratory composition into composite sample SP-1,2,3\*.

Upon recovery of the samples, the ends of the brass tube were sealed with aluminum foil, capped with plastic end caps, secured with aluminized tape, and properly labelled. The label information included the date, time of sampling, identification number, project name and number, and analyses requested. Under proper Chain of Custody procedures, the samples were placed on ice inside a thermally-insulated cooler for subsequent transport to a State-certified analytical laboratory. A copy of the Chain of Custody form is included in Appendix C.

All soil samples were delivered to Chromalab, Inc., of San Ramon, California (State-certification #238 and #655, Federal ID #68-0140157). Each sample was analyzed for the following parameters: Total Petroleum Hydrocarbons as gasoline (TPHg) using EPA Method 5030/8015; Total Petroleum Hydrocarbons as diesel (TPHd) using EPA Method 3510/8015; Benzene, Toluene, Ethylbenzene, and Total Xylenes (BTEX) using EPA Method 8020; Total Oil and Grease (TOG) using Standard Method 5520 E&F; Purgeable Halocarbons using EPA Method 8010; Cadmium (Cd) using EPA Method 7130; Chromium (Cr) using EPA Method 7190; Lead (Pb) using EPA Method 7420; Nickel (Ni) using EPA Method 7520; and Zinc (Zn) using EPA Method 7950.

#### **ANALYTICAL RESULTS**

The analytical results for soil samples DH-1, DH-2, and SP-1,2,3\* are presented in Table 1 (TPHg & BTEX), Table 2 (TPHd & TOG), Table 3 (Purgeable Halocarbons) and Table 4 (Cd, Cr, Pb, Ni, Zn). Included in each table is the detection limit for each parameter. A copy of the laboratory report is included in Appendix C.

Soil sample DH-1 contained TPHg at a concentration of 82 parts per million (ppm). The BTEX constituents were detected at concentrations of 23 parts per billion (ppb) of Benzene, 11 ppb of



Toluene, 130 ppb of Ethylbenzene, and 670 ppb of Total Xylenes. TOG was detected at a reported concentration of 2700 ppm. The five LUFT priority metals (Cd, Cr, Pb, Ni, and Zn) were present at concentrations of 0.412 ppm of Cadmium, 3.19 ppm of Chromium, 3.38 ppm of Lead, 2.70 ppm of Nickel, and 7.03 ppm of Zinc. The Purgeable Halocarbon Tetrachloroethene was detected at a concentration of 85 ppb. TPHd was not detected in this sample.

Soil sample DH-2 contained TPHg at a reported concentration of 11 ppm. The BTEX constituents Ethylbenzene and Total Xylenes were detected at concentrations of 17 ppb and 100 ppb, respectively. TOG was present at a concentration of 820 ppm. The five LUFT priority metals were detected at concentrations of 0.483 ppm of Cadmium, 3.59 ppm of Chromium, 3.79 ppm of Lead, 3.04 ppm of Nickel, and 7.26 ppm of Zinc. The Purgeable Halocarbon Tetrachloroethene was present at a concentration of 20 ppb. TPHd, Benzene, and Toluene were not detected in this sample.

Composited soil stockpile sample SP-1,2,3\* contained TPHg at a concentration of 2.6 ppm. The BTEX constituents were detected at concentrations of 5.0 ppb of Benzene, 34 ppb of Toluene, 16 ppb of Ethylbenzene, and 140 ppb of Total Xylenes. TOG was present at a reported concentration of 3000 ppm. The five LUFT priority metals were present at concentrations of 0.549 ppm of Cadmium, 3.27 ppm of Chromium, 4.76 ppm of Lead, 3.19 ppm of Nickel, and 14.5 ppm of Zinc. The Purgeable Halocarbon Tetrachloroethene was detected at a concentration of 84 ppb. TPHd was not detected in this sample.

Sample Number	TPHg (ppm)	Benzene (ppb)	Toluene (ppb)	Ethylbenzene (ppb)	Xylenes (ppb)
DH-1	82	23	11	130	670
DH-2	11	ND	ND	17	100
SP-1,2,3*	2.6	5.0	34	16	140
DETECTION LIMIT	1.0	5.0	5.0	5.0	5.0
METHOD OF ANALYSIS	5030/ 8015	8020	8020	8020	8020
ND = Not Detected					

Table 1 Analytical Results (TPHg & BTEX)

Sample Number	TPHd (ppm)	Oil and Grease (ppm)
DH-1	ND	2700
DH-2	ND	820
SP-1,2,3*	ND	3000
DETECTION LIMIT	1.0	10
METHOD OF ANALYSIS	3550/ 8015	5520 E&F

ppm = parts per million  
ND = Not Detected

Table 2 Analytical Results (TPHd & TOG)

Sample Number	Purgeable Halocarbon	Concentration (ppb)
DH-1	Tetrachloroethene	85
DH-2	Tetrachloroethene	20
SP-1,2,3*	Tetrachloroethene	84
DETECTION LIMIT		0.5
METHOD OF ANALYSIS	EPA 601	

ppb = parts per billion

Table 3 Analytical Results (Purgeable Halocarbons)

Sample Number	Cadmium (ppm)	Chromium (ppm)	Lead (ppm)	Nickel (ppm)	Zinc (ppm)
DH-1	0.412	3.19	3.38	2.70	7.03
DH-2	0.483	3.59	3.79	3.04	7.26
SP-1,2,3*	0.549	3.27	4.76	3.19	14.5
DETECTION LIMIT	0.005	0.05	0.05	0.04	0.005
STLC	1.0	5.0	5.0	20	250
TTLIC	100	500	1000	2000	5000
METHOD OF ANALYSIS	7130	7190	7420	7590	7950

ppm = parts per million

STLC = Soluble Threshold Limit Concentration  
TTLIC = Total Threshold Limit Concentration

Table 4 Analytical Results (Cd, Cr, Pb, Ni, Zn)

## FINDINGS AND RECOMMENDATIONS

### Findings

The following is a summary of the results and findings of our underground storage tank removal program and the laboratory analytical results of the soil samples:

- The material used as back-fill during the initial tank installation was a grayish-brown, poorly sorted, gravelly sand.
- The native soils were comprised mainly of black, moderately plastic clays and silty clays.
- A slight to moderate product odor was noted in some of the excavated soils.
- Groundwater was not encountered in the tank pit.
- Visual inspection of the removed tank did not indicate any signs of rupture, puncture, or cracking.

Analytical results of the pit floor and stockpile samples indicate the presence of the following contaminants:

- TOG was detected at concentrations ranging from 3000 ppm to 820 ppm.
- TPHg was detected at concentrations ranging from 82 ppm to 2.6 ppm.
- Benzene was detected at concentrations ranging from 23 ppb to non-detectable.
- Toluene was detected at concentrations ranging from 34 ppb to non-detectable.
- Ethylbenzene was detected at concentrations ranging from 130 ppb to 16 ppb.
- Total Xylenes were detected at concentrations ranging from 670 ppb to 100 ppb.
- Tetrachloroethene was detected at concentrations ranging from 85 ppb to 20 ppb.

Groundwater is believed to occur at a depth of approximately 10 to 15 feet below surface grade.

The native soils which are underlying the site are comprised of low permeability clays and silty clays. These types of sediments tend to act as a retardant to the vertical and lateral migration of contaminants.

### Recommendations

Based on the above findings, TECC recommends that the following actions be considered:

#### **Alternative #1 - Excavation of Contaminated Soils**

The purpose of this action is to excavate contaminated soils, to the maximum extent possible and feasible, in order to prevent the lateral and vertical migration of contaminants into the groundwater and/or areas of clean soil. If soil or possible groundwater contamination persists after the excavation of soils, a soil and/or groundwater investigation and remediation are required by the Alameda County Water District. This action is discussed below as Alternative #2.

## Alternative #2 - Soil and Groundwater Investigation

The purpose of this action is two-fold: The first objective is to define the lateral and vertical extent of soil contamination; the second objective is to determine if groundwater has been impacted by petroleum hydrocarbon contamination.

Determination of the lateral and vertical extent of soil contamination may be achieved by the installation and sampling of exploratory borings. In order to determine the extent, the borings must be extended laterally until non-detectable concentrations are encountered in the soil samples from each boring and must be extended vertically to the top of the groundwater table.


To assess the possibility of groundwater contamination, at least one groundwater monitoring well must be installed in the confirmed down-gradient direction from the former tank location. If there is no confirmed direction of groundwater flow, then additional monitoring wells may be required by the Alameda County Water District.

Copies of this report should be sent to:

- Alameda County Health Agency - Hazardous Materials Division  
Attn: Ravi Arulanantham  
80 Swan Way Room 200  
Oakland, CA 94621
- Regional Water Quality Control Board  
UST Division  
2101 Webster Street Suite 500  
Oakland, CA 94621

### LIMITATIONS

The conclusions and professional guidelines presented herein were developed in accordance with generally accepted practice for addressing fuel leaks from underground storage tanks as outlined in the guidelines from the Alameda County Water District, Alameda County Health Agency, and the California Water Quality Control Board. Because the analytical results are based on data collected from the sampling locations only, TECC cannot have full knowledge of the underlying conditions at the site. Conditions at the project site may change with time due to the works of man and/or acts of nature. Accordingly, the findings of this report may be subject to change in light of new information.




Scale: 1 inch = 1/2 mile

SITE LOCATION MAP


Figure 1

WORKING TOWARDS A CLEANER ENVIRONMENT



SITE CHARACTERIZATION MAP

Figure 2



Scale: 1" = 20 feet

SAMPLING LOCATION MAP

Figure 3



APPENDIX A

TANK REMOVAL PERMITS



SERVING  
DUBLIN & SAN RAMON

# DOUGHERTY REGIONAL FIRE AUTHORITY

9399 Fircrest Lane  
San Ramon, CA 94583  
(Telephone) 415-829-2333

Invoice Number :91-253  
Date :Sep 19, 1991

Company Name :A.E.S.  
:775 MONTAGUE EXPWY  
:MILPITAS, CA  
:95035

Fee for Plan Review/Inspection  
Of:UNDERGROUD FUEL TANK REMOVAL  
:ONE TANK  
:  
:

Located at:7099 AMADOR VALLEY BLVD.  
:DUBLIN HONDA  
:  
:

In the City Of:DUBLIN

Total Amount Due:\$100.00

Please Make Check Payable to Dougherty Regional Fire Authority and  
Include a Copy of this Invoice With your Remittance

-----  
For Dept. Use Only

PD.      Date.                      X.                      A. N    A01-3680

**FIRE SPRINKLERS SAVE LIVES**


APPENDIX B

HAZARDOUS WASTE MANIFEST/CERTIFICATE OF DISPOSAL

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

90537777

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		Generator's US EPA ID No. C A C 0 0 0 6 2 6 1 2 0 0 0 0 0 1		Manifest Document No. 2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address DUBLIN HONDA 7099 Amador Plaza Road, Dublin, CA. 94568				A. State Manifest Document Number <b>90537777</b>	
4. Generator's Phone (610) 828-4638				B. State Generator's ID	
5. Transporter 1 Company Name H & H Ship Service Company		6. US EPA ID Number C A D 0 0 4 7 7 1 1 1 6 8		C. State Transporter's ID 200554	
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone (415) 643-4836	
9. Designated Facility Name and Site Address Frickson, Inc. 255 Parr Blvd. Richmond, Ca. 94801		10. US EPA ID Number C A D 0 0 9 4 6 6 3 9 2		E. State Transporter's ID	
				F. Transporter's Phone	
				G. State Facility's ID C A D 0 0 9 4 6 6 3 9 2	
				H. Facility's Phone (415) 236-1393	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)			12. Containers No.	13. Total Quantity	14. Unit Wt/Vol
a. Waste Empty Storage Tank NON-RCRA Hazardous Waste Solid			2	1005100	State Waste No. 512
b.					EPA/Other None
c.					State
d.					EPA/Other
J. Additional Descriptions for Materials Listed Above Qts: Empty Storage Tank (a) & Tank (a) have been inerted with 15 lbs. Dry Ice per 1000 Gals. Capacity.			K. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Keep away from sources of ignition. Always wear hardhats when working around U.S.T.'s. 24 Hr. Contact Name H & H Phone # (415) 543-4835. JOB #9378					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name Thomas Colegan		Signature Thomas Colegan		Month Day Year 11 10 1991	
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name JOSE J. MURENO		Signature Jose J. Moreno		Month Day Year 11 10 1991	
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.					
Printed/Typed Name		Signature		Month Day Year	



**ENVIRONMENTAL SERVICES**  
(DIVISION OF H&H SHIP SERVICE CO., INC.)

**CERTIFICATE OF DISPOSAL**

OCTOBER 04, 1991

H & H Ship Service Company hereby certifies to **THE ENVIRONMENTAL CONSTRUCTION** that:

1. The storage tank(s), size(s) **ONE (1) 500 GALS.**

removed from the **DUBLIN HONDA**

facility at **7099 AMADOR PLAZA ROAD**

**DUBLIN, CALIFORNIA**

were transported to H & H Ship Service Company, 220 China Basin St., San Francisco, California 94107.


2. The following tank(s), H & H Job Number **9378** have been steamed cleaned, cut with approximately 2' X 2' holes, rendered harmless and disposed of as scrap metal.

3. Disposal site: **LEVIN METALS COMPANY, RICHMOND, CALIFORNIA.**

4. The foregoing method of destruction/disposal is suitable for the materials involved, and fully complies with all applicable regulatory and permit requirements.

5. Should you require further information, please call (415) 543-4835.

Very Truly Yours,

  
Cleveland Valley  
Operations Coordinator

220 CHINA BASIN, SAN FRANCISCO, CA 94107 • DAY AND NIGHT: 543-4835



APPENDIX C

LABORATORY REPORT/CHAIN OF CUSTODY

# CHROMALAB, INC.

5 DAYS TURNAROUND

Analytical Laboratory (E694)

October 8, 1991

ChromaLab File No.: 1091014

THE ENVIRONMENTAL CONSTRUCTION CO. Attn: Ron LeGue

RE: Three soil samples for Gasoline/BTEX, Diesel, Oil & Grease, Cadmium, Chromium, Lead, Nickel, and Zinc analyses

Project Name: DUBLIN HONDA

Project Location: 7099 Amador Plaza Rd.

Project Number: 319

Date Sampled: Oct. 1, 1991

Date Submitted: Oct. 1, 1991

Date Extracted: Oct. 3-7, 1991

Date Analyzed: Oct. 3-7, 1991


## RESULTS:

Sample I.D.	Gasoline (mg/kg)	Diesel (mg/kg)	Benzene (µg/kg)	Toluene (µg/kg)	Ethyl Benzene (µg/kg)	Total Xylenes (µg/kg)
DH-1	82	N.D.	23	11	130	670
DH-2	11	N.D.	N.D.	N.D.	17	100
SP-1,2,3*	2.6	N.D.	5.0	34	16	140
BLANK	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
SPIKE REC.	98.0%	93.0%	89.3%	88.3%	89.5%	90.8%
DUP SPIKE REC	91.8%	100.7%	83.3%	84.2%	87.2%	82.7%
DET. LIMIT	1.0	1.0	5.0	5.0	5.0	5.0
METHOD OF ANALYSIS	5030/ 8015	3550/ 8015	8020	8020	8020	8020

Sample I.D.	Oil & Grease (mg/kg)	Cadmium (mg/kg)	Chromium (mg/kg)	Lead (mg/kg)	Nickel (mg/kg)	Zinc (mg/kg)
DH-1	2700	0.412	3.19	3.38	2.70	7.03
DH-2	820	0.483	3.59	3.79	3.04	7.26
SP-1,2,3*	3000	0.549	3.27	4.76	3.19	14.5
BLANK	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
SPIKE REC.	----	91.4%	88.7%	95.2%	94.6%	100.8%
DUP SPIKE REC	----	89.5%	90.1%	101.5%	93.0%	103.5%
DET. LIMIT	10	0.005	0.05	0.05	0.04	0.005
METHOD OF ANALYSIS	5520 E&F	7130	7190	7420	7520	7950

\*Composited soil sample.

ChromaLab, Inc.

  
David Duong  
Chief Chemist

  
Eric Tam  
Laboratory Director

# CHROMALAB, INC.

5 DAYS TURNAROUND

Analytical Laboratory (E694)

October 8, 1991

ChromaLab File # 1091014 A

Client: The Environmental Construction Company

Attn: Ron LeGue

Date Sampled: Oct. 01, 1991

Date Submitted: Oct. 01, 1991

Date Analyzed: Oct. 08, 1991

Project Name: Dublin Honda

Project Number: 319


Sample I.D.: DH-1

Method of Analysis: 8010


Detection Limit: 5.0 µg/kg

COMPOUND NAME	µg/kg	Spike Recovery	
CHLOROMETHANE	N.D.	---	---
VINYL CHLORIDE	N.D.	---	---
BROMOMETHANE	N.D.	---	---
CHLOROETHANE	N.D.	---	---
TRICHLOROFLUOROMETHANE	N.D.	91.8%	92.5%
1,1-DICHLOROETHENE	N.D.	---	---
METHYLENE CHLORIDE	N.D.	---	---
1,2-DICHLOROETHENE (TOTAL)	N.D.	---	---
1,1-DICHLOROETHANE	N.D.	---	---
CHLOROFORM	N.D.	96.8%	97.2%
1,1,1-TRICHLOROETHANE	N.D.	---	---
CARBON TETRACHLORIDE	N.D.	---	---
1,2-DICHLOROETHANE	N.D.	---	---
TRICHLOROETHENE	N.D.	---	---
1,2-DICHLOROPROPANE	N.D.	---	---
BROMODICHLOROMETHANE	N.D.	---	---
2-CHLOROETHYL VINYLETHER	N.D.	---	---
TRANS-1,3-DICHLOROPROPENE	N.D.	---	---
CIS-1,3-DICHLOROPROPENE	N.D.	---	---
1,1,2-TRICHLOROETHANE	N.D.	90.5%	93.7%
TETRACHLOROETHENE	85	---	---
DIBROMOCHLOROMETHANE	N.D.	---	---
CHLOROBENZENE	N.D.	---	---
BROMOFORM	N.D.	---	---
1,1,2,2-TETRACHLOROETHANE	N.D.	---	---
1,3-DICHLOROBENZENE	N.D.	---	---
1,4-DICHLOROBENZENE	N.D.	---	---
1,2-DICHLOROBENZENE	N.D.	96.1%	98.2%

ChromaLab, Inc.



David Duong  
Senior Chemist



Eric Tam  
Lab Director



# CHROMALAB, INC.

5 DAYS TURNAROUND

Analytical Laboratory (E694)

October 8, 1991

ChromaLab File # 1091014 B

Client: The Environmental Construction Company

Attn: Ron LeGue

Date Sampled: Oct. 01, 1991

Date Submitted: Oct. 01, 1991

Date Analyzed: Oct. 08, 1991

Project Name: Dublin Honda

Project Number: 319


Sample I.D.: DH-2

Method of Analysis: 8010

Detection Limit: 5.0 µg/kg

COMPOUND NAME	µg/kg	Spike Recovery	
CHLOROMETHANE	N.D.	---	---
VINYL CHLORIDE	N.D.	---	---
BROMOMETHANE	N.D.	---	---
CHLOROETHANE	N.D.	---	---
TRICHLOROFLUOROMETHANE	N.D.	91.8%	92.5%
1,1-DICHLOROETHENE	N.D.	---	---
METHYLENE CHLORIDE	N.D.	---	---
1,2-DICHLOROETHENE (TOTAL)	N.D.	---	---
1,1-DICHLOROETHANE	N.D.	---	---
CHLOROFORM	N.D.	96.8%	97.2%
1,1,1-TRICHLOROETHANE	N.D.	---	---
CARBON TETRACHLORIDE	N.D.	---	---
1,2-DICHLOROETHANE	N.D.	---	---
TRICHLOROETHENE	N.D.	---	---
1,2-DICHLOROPROPANE	N.D.	---	---
BROMODICHLOROMETHANE	N.D.	---	---
2-CHLOROETHYL VINYLETHER	N.D.	---	---
TRANS-1,3-DICHLOROPROPENE	N.D.	---	---
CIS-1,3-DICHLOROPROPENE	N.D.	---	---
1,1,2-TRICHLOROETHANE	N.D.	90.5%	93.7%
TETRACHLOROETHENE	20	---	---
DIBROMOCHLOROMETHANE	N.D.	---	---
CHLOROBENZENE	N.D.	---	---
BROMOFORM	N.D.	---	---
1,1,2,2-TETRACHLOROETHANE	N.D.	---	---
1,3-DICHLOROBENZENE	N.D.	---	---
1,4-DICHLOROBENZENE	N.D.	---	---
1,2-DICHLOROBENZENE	N.D.	96.1%	98.2%

ChromaLab, Inc.

  
David Duong  
Senior Chemist

  
Eric Tam  
Lab Director

# CHROMALAB, INC.

5 DAYS TURNAROUND

Analytical Laboratory (E694)

October 8, 1991

ChromaLab File # 1091014 C

Client: The Environmental Construction Company

Attn: Ron LeGue

Date Sampled: Oct. 01, 1991

Date Submitted: Oct. 01, 1991

Date Analyzed: Oct. 08, 1991

Project Name: Dublin Honda

Project Number: 319


Sample I.D.: SP-1,2,3 (COMPOSITE)

Method of Analysis: 8010

Detection Limit: 5.0 µg/kg

COMPOUND NAME	µg/kg	Spike Recovery	
CHLOROMETHANE	N.D.	---	---
VINYL CHLORIDE	N.D.	---	---
BROMOMETHANE	N.D.	---	---
CHLOROETHANE	N.D.	---	---
TRICHLOROFLUOROMETHANE	N.D.	91.8%	92.5%
1,1-DICHLOROETHENE	N.D.	---	---
METHYLENE CHLORIDE	N.D.	---	---
1,2-DICHLOROETHENE (TOTAL)	N.D.	---	---
1,1-DICHLOROETHANE	N.D.	---	---
CHLOROFORM	N.D.	96.8%	97.2%
1,1,1-TRICHLOROETHANE	N.D.	---	---
CARBON TETRACHLORIDE	N.D.	---	---
1,2-DICHLOROETHANE	N.D.	---	---
TRICHLOROETHENE	N.D.	---	---
1,2-DICHLOROPROPANE	N.D.	---	---
BROMODICHLOROMETHANE	N.D.	---	---
2-CHLOROETHYL VINYLETHER	N.D.	---	---
TRANS-1,3-DICHLOROPROPENE	N.D.	---	---
CIS-1,3-DICHLOROPROPENE	N.D.	---	---
1,1,2-TRICHLOROETHANE	N.D.	90.5%	93.7%
TETRACHLOROETHENE	84	---	---
DIBROMOCHLOROMETHANE	N.D.	---	---
CHLOROBENZENE	N.D.	---	---
BROMOFORM	N.D.	---	---
1,1,2,2-TETRACHLOROETHANE	N.D.	---	---
1,3-DICHLOROBENZENE	N.D.	---	---
1,4-DICHLOROBENZENE	N.D.	---	---
1,2-DICHLOROBENZENE	N.D.	96.1%	98.2%

ChromaLab, Inc.



David Duong  
Senior Chemist



Eric Tam  
Lab Director

