RMC PACIFIC MATERIALS



6601 KOLL CENTER PARKWAY P.O. BOX 5252 PLEASANTON, CALIFORNIA 94566 (925) 426-8787 • fax: (925) 426-2281 www.rmcpacific.com

12/29/2003

Robert Weston Alameda County Dept. Environmental Health 1131 Harbor Bay Parkway, Room 250 Alameda, Ca. 94502-6577 Alamada County

DEC 3 1 2003

Environmented Hacith

RE: RMC Pacific Materials - Eliot Aggregate Plant Fuel System Upgrade - Under Dispenser Soil Sampling Results 1544 Stanley Blvd., Pleasanton, CA.

Mr. Weston,

RMC Pacific Materials is submitting the attached report describing the results of a subsurface soil investigation at the above-referenced property. This report is being submitted as part of the SB 989 upgrade requirements to UST fuel systems at facility. The report describes the sampling protocol and results of laboratory analysis on a soil sample taken from directly beneath the gasoline dispenser.

If you have any questions or concerns, please contact me at (925) 426-2261.

Sincerely,

Robert Aldenhuysen

Environmental Supervisor

cc:

R. Bier

D. Tsuchida

B. Kelly

J. Robertson

Files



Submission#: 2003-11-0716

RMC Pacific Materials, Inc.

December 01, 2003

P.O. Box 5252 Pleasanton, CA 94566

Attn.:

Robert Aldenhuysen

Project:

EL10T

Dear Mr. Aldenhuysen,

Attached is our report for your samples received on 11/20/2003 15:01

This report has been reviewed and approved for release. Reproduction of this report is permitted only in its entirety.

Please note that any unused portion of the samples will be discarded after 01/04/2004 unless you have requested otherwise.

We appreciate the opportunity to be of service to you. If you have any questions, please call me at (925) 484-1919.

You can also contact me via email. My email address is: vvancil@stl-inc.com

Sincerely,

Vincent Vancil

Project Manager

SUBSURFACE SOIL INVESTIGATION REPORT RMC Pacific Materials - Eliot Aggregate Plant Under Dispenser Fuel System Upgrade

∪nder Dispenser Fuel System Upgrade 1544 Stanley Blvd., Pleasanton, CA.

INTRODUCTION

ĭ

This report describes the results of a subsurface soil investigation beneath the gasoline fuel dispenser at the above-referenced site. Analysis of the soil sample by a state certified laboratory indicates that petroleum contamination exists directly beneath the dispenser.

SAMPLING PROTOCOL

In late November 2003 both the gasoline and diesel UST fuel dispensers at the Eliot Aggregate Plant were upgraded with under-dispenser containment sumps to meet the SB 989 requirements. Mr. Robert Weston of the Alameda County Environmental Health Department was present to inspect the upgrade work and the sampling of soil beneath the dispensers.

Sampling under the gasoline dispenser began after approximately eighteen inches of compacted aggregate fill material was removed with a hand shovel. A 2-inch diameter hand auger was then used to dig into the native soil layer. Upon penetrating into the native soil layer the hand auger was removed and a 2-inch drive-sampler containing a clean laboratory supplied 2-inch brass sleeve was inserted into the hole. The sampler was then driven into the soil with a slide hammer until the sampling tube was completely filled with soil. The sampler was then extracted from the hole; the brass sleeve was removed from the sampler and soil sample packed down with latex-gloved hands. The ends of the brass sleeve were then covered with a clean section of plastic sheeting and laboratory provided end caps, leaving no space for volatilization of organic compounds. The sample was promptly labeled and then placed into a chilled ice chest for subsequent laboratory analysis at Severn Trent Laboratory (STL) in Pleasanton. Proper chain-ofcustody protocol was maintained at all times. An attempt to sample the soil beneath the diesel dispenser proved unsuccessful due to the thick volume of aggregate fill material underlying that dispenser, making it very difficult to excavate the aggregate without caving in the sidewalls before reaching native soil. After a brief discussion with Mr. Weston it was decided that a sample would not be required due to the small amount of contaminated gravel observed and the sampling conditions. All petroleum contaminated aggregate material removed during the dispenser upgrade and sampling of the two dispenser areas was placed into two sealed 55-gallon drums for later, manifested, off-site disposal (copy of manifest to be supplied at a future date).

Results of Analysis

The soil sample taken from beneath the gasoline dispenser was analyzed by STL for TPH-gasoline, BTEX and MTBE (EPA method 8015M/8021B). Laboratory analyses indicate that petroleum contamination was detected in the soil sample. The concentration of gasoline in the sample was found to be 2,300 mg/Kg. The levels of BTEX were as follows: Benzene - 12 mg/Kg, toluene - 110 mg/Kg, ethyl benzene - 53 mg/Kg, and xylene - 260 mg/Kg. The analysis for MTBE indicated a level of 71 mg/Kg. The results of analysis are presented in Table 1. A copy of the laboratory report and the chain-of-custody are included in Appendix A.

Conclusions

Based on the laboratory analysis of the soil sample detectable concentration levels of petroleum contamination exist under the site's gasoline dispenser. The fuel upgrade contractor (Reinholdt Engineering Construction) had not reported finding any loose or leaking connections during any of the previous annual inspections or upgrade repairs to the system. RMC contends that this contamination is surficial and that it most likely came from the accumulation of minor fuel spillage running down through small joint cracks in the concrete pad during the filling of site vehicles. RMC knows that the groundwater level under the plant is at approximately 125 feet below surface grade and has therefore not been affected. RMC requests that site clean up be postponed until the UST system is removed in the coming years. For the foreseeable future RMC has instituted new underdispenser inspection procedures to monitor the system on a routine basis.

Alamada County

DEC 3 1 2003

Environmanicii Hecim.

Appendix A

Laboratory Results of Analysis

Table 1


Eliot Aggregate Plant Results of Analysis - Gas/BTEX Compounds

Under Dispenser Soil Sampling

Sample Sample Sample Gasoline Benzene Toluene Ethyl-benzene Xylene MT Date ID Depth¹ (mg/Kg) (mg/Kg) (mg/Kg) (mg/Kg) (mg/Kg) (mg/Kg) (mg/Kg)									
	Sample	Sample	Sample	Gasoline	Benzene	Toluene		Xylene	MTBE
	Date	ID	Depth ¹	(mg/Kg)	(mg/Kg)	(mg/Kg)	(mg/Kg)	(mg/Kg)	(mg/Kg)
11/20/2003 G-1 3 2300 12 110 53 260 71	11/20/2003	G-1	3	2300	12	110	53	260	71

Notes:

^{1 =} feet below surface grade





RMC Pacific Materials, Inc. Attn.: Robert Aldenhuysen

P.O. Box 5252 Pleasanton, CA 94566

Phone: (925) 426-2261 Fax: (925) 426-2231

Project: EL10T

Received: 11/20/2003 15:01

Samples Reported

Sample Name	Date Sampled	Matrix	Lab#
G-1	11/20/2003 13:55	Soil	1





RMC Pacific Materials, Inc. Attn.: Robert Aldenhuysen

P.O. Box 5252

Pleasanton, CA 94566

Phone: (925) 426-2261 Fax: (925) 426-2231

Project: EL10T

Received: 11/20/2003 15:01

Prep(s): 5030

5030

Test(s):

8015M

8021B

Sample ID: G-1

_ .

Lab ID:

2003-11-0716 - 1

Sampled:

11/20/2003 13:55

Extracted:

11/25/2003 14:05

Matrix: Soil

QC Batch#:

2003/11/25-05.05

Compound	Conc.	RL	Unit	Dilution	Analyzed	Flag
Gasoline	2300	100	mg/Kg	10.00	11/25/2003 14:05	
Benzene	12	6.2	mg/Kg	10.00	11/25/2003 14:05	
Toluene	110	6.2	mg/Kg	10.00	11/25/2003 14:05	
Ethyl benzene	53	6.2	mg/Kg	10.00	11/25/2003 14:05	
Xylene(s)	260	6.2	mg/Kg	10.00	11/25/2003 14:05	
MTBE	71	6.2	mg/Kg	10.00	11/25/2003 14:05	
Surrogate(s)						
Trifluorotoluene	NA	53-125	%	1.00	11/25/2003 14:05	sd
4-Bromofluorobenzene-FID	NA	58-124	%	1.00	11/25/2003 14:05	sd





RMC Pacific Materials, Inc. Attn.: Robert Aldenhuysen

P.O. Box 5252

Pleasanton, CA 94566

Phone: (925) 426-2261 Fax: (925) 426-2231

Project: EL10T

Received: 11/20/2003 15:01

Batch QC Report

Prep(s): 5030 Method Blank

MB: 2003/11/25-05.05-001

Soil

Test(s): 8015M

QC Batch # 2003/11/25-05.05

Date Extracted: 11/25/2003 10:29

Compound	Conc.	RL	Unit	Analyzed	Flag
Gasoline	ND	10	mg/Kg	11/25/2003 10:29	
Benzene	ND	0.62	mg/Kg	11/25/2003 10:29	
Toluene	ND	0.62	mg/Kg	11/25/2003 10:29	
Ethyl benzene	ND	0.62	mg/Kg	11/25/2003 10:29	
Xylene(s)	ND	0.62	mg/Kg	11/25/2003 10:29	
MTBE	ND	0.62	mg/Kg	11/25/2003 10:29	
Surrogates(s)					
Trifluorotoluene	101.6	53-125	%	11/25/2003 10:29	
4-Bromofluorobenzene-FID	112.4	58-124	%	11/25/2003 10:29	





RMC Pacific Materials, Inc. Attn.: Robert Aldenhuysen

P.O. Box 5252 Pleasanton, CA 94566

Phone: (925) 426-2261 Fax: (925) 426-2231

Project: EL10T

Received: 11/20/2003 15:01

Batch QC Report

Prep(s): 5030

Test(s): 8021B

Laboratory Control Spike

Soil

QC Batch # 2003/11/25-05.05

LCS

2003/11/25-05.05-002

Extracted: 11/25/2003


Analyzed: 11/25/2003 11:01

LCSD 2003/11/25-05.05-003

Extracted: 11/25/2003

Analyzed: 11/25/2003 11:32

Compound	Conc.	mg/Kg	Exp.Conc.	Reco	very %	RPD	Ctrl.Lim	its %	Fla	ıgs
	LCS	LCSD		LCS	LCSD	%	Rec.	RPD	LCS	LÇSD
Benzene	0.120	0.126	0.125	96.0	100.8	4.9	77-123	35		
Toluene	0.125	0.130	0.125	100.0	104.0	3.9	78-122	35		
Ethyl benzene	0.117	0.124	0.125	93.6	99.2	5.8	70-130	35		
Xylene(s)	0.376	0.395	0.375	100.3	105.3	4.9	75-125	35		
Surrogates(s)									1	
Trifluorotoluene	543	561	500	108.6	112.2		53-125	0		





RMC Pacific Materials, Inc. Attn.: Robert Aldenhuysen

P.O. Box 5252 Pleasanton, CA 94566

Phone: (925) 426-2261 Fax: (925) 426-2231

Project: EL10T

Received: 11/20/2003 15:01

Batch QC Report

Prep(s): 5030

Test(s): 8015M

Laboratory Control Spike

Soil

QC Batch # 2003/11/25-05.05

LCS

2003/11/25-05.05-004

Extracted: 11/25/2003

Analyzed: 11/25/2003 09:55 Analyzed: 11/25/2003 10:27

LCSD

2003/11/25-05.05-005

Extracted: 11/25/2003

Compound	Conc.	mg/Kg	Exp.Conc.	Reco	vегу %	RPD	Ctrl.Lim	its %	Fla	igs
	LCS	LCSD		LCS	LCSD	%	Rec.	RPD	LCS	LCSD
Gasoline	0.635	0.651	0.625	101.6	104.2	2.5	75-125	35		
Surrogates(s)				İ						
4-Bromofluorobenzene-FID	535	552	500	107.0	110.4		58-124			





RMC Pacific Materials, Inc. Attn.: Robert Aldenhuysen

P.O. Box 5252 Pleasanton, CA 94566

Phone: (925) 426-2261 Fax: (925) 426-2231

Project: EL10T

Received: 11/20/2003 15:01

Legend and Notes

Result Flag

sd

Surrogate recovery not reportable due to required dilution.



Reference # 80454

					\wedge		Iaii.	Olu	Cilius	-			, (Y	٠.	Jale /	11 M	103	Го	ige	`	" <u></u>	
Report To													Requ	est									
Attn: ROB ALDER	VHU4 SE	w				:X hanol		3)			608 608			≾ ı				14					
Company: PMC PAC	1FIC		8260B ATBE	8	ca Ge ther	O BTE		vocs		enu		8310		II RCRA		E ()	Alkalinity TDS	□ NO₃ □					
Address: PO BOX Phone (925) 426 226/ Ema	<u>5252</u>		2 ×	0 826	Sii C	⊐ Gas XA, EDI	SUC	5/MS (. SS	Petrol Total	EPA 8081 EPA 8082		Ê	JFT C		romiu me fo	D Ak	200					ιņ
			188E	atic:		98: I	arb 021	s GC	2/M/S		PA PA	8270	747		9	t Ch		SO. D					aine.
Bill To:	Sampled By	y:	- D 8015/8021 CD 8260B	Purgeable Aromatics BTEX EPA - □ 8021 □ 8260B	TEPH EPA 8015M ☐ Silica Gel	Fuel Tests EPA 82608: □ Gas □ BTEX □ Five Oxyenates □ DCA, EDB □ Ethanol	Purgeable Halocarbons (HVOCs) EPA 8021	Volatile Organics GC/MS (VOCs)	Semivolatiles GC/MS □ EPA 8270 □ 625	Oil and Grease D Petroleum (EPA 1664) D Total			CAM17 Metals (EPA 6010/7470/7471)	Metals: ☐ Lead ☐ LUFT ☐ Other:	W.E.T (STLC) TCLP	Hexavalent Chromium pH (24h hold time for H ₂ O)	c Coná.	0 di					Number of Containers
Attn:	Phone:		TPH EPA	geable	PH EP	Tests Five Oxy	geable 'OCs)	atile O EPA 8	nivotat EPA 8	and G A 166	Pesticides PCBs	PNAs by	M17 M A 601	als: □)ther:	N T	Hex)	Spec (TSS						nber o
Sample ID Date	e Time	Mat Pres rix erv.	Ĕ×	PLE	12 1	- F	₽.	Voli	Ser	<u>e</u>	9 P	a Z	CEP CAI	Met		00	00	Anions					ş
G-/ /20/	13 13 ⁵⁵ 5	SCR N/A	X															ļ 					
•			ļ .											,,	ļ			ļ					
· · · · · · · · · · · · · · · · · · ·														<u>.</u>	ļ			<u> </u>					
			 		<u> </u>					, <u>.</u>		<u></u>						<u> </u>					
												·											\vdash
			-												-						}		
						· .									 			 					\vdash
	-															·							\square
			;															i					
Project Info.		e Receip	ot		(1) Re	linguish	ed by:	1/7	4	(101 (206)	2) F	Relinquis	shed by	-			3)	Relinqu	uished t	y:			
Proct Name:	# of Con	tainers:			Signa	iture	366	Sa_		<u> </u>	Sign	nature			Τέ	me	- <u>-</u>	gnature			 1	ime	_
Project#:	Head Sp	ace:	-		R	SERT	- AL	DEN	44 S	1206.	.3							J					
PO#:	Temp:		4.0	0_	Printe	ed Name	9		Da	te	Prin	ited Nar	ne			Date		rinted N	ame			Date	_
Credit Card#:	Conform	s to record:	7.0		Comp	pany .	164	CIF		747E	Cor	npany			.		- c	ompany	ı				-
T	_														·	T1720 T2 2		`					
A 5 Day 72h 48h 24h	Other:	,			1) Re	ceived I	by:				2) F	Received	d by:			ν.	3)	Receiv	ed by:	Law	mot	Q.	
Report Routine Level 3 D	Level 4 DE	DD ☐ State ☐ Globa		EDF	Signa	ture			Ţim	e	Sigi	nature			Ti	me	Si	gnature	<u>;</u>			ime	_
				_	Printe	ed Name			Da	te	Prin	ited Nar	me		·······································	ate	$-\mid \frac{\ell}{P_0} \mid$	rinted N	avv ame	ing	ton	/50 Date	ソ
•							_						- · · -		-	-,0			- 5 ₁ =	_ /	1/20	/4-2	
					Comp	pany					Cor	прапу					_ _	ompany			, -/	<i></i>	_
u ₹											1						1					Rev 0	17 <i>1</i> 02



STL San Francisco

Sample Receipt Checklist

Submission #:2003- 1 - 0716	
Checklist completed by: (initials) Date: 1 / 20/03	
Courier name: STL San Francisco Client	Not
Custody seals intact on shipping container/samples	Yes No Present
Chain of custody present?	Yes No
Chain of custody signed when relinquished and received?	YesNo
Chain of custody agrees with sample labels?	YesNo
Samples in proper container/bottle?	YesNo
Sample containers intact?	YesNo
Sufficient sample volume for indicated test?	YesNo
All samples received within holding time?	L D YesNo
Container/Temp Blank temperature in compliance (4 $^{\circ}$ C \pm 2)?	Temp: TC Yes No
	Ice Present YesNo
Water - VOA vials have zero headspace?	No VOA vials submitted Yes No
Water - pH acceptable upon receipt? ☐ Yes ☐ No Arcl ☐ pH adjusted— Preservative used: ☐ HNO₃ ☐ HCl ☐ H₂SO₄ ☐ NaOH ☐ For any item check-listed "No", provided detail of discrepancy in comme Comments: ← Lux from Damplug	
Project Management [Routing for instruction of indicate	ed discrepancy(ies)]
Project Manager: (initials) Date:/03	
Client contacted: ☐ Yes ☐ No	
Summary of discussion:	
	the state of the s
The state of the s	
Corrective Action (per PM/Client):	
Corrective Action (per PM/Client):	