QUARTERLY GROUNDWATER MONITORING LIVERMORE ARCADE SHOPPING CENTER FIRST STREET AND SOUTH P STREET LIVERMORE, CALIFORNIA

3/18/21

Prepared for:

Grubb & Ellis Realty Income Trust One Montgomery Street West Tower, 32nd Floor San Francisco, California 94104

Prepared by:

Hygienetics, Inc. 2200 Powell Street, Suite 880 Emeryville, California 94608

March 18, 1991

Project No. 48016.04

MW4/R0318ARC

TABLE OF CONTENTS

		PAGE
1.1	Purpose and Scope of Work	1
1.2	Site Location	1
1.3	Site Description	1
1.4	Introduction	1
1.5	Groundwater Monitoring Well Installation	2
1.6	Groundwater Sampling and Analysis	2
1.7	Results and Discussion	4

TABLES

TABLE 1 SUMMARY OF ANALYTICAL RESULTS FOR GROUNDWATER SAMPLES

FIGURES

FIGURE 1 SITE LOCATION MAP

FIGURE 2 PCE CONCENTRATION DISTRIBUTION AND WELL LOCATION MAP

APPENDICES

APPENDIX A ANALYTICAL RESULTS FOR GROUNDWATER SAMPLES

APPENDIX B CHAIN OF CUSTODY RECORDS

APPENDIX C LIMITATIONS

1.1 Purpose and Scope of Work

This is the first quarterly groundwater monitoring report performed at the Livermore Arcade Shopping Center property located in Livermore, California, hereinafter referred to as the "Site." The investigation was conducted on behalf of Grubb & Ellis Realty Income Trust, referred to in this report as "Grubb & Ellis."

The purpose of this investigation is to monitor the concentration of tetrachloroethene (also known as perchloroethylene, perk, or PCE) discovered in the groundwater at the Site. Benzene, toluene, total xylene isomers, and ethylbezene (BTXE), common components of gasoline, were also detected in the groundwater at the Site.

Hygienetics will evaluate the analytical results and present findings to the Regional Water Quality Control Board (RWQCB) on behalf of Grubb & Ellis. This investigation is subject to the terms and limitations included as Appendix C of this report.

1.2 Site Location

Livermore is located approximately 25 miles east of San Francisco Bay along Highway 580 (Figure 1). The Livermore Arcade Shopping Center is located at the northwest corner of First Street and South P Street in downtown Livermore, California. Railroad Avenue borders the Site to the north. South S Street borders the Site to the west.

1.3 Site Description

The Site is listed at the Alameda County Assessor's Office on Map 98, Page 403, Parcel 8-4. The Livermore Arcade Shopping Center, which was built in 1972, houses fourteen businesses [twelve (12) retail stores and two (2) restaurants]. The Site occupies approximately 11.75 acres, including the asphalt parking areas. Site topography is relatively flat with runoff moving to the north and west. Ornamental vegetation consists of grass, ivy, bushes, and small trees. The Site is located in a critical groundwater recharge area.

1.4 Introduction

Hygienetics is currently working on the final design of a groundwater extraction system which was approved by the Alameda County Department of Environmental Health and the State of California Regional Water Quality Control Board. The quarterly

monitoring plan began on March 5, 1991, when Hygienetics collected a groundwater sample from each of the five monitoring wells shown in Figure 2. These wells were chosen as the best sampling locations to monitor the PCE concentrations over time.

1.5 Groundwater Monitoring Well Installation

Monitoring wells were installed at various times between March and October 1990. The monitoring wells were constructed in accordance with the Alameda County Zone 7 permitting and construction procedures. Monitoring wells were constructed of 2.0 and 4.0 inch inner diameter, flush-jointed, Schedule 40 PVC risers attached to factory-perforated, slotted PVC well screen sections. The base of each well was fitted with a threaded PVC The annuli between the screen and the auger hole were packed with #2 or #3 Grade Monterey Sand to at least two feet above the screen. A three-foot thick bentonite pellet plug was then placed above the sand. The remaining annular spaces around the riser sections were grouted with neat cement to near grade. A cast iron christie box, with galvanized steel apron, was set in concrete over each well and finished flush with the surrounding asphalt. The top of each well casing was fitted with a watertight, locking cap.

1.6 Groundwater Sampling and Analysis

A groundwater sample was collected from each of the five wells on March 5, 1991. Prior to sampling, a minimum of three standing volumes of water were purged from each well utilizing a precleaned teflon bailer. The associated equipment was cleaned between each well with de-ionized water to minimize the potential for cross contamination. All samples were immediately placed on ice and transported under chain of custody protocol to BC Analytical in Emeryville, California. Chain of custody records are included in Appendix B.

The groundwater samples were analyzed for volatile organics by EPA Method 624. The level of the PCE concentration detected at each groundwater monitoring well is listed in Table 1. The laboratory data is included in Appendix A.

TABLE 1
Summary of Analytical Results

Groundwater Samples

Sample <u>Location</u>	<u>Parameter</u>	Concentration (ug/1)	Date <u>Sampled</u>
MW6	Tetrachloroethene*	43	03/05/91
MW7	Trichloroethene Tetrachloroethene* cis-1,2-Dichloroethene	190 1,700 37	03/05/91
MW9	Chloroform	2	03/05/91
MW13	Tetrachloroethene*	34	03/05/91
MW14	Methylene Chloride	6	03/05/91

1.7 Results and Discussion

The aerial extent of the PCE plume has remained the same as previously shown in Hygienetics Subsurface Investigation, October 12, 1990 (Figure 2).

The PCE concentration in groundwater at monitoring well MW7 increased from 900 ug/l, as reported in the October 1990 report, to 1700 ug/l detected in this recent sampling. Compounds suspected to be degradation products of the PCE are present in the groundwater at monitoring well MW7.

No gasoline compounds were detected in this latest groundwater sampling.

^{*} Also known as perchloroethylene, perk, PCE

mg/l = micrograms per liter (equivalent to parts per billion)

Methylene chloride, detected in the groundwater samples collected from monitoring well MW14, is a solvent commonly used in laboratories as part of the extraction process. It is sometimes accidentally introduced to the sample during the analysis.

Chloroform was detected in groundwater at monitoring well MW9. In this case, it may be a by-product of chlorine which is used as a disinfectant in potable water systems.

The next quarterly sampling of these monitoring wells will be in June 1991.


Sincerely,

HYGIENETICS, INC.

Michael Wright, #.E.A. Environmental Geologist

MW:nnp/48016.04


MW4/R0318ARC



Architects / Engineers **Environmental Consultants** Livermore, California REV. DATE DESCRIPTION

FIGURE 2

PCE CONCENTRATION DISTRIBUTION AND WELL LOCATION MAP



MAKEPEACE

APPENDIX A

ANALYTICAL RESULTS FOR GROUNDWATER SAMPLES

Analytical Report

LOG NO: E91-03-113

Received: 05 MAR 91 Mailed : 21 MAR 91

Mr. Michael Wright Hygienetics 2200 Powell Street Suite 1095 Emeryville, California 94608

Project: Arcade

REPORT OF ANALYTICAL RESULTS

Page 1

LOG NO SAMPLE DESCRIPTION, G	ROUND WATE	ER SAMPLES		DA'	re sampled
03-113-1 MW-6 03-113-2 MW-7 03-113-3 MW-9 03-113-4 MW-13 03-113-5 MW-14	·	. .	\		05 MAR 91 05 MAR 91 05 MAR 91 05 MAR 91 05 MAR 91
PARAMETER	03-113-1	03-113-2	03-113-3	03-113-4	03-113-5
Volatile Organics (EPA 624) Date Analyzed	03.07.91	03.12.91	03.07.91 03.07.91	03.07.91 03.07.91	03.15.91 03.15.91
Date Extracted Dilution Factor, Times	03.07.91	03.12.91 20	1	1	1
_ 1,1,1-Trichloroethane, ug/L	<1	<20	<1	<1	<1
1,1,2,2-Tetrachloroethane, ug/L	<1	<20	<1	<1	<1 <1
1,1,2-Trichloroethane, ug/L	<1	<20	<1	<1 <1	<1
1,1-Dichloroethane, ug/L	<1	<20	<1 <1	<1	<1
1,1-Dichloroethene, ug/L	<1	<20	<1 <1	<1	<1
1,2-Dichloroethane, ug/L	<1	<20 <20	<1	<1	<1
1,2-Dichlorobenzene, ug/L	<1 <1	<20	<1	<1	<1
1,2-Dichloropropane, ug/L	<1	<20	<1	<1	<1
1,3-Dichlorobenzene, ug/L	<1	<20	<1	<1	<1
<pre>1,4-Dichlorobenzene, ug/L 2-Chloroethylvinylether, ug/L</pre>	<1	<20	<1	<1	<1
2-Hexanone, ug/L	<1	<20	<1	<1	<1
4-Methyl-2-Pentanone, ug/L	<1	<20	<1	<1	<1
Acetone, ug/L	<10	<200	<10	<10	<10
Acrolein, ug/L	<10	<200	<10	<10	<10
Acrylonitrile, ug/L	<10	<200	<10	<10	<10
Bromodichloromethane, ug/L	<1	<20	<1	<1	<1
Bromomethane, ug/L	<1	<20	<1	<1	<1
Benzene, ug/L	<1	<20	<1	<1	<1

B C A

Analytical Report

LOG NO: E91-03-113

Received: 05 MAR 91 Mailed : 21 MAR 91

Mr. Michael Wright
Hygienetics
2200 Powell Street Suite 1095
Emeryville, California 94608

Project: Arcade

REPORT OF ANALYTICAL RESULTS

Page 2

LOG NO SAMPLE DESCRIPTION,	GROUND WATE	R SAMPLES		DA?	E SAMPLED
00 110 1 NT C					05 MAR 91
03-113-1 MW-6					05 MAR 91
03-113-2 MW-7					05 MAR 91
03-113-3 MW-9					05 MAR 91
03-113-4 MW-13 03-113-5 MW-14					05 MAR 91
02-112-2 Hu-14					
PARAMETER	03-113-1	03-113-2	03-113-3	03-113-4	03-113-5
Bromoform, ug/L		<20	<1	<1	<1
Chlorobenzene, ug/L	<1	<20	<1	<1	<1
Carbon Tetrachloride, ug/L	<1	<20	<1	<1	<1
Chloroethane, ug/L	<1	<20	<1	<1	<1
Chloroform, ug/L	1	<20	2	<1	<1
Chloromethane, ug/L	<1	<20	<1	<1	<1
Carbon Disulfide, ug/L	<1	<20	<1	<1	<1
Dibromochloromethane, ug/L	<1	<20	<1	<1	<1
Ethylbenzene, ug/L	<1	<20	<1	<1	<1
Freon 113, ug/L	<1	<20	<1	<1	<1
Methyl ethyl ketone, ug/L	<20	<400	<1	<20	<20
Methylene chloride, ug/L	<5	<100	<5	<5	6
Styrene, ug/L	<1	<20	<1	<1	<1
Trichloroethene, ug/L	<1	190	<1	<1	<1 <1
Trichlorofluoromethane, ug/L	<1	<20	<1	<1	<1
Toluene, ug/L	<1	<20	<1	<1	<1
Tetrachloroethene, ug/L	43	1700	<1	34	<1
Vinyl acetate, ug/L	<1	<20	<1	<1	<1
Vinyl chloride, ug/L	<1	<20	<1	<1	<1
Total Xylene Isomers, ug/L	<1	<20	<1	<1	<1
cis-1,2-Dichloroethene, ug/L	<1	37	<1	<1 <1	<1
cis-1,3-Dichloropropene, ug/L trans-1,2-Dichloroethene, ug/L	<1 <1	<20 <20	<1 <1	<1	<1
1					

BCA

Analytical Report

LOG NO: E91-03-113

Received: 05 MAR 91 Mailed : 21 MAR 91

Mr. Michael Wright Hygienetics 2200 Powell Street Suite 1095 Emeryville, California 94608

Project: Arcade

REPORT OF ANALYTICAL RESULTS

Page 3

LOG NO	SAMPLE DESCRIPTION,	GROUND WA	TER SAMPLES		DA	TE SAMPLED
03-113-1 03-113-2 03-113-3 03-113-4 03-113-5	MW-6 MW-7 MW-9 MW-13 MW-14					05 MAR 91 05 MAR 91 05 MAR 91 05 MAR 91 05 MAR 91
PARAMETER		03-113-1	03-113-2	03-113-3	03-113-4	03-113-5
trans-1,3-	Dichloropropene, ug/	L <1	<20	<1	<1	<1

Sim D. Lessley, P.D., Laboratory Director

D C A

CHAIN OF CUST	_	BCA Log Number				
Client name	Project or PO#		7	nalyses required	/ :	
Address 2700 Powell St.	Phone 547 38	% /		////	, , , , , , , , , , , , , , , , , , ,	
City Stale, Zip Fred Ville 94608	Report Alention Wright	_	\forall / / /			3
tab Type Sampled by	1 .	mber				
Sample Date Time See key number sampled sampled below		of ainers			Remarks	
MU63/5 2:50m GW 40	ml VQA	1				
73/5 3:45 GW 40	ml UDA	1 /				
93/5 2:15 BW 4B	ml VOA	1 (/				
13 3/5 1:45 GW 40	ml NOA	1 //				
	ml UBA		_			
					·	
	9					
	Print Name		Company	<u> </u>	Date	Time
Signature / Relinquished by	Michael Wright	HUAI	enetic	. 5	3/5/715	1:50p
Received by	D. THONGKHAM	BUA			75/71 1	1:50
Relinquished by						
Received by		•				
Relinquished by						
Received by Laboratory		, <u></u>	Ţ;			
B C ANALYTICAL 1255 Powell Street, Emeryville, CA 94608 (415) 428-2300 801 Western Avenue, Glendale, CA 91201 (818) 247-5737	Note: Samples are discarded 30 days after results are reg Hazardous samples will be returned to client or dis Disposal arrangements:	posed of all client's expense	e .	KEY, AQ—Aqueous N/ GW-Groundwater SO-	t-Nonaqueous St -Soil OT-Other P	- Sludge 'EPetroleum

1200 Pacifico Avenue, Anaheim, CA 92805 (714) 978-0113

Limitations

The findings set forth in the attached Site Assessment Report are strictly limited in time and scope to the date of the evaluation(s). The conclusions presented in the Report are based solely on the services described therein, and not on scientific tasks of procedures beyond the scope of agreed upon services or the time and budgeting restraints imposed by the client.

The purpose of this report was to assess the physical characteristics of the subject Site with respect to the presence in the environment of hazardous material or oil. No specific attempt was made to check on the compliance of present or past owners or operators of the Site with federal, state or local laws and regulations; environmental or otherwise.

Partial findings of this investigation are based on data provided by others. No warranty is expressed or implied with the usage of such data. Much of the information provided in this report is based upon personal interviews and research of available documents, records and maps held by the appropriate government and private agencies. This is subject to the limitations of historical documentation, available and accuracy of pertinent records, and the personal recollection of those persons contacted by Hygienetics.

Observations were made of the Site and of structures on the Site as indicated within the Report. Where access to portions of the Site or structures on the Site were unavailable or limited. Hygienetics is unable to render an opinion as to the presence or indirect evidence relating to hazardous material or oil, in that portion of the Site or structure. In addition, Hygienetics renders no opinion as to the presence of hazardous material or oil, where direct observations of the interior walls, floors or ceilings of a structure on a Site was obstructed by objects or coverings on or over these surfaces.

The initial Site investigation took into account the natural and manmade features of the Site, including any unusual or suspect phenomenon. These factors combined with the Site's geology, hydrology, topography, and past and present land uses served as a basis for choosing a methodology and location for surface sampling, indeed surface sampling was conducted. The surface data, if provided is meant as a representative overview of the Site. The conclusions and recommendations contained in this report may be based in part upon various types of chemical data and are contingent upon their validity. As indicated within the Report, some of these data are preliminary "screening" level data, and should be confirmed with qualitative analysis if more specific information is necessary. It should be noted that variations is the types and concentrations of contaminants and variations in their flow paths may occur due to seasonal water table fluctuations, past disposal practices, the passage of time and other factors. Should additional data or variations of current data become available in the future, this data should be reviewed, and the conclusions and recommendations presented herein modified accordingly.

Chemical analysis may have been performed for specific parameters during the course of this Site assessment, as described in the text. However, it should be noted that additional chemical constituents not searched for during the current study may be present in soil and/or groundwater at the Site.

The presence of radioactive materials, biological hazards and asbestos was not investigated unless specifically noted otherwise.