

## Jakub, Barbara, Env. Health

---

**From:** Foss, Bob (Robert) [bfoss@croworld.com]  
**Sent:** Monday, November 22, 2010 3:19 PM  
**To:** Jakub, Barbara, Env. Health  
**Cc:** schrag@nady.com  
**Subject:** RE: Floor drain  
**Attachments:** IMG2176.JPG; IMG2172.JPG; IMG2173.JPG; IMG2174.JPG; IMG2175.JPG; IMG2170.JPG

It appears to be just a core through the concrete and into the subsurface. There is no evidence that a drain pipe ever existed and was either removed or rusted away. There is another core approximately 1 ft (+/-) toward the northeast from the "main" one and that does not show any remnant of a pipe either. Take a look at the attached photos for more detail on this. IMG2170 shows that the tenants have placed a fountain directly above this circular depression. IMG2172 shows the two holes after the fountain was moved. IMG2172 is taken looking approx east. Our original thought was that this "drain" traced toward the northeast and connected to the storm drain/sanitary sewer running northward toward the street in the breezeway. However, as you can see from the photos, there is no pipe leading away from these two holes in that direction.

**Robert C. Foss, P.G.**  
**Conestoga-Rovers & Associates (CRA)**  
**5900 Hollis Street, Suite A**  
**Emeryville, CA 94608**  
**(510) 420-3348 office**  
**(925) 413-8707 cell**  
**(510) 420-9170 fax**

---

**From:** Jakub, Barbara, Env. Health [<mailto:barbara.jakub@acgov.org>]  
**Sent:** Monday, November 22, 2010 3:03 PM  
**To:** Foss, Bob (Robert)  
**Subject:** Floor drain

Bob,

Is that floor drain at the 1167 address connected to anything? I don't see the lines on the new map.

Barbara Jakub, P.G.  
Hazardous Materials Specialist  
Alameda County Environmental Health  
1131 Harbor Bay Pky.  
Alameda, CA 94502  
Direct: 510-639-1287  
Fax: 510-337-9335

PDF copies of case files can be downloaded at:

<http://www.acgov.org/aceh/lop/ust.htm>











