

PHOTOS TAKEN BY RON OWCARZ  
AT UGT MODIFICATION AT VICKY  
SHELL, 2120 MONTANA ST. IN OAK.  
ON 7/6, 7/19 + 7/20/93



7/20/93-Photo taken by Ron Owcasz at Bansal Shell, 2120 Montana Ave. in Oak. Red caps indicate soil sample locations in side wall of pit overexcavation for UGT pipe med. @



7/20/93 Photo taken by Ron Owcasz at Shell station @ 2120 Montana Ave. in Oak for piping of UGT med. where soil contamination was found at pit overexcavation. @



7/20/93-Photo taken by Ron Owcasz at Bansal Shell, 2120 Montana Ave. Oak. Shown is soil cont. at side wall of pit overexcavation for UGT pipe med. @



7/19/93-Photo taken by Ron Swartz at Banzal  
Shell, 2120 Montana Ave. Oak shown is Allison  
Watts taking soil samples at pit overexcavation. Ⓜ



7/19/93-Photo taken by Ron Swartz at Banzal  
Shell, 2120 Montana Ave. Oak shown is Allison  
Watts taking soil samples after pit reexcavation. Ⓜ





7/6/93 - Photo taken by <sup>2215117976-B</sup> Ron Owsatz at Bansal shell, 2120 Montana Ave, Oak. Shown is Allison Watts taking soil sample in side wall of pit where cont. was found at old piping node. (R)



7/6/93 - Photo taken by <sup>2215117976-B</sup> Ron Owsatz at Bansal shell, 2120 Montana Ave, Oak. Shown is Allison Watts taking soil sample at end of old piping where some soil cont. was observed. (R)



7/6/93 - Photo taken by <sup>2215117976-B</sup> Ron Owsatz at Bansal shell, 2120 Montana Ave. Oak. Shown is new sump that failed sump test twice. Also note soil cont. at side well adjacent to it. (R)



7/6/93 - Photo taken by Ron Cuccare at Banzal  
Shell, 2120 Hartana Ave, Oak. Shown is soil sample  
location at end of old pipe line for UST med. ②



7/6/93 - Photo taken by Ron Cuccare at Banzal  
Shell, 2120 Hartana Ave, Oak. Shown is Allison  
Watts taking soil sample under middle of old  
piping where some soil cont. was observed. ②