

tank bottom - holes, pits



T2

Holland Oil

9-9-95

tank bottom - holes




T2

Holland Oil

9-9-98

water draining from tank



T3

Holland
Oil

9-9-95

tank bottom - holes



T2

Holland
Oil

9-9-95

E 14th →



9-9-95

Holland Oil

T4



T4

Holland Oil

9-9-95



T7

Holland Oil

9-9-95




T8

Holland Oil

9-9-95

water discharging from tank



T3

Holland
Oil

9-9-95



T3

Holland
Oil

9-9-95



T3

Holland Oil

9-9-95



T3

Holland
Oil

9-9-95

R E 14th



TR

9-9-95

Holland Oil

deep pits, tank bottom

← E14th St.



T1,2

9-9-95

Holland Oil



T1

9-9-95

Holland Oil

↑
up



9-9-95

Holland Oil



T2,6



T1,3

Holland Oil 9-9-95



T5,7,8

Holland 9-9-98



T2,6

Holland Oil 9-9-95



Holland Oil 8-14-98
16301 E. 14th
San Leandro



Holland Oil 8-14-98
16301 E. 14th
S. Leandro



Holland Oil 8-14-98
16301 E. 14th
San Leandro



PCB 8-14-98
Holland Oil
16301 E. 14th
San Leandro



Holland Oil

8-5-98



Holland Oil

8-5-98



Holland Oil

8-5-98



Holland Oil
16301 E. 14th
San Leandro

4/15/98



Holland Oil
16301 E. 14th
San Leandro

4/15/98



Holland Oil
16301 E. 14
San Leandro

4/15/98



Holland Oil 9-4-95



Holland Oil 9-4-95

Holland Oil facility
16301 E. 14th Street

8/23/93



- views from Little League
field SW of site,
showing lack of progress
to begin removing "clutter"
from site

Jack Holland Sr. Oil Co.
16301 E. 14th St.
San Antonio, TX



Soil discoloration in the
5,000 gal diesel tank pit area

~~XXXXXXXXXX~~

Jack Holland Sr. Oil Co.
16301 E. 14th St.
Son Canyon, AZ 8594



John Holland Sr. Oil Co.
Soil discoloration near the
fill pipe of the
6,000 gal. diesel tank

Soil discoloration near
the fill pipe of
the 6,000 gal diesel
tank