

Phone Log

- 10/2/96 Spoke w/ S. Zeriman Re: site. He will send in CLR ASAP & UST closure report w/in next two weeks. He did not complete OE since contamin. was still very evident 2 ft below bottom of pit & there were problems w/ excavation stability. LW was not present in pit. We discussed a rapid SA might be approp. before considering MW install.
- 11/13/96 Scott Zeriman called to discuss ~~the~~ req'ts for a soil & gw investigation. Told him to use RWQCB'S guidelines & RBCA as guides to create a ^{w/ P for} soil & gw investigation.
- 01/9/97 Robert Kitay called. Field work planned for 1/20/97.
- 01/13/97 Called Robert Kitay ~~re~~ re: approval of WP. See letter

- Site map w/ sample locations
- Querey?
- Date of SP Soil? —
- UST closure plan?
- ULR will be sent in w/ report.
- Groundwater samples? → Tank H₂O.
Groundwater noted in pit.

Not used as fuel UST
Inside building - OE was not safe - due to 2' (2' bgs)
still green.

→ no gas encountered assumed @ 9-10' bgs.

Challenge Pumps

Attn:

David Goodearl
Geo M. Martin Company
1250 67th St
Emeryville CA 94608