
RO 2513



GROUNDWATER MONITORING WELL INSTALLATION AND BASELINE GROUNDWATER MONITORING REPORT

BENNER AUTO REPAIR 488 25TH STREET OAKLAND, CALIFORNIA

Prepared for

JOSEPH & LORETTA BENNER FAMILY TRUST OAKLAND, CALIFORNIA

June 2005



GEOSCIENCE & ENGINEERING CONSULTING

Ro2518

STELLAR ENVIRONMENTAL SOLUTIONS

2198 SIXTH STREET, SUITE 201, BERKELEY, CA 94710 Tel: 510.644.3123 ★ Fax: 510.644.3859

TRANSMITTAL MEMORANDUM

To: ALAMEDA COUNTY LOCAL OVERSIGHT	DATE: JUNE 21, 2005	
ATTENTION: MR. DON H	WANG	FILE:
	NVESTIGATION TREET, OAKLAND, CA	
We are sending:	(HEREWITH	☐ UNDER SEPARATE COVER
	▼ VIA MAIL	□ VIA
		VELL INSTALLATION AND BASELINE REPORT" (DATED 6/20/05)
	☐ AS REQUESTED	☐ FOR YOUR APPROVAL
	☐ FOR REVIEW	FOR YOUR USE
	☐ FOR SIGNATURE	☐ FOR YOUR FILES
COPIES TO: MR. MIKE E (PROPERTY		By: Bruce Rucker
	ED.	COLINE D



ENVIRONMENTAL MENERY SERVICES



GEOSCIENCE & ENGINEERING CONSULTING

June 20, 2005

Mr. Don Hwang - Hazardous Materials Specialist Alameda County Health Care Services Agency Department of Environmental Health – Local Oversight Program 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502

Subject:

Groundwater Monitoring Well Installation and Baseline Groundwater Monitoring Report

Benner Automotive - 488 25th Street, Oakland, California

Alameda County Health Case No. RO002518 Water Board GeoTracker Global ID T0600114301

Dear Mr. Hwang:

This report documents groundwater monitoring well installation and sampling activities conducted in May and June 2005 by Stellar Environmental Solutions, Inc. at the referenced site. The scope of work was conducted in accordance with our March 2005 technical workplan. The work tasks included: 1) installing three shallow groundwater monitoring wells in the vicinity of a former gasoline underground fuel storage tank; 2) performing well development and surveying; and 3) conducting the initial groundwater sampling event.

The data indicate that residual contaminant concentrations in shallow groundwater are significantly lower than those detected in previous (2003 and 2004) borehole sampling events. Continued groundwater monitoring is warranted to evaluate plume stability over time.

Please contact us at (510) 644-3123 if you have any questions.

Sincerely,

Bruce Rucker, R.G., R.E.A.

Bruse M. Ruly.

Project Manager and Senior Geologist

Richard S. Makdisi, R.G., R.E.A.

Beneal S. Makdin

Principal

cc: Mr. Michael Benner - Representative of Benner Family Trust

2 PRODUCTADAD & DRA AUTO PROCESSED O Bottom AutoReport Report May 2001 Wall trademock of PART Well bright your SHELF Hell dark

GROUNDWATER MONITORING WELL INSTALLATION AND BASELINE GROUNDWATER MONITORING REPORT

BENNER AUTOMOTIVE 488 25TH STREET OAKLAND, CALIFORNIA

Prepared for:

JOSEPH & LORETTA BENNER FAMILY TRUST 488 25th STREET OAKLAND, CALIFORNIA 94612

Prepared by:

STELLAR ENVIRONMENTAL SOLUTIONS, INC. 2198 SIXTH STREET BERKELEY, CALIFORNIA 94710

June 20, 2005

Project No. 2002-55

TABLE OF CONTENTS

Sectio	on Control of the Con	Page
1.0	INTRODUCTION	1
	Project Background	1
2.0	WELL INSTALLATIONS	7
3.0	MAY 2005 GROUNDWATER WELL SAMPLING	10
4.0	REGULATORY CONSIDERATIONS	12
	Regulatory Status	12
5.0	LITHOLOGY AND GROUNDWATER HYDROLOGY	15
	LithologyGroundwater Hydrology	15 19
6.0	ANALYTICAL RESULTS AND FINDINGS DISCUSSION	22
	Nature and Extent of Groundwater Contamination	30
7.0	SUMMARY, CONCLUSIONS, OPINION, AND RECOMMENDATIONS	33
	Summary and Conclusions Proposed Actions	33 35
8.0	REFERENCES	36

TABLE OF CONTENTS (continued)

Section	Page
9.0 LIMIT	ATIONS
Appendices	
Appendix A	Drilling Permits and DWR Well Completion Forms
Appendix B	Field Activity Photodocumentation
Appendix C	Borehole Geologic Logs and Well Completion Diagrams
Appendix D	Well Development and Sampling Documentation
Appendix E	Current Investigation Analytical Laboratory Reports & Chain-of-Custody Records
Appendix F	Waste Soil Transport Documentation

TABLES AND FIGURES

Tables	Page
Table 1	Groundwater Monitoring Well Construction and Groundwater Elevation Data 488-25 th Street, Oakland, California
Table 2	Historical and Current Soil Analytical Results 488 25 th Street, Oakland, California
Table 3	Current and Historical Groundwater Analytical Results 488 25 th Street, Oakland, California
Figures	Page
Figure 1	Site Location Map2
Figure 2	Site Plan With Historical Boreholes and Immediate Vicinity Utilities3
Figure 3	Cross-Section Locations
Figure 4	Geologic Cross-Sections A-A' and B-B'
Figure 5	Geologic Cross-Section C-C'
Figure 6	May 2005 Groundwater Elevations
Figure 7	May 2005 Groundwater Analytical Results

1.0 INTRODUCTION

PROJECT BACKGROUND

Stellar Environmental Solutions, Inc. (SES) was retained by the Joseph & Loretta Benn Family Trust (as property owner) to conduct groundwater monitoring well installation and sampling activities at 488 25th Street in Oakland, California. This work follows the removal of one gasoline underground fuel storage tank (UFST) in 2003, and a Preliminary Site Assessment (PSA) in July 2003, and additional site characterization (borehole drilling and sampling) in July 2004. Previous site corrective actions and investigations are summarized later in this report. The Alameda County Department of Environmental Health (ACDEH) is the lead regulatory agency for the investigation, and has assigned the site as Fuel Leak Case No. RO002518.

SITE AND VICINITY DESCRIPTION


The project site is an active automobile service facility (Benner Automotive) at 488 25th Street, Oakland, Alameda County, California (site). The site is located in downtown Oakland on the north side of 25th Street, approximately 500 feet east of Telegraph Avenue. Figure 1 is a site location map. Figure 2 is a site plan showing the location of the former UFST.


PREVIOUS INVESTIGATIONS

Historical (and current investigation) soil and groundwater sample analytical results are discussed in Section 6.0 of this report. Figure 2 shows the location of the former UFST and historical (prior to the current investigation phase) borehole locations.

January 2003 UFST Removal Findings

Gasoline-range hydrocarbons (2,500 milligrams per kilogram [mg/kg]) were detected in one of the two base-of-excavation confirmation soil samples. Neither BTEX (benzene, toluene, ethylbenzene, and xylene) nor MTBE (methyl *tertiary*-butyl ether) were detected in that sample, although method reporting limits were elevated due to required dilution. No contamination was detected at the other end of the UFST excavation. Lead was detected at background concentrations, and was deemed not to be a site contaminant of concern. A total of 40 tons of backfill material—with visual and





odiferous evidence of petroleum contamination—was offhauled for Class II landfill disposal. The excavation was then backfilled with clean imported fill and compacted to 95 percent relative compaction.

The base of the original UFST excavation, as evidenced by the interface between backfill material and native soils, was approximately 7 feet below ground surface (bgs), and was underlain by approximately 2 feet of sandy backfill material. Except for potholing with the backhoe bucket to obtain samples of native soil, no additional soil excavation was conducted (beyond that required to expose and remove the UFST). Groundwater was not encountered in the excavation.

July 2003 PSA Findings

Five exploratory boreholes were advanced to depths of 16 to 25 feet on three sides of the former UFST excavation (all within 10 feet of the former excavation), and one was advanced through the approximate center of the former excavation. A total of ten soil samples were collected for laboratory analysis from the unsaturated zone, at depths between 6.5 and 11.5 feet. An additional five soil samples (one from each borehole) were collected at depths below the upper water-bearing zone. One grab-groundwater sample was collected from each borehole. The boreholes were geologically logged from continuous soil cores.

Soil contamination above regulatory agency screening levels appeared to be constrained to an approximately 2-foot-thick zone above groundwater, in the immediate vicinity of the former UFST excavation.

Shallow groundwater in the immediate vicinity of the former UFST had been impacted by gasoline above screening-level criteria, with no apparent contamination by BTEX or MTBE. The area of maximum gasoline contamination appeared to be beneath the UFST and to the east and south, with minor to insignificant gasoline contamination to the west and northwest.

Exploratory borehole PID readings and soil sample analytical results suggested no soil or groundwater contamination beneath the upper water-bearing zone.

July 2004 Additional Site Characterization Findings

Additional site characterization was conducted in July 2004. Six exploratory boreholes were drilled and sampled in the vicinity of the former UFSTs. Thirty soil samples and six borehole grab-groundwater samples were collected for analysis. One adjacent property groundwater monitoring well was also sampled.

The lateral and vertical extent of soil contamination above regulatory agency screening levels was well defined by available data, and appeared to be limited to an approximately 2-foot-thick zone above groundwater in the immediate vicinity of the former UFST excavation. The data suggested that no significant mass of residual soil contamination exists to act as a long-term source of groundwater contamination; this likely due to the age of the release and the subsequent diffusion of hydrocarbons to groundwater.

The water-bearing zone from which samples were taken at a maximum depth of 16 feet bgs has been impacted by several contaminants above the Environmental Screening Level (ESL) criteria set by the Regional Water Quality Control Board (Water Board); the contaminants consist primarily of gasoline, with lesser concentrations of ethylbenzene, xylenes, and MTBE. There was no apparent contamination above ESLs of benzene, toluene, fuel oxygenates, or lead scavengers.

The long axis of the groundwater contaminant plume was oriented north-south (consistent with local groundwater flow direction), with the eastern and western lateral limits well defined. The contaminant plume had apparently migrated offsite to the south, with gasoline concentrations up to 120,000 milligrams per liter (mg/L) in a borehole approximately 35 feet south of the property. The southern extent of the groundwater contaminant plume was not defined.

Neither soil nor groundwater concentrations exceeded ESL criteria for potential indoor air impacts.

Exploratory borehole photoionization detector (PID) readings and soil sample analytical results suggested no soil or groundwater contamination beneath the upper water-bearing zone (i.e., deeper than 11 feet below grade).

The contaminant geometry and relatively lower concentrations of volatile components (e.g., benzene) suggested an old release; there is downgradient migration through groundwater such that the center of contaminant mass is at least 35 feet from the UFST, and the plume appears to have disconnected from the source area. This distribution corroborates the absence of a continuing source of contamination to groundwater (i.e., residual contaminated soil).

No vicinity water wells were identified that could intercept site-sourced groundwater contamination, except for an inactive groundwater monitoring well (installed to monitor a fuel release) at a property across the street. This well is not considered a receptor, as it was installed specifically to monitor similar petroleum contamination.

The only underground utilities identified at a possible groundwater depth are sanitary and storm sewer lines located approximately 150 feet west (crossgradient) of the subject property. Based on the distance of these lines from the site, it is unlikely that they are located near enough to intercept site-sourced groundwater, and to therefore act as preferential contaminant migration pathways.

An adjacent property groundwater monitoring well (across 25th Street, to the southeast) was installed to monitor a former UFST. Based on July 2004 groundwater sampling conducted by SES, that well appears to define the eastern lateral edge of the contaminant plume (i.e., no contamination was detected).

CURRENT PROGRAM OBJECTIVES AND SCOPE OF WORK

This current phase of the investigation was conducted to provide "permanent" groundwater monitoring points (wells) to allow for periodic monitoring of the contaminant plume, and to provide additional data on site hydrogeology and lithologic conditions.

2.0 WELL INSTALLATIONS

This section summarizes the installation, development, and surveying of three shallow groundwater monitoring wells at the subject property in May and June 2005. Figure 2 (in Section 1.0) shows the area of the former UFST, as well as previous borehole locations.

Underground Service Alert (USA) was contacted before drilling to identify potential underground utilities (none were encountered during drilling). Appendix A contains the Alameda County Public Works Agency drilling permit and City of Oakland excavation and encroachment permits. SES notified both those agencies of the schedule for our work; neither agency performed an onsite inspection during our work. Appendix A also contains the California Department of Water Resources (DWR) Well Completion Reports. Appendix B contains photodocumentation of the investigation field activities.

Drilling, soil sampling, and well installation were conducted on May 25, 2005. Drilling was conducted by Vironex, Inc. (C-57 License No. 705927) under the direct supervision of a SES representative. The primary objectives of the well installation program were to:

- Provide "permanent" groundwater monitoring points to evaluate the magnitude of groundwater contamination and evaluate groundwater flow direction; and
- Provide additional information on site lithology and soil contaminant concentrations.

Three groundwater monitoring wells were installed:

- MW-1: 30 feet to the northeast of the former UFST, near the former dispenser, and within 2 feet of previous BH-11).
- MW-2: 45 feet southeast of the former UFST (on the south side of 25th Street), approximately 5 feet west of previous BH-07.
- MW-3: 30 feet south of the former UFST (on the south side of 25th Street), within 2 feet of previous BH-06.

Soil Sampling

The boreholes were drilled with a truck-mounted GeoProbeTM (direct-push) rig. The boreholes were advanced with 3½-inch-diameter "dual-tube" equipment. This equipment advances a hollow outer

steel casing, with an approximately 2-inch-diameter inner soil sampling casing lined with acetate sleeves (5-foot-long sleeves). Continuous soil cores were collected in 4-foot-long segments, which were retrieved while the outer casing stayed in place to keep the borehole open. Borehole geologic logs for the current phase boreholes are included in Appendix C.

Soil samples were collected from each borehole for laboratory analysis at depths of approximately 10 feet, 15 feet, 20 feet, and 25 feet. The samples were actually collected from the 6-inch interval (e.g., 9.5 feet to 10 feet) because there is better depth control on the bottom of the 5-foot-long sampler than on the top. In the MW-2 borehole, a 30-foot-deep soil sample was also collected. Following collection of that sample, the bottom 5 feet of the borehole (25 feet to 30 feet) was backfilled with bentonite, so that the base of the borehole before well emplacement was 25 feet deep.

Soil samples selected for laboratory analysis were sealed within an approximately 6-inch length of the acetate sampling sleeve, capped with non-reactive plastic caps, labeled, chilled, and shipped to the analytical laboratory under chain-of-custody documentation.

Well Installations

Due to limited access inside the building, which precluded hollow-stem auger well installation, the wells were installed using the GeoProbeTM equipment. The wells were "pre-packed" GeoProbeTM wells (i.e., pre-constructed annular filter pack and bentonite seal that are assembled in the field). This technique has the advantage of generating less soil cuttings and less well development/purge water. This well installation technique was approved by the Alameda County Public Works Agency (ACPWA). The well emplacement procedure was as follows:

- 2-inch continuous core sampling rods were withdrawn after sampling.
- The pre-packed well was emplaced inside the outer casing, supplemental sand was added to fill the annular space around the pre-packed screens and to cover the top of the well screens approximately 1 foot, and the sand was wetted
- Bentonite chips were added on top of the sand and hydrated.
- Portland cement grout slurry was brought to near ground surface, and the well box was installed in concrete.

The following are key well construction specifications:

- Well screen and filter pack ("pre-packed): 15-feet-long, 2½-inch outside diameter stainless steel mesh, enclosing ¾-inch-thick #20/40 sand, wrapped around 1-inch inside diameter (0.010-inch slotted) Schedule 40 PVC screen, with an additional 1 foot of sand on top.
- Well riser: 1-inch inside diameter Schedule 40 PVC.

- Pollution seal: 2-foot-thick layer of bentonite chips (hydrated) from 9 feet to 7 feet, overlain by Portland cement grout slurry to 1 foot deep, overlain by rapid-set concrete (from 1 foot to surface). In accordance with ACPWA requirements, the diameter of the uppermost portion of the seal (upper 1 foot) was 10 inches.
- Surface completion: Christy-type flush-mount steel box (7-inch-diameter) inside a 10-inch-diameter hole cut in the asphalt/concrete, and locking well casing caps.

Well Development

On May 31, 2005, the wells were developed (by North State Environmental of South San Francisco, California) by surging and pumping (ten casing volumes per well) to set the annular sand pack, and to reduce the potential for fine-grained native materials to infiltrate the sand pack. Approximately 10 gallons of well development purge water was generated and containerized onsite (see below). Appendix D contains the well development field records.

Well Surveying

On June 3, 2005, the horizontal coordinates and vertical elevations of the well casing tops were surveyed by a licensed California land surveyor, in accordance with California "GeoTracker" requirements. The "Geo Survey" data for this surveying event were uploaded as an Electronic Data Deliverable (EDD) to the California GeoTracker on-line database.

Investigation-Derived Waste

Waste soil from the well installations was combined with the waste soil from the two previous borehole programs (2003 and 2004) in two labeled, steel 55-gallon drums. Following all drilling, a composite sample ("Soil Drum Comp.") from the two drums was collected for laboratory analysis, so the soil could be profiled for disposal. Appendix E contains the certified analytical laboratory report and chain-of-custody record for that sample. The analytical results demonstrated that the soil is uncontaminated (and non-hazardous), and amenable for disposal at a permitted Class III or II landfill. The drummed soil was transported offsite for disposal (at D.K. Environmental in Los Angeles, California) on June 7, 2005. Appendix F contains the soil transport documentation.

Wastewater from well development and equipment decontamination rinseate was containerized in a labeled, steel 55-gallon drum. As a cost-savings measure, wastewater from future groundwater monitoring events will continue to be accumulated and stored at the site, and will be properly profiled and disposed of at a permitted non-hazardous liquids treatment facility at a later date.

3.0 MAY 2005 GROUNDWATER WELL SAMPLING

This section presents the groundwater monitoring and sampling methods for the baseline groundwater sampling event. Analytical results are discussed in a subsequent section. Activities included:

- Measuring static water levels with an electric water level indicator;
- Purging wells to obtain representative formation water (and collecting aquifer stability parameters between each purging); and
- Collecting post-purge groundwater samples for laboratory analysis.

Groundwater monitoring well water level measurements, purging, and sampling activities were conducted on May 31, 2005 by North State Environmental under the supervision of SES personnel. Sampling was conducted immediately following well development (discussed in Section 3.0). Table 1 shows the well construction and groundwater elevation data. Appendix D contains the groundwater monitoring field records for the sampling event.

Table 1
Groundwater Monitoring Well Construction and Groundwater Elevation Data
488-25th Street, Oakland, California

Well	Well Depth	Screened Interval	TOC Elevation	Groundwater Elevation (5/31/05)
MW-1	25	10 to 25	25.24	15.15
MW-2	25	10 to 25	23.71	14.69
MW-3	25	10 to 25	23.86	15.06

Notes:

TOC = Top of casing.

All wells are 1-inch-diameter.

All elevations are in feet above mean sea level.

As the first task of the monitoring event, static water levels were measured using an electric water level indicator. Because the wells were sampled immediately following well development (which included purging ten casing volumes and measuring aquifer stability parameters between each

purged casing), additional purging was not conducted prior to sampling. Neither separate-phase petroleum product nor sheen was noted during well purging/sampling.

The "Geo Well" data for this event (water levels) were uploaded as an EDD to the California GeoTracker on-line database.

4.0 REGULATORY CONSIDERATIONS

REGULATORY STATUS

The lead regulatory agency for petroleum contamination cases in the City of Oakland is Alameda County Health, which is a Local Oversight Program (LOP) for the State Water Resources Control Board (covering Water Board Region 2). As such, Alameda County Health directly oversees soil and groundwater investigations/remediation on UFST sites (with or without Water Board guidance) until determining that case closure is appropriate, at which time Alameda County Health recommends case closure to the Water Board. Alameda County Health Care Services has designated the case as Fuel Leak Case No. RO002518. The site is listed in the Water Board's GeoTracker database of reported releases from petroleum UFSTs (Global ID T0600114301.

RESIDUAL CONTAMINATION REGULATORY CONSIDERATIONS

The most applicable published numerical criteria governing residual soil and groundwater contamination at this site are the Water Board's ESLs (Water Board, 2005). These are screening-level criteria used to evaluate if additional investigation and/or remediation is warranted. Criteria to be considered in using the ESLs include: contamination limited to surface soil (less than 10 feet deep) or to subsurface soil; fine-grained vs. coarse-grained soil; residential or commercial/industrial land use; and whether groundwater is or is not a known or potential drinking water source. For the detected site contaminants, the ESL values are the same for surface soil and subsurface soil.

The appropriate ESLs for this site are for coarse-grained soil (a conservative assumption, as grain-size analysis has not been conducted and the soils are generally clay) and commercial/industrial land use (because the owner has no plans to redevelop the property with residential land use). Qualifying for the (usually higher) ESL values for sites where groundwater is not a current or potential drinking water source requires obtaining a site-specific variance from the Water Board. The Water Board completed an East Bay Beneficial Use Study (Water Board, 1999) that covers the Richmond-to-Hayward East Bay Basin Area and, based on multiple technical criteria, divided the Basin into three zones:

- Zone A (significant drinking water resource);
- Zone B (groundwater unlikely to be used as drinking water source); and
- Zone C (shallow groundwater proposed for redesignation as Municipal Supply Beneficial Use).

The subject site falls within Zone A. The most conservative assumption for the site is that there is a potential for private drinking water wells to be impacted. However, a search of vicinity water wells identified no wells downgradient of the subject property (SES, 2004c). There is an inactive groundwater monitoring well immediately downgradient of the site; however, that well was installed to monitor a fuel release. This suggests that the less conservative ESLs of "a potential or current drinking water source is not threatened" may be appropriate when the site is considered for case closure. Until case closure is considered, this report (and future reports) will discuss residual soil and groundwater contamination in the context of the more conservative ESL criteria (for the scenario where groundwater is a potential drinking water resource).

SITE CLOSURE CRITERIA

Alameda County Health and the Water Board generally require that the following criteria be met before issuing regulatory closure of petroleum release cases:

- The contaminant source has been removed (i.e., the UFSTs and obviously-contaminated backfill material). This criterion has been met, and the available soil analytical results indicate that the majority of contaminated soil has been removed and that residual gasoline contamination will not be an appreciable long-term source of groundwater contamination.
- 2. The groundwater contaminant plume is stable or reducing (i.e., groundwater contamination is not increasing in concentration or lateral extent). This criterion has not yet been met, and will be evaluated based on the ongoing quarterly groundwater sampling program.
- 3. If residual contamination (soil or groundwater) exists, there is no reasonable risk to sensitive receptors (i.e., contaminant discharge to surface water or water supply wells) or to site occupants. This criterion is generally met by conducting a sensitive receptor survey and/or a Risk-Based Corrective Action (RBCA) assessment that models the fate and transport of residual contamination in the context of potential impacts to sensitive receptors. This task is generally conducted after the previous two criteria have been met. Based on the apparent absence of benzene (the probable "risk driver" compound for this site) at elevated concentrations and the likely absence of sensitive receptors, if one eliminates private wells as potential receptors, the site would likely pass the RBCA assessment.

GEOTRACKER COMPLIANCE

This site is listed in the Water Board's GeoTracker database, and all required electronic uploads have been made for previous site activities. Tasks conducted in this phase of work related to GeoTracker compliance included:

- Uploading Field Point Names (list of well names).
- Surveying the site wells (horizontal coordinates and vertical elevations) in conformance with GeoTracker data requirements, and uploading the GeoXY and GeoZ data sets.
- Uploading *GeoWell* (water level monitoring-related data uploaded for the initial (Q2 2005) monitoring event).
- Uploading GeoReport (portable data format [pdf]) electronic copy of this report.
- Uploading *GeoMap* (pdf electronic copy of a site plan showing the locations of monitoring wells.
- Uploading *EDDs* (electronic version of the analytical laboratory reports for the well installation soil samples and the groundwater sampling event).

A hard copy of this report was mailed to Alameda County Health. In accordance with California GeoTracker requirements, site reports generated after July 1, 2005 will only be uploaded to the GeoTracker online database. No hard copy reports will be mailed to regulatory agencies.

5.0 LITHOLOGY AND GROUNDWATER HYDROLOGY

This section discusses the site lithology and groundwater hydrology, based on the three borehole sampling programs, conducted in 2003 through 2005.


Including the 3 well installation boreholes advanced during the current investigation, a total of 14 exploratory boreholes at the subject property have been geologically logged using the visual method of the Unified Soils Classification System, and have been evaluated. One borehole (BH-01) was advanced through the former UST excavation, and the remainder were advanced through native soil. Two of the recent monitoring well boreholes (MW-1 and MW-3) were advanced immediately adjacent to previous exploratory boreholes (BH-11 and BH-06, respectively). No substantial differences were noted between the 2004 and recent boreholes at those locations, except as stated below.


The majority of site boreholes have been advanced to at least 24 feet bgs. One of the 2005 well installation boreholes was advanced to 30 feet bgs. These intervals include the upper water-bearing zone and the underlying low-permeability non-water-bearing zone (aquitard).


Borehole logs for the current investigation are included in Appendix C. Cross-section locations are shown on Figure 3. Figures 4 and 5 show three geologic cross-sections for the site—one along the longitudinal axis of the plume (approximately north-south), and two perpendicular to the plume axis (approximately east-west).


LITHOLOGY

A laterally-extensive clay (occasionally gravelly) is present in all boreholes, extending from ground surface to approximately 17 to 20 feet bgs. Two of the boreholes (BH-02 and United Glass MW-1) contain a thin (1- to 3-foot-thick) sandy lens between 10 and 15 feet bgs. The clay layer is generally underlain by a sand or gravel unit, beginning at depths of 18.5 to 21.5 feet bgs. This more permeable unit varies in thickness from 2.5 feet to at least 5.5 feet. In the majority of boreholes, this unit consists of sand grading downward into gravel. A clay unit was encountered below the sand/gravel unit in most of the boreholes greater than 20 feet bgs. In several of the boreholes, the underlying clay unit was not reached, but is likely shallower than 30 feet bgs. The lithology is typical of this area of









Geoscience & Engineering Consulting

488-25th Street, Oakland, CA

by: MJC

JUNE 2005

Oakland, showing lenticular lenses of more permeable sand and gravel (paleochannels) flanked by low-permeability clays and silts (overbank deposits). These deposits typically display small-scale lateral and vertical heterogeneity.

Borehole BH-01 (advanced through the former UFST excavation) encountered excavation backfill material (gravelly, clayey silt) to a depth of approximately 9 feet bgs, underlain by native soil (as described above).

GROUNDWATER HYDROLOGY

In the July 2003 borehole program, very moist to wet soil samples were encountered in site boreholes, at depths of approximately 9.5 to 12 feet bgs, with equilibrated groundwater levels in boreholes at approximately 10 feet bgs.


In the July 2004 program, there was no evidence of water in any boreholes above 12 feet bgs (either saturated samples or measurable water in boreholes). Water entered the boreholes after the sampling rods were advanced from 12 to 16 feet bgs, and the water quickly rose to depths between approximately 7 and 10 feet bgs. In the majority of boreholes, groundwater was first encountered in the upper clay unit rather than the underlying sand/gravel unit. Relatively dry soils were encountered below this upper water-bearing zone, and groundwater was again encountered in the fully saturated sands at approximately 20 feet bgs. The underlying clay unit showed little to no water.

In the May 2005 boreholes, there was no evidence of water in any boreholes above 20 feet bgs (either saturated samples or measurable water in boreholes). Water entered the boreholes after the sampling rods were advanced from 20 to 24 feet bgs, and the water quickly rose to depths between approximately 9 and 10 feet bgs. The underlying clay unit showed little to no moisture.

Depth to groundwater (equilibrated in wells) in the May 2005 monitoring event ranged from approximately 8.8 to 10.1 feet below grade (approximately 14.7 to 15.2 feet above man sea level). These equilibrated water levels in the wells were approximately 10 feet above first occurrence of saturated cuttings in boreholes, indicating that groundwater at the site occurs under confining or semi-confining conditions. The direction of local groundwater flow in this event was to the southwest, with a relatively flat hydraulic gradient (0.01 feet/foot). Figure 6 shows groundwater elevations and flow contours. The direction of groundwater flow in the (surveyed) 2003 piezometers was to the south-southeast.

The available data suggest that:

■ Depth to first occurrence of groundwater (during drilling) has dropped approximately 10 feet between the 2003 and 2005 borehole programs, with no obvious seasonal correlation.



- In the previous (higher groundwater) events, relatively dry soils were encountered between an upper water-bearing zone (less than 16 feet bgs) and a lower water-bearing zone (at approximately 20 feet bgs, indicating that perched water exists during higher groundwater conditions.
- In all three of the borehole programs, groundwater equilibrates at approximately 10 feet bgs, indicating semi-confining conditions.
- Groundwater flow is generally to the south-southwest.

6.0 ANALYTICAL RESULTS AND FINDINGS DISCUSSION

This section presents the findings of the well installation program, and discusses the hydrocarbon contamination in the soil and groundwater based on the analytical results.

All soil and groundwater samples in the well installation and initial groundwater sampling activities were analyzed for:

- Total volatile hydrocarbons gasoline range (TVHg), by modified EPA Method 8015;
- BTEX, MTBE, fuel oxygenates (TAME, ETBE, DIPE, TBA, and ethanol), and lead scavengers (EDB and EDC), by EPA Method 8260.

The current investigation soil samples were analyzed by Curtis & Tompkins, Ltd (Berkeley, California). The current investigation groundwater samples were analyzed by North State Labs (South San Francisco, California). Both labs maintain current ELAP certifications for all of the analytical methods utilized in this investigation. Appendix E contains the certified analytical laboratory reports and chain-of-custody records.

Residual Soil Contamination

Table 2 summarizes the historical (UFST removal and PSA) and current (well installation) soil sampling analytical results. The only soil contaminant detected above ESLs in residual soils (including both the UFST excavation and the 2003 and 2004 borehole programs) is gasoline (at a maximum of 2,500 mg/kg directly beneath the former UST). Lesser concentrations (maximum of 150 mg/kg) were detected in several boreholes. Neither BTEX, MTBE, fuel oxygenates, nor lead scavengers have been detected above ESL criteria. The only analyte detected in the monitoring well installation soil samples was gasoline, at 1.3 mg/kg in MW-3 at approximately 10 feet.

In the May 2005 monitoring well installation boreholes, a slight petroleum odor was noted in two of the boreholes (MW-1 and MW-03) in the depth intervals of approximately 10 to 14 feet (MW-1) and 7 to 10 feet (MW-2). No contamination was detected (by lab analysis) in soil samples collected from those intervals.

These data indicate that residual soils do not contain an appreciable mass of fuel contamination.

Table 2
Historical and Current Soil Analytical Results
488 25th Street, Oakland, California ^(a)

Sample I.D.	Sample Depth	TVHg	Benzene	Toluene	Ethylbenzene	Total Xylenes	MTBE	Lead Scavengers and Fuel Oxygenates (c)
January 2003 Base of	f UFST Excavation	on Soil Samples						
UFST Base-East	9.0	2,500	<1.7 ^(b)	<1.7 ^(b)	<1.7 ^(b)	<1.7 (b)	<1.7 ^(b)	NA
UFST Base-West	9.0	<1.1	<0.0053	< 0.0053	<0.0053	< 0.0053	< 0.0053	NA
July 2003 Explorator	ry Borehole Soil S	Samples						
BH-1-10'	10.0	14	<0.0054	<0.0054	<0.0054	< 0.0054	<0.022	NA
BH-1-14'	14.0	<1.1	< 0.0053	< 0.0053	<0.0053	<0.0053	<0.021	NA
BH-2-6.5'	6.5	<1.1	<0.0054	< 0.0054	<0.0054	< 0.0054	<00022	NA
BH-2-9'	9.0	<1.0	<0.0050	<0.0050	< 0.0050	<0.0050	< 0.020	NA
BH-2-15'	15.0	<1.1	<0.0053	<0.0053	<0.0053	< 0.0053	<0.021	NA
BH-3-5'	5.0	<1.0	<0.0052	< 0.0052	<0.0052	< 0.0052	<0.021	NA
BH-3-9'	9.0	<1.1	<0.0054	< 0.0054	< 0.0054	<0.0054	<0.022	NA
ВН-3-13'	13.0	<1.0	<0.0052	<0.0052	<0.0052	<0.0052	<0.021	NA
BH-4-5'	5.0	<1.0	<0.0051	<0.0051	<0.0051	<0.0051	<0.020	NA
ВН-4-9'	9.0	<1.0	<0.0052	<0.0052	<0.0052	<0.0052	<0.021	NA
BH-4-13'	13.0	<1.1	<0.0055	< 0.0055	<0.0055	<0.0055	<0.022	NA
BH-5-6.5'	6.5	<1.1	< 0.0054	< 0.0054	<0.0054	<0.0054	<0.022	NA
BH-5-11.5'	11.5	49	<0.010	<0.010	< 0.010	< 0.010	<0.040	NA
BH-5-13'	13.0	1.7	<0.0053	< 0.0053	< 0.0053	< 0.0053	<0.021	NA

Table 2 continued

Sample I.D.	Sample Depth (feet)	TVHg	Benzene	Toluene	Ethylbenzene	Total Xylenes	мтве	Lead Scavengers and Fuel Oxygenates ^(c)
July 2004 Exploratory	y Borehole Soil S	Samples						
BH-06-4.5°	4.5	7.3	< 0.0056	< 0.0056	<0.0056	< 0.0056	<0.0048	ND
BH-06-9.5'	9.5	<1.1	<0.0053	<0.0053	< 0.0053	< 0.0053	<0.0049	ND
BH-06-14.5°	14.5	4.9	<0.0054	0.0082	<0.0054	<0.0054	<0.0047	ND
BH-06-19.5°	19.5	<1.1	< 0.0054	< 0.0054	<0.0054	< 0.0054	<0.0049	ND
BH-06-22.5°	22.5	<1.0	<0.0051	< 0.0051	<0.0051	< 0.0051	<0.0045	ND
BH-07-4.5'	4.5	<1.1	<0.0053	< 0.0053	<0.0053	< 0.0053	<0.0050	ND
BH-07-10.5'	10.5	7.9	<0.0054	0.009	<0.0054	<0.0054	<0.0047	ND
BH-07-14.5'	14.5	<0.98	< 0.0049	<0.0049	<0.0049	<0.0049	<0.0045	ND
BH-07-19.5'	19.5	<0.96	<0.0048	<0.0048	<0.0048	<0.0048	<0.0049	ND
BH-07-23.5'	23.5	<1.0	<0.0052	<0.0052	<0.0052	< 0.0052	<0.0046	ND
BH-08-4.5'	4.5	<1.0	<0.0052	<0.0052	<0.0052	<0.0052	<0.0049	ND
BH-08-9.5'	9.5	<1.1	< 0.0053	< 0.0053	<0.0053	< 0.0053	<0.0047	ND
BH-08-14.5'	14.5	< 0.97	<0.0049	<0.0049	<0.0049	< 0.0049	< 0.0045	ND
BH-08-20'	20	3.6	<0.0054	< 0.0054	<0.0054	< 0.0054	<0.0049	ND
BH-08-23.5'	23.5	<1.1	<0.0055	< 0.0055	<0.0055	< 0.0055	<0.0046	ND
BH-09-4.5'	4.5	<1.0	<0.0051	< 0.0051	<0.0051	<0.0051	<0.0045	ND
BH-09-11'	11	150	<0.0500	<0.0500	<0.0500	0.120	<0.0049	ND
BH-09-15.5'	15.5	<0.99	<0.0050	< 0.0050	<0.0050	<0.0050	<0.0045	ND

Table 2 continued

Sample 1D	Sample Depth (feet)	TVHg	Benzene	Toluene	Ethylbenzene	Total Xylenes	MTBE	Lead Scavengers and Fuel Oxygenates (c)
July 2004 Exploratory	Borehole Soil S	amples (continu	ed)				•	
BH-09-19.5'	19.5	<0.98	<0.0049	<0.0049	<0.0049	<0.0049	< 0.0047	ND
BH-09-23.5°	23.5	<1.0	< 0.0051	< 0.0051	< 0.0051	<0.0051	<0.0049	ND
BH-10-4.5'	4.5	<1.0	<0.0052	<0.0052	<0.0052	< 0.0052	<0.0049	ND
BH-10-9.5'	9.5	<1.1	< 0.0055	< 0.0055	< 0.0055	< 0.0055	<0.0047	ND
BH-10-14.5'	14.5	<1.0	< 0.0052	<0.0052	<0.0052	< 0.0052	<0.0048	ND
BH-10-19.5°	19.5	<0.99	<0.0050	<0.0050	< 0.0050	<0.0050	< 0.0045	ND
BH-10-23.5'	23.5	<1.0	<0.0050	<0.0050	<0.0050	<0.0050	<0.0047	ND
BH-11-4.5'	4.5	<0.97	<0.0049	<0.0049	<0.0049	<0.0049	<0.0049	ND
BH-11-11'	11	130	<0.0250	0.240	<0.0250	<0.0250	<0.0047	ND
BH-11-15'	15	<1.0	< 0.0051	< 0.0051	<0.0051	<0.0051	<0.0050	ND
BH-11-19.5	19.5	<1.0	< 0.0052	<0.0052	<0.0052	< 0.0052	<0.0048	ND
BH-11-23.5'	23.5	<1.0	<0.0052	<0.0052	<0.0052	<0.0052	<0.0046	ND
May 2005 Well Instal	lation Soil Samp	les					·	
MW-1-9.5'	9.5	< 1.0	< 0.0049	< 0.0049	< 0.0049	< 0.0049	< 0.0049	ND
MW-1-14.5'	14.5	< 1.0	< 0.0046	< 0.0046	< 0.0046	< 0.0046	< 0.0046	ND
MW-1-19.5'	19.5	< 1.1	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	ND
MW-1-24.5'	24.5	< 1.1	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 0.0050	ND
MW-2-9.5'	9.5	< 0.93	< 0.0048	< 0.0048	< 0.0048	< 0.0048	< 0.0048	ND

Table 2 continued

Sample I.D.	Sample Depth (feet)	TVHg	Benzene	Toluene	Ethylbenzene	Total Xylenes	мтве	Lead Scavengers and Fuel Oxygenates (c)
May 2005 Well Instal	lation Soil Samp	les (continued)						
MW-2-14.5'	14.5	< 1.1	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	ND
MW-2-19.5'	19.5	< 1.0	< 0.0047	< 0.0047	< 0.0047	< 0.0047	< 0.0047	ND
MW-2-24.5'	24.5	< 1.1	< 0.0049	< 0.0049	< 0.0049	< 0.0049	< 0.0049	ND
MW-3-9.5'	9.5	1.3	< 0.0046	< 0.0046	< 0.0046	< 0.0046	< 0.0046	ND
MW-3-14.5'	14.5	< 1.0	< 0.0046	< 0.0046	< 0.0046	< 0.0046	< 0.0046	ND
MW-3-19.5'	19.5	< 0.93	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	ND
MW-3-24.5'	24.5	< 1.1	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	ND
MW-3-29.5'	29.5	< 1.0	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 0.0050	ND
Soil Composi	ite (drum profile)	< 1.1	< 0.0054	< 0.0054	< 0.0054	< 0.0054	< 0.022	NA
	Soil ESLs	100	0.044	2,9	3.3	1.5	0.023	Various

Notes:

ESLs = California Water Board (San Francisco Bay Region) Environmental Screening Levels for commercial/industrial sites where groundwater is a potential drinking water resource.

TVHg = total volatile hydrocarbons - gasoline range

MTBE = methyl tertiary-butyl ether

NA = not analyzed for these constituents

ND = not detected (see Appendix E for reporting limits)

⁽a) All concentrations are in mg/kg.

⁽b) High concentrations of gasoline required sample dilution, resulting in the listed increased method reporting limit.

⁽e) See Appendix E for full list of analytes.

Residual Groundwater Contamination

Table 3 summarizes historical grab-groundwater sampling analytical results, as well as the analytical results from the May 2005 well sampling event. Figure 7 shows the groundwater analytical results for the current event.

Gasoline

Gasoline was detected in all but 1 of the 11 exploratory borehole grab-groundwater samples collected in 2003 and 2004. The maximum concentration was 120,000 microgram per liter (μ g/L) (in BH-06, located across 25th Street from the subject property). All other gasoline concentrations were 7,900 μ g/L or less. These data indicate that the gasoline plume extended from BH-11 (just northwest of the former UFST) to across 25th Street, and was laterally restricted to the east and west. Gasoline was not detected in the offsite (to the southeast) United Glass monitoring well in 2004.

In the May 2005 groundwater sampling event, gasoline concentrations were significantly lower than in previous samples. The maximum gasoline concentration was 64 µg/L (well MW-1), and a similar concentration (57 µg/L) was detected in well MW-3. No gasoline was detected in well MW-2.

MTBE and BTEX Compounds

In the 2003 and 2004 boreholes, the only BTEX constituents detected above ESL criteria were ethylbenzene (maximum of $70 \,\mu\text{g/L}$) and xylenes (maximum of $540 \,\mu\text{g/L}$). The maximum MTBE concentration was $8.2 \,\mu\text{g/L}$. The maximum concentrations of ethylbenzene and xylenes were detected in downgradient borehole BH-06, and the maximum concentration of MTBE was detected in upgradient borehole BH-11. Benzene was not detected in those samples. No BTEX constituents were detected in the offsite (to the southeast) United Glass monitoring well in 2004, and MTBE was present at $1.2 \,\mu\text{g/L}$.

Neither BTEX compounds nor MTBE were detected in the May 2005 groundwater monitoring well sampling.

Fuel Oxygenates and Lead Scavengers

Neither fuel oxyenates nor lead scavengers were detected in the 2004 exploratory borehole grabgroundwater samples or the May 2005 groundwater monitoring well sampling.

Table 3 Current and Historical Groundwater Analytical Results 488 25th Street, Oakland, California ^(a)

	Sample Depth				Ethyl-	Total		Lead Scavengers and Fuel Oxygenates (b)
Sample I.D.	(feet)	TVHg	Benzene	Toluene	benzene	Xylenes	MTBE	Oxygenates
July 2003 Borel					-			
BH-01-GW	~ 10-11	5,800	<0.50	<0.50	7.4	4.5	<2.0	NA
BH-02-GW	~ 10-11	7,900	<13	15	24	61	<50	NA
BH-03-GW	~ 10-11	3,700	<1.0	<1.0	<1.0	<1.0	<4.0	NA
BH-04-GW	~ 10-11	260	< 0.50	<0.50	< 0.50	< 0.50	<2.0	NA
BH-05-GW	~ 10-11	260	< 0.50	< 0.50	<0.50	<0.50	3.1	NA
July 2004 Bore	hole Groun	dwater Sampl	les					
BH-06-GW	~ 12-16	120,000	<13	<13	70	540	<1.7	ND
BH-07-GW	~ 12-16	2,000	< 0.50	3.4	8.1	14	<0.50	ND
BH-08-GW	- 12-16	380	< 0.50	0.77	<0.50	1.6	< 0.50	ND
BH-09-GW	~ 12-16	7,700	<1.0	<1.0	21	39.7	< 0.50	ND
BH-10-GW	~ 12-16	<50	<0.50	<0.50	< 0.50	<0.50	<0.50	ND
BH-11-GW	~ 12-16	1,300	<0.50	<0.50	0.88	6.0	8.2	ND
July 2004 Unite	ed Glass Gr	oundwater M	onitoring W	ell Sample (gr	ab sample)			
UG-MW-1	NA	<50	<0.50	< 0.50	<0.50	< 0.50	1.2	ND
May 2005 Grou	ındwater S	ampling Even	t					
MW-1	~20'	64	<0.50	< 0.50	<0.50	<1.0	< 0.50	ND
MW-2	~20'	< 50	<0.50	< 0.50	< 0.50	<1.0	< 0.50	ND
MW-3	~20'	57	< 0.50	< 0.50	< 0.50	<1.0	<0.50	ND
Groundwat	er ESLs ^(c)	100	1.0	40	30	13	5.0	Various
	ing Water andards ^(d)	NLP	5.0	1,000	700	10,000	13 ^(e)	Various

Notes:

TVHg = total volatile hydrocarbons -- gasoline range MTBE = methyl *tertiary*-butyl ether.

NA = not analyzed for these constituents

ND = not detected (see Appendix E for reporting limits)


⁽a) All concentrations are in µg/L.

⁽b) See Appendix E for full list of analytes.

⁽c) ESLs = Regional Water Quality Control Board, San Francisco Bay Region Environmental Screening Levels for commercial/industrial sites where groundwater is a potential drinking water resource.

⁽d) Primary Maximum Contaminant Level (MCL), unless specified otherwise.

⁽e) State of California Public Health Goal (PHG).



Summary of Residual Groundwater Contamination

Gasoline concentrations were significantly lower in the May 2005 groundwater monitoring well samples relative to the 2003 and 2004 borehole grab-groundwater samples. Further, none of the BTEX compounds or MTBE detected in the borehole samples were detected in the recent groundwater well sampling event. The significant reduction in concentrations observed in the well compared to the previous borehole grab-groundwater samples could be due to a combination of causes. Borehole grab-groundwater samples commonly exhibit greater concentrations than samples collected from constructed monitoring wells, because the grab-groundwater samples can be turbid and contain appreciable contamination that is adsorbed onto suspended solids. It is also possible that the reduced concentrations are in part the result of seasonal fluctuations in groundwater levels and concomitant "pulses" of dissolved contamination. Future groundwater monitoring should clarify the representativeness of the baseline monitoring event concentrations.

It is highly unlikely that the reduced groundwater contaminant concentrations are the result of natural attenuation (discussed below), given the relatively short (1 year) time between the 2004 and 2005 sampling events. Likewise, it is unlikely that the reduced concentrations are explained by downgradient migration of the contaminant plume.

The May 2005 groundwater monitoring well data indicate that groundwater contamination above ESL criteria likely does not extend offsite.

NATURE AND EXTENT OF GROUNDWATER CONTAMINATION

Plume Geometry

The well data indicate that gasoline is present (apparently only at concentrations below the $100 \,\mu\text{g/L}$ ESL) over an approximately 3,500-square foot area. The plume's longitudinal axis appears to be oriented north-northwest by south-southeast, and extends approximately 70 feet, from at least MW-1 to MW-3. The plume's eastern and western edges (crossgradient) appear to be laterally constrained, approximately 50 feet wide.

As discussed previously, local groundwater flow direction appears to be to the southwest, which is relatively consistent with the footprint of the plume.

Natural Attenuation

Numerous field and laboratory studies have concluded that the subsurface behavior of petroleum hydrocarbons is significantly impacted by their high capacity to undergo relatively rapid

biodegradation (McDonald and Kavanaugh, 1994; McAllister and Chiang, 1994; Wilson et. al., 1994; Lawrence Livermore National Laboratory, 1995).

Petroleum hydrocarbons require molecular oxygen for breakdown of the ring structure of specific constituents. Accordingly, although biodegradation of hydrocarbons can occur under anaerobic conditions, hydrocarbon biodegradation is greatest under aerobic conditions. As a result of the demonstrated degradability of petroleum hydrocarbons, Remediation by Natural Attenuation (RNA) has been a viable option for addressing many hydrocarbon plumes, replacing the need for active remediation, when source area remediation has been effective in removing a significant amount of the original mass of contamination released into the environment. Specifically, biodegradation of petroleum hydrocarbons in groundwater has a significant role in creating a stable plume, minimizing groundwater plume configuration and concentrations over time. The 1995 Lawrence Livermore National Laboratory study, which collected data on the lengths of hundreds of hydrocarbon plumes, found significant attenuation of concentration die-out within approximately 300 feet of the source. Hydrocarbon biodegradation and presence of a stable plume have subsequently become the basis for application of risk-based methodologies in support of site closure (Water Board, 1996).

Plume Stability

One groundwater monitoring event has been completed in three site wells. Future monitoring will determine the stability of the plume.

Potential for Surface Water Contamination

There are no nearby surface water bodies that could be impacted by the plume associated with this site.

Groundwater Impacts and Beneficial Uses

In general, as discussed in Section 4, impacts of groundwater contamination by petroleum products are evaluated on a case-by-case basis by the regulators, in consideration of all applicable ARARs, local geography, location of sensitive receptors, etc. The subject site falls within Zone A, where the most conservative assumption for the site is the potential for private drinking water wells to be impacted. However, the site location (with no documented or likely extractive groundwater use) suggests that the less conservative ESLs of "a potential or current drinking water source is not threatened" may be appropriate when the site is considered for case closure.

Because groundwater concentrations appear to be below ESL criteria and drinking water standards, the discussion of whether to use the more restrictive or more conservative ESL criteria is moot, and Alameda County Health and the Water Board will likely evaluate residual groundwater concentrations in the context of drinking water standards and land use.

Other Considerations

Residual soil and groundwater concentrations are below any published Water Board ESLs related to potential soil gas intrusion, and therefore no such impact is likely.

Residual soil contamination (and groundwater contamination) is no shallower than 10 feet deep, which is below any likely future excavations (e.g., utility trenching), and therefore has a low potential to pose health or safety impacts to those activities.

7.0 SUMMARY, CONCLUSIONS, OPINION, AND RECOMMENDATIONS

SUMMARY AND CONCLUSIONS

The available data support the following findings and conclusions:

- One site 1,000-gallon gasoline UFST was removed in January 2003 under regulatory oversight, along with 40 tons of obviously-contaminated backfill material. Gasoline was detected at 2,500 mg/kg in native soil 2 feet beneath the UFST (at a depth of 9 feet); BTEX and MTBE concentrations were less than approximately 2 mg/kg each. Groundwater was not encountered (excavation depth of 9 feet).
- The lead agency for UFST-related petroleum contamination sites is Alameda County Health, which has provided oversight of this case since the UFST removal report was submitted in January 2003.
- The subject property is located within the Water Board Zone A (Significant Drinking Water Source Potential) designation as described in the 1999 East Bay Plain Beneficial Use Study.
- A PSA was conducted in July 2003. Five exploratory boreholes were advanced to depths of 16 to 25 feet on three sides of the former UFST excavation (all within 10 feet of the former excavation), and one was advanced through the approximate center of the former excavation. A total of ten soil samples were collected for laboratory analysis from the unsaturated zone, at depths between 6.5 and 11.5 feet. An additional five soil samples (one from each borehole) were collected at depths below the upper water-bearing zone. One grabgroundwater sample was collected from each borehole.
- Additional site characterization was conducted in July 2004. Six exploratory boreholes were drilled and sampled in the vicinity of the former UFSTs. Thirty soil samples and six borehole grab-groundwater samples were collected for analysis. One adjacent property groundwater monitoring well was also sampled.
- Three site shallow groundwater monitoring wells were installed, developed, and surveyed in May and June 2005.
- Site lithology consists of a laterally-extensive clay unit to depths of approximately 17 feet to 20 feet, underlain by a more permeable sand/gravel unit with thicknesses between 2.5 feet

and up to 5.5 feet. In higher groundwater conditions (2003 and 2004 programs), groundwater was first encountered at the 7- to 10-foot-depth range (2003) and the 15- to 16-foot-depth range (2004), with an underlying unsaturated zone. A second fully saturated zone is encountered at 20 feet deep. In the current investigation, groundwater was first encountered at the 20-foot-deep range, suggesting that groundwater depths have fallen approximately 10 feet since 2003. The lower water-bearing zone is underlain by an unsaturated clay unit.

- Groundwater occurs under semi-confining conditions, equilibrating at depths approximately 10 feet above first occurrence (2005 program). Local groundwater flow direction is to the southwest with a relatively shallow hydraulic gradient.
- The lateral and vertical extent of soil contamination above regulatory agency screening levels is well defined by available data, and appears to be limited to an approximately 2-foot-thick zone above groundwater, in the immediate vicinity of the former UFST excavation. The data suggest that no significant mass of residual soil contamination exists to act as a long-term source of groundwater contamination; this is likely due to the age of the release and the subsequent diffusion of hydrocarbons to groundwater. No contamination above ESL criteria has been detected in the unsaturated clay unit that underlies the shallow water-bearing zone.
- Groundwater contamination in the 2005 well baseline sampling event was several orders of magnitude below concentrations in the 2003 and 2004 borehole programs. This could result from a combination of causes, including the filtration of contaminated dissolved solids by the well annular filter pack and/or the result of seasonal fluctuations in groundwater levels and concomitant "pulses" of dissolved contamination. However, it is highly unlikely that the reduced concentrations are the result of either natural attenuation or plume migration.
- Current gasoline concentrations in groundwater do not exceed the 100 μg/L Water Board ESL. Neither BTEX, MTBE, lead scavengers, nor fuel oxygenates were detected.
- The long axis of the groundwater contaminant plume is oriented approximately north-south (generally consistent with the southwesterly groundwater flow direction), with the eastern and western lateral limits well defined.
- Neither soil nor groundwater concentrations exceed ESL criteria for potential indoor air impacts.
- No vicinity water wells have been identified that could intercept site-sourced groundwater contamination, except for an inactive groundwater monitoring well (installed to monitor a fuel release) at a property across the street. This well is not considered a receptor, as it was installed specifically to monitor similar petroleum contamination.
- The only underground utilities identified at a possible groundwater depth are sanitary and storm sewer lines located approximately 150 feet west (apparently crossgradient) of the

Z-PROJECTS2002 & 2003 Active Projects/2002-55-Benner Auto Repair/Reports/May 2005 Well Installation/REPORT-Well Install-June 2005 Foul). de

subject property. Based on the distance of these lines from the site, it is unlikely that they are located near enough to intercept site-sourced groundwater, and to therefore act as preferential contaminant migration pathways.

- The property owner has been accepted into and has been receiving reimbursement from the State of California Underground Storage Tank Cleanup Fund (Fund) for regulatory agency-directed corrective action and investigation costs.
- All required electronic uploads for previous work have been made to the California GeoTracker on-line database system.

PROPOSED ACTIONS

- The property owner proposes to continue the quarterly groundwater monitoring well monitoring and sampling program, in accordance with the technical workplan approved by ACDEH. This will include electronic uploads of water level and groundwater contamination data for future monitoring events to the California GeoTracker system.
- Based on the absence of fuel oxygenates and lead scavengers, the property owner proposes that testing be discontinued for these contaminants in future groundwater monitoring events.
- The property owner will continue to pursue reimbursement of eligible incurred corrective action costs from the California UST Cleanup Fund.

8.0 REFERENCES

- Alameda County Health Care Services Agency, Environmental Health Services (Alameda County Health), 2004. Letter requesting scope of work revisions to technical workplan for 488 25th Street, Oakland, California. March 23.
- Alameda County Health, 2003a. Letter requesting technical workplan for 488 25th Street, Oakland, California. April 2.
- Alameda County Health, 2003b. Letter requesting scope of work revisions to technical workplan for 488 25th Street, Oakland, California. June 26.
- Alameda County Health, 2003c. Letter approving technical workplan for 488 25th Street, Oakland, California. July 8.
- Alameda County Health, 2003d. Letter requesting additional site characterization activities for 488 25th Street, Oakland, California. December 17.
- Lawrence Livermore National Laboratory, 1995. California Leaking Underground Fuel Tank Historical Case Analyses (UCRL-AR-121762).
- MacDonald, J.A. and M.C. Kavanaugh, 1994. Restoring Contaminated Groundwater: An Achievable Goal. Environmental Science and Technology, Vol. 28, No. 8.
- McAllister, P.M. and C.Y. Chiang, 1994. A Practical Approach to Evaluating Natural Attenuation of Contaminants in Ground Water, Ground Water Monitoring and Remediation. Spring.
- Regional Water Quality Control Board (Water Board), San Francisco Bay Region, 2005. Screening for Environmental Concerns at Sites With Contaminated Soil and Groundwater.
- Regional Water Quality Control Board (Water Board), San Francisco Bay Region, 1999. East Bay Plain Groundwater Basin Beneficial Use Evaluation Report. June.

- Stellar Environmental Solutions, Inc. (SES), 2004a. Workplan for Groundwater Characterization, Benner Automotive, 488 25th Street, Oakland, California. February 13.
- SES, 2004b. Workplan Addendum for Groundwater Characterization, Benner Automotive, 488 25th Street, Oakland, California. March 26.
- SES, 2004c. Additional Site Characterization Report, Benner Automotive Facility, 488 25th Street, Oakland, California. August 9.
- SES, 2003a. Gasoline Underground Storage Tank Removal Report, Benner Automotive, 488 25th Street, Oakland, California. January 24.
- SES, 2003b. Workplan for Site Investigation Benner Auto Repair, Inc. Facility, 488 25th Street, Oakland, California. April 21.
- SES, 2003c. Revisions to Workplan for Site Investigation Benner Auto Repair, Inc. Facility, 488 25th Street, Oakland, California. July 2.
- SES, 2003d. Preliminary Site Assessment Report Benner Automotive, 488 25th Street, Oakland, California. July 2.
- Wilson, J.T., F.M. Pfeffer, J.W. Weaver, D.H. Kampbell, R.S. Kerr, T.H. Wiedemeir, J.E.
 Hansen, and R.N. Miller, 1994. Intrinsic Bioremediation of JP-4 Jet Fuel, Proc.
 Symposium on Intrinsic Bioremediation of Groundwater, Denver Colorado. August 30-September 1.

9.0 LIMITATIONS

This report has been prepared for the exclusive use of Joseph and Loretta Benner Family Trust, Benner Automotive, their authorized representatives, and the regulatory agencies. No reliance on this report shall be made by anyone other than those for whom it was prepared.

The findings and conclusions presented in this report are based on a review of previous investigators' findings at the site, as well as site investigations conducted by SES since 2003. This report has been prepared in accordance with generally accepted methodologies and standards of practice. The SES personnel who performed this limited remedial investigation are qualified to perform such investigations and have accurately reported the information available, but cannot attest to the validity of that information. No warranty, expressed or implied, is made as to the findings, conclusions, and recommendations included in the report.

The findings of this report are valid as of the present. Site conditions may change with the passage of time, natural processes, or human intervention, which can invalidate the findings and conclusions presented in this report. As such, this report should be considered a reflection of the current site conditions as based on the activities completed.



ALAMEDA COUNTY PUBLIC WORKS AGENCY

WATER RESOURCES SECTION

399 ELMHURST ST, HAYWARD CA. 94544-1395

PHONE (510) 674-6633 Junies You

FAX (510) 782-1939 www.acfcwcd.org APPLICANTS: PLEASE ATTACH A SITE MAP FOR ALL DRILLING CERMIC APPLICATION DESTRUCTION OF WELLS OVER 45 FEET REQUIRES A SEPARATE PERMIT APPLICATION

DRILLING PERMIT APPLICATION

FOR APPLICANT TO COMPLETE	FOR OFFICE USE
OCATIONOF PROJECT 488 -25th Street	PERMIT NUMBER W05 - USGS
	WELLINDMBER
CAKLAND CA	APN
The second secon	PERMIT CONDITIONS
The state of the s	Gircled Periot Requirements Apply
CLIENC	
vame DENDER AUTO KEPAIR	A. GENERAL
Address 488 - 254 51700 1000 516 - 832-1244	1 A permit application should be submitted so as to arrive at the ACPWA office rive days prior to
City OAKLAND Zip	proposed starting date.
APPLICANT . A CL	Typhont to ACPWA within 60 days after completion of
Same Stoler Fail Expensional Soldifical	ermitted original Department of Wales Resources-
2196 State St. # 201	Well Completion Report.
\6dress Phone <u>S& w 441 \$123</u>	 Permit is vind if project not began within 90 days of approval date
in Karketay (A 20 9-110	B. WATER SUPPLY WELLS
	1. Minimum surface seal thekness is two pickes of
TYPE OF PROJECT	comene growt placed by tremie
Well Construction Geometrical Investmation	 Minimum seuf depth is 50 feet for immocipal and
Carhodic Protection General	Industrial wells or 20 feet for denoestic and irrigation wells unless a lesson depth is specially approved.
Water Supply Contamination Monitoring West Destruction	C. CROUNDWATER MONITORING WELLS
and the state of t	INCLUDING PIEZOMETERS
ROPOSED WATER SUPPLY WELL OSE	1. Minimum surface scal duckness is two meles of
New Domestic Replacement Domestic	aginsmi grout placed by trenue.
Municipal Irrigation	2. Minimum soul depth for monitoring wells is the
Industrial Other	maximum depth practicable or 20 feet. D. GEOTECHNICAL/CONTAMINATION
DRILLING METHOD:	Backfill bore hale by tremic with centent groun or comen
Mud Rosary Air Komay Auger	group sand mixture. Lipper over-three feet replaced in kind
Cable Other X DIRECT PUBL	तर अन्ति दलक्ष्यक्ष्यस्य दक्षमानुद्रः
DRILLEIC'S NAME EROOD ENGINEERING PRODUCT	E. CATHODIC Fill brite into de zame with concrete placed by treme
BUILDING NAME FLAGO STORESTON LASSON	F. WELL DESTRUCTION
DRILLER'S LICENSE NO. C-ST # 777007	Send a map of work site. A separate permit is required
	for wells deeper than 45 feet
	(G) Spigul conditions
WELL PROJECTS # #G	NOTE: One application units be submitted for each well or well
Dr.H. Hole Diameter 7 1 in. Maximum Cusing Diameter 1" in. Depth 25 ii.	destructing Multiple borness on one application are acceptable
Drill Hole Diameter 3 1/4 m. Maximum Casing Diameter 1/4 m. Depth 25 n. Nurface Soil Depth 9 ft. Owner's Well Number MW-	for gentechnical and contamination my estigations
GEOTECHNICALICONTAMINATION PROJECTS See all	ached 3/18/05
Number of Borings Maximum Flate Diameter in. Depth to the Action of the	al addendum
Flate Diameter in. Depth totrackwise	al addendin
TARTING DATE April 14 Zoo5	
•	1.A 2.57.2
COMPLETION DATE Apr. 1 14 2005	APPROVED DATE 3-12-
	APPROVED BATE
hereby agree to comply with all requirements of this permit and Alameda County Ordina	since No. 73-68.
1 Bl	
APPLICANT'S SIGNATURE BALL M. TOWN RG. 6814 DATE 3/15	\$49.54 \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\
	1 \\\\
LEASE PRINT NAME BOVE REV.S.	11:114
	\ \ \
	1 1 1



ALAMEDA COUNTY PUBLIC WORKS AGENCY

WATER RESOURCES SECTION 300 REMNUIST ST. HAYWARD CA. 04544-1295 PHONE (510) 678-6633 James Yao

FAX (518) 782-1939
APPLICANTS: PLEASE ATTACH A SITE MAP FOR ALL DRILLING PERMIT APPLICATIONS
DESTRUCTION OF WELLS OVER 45 FEET REQUIRES A SEPARATE PERMIT APPLICATION

DRILLING PERMIT APPLICATION

FOR APPLICANT TO COMPLETE	FOR OFFICE USE ASC
LOCATION OF PROJECT 488 - 25" STEEL	PERMIT NUMBER W61 NUMBER
CAKLAND CA	APN
	PERMIT CONDITIONS Circled Permit Requirements Apply
CLIENT DER AUTO REPAIR Name DERINGER AUTO REPAIR Address 485 274 5788 Phone 516 222-1244 Cio CAMANO Zip Zip	(CENERAL. 1. A paramet application should be submitted so as to acrive at the ACPWA office five days prior in proposed starting date.
APPLICANT Name THE STATE OF TH	2. Nubmit to ACPWA within 6ft days after completion of bermitted original Department of Water Resources—Well Completion Report Permit is void if project not begun within 90 days or approval date B. WATER SUPPLY WELLS L. Minimum sertace seal thickness is two inches of
TYPE OF PROJECT Well Construction Cathodic Protection Water Supply Monitoring General Contamination Well Destruction	coment grout placed by tremic. 2. Minimum seed depth is 50 feet for installingal and industrial wells or 20 feet for domestic and strigation wells unless a lesser depth is specially approved. C. CROUNDWATER MONITORING WELLS INCLUDING PIEZOMETERS
PROPOSED WATER SUPPLY WELL USS. New Domestic 3 Replacement Domestic Nunicipal Irrigation Other	1. Minimum surface sent thickness is two inches of cement grout placed by teenite. 2. Minimum scal depth for inoritoring wells as the maximum apply practicable or 20 teet. D. GEOTECHNICALCUNTAMINATION
DRILLING METHOD: Mud Roday Air Roday August Cable Other Direct Puth DRILLING NAME Englishmental Packets	Backfill have hole by tremie with dement grout or content grout/sand mixture. Upper two-three feet replaced to kind or with compacted cuttings. E. CATHODIC Fill hole anode zone with emissive physical by terms.
DRILLER'S LICENSE NO. (-57 # FFFDOT	F. WELL DESTRUCTION Send a map of work site A suppresse permit is required for wells deeper than 45 feet. CONDITIONS WHILE CONDITIONS WHILE TO SET TO
WELL PROJECTS Chall Hole Distractor 3 //1 in Maximum Casing Oranictor 1" in Depth 25 ii Depth 41 ii Depth 25 ii Depth 41 ii Depth 25 ii Depth 41 ii Depth 25 ii Depth 41 iii Depth 25 ii Depth 41 iii Depth 42 iii Depth 41 iii Depth 42 iii Depth 42 iii Depth 41 iii Depth 42 iii	NOTE: One application must be submitted for each well or well destruction. Multiple burings on one application are acceptable
Number of Borings Maximum	attached 3/18/05 unival addendum
STARTING DATE April 14 2005	DATE 3-22-05
Thereby agree to comply with all requirements of this permit and Alameda County APPLICANT'S SIGNATURE BAND M Rum RE-6814 DATE	Ordinance No. 73-66.



ALAMEDA COUNTY PUBLIC WORKS AGENCY

WATER RESOURCES SECTION
399 ELMHURST ST. HAYWARD CA. P4544-1395
PHONE (510) 670-6633 James You

FAX: (\$10) 782-1939 WWW.Refewed.org APPLICANTS: PLEASE ATTACH A SITE MAP FOR ALL DRILLING PERMIT APPLICATIONS DESTRUCTION OF WELLS OVER 45 FEET REQUIRES A SEPARATE PERMIT APPLICATION

DRILLING PERMIT APPLICATION

FÜR APPLICANT FO COMPLETE	FOR GEFFICE OSE 172/0
OCATION OF PROJECT 486 - 25th Street	WELL NUMBER WS-USB
CAKLAND CH	APN
	PERMIT CONDITIONS
	Circled Permit Requirements Apply
LIENT DENINER AUTO REPAIR	A. GENERAL
AMO 12 NOBESC 7010 KET 11-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1	1. A permit application should be submitted so as to
in CALLAGO Phone 5/6 - 332-1244	arrive at the ACPWA office tive days prof to acopysed starting date.
	7. Submit to ACTWA within 60 days after completion of
ame Star Empressibility Silverice Sec. 7 2106 Sum St # 201 Fax 510-1644 SEC.5	primited original Department of Water Resources-
	Well Completion Report 1. Permit is void if project not begin within 90 days of
ddiess Home Sign 441 3123	approval date
The state of the s	B. WATER SUPPLY WELLS
	 Minimum surface sea; thickness is two mobes of cament group placed by treme.
YPE OF PROJECT Well Construction Georgeomical Investigation	2. Minimum scal depth is 20 feet for managinal and
Carhodic Protection General	hidustrial wells or 20 feet for demostic and impation
Water Supply Contamination	wells unless a lesser depth is specially approved. C. GROUNDWATER MONITORING WELLS
Monitoring Well Destruction	INCLUDING PIEXOMETERS
ROPOSED WATER SUPPLY WELL USE	1. Manimum surface seal diackness is two inches of
New Dumestic Replacement Domestic	coment grout placed by teemic
Manicipal ! Irrigation	 Minimum seal depth for inunitaring wells is the meximum depth proclimation or 20 feet
Industrial Other	D. GEOTECHNICAL/CONTAMINATION
ORILLING METHOD:	Backfill hore hole by menne with cement grout or cement
Mud Rolary Auger	grouts and income. Upper two-three feet replaced in kind or with compared cottings.
Cubic Other Wikisit Publi	E. CATHODIC
RILLER'S NAME ENTED ENTERING POLICE	Fill hale anode some with concrete placed by trende.
	F. WELL DESTRUCTION Send a map of work site A separate permit is required.
RILLER'S LICENSE NO. C-SF# 777007	for wells deeper than 45 feet.
	CONSMICTACIONAL MENTS
VELL PROJECTS He	NOTE: One application must be submitted for each well or well
Drill Hole Diameter 3 11 in. Maximum Casing Diameter 11 in. Depth 25 0	destriction. Multiple borings on one application are acceptable
Casing Diameter 1" in. Death 25 0 Surface Seal Depth 41 fr. Owner's Well Number MW-3	for gentechnical and exponentation investigations.
EEOTECHNICAL/CONTAMINATION PROJECTS See affect	ched 31,8105
Number of Borines Maximum	
Hole Diameter in. Dapth in. Technica	l addendym
TARTING DATE April 14 2005	27000
1 -	
OMPLETION DATE April 14 2005	APPROVED A
	N. 7145 / / \
hereby agree to compty with all requirements of this permit and Alameda County Ordinan	JRC (AID 1/7 GU)
LEASE PRINT NAME POWE PARE PROVINCE REVISIT	<u>√c;</u>
	\ \ V
LEASE PRINT NAME TO LEE LAW KEE	1-114
	\



EXCAVATION PERMIT

CIVIL ENGINEERIN

TO EXCAVATE IN STREETS OR OTHER SPECIFIED WORK

PAGE 2 of 2

Permit valid for 90 days from date of issuance.

APPROX. START DATE APPROX. END DATE MAY 25 2005 MAY 28 2005 APPROX. END DATE CONTRACTOR'S LICENSE # AND CLASS ATTENTION: 1- State law requires that the contractor/owner call Underground Service Alert (USA) two working days before excavating. This permit is not valid unless applicant has secured an inquiry identification number issued by USA. The USA telephone number is 1-800-642-2444. Underground Service Alert (USA) # 180 43 9 2- 48 hours prior to starting work, you MUST CALL (510) 238-3651 to schedule an inspection. 3- 48 hours prior to re-paving, a compaction certificate is required (waived for approved slurry backfill). OWNER/BUILDER Thereby affirm that I am exempt from the Contractor's License Law for the following reason (Sec. 7031.5 Business and Professions Code: Any city or county which requires a permit is income to the applicant for such permit to file a signed statement that he is licensed pursuant to the
APPROX. START DATE APPROX. END DATE M4 25 2005 (Permit not valid without 24-Hour number) CONTRACTOR'S LICENSE # AND CLASS CITY BUSINESS TAX # 705927 (C-57) ATTENTION: 1- State law requires that the contractor/owner call Underground Service Alert (USA) two working days before excavating. This permit is not valid unless applicant has secured an inquiry identification number issued by USA. The USA telephone number is 1-800-642-2449. Underground Service Alert (USA) # 130 H39 2- 48 hours prior to starting work, you MUST CALL (510) 238-3651 to schedule an inspection. 3- 48 hours prior to re-paving, a compaction certificate is required (waived for approved slurry backfill).
APPROX. START DATE M44 25 2005 M44 28 2005 (Permit not valid without 24-Hour number) CONTRACTOR'S LICENSE # AND CLASS CITY BUSINESS TAX # 705927 (C-57) ATTENTION: 1- State law requires that the contractor/owner call Underground Service Alert (USA) two working days before excavating. This permit is not valid unless applicant has secured an inquiry identification number issued by USA. The USA telephone number is 1-800-642-2444. Underground Service Alert (USA) # 180 43 9 2- 48 hours prior to starting work, you MUST CALL (510) 238-3651 to schedule an inspection. 3- 48 hours prior to re-paving, a compaction certificate is required (waived for approved slurry backfill). OWNER/BUILDER
CONTRACTOR'S LICENSE # AND CLASS CITY BUSINESS TAX # 705 927 (C-57) ATTENTION: 1- State law requires that the contractor/owner call Underground Service Alent (USA) two working days before excavating. This permit is not valid unless applicant has secured an inquiry identification number issued by USA. The USA telephone number is 1-800-642-2444. Underground Service Alent (USA) # 180 H 3 9 2- 48 hours prior to starting work, you MUST CALL (510) 238-3651 to schedule an inspection. 3- 48 hours prior to re-paving, a compaction certificate is required (waived for approved slurry backfill). OWNER/BUILDER
ATTENTION: 1- State law requires that the contractor/owner call Underground Service Alert (USA) two working days before excavating. This permit is not valid unless applicant has secured an inquiry identification number issued by USA. The USA telephone number is 1-800-642-2444. Underground Service Alert (USA) # 18043 9 2- 48 hours prior to starting work, you MUST CALL (510) 238-3651 to schedule an inspection. 3- 48 hours prior to re-paving, a compaction certificate is required (waived for approved slurry backfill). OWNER/BUILDER
ATTENTION: 1. State law requires that the contractor/owner call Underground Service Alert (USA) two working days before excavating. This permit is not valid unless applicant has secured an inquiry identification number issued by USA. The USA telephone number is 1-800-642-2444. Underground Service Alert (USA) #
ATTENTION: 1. State law requires that the contractor/owner call Underground Service Alert (USA) two working days before excavating. This permit is not valid unless applicant has 1. State law requires that the contractor/owner call Underground Service Alert (USA) two working days before excavating. This permit is not valid unless applicant has 1. State law requires that the contractor/owner call Underground Service Alert (USA) #
2- 48 hours prior to starting work, you MUST CALL (510) 238-3651 to schedule an inspection. 3- 48 hours prior to re-paving, a compaction certificate is required (waived for approved slurry backfill). OWNER/BUILDER
2- 48 hours prior to starting work, you MUST CALL (510) 238-3651 to schedule an inspection. 3- 48 hours prior to re-paving, a compaction certificate is required (waived for approved slurry backfill). OWNER/BUILDER
3- 48 hours prior to re-paving, a compaction certificate is required (walved for approved start) of the start
OWNER/BUILDER
OWNER/BUILDER Owner/
OWNER/BUILDER
the Contractor's License Law for the following reason (see, 1051.) District the property that he is licensed purguant to the
construct after amorove, actualism, of tepad and account of the Distances and Processions Coop, of that he are not account to the distances and processions coop, of that he are not account to the distance and processions coop, of that he are not account to the distance and processions coop, of the distance and processions are not account to the distance and the di
provisions of the Contractor's Lieutes law chapter of the chapter of the contractor's Lieutes law chapter of the chapter
Professions Code: The Contractor's Literate Law the type of the building or improvement is sold within one year of completion,
provided that such improvements are not interest of other or the purpose of sale). burden of proving that he did not build or improve for the purpose of sale). l, as owner of the property, an exempt from the sale requirements of the above due to: (1) I am improving my principal place of residence or appurtenances thereto, (2) the work will be a source of the property, an exempt from the sale requirements of the above due to: (1) I am improving my principal place of residence or appurtenances thereto, (2) the work will be a source of the property, and exempt from the sale requirements of the above due to: (1) I am improving my principal place of residence or appurtenances thereto, (2) the work will be a source of the property, and exempt from the sale requirements of the above due to: (1) I am improving my principal place of residence or appurtenances thereto, (2) the work will be a source of the property, and exempt from the sale requirements of the above due to: (1) I am improving my principal place of residence or appurtenances thereto, (2) the work will be a source of the property, and (3) I have not claimed exemption on this subdivision on more than
burden of proving that he did not nature of unproveror in purpoveror in
he performed prior to sale, (3) I nave restore a first period. (Sec. 7044 Business and Professions Code).
be performed prior to sale, (3) I nave resided in the less and Professions Code). structures more than once during any three-year period. (Sec. 7044 Business and Professions Code). I, as owner of the property, am exclusively contracting with licensed contractors to construct the project, (Sec. 7044. Business and Professions Code: The Contractor's License Law over of the property, am exclusively contractor's License law). does not apply to an owner of property who builds or improves thereon, and who contracts for such projects with a contractor(s) licensed pursuant to the Contractor's License law). B&PC for this reason.
does not apply to an owner of property who builds or improves aletted, and who builds or improves aletted
WORKER'S COMPENSATION
WORKER'S COMPENSATION I hereby affirm that I have a certificate of consent to self-insure, or a certificate of Worker's Compensation Insurance, or a certified copy thereof (Sec. 3700, Labor Code).
Company Name
Policy #
Policy # 1 certify that in the performance of the work for which this permit is issued, I shall not employ any person in any manner so as to become subject to the Worker's Compensation La
of California (not required for work valued at one hundred dollars (\$100) or less).
We dead Compensation provisions of the Labor Code, you must forthwite
NOTICE TO APPLICANT: If, after making this Certificate of Exemption, you should become subject to the Worker's Compensation provisions of the Labor Code, you must forthwit NOTICE TO APPLICANT: If, after making this Certificate of Exemption, you should become subject to the Worker's Compensation provisions of the Labor Code, you must forthwit comply with such provisions or this permit shall be deemed revoked. This permit is issued pursuant to all provisions of Title 12 Chapter 12.12 of the Oakland Municipal Code. It is comply with such provisions or this permit or arising out of permittee's failure that the permit or arising out of permittee's failure that the permit or arising out of permittee's failure that the permit of the City its office.
couply with such provisions or his permit sain be continued to the coupling the permit of arising out of work performed under the permit of arising out of the permit of the per
granted upon the express condition that the permittee shall be responsible for all claims and habilities arising out of work performed infer inc permit to arising out of the permittee shall be responsible for all claims and habilities arising out of work performed infer inc permit to arising out of the permittee shall upon the express condition that the permittee shall and by acceptance of the permit agrees to defend, indemnify, save and hold harmless the City, its office perform the obligations with respect to street maintenance. The permittee shall and by acceptance of the permit agrees to defend, indemnify, save and hold harmless the City, its office perform the obligations with respect to street maintenance. The permittee shall be responsible for all claims and habilities arising out of work performed indemnify, save and hold harmless the City, its office perform the obligations with respect to street maintenance. The permittee shall upon the permittee
and employees, from and against any and all suits, claims, or and employees, from the obligations with respect to sacce manufacture of permittee's failure to perform the obligations with respect to sacce manufacture of permittee's failure to perform the obligations with respect to sacce manufacture of permittee's failure to perform the obligations with respect to sacce manufacture of permittee's failure to perform the obligations.
sustained or arising in the construction of the work performed under the permit of in consequence of the Office of Planning and Building permit is void 90 days from the date of issuance unless an extension is granted by the Director of the Office of Planning and Building.
I hereby affirm that I am licensed under provisions of Chapter 9 of Division 3 of the Business and Professions. Code and my license is in full force and effect (if contractor), that I have
I hereby affirm that I am licensed under provisions of Chapter's of Structure and correct under penalty of law. this permit and agree to its requirements, and that the above information is true and correct under penalty of law.
The state of the s
body (1-
Signature of Permittee Agent for Contractor Owner Date LIMITED OPERATION AREA?
DATE STREET LAST SPECIAL PAVING DETAIL HOLIDAY RESTRICTION
RESURFACED REQUIRED? 6 YES 500 (NOV 1- JAN 3)
ISSUED BY DATE ISSUED

CONFIDENTIAL

STATE OF CALIFORNIA DWR WELL COMPLETION REPORT (WELL LOGS)

REMOVED

CONFIDENTIAL

STATE OF CALIFORNIA DWR WELL COMPLETION REPORT (WELL LOGS)

REMOVED

CONFIDENTIAL

STATE OF CALIFORNIA DWR WELL COMPLETION REPORT (WELL LOGS)

REMOVED



Subject: Direct push drill rig at location MW-1.

Site: Benner Automotive, 488 25th Street, Oakland, California

Date Taken: May 25, 2005 Project No.: SES 2002-55

Photographer: Joe Dinan Photo No.: 01



Subject: Installing pre-packed monitoring well at MW-1.

Site: Benner Automotive, 488 25th Street, Oakland, California

Date Taken: May 25, 2005 Project No.: SES 2002-55

Photographer: Joe Dinan Photo No.: 02



Subject: Emplacing pollution seal at MW-1

Site: Benner Automotive, 488 25th Street, Oakland, California

Date Taken: May 25, 2005 Project No.: SES 2002-55

Photographer: Joe Dinan Photo No.: 03



Subject: Concrete coring at MW-2.

Site: Benner Automotive, 488 25th Street, Oakland, California

Date Taken: May 25, 2005 Project No.: SES 2002-55

Photographer: Joe Dinan Photo No.: 04



Subject: Setting well box and surface completion at MW-2.

Site: Benner Automotive, 488 25th Street, Oakland, California

Date Taken: May 25, 2005 Project No.: SES 2002-55

Photographer: Joe Dinan Photo No.: 05



Subject: Direct push drill rig at location MW-3.

Site: Benner Automotive, 488 25th Street, Oakland, California


Date Taken: May 25, 2005 Project No.: SES 2002-55

Photographer: Joe Dinan Photo No.: 06



Soil Boring and Well Construction Log

	BORING NUMBER MW-1 Page 1 of 3
PROJECT Benner Auto Repair	OWNER Benner Family Trust
LOCATION 488-25th Street	PROJECT NUMBER 2002-55
TOTAL DEPTH25'	BOREHOLE DIA. 3.25-inch
SURFACE ELEV. Unknown	WATER FIRST ENCOUNTERED
DRILLING COMPANYVironex, Inc.	DRILLING METHOD Geo Probe (direct push)
	Joe Dinan DATE DRILLED 5/25/05










Soil Boring and Well Construction Log

		BORING NUMBER MY	N-1 Page 2 of 3
PROJECT Benner Auto Repair		OWNER Benner I	Family Trust
LOCATION 488-25th Stre		PROJECT NUMBER	2002-55
TOTAL DEPTH25'		BOREHOLE DIA 3.	
SURFACE ELEV. Unknow	vn	WATER FIRST ENCOU	NTERED
DRILLING COMPANY	/ironex, Inc.	DRILLING METHOD _	Geo Probe (direct push)
DRILLER Kurt		Joe Dinan	DATE DRILLED 5/25/05





Soil Boring and Well Construction Log


n	BORING NUMBER MW-1 Page 3 of 3
PROJECT Benner Auto Repair	OWNER Benner Family Trust
LOCATION 488-25th Street	PROJECT NUMBER 2002-55
TOTAL DEPTH	BOREHOLE DIA. 3.25-inch
SURFACE ELEV. Unknown	WATER FIRST ENCOUNTERED
DRILLING COMPANY Vironex, Inc.	DRILLING METHOD Geo Probe (direct push)
DRILLER Kurt GEOLOGIST	Joe Dinan DATE DRILLED 5/25/05

DEPTH	GRAPHIC Z	A B B B B B B B B B B B B B B B B B B B	PENALDICO	WELL CONSTRUCTION
(feet)	GRAPHIC LOG	DESCRIPTION/SOIL CLASSIFICATION	REMARKS	MW-1
20		20' Saturated brown, sandy clay, cohesi	No water in borehole until 20'. Water level rose to ~11' bgs within 2 hours.	
22		23' Color change to blue-grey, stiff,	5	
23 -		cohesive, sl. moist		
25	MW-1-24.5	Bottom of borehole = 25'		Bottom of Borehole
26				
27 —				
29 =				
30 =		·s		
0				



Soil Boring and Well Construction Log


	BORING NUMBER MVV-2 Page of3
PROJECT Benner Auto Repair	OWNER Benner Family Trust
LOCATION 488-25th Street	PROJECT NUMBER 2002-55
TOTAL DEPTH25'	BOREHOLE DIA. 3.25-inch
SURFACE ELEV. Unknown	WATER FIRST ENCOUNTERED
DRILLING COMPANY Vironex, Inc.	DRILLING METHOD Geo Probe (direct push)
DRILLER Kurt GEOLOGIST	Joe Dinan DATE DRILLED 5/25/05



	5	T	E	П	П		
H	Envi	RONM	ENTA	ı. Sı	DLUT	ions,	INC
**************************************	FOSCIE	NCE &	ENG	INEER	ING (Consu	LTING

Soil Boring and Well Construction Log

	BORING NUMBER MW-2 Page 2 of 3
PROJECT Benner Auto Repair	OWNER Benner Family Trust
LOCATION 488-25th Street	PROJECT NUMBER 2002-55
TOTAL DEPTH25'	BOREHOLE DIA. 3.25-inch
SURFACE ELEV. Unknown	WATER FIRST ENCOUNTERED
DRILLING COMPANYVironex, Inc.	DRILLING METHOD Geo Probe (direct push)
DRILLER Kurt GEOLOGIST	Joe Dinan DATE DRILLED 5/25/05





Soil Boring and Well Construction Log

		BORING NUMBER M	W-2 Page _	3 of <u>3</u>
PROJECT Benner Auto	Repair	OWNER Benner	Family Trust	
LOCATION 488-25th St		PROJECT NUMBER _		
TOTAL DEPTH25'		BOREHOLE DIA3		
SURFACE ELEV. Unkn				20'
DRILLING COMPANY _	Vironex, Inc.	DRILLING METHOD	Geo Probe	(direct push)
DRILLER Kurt	GEOLOGIS	T Joe Dinan	DATE DRILL	ED _5/25/05
DEPTH GRAPHIC PROBLEMS (feet) GRAPHIC LOG	DESCRIPTION/SO	IL CLASSIFICATION	REMARKS	WELL CONSTRUCTION MW-2
20 - 21 - 21 - 21 - 21 - 21 - 21 - 21 -	20' Saturated, soft		No water in borehole until 20'. Water level rose to -9' bgs within 3 hours.	
22 = /././.	22' Color change to blu	ue-grey, mod. stiff		
24 — [MW-2-24.5]	Grey silty clay (CL), sti	ff, cohesive, sl. moist		
	Bottom of borehole = 2	25'		Bottom of Borehole
26 -				
27 =				
28 -				
29 🗖				2
4				
30 🗆				1
				ľ
-				
	2" PVC screen Hvd	rated T #20/40	□ Portland	■ Groundwater



Soil Boring and Well Construction Log


	BORING NUMBER MW-3 Page 1 of 3
PROJECT Benner Auto Repair	OWNER Benner Family Trust
	PROJECT NUMBER 2002-55
	BOREHOLE DIA. 3.25-inch
	WATER FIRST ENCOUNTERED
	DRILLING METHOD Geo Probe (direct push)
DRILLER Kurt GEOLOGIST	Joe Dinan DATE DRILLED 5/25/05

DEPTH	CRAPHIC	当後		700011120111	WELL CONSTRUCTION
(feet)	GRAPHIC LOG	SAMPLE INTERVA RECOVER	DESCRIPTION/SOIL CLASSIFICATION	REMARKS	MW-3
0	2 a w		Asphalt then concrete	Continuous core sampling	
1=			No recovery from 0.5'-4'		
2					
3					
4			4' Black silty clay (CL), stiff, cohesive, mod. friable, sl. moist, occ. gravel		
5			5' Blue-grey mottling		
6		11			
7		11			
8]			
9			9' Petroleum odor		
10	MW-3-9.5'				
7	////	1	8		



Soil Boring and Well Construction Log

	BORING NUMBER MW-3 Page 2 of 3
PROJECT Benner Auto Repair	OWNER Benner Family Trust
	PROJECT NUMBER 2002-55
TOTAL DEPTH30'	BOREHOLE DIA. 3.25-inch
SURFACE ELEV. Unknown	WATER FIRST ENCOUNTERED
DRILLING COMPANY Vironex, Inc.	DRILLING METHOD _ Geo Probe (direct push)
	Joe Dinan DATE DRILLED 5/25/05
	Tursi concrete



4	S	T	层			A	R
	Envi	RONN	ENTA	L S	TUJIC	ions,	INC
′‱‱ (EOSCIE	NCE &	ENG	INEE	HNG !	Consul	TING

Soil Boring and Well Construction Log

	BORING NUMBER MW-3 Page 3 of 3
PROJECT Benner Auto Repair	OWNER Benner Family Trust
LOCATION 488-25th Street	PROJECT NUMBER 2002-55
	BOREHOLE DIA. 3.25-inch
SURFACE ELEV. Unknown	WATER FIRST ENCOUNTERED
	DRILLING METHOD _ Geo Probe (direct push)
	Joe Dinan DATE DRILLED 5/25/05

DEPTH (feet)	GRAPHIC LOG	SAMPLE INTERVAL/ RECOVERY	DESCRIPTION/SOIL CLASSIFICATION	REMARKS	WELL CONSTRUCTION
20	\\\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	87	Brown gravelly clayey sand (SC), soft, cohesive, saturated, 20.5' Becomes moist	No water in borehole until 20'. Water level rose to -8.7' bgs within 2 hours.	
25	MW-3-24.5		Dark brown sandy clay (CL), moist, cohesive, mod. stiff, minor gravel	2	
28 -			28' Becomes v. stiff, sl. moist	٠	
30 =	MW-3-29.5		Bottom of borehole = 30'		Bottom of Borehole

Well Construction Legend:

2" PVC screen (0.010-in. slots) Hydrated bentonite pellets #20/40 Sand Portland cement & water grout



NORTH STATE LABS

FLUID-LEVEL MONITORING DATA

Project No:	Date:	5-31-05
Project/Site Location: 488 25TH ST.,	OAKLAND,	CA
Technician: Scott Cassady	Method:	ELECTRONIC

Well	Depth to Water (feet)	Depth to Product (feet)	Product Thickness (feet)	Total Well Depth (feet)	Comments
WM-1	10.09			24.66	1240
MW-2	9.02			24.35	1235
MW-3	8.80			24.87	1250
				P 1	
					U,
	17				

Measurements referenced to top of well casing. NORTH

Page ____ of ___

NORTH STATE LABS

WELL PURGING/SAMPLING DATA

	umber:_		-11-	1	•	115.	3-31-0								
roject	Site Loca	tion:	ENNER	AUTOM	OTIVE	_									
				, CA S											
Samueler	Technic			, 00	-										
	ancter (in				0.75	1 2	!	4	6						
	hamos (ga				0.02	0.	2	0.7	1.52						
Well No.	MW				Well No.	MW-	2_								
A. Total	Well Dep	da	1 2	4.66	A. Total	Well Dep	fh		4.35						
	To Water		10	0.09	B. Depth	B. Depth To Water									
	Height (A			1.57		C. Water Height (A-B) 15.33									
	Casing Di			.75		Casing Di			0.75						
	Case Vol			29	E. Casing	Com Wal	ome (CxE		2.31						
	e Volume			.9	G. Com	Volume	(s)(CxEx	5	3.1						
H. 80%	Recharge I	evel		0.36	H. 80% I				.33						
Pinish To Post Pur Depth to Time Me Recharge Depth to	water Water washed:	0 18.68 1503 766	2.6	2.9	Finish Ti Pant Part Dopth to Time Me Mechany		18.21 1405 1405	2.8	3.1						
			_	_			-	_							
pH	6.78	6.98	7.03	7.09	piH	6.68	6.74	6.79	6.78						
T(°C)		20.8	20.8	20.6	T(°C)	23.2	-	20.1	20.5						
DO mg/L	815	792	769	783	Cond. DO mg/L	837	764	718	615						
DO%					DO%										
Turbidity					Turbidity										
ORP					ORP										
Same	ry Dete:		-		See	y Date:									
Total Ga	llous Parg	pd: 2.0	1				pd: 3.1								
	wice: (4				Purge de	vioe: (5	co 37	00							
	g Device:							BAILER	5						
Sample (Collection	Time: 1	615				Time: /								
-		- "	01500	1.1			e#Orior		-,						

NORTH STATE LABS

WELL PURGING/SAMPLING DATA

roject Number:					5.3	1-05	
roject / Site Loc	ation: B	ENNER	AUTOMO	TIVE			
355	L	88 2	5TH ST				
		AKLANT	CA	1			
iampler/Techni Casing Diameter (i				0.75	2	4	6
lasing Volumes (2				0.02	0.2	0.7	1.52
See Acustore (E	imores)						-
Well No. Mu	(-3_			Well No.			
A. Total Well De			1.87	A. Total We			
B. Depth To Wat			.80	B. Depth To		_	
C. Water Height			0.07	C. Water He	es Diseaster		
D. Well Casing D			0.75	D. Well Casi	ng rymenters	_	
E. Casing Volume F. Single Case Vo	shame (CyE		0.32	E. Casing Vo F. Single Ca	e Volume (C	SE)	
G. Case Volum	o(s)(CxEx		3.2	G. Case Vo	ohmue(s)(Cxi	x)	10151
H. 80% Recharge			1.12	H. 80% Reci			15
77767	10.15 1545 9.05 1605			1	formerson ter red: mark 7 has ter.		
Gals. 2.3	2.6	2.9	3.2	Gais.			+-
pH 6.68	6.63	6.65	6.65	Hq		_	-
T(C) 22.5		20.2	20.4	T(C)			+-
Count 458	409	404	399.	Cond.			-
DO		1		DO mg/L		1	1
mg/L DO %	-	+		DO%			1
Turbidity	+	+		Tuebidity			1
ORP	1	1		ORP			
Summary Data:	0			Summary I	Reduc		
Total Gallous Po		7_		Total Galler			
Purge device:				Purge devic			
Sampling Device				Sampling D			
Sample Collection			7		lection Time:		
Sample Appeara			IGN		carance/Odo		



Curtis & Tompkins, Ltd., Analytical Laboratories, Since 1878

2323 Fifth Street, Berkeley, CA 9471O, Phone (510) 486-0900

ANALYTICAL REPORT

Prepared for:

Stellar Environmental Solutions 2198 6th Street Suite 201 Berkeley, CA 94710

Date: 01-JUN-05 Lab Job Number: 179661

Project ID: 2002-55

Location: Benner Automotive

This data package has been reviewed for technical correctness and completeness. Release of this data has been authorized by the Laboratory Manager or the Manager's designee, as verified by the following signatures. The results contained in this report meet all requirements of NELAC and pertain only to those samples which were submitted for analysis.

Reviewed by:

Project Manager

Reviewed by:

Manager

This package may be reproduced only in its entirety.

NELAP # 01107CA

Page 1 of ____



CASE NARRATIVE

Laboratory number:

179661

Client: Project: Stellar Environmental Solutions

2002-55

Location:

Benner Automotive

Request Date:

05/25/05

Samples Received:

05/25/05

This hardcopy data package contains sample and QC results for fourteen soil samples, requested for the above referenced project on 05/25/05. The samples were received cold and intact.

TPH-Purgeables and/or BTXE by GC (EPA 8015B and EPA 8021B): No analytical problems were encountered.

Volatile Organics by GC/MS (EPA 8260B):

Low response was observed for tert-butyl alcohol (TBA) in the CCV analyzed 05/31/05 18:00; this analyte met minimum response criteria, and affected data was qualified with "b". High surrogate recoveries were observed for 1,2-dichloroethane-d4 in MW-2-9.5' (lab # 179661-001) and MW-1-9.5' (lab # 179661-005); no target analytes were detected in these samples. No other analytical problems were encountered.

Chain of Custody Record

job no. 17966/

	ooratory <u>Curtis and Tomp</u> dress <u>2323 Fifth Stree</u>	t			-	thod of Shipment <u>Ha</u>	nd Deli	very	- -											Page of	2
	Berkeley, Califor 510-486-0900	rnia 94/10) ————		— _{Air}	bill No.			_							Analy	sis Re	periup]
_					_ _{Co}	oler No.			_				\square	$\overline{}$	7	7	7	\overline{T}	7	777]
	pject Owner Benner Auto	Repair			— Pro	ject ManagerBruc	e Ruck	er	_	/	_ /	/ Se /	′ /	//	/ /	/ /	/ /	/ /	/ /	' / /	
Sit	e Address Oakland, Ca		-			ephone No. <u>(510)</u> 644-	3123		_		y / 5	\$ /	//	/ /						//	
-	oject Name Benner Auto	Repair				x No(510) 644-	3859		_	/ ~	/ॐ	Containers	/ ङ्ग		/	/	/	/ .	/ /	/ / Remark	ks
	oject Number 2002-55				_	mplers: (Signature)	ach C	2-	_ /				3/ }	/ /	' /	/		′ /			
	·	Location/	1	[Sample			eservation	1/		1		¥ /	′ /						/	
	Field Sample Number	Depth	Date	Time	Туре	Type/Size of Container	Cooler	Chemical	<u>/</u>	_		(('{-		-	\leftarrow	_	_	\leftarrow	/	-
	MW-2-9-5'	7.5°	05/25	905	soil	acetate sleeve	yes	none	No	~	X,	X				ļ					
۱,	MW-Z-14.5'	14.51	05/25	915	soil	acetate sleeve	yes	none		١	X	X		<u> </u>							
	Mw-2-19-5'	19.5'	05/25	918	soil	acetate sleeve	yes	none		1	X	X									
	1w-2-24.5'	24.5	05/25	920	soil	acetate sleeve	yes	none	1)	1		X	Ì								
	4W-1-9.5'	4.5'	05/25	1010	soil	acetate sleeve	yes	none	1	Ţ	X	X									
	NW-1-14.81	14.5'	05/25	1020	soil	acetate sleeve	yes	none		ι	X	X									
	4W-1-14.8	19-5"	¢ 5/25	10:30	şoil	acetate sleeve	yes	none	1/	l	X	X									
		24.5°	05/25			acetate sleeve	yes	none	\setminus	1	X	X		_			ļ		ļ		
· [· · ·	10-1-245'	9:5'	05/25	1/0	soil	acetate sleeve	ves	none)	1	X	X									
۱H	Mw-3- 9.5'		D5/25	1,6 000		acetate sleeve	ves	none	1/	t	X	Y		+	1		 	1	一		
٥Į⊿	NW-3-14.5'	14.5'		1130	soil	acetate sleeve	 	 	+		1	\		-	╁		-	╁	-		
ľ	Mw-3-19.5'	19-5'	05/25	+	 		yes	none	1	1	X	X				 	!	<u> </u>	-		
H	MW-3-24.5'	PA-2,	05/25	1150	soil	acetate sleeve	yes	none		1	X	X			<u>Ļ</u>	1		<u> </u>	<u> </u>		
F	Relinquished by:	<u></u>	Date 5/25	Receive Signs	/ 1	Tavanyalok.	Date 25	Signature	by:					Date	R	eceive Signa					Date
	Printed Joe Dinan		Time	Printe		wann Cuti	Time	'' '						Time	•	Printe	ed				Time
	Company Stellar Environm	nental	1357		(4+	<u>م</u>									C					
-				Cam	pany		<u>- </u>	Refinguished						Date	, _P	Comp					Date
	Turnaround Time: 5 Day TAT					<u> </u>		Signature	-							Signa			<u>-</u> .		
	Comments: (A) BTEX		DВ,	EDC,	TAM	ETBE, DIPE,	TBA								_						
<u> </u>	ethar	<u> </u>						Printed _						· Time	•	Printe	ed				Time
9							<i>-</i>	Company						-		Com	рапу _				

Chain of Custody Record

ab job no. 17966/

Address 2323 Fifth Street					ethod of Shipment <u>Ha</u> 	ina Dei	ivery													Page _	2 of	2
Berkeley, Califo		0						_				, ,										
510-486-0900				Ai	rbill No			_			/					Analy	sis Red	quired			. /	
Project Owner Benner Auto Site Address 488-25th Str Oakland, Ca	reet			Pr	ooler NoBruc oject ManagerBruc lephone No(510) 644-	e Ruck 3123	er	 		· fered	Soulishings.	[1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	1/	7	7/	7/	7/		7	
Project Name Benner Auto	Repair				x No(510) 644-			_	/`	. المح		//	$\chi_{\hat{\mathcal{Q}}}$	1	/ /	/ ,	/			/ /	Remark	ks
Project Number 2002-55	·			Sa	ımplers: <i>(Signature)</i>	yl. A	<u> </u>	-/	/ /	/ /	# D					/			' /			
Field Sample Number	Location/ Depth	Date	Time	Sample Type	Type/Size of Container	Pr	eservation Chemical	V		/	70		30	/ /	/ /	/ ,	Ι,		/ ,			
MW-3-29.5'	29.5	05/25	1200	soil	acetate sleeve	yes	none	No	1	X	X											
Soil Drum Comp		1	1245	\$	1602 Glass Jar	 	\$	1	1			X										
'														T								
															_	\dashv	寸					
	-		-										寸			-	1					
																+		-	-			
	•		<u> </u>					-								+						
				, <u>.</u>	<u> </u>			 —	<u> </u>				\dashv			\dashv						
		+							<u> </u>		<u> </u>		-			\dashv						
	 _	<u> </u>						_	<u> </u>	_	ļ		\rightarrow	_		\downarrow	\dashv					
		-						_	<u> </u>													
		ļ							<u> </u>					\perp								
		<u> </u>				_			<u> </u>													
Relinquished by Signature		Date 5/25	Received Signal	ur	Parametri	Dete	Relinquished Signature	b y :					-)ale	i	eived t	•					Date
Printed Joe Dinan		Time	Printe	14	vanha CorAvi	Time	Printed						- ¬	îme	Pı	rinted						Time
Company Stellar Environme	ental	1357	Comp	any(C+T	210	Company .						_		_ c	ompar	NV.					
Turnaround Time: 5 Day TAT					_		Relinquished	by:			-		-	Date	 	eived t						Date
	MTBE	EDB	EDC	- TAI	VE, ETBE, DILE,	TBA	Signature						-		Si	gnatu	re					
etha	nol						Printed						_ 1	ime	Pr	inted						Time
	•				and the second s		a icaOn		٠]	
<u> </u>					1. 2017	135	Company .						-		l c	ompar	'Y					



Total Volatile Hydrocarbons Benner Automotive EPA 5030B 179661 Lab #: Location: Stellar Environmental Solutions Client: Prep: Project#: 2002-55 05/25/05 05/25/05 05/26/05 Sampled: Matrix: as received Received: Basis: Diln Fac: 1.000 Analyzed: Batch#: 102387

Field ID:

MW-2-9.5'

Type: Lab ID:

SAMPLE 179661-001 Units:

mg/Kg

Analysis:

EPA 8015B

Analyte	Result	RL
Gasoline C7-C12	ND	0.93
Surrogate	%REC Limits	
Trifluorotoluene (FID)	100 60-138	
Bromofluorobenzene (FID)	108 <u>66-148</u>	

Field ID:

MW-2-14.5'

Type: Lab ID: SAMPLE 179661-002 Units:

mg/Kg

Analysis:

EPA 8015B

Analyte	i i	Result	RL	
Gasoline C7-C12	ND		1.1	
	#REC	Limits		
Trifluorotoluene (FID)	105	60-138		
Bromofluorobenzene (FID)	110	66-148		

Field ID:

MW-2-19.5'

Type:

SAMPLE

Lab ID:

179661-003

Units:

mg/Kg

Analysis: EPA 8015B

Analyte	Resul	RL
Gasoline C7-C12	ND	1.0
Surrogate	%REC Limit	8
Trifluorotoluene (FID)	100 60-11	8
Bromofluorobenzene (FID)	104 66-14	8

Field ID:

MW-2-24.5'

Type: Lab ID: SAMPLE

179661-004

Units:

mg/Kg

EPA 8015B Analysis:

Analyte		Result	Ri	
Gasoline C7-C12	NI	Ö	1.1	
Surrogate	FREC	Limits		
Trifluorotoluene (FID)	104	60-138		
Bromofluorobenzene (FID)	105	66-148		

ND= Not Detected RL= Reporting Limit Page 1 of 4



Total Volatile Hydrocarbons Benner Automotive EPA 5030B Lab #: 179661 Location: Stellar Environmental Solutions Client: Prep: Project#: 2002-55 05/25/05 05/25/05 05/26/05 Matrix: Soil Sampled: Basis: as received Received: 1.000 Diln Fac: Analyzed: Batch#: 102387

Field ID: Type:

MW-1-9.51

SAMPLE Lab ID: 179661-005 Units:

mg/Kg

EPA 8015B Analysis:

	Result	RI	70 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
Gasoline C7-C12	ND	1.0	
			000000000000000000000000000000000000000

Surrogate **Limits** 60-138 Trifluorotoluene (FID) 105 Bromofluorobenzene (FID) 106 66-148

Field ID:

MW-1-14.5'

SAMPLE

Units:

mg/Kg

EPA 8015B

Type: Lab ID: Analysis: 179661-006 Analyte Result RL

Gasoline C7-C12	N	D	1.0	
				_
Surrogate	*REC	Limits		
Trifluorotoluene (FID)	101	60-138		
Bromofluorobenzene (FID)	105	66-148		_

Field ID:

MW-1-19.5'

Type:

SAMPLE

179661-007

Units: Analysis: mg/Kg

EPA 8015B

Analyte Gasoline C7-C12 Result ND

Surrogate	¥REC	Limits	
Trifluorotoluene (FID)	102		
Bromofluorobenzene (FID)	106	66-148	

Field ID:

MW-1-24.5'

Type: Lab ID:

SAMPLE

179661-008

Units: Analysis: mg/Kg

EPA 8015B

Analyte Result Gasoline C7-C12

Surrogate	*REC	Limits	
Trifluorotoluene (FID)	100	60-138	,
Bromofluorobenzene (FID)	104	66-148	<u> </u>



Total Volatile Hydrocarbons

179661 Benner Automotive Lab #: Location:

Client: Stellar Environmental Solutions Prep: EPA 5030B

Project#: 2002-55

05/25/05 Matrix: Sampled: 05/25/05 as received Received: Basis: 05/26/05

Diln Fac: 1.000 Analyzed: Batch#: 102387

Field ID:

MW-3-9.5'

Type: Lab ID: SAMPLE 179661-009 Units:

mg/Kg EPA 8015B Analysis:

Result Analyte Gasoline C7-C12 1.0

Surrogate %REC Limits Trifluorotoluene (FID) 122 60-138 Bromofluorobenzene (FID) 115 66-148

Field ID:

MW-3-14.5'

Type: Lab ID:

SAMPLE

179661-010

Units:

mq/Kg

EPA 8015B Analysis:

Analyte Gasoline C7-C12 Result ND 1.0

%REC Limits Surrogate Trifluorotoluene (FID) 100 60-138 66-148 Bromofluorobenzene (FID) 105

Field ID:

MW-3-19.5'

Type: Lab ID: SAMPLE

179661-011

Units: Analysis: mg/Kg

EPA 8015B

Result

Analyte Gasoline C7-C12 ND 0.93

Surrogate %REC Limits Trifluorotoluene (FID) 103 60-138 Bromofluorobenzene (FID) 108 66-148

Field ID: Type:

MW-3-24.5'

SAMPLE 179661-012

Lab ID:

Units:

EPA 8015B Analysis:

Result Analyte

Gasoline C7-C12

*REC Limits 106 60-138 Surrogate Trifluorotoluene (FID) Bromofluorobenzene (FID) 108 66-148

ND= Not Detected RL= Reporting Limit Page 3 of 4

2.0



Total Volatile Hydrocarbons Lab #: Client: 179661 Benner Automotive EPA 5030B Location: Stellar Environmental Solutions Prep: Project#: 2002-55 Matrix: 05/25/05 05/25/05 05/26/05 Soil Sampled: Basis: Diln Fac: as received 1.000 Received: Analyzed: Batch#: 102387

Field ID: Type:

MW-3-29.5'

SAMPLE

Units: Analysis:

mg/Kg EPA 8015B

Lab ID:

179661-013

	e Result	. RL	
Gasoline C7-C12	ND	1.0	

Surrogate	%REC	Limits
Trifluorotoluene (FID)	103	60-138
Bromofluorobenzene (FID)	110	66-148

Field ID:

SOIL DRUM COMP

Lab ID:

179661-014

Type:

SAMPLE

Analyte	Result	RL	Units	Analysis
Gasoline C7-C12	ND	1.1	mq/Kq EPA	8015B
MTBE	ND	22	ug/Kg EPA	
Benzene	ND	5.4	ug/Kg EPA	
Toluene	ND	5,4	ug/Kg EPA	8021B
Ethylbenzene	ND	5.4	ug/Kg EPA	
n,p-Xylenes	ND	5.4	ug/Kg EPA	8021B
o-Xylene	ND	5.4	ug/Kg EPA	

Surrogate	%REC	Limits	Analysi	S
Trifluorotoluene (FID)	102	60-138	EPA 8015B	
Bromofluorobenzene (FID)	111	66-148	EPA 8015B	
Trifluorotoluene (PID)	75	62-126	EPA 8021B	
Bromofluorobenzene (PID)	81	72-133	EPA 8021B	

Type:

BLANK

Lab ID:

QC295160

1.0 20	mg/Kg		8015B	
20	_ /			
20	uq/Kq	EPA	8021B	
5.0	ug/Kg	EPA	8021B	
5.0	-,	EPA	8021B	
5.0	ug/Kg			
5.0	ug/Kg			
5.0	uq/Kq	EPA	8021B	
	5.0 5.0 5.0	5.0 ug/Kg 5.0 ug/Kg 5.0 ug/Kg 5.0 ug/Kg	5.0 ug/Kg EPA 5.0 ug/Kg EPA 5.0 ug/Kg EPA 5.0 ug/Kg EPA	5.0 ug/kg EPA 8021B 5.0 ug/kg EPA 8021B 5.0 ug/kg EPA 8021B 5.0 ug/kg EPA 8021B

Surrogate	*REC	Limits	Analysis	
Trifluorotoluene (FID)	104	60-138	EPA 8015B	
Bromofluorobenzene (FID)	108	66-148	EPA 8015B	
Trifluorotoluene (PID)	77	62-126	EPA 8021B	
Bromofluorobenzene (PID)	82	72-133	EPA 8021B	



	Total Volati	ile Hydrocarbo	ns
Lab #:	179661	Location:	Benner Automotive
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B
Project#:	2002-55	Analysis:	EPA 8021B
Type:	LCS	Basis:	as received
Lab ID:	QC295161	Diln Fac:	1.000
Matrix:	Soil	Batch#:	102387
Units:	ug/Kg	Analyzed:	05/26/05

Analyte	Spiked	Result	%REC	Limits
MTBE	100.0	101.7	102	70-137
Benzene	100.0	99.87	100	80-120
Toluene	100.0	97.70	98	80-120
Ethylbenzene	100.0	95.51	96	80-120
m,p-Xylenes	100.0	87.83	88	80-120
o-Xylene	100.0	92.76	93	80-120

-	Surroga		%REC	Limits	
	Trifluorotoluene	(PID)	76	62-126	
	Bromofluorobenzen		83	72-133	



	Total Vola	tile Hydrocarbo	ons	
	179661	Location:	Benner Automotive	
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B	
Project#:	2002-55	Analysis:	EPA 8015B	
Type:	LCS	Basis:	as received	
Lab ID:	QC295162	Diln Fac:	1.000	
Matrix:	Soil	Batch#:	102387	
Units:	mg/Kg	Analyzed:	05/26/05	

Analyte	Spiked	Result	%RE	C Limits	
Gasoline C7-C12	10.00	9.845	98	80-120	

Surrogate	%REC	Limits	
Trifluorotoluene (FID)	130	60-138	
Bromofluorobenzene (FID)	123	66-148	f



	Total Volat	ile Hydrocarbo	ns
Lab #:	179661	Location:	Benner Automotive
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B
Project#: :	2002-55	Analysis:	EPA 8015B
Field ID:	SOIL DRUM COMP	Diln Fac:	1.000
MSS Lab ID	: 179661-014	Batch#:	102387
Matrix:	Soil	Sampled:	05/25/05
Units:	mg/Kg	Received:	05/25/05
Basis:	as received	Analyzed:	05/26/05

MS

Lab ID: QC295163

Analyte	MSS Result	Spiked	Result	%RE	C Limits
Gasoline C7-C12	<0.1197	10.00	8.647	86	43-120

	Surroga	te	%REC	Limits		
l	Trifluorotoluene	(FID)	116	60-138		
'	Bromofluorobenzen	e (FID)	114	66-148		

Type:

MSD

Lab ID:

QC295164

Analyte		Spiked	Result	%REC	2 Limits	RPD	Lim
Gasoline C7-C12		10.00	9.517	95	43-120	10	27
							Otomory, a processor and
Surrogate	%REC	Limits					
Trifluorotoluene (FID)	121	60-138					
Bromofluorobenzene (FID)	117	66-148					



		BTXE & Oxygenates		I
Lab #:	179661	Location:	Benner Automotive	
Client:	Stellar Environmental S	olutions Prep:	EPA 5030B	
Project#:	2002-55	Analysis:	EPA 8260B	
Field ID:	MW-2-9.5'	Diln Fac:	0.9615	
Lab ID:	179661-001	Batch#:	102431	•
Matrix:	Soil	Sampled:	05/25/05	- 2
Units:	ug/Kg	Received:	05/25/05	
Basis:	as received	Analyzed:	05/27/05	_

Analyte	Result	RL	
tert-Butyl Alcohol (TBA)	ND	96	
MTBE	ND	4.8	
Isopropyl Ether (DIPE)	ND	4.8	8
Ethyl tert-Butyl Ether (ETBE)	ND	4.8	
1,2-Dichloroethane	ND	4.8	
Benzene	ND	4.8	
Methyl tert-Amyl Ether (TAME)	ND	4.8	_
Toluene	ND	4.8	_
1,2-Dibromoethane	ND	4.8	
Ethylbenzene	ND	4.8	•
m,p-Xylenes	ND	4.8	
o-Xylene	ND	4.8	
Ethanol	ND	960	

Surrogate	%REC	Limits	
Dibromofluoromethane	114	78-120	Ħ
1,2-Dichloroethane-d4	122 *	80-120	_
Toluene-d8	100	80-120	_
Bromofluorobenzene	95	80-120	I

^{*=} Value outside of QC limits; see narrative
ND= Not Detected
RL= Reporting Limit
Page 1 of 1



	BTXE 6	Oxygenates	
Lab #:	179661	Location:	Benner Automotive
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B
Project#:	2002-55	Analysis:	EPA 8260B
Field ID:	MW-2-14.5'	Diln Fac:	0.9091
Lab ID:	179661-002	Batch#:	102431
Matrix:	Soil	Sampled:	05/25/05
Units:	ug/Kg	Received:	05/25/05
Basis:	as received	Analyzed:	05/27/05

Analyte	Result	RL
tert-Butyl Alcohol (TBA)	ND	91
MTBE	ND	4.5
Isopropyl Ether (DIPE)	ND	4.5
Ethyl tert-Butyl Ether (ETBE)	ND	4.5
1,2-Dichloroethane	ND	4.5
Benzene	ND	4.5
Methyl tert-Amyl Ether (TAME)	ND	4.5
Toluene .	ND	4.5
1,2-Dibromoethane	ND	4.5
Ethylbenzene	ND	4.5
m,p-Xylenes	ND .	4.5
o-Xylene	ND	4.5
Ethanol	ND	910

	Surrogate	%REC	Limits
Z	Dibromofluoromethane	108	78-120
	1,2-Dichloroethane-d4	117	80-120
_	Toluene-d8	99	80-120
ı	Bromofluorobenzene	96	80-120



	BTXE &	Oxygenates		
Lab #: :	179661	Location:	Benner Automotive	
Client: :	Stellar Environmental Solutions	Prep:	EPA 5030B	
Project#: :	2002-55	Analysis:	EPA 8260B	
Field ID:	MW-2-19.5'	Diln Fac:	0.9434	
Lab ID:	179661-003	Batch#:	102431	
Matrix:	Soil	Sampled:	05/25/05	
Units:	ug/Kg	Received:	05/25/05	
Basis:	as received	Analyzed:	05/28/05	

Analyte	Result	RL	
tert-Butyl Alcohol (TBA)	ND	94	
MTBE	ND	4.7	
Isopropyl Ether (DIPE)	ND	4.7	
Ethyl tert-Butyl Ether (ETBE)	ND	4.7	
1,2-Dichloroethane	ND	4.7	•
Benzene	ND	4.7	(
Methyl tert-Amyl Ether (TAME)	ND	4.7	,
Toluene	ND	4.7	
1,2-Dibromoethane	ND	4.7	
Ethylbenzene	ND	4.7	_
m,p-Xylenes	ND	4.7	
o-Xylene	ND	4.7	
Ethanol	ND	940	

Surrogate	*REC	Limits	
Dibromofluoromethane	110	78-120	
1,2-Dichloroethane-d4	120	80-120	
Toluene-d8	99	80-120	
Bromofluorobenzene	98	80-120	



	BTXE	& Oxygenates	
Lab #:	179661	Location:	Benner Automotive
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B
Project#:	2002-55	Analysis:	EPA 8260B
Field ID:	MW-2-24.5	Diln Fac:	0.9804
Lab ID:	179661-004	Batch#:	102431
Matrix:	Soil	Sampled:	05/25/05
Units:	ug/Kg	Received:	05/25/05
Basis:	as received	Analyzed:	05/28/05

Analyte	Result	RL
tert-Butyl Alcohol (TBA)	ND	98
MTBE	ND	4.9
Isopropyl Ether (DIPE)	ND	4.9
Ethyl tert-Butyl Ether (ETBE)	ND	4.9
1,2-Dichloroethane	ND	4.9
Benzene	ND	4.9
Methyl tert-Amyl Ether (TAME)	ND	4.9
Toluene	ND	4.9
1,2-Dibromoethane	ND	4.9
Ethylbenzene	ND	4.9
m,p-Xylenes	ND	4.9
o-Xylene	ND	4.9
Ethanol	ND	980

	Surrogate	*REC	Limits
	Dibromofluoromethane	111	78-120
_	1,2-Dichloroethane-d4	120	80-120
-	Toluene-d8	97	80-120
	Bromofluorobenzene	98	80-120



	ETAR 6	Oxygenates		
Lab #:	179661	Location:	Benner Automotive	
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B	
Project#:	2002-55	Analysis:	EPA 8260B	
Field ID:	MW-1-9.5'	Diln Fac:	0.9804	
Lab ID:	179661-005	Batch#:	102431	
Matrix:	Soil	Sampled:	05/25/05	
Units:	ug/Kg	Received:	05/25/05	
Basis:	as received	Analyzed:	05/28/05	

Analyte	Result	RL	
tert-Butyl Alcohol (TBA)	ND	98	
MTBE	ND	4.9	
Isopropyl Ether (DIPE)	ND	4.9	J
Ethyl tert-Butyl Ether (ETBE)	ND	4.9	
1,2-Dichloroethane	ND	4.9	9
Benzene	ND	4.9	
Methyl tert-Amyl Ether (TAME)	N D	4.9	_
Toluene	ND	4.9	_
1,2-Dibromoethane	ND	4.9	T .
Ethylbenzene	ND	4.9	
m,p-Xylenes	ND	4.9	
o-Xylene	ND	4.9	9
Ethanol	ND	980	5

1,2-Dichloroethane-d4 126 * 80-120 Toluene-d8 101 80-120	Surrogate	%REC	Limits
Toluene-d8 101 80-120	Dibromofluoromethane	110	78-120
202 00 420	1,2-Dichloroethane-d4	126 *	80-120
Bromofluorobenzene 94 80-120	Toluene-d8	101	80-120
	Bromofluorobenzene	94	80-120

RL= Reporting Limit Page 1 of 1

^{*=} Value outside of QC limits; see narrative

ND= Not Detected



	BTXE 6	. Oxygenates	
Lab #:	179661	Location:	Benner Automotive
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B
Project#:	2002-55	Analysis:	EPA 8260B
Field ID:	MW-1-14.5'	Diln Fac:	0.9259
Lab ID:	179661-006	Batch#:	102431
Matrix:	Soil	Sampled:	05/25/05
Units:	ug/Kg	Received:	05/25/05
Basis:	as received	Analyzed:	05/28/05

Analyte	Result	RL
tert-Butyl Alcohol (TBA)	ND	93
MTBE	ND	4.6
Isopropyl Ether (DIPE)	ND	4.6
Ethyl tert-Butyl Ether (ETBE)	ND	4.6
1,2-Dichloroethane	, ND	4.6
Benzene	ND	4.6
Methyl tert-Amyl Ether (TAME)	ND	4.6
Toluene	ND	4.6
1,2-Dibromoethane	ND	4.6
Ethylbenzene	ND	4.6
m,p-Xylenes	ND	4.6
o-Xylene	ND	4.6
Ethanol	ND	930

Surrogate	%REC	Limits
Dibromofluoromethane	109	78-120
1,2-Dichloroethane-d4	120	80-120
Toluene-d8	97	80-120
Bromofluorobenzene	97	80-120



		BTXE &	Oxygenates		
Lab #: 1	179661		Location:	Benner Automotive	
Client: S	Stellar Environmental	Solutions	Prep:	EPA 5030B	
Project#: 2	2002-55		Analysis:	EPA 8260B	
Field ID:	MW-1-19.5'		Diln Fac:	0.9091	
Lab ID:	179661-007		Batch#:	102482	
Matrix:	Soil		Sampled:	05/25/05	
Units:	ug/Kg		Received:	05/25/05	
Basis:	as received		Analyzed:	05/31/05	

Analyte	Result	RL	
tert-Butyl Alcohol (TBA)	ND	91	
MTBE	ND	4.5	1
Isopropyl Ether (DIPE)	ND	4.5	
Ethyl tert-Butyl Ether (ETBE)	ND	4.5	
1,2-Dichloroethane	ND	4.5	•
Benzene	ND	4.5	
Methyl tert-Amyl Ether (TAME)	ND	4.5	
Toluene	ND	4.5	_
1,2-Dibromoethane	ND	4.5	
Ethylbenzene	ND	4.5	•
m,p-Xylenes	ND	4.5	
o-Xylene	ND	4.5	•
Ethanol	ND	910	

Surrogate	%REC	Limits	
Dibromofluoromethane	96	78-120	22.53.6
1,2-Dichloroethane-d4	103	80-120	_
Toluene-d8	96	80-120	-
Bromofluorobenzene	97	80-120	



	BTXE &	Oxygenates	
Lab #:	179661	Location:	Benner Automotive
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B
Project#:	2002-55	Analysis:	EPA 8260B
Field ID:	MW-1-24.5'	Diln Fac:	1.000
Lab ID:	179661-008	Batch#:	102482
Matrix:	Soil	Sampled:	05/25/05
Units:	ug/Kg	Received:	05/25/05
Basis:	as received	Analyzed:	05/31/05

Analyte	Result	RL
tert-Butyl Alcohol (TBA)	ND	100
MTBE	ND	5.0
Isopropyl Ether (DIPE)	ND	5.0
Ethyl tert-Butyl Ether (ETBE)	ND	5.0
1,2-Dichloroethane	ND	5.0
Benzene	ND	. 5.0
Methyl tert-Amyl Ether (TAME)	ND	5.0
Toluene	ND	5.0
1,2-Dibromoethane	ND	5.0
Ethylbenzene	ND	5.0
m,p-Xylenes	ND	5.0
o-Xylene	ND	5.0
Ethanol	ND	1,000

Sur	ogate	%rec	Limits
Dibromofluorom	nethane	97	78-120
1,2-Dichloroet	:hane-d4	105	80-120
Toluene-d8		97	80-120
Bromofluorober	izene	98	80-120



	BTXE &	Oxygenates		
Lab #:	179661	Location:	Benner Automotive	<u>2000/00/00/00</u>
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B	
Project#:	2002-55	Analysis:	EPA 8260B	ł
Field ID:	MW-3-9.5'	Diln Fac:	0.9259	
Lab ID:	179661-009	Batch#:	102482	1
Matrix:	Soil	Sampled:	05/25/05	
Units:	ug/Kg	Received:	05/25/05	
Basis:	as received	Analyzed:	06/01/05	1

Analyte	Result	RL	
tert-Butyl Alcohol (TBA)	ND	93	
MTBE	ND	4.6	
Isopropyl Ether (DIPE)	ND	4.6	
Ethyl tert-Butyl Ether (ETBE)	ND	4.6	
1,2-Dichloroethane	ИD	4.6	
Benzene	ND	4.6	
Methyl tert-Amyl Ether (TAME)	ND	4.6	_
Toluene	ND	4.6	-
1,2-Dibromoethane	ND	4.6	
Ethylbenzene	ND	4.6	•
m,p-Xylenes	ND	4.6	_
o-Xylene	ND	4.6	
Ethanol	ND	930	8

Surrogate	%REC	Limits	
Dibromofluoromethane	101	78-120	****
1,2-Dichloroethane-d4	110	80-120	_
Toluene-d8	98	80-120	_
Bromofluorobenzene	95	80-120	



	BTXE &	Oxygenates	
Lab #:	179661	Location:	Benner Automotive
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B
Project#:	2002-55	Analysis:	EPA 8260B
Field ID:	MW-3-14.5	Diln Fac:	0.9259
Lab ID:	179661-010	Batch#:	102482
Matrix:	Soil	Sampled:	05/25/05
Units:	ug/Kg	Received:	05/25/05
Basis:	as received	Analyzed:	06/01/05

Analyte	Result	RL .
tert-Butyl Alcohol (TBA)	ND	93
MTBE	ND	4.6
Isopropyl Ether (DIPE)	ND	4.6
Ethyl tert-Butyl Ether (ETBE)	ND	4.6
1,2-Dichloroethane	ND	4.6
Benzene	ND	4.6
Methyl tert-Amyl Ether (TAME)	ND	4.6
Toluene	ND	4.6
1,2-Dibromoethane	ND	4.6
Ethylbenzene	ND	4.6
m,p-Xylenes	ND	4.6
o-Xylene	ND	4.6
Ethanol	ND	930

	Surrogate	*REC	Limits
	Dibromofluoromethane	99	78-120
_	1,2-Dichloroethane-d4	108	80-120
	Toluene-d8	98	80-120
	Bromofluorobenzene	98	80-120



		Oxygenates	
Lab #:	179661	Location:	Benner Automotive
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B
Project#:	2002-55	Analysis:	EPA 8260B
Field ID:	MW-3-19.5'	Diln Fac:	0.9091
Lab ID:	179661-011	Batch#:	102482
Matrix:	Soil	Sampled:	05/25/05
Units:	ug/Kg	Received:	05/25/05
Basis:	as received	Analyzed:	06/01/05

Analyte	Result	RL	
tert-Butyl Alcohol (TBA)	ND	91	_
MTBE	ND	4.5	
Isopropyl Ether (DIPE)	ND	4.5	
Ethyl tert-Butyl Ether (ETBE)	ND	4.5	
1,2-Dichloroethane	ND	4.5	
Benzene	ND	4.5	
Methyl tert-Amyl Ether (TAME)	ND	4.5	_
Toluene	ND	4.5	_
1,2-Dibromoethane	ND	4.5	
Ethylbenzene	ND	4.5	
m,p-Xylenes	ND	4.5	_
o-Xylene	ND	4.5	
Ethanol	ND	910	

Surrogate	%REC	Limits	
Dibromofluoromethane	99	78-120	
1,2-Dichloroethane-d4	106	80-120	-
Toluene-d8	96	80-120	_
Bromofluorobenzene	99	80-120	



		BTKE &	Oxygenates	
Lab #:	179661		Location:	Benner Automotive
Client:	Stellar Environmental	Solutions	Prep:	EPA 5030B
Project#:	2002-55		Analysis:	EPA 8260B
Field ID:	MW-3-24.5'		Diln Fac:	0.8929
Lab ID:	179661-012		Batch#:	102482
Matrix:	Soil		Sampled:	05/25/05
Units:	ug/Kg		Received:	05/25/05
Basis:	as received		Analyzed:	06/01/05

folksonen		
Analyte	Result	RL
tert-Butyl Alcohol (TBA)	ND	89
MTBE	ND	4.5
Isopropyl Ether (DIPE)	ND	4.5
Ethyl tert-Butyl Ether (ETBE)	ND	4.5
1,2-Dichloroethane	ND	4.5
Benzene	ND	4.5
Methyl tert-Amyl Ether (TAME)	ND	4.5
Toluene	ND	4.5
1,2-Dibromoethane	ND	4.5
Ethylbenzene	ND	4.5
m,p-Xylenes	ND	4.5
o-Xylene	ND	4.5
Ethanol	ND	890

	Surrogate	%RBC	Limite
	Dibromofluoromethane	101	78-120
	1,2-Dichloroethane-d4	110	80-120
_	Toluene-d8	96	80~120
	Bromofluorobenzene	99	80~120



		BTME & Oxygenates	
Lab #:	179661	Location:	Benner Automotive
Client:	Stellar Environmental Solu	ıtions Prep:	EPA 5030B
Project#:	2002-55	Analysis:	EPA 8260B
Field ID:	MW-3-29.5'	Diln Fac:	1.000
Lab ID:	179661-013	Batch#:	102482
Matrix:	Soil	Sampled:	05/25/05
Units:	ug/Kg	Received:	05/25/05
Basis:	as received	Analyzed:	06/01/05

tert-Butyl Alcohol (TBA)	ND	100	
MTBE	ND	5.0	
Isopropyl Ether (DIPE)	ND	5.0	
Ethyl tert-Butyl Ether (ETBE)	ND	5.0	
1,2-Dichloroethane	ND	5.0	
Benzene	ND	5.0	•
Methyl tert-Amyl Ether (TAME)	ND	5.0	_
Toluene	ND	5.0	_
1,2-Dibromoethane	ND	5.0	
Ethylbenzene	ND	5.0	
m,p-Xylenes	ND	5.0	
o-Xylene	ND	5.0	
Ethanol	ND	1,000	

Surrogate	%RBC	Limits	
Dibromofluoromethane	92	78-120	1
1,2-Dichloroethane-d4	110	80-120	_
Toluene-d8	96	80-120	_
Bromofluorobenzene	98	80-120	



	BTXE &	Oxygenates	
Lab #:	179661	Location:	Benner Automotive
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B
Project#:	2002-55	Analysis:	EPA 8260B
Type:	LCS	Basis:	as received
Lab ID:	QC295342	Diln Fac:	1.000
Matrix:	Soil	Batch#:	102431
Units:	ug/Kg	Analyzed:	05/27/05

Analyte	Spiked	Result	%REC	Limits
tert-Butyl Alcohol (TBA)	125.0	120.6	97	65-136
MTBE	25.00	27.66	111	76-128
Isopropyl Ether (DIPE)	25.00	24.14	97	75-122
Ethyl tert-Butyl Ether (ETBE)	25.00	28.89	116	75-120
1,2-Dichloroethane	25.00	24.59	98	75-120
Benzene	25.00	24.38	98	80-120
Methyl tert-Amyl Ether (TAME)	25.00	29.75	119	75-120
Toluene	25.00	24.58	98	80-120
1,2-Dibromoethane	25.00	25.60	102	80-120
Ethylbenzene	25.00	24.79	99	80-120
m,p-Xylenes	50.00	49.20	98	80-120
o-Xylene	25.00	24.37	97	79-120

Surrogate	%REC	. Limita
Dibromofluoromethane	97	78-120
1,2-Dichloroethane-d4	96	80-120
Toluene-d8	95	80-120
Bromofluorobenzene	88	80-120



	BIXE	Oxygenates	
Lab #:	179661	Location:	Benner Automotive
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B
Project#:	2002-55	Analysis:	EPA 8260B
Type:	BLANK	Basis:	as received
Lab ID:	QC295343	Diln Fac:	1.000
Matrix:	Soil	Batch#:	102431
Units:	ug/Kg	Analyzed:	05/27/05

Analyte	Result :		
tert-Butyl Alcohol (TBA)	ND	100	•
MTBE	ИD	5.0	:
Isopropyl Ether (DIPE)	ND	5.0	
Ethyl tert-Butyl Ether (ETBE)	ND	5.0	
1,2-Dichloroethane	ND	5.0	1
Benzene	ND	5.0	
Methyl tert-Amyl Ether (TAME)	ND	5.0	_
Toluene	ND	5.0	
1,2-Dibromoethane	ND	5.0	
Ethylbenzene	ND	5.0	•
m,p-Xylenes	ND	5.0	
o-Xylene	ND	5.0	1
Ethanol	ND	1,000	1

Surrogate	*REC	Limits	
Dibromofluoromethane	96	78-120	
1,2-Dichloroethane-d4	98	80-120	
Toluene-d8	96	80-120	
Bromofluorobenzene	97	80-120	



	BTXE &	Oxygenates	
Lab #:	179661	Location:	Benner Automotive
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B
Project#:	2002-55	Analysis:	EPA 8260B
Type:	BLANK	Basis:	as received
Lab ID:	QC295344	Diln Fac:	1.000
Matrix:	Soil	Batch#:	102431
Units:	ug/Kg	Analyzed:	05/27/05

Analyte	Result	RL
tert-Butyl Alcohol (TBA)	ND	100
MTBE	ND	5.0
Isopropyl Ether (DIPE)	ND	5.0
Ethyl tert-Butyl Ether (ETBE)	ND	5.0
1,2-Dichloroethane	ND	5.0
Benzene	ND	5.0
Methyl tert-Amyl Ether (TAME)	ND	5.0
Toluene	ND	5.0
1,2-Dibromoethane	ND	5.0
Ethylbenzene	ND	5.0
m,p-Xylenes	ND	5.0
o-Xylene	ND	5.0
Ethanol	ND	1,000

	Surrogate	%rec	Limits
	Dibromofluoromethane	99	78-120
_	1,2-Dichloroethane-d4	96	80-120
_	Toluene-d8	96	80-120
	Bromofluorobenzene	93	80-120



	BTXE &	Oxygenates	
Lab #:	179661		
Client:		Location:	Benner Automotive
	Stellar Environmental Solutions	Prep:	EPA 5030B
Project#:	2002-55	Analysis:	EPA 8260B
Type:	LCS	Basis:	as received
Lab ID:	QC295565	Diln Fac:	1.000
Matrix:	Soil	Batch#:	102482
Units:	ug/Kg	Analyzed:	05/31/05

Analyte	Spiked	Result	%REC	: Limits	
tert-Butyl Alcohol (TBA)	125.0	123.1 b	98	65-136	
MTBE	25.00	25.27	101	76-128	1
Isopropyl Ether (DIPE)	25.00	23.31	93	75-122	•
Ethyl tert-Butyl Ether (ETBE)	25.00	27.13	109	75-120	
1,2-Dichloroethane	25.00	25.31	101	75-120	f
Benzene	25.00	28.08	112	80-120	
Methyl tert-Amyl Ether (TAME)	25.00	28.66	115	75-120	
Toluene .	25.00	27.28	109	80-120	
1,2-Dibromoethane	25.00	26.88	108	80-120	1
Ethylbenzene	25.00	28.49	114	80-120	•
m,p-Xylenes	50.00	56.26	113	80-120	_
o-Xylene	25.00	27.57	110	79-120	1

Surrogate	%REC	Limits		
Dibromofluoromethane	90	78-120		
1,2-Dichloroethane-d4	91	80-120		
Toluene-d8	95	80-120		_
Bromofluorobenzene	87	80-120		_



	BTXE &	Oxygenates	
Lab #:	179661	Location:	Benner Automotive
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B
Project#:	2002-55	Analysis:	EPA 8260B
Type:	BLANK	Basis:	as received
Lab ID:	QC295566	Diln Fac:	1.000
Matrix:	Soil	Batch#:	102482
Units:	ug/Kg	Analyzed:	05/31/05

Analyte	Result	RL
tert-Butyl Alcohol (TBA)	N D	100
MTBE	ND	5.0
Isopropyl Ether (DIPE)	ND	5.0
Ethyl tert-Butyl Ether (ETBE)	ND	5.0
1,2-Dichloroethane	ND	5.0
Benzene	ND	5.0
Methyl tert-Amyl Ether (TAME)	ND	5.0
Toluene	ND	5.0
1,2-Dibromoethane	ND	5.0
Ethylbenzene	ND	5.0
m,p-Xylenes	ND	5.0
o-Xylene	ND	5.0
Ethanol	ND	1,000

Surrogate	%RE(: Limits
Dibromofluoromethane	92	78-120
1,2-Dichloroethane-d4	96	80-120
Toluene-d8	96	80-120
Bromofluorobenzene	94	80-120



BT	XE & Oxygenates		
Lab #: 179661 Client: Stellar Environmental Solutio Project#: 2002-55	Location: ons Prep: Analysis:	Benner Automotive EPA 5030B EPA 8260B	
Field ID: ZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZ	Batch#: Sampled: Received: Analyzed:	102482 05/25/05 05/25/05 05/31/05	1

Type: Lab ID:

MS QC295641

Diln Fac: 0.8475

Analyte	MISS RESUME	Spileed	Result	*REC	Limits
tert-Butyl Alcohol (TBA)	<11.22	105.9	100.9 b	95	51-131
MTBE	<0.7226	21.19	20.79	98	69-122
Isopropyl Ether (DIPE)	<0.9122	21.19	19.77	93	72-120
Ethyl tert-Butyl Ether (ETBE)	<0.7433	21.19	22.82	108	74-120
1,2-Dichloroethane	<0.7068	21.19	19.09	90	64-120
Benzene	<1.053	21.19	20.36	96	70-120
Methyl tert-Amyl Ether (TAME)	<0.6970	21.19	22.77	107	76-120
Toluene	4.927	21.19	22.45	83	64-120
1,2-Dibromoethane	<0.7813	21.19	19.28	91	64-120
Ethylbenzene	<1.055	21.19	20.18	95	61-120
m,p-Xylenes	<2.061	42.37	39.12	92	59-120
o-Xylene	<0.9841	21.19	18.98	90	58-120

Surrogate	*REC	
Dibromofluoromethane	96	78-120
1,2-Dichloroethane-d4	101	80-120
Toluene-d8	96	80-120
Bromofluorobenzene	92	80-120

Type: Lab ID:

MSD QC295642

Diln Fac: 0.8197

Analyte	6(p) 4 ke/s	Result	*REC	Limits	RPD	
tert-Butyl Alcohol (TBA)	102.5	98.34 b	96	51-131	1	33
MTBE	20.49	20.78	101	69-122	3	20_
Isopropyl Ether (DIPE)	20.49	19.73	96	72-120	3	2:
Ethyl tert-Butyl Ether (ETBE)	20.49	22.78	111	74-120	3	20
1,2-Dichloroethane	20.49	19.19	94	64-120	4	20
Benzene	20.49	19.50	95	70-120	î	20
Methyl tert-Amyl Ether (TAME)	20.49	22.47	110	76-120	<u> </u>	20
Toluene	20.49	21.80	82	64-120	ō	20
1,2-Dibromoethane	20.49	19.01	93	64-120	2	$\tilde{2}\tilde{d}$
Ethylbenzene	20.49	19.40	95	61-120	ī	20
m,p-Xylenes	40.98	37.13	91	59-120	2	20_
o-Xylene	20.49	18.08	88	58-120	~ 2	20

Surrogate	*REC	Limits		
Dibromofluoromethane	97	78-120		
1,2-Dichloroethane-d4	102	80-120		
Toluene-d8	97	80-120		
Bromofluorobenzene	91	80-120		


b= See narrative
RPD= Relative Percent Difference
Page 1 of 1

		-			Chain d	of Cus	tody	Rec	orc	ī		_		<u>(</u>	5-	O ?	٦٤	0	Lab Job no	
Laboratory North S Address 815 Du	BUQUE	Ανί	Ξ,	Sh	ethod of Shipment He					k	(O	ŒŰ	FREP	ci si	R	<i>7</i> 27	`			-31-05 1_ of 1_
SOUTH SAN FR (650) 266-4		CA	9408	\wedge	bill No.					/		7		-			Tequire	d	<u></u>	7
Project Owner BENNER Site Address 488 - 2 OAKLAND Project Name BENNER Project Number	2 Automo 5TH ST. CA R Autom			Pro Tel	ooler No	4-3123 4-3859	N .	 /		No. Co.	Sr. Consiners	2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/		7	/					Remarks
Field Sample Number	Location/ Depth	Date	Time	Sample Type	Type/Size of Container		servation Chemical	$\exists /$		1	2/4 2/4		//	' /	' /					
MW-I	_	5-34-05	1615	GW HzO	4 VOA'S	YES	HCL	NO		×	X	×			1					· · · · · · · · · · · · · · · · · · ·
MW-2	_		1555					$\exists I$		×	Х	メ	-				1			······································
MW-3	_	V	1545	\bigvee	\ <u></u>	V		V		×	X	×								
																				_
														-	\perp	_	_			
		ļ													+	-	-			
						+								+	+	+	-	 		
						1		+					+		 		-			
		 				+	-							-	 	-	-	 		
-																				
A																				
Relinquished by:	7 1	Date 5-31-05	Received Signat	lure		- S-31-6	Relinquishe Signature	•					Da d	e (Receive Signa	-				Date
Printed SCOTT CASSA, Company N.S.E.		Time 115	Printe	١	TIS NSlab	_ Time S א	Printed _						- Tim	e	Printe					Time
Turnaround Time: STD T	AT		отпр				Company Relinquishe						- Dat	e f	Comp Receive					- Date
Comments: GLOBAL 1		01143	જી (- 1,	Signature	·					-		Signa	Mure _		•		
FIRD POINT IDS	- MW-1,	MW	-2,1	1W-3	3		Printed _						- Tim		Printe	ed				Time

Company

Stellar Environmental Solutions

Time



	SAMPLE RECEIPT CH	ECKLIST			
Client Name: Stellar	Ref/Job No: 05-0	018		Date: <u>5.3</u>	1.05
Checked By: EK					
Matrix: Soil:Water:	Other:				<u> </u>
If Received via Shipment (If dropped of	f in person this section	does not app	ly):		
Carrier Name:		``			
Shipping Container/Cooler In Good Cor	edition?	Y		1	
Shipping Container/Cooler in Good Cor	lattorn			1	
Custody Seals Intact on Shipping Contain	ner?	Y	N	N/A	
No. of coolers:	Temperature of Cool	er:		In Range?:	ΥN
Custody Seals intact on sample containe	rs?	◈	N	N/A	
Chain of Custody present?		Ŷ	N]	
Chain of Custody Signatures & Date/Tim	ne correct?	Ŷ_	N]	
Chain of custody agrees with sample lab		<u> </u>	N	٦	
Chair of Casody agrees with Jamper too					
Samples in proper containers?		(Y)	<u> </u>		
Sample containers Intact?		(N		
Sufficient sample volume for indicated t	ests?	(Y)	N]	
All Samples received within holding tim	es?	(K)	N		
Temperature Blank present? Record Te	mp if present.	Y	(N)	Temp:	ŧ
For water samples- VOAS have zero he	adspace?	®	N	N/A	
Samples received in bottles with proper	r preservative?	- 0	N	N/A	
pH adjusted - Preservative used:	HNO3: HCl: Supplier:	H2SO4: Lot:	_ NaOH:	_ ZnOAc:	
For water samples for the analysis of to	otal recoverable metals	not digested	- pH <2?	See attac	ched sheet
					
Corrective Action Record:		<u> </u>			
Client Contacted:	Date Contacted:	· · · · · · · · · · · · · · · · · · ·	Person C	ontacted:	·
Contacted by:	Regarding:		·		
Comments:	MARKET			<u> </u>	
Corrective Action:	,				



Case Narrative

Client: Stellar Environmental Solutions Project: 488-25TH ST OAKLAND

Lab No:

05-0810

Date Received:

05/31/05

Date reported: 06/07/05

Three water samples were analyzed for gasoline by method 8015B, BTEX and fuel oxygenates by GC/MS method 8260B. All results for QC/QA samples were within acceptance limits. No errors occurred during analysis.

Erin Cunniffe

Laboratory Director



CERTIFICATE OF ANALYSIS

Lab Number:

05-0810

Client:

Stellar Env. Solutions

Project:

488-25TH ST OAKLAND

Date Reported: 06/07/2005

Gasoline Range Hydrocarbons by Method 8015B

Analyte		Method	Result	Unit Date Sampled	Date Analyzed
Sample: 05-0810-01	Client	ID: MW-1		05/31/2005	W
Gasoline Range Orga	anics	SW8020F	64	UG/L	06/03/2005
Sample: 05-0810-02	Client	ID: MW-2		05/31/2005	W
Gasoline Range Orga	anics	SW8020E	7 ND<50	UG/L	06/03/2009
Sample: 05-0810-03	Client	ID: MW-3		05/31/2005	W
Gasoline Range Orga	anics	SW8020F	r 57	UG/L	06/03/2009



ANALYSIS CERTIFICATE O F

Quality Control/Quality Assurance

Lab Number:

05-0810

Client:

Stellar Env. Solutions

Project:

488-25TH ST OAKLAND

Date Reported: 06/07/2005

Gasoline Range Hydrocarbons by Method 8015B

Analyte	Method	Repor Limit	ting Unit	Blank	MS/MSD Recovery	RPD
Gasoline Range Organics	SW8020F	50	UG/L	ND	100/104	4

ELAP Certificate NO:1753 Reviewed and Approved

Erin Cunniffe, Laboratory Director

2 of 2 Page



CERTIFICATE O F ANALYSIS

Job Number: 05-0810

Client

: Stellar Env. Solutions

Project : 488-25TH ST OAKLAND Date Sampled : 05/31/2005

Date Analyzed: 06/06/2005

Date Reported: 06/07/2005

Volatile Organics by GC/MS Method 8260B

Laboratory Number	05-0810-01	05-0810-02	05-0810-03
Client ID	MW-1	MW-2	MW-3
Matrix	W	W	W
Analyte	UG/L	UG/L	UG/L
Methyl-tert-butyl ether	ND<0.5	ND<0.5	ND<0.5
Ethyl tert-butyl ether	ND<1	ND<1	ND<1
tert-Amyl methyl ether Di-isopropyl ether (DIPE)	ND<1	ND<1	ND<1
	ND<0.5	ND<0.5	ND<0.5
tert-Butyl alcohol 1,2-Dichloroethane	ND<10	ND<10	ND<10 .
	ND<1	ND<1	ND<1
1,2-Dibromoethane	ND<1	ND<1	ND<1
Ethanol	ND<50	ND<50	ND<50
Benzene	ND<0.5	ND<0.5	ND<0.5
Toluene	ND<0.5	ND<0.5	ND<0.5
Ethylbenzene	ND<0.5	ND<0.5	ND<0.5
Xylene, Isomers m & p	ND<1	ND<1	ND<1
o-xylene SUR-Dibromofluoromethane	ND<0.5	ND<0.5	ND<0.5
SUR-Toluene-d8	97	101 85	100 96
SUR-4-Bromofluorobenzene SUR-1,2-Dichloroethane-d4	95	91	96
	101	105	107



CERTIFICATE OF ANALYSIS

Job Number: 05-0810

Client : Stellar Env. Solutions

Project : 488-25TH ST OAKLAND

Date Sampled : 05/31/2005

Date Analyzed: 06/06/2005

Date Reported: 06/07/2005

Volatile Organics by GC/MS Method 8260B Quality Control/Quality Assurance Summary

Laboratory Number	05-0810	MS/MSD	RPD	Recovery	RPD
Client ID	Blank	Recovery		Limit	Limit
Matrix	W	W			
Analyte	Results UG/L	%Recoveries			
Ethanol	ND<50			•	
Methyl-tert-butyl ether	ND<0.5				
Di-isopropyl ether (DIPE)	ND<0.5				
tert-butyl Alcohol	ND<10			•	
Ethyl tert-butyl ether	ND<1				
tert-Amyl methyl ether	ND<1				
1,2-Dichloroethane	ND<1				
1,2-Dibromoethane	ND<1				•
Benzene	ND<0.5	89/91	2	70-130	30
Ethylbenzene	ND<0.5				
Toluene	ND<0.5	88/91	3	70-130	30
o-xylene	ND<0.5				
Xylene, Isomers m & p	ND<1				
1,1-Dichloroethene	ND<0.5	116/116	0	70-130	30
Trichloroethene	ND<0.5	98/100	2	70-130	30
Chlorobenzene	ND<1	100/100	0	70-130	30
SUR-Dibromofluoromethane	98	96/96	0	85-115	30
SUR-Toluene-d8	87	89/89	0	85-115	30
SUR-4-Bromofluorobenzene	95	96/98	2	85-115	30
SUR-1,2-Dichloroethane-d4	92	101/101	0	85-115	30

Reviewed and Approved

Erin Cunniffe Laboratory Director

NON-HAZARDOUS WASTE MANIFEST

	e print or type (Form designed for use on elite (12 pitch) typewriter) NON-HAZARDOUS 1. Generator's US EPA ID No.		Manifest N. N. T. C. C. C. C.		2. Page 1			
	WASTE MANIFEST	}	N/A		Document N	[∞] N750269	of	
	3. Generator's Name and Mailing Address		SITE = SAME					
	BENNER AUTO REPAIR		•		İ			
	488 25TH STREET, OAKL	AND, CA 94612						
	4. Generator's Phone (510) 644-312	23						
	5. Transporter 1 Company Name	6.	6. US EPA ID Number		A. State Transporter's ID			
	NORTH STATE ENVIRONM	ENTAL	AL			B. Transporter 1 Phone		
	7. Transporter 2 Company Name	8.	8. US EPA ID Number		C. State Transporter's ID			
					D. Transporter 2 Phone			
	9. Designated Facility Name and Site Address	10.	US EPA ID Number		E. State Faci	lity's ID		
	D.K. ENVIRONMENTAL				<u> </u>			
	3650 EAST 26TH STREET	, LOS ANGELES,	CA 90223		F. Facility's P	hone (323) 268-56	054	
	11. WASTE DESCRIPTION			1				
	TI. WAS TE DESCRIPTION	•	V		ntainers	13. Total	ي ا	
	a			No.	Туре	Quantity	W	
	NON-HAZARDOUS WASTE,	SOLÍD	·		DM		P	
	(SOIL)			02	D 11	00600	1 *	
G	b.				·•		 	
Ĕ	~						1	
N							1	
E	c.			+ -			+	
A	_							
III							i	
<u> </u>	d.		"		- 1		 	
	\ ·							
	G. Additional Descriptions for Materials Listed Abov	/e			H. Handling C	odes for Wastes Listed Above		
	A. 350606-06		-			•		
				I				
		•				·		
		<u> </u>			*			
		ormation		• •		2		
	15. Special Handling Instructions and Additional Info					3)55		
	15. Special Handling Instructions and Additional Info		*		C.			
	15. Special Handling Instructions and Additional Info		N.		0			
	15. Special Handling Instructions and Additional Info		•	÷	Ċ			
	15. Special Handling Instructions and Additional Info		*	:	•			
	15. Special Handling Instructions and Additional Info							
			ent are tutly and accurately, described	d and are in al				
	15. Special Handling Instructions and Additional Info 16. GENERATOR'S CERTIFICATION: I hereby cert in proper condition for transport. The materials of		tent are fully and accurately, described subject to federal hazardous waster of	d and are in al				
			tent are fully and accurately described subject to federal hazardous waste re	d and are in all egulations.			Date	
			nent are fully and accurately described subject to lederal hazardous waste re	d and are in all egulations.		Month	Date Day	
	16. GENERATOR'S CERTIFICATION: I hereby cert in proper condition for transport. The materials of		0110	d and are in all equilations.				
	16. GENERATOR'S CERTIFICATION: I hereby cert in proper condition for transport. The materials of	tify that the contents of this shipn lescaped on this manifest are not	0110	d and are in all egulations.				
THE	16. GENERATOR'S CERTIFICATION: I hereby cert in proper condition for transport. The materials of Printed Typed Name 17. Transporter 1 Acknowledgement of Receipt of M. Printed/Typed Name	tify that the contents of this shipn lescribed on this manifest are not atenals	0110	d and are in all egulations.			Day 07]	
THE	16. GENERATOR'S CERTIFICATION: I hereby cert in proper condition for transport. The materials of Printed Typed Name 17. Transporter 1 Acknowledgement of Receipt of M. Printed/Typed Name	tify that the contents of this shipn lescaped on this manifest are not	Signaffre S	d and are in all egulations.		Month OC	Day 071 Date	
TRANSOR O	16. GENERATOR'S CERTIFICATION: I hereby cert in proper condition for transport. The materials of Printed Typed Name 17. Transporter 1 Acknowledgement of Receipt of M. Printed/Typed Name	tify that the contents of this shipn lescribed on this manifest are not atenals	Signaffre S	d and are in all egulations.		Month OG Month & & & K	Day 071 Date	
TRANSPORT	16. GENERATOR'S CERTIFICATION: I hereby cert in proper condition for transport. The materials of Printed Typed Name 17. Transporter 1 Acknowledgement of Receipt of M. Printed/Typed Name 3. Table 1. Acknowledgement of Receipt of M. Printed/Typed Name	tify that the contents of this shipn lescribed on this manifest are not atenals	Signaffre S	d and are in all egulations.		Month OG Month & & & K	Day Date	
TRANSOR O	16. GENERATOR'S CERTIFICATION: I hereby cert in proper condition for transport. The materials of Printed Typed Name 17. Transporter 1 Acknowledgement of Receipt of M. Printed/Typed Name 19. Transporter 2 Acknowledgement of Receipt of M.	tify that the contents of this shipn lescribed on this manifest are not atenals	Signature Signature	d and are in all equilations.		Month OC Month & & &	Day Date Day Date	
TRANSPORT	16. GENERATOR'S CERTIFICATION: I hereby cert in proper condition for transport. The materials of Printed Typed Name 17. Transporter 1 Acknowledgement of Receipt of M. Printed/Typed Name 19. Transporter 2 Acknowledgement of Receipt of M. Printed/Typed Name	tify that the contents of this shipn lescribed on this manifest are not atenals	Signature Signature	d and are in all equilations.		Month OC Month & & &	Day Date Day Date	
TRANSPORTUR	16. GENERATOR'S CERTIFICATION: I hereby cert in proper condition for transport. The materials of Printed Typed Name 17. Transporter 1 Acknowledgement of Receipt of M. Printed/Typed Name 19. Transporter 2 Acknowledgement of Receipt of M. Printed/Typed Name	tify that the contents of this shipn lescribed on this manifest are not atenals	Signature Signature	d and are in all egulations.		Month OC Month & & &	Day Date Day Date	
TRANSPORTER FACO	16. GENERATOR'S CERTIFICATION: I hereby cert in proper condition for transport. The materials of Printed Typed Name 17. Transporter 1 Acknowledgement of Receipt of Management of Receipt of Manage	tify that the contents of this shipn lescribed on this manifest are not laterials	Signature Signature Signature Signature	- Ca		Month OC Month & & &	Day Date Day Date	
TRANSPORTER FACO	16. GENERATOR'S CERTIFICATION: I hereby cert in proper condition for transport. The materials of Printed Typed Name 17. Transporter 1 Acknowledgement of Receipt of M. Printed/Typed Name 19. Transporter 2 Acknowledgement of Receipt of M. Printed/Typed Name	tify that the contents of this shipn lescribed on this manifest are not laterials	Signature Signature Signature Signature	- Ca		Month OC Month & & &	Day Date Day Date	
TRANSPORTER FACO	16. GENERATOR'S CERTIFICATION: I hereby cert in proper condition for transport. The materials of Printed Typed Name 17. Transporter 1 Acknowledgement of Receipt of Management of Receipt of Manage	tify that the contents of this shipn lescribed on this manifest are not laterials	Signature Signature Signature Signature	- Ca		Month OC Month Month	Day Date Day Date	