

①



Standing between
main & siding
Looking westward
approx. 50' east
of Ave "A".
Loader leaning
against train.

②

Standing between
passing track
& Fence looking
westward.
Loader leaning
against train on
south side of
track.



(3)



Standing on South Side of track approx 10' off Ave "A" Looking westward. Loader leaning against train.

Standing in the middle of passing track looking westward. Note position of motor.



(4)

5



Standing on
South Side of
right of way

6

Standing approx.
50' east of Ave
"A" between main
+ passing
track, Loader
has been removed
From Fouling main
track - now
sitting directly
on top of
passing track.



⑨



Standing on the east edge of Avenue "A" looking westward. Note wheel marks on xing + siding misalignment on passing track.

Standing in middle of passing track looking westward - approx 6 cars from head end of train. Cars 2+3 derailed.



⑧

9



Standing in the middle of Adjacent Street, South Side of main track. Note 2nd Container is sitting on 2nd car - articulated car # TTAX 76832. truck #3 derailed.

Standing in the middle of passing track looking westward - approx 7 poles to Ave "A". Note damage on APC cars

10



11



Standing beside
lead locomotive
looking westward.
Note damage on
both locomotives
passing track
severely
misaligned.

12

Standing between
passing track
& main track
at head end of
train. Note
damage to lead
locomotive 6225.



13



Standing between
passing + main
track. picture
taken of rear
end of lead
Locomotive,
Axel # L-6.

Standing between
passing track
+ main track
at rear of 2nd
Locomotive.

note: damage
of R-2 bearing
cap



14

