Detterman, Mark, Env. Health

From: Daniel Villanueva [dvillanueva@advgeoenv.com]
Sent: Wednesday. December 23. 2015 2:07 PM

To: Detterman, Mark, Env. Health

Subject: Well Construction Details and Locations Table **Attachments:** Table 1 SVC Well Construction Details.pdf

Categories: Red Category

Mark,

Please see the requested table as required by phone meeting on 23 December 2015.

Let me know if you have any questions.

Regards,

Daniel Villanueva

Project Geologist

Advanced GeoEnvironmental, Inc.

Environmental • Industrial Hygiene • Geotechnical • Contracting

Phone: 800-511-9300 Fax: 888-445-8786

dvillanueva@advgeoenv.com

www.advgeoenv.com

This email/fax message is for the sole use of the intended recipient(s) and may contain confidential and privileged information. Any unauthorized review, use, disclosure or distribution of this email/fax is prohibited. If you are not the intended recipient, please contact the sender by email/fax and destroy all paper and electronic copies of the original message.

From: Detterman, Mark, Env. Health [mailto:Mark.Detterman@acgov.org]

Sent: Wednesday, December 23, 2015 12:28 PM

To: Daniel Villanueva Subject: Email Followup

Daniel

I've not received an email / PDF yet and wanted to check to make sure it had or had not been sent.

Mark Detterman

Senior Hazardous Materials Specialist, PG, CEG

Alameda County Environmental Health

1131 Harbor Bay Parkway

Alameda, CA 94502 Direct: 510.567.6876 Fax: 510.337.9335

Email: mark.detterman@acgov.org

PDF copies of case files can be downloaded at:

http://www.acgov.org/aceh/lop/ust.htm

TABLE 1

WELL CONSTRUCTION DETAILS

Swiss Valley Cleaners

1395 MacArthur Boulevard, San Leandro, California

Well ID	Installation Date	Borehole Diameter (inch)	Total Drilled Depth (feet bsg)	Total Well Depth (feet bsg)	Casing Elevation (ft MSL)	Well Casing Material	Slot Size (inch)	Screen Interval (feet)	Filter Pack Interval (feet bsg)	Bentonite Interval (feet bsg)	Grout Interval (feet bsg)	Well Location
VW-1	08-21-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	1395 MacArthur (Swiss Valley Cleaners)
VW-2	08-21-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	Front of Facility
VW-3	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	1395 MacArthur (Swiss Valley Cleaners)
VW-4	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	Front of Facility
VW-5	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	1369 MacArthur (Former Jazzercise)
VW-6	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	1369 MacArthur (Former Jazzercise)
VW-7	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	1369 MacArthur (Former Jazzercise)
VW-8	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	1369 MacArthur (Former Jazzercise)
VW-9	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	Rear of Facility
VW-10	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	Rear of Facility
VW-11	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	Rear of Facility
VW-12	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	Front of Facility
VW-13	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	Front of Facility
VW-14	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	Rear of Facility
VW-15	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	Rear of Facility
VW-16	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	Rear of Facility
VW-17	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	Front of Facility
VW-18	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	1395 MacArthur (Swiss Valley Cleaners)
VW-19	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	Rear of Facility
VW-20	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	1395 MacArthur (Swiss Valley Cleaners)
VW-21	08-22-2014	7	7	7	NM	PVC	0.020	2 to 7	2 to 7	0.5 to 2	none	1395 MacArthur (Swiss Valley Cleaners)

Notes:

bsg: below surface grade NM: Not measured