| | UNDERGROUND STORAGE TANK (UST) SITE - UNAUTHORIZED RELEASE / CONTAMINATION REPORT | | |
|--|--|--|--|
| | MERGENCY HAS STATE OFFICE OF EMERGENCY SERVICES YES AND REPORT BEEN FILED? DYES XNO | FOR LOCAL AGENCY USE ONLY THEREBY CERTIFY THAT LAM A DESIGNATED GOVE | ERNMENT EMPLOYEE AND THAT I HAVE |
| RI | PORT DATE CASE # | REPORTED THIS INFORMATION TO LOCAL OFFICIAL THE HEALTH AND SAFETY CODE. | LS PURSUANT TO SECTION 25180,7 OF |
| 5, | /30/2013 | SIGNED |) DATE |
| | NAME OF INDIVIDUAL FILING REPORT PHONE David Hinds (025) | SIGNATURE | 1/ 5/2V12 |
| REPORTED BY | David Hinds (925) | 989-8223 COL | -/ X- X-UIS |
| | ☐ LOCAL AGENCY ☐ REGIONAL BOARD ☐ OWNER/OPERATOR ☐ OTHER ADDRESS | Petromart Retail Group | |
| | 587 Ygnacio Valley Road | Walnut Creek | Ca 94596 STATE ZIP |
| RESPONSIBLE PARTY | NAME PLUNKNOW | CONTACT PERSON | PHONE () |
| SPON | ADDRESS | | 1\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ |
| R. | STREET | CITY | STATE ZIP |
| Z | FACILITY NAME (IF APPLICABLE) College Ave Shell | OPERATOR Petromart Retail Group | PHONE (925) 979-0560 |
| SITE LOCATION | ADDRESS | | |
| | 6039 College Ave | Oakland Alameda county | 94618 zip |
| မြ | CROSS STREET Claremont | | |
| <u> </u> | LOCAL AGENCY AGENCY NAME | POP | PHONE |
| (MPLEMENTING AGENCIES | Oakland Fire Prevention Bureau | | (510) 238-7253 |
| | REGIONAL BOARD | | PHONE |
| | BBAQMD | | l() |
| SUBSTANCES INVOLVED | (1) NAME | QUANTI | ITY LOST (GALLONS) |
| | Gasoline | | |
| | (2) | | F-1.,, |
| | DATE DISCOVERED HOW DISCOVERED Trank T | M | Unknovyn |
| OVERY/ABATEMENT | Unknown | Test Xstank Removel ory Control Subsurface Munitoring | Nulsance Conditions Other |
| /ABAT | DATE DISCHARGE BEGAN | METHOD USED TO STOP DISCHARGE (CHECK | |
| VERY | ∑ I ∪nknown | Remove Contents Close Tank Repair Tank Change Proced | lure |
| DISCO | HAS DISCHARGE BEEN STOPPED? Yes No IF YES, DATE | Replace Tank Other | |
| | SOURCE OF DISCHARGE UNKnown CAUSE(S) | Repair Piping Which nown | |
| SOURCE/ CAUSE | ☐ Tank ☐ Piping ☐ Dispenser ☐ Delivery Problem ☐ Spill ☐ Submeraible Turbine Pump (STP) ☐ Other ☐ Installati | ☐ Overfill ☐ Physical/Mechanical Damage ☐ Colion Problem ☐ Unknown ☐ Other | rrosion |
| CASE | CHECK ONE ONLY Mundelermined | | |
| CURRENT STATUS | CHECK ONE ONLY | pen - Verification Monitoring | |
| | ☐ Open - Assessment & Interim Remedial Action ☐ Op | nen - verinisation Monitoring nen - Inactive osed No Further Action Required | ŀ |
| NOT- | CHECK APPROPRIATE ACTION(S) Human health exposure control? | | |
| AL AC | | | |
| REMEDIAL ACTION | ☐ No Action Required (NAR) ☐ Excavate & Treat (ET) ☐ Excavate & Dispose (ED) ☐ Free Product Removal (FPR) | ☐ Treatment at Hookup (TH) ☐ Replace Supply (RS) | ☐ Other |
| | This is being filled out at the request of the Fire Dept. The tanks were tested and found to be tight numerous times and were | | |
| COMMENTS | continuously electronically monitored without issue. There indication or evidence of any missing product or leak of any years the tanks have been in this station. | was no inventory shortage under our o | wnership. We have no |