# ALAMEDA COUNTY HEALTH CARE SERVICES

**AGENCY** 



DAVID J. KEARS, Agency Director

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577

Alameda, CA 94502-657 (510) 567-6700 FAX (510) 337-9335

July 21, 2004

Mr. Jeffrey Hunt Plywood Lumber & Sales 1618 28<sup>th</sup> St. Oakland, CA 94608

Dear Mr. Hunt:

Subject:

Fuel Leak Site Case Closure For Plywood & Lumber Sales, 4050 Horton Street, Emeryville,

California, 94608; Case No. RO0000328; Underground Storage Tank Cleanup Fund No.

002394

This letter transmits the enclosed underground storage tank (UST) case closure letter in accordance with Chapter 6.75 (Article 4, Section 25299.37[h]). The State Water Resources Control Board adopted this letter on February 20, 1997. As of March 1, 1997, the Alameda County Environmental Health (ACEH) is required to use this case closure letter for all UST leak sites. We are also transmitting to you the enclosed case closure summary. These documents confirm the completion of the investigation and cleanup of the reported release at the subject site. The subject fuel leak case is closed.

#### SITE INVESTIGATION AND CLEANUP SUMMARY

Please be advised that the following conditions exist at the site:

Residual soil and groundwater pollution remains in place at your site. Up to 1,100 ppb TPHG, 600 ppb TPHD, 60 ppb benzene remain in groundwater at this site. Up to 0.27 ppm benzene and 0.0022 ppm 1,2-dichloroethane remain in soils at this site.

If you have any questions, please call Roseanna Garcia - La Grille at (510) 777-2149. Thank you.

Sincerely,

Donna L. Drogos, P.E.

LOP and Toxics Program Manager

#### Enclosures.

Remedial Action Completion Certificate

2 Case Closure Summary

CC:

Ms. Betty Graham (w/enc) SF- Regional Water Quality Control Board 1515 Clay Street, Suite 1400 Oakland, CA 94612

Mr. Ignacio Dayrit (w/enc) City of Emeryville, Planning Department 1333 Park Avenue Emeryville, CA 94608 Mr. Toru Okamoto (w/enc)
State Water Resources Control Board
UST Cleanup Fund
P.O. Box 944212
Sacramento, CA 94244-2120

R. Garica – La Grille (w/orig enc), D. Drogos (w/enc)

**AGENCY** 



DAVID J. KEARS, Agency Director

ENVIRONMENTAL HEALTH SERVICES

ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

July 21, 2004

Mr. Jeffrey Hunt Plywood Lumber & Sales 1618 28<sup>th</sup> St. Oakland, CA 94608

Dear Mr. Hunt:

Subject:

Fuel Leak Site Case Closure For Plywood & Lumber Sales, 4050 Horton Street, Emeryville,

California, 94608; Case No. RO0000328; Underground Storage Tank Cleanup Fund No.

002394

This letter confirms the completion of a site investigation and remedial action for the underground storage tank(s) formerly located at the above-described location. Thank you for your cooperation throughout this investigation. Your willingness and promptness in responding to our inquiries concerning the former underground storage tank(s) are greatly appreciated.

Based on information in the above-referenced file and with the provision that the information provided to this agency was accurate and representative of site conditions, this agency finds that the site investigation and corrective action carried out at your underground storage tank(s) site is in compliance with the requirements of subdivisions (a) and (b) of Section 25299.37 of the Health and Safety Code and with corrective action regulations adopted pursuant to Section 25299.77 of the Health and Safety Code and that no further action related to the petroleum release(s) at the site is required.

This notice is issued pursuant to subdivision (h) of Section 25299.37 of the Health and Safety Code.

Please contact our office if you have any questions regarding this matter.

Sincerely,

Mee Ling Tung

Director

Alameda County Environmental Health

## CASE CLOSURE SUMMARY LEAKING UNDERGROUND FUEL STORAGE TANK - LOCAL OVERSIGHT PROGRAM

MAY - 5 2004

#### I. AGENCY INFORMATION

BG

Date: May 3, 2004

Agency Name: Alameda County Environmental Health	Address: 1131 Harbor Bay Parkway
City/State/Zip: Alameda, CA 94502-6577	Phone: (510) 567-6762
Responsible Staff Person: Eva Chu	Title: Hazardous Materials Specialist

#### II. CASE INFORMATION

Alamada Coming

	<del></del>			
Site Facility Name: Plywood and	Lumber Sales	JUH 2 2 2024		
Site Facility Address: 4050 Horto	on Street, Emeryville, CA 94608	Branch Co.		
RB Case No.:	Local Case No.: 4255	LOP Case No.: RO0000328		
URF Filing Date: 01/14/1992 SWEEPS No.:		APN: 049-0617-016-02		
Responsible Parties	Addresses	Phone Numbers		
Pływood Lumber & Sales c/o Jeffrey Hunt	1618 28th Street Oakland, CA 94608	510/547-7257		

Tank I.D. No	Size in Gallons	Contents	Closed In Place/Removed?	Date
11	1,000	Gasoline	Removed	12/10/1990
	Piping		Removed	12/10/1990

#### III. RELEASE AND SITE CHARACTERIZATION INFORMATION

Site characterization complete? Yes No Date Approved By Oversight Agency:				
Monitoring wells installed? No Number: N/A Proper screened interval				
Highest GW Depth Below Ground Surface: 8.38' based on MW-18, well nearest to former UST Lowest Depth: 10.09' (MW-18) Flow Direction: westerly				

Summary of Production Weils in Vicinity No.	armking water wells identified within 2 miles of the site
Are dripking water wells affected? No	Aguifer Name   Fast Bay Plain
Is surface water affected? No	Nearest SW Name San Francisco Bay is 2 miles west of site
Off-Site Beneric aid se Impects (Addresses Lo	eations) None
Reports on file! Yes	Where are reports filed? Mameda County Environmental Health

TREATMENT AND DISPOSAL OF A	AFFECTED MATERIAL
-----------------------------	-------------------

L			
Material	Amount (Include Units)	Action (Treatment or Disposal w/Destination)	Date
Tank	1-1000 gal UST Erickson Inc, 225 Parr Blvd, Richmond, CA		12/10/1990
Piping			12/10/1990
Free Product	1000 gal	Allied Oil, Alviso, CA	12/10/1990
Soil 500 cy		B & J Landfill in Vacaville, CA	Jun-Jul 1994
Groundwater	Not reported		

## MAXIMUM DOCUMENTED CONTAMINANT CONCENTRATIONSCBEFORE AND AFTER CLEANUP (Please see Attachments 1-3 for additional information on contaminant locations and concentrations)

	Soil (	ppm)	Water (ppb)	
Contaminant	Before <sup>1</sup>	After <sup>2</sup>	Before <sup>3</sup>	A fter⁴
TPH (Gas)	530	<1	200,000	1,100
TPH (Diesel)	57	<1	19,000	600
Oil & Grease	177	<50	6,400	NA
Benzene	5 3	.27	11,000	60
Toluene	5 1	<.005	10,000	19
Ethyl Benzene	5.5	.008	<.5	19
Xylene	17	.011	4,800	34
Heavy Metals: Lead/Chromium*	761/30.5*	5.9/76*	680/122*	<3/56,000*
MTBE (if not analyzed, explain below)	NA NA	<.005	NA	<5.0
Other (8240/8270)	.0022**	.0022**	***	***

#### Notes:

Site History and Description of Corrective Actions

**UST Removal** Im December 10, 1990, a 1000-gailon UST was removed. Thee product was noted to be floating on groundwater in the tank pit at 6.5 feet bgs. A soil sample was collected from the cap, thank fringe (6 feet bgs) at each end of the tank (sample Zac1 and Zac2). A grab groundwater samples was also collected. Each sample was analyzed for TPHg. TPHd. TOG. B.H.X. HVOCs, and 5 metals (Cd. Cr. Pb. Nr. Zn.). Groundwater was pumped from the tank pit prior to backfithing.

Up to 68ppm IPHg, 44ppm IPHd, 177ppm IOO, 2.2, 1.6, 0.45, and 1 10ppm BTEX, respectively, was detected in the soil samples. Groundwater contained 2003,00pph IPHg, 19,000pph 1PHd, and 11,000pph benzene. Trace levers or 1.2 DCA (10022ppm) was also found in soil.

<sup>\*</sup> Cadmium, nickel, and zinc also detected at 1.3, 46.6, and 431ppm, respectively, in soil samples. No groundwater data for Cd, Ni, or Zn. The SF-RWQCB is providing chromium/lead regulatory oversight for the plume originating at 1401 Park Street, which appears to be the source of these contaminants. Case closure from ACEH applies only to the petroleum hydrocarbon plumes.

<sup>\*\* 1,2-</sup>Dichloroethane.

<sup>\*\*\*</sup> See attached tables for analytical results of chlorinated compounds detected in groundwater. These compounds are from an off site source.

continued.....

Soil and Water Investigation – Between June 1992 and June 1993. 15 test borings were drilled at the site to depths ranging from 9.5 to 15.5 feet bgs. Soil samples were collected at various depths. Up to 530ppm TPHg, 5.3ppm benzene, and 761ppm lead and 421 ppm zinc were detected in the 6 feet bgs soil samples.

Petroleum hydrocarbon and lead-contaminated soil was excavated from the site in June 1994. Approximately 130 tons of lead-contaminated soil and 600 tons of hydrocarbon-contaminated soil were excavated. Bottom and sidewall confirmation soil samples (#7, #9 through 21 and #26-27) were obtained at 6 to 7 feet bgs. One soil sample was collected at 9 feet bgs (#28) after additional excavation. A maximum of 0.27ppm benzene remain in soil (beneath the sidewalk/street) at 7 to 9 feet bgs. Toluene, ethyl-benzene and xylenes were below laboratory detection limits.

In January 1996, a soil boring (B-16) was advanced within 15 feet and west of the former UST. Soil at 8 feet bgs contained 0.06ppm benzene. A grab groundwater sample from the boring contained 1,100 ppb TPHg, 60ppb benzene, 190ppb TCE and 56,000ppb Cr. It appears that HVOCs and Cr in groundwater is associated with the Electro-Coatings plume (located at 1401 Park Street), where the RWQCB is the lead oversight agency

In October 2003, additional soil borings (SS#1 through SS#4) were advanced to 15 feet bgs at the site. Boring SS#4 did not have sufficient groundwater for a grab groundwater sample to be collected. Soil, water, and soil vapor samples were collected from SS#1 through SS#3 to demonstrate that hexavalent Cr was migrating to the subject site from an offsite source, and that residual benzene in soil and groundwater did not pose a risk to human health. Soil analytical results revealed up to 79ppm TPHg and 0.057ppm benzene in soil from boring SS#1 at 5 feet bgs. These constituents were not detected in the 10 feet bgs sample. Grab groundwater samples from the three boreholes all contained hexavalent Cr at concentrations ranging from 6,600 to 14,000ppb, in addition to TCE and PCE.

All soil vapor constituents detected, with the exception of 114 ug/m³ benzene, were below the RWWQB's Environmental Screening Level.

Monitoring Well Installation – No groundwater monitoring wells were installed at the site for the petroleum hydrocarbon release. However, Electro-Plating Coating installed two wells, MW-18 and MW-18A, for the investigation of HVOC and Cr contamination. These wells are within 40 feet of the former UST. Groundwater from these wells was not been analyzed for TPH but was analyzed for VOCs. No BTEX constituents were detected in the groundwater samples.

Site Geology and Hydrogeology – The site is underlain within 2 feet of fill. Beneath the fill and extending to the maximum depth explored, were stiff silty clays and medium dense clayey sands. The clayey sands contained varying amounts of clay with occasional gravel. The soils exhibited very low permeability. Groundwater tends to flow to the west (based on groundwater flow direction obtained from the adjacent Electro-Coatings facility.

#### IV. CLOSURE

Does completed corrective action protect existing l	peneficial uses per the Regional Board B	asin Plan? Yes No
Does completed corrective action protect potential	beneficial uses per the Regional Board I	Basin Plan? Yes No
Does corrective action protect public health for cu specific determinations concerning public health ris appear that the release would present a risk to hum	k. However, based upon the information	available in our files to date, it does not
Site Management Requirements None		
Should corrective action be reviewed if land use ch	ianges, 70	
Mon toring Wells Decommissioned NA	Number Decommissioned NA	Number Retained NA
List Enforcement Actions Taken None		
List Enforcement Actions Resembled None		

#### V. ADDITIONAL COMMENTS, DATA, ETC.

#### Considerations and/or Variances:

Residual benzene vapor concentrations in soil (114 ug/m3) exceed the RWQCB's ESL. The consultant RT Hicks determined that when compared with the Johnson and Ettinger model for soil vapor intrusion to an indoor residential scenario, then human health risk did not exceed 1.6E-06.

The SF-RWQCB is the lead agency providing oversight for cleanup of hexavalent chromium and HVOCs in groundwater.

#### Conclusion:

Alameda County Environmental Health staff believes that the levels of residual contamination do not pose a significant threat to water resources, public health and safety, and the environment. ACEH staff recommend closure for this site.

#### VI. LOCAL AGENCY REPRESENTATIVE DATA

Prepared by: Eva Chu	Title: Hazardous Materials Specialist
Signature:	Date: 5/3/04
Approved by: Donna L. Drogos, P.E.	Title: Supervising Hazardous Materials Specialist
Signature: Land Alas &	Date: 05/03/04

This closure approval is based upon the available information and with the provision that the information provided to this agency was accurate and representative of site conditions.

#### VII. REGIONAL BOARD NOTIFICATION


Regional Board Staff Name: Betty Graham	Title: Associate Water Resources Control Engineer
RB Response: Concur, based solely upon information contained in this case closure summary.	Date Submitted to RB:
Signature: Self J	Date: 6/21/04


#### Attachments:


- 1. Site Vicinity Map
- 2. Site Plan with Sampling Locations, 1992 to 1996 (2pp)
- 3. Soil Analytical Data, 1990 to 1992 (2pp)
- 4 Grab Groundwater Analytical Results from Tank Pit, 1990 (2pp)
- 5 Confirmation So I Analytical Results from 1994 Excavation
- Groundwater Analytical Results from Soil Boring B-16 and Moni oring Well
- Site Plan with Soi. Vapor Sample Locations
- 8 Soil, Groundwater, and Air Analytical Results from 2003 Investigation (5pp)
- 9 Piezometrie Surface Contour Map
- 10 Soit Boring Logs (9pp)

Pay for the care discipline COSECTOSER FEFTER and the planted by a filter gapous price intenticular affects

PLYWOOD LUMBER AND SALES 4050 HORTON STREET EMERYVILLE, CA










Table 1
Hydrocarbon Concentrations in Soil

Boring	Depth (feet)	Oil and Grease (mg/kg) <sup>3</sup>	TEH <sup>1</sup> (mg/kg)	TVH <sup>2</sup> (mg/kg)	Benzene (ug/kg)4	Toluene (ug/kg)	Ethyl- Benzene (ug/kg)	Xylene (ug/kg)
Zac 16	6.0	177	<10	26	2200	1600	310	540
Zac 2	6.0	<30	44	68	130	240	450	1100
1 1 1	*6.0 8.0 10.5	୍ୟ <b>େ</b> ଡ <50 <50	*30 <1 <1	.150 2 1	5300 43 30	5100 15 24	5500 7 <5	17000 » 15 9
2 2	4.0 6.0	<50 <50	3 34	13 170 =	-~ 250° <400	29 420	180 1300	220 1500
3 3	6.0 7.5	170 . <50	57. <1	210 1	570 <5	<400 6	2100 <5	950 5
4 4	4.0 6.0	<50 <50	<1 <1	2 2	14 14	5 <b>&lt;</b> 5	<5 <5	9 6
5 5	6.0 8.0	<50 <50	4 <1	160 <1	<200 <5	490 11	630 <5	<200 <5
7 7	4.0 6.0	<50 <50	7 <1	7 1	120 270	68 28	4 <5	270 12
8 8	6.5 9.5	5 	<1 	<1 <1	<5 	<5 	<5 	<5 ~~
9 9	6 9		<1 	<1 <1	<5 	<5 	<5 ··	<5 
10	6			<1	<5	<5	<5	<5
11	6			≫ <b>5</b> 30				
12 12	3 6		70 apr	<1 <1	 <5	 <5	<del></del> <5	<del></del> <5
13 13	3 6			<1 <1	<del></del> <5	 <5	 <5	<del></del> <5
15 15	3 6			<1 <1	<del></del> <5	<del></del> <5	<b></b> <5	 <5

TEH = Toral extractable hydrocarbons, as diesel

TVH = T. al volatile hydrocarbons, as gasoline

mg/kg = milligrams per kilogram

ug/kg = micrograms per kilogram

Test not requested

Samples obtained by Zaccor, Inc. following tank removal

Table 2 Heavy Metal Concentrations in Soil

Boring	Depth (feet)	Cadmium (mg/kg) <sup>1</sup>	Chromium (total) (mg/kg)	Lead (mg/kg)	Nickel (mg/kg)	Zinc (mg/kg)
Zac 1	6.0	0.34	28.1	61	46.6	179
Zac 2	6.0	<0.25	30.5	6.6	27.9	29.1
1	6.0	1.3	33.3		44.7	(421)
2	4.0	0.32	36.8	5	35.0	37
3 🔎	6.0	<0.25	33.1	5	30.6	171
4	4.0	<0.25	36.6	4	32.3	45
5	6.0	<0.25	36.0	3	28.5	30

Table 3 Volatile Organic Chemical Concentrations in Soil

Boring	Depth (feet)	1,2 DCA <sup>2</sup> (ug/kg) <sup>3</sup>	EPA 8010 Chemicals (mg/kg)
Zac 1	6.0	<50	$ND^4$
Zac 2	6.0	2.2	ND
1	6.0	· <250	ND
2	4.0	<10	ND
3	6.0	<250	ND
4	4.0	<5	ND
5	6.0	<25	ND

mg/kg = milligrams per kilogram

<sup>1,2-</sup>dichloroethane

micrograms per kilograms not detected above the reporting limits

### ANALYSIS DATA SHEET - TOTAL PETROLEUM HYDROCARBONS (GASOLINE WITH BTEX) ANAMETRIX, INC. - (408) 432-8192

Anametrix W.O.: 9012085
Matrix : WATER Date Sampled: 12/10/90

Project Number : Z0121090M1 Date Released : 12/27/90

	Reporting Limit	Sample I.D.# #3	Sample I.D.# 12B1217B		
COMPOUNDS	' (ug/L)	-03	BLANK	 	
Benzene	0.5	11000	ND		
Toluene	0.5	10000	ND		
Ethylbenzene	0.5	ND	ND		
Total Xylenes	0.5	4800	ND		
TPH as Gasoline	50	<b>\$000</b> 00	ИD		
% Surrogate Reco	overy	123%	97%		
Instrument I.1	D	HP12	HP12		
Date Analyzed		12/17/90	12/17/90		
RLMF		2500	1		

ND'- Not detected at or above the practical quantitation limit for the method.

TPHg - Total Petroleum Hydrocarbons as gasoline is determined by GCFID using EPA Method 5030.

BTEX - Benzene, Toluene, Ethylbenzene, and Total Xylenes are determined by modified EPA 8020.

RIMF - Reporting Limit Multiplication Factor.

Anametrix control limits for surrogate recovery are 50-150%.

All testing procedures follow California Department of Health Services (Cal-DHS) approved methods.

#### ORGANIC ANALYSIS DATA SHEET - EPA METHOD 601/8010 ANAMETRIX, INC. (408) 432-8192

ample I.D. : Z0121090M1 #3 Anametrix I.D. : 9012085-03

Analyst pate sampled: 12/10/90 pate analyzed: 12/17/90 Supervisor

Date released : 12/27/90 pilution Instrument ID : HP24

CAS #	Compound Name	Reporting Limit (ug/1)	Amount Found (ug/1)
74-87-3 74-83-9 75-71-8 75-01-4 75-00-3 75-09-2 75-69-4 75-34-3 156-59-2 156-60-5 67-66-3 76-13-1 107-06-2 71-55-6 56-23-5 75-27-4 78-87-5 10061-02-6 79-01-6 124-48-1 79-00-5 10061-01-5	* Chloromethane * Bromomethane * Dichlorodifluoromethane * Vinyl Chloride * Chloroethane * Methylene Chloride * Trichlorofluoromethane * 1,1-Dichloroethene * 1,1-Dichloroethane * Cis-1,2-Dichloroethene * Trans-1,2-Dichloroethene * Chloroform # Trichlorotrifluoroethane * 1,2-Dichloroethane * 1,1-Trichloroethane * 1,1-Trichloroethane * 1,2-Dichloromethane * Trans-1,3-Dichloropropene * Trans-1,3-Dichloropropene * Trichloroethene * Dibromochloromethane * 1,1,2-Trichloroethane * 1,1,2-Trichloroethane * 1,1,2-Trichloroethane * cis-1,3-Dichloropropene	100 50 100 50 50 50 50 50 50 50 50 50 50 50 50	(ug/1)  ND
110-75-8 75-25-2 127-18-4	* 2-Chloroethylvinylether * Bromoform * Tetrachloroethene	100 50 50	ND ND
79-34-5 108-90-7 95-50-1 541-73-1	* 1,1,2,2-Tetrachloroethane * Chlorobenzene * 1,2-Dichlorobenzene * 1,3-Dichlorobenzene	50 50 50 100 100	ND ND ND ND ND
106-46-7   	* 1,4-Dichlorobenzene   % Surrogate Recovery	100 51-136%	ND

ND: Not detected at or above the practical quantitation limit for the method.

A compound added by Anametrix, Inc.

A 601/8010 approved compound (Federal Register, 10/26/84).

Table 1.

Petroleum Hydrocarbon Contaminant Concentrations in Soil

1	Petroleum Hydrocarbon Contaminant Concentrations in Soil										
		,					Ethyl	Total	Total	STLC	TCLP
Sample	Depth	O&G	TEH	_ TVH ઼¹	Benzene	Toluene	Benzene	Xylenes	Lead	Lead	Lead
	(feet)	(mg/kg)	(mg/kg)	(mg/kg)	(μg/kg)	(µg/kg)	(μg/kg)	(μg/kg)	(mg/kg)	(μg/l)	(µg/l)
Excavation Sar	<u>nples</u>										
7	6	<50	<1	<1	<5	·<5	<5	<5	<5	-	-
9*	7	<50	12	49	31	27	150	180	<5	-	-
10	7	<50	<1	<1	<5	<5	<5	<5	<5	-	-
11	6	<50	<1	<1	<5	<5	<5	<5	•	-	-
12	6	<50	<1	<1	<5	<5	<5	<5	-	~	-
13	7	<50	<1	<1	<5	<5	<5	<5	-	-	•
14	6	<50	<1	<1	<5	<5	<5	<5	-	-	-
15	6	<50	<1	<1	<5	<5	<5	<5	-	-	-
16	6	<50	<1	<1	<5	<5	<5	<5	-	-	-
· 17	6	<50	<1	<1	<5	<5	<5	<5	-	•	-
18	7.5	<50	<1	<1	85	<5	8	<5		-	-
19	7	<50	<1	<1	<5	<5	<5	11	•	-	-
20 ·	6	<50	<1	<1	<5	<5	<5	<5	-	-	-
21	6	<50	<1	<1	<5	<5	<5	<5	-	-	•
26	7.5	<50	<1	<1	<5	<5	<5	<5	-	-	-
27	7.5	<50	<1	<1	<5	<5	<5	<5	-	-	•
28	9	50	<1	<1	44	<5	<5	<5	-	-	-
Stockpile Sam	<u>ples</u>										
Composite 1		_	-	17	64	39	140	230	390	22,000	1,100
Composite 2		-	-	<1	<5	<5	<5	<5	24	-	-
5	6	-	-	-	-	-	-	-	<5	-	-
6	6	-	-	-	-	-	-	-	63	-	-
8	6	-	-	-	-	-	-	-	<5	-	-

O & G = Oil & Grease

TEH = Total Extractable Hydrocarbons, as kerosene

TVH = Total Volatile Hydrocarbons

mg/kg = Milligrams per kilogram

μg/kg = Micrograms per kilogram

Composite 1 = Composite of Samples 1, 2, 3 and 4

Composite 2 = Composite of Samples 22, 23, 24 and 25

\* = Subsequently removed by supplemental excavation

STLC = Soluble Threshold Limit Concentration

TCLP = Toxicity Characteristic Leaching Potential

851.001

Table 2
Chemical Concentrations in Groundwater

Sample (050) 2080 Hor	<u>Date</u> ton Stree	(mg/l)	(ug/l)	TP <b>H-g</b> (ug/l)	Benzene (ug/l)	Toluene (ug/l)	Ethyl- benzene (ug/l)				1,1-DCE (ug/l)	cis- 1,2-DCE <u>(ug/l)</u>	trans- 1,2-DCE <u>(ug/l)</u>	1,1,1-TCA (ug/l)	Acetone (ug/l)	2- Butanone (ug/l)	Dissolved** Chromium (ug/l)	Dissolved** Lead (ug/l)
B-16	Jan-96	<b>&lt;</b> 5	600*	1100	60	19	19	34	8.5	190	8.1	23	14	7	15	8.3	56,000	⊲ ■
Electro-C	Coatings I	nvestigat	<u>ion</u>									-						
MW-17	Dec-95	NA	NA	NA	NA	NA	NA	NA	13	360	38	24	<10	<10	NA	NA	160,000	NA
MW-18	Dec-95	NA	NA	ΝA	NA	NA	NA	NA	<10	280	<10	18	<10	<10	NA	NA	20,000	NA

#### Notes.

O&G = Oil and grease, SMWW 17 5520 EF

TPH-d = Total petroleum hydrocarbons as diesel, EPA 8015 modified

TPH-g = Total petroleum hydrocarbons as gasoline, EPA 8015 modified

PCE = Tetrachloroethene

TCE = Trichloroethene

I,I-DCE = 1,1-Dichloroethene

cis-1,2-DCE = cis-1,2-Dichloroethene

trans-1,2-DCE = trans-1,2-Dichloroethene

1,1,1-TCA = 1,1,1-Trichloroethane


ug/I = micrograms per liter

NA = Not analyzed

<0.5 = Analyte not detected above the stated laboratory reporting limit

<sup>\* =</sup> Sample exhibits fuel pattern which does not resemble standard

<sup>\*\* =</sup> Sample was filtered by the laboratory prior to analysis




	Soil - ug/Kg		RL	ESL
SS#1-5ft	Gasoline C7-C12 (mg/Kg)	<i>7</i> 9	1.9	100
	Benzene	57	23	44
	Toluene	62	23	2900
	Ethylbenzene	890	250	3300
	m,p-xylenes	1200	23	1500
	o-Xylene	43	23	1500
	Isoproplybenzene	210	23	
	Propylbenzene	810	23	
	1, 3, 5-Trimethylbenzene	2400	250	
	1, 2, 4-Trimethylbenzene	7900	250	not available
	sec-Butylbenzene	100	23	<b>{</b>
	para-Isopropyl Toluene	51	23	
	n-Butylbenzene	450	23	
	Naphthalene	1700	250	4200
	Hexavalent Chromium	ND	50	1800
	MTBE	ND	23	23
SS#1-10ft	Gasoline C7-C12 (mg/Kg)	ND	1	100
	Methylene Chloride	58	19	<b>7</b> 7
	Hexavalent Chromium	2800	1200	1800
	MTBE	ND	4.6	23
	Benzene	ND	4.6	44
	Toluene	ND	4.6	2900
	Ethylbenzene	ND	4.6	3300
	m, p-xylenes	ND	4.6	1500
	o -xylene	ND	4.6	
	Naphthalene	ND	4.6	4200
SS#1-15f+	Gasoline C7-C12 (mg/Kg)	ND	1	100
	Methylene Chloride	170	20	77
	Hexavalent Chromium	6500	240	1800
	MTBE	ND	5	23
	Benzene	ND	5	44 44
	Toluene	ND	5	2900
	Ethylbenzene	ND	5	3300
	m, p-xylenes	ND	5	
	o -xylene	ND	5	1500
	Naphthalene	ND	5	4200
	- mpression	~ 12	2	


CC#5 EG	Cocolina C7 C12 (ma/Va)	ND	1	100
SS#2-5ft	Gasoline C7-C12 (mg/Kg)	63	19	77
	Methylene Chloride	ND	50	1800
	Hexavalent Chromium MTBE	ND	4.6	23
			4.6	44 44
	Benzene	ND		
	Toluene	ND	4.6	2900
	Ethylbenzene	ND	4.6	3300
	m, p-xylenes	ND	4.6	1500
	o -xylene	ND	4.6	4200
	Naphthalene	ND	4.6	4200
SS#2-10ft	Gasoline C7-C12 (mg/Kg)	ND	1	100
	Methylene Chloride	59	19	77
	Hexavalent Chromium	900	50	1800
	MTBE	ND	4.8	23
	Benzene	ND	4.8	44
	Toluene	ND	4.8	2900
	Ethylbenzene	ND	4.8	3300
	m, p-xylenes	ND	4.8	
	o -xylene	ND	4.8	1500
	Naphthalene	ND	4.8	4200
	* An partition of the same of	112	2.0	*****
SS#2-15ft	Gasoline C7-C12 (mg/Kg)	ND	1	100
	Methylene Chloride	<i>7</i> 5	20	77
	Hexavalent Chromium	2800	160	1804
	MTBE	ND	4.9	23
	Benzene	ND	4.9	44
	Toluene	ND	4.9	2900
	Ethylbenzene	ND	4.9	3300
	m, p-xylenes	ND	4.9	
	o -xylene	ND	4.9	1500
	Naphthalene	ND	4.9	4200
	<b></b>			
SS#3-5ft	Gasoline C7-C12 (mg/Kg)	ND	1	100
	Acetone	24	19	235
	Methylene Chloride	<b>74</b>	19	<i>77</i>
	Hexavalent Chromium	ND	0.05	1804
	MTBE	ND	4.8	23
	Benzene	ND	4.8	44
	Toluene	ND	4.8	2900
	Ethylbenzene	ND	4.8	3300
	m, p-xylenes	ND	4.8	1500
	o -xylene	ND	48	1500
	Naphthalene	ND	4.8	4200
CC#3 100	Carolina C7 C12 (m ~ /V -)	N <sup>1</sup> D	7	100
SS#3-10ft	Gasoline C7-C12 (mg/Kg)	ND	1	
	Methylene Chloride	89	18	77
	Hexavalent Chromium	4100	120	1804


MTBE	ND	4.5	23
Benzene	ND	4.5	44
Toluene	ND	4.5	2900
Ethylbenzene	ND	4.5	3300
m, p-xylenes	ND	4.5	1500
o -xylene	ND	4.5	1500
Naphthalene	ND	4.5	4200

Sample	Sample Analyte		RL	ESL
	Water	ug/L		
SS1	Gasoline C7-C12	110	50	100
<i>S</i> S1	trans-1, 2-Dichloroethene	6.5	5	10
SS1	cis-1, 2-Dichloropropane	<b>31</b>	, <b>5</b>	6
SS1	Trichloroethene	98	<b>5</b>	***: <b>5</b>
SS1	Tetrachloroethene	7.7	5	5.
<i>S</i> S1	Hexavalent Chromium	9900	240	1
SS1	MTBE	ND	5	5
SS1	Benzene	ND	5	1
SS1	Toluene	ND	5	4
SS1	Ethylbenzene	ND	5	3
SS1	m, p-xylenes	ND	5	1.3
SS1	o -xylene	ND	5	1.3
SS1	Naphthalene	ND	5	2.1
SS2	Gasoline C7-C12	ND	50	100
SS2	trans-1, 2-Dichloroethene	6	5	10
SS2	cis-1, 2-Dichleropropane	26	5	6
SS2	Trichloroethene	68	5	5
SS2	Tetrachloroethene	7.2	5	5
SS2	Hexavalent Chromium	14000	240	11
SS2	MTBE	ND	5	5
SS2	Benzene	ND	5	1
SS2	Toluene	ND	5	4
SS2	Ethylbenzene	ND	5	3
SS2	m, p-xylenes	ND	5	1.3
SS2	o -xylene	ND	5	1.3
SS2	Naphthalene	ND	5	2.1
SS3	trans-1, 2-Dichloroethene	8.8	5	10
SS3	cis-1, 2-Dichloroethene	32	5	6
SS3	Trichlomethene	36	5	5
<i>S</i> S3	Hexavalent Chromium	6600	240	11
SS3	MTBE	ND	5	5
SS3	Benzene	ND	5	1
SS3	Toluene	ND	5	4
SS3	Ethylbenzene	ND	5	3
SS3	m, p-xylenes	ND	5	1.0
SS3	o -xylene	ND	5	1.3
S53	Naphthalene	ND	5	2 1




Sample	Analyte	Result	ESL
	Air ug/m <sup>3</sup>		
#1	Dichlorodifluoromethane	2.5	
	Chloromethane	1.04	1352
	m, p-Xylene	1 <i>7</i> 7	20857
	o-xylene	66.7	2.0037
	Toluene	115	83429
	Benzene	19.8	84
	Ethylbenzene	110	2212
	Methyl-t-butyl ether	27.9	9359
#2	Dichlorodifluoromethane	2.5	
	Chloromethane	1.04	1352
	m, p-Xylene	221	20857
	o-xylene	50.8	20657
	Toluene	82	83429
	Benzene	114	84
	Ethylbenzene	86.6	2212
	Methyl-t-butyl ether	9.17	9359
#3	Dichlorodifluoromethane	2.5	
	m, p-Xylene	398	20857
	o-xylene	57.4	20657
	Toluene	73.2	83429
	Ethylbenzene	265	2212
	Methyl-t-butyl ether	8.8	9359
#4	Chloromethane	2.4	1352
	m, p-Xylene	287	00057
	o-xylene	132	20857
	Toluene	460	83429
	Ethylbenzene	309	2212





## LOG OF TEST BORING 2



Subsurface Consultants JOB NUMBER


4050 HORTON STREET - EMERYVILLE, CA

JOB NUMBER DATE APPROVED 851,001 6/24/92 UC

2

#### LOG OF TEST BORING 8" Hollow Stem Auger BLOWS PER FOOT 6/4/92 DATE DRILLED PPM LABORATORY TESTS ELEVATION ASPHALTIC CONCRETE - 4" thick LIGHT BROWN CLAYEY SAND (SC) medium dense, moist (fill) strong hydrocarbon odor BLACK SILTY CLAY (CL) 15 250 stiff, moist **GRAY SILTY CLAY (CL)** 1500 10 stiff, moist MOTTLED GRAY SILTY CLAY (CL) stiff, moist 15 20 slight hydrocarbon odor MOTTLED BROWN GRAY SANDY SILTY 10 15 20 CLAY (CL) stiff, moist GROUNDWATER NOT ENCOUNTERED **DURING DRILLING**





851.001


Subsurface Consultants JOS NUMBER

4050 HORTON STREET - EMERYVILLE, CA


DATE 6/24/92 PLATE

APPROVED

Me








Subsurface Consultants JOB NUMBER

4050 HORTON STREET - EMERYVILLE, CA

JOB NUMBER 851.001 DATE 6/24/92 APPROVED H

4



Subsurface Consultants JOB NUMBER


4050 HORTON STREET - EMERYVILLE, CA

851.001

DATE APPROVED 6/24/92

#### LOG OF TEST BORING 8" Hollow Stem Auger DRY DENSITY (PCF) 6/18.93 BLOWS PER FOOT DATE DRILLED OVM (PPM) LABORATORY TESTS ELEVATION CONCRETE SLAB - 5" thick 9 LIGHT BROWN CLAYEY SAND (SM) medium dense, moist (fill) BLACK SILTY CLAY (CL) 0 stiff, moist GRAY SILTY CLAY (CL) stiff, moist MOTTLED BROWN AND GRAY SILTY CLAY (CL) 12 stiff, moist 10 20 Boring backfilled with cement grout **GROUNDWATER NOT ENCOUNTERED** 140 pounds **DURING DRILLING** HAMMER WEIGHT: 30 inches HAMMER DROP:

## LOG OF TEST BORING 9




Subsurface Consultants JOB NUMBER


4050 HORTON STREET - EMERYVILLE, CA


 DOB NUMBER
 DATE
 APPROVED

 851.001
 6/21/93
 HC

6







Subsurface Consultants

4050 HORTON STREET - EMERYVILLE, CA

DURING DRILLING


Boring backfilled with cement grout

GROUNDWATER NOT ENCOUNTERED


 JOB NUMBER
 DATE
 APPROVE

 851.001
 6/21/93
 M

8







Subsurface Consultants JOB NUMBER

4050 HORTON STREET - EMERYVILLE, CA

 JOB NUMBER
 DATE
 APPROVED

 851.001
 6/21/93
 HC

9

	Logger:	Michelle Hunter	Client:	Well ID:	
	Driller:		PALS		
Drilling	Method:		Project Name:		
	tart Date:		UST Investigation		
	End Date:		Location:	SS-2	
Notes:			4050 Horton Street		
			Emeryville, CA		
			Alameda County		
Depth	Geopr	robe			
(feet)		Description	Lithology	Comments	
0.0		Ashalt Cap, Base Coarse			
0.0		Ashalt Cap, Bass States			
1.0					
1.0		sand, gravel, brown, gray			
		Sand, graver, brown, gray			
2.0				<del> </del>	
	· ·	<del>                                     </del>		stiff plastic	
3.0				Juli plastic	
		<del>  </del>			
4.0		der de de mare blera			
		clay, dark grey, blue		lighter gray with	
5.0				brown	
	·· · · · · · · · · · · · · · · · · · ·				
6.0					
7.0					
8.0					
		clay, sand, gravel, brown, gr	ey ey		
9.0					
	:				
10.0	, ,				
11.0					
		gravel, sand, clay, rust, brow	un l		
12.0		graver, sarid, clay, rust, brow	711		
13.0	**************************************			wet	
-					
14.0				rust streaks	
		clay, sand, gray, brown			
15.0					
10,0					
16.0					
<del></del>		R.T. Hicks Consultants, Ltd		Die 4	
	901 Rio	Grande NW Albuquerque, NM 87104	Plywood and Lumber Sales	Plate 4	
		05-266-5004 Fax: 505-266-0745	11000	Oot-b 2002	
	5/0		UST Investigation	October 2003	

Logger:		Michelle Hunter	Client:	Well ID:
Driller:		Precision Sampling	PALS	
Drilling Method:		Geoprobe	Project Name:	
Start Date:			UST Investigation	
End Date:			Location:	SS-3
Notes:			4050 Horton Street	4
			Emeryville, CA	
			Alameda County	
	1 2 3 h			
Depth	Geoprobe			
(feet)		Description	Lithology	Comments
0.0		Ashalt Cap, Base Coarse		
1.0		clay, gravel, sand, grey,brown		streaks of rust, blue, black
20				Dido, black
3 0				
40		clay, sand, gravel, grey,brown		
5.0				
6 0				
7.0		clay, grey		streaks of white sand
8.0		clay, sand, brown		streaks of white sand, gravel
9.0		clay, brown		lenses
10.0		olay, Morri		
Authoritecture (1995) (	**************************************	cks Consultants, Ltd  NW Albuquerque, NM 87104	Plywood and Lumber Sales	Plate 5
505-266-5004 Fax: 505-266-0745			UST Investigation	October 2003

Logger:		Michelle Hunter	Client:	Well ID:
Driller:		Precision Sampling	PALS	
Drilling M		Ge <b>oprobe</b>	Project Name:	
	t Date:		UST Investigation	
Enc	I Date:		Location:	SS-4
Notes:			4050 Horton Street	
			Emeryville, CA	
			Alameda County	
	The state of the s			
Depth	Geoprobe	_	i Manada ma	Comments
(feet)		Description	Lithology	Oomnenes
0 0		Ashalt Cap, Base Coarse		
10				
		clay, <b>gravel, sand, rust</b>		1
20	ļ			some gray-blue clay at 3 feet
30		clay, black		
40				
50				
		clay, black, blue		
60				
70		clay,sand, grey		streaks of white sand
80				
		clay, gravel, gray, brown		streaks of white sand, gravel lenses
90		clay, sand, gravel, brown		rust colored streaks
100		Jidy, Junta, States, Midth		
C. Philippine and the Control of the				
R.T. Hicks Consulta <b>nts, Ltd</b>			Plywood and Lumber Sai	es Plate 6
901		Albuque <b>rque, NM 87104</b> Fax: 50 <b>5-266-0745</b>	UST Investigation	October 2003

#### Well Log Legend

The state of the s

Sand



Clay



Sand/Gravel



Clay, Gravel, Sand



Cobble



Clay, Sand, Gravel



Asphalt Cap/Base Coarse

	Logger:	Miche Hunter	Client:	Well ID:
Driller: Precision Sampling Drilling Method: Geoprobe Start Date:		Precision Sampling	PALS	
			Project Name:	
		*** · · · · · · · · · · · · · · · · · ·	UST Investigation	
	nd Date:		Location:	SS-1
Notes:			4050 Horton Street	
			Emeryville, CA	<del></del>
			Alameda County	
Depth	Geoprobe			
(feet)	Ocopiose	Description	Lithology	Comments
0.0		Ashalt Cap, Base Coarse		
		, , , , , , , , , , , , , , , , , , , ,		
1.0				
		sand, gravel, brown, gray		
2.0				
3.0				
3.0				
4.0				stiff plastic clay
4.0				Jim plastic day
5.0		clay, dark grey, blue		hydrocarbon smell
0.0				
6.0				white pebbles
		clay, sand, brown		
7.0		Glay, Sailu, Blowii		
		<del></del>		
8.0		clay,very little gravel,		no hydrocarbon smell
9.0		brown, grey		no nyurocarbon sinen
0.0				
10.0				
11.0				
40.0				
12.0				wet
13.0		<del> </del>		
14.0		clay, sand, gravel, brown,		
		gray		
15.0				
16.0				
,0.0				
1	1		A	
R.T. Hicks Consultants, Ltd			Plywood and Lumber Sales	Plate 3
90		V Albuquerque, NM 87104 4 Fax: 505-266-0745	UST Investigation	October 2003
on the second of	<i>3</i> 03-206-300 <sup>,</sup>	4 rax: 303-200-0743	OST mivestigation	JULUDEI 2003

50: L 3021NG 200 55-