

ENVIRONMENTAL RESOLUTIONS, INC.

JAN 1 1 2002

TRANSMITTAL

TO: Ms. Eva Chu

Alameda County Health Care Services Agency Department of Environmental Health

1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

DATE: January 7, 2002

PROJECT NUMBER: 223503T5

SUBJECT: Tosco Service Station 1156,

4276 MacArthur Boulevard,

Oakland, California.

FROM: Paul D. Blank TITLE: Project Manager

WE ARE SENDING YOU:

COPIES	DATED	DESCRIPTION	
1	January 4, 2001	Supplemental Evalu Site Conceptual Mo	ation of Soil and Groundwater and del
THESE AI	RE TRANSMITTED a	s checked below:	
[] For r	eview and comment	[] Approved as submitted	[] Resubmit copies for approval
[X] As r	equested	[] Approved as noted	[] Submit copies for distribution
[] For approval		[] Return for corrections	[] Return corrected prints
[X] For	your files	[] For distribution to regul	atory agencies
			, a subsidiary of Phillips Petroleum rding one copy of the above-referenced

document directly to your office. Please call me at (415) 382-5988 with any questions or comments.

Faul D. Blank, Project Manager

cc: Mr. Dave DeWitt, Phillips 66 Company

Mr. James Yoo, Alameda County Public Works Agency, Water Resources Section

Ms. Jolanta Uchman, California Regional Water Quality Control Board, San Francisco Bay Region

ERI Project File 223503T5



ENVIRONMENTAL RESOLUTIONS, INC.

January 4, 2002 ERI 223503.R02

JAN 1 1 2002

Mr. Dave DeWitt Phillips 66 Company 2000 Crow Canyon Place, Suite 400 San Ramon, California 94583

Subject:

Supplemental Evaluation of Soil and Groundwater and Site Conceptual Model,

Tosco Service Station 1156, 4276 MacArthur Boulevard, Oakland, California.

Mr. DeWitt:

At the request of Tosco Corporation (Tosco), a subsidiary of Phillips Petroleum Company, Environmental Resolutions, Inc. (ERI) performed an environmental investigation at the subject site, and prepared a site conceptual model (SCM). ERI performed the work in response to a letter from the Alameda County Health Care Services Agency (the County), dated March 8, 2000 (Attachment A). The purpose of the work was to evaluate the lateral extent of dissolved hydrocarbons previously detected in groundwater beneath the site, and to evaluate the potential sources of, receptors to, and transport mechanisms for petroleum hydrocarbons in the subsurface.

BACKGROUND

Site Description

The site is located on the southeastern corner of MacArthur Boulevard and High Street in Oakland, California, as shown on the Site Vicinity Map (Plate 1). Properties in the vicinity of the site are occupied by commercial and residential developments.

The locations of the former underground storage tanks (USTs), associated piping and dispensers, existing USTs and dispensers, existing groundwater monitoring wells, and other site features are shown on the Generalized Site Plan (Plate 2). The site is currently operated as a gasoline service station.

Previous Environmental Work

Tosco initiated environmental assessment activities at the site in 1998. Previous environmental work completed at the site includes:

- Compliance soil sampling during removal of two 10,000-gallon, single-walled gasoline USTs, one 280-gallon single walled steel used-oil UST, and associated product lines and dispensers (ERI, 1998);
- Excavation and disposal of approximately 1,350 tons of soil and backfill from the new and former gasoline and used-oil UST cavities and product trenches (ERI, 1998);

- Installation of four on-site groundwater monitoring wells (MW1 through MW4) (ERI, 1999);
 and.
- Ongoing quarterly groundwater monitoring and sampling.

The results of previous environmental investigations indicate that petroleum hydrocarbons are present in soil and groundwater beneath the site.

PRESENT INVESTIGATION

Scope of Work

ERI previously submitted a Work Plan for Supplemental Evaluation of Soil and Groundwater (Work Plan), dated August 28, 2000, to the County. The County approved the Work Plan in a letter dated September 18, 2000 (Attachment A). As proposed in the Work Plan, ERI drilled three soil borings (MW5 through MW7) and installed groundwater monitoring wells in the respective borings. ERI obtained a well installation permit from the Alameda County Public Works Agency and an encroachment permit from the City of Oakland Engineering Services Department prior to performing the field work. Copies of the permits are provided in Attachment B. ERI performed field work in general accordance with ERI's Work Plan, and in accordance with a site-specific Health and Safety Plan that was kept on site during field operations, and ERI's field protocol (Attachment C).

In addition to the work proposed in the Work Plan, and at the request of Tosco, ERI installed a tank pit "well within the backfill of the UST cavity. No permit was required for the work. The purpose of tank pit well installation was to facilitate future groundwater extraction from the UST cavity as an interimate remedial action.

ERI also conducted an underground utility survey and a groundwater receptor survey. The purpose of these tasks was to identify potential preferred migration pathways and sensitive receptors near the site.

UST Cavity Well Installation

On July 17, 2001, ERI installed tank pit well TP1 by driving a 4-inch diameter open-bottom slotted casing by hand into the pea gravel backfill of the UST cavity, while concurrently extracting the pea gravel from inside the casing with vacuum provided by a truck-mounted vacuum pump. The casing was advanced until native soil was encountered at approximately 13 feet below ground surface (bgs). A 3-inch diameter closed-bottom slotted casing was installed within the 4-inch casing. The location of well TP1 is shown on Plate 2.

Soil Borings

On August 29, 2001, ERI's geologist observed Woodward Drilling Company, Inc. (Woodward) of Rio Vista, California, drill three 8-inch diameter soil borings (MW5 through MW7). Soil samples were collected from the borings during drilling at approximately 5-foot intervals. Borings MW5 through MW7 were advanced to approximately 25 feet bgs.

ERI's geologist identified the soil samples collected from the soil boring using visual and manual methods, and classified the samples according to the Unified Soil Classification System (USCS) (Attachment D). Descriptions of the materials encountered are presented on the Boring Logs (Attachment D).

Soil cuttings generated during drilling activities were temporarily stockpiled on site and covered with plastic sheeting pending appropriate disposal by Tosco. ERI collected one composite soil sample (four brass sleeves) from the stockpile for laboratory analysis to be used in evaluating disposal options.

Monitoring Well Construction, Surveying, Development, and Sampling

On August 29, 2001, ERI observed Woodward construct groundwater monitoring wells MW5 through MW7 in borings MW5 through MW7, respectively. The locations of the wells are shown on Plate 2. The well construction details are shown on the Boring Logs (Attachment D).

In September 2001, Morrow Surveying of West Sacramento, California, a California-licensed land surveyor, surveyed the new well locations relative to a permanent datum and top of casing (TOC) elevations relative to mean sea level.

On October 3, 2001, Gettler-Ryan, Inc. (GRI), under direct contract to Tosco, developed newly-installed groundwater monitoring wells MW5 through MW7, and monitored and sampled wells MW1 through MW7. GRI's field procedures, field notes, and laboratory analysis reports are included in their Fourth Quarter Event of October 3 and 5, 2001 – Groundwater Monitoring & Sampling Report, dated November 12, 2001. Cumulative groundwater monitoring and sampling data from that report are provided in Attachment E. Tosco and GRI were responsible for proper storage and disposal of waste water generated during well development and purging.

Analytical Methods - Soil Samples

ERI submitted soil samples collected from borings MW5 through MW7 for laboratory analysis to Sequoia Analytical Laboratories, Inc. (Sequoia) a California state-certified laboratory, under Chain-of-Custody protocol. Select soil samples were analyzed for total petroleum hydrocarbons as gasoline (TPHg) using EPA Method 8015M; and benzene, toluene, ethylbenzene, total xylenes (BTEX) and methyl tertiary butyl ether (MTBE) using EPA Method 8020. The laboratory analysis reports and Chain-of-Custody records are provided in Attachment F.

ERI submitted the composite soil sample collected from the soil stockpile generated during drilling activities to Sequoia, under Chain-of-Custody protocol, for laboratory analysis of TPHg, BTEX, and MTBE using the EPA Methods referenced above, and total lead using EPA Method 6010A.

Soil Stockpile Disposal

Approximately 1.45 tons of soil cuttings were generated during drilling activities at the site. Manley & Sons Trucking, Inc. of Sacramento, California, under direct contract to Tosco, transported the soil to the Forward, Inc. landfill in Manteca, California, for disposal. The soil disposal confirmation is provided in Attachment H.

Groundwater Extraction from UST Cavity

Subsequent to the installation of TP1, Tosco initiated regular purging of groundwater from the backfill of the UST cavity. Onyx Industrial Services (Onyx), under direct contract to Tosco, purges the UST cavity by inserting a hose into TP1 and applying a vacuum provided by a 5,000-gallon capacity vacuum truck. Between July 31 and December 28, 2001, Onyx extracted approximately 41,000 gallons of hydrocarbon-impacted groundwater from the UST cavity and approximately 600 gallons of hydrocarbon-impacted groundwater from monitoring well MW1. Onyx transports the extracted groundwater to the Tosco Refinery in Rodeo, California, for treatment and disposal.

Underground Utility Survey

To locate buried utility lines, ERI mapped the locations and identities of utility vaults on the site and in the adjacent streets and sidewalks. In addition, ERI obtained maps of utility locations, and information regarding utility depth, trend, and backfill type of underground sanitary sewer, storm sewer, telephone, water, gas, and electric lines from the City, Pacific Bell, Pacific Gas & Electric, and the East Bay Municipal Utilities District for the intersection of MacArthur Boulevard and High Street in Oakland, California.

Groundwater Receptor Survey

ERI performed a groundwater receptor survey, which included a search of well records held by the California Department of Water Resources (DWR) and a search of the GeoTracker® database, to identify wells within a one-half mile radius of the site. The GeoTracker® database is maintained by the California State Water Resources Control Board.

On October 5, 2001, ERI performed a field receptor survey with in a one-half mile radius of the site. ERI's representative visually surveyed all properties within the one-half mile radius for the existence of wells, surface water-bodies, and potentially sensitive environmental habitats. In addition, ERI attempted to find evidence of the existence of the eight wells identified during the searches of the GeoTracker® and DWR databases.

RESULTS OF INVESTIGATION

The results of laboratory analyses of soil samples collected from borings MW5 through MW7 are summarized in Table 1. The results of laboratory analyses of groundwater samples collected from newly-installed wells MW5 through MW7 are included in the cumulative groundwater monitoring and sampling data provided in Attachment E.

ERI's underground utility survey revealed buried sanitary sewer, storm sewer, telephone, water, gas, and electric lines beneath and in the vicinity of the site. The deepest underground utility appears to be the storm sewer line located beneath MacArthur Boulevard at approximately 4-6 feet bgs. The locations, typical depths, and typical backfill materials of the utility lines are shown on Plate 3.

SITE CONCEPTUAL MODEL

Summary of Site Conditions

Site Geology and Hydrogeology

The site is underlain by Recent alluvial deposits (CDMG, 1973). Borings logged during the installation of groundwater monitoring wells MW1 through MW7 indicate that the site and vicinity are underlain by mixtures of sand, silt, and clay to a depth of 31.5 feet bgs, the maximum depth explored. The boring logs for wells MW1 through MW7 are provided in Attachment D. Cross sections A-A' (Plate 4) and B-B' (Plate 5) depict ERI's interpretation of the soil stratigraphy. ERI interprets a gradual change from mostly clay to mostly silty clay at approximately 10 to 25 feet bgs. The locations of cross sections A-A' and B-B' are shown on Plate 2.

The saturated zone encountered beneath and in the vicinity of the site consists of an unconfined water table aquifer that extends to the maximum depth explored (approximately 31.5 feet bgs). The depth to groundwater measurements from the monitoring wells range seasonally between approximately 2 and 10 feet bgs. Cumulative groundwater monitoring data are provided in Attachment E. The groundwater flow direction has been consistently toward the west with the hydraulic gradient ranging from 0.05 to 0.1 (the average hydraulic gradient over 10 groundwater monitoring events is 0.07). The direction of historical groundwater flow is shown on the Groundwater Flow Direction Rose Diagram (Plate 6).

Distribution of Residual Hydrocarbons

Cumulative results of laboratory analyses and locations of soil samples collected during environmental assessment activities are provided in Table 1 and Attachment G. It appears that the impacted soil is concentrated in the vicinity of the former used-oil and former gasoline USTs, although residual hydrocarbons were also detected beneath product lines and dispensers. Based on the data, residual hydrocarbons in soil are delineated to the west and southwest by B2 (well MW2) and MW5. Residual hydrocarbons are not well defined toward the north, east, or southeast; however, these directions are upgradient and crossgradient, and generally uphill from the site. It is unlikely that residual hydrocarbons migrated aggressively in these directions.

Distribution of Dissolved Hydrocarbons in Groundwater

Based on the cumulative groundwater monitoring and sampling data, dissolved hydrocarbons are present in groundwater beneath and downgradient of the site. Cumulative results of laboratory analyses of groundwater samples collected from groundwater monitoring wells MW1 through MW7 are provided in Attachment E. Isoconcentration maps showing the concentrations of dissolved gasoline hydrocarbons (quantified as TPHg) and MTBE detected in groundwater samples collected during the fourth quarter 2001 groundwater monitoring and sampling event are shown on Plates 7 and 8, respectively. Dissolved hydrocarbons in groundwater beneath and in the vicinity of the site remain undelineated toward the west and south. Graphs showing hydrocarbon concentrations versus time and depth-to-water data for monitoring wells MW1 through MW4 are presented in Hydrographs 1 through 4, respectively.

5

Source Identification and Transport Mechanisms

Source Identification

The distribution of petroleum hydrocarbons in soil and groundwater indicates that the former used-oil UST and the former gasoline UST system (including dispensers and piping) were the probable primary sources of hydrocarbons in the subsurface. These primary sources have been removed. Hydrographs 1 through 4 indicate that dissolved hydrocarbon concentrations in the on-site wells have remained relatively stable since well installation in 1999. It does not appear that there has been a release from the new gasoline UST system; therefore, ERI concludes that no primary source of hydrocarbons remains at the site.

The residual hydrocarbons in soil described above are identified as the secondary source of dissolved hydrocarbons in groundwater.

Transport Mechanisms

ERI identified two transport mechanisms for migration of petroleum hydrocarbons in the subsurface: dissolution of residual hydrocarbons in vadose sediment and unsaturated flow, and advective transport of dissolved hydrocarbons. Residual hydrocarbons in vadose-zone soil can dissolve into soil moisture in the vadose sediment, which can subsequently flow to the water table. Dissolution can also occur in phreatic groundwater when the water table is sufficiently high. Groundwater containing dissolved hydrocarbons will migrate in response to the natural hydraulic gradient within the water-table aquifer.

Based on cumulative groundwater monitoring data and the results of ERI's underground utility survey, it is ERI's opinion that it is possible that utility trenches located in the vicinity of the site provide potential preferential pathways for groundwater flow. The data indicate groundwater may intersect utility trenches during periods when the water table is high. However, the groundwater surface is typically lower then the reported depth of buried utilities, and therefore the potential for groundwater flow through utility trenches is low.

Groundwater Receptor Survey

The GeoTracker® database search revealed four public water supply wells, owned by the East Bay Regional Park District (Park District), within the search radius. ERI contacted the Park District to verify the existence, location, depth, and uses of the four wells revealed during the database search. The representatives from the Park District have no knowledge or records of any wells located in this area and indicated that the wells may belong to the East Bay Municipal Utility District (EBMUD). ERI contacted the EBMUD; however, EBMUD has no knowledge or records of any wells located in this area.

The DWR database revealed four water supply wells, belonging to Mills College, within the search radius. ERI contacted Mills College to verify the existence, location, depth, and uses of the four wells. A representative from Mills College indicated that all wells associated with Mills College had been destroyed approximately ten years ago and that Mills College is now connected to a municipal water supply. The DWR search also revealed a well located at 3397 Arkansas Street, approximately 880 feet outside of the search radius.

6

No wells, surface water-bodies, or potentially sensitive environmental habitats were identified during ERI's field receptor survey. In an attempt to locate the nearest potential groundwater receptor, ERI approached the residence at the 3397 Arkansas Street address, even though it is located approximately 880 feet outside the search radius, and received no response. The results of ERI's groundwater receptor survey are provided in Attachment I.

Plume Stability

ERI evaluates the stability of the dissolved hydrocarbon plume based on concentration trends and plume size. Hydrographs 1 through 4 depict relatively stable concentrations of TPHg and MTBE in groundwater in the on-site wells. Concentrations fluctuate through time, perhaps due to groundwater level or other factors, but remain generally within the same order-of-magnitude. The dissolved concentration trends do not indicate an ongoing release or subsequent releases of hydrocarbons to the subsurface since well installation. In terms of concentration, ERI considers the dissolved hydrocarbon plume to be stable.

Presently, insufficient data exist to evaluate whether the plume is stable in terms of size. Dissolved hydrocarbons in groundwater beneath the site remain undefined toward the west and south, as shown on Plates 7 and 8.

Summary of Remedial Efforts

Environmental remediation efforts at the site have included:

- Removal of approximately 1,350 tons of hydrocarbon-impacted soil and backfill from the UST cavity and product line trenches (ERI, 1998), including remedial excavation of impacted soil from the vicinity of the former used-oil UST. Based on the results of laboratory analyses of soil samples collected from the excavated soil, approximately 51 pounds of hydrocarbons were removed from the subsurface.
- Extraction of approximately 36,000 gallons of hydrocarbon-impacted groundwater from the UST cavity.

DOCUMENT DISTRIBUTION

ERI recommends copies of this report be forwarded to:

Ms. Eva Chu Alameda County Health Care Services Agency Department of Environmental Health Services 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Ms. Jolanta Uchman California Region Water Quality Control Board San Francisco Bay Region 1515 Clay Street, Suite 1400 Oakland, California 94612

Please call Mr. Paul D. Blank, ERI's project manager for the site, at (415) 382-5988 with any questions regarding this report.

Sincerely, Environmental Resolutions, Inc.

Bily Bellud

Robert A. Saur Senior Staff Geologist

John B. Bobbitt R.G. 4313

Attachments: References

Table 1: Results of Laboratory Analysis of Soil Samples

Plate 1: Site Vicinity Map
Plate 2: Generalized Site Plan
Plate 3: Underground Utility Map

Plate 4: Cross-Section A-A'
Plate 5: Cross-Section B-B'

Plate 6: Groundwater Flow Direction Rose Diagram

Plate 7: TPHg Concentrations in Groundwater (October 3, 2001)
Plate 8: MTBE Concentrations in Groundwater (October 3, 2001)

Hydrograph 1: Well MW1: Concentrations and Depth-to-Water vs. Time Hydrograph 2: Well MW2: Concentrations and Depth-to-Water vs. Time Hydrograph 3: Well MW3: Concentrations and Depth-to-Water vs. Time Hydrograph 4: Well MW4: Concentrations and Depth-to-Water vs. Time

Attachment A: Regulatory Correspondence

Attachment B: Permits

Attachment C: Field Protocol

Attachment D: Unified Soil Classification System, Symbol Key, and Boring Logs

Attachment E: Cumulative Groundwater Monitoring and Sampling Data Attachment F: Laboratory Analysis Reports and Chain-of-Custody Records

Attachment G: Soil Sample Locations and Analytical Results

Attachment H: Soil Disposal Confirmation

Attachment I: Results of Groundwater Receptor Survey

REFERENCES

California Department of Water Resources. September 1975. California Ground Water. Bulletin 118

California Division of Mines and Geology. 1964 (reprinted 1973) Geologic Map of California. Weed Sheet.

Environmental Resolutions, Inc. August 24, 1998. <u>Underground Storage Tank and Associated Piping and Dispenser Replacement Report</u>. ERI 223532.R01.

Environmental Resolutions, Inc. October 11, 1999. <u>Evaluation of Soil and Groundwater at Tosco 76</u> <u>Service Station 1156, 4276 MacArthur Boulevard, Oakland, California</u>. ERI 223503.R01.

Environmental Resolutions, Inc. August 28, 2000. Work Plan for Supplemental Evaluation of Soil and Groundwater at Tosco 76 Service Station 1156, 4276 MacArthur Boulevard, Oakland, California. ERI 223503.W02.

Gettler-Ryan, Inc. (GRI). November 12, 2001. Fourth Quarter Event of October 3 and 5, 2001. Groundwater Monitoring & Sampling Report, Tosco 76 Service Station #1156, 4276 MacArthur Boulevard, Oakland, California, G-R Job #180225.


United States Geological Survey (USGS). 1980. 7.5-Minute Topographic Quadrangle Map, Oakland West, California.

TABLE 1 RESULTS OF LABORATORY ANALYSIS OF SOIL SAMPLES

Tosco Service Station 1156 4276 MacArthur Boulevard Oakland, California (Page 1 of 1)

Sample	Sample Depth	Date	TPHg	В	T	E	Χ .	MTBE	Lead
Designation	(feet bgs)	Sampled	<			ppm			>
il Boring Samples									
S-5-MW5	5	8/29/01	<1.0	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 0.0050	NA
S-5-MW6	5	8/29/01	< 1.0	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 0.0050	NA
S-5-MW7	5	8/29/01	< 1.0	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 0.0050	NA
S-10-MW7	10	8/29/01	< 5.0	0.18	< 0.025	0.085	0.34	< 0.25	NA
il Stockpile Sample									
S-SP1-(1-4)	NA	8/29/01	<1.0	0.0051	< 0.0050	0.0075	0.031	0.062/0.025a	< 5.5

S-5-MW5	= Soil sample-depth-boring MW5.
S-SP1-(1-4)	= Composited stockpiled soil sample-stockpile number-sample sleeve numbers.
TPHg	= Total petroleum hydrocarbons as gasoline analyzed using EPA Method 8015M.
BTEX	= Benzene, toluene, ethylbenzene, and total xylenes analyzed using EPA Method 8020.
MTBE	Methyl tertiary butyl ether analyzed using EPA Method 8020.
Lead	= Total lead analyzed using EPA Method 6010A.
bgs	= Below ground surface.
ppm	= Parts per million.
NA	Not applicable/Not analyzed.
a	= MTBE analyzed using EPA Method 8260B.








SITE VICINITY MAP

TOSCO 76 SERVICE STATION 1156 4276 MacArthur Boulevard Oakland, California

PLATE

1





GENERALIZED SITE PLAN

TOSCO 76 SERVICE STATION 1156 4276 MacArthur Boulevard Oakland, California

EXPLANATION	PROJECT NO.
₩7 Groundwater Monitoring Well	2235
B B'	PLATE
Cross Section Location	2
Tank Pit Backfill Well	Demonster 18, 2001







UNDERGROUND UTILITY MAP


TOSCO 76 SERVICE STATION 1156 4276 MacArthur Boulevard Oakland, California

EXPLANATION	PROJECT NO.
Groundwater Monitoring Well	2235
	PLATE
TP1	3
Tank Pit Backfill Well	December 18, 2001



Mostly Silty Clay





FN 2235 ROSE

EXPLANATION

Compass Direction

10 Data Points Shown

Rose diagram developed by evaluating the groundwater gradient direction from the quarterly monitoring data. Each circle on the rose diagram represents the number of monitoring events that the gradient plotted in that 22 1/2 degree sector.




GROUNDWATER FLOW DIRECTION ROSE DIAGRAM

TOSCO 76 SERVICE STATION 1156 4276 MacArthur Boulevard Oakland, California PROJECT NO.

2235

PLATE

6






TPHg IN GROUNDWATER (October 3, 2001)

TOSCO 76 SERVICE STATION 1156 4276 MacArthur Boulevard Oakland, California

EXPLANATION	PROJECT NO.
Groundwater Monitoring Well	2235
99,000 TPHg Concentration (ppb)	
10,000 Line of Equal TPHs Concentration (ppS)	PLATE
Tank Pit Backfill Well	Describer 18, 8001






MTBE IN GROUNDWATER (October 3, 2001)


TOSCO 76 SERVICE STATION 1156 4276 MacArthur Boulevard Oakland, California

EXPLANATION	PROJECT NO.
Groundwater Monitoring Well 40,000 MTBE Concentration (ppb)	2235
	PLATE
TP1 Tank Pit Backfill Well	December 18, 8081


HYDROGRAPH 1
Well MW1: Concentrations and Depth-to-Water vs. Time
Tosco Service Station 1156
Oakland, California




HYDROGRAPH 2
Well MW2: Concentrations and Depth-to-Water vs. Time
Tosco Service Station 1156
Oakland, California



HYDROGRAPH 3
Well MW3: Concentrations and Depth-to-Water vs. Time
Tosco Service Station 1156
Oakland, California



HYDROGRAPH 4
Well MW4: Concentrations and Depth-to-Water vs. Time
Tosco Service Station 1156
Oakland, California



ATTACHMENT A REGULATORY CORRESPONDENCE

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION (LOP) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

StID 1163

March 8, 2000

grower in John Grander Alex

Mr. Dave DeWitt Tosco P.O. Box 5155 San Ramon, CA 94583

RE:

Offsite Monitoring Wells for 76 Service Station #1156, at 4276 MacArthur

Blvd., Oakland, CA

Dear Mr. DeWitt:

I have completed review of Gettler-Ryan Inc.'s February 2000 First Quarter 2000 Groundwater Monitoring Well and Sampling Report prepared for the above referenced site. That report summarized the groundwater sampling event in January 2000. Laboratory analytical results identified up to 33,100 ppb MTBE in Well MW-2.

There appears to be an increase in MTBE concentration in groundwater samples from Wells MW-2, MW-3, and MW-4. At this time, an offsite investigation is required to delineate the extent of the MTBE plume. A workplan for this phase of investigation is due within 90 days of the date of this letter, or by June 12, 2000.

If you have any questions, I can be reached at (510) 567-6762.

eva chu

Hazardous Materials Specialist

New due date 8-31-00 need SCM also

080 7-21-00 via phre cell

76ss1156-5

į	Post-it Fax Note	7671	Date	# of pages
	To Glann M.		From Dave	$D \mathcal{D} $
	Co./Dept.	4.4	Co. 28 11 11 11 11 11 11 11 11 11 11 11 11 11	er bis i de arriva estas de la
4 - 40	Phone #		Phone s	
	Fax #	Contract.	Fax #	design of the second


22350515

ALAMEDA COUNTY HEALTH CARE SERVICES

AGENCY

DAVID. J. KEARS, Agency Director





ENVIRONMENTAL HEALTH SERVICES

ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

StID 1163

September 18, 2000

Mr. Dave DeWitt Tosco P.O.Box 5155 San Ramon, CA 94583

RE: Work Plan Approval for 76 SS #1156 at 4276 MacArthur, Oakland, CA

Dear Mr. DeWitt:

I have completed review of Environmental Resolutions, Inc.'s August 2000 Work Plan for Supplemental Evaluation of Soil and Groundwater prepared for the above referenced site. The proposal to install three off-site groundwater monitoring wells to evaluate the lateral extent of the contaminant plume is acceptable.

Field work should commence within 60 days of the date of this letter, or by November 20, 2000. Please provide 72 hours advance notice of field activities. If you have any questions, I can be reached at (510) 567-6762.

eva chu

√c:

Hazardous Materials Specialist

Paul Blank, ERI, 73 Digital Drive, Suite 100, Novato, CA 94949-5791

ATTACHMENT B PERMITS



ALAMEDA COUNTY PUBLIC WORKS AGENCY

WATER RESOURCES SECTION 399 ELMHURST ST. HAYWARD CA. 94544-1395 PHONE (\$10) 670-5554 MARLON MAGALLANES/FRANK CODD (\$10) 670-5783 FAX (510)782-1939

DRILLING PERMIT APPLICATION

for applicant to complete	FOR OFFICE USE
OCATION OF PROJECT TOSCO 76 Service Staten 1156	PERMIT NUMBER WOI-448 WELL NUMBER
pakland C4	APN
	PERMIT CONDITIONS
LICHT	Circled Permit Requirements Apply
AND TUSCO Marketon Co Attn: Dave Dewitt	/ A. GENERAL
ddress 2000 Crow Con You Pl Phone 925-277-2584	I. A permit application should be submitted so as to
ily San Rayman Ste 40 210 9 75 83	arrive at the ACPWA office five days prior to
	proposed starting date.
PPLICANT Mental Resolutions Inc Alta: RobSa	2 Submit to ACPWA within 60 days after completion of
lance Environ montal Nesolutions Inc Alth: Nobba	
ddress 73 0.9. tm 1 Dr Stelke Phone 415-357-3571	Well Completion Report. 3. Permit is void if project not begun within 90 days of
try Neverto Zip 94949	sporoval dale
	B. WATER SUPPLY WELLS
	1 Minimum surface seal thickness is two toches of
YPE OF PROJECT	cement grout placed by treinie.
Well Construction Geolechnical Investigation	2 Minimum scal depth is 50 feet for municipal and
Cathodic Protection G General G	industrial wells or 20 feet for domestic and imigation
Water Supply O Contamination O	wells unless a lesser depth is specially approved
Monitoring Well Destruction D	C GROUNDWATER MONITORING WELLS
ROPOSED WATER SUPPLY WELL USE	INCLUDING PIEZOMETERS 1. Minimum surface spal thickness is two metes of
NOPOSED WATER SUFFEE WELL USE New Domestic () Replacement Domestic ()	cement grout placed by tremie-
	2.Minimum seal depth for monitoring wells is the
Municipal () Irrigation () Industrial () Other () ()	maximum depth practicable or 30 feet.
Industriat 6 Other	D. GEOTECHNICAL
PRILLING METHOD:	Backfill bore hale by tremie with coment group or comen'
Mud Rotary D Air Rotary O Auger X	grouvsand miniture. Upper two-three feet replaced in 1972
Cable (1 Other D	or with compacted cuttings
	E. CATHODIC
DRILLER'S NAME Woodened Prilling Co.	Fill hale anode zone with concrete placed by users
V	F. WELL DESTRUCTION
ORILLER'S LICENSE NO 710079	See attached requirements for destruction of sanitary
	wells.Send a map of work site. A different perm i application is required for wells deeper than 43 1991
	G. SPECIAL CONDITIONS
VELL PROJECTS OF	WI WI WWW WWITH THE THE
Drill Hole Diameterin Maximum_	NOTE: One application must be submitted for each well or well
Casing Diameter A in. Depth 20 ft.	destruction. Multiple portings on one application are acceptable
Surface Scal Depth 4 A Owner's Well Number MW6	for geoleckalcal and contamination investigations.
JEOTECHNICAL PROJECTS	
Number of Borings Maximum	
Hole Diarneter in. Depth 6.	(00
-1/1: In Olamba	W/X (SI-)
STIMATED STARTING DATE 7/10/0 0 000	APPROVED DATE D'OU
STIMATED COMPLETION DATE 3/16/01	APPROVED DATE
hereby agree to comply with all requirements of this permit and Alameda County Or	dinance No. 71,62
,	
APPLICANT'S SIGNATURE KOLLSON DATE G	<u> </u>
LEASE PRINT NAME RUS SOUT REV	r.6 -3-00



ALAMEDA COUNTY PUBLIC WORKS AGENCY

WATER RESOURCES SECTION

J99 ELMHURST ST, HAYWARD CA. 94544-1395

PHONE (510) 670-5554 MARLON MAGALLANES/FRANK CODD (510) 670-5783

FAX (510)787-1939

APPLICATION
FOR OFFICE USE PERMIT NUMBER WELL NUMBER APN
Circled Permit Requirements Apply A. GENERAL 1. A permit application should be submitted so as to arrive at the ACPWA office five days prior to proposed starting date. 2. Submit to ACPWA within 60 days after completion of permitted original Department of Water Resources. Well Completion Report 3. Permit is void if project not begun within 90 days of approval date.
B. WATER SUPPLY WELLS I. Minimum surface seal thickness is two inches of cement grout placed by teemic. 2. Minimum seal depth is 50 feet for municipal and industrial wells or 20 feet for domestic and imigation wells unless a baser depth is specially approved. C. GROUNDWATER MONITORING WELLS. I. Minimum surface seal thickness is two inches of cement grout placed by treme. 2. Minimum seal depth for monitoring wells is the maximum depth practicable or 20 feet. D. GEOTECHNICAL. Backfill bore hole by tremie with coment grout or cement grouts and mixture. Upper two-three feet replaced in kind or with compacted cuttings. E. CATHODIC Fill hole anode zone with concrete placed by tramic. F. WELL DESTRUCTION See stached requirements for destruction of shall ow wells. Send a map of work site. A different permit application is required for wells deeper than 45 terms.
G. SPECIAL CONDITIONS NOTE: One application must be submitted for each well or well of delication must be submitted for each well or delication. Multiple borings on one application are acceptable for geolechnical and contamination investigations.
APPROVED DATE 6-9-0/ 8/4 6-5-00



ALAMEDA COUNTY PUBLIC WORKS AGENCY

WATER RESOURCES SECTION 399 ELMHURST ST, HAYWARD CA. 94544-1395 PHONE (510) 670-5554 MARLON MAGALLANES/FRANK CODD (510) 670-5783 FAX (510)782-1939

DRILLING PERMIT	APPLICATION
FOR APPLICANT TO COMPLETE	FOR OFFICE USE
OCATION OF PROJECT TOSCO 76 Service Station 1156	PERMIT NUMBER WOI- 450
4276 Mac Ar Mur Blod	WELL NUMBER
Oakland, CA	M9A
ر ما	DEDLATE GOALD WOOLG
	PERMIT CONDITIONS Circled Permit Requirements Apply
LIENT A.	Curried Fellow Reducements Apply
HIERT Tosco Marketing Co Attn: Dave Dewitt Hodgess 2000 Cry Canyon Place Phone 935-277-3384	A. GENERAL
Address 2000 COM Canyon Place Phone 935- 277-3384	1. A permit application should be submitted so as to
try Say Ramon the 400 Zip 94583	arrive at the ACPWA diffice five days prior to
APPLICANT 1.00	proposed starting date.
Jane Environmental Resolutions Inc Attn: Rob Saur	2 Submit to ACPWA within 60 days after completion of
Fax 4157 T&7 = 104-7	Vell Completion Report.
Address 23 Din tal De Stelou Phone 415-382-35-91	3. Permit is void if project not begun within 90 days of
Tip Novato Zip 94949	approval date
	B. WATER SUPPLY WELLS
TYPE OF PROJECT	1. Minimum surface seat thickness is (we inches of
Well Construction Geotechnical Investigation	cement grout placed by tremie
Cathodic Protection General	2. Minimum seal depth is 50 feet for municipal and industrial wells or 20 feet for domestic and impation
Water Supply D Contamination ()	wells unless a lesser depth is specially approved
Monitoring Well Destruction 0	COROUNDWATER MONITORING WELLS
' ·	INCLUDING PIEZOMETERS
ROPOSED WATER SUPPLY WELL USE	1. Minimum surface seal thickness is two mones of
New Domestic D Replacement Domestic D	cement grout placed by tremie.
Municipal C Irrigation 0	2.Minimum seal depth for monitoring wells is the
Industrial O Other	maximum depth practicable or 20 feet
DRILLING METHOD:	D. GEOTECHNICAL
Mud Rolary D Air Rolary O Auger	Bookfill bore hole by tremie with cament grout or came?
Cable D Other D	growVeand mixture.Upper two-three feet replaced in king.
	of with compacted custings. E. CATHODIC
DRILLER'S NAME Wood ward Prilling Co.	Fill hale enode zone with concrete placed by themse
	F. WELL DESTRUCTION
IRILLER'S LICENSE NO. 710079	See attached requirements for destruction of shallow
	wells. Sond a map of work site. A different perm "
	application is required for wells deeper than 45 too:
VELL PROJECTS	G. SPECIAL CONDITIONS
Drill Hole Diameter & In. Maximum	NOTE: One application must be submitted for each well or well
Cosing Diameter g in Death gg is	destruction. Multiple borings on one application are acceptable
Surface Seal Depth 4 ft. Owner's Well Number MUS	for geotechnical and contamination investigations.
STOREGULICAL BROTES	
DEOTECHNICAL PROJECTS Number of Borings Maximum	
Hole Diancterin. Depthft.	
my color	Las Marchall
STIMATED STARTING DATE 8/28/01.	$1^{\prime\prime\prime}$ M 1 1 1 1 1 1
STIMATED COMPLETION DATE THE STATE STATE OF	APPROVED DATE
hereby agree to comply with all requirements of this permit and Alameda County Ordi	handa No. 21 (2 / 1 / 1 / 1 / 1
The same of the best of the be	Marke (10, 13-08.)
LIPPLICANT'S BIGNATURE NO NEW DATE 6/8	8/6L \
0) (
LEASE PRINT NAME KOL SQUE Rev. 6	-5-90
	\sim

Recording 1	Requested b	v:		alama ar basilisi silik kilo ala	a <u>je da na Brown jel</u> ao, di ar	الماسين يعمل	- The proof of the state of the	o de garagonia de la del
	ŌĀKLANI		· · · · · · · · · · · · · · · · · · ·		— — — — — — — — — — — — — — — — — — —		****	
317 i D . 12	Taran kaun k		e my e	1 14 22 1	to a second to		* ** ##1 -	
City of O	orded Mail to	0:						
•	ity & Econo	mic						
	nent Agency							
. •	Services Di							•
	g Informatic		••		•			
•	_	Plaza, 2nd Flo	or					
Oakland,	CA 94612		•					
m 1 37 D C	NY DADOT	И АПВАНИ						
TAX ROLL PARCEL NUMBER (ASSESSOR'S REFERENCE NUMBER)		10 to				•		
(ASSESS)		· · · · · · · · · · · · · · · · · · ·	DEK)	1 ut 1 t 21 . A t 10				
030	1981	150						
MAP	BLOCK	PARCEL	SUB					
Address	s: 4266 M	ACARTHUR	BLVD.	:	Space 1	Above for R	ecorder's Use	Only
							_	
		MINOR E	NCROACH	MENT PER	MIT AND AG	REEMENT		
mogaco.	NAADIZDO	EDIC COM	NTS7 4h.a 1		tain maal mmama	بالسممال بيس	ad in the Co	ant Dood
					tain real prope ily known as			
				-	nal Revocable			
					ng wells. The l			
					a part hereof.			
					Carola Munich,		-	_
	hibit 'B').		F F		,			• ,
• •	٠.						,	
				bound by the	e conditions for	granting as	n Encroachme	nt Permit
attache	d hereto and	made a part h	ereof.				•	
m 1		.11 1 1	41	د د د		m of the new	an antar dagarib	ed above
_		iii be binding i s in interest the	-	dersigned, in	e present owne	is of the pro	operty describ	eu above,
and me	II Successor	s in micrest mi	1001.					
In witne	ess whereof	I have set my	signature tl	nis /3	_ day of _ <u>J</u>	LLY ,200	1.	
		,				J'		
TOSCO) MARKET	TNIC COMPA						
<i>f</i> \ .	-: a 1/	TING COMPA	NY -	•		,*		
<u> </u>	م) اسرالهن		NY			,		·
NAME	- 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1	and	NY			<i>:</i>		
	: David J	and Comille				÷		
HILE	: Down J Regional	and Comille		en Official III	. Outo	·		
111LE:	: Doluip J Regiónal	2 Comille Err. Comp		e∧ . or Official Us	e Only			
111LE	: Dough J Regional	and Comille	Manag —Below fo	e∕ . or Official Us TY OF OAI				
	Regional	and Comille	Manag Below fo	e de la companya de				
Dat	Regional	and Comille	Manay —Below fo CI By:	TY OF OAI	KLAND		- · · · · · · · · · · · · · · · · · · ·	
	Regional	and Comille	Ma~a y —Below fo CI By:	TY OF OAL	CLAND ONG			
	Regional	and Comille	Manage Below fo CI By: CA Di	TY OF OAL	KLAND			
	Regional	and Comille	Manage Below for CI By: CA Di For:	ALVIN N. W	CLAND ONG Iding Services			
	Regional	and Comille	Manage Below for CI By: CA Di For: W	ALVIN N. W rector of But	CLAND ONG Iding Services CLAGGETT			
	Regional	and Comille	Manage Below for CI By: CA Di For: W Ex	ALVIN N. W rector of But ILLIAM E. G recutive Direct	CLAND ONG Iding Services CLAGGETT	looment Ao	encv	



EXCAVATION PERMIT TO EXCAVATE IN STREETS OR OTHER SPECIFIED WORK

ENGINEERING

CIVIL

APPROX. ETANT DATE Ormal not reads wheat A-foor number) CONTENCTOR'S LICINSE PLAND CLASS CITY BUSINESS TAX # CITY BUSINESS TAX # ATTENTOR Description of the content of the foot content winter all (Auroga or Jacob or CITY) was a failed by a foot or content or Jacob or CITY BUSINESS TAX # ATTENTOR AS hours prior to starting work, YOU MUST CALL (510) 238-3651 TOSCHEDULE AN INSPECTION. OWNER/BULLER Lardy affirm that I am compt from the Commette's Linear Law for the following reason (500, 781.1 Business and Professional Code: Any dily or consequently which requires a primar to comments, also, improve, familiar, or repair any strong to the foot of the fo	PERMIT NUMBER X 0 1 0 2 7 2	SITE ADDRESS/LOCATION 4266 MACANTHIN BL
ATTENTOS De la per pour la fact de a concessioners cell Undergree de Section des (TOS) was welled by Novel une content. The permit is not valid patient population of a content of the co	APPROX. START DATE APPROX. END DATE	■ 通過性能等等的個別的概念。如何可能是一個人工事等的可能可能可能可能可能可能是可能可能可能可能可能可能可能可能。
Due to a version for the comments owner and (Seebey news) Section Section (TO 10) which all the process of the part of the section of the part of the process of the	CONTRACTOR'S LICENSE FAND CLASS	CITY BUSINESS TAX /
OWNER/BUILDER Interby stime that I am example from the Connector's License Law for the following reason (Sec. 7031.5) Biteness and Professions Code. Any object woman which prepare a permit to constituent of the Connector. I License Law for the following reason (Sec. 7031.5) Biteness and Professions Code, or that he is example to the connection with Sec. 7000. of Division 3 of the Business and Professions Code, or that he is example to the connection of the connection of the property of the second preparent of the property of the second preparent of the property of the second in property of the second of property of the second in property of the second of the property of the prop	State law requires that the contractor/owner call Underground Sept	oles Alert (USA) two working days before excavating. This permit is not valid unless applicant has secured an enumber is 1 (800) 642-2444. UNDERGROUND SERVICE ALERT (USA) 6:
Thereby affirm that I am example from the Contractor's License Law for the following reason (Sec. 7011.5 Bisiness and Professiona Code: Any only or county which requires a permit to construct, shore, improve, denoted, for experience of the instance, also requires the significant for each promit to this a signed season of the law for the alleged examples. Any violation of fourth 7011.5 by any person to the a promit to the a signed examples. Any violation of fourth 7011.5 by any person in any person to the alleged examples. Any violation of fourth 7011.5 by any person to the promit to the alleged examples. Any violation of fourth 7011.5 by any person of the promit of	48 hours prior to starting work, YOU MUST CALL (510) 238-3651 TO SCHEDULE AN INSPECTION.	
Policy # Company Name NOTICE TO AFFLICANT. If, after making this Certificate of Exemption, you should become subject to the Worker's Compensation provisions of the Labor Code, you must forthwith compty with such provisions or this permit all be deemed revoked. This permit is issued, the express condition that the permittee shall be responsible for all claims and liabilities arising out of work performed under the permittee shall be responsible for all claims and liabilities arising out of work performed under the permittee shall be responsible for all claims and liabilities arising out of work performed under the permittee shall not perform the obligations with respect to street maintenance. The permittee shall, and by acceptance of the permit agrees to defend, indemnity, save and bold harmises the City, to officers and employees, from and agrees or defend agrees to defend, indemnity, assee and bold harmises the City, to officers and employees, from the agrees and agree to defend, indemnity, assee and bold harmises the City, to officers permit is roid 90 days from the date of issuance varies as extension is graited by the Director of the Office of Planning and Building. Company from the late of issuance varies as extension is graited by the Director of the Office of Planning and Building. Company for the date of issuance varies as extension is graited by the Director of the Office of Planning and Building. Company for the Contractory, that I have read this permit and agree to its requirements, and that the above information is true and correct under penalty of law. Date of Planning and Building. Company for the Contractory, that I have read this permit date of the permittee and correct under penalty of law. Date of Planning and Date of the Contractory, that I have read this permit date of the Contr	I hereby affirm that I am exempt from the Contractor's License Law for the for construct, alter, improve, demolish, or repair any structure, prior to its issuance provisions of the Contractor's License law Chapter 9 (commencing with Sec. alleged exemption. Any violation of Section 7031.5 by any applicant for a per I, as an owner of the property, or my employees with wages as their sole of Professions Code: The Contractor's License Law does not apply to an owner provided that much improvements are not intended or offered for sale. If howe burden of proving that he did not build or improve for the purpose of sale). I, as owner of the property, an exempt from the sale requirements of the a be performed prior to sale, (3) I have resided in the residence for the 12 month structures more than once during any three-year period. (Sec. 7044 Business a II, as owner of the property, am exclusively contracting with licensed contradoes not apply to an owner of property who builds or improves thereon, and a	co, also requires the applicant for such permit to file a signed statement that he is licensed persuant to the (7000) of Division 3 of the Business and Professions Code, or that he is exempt therefrom and the basis for the unit subjects the applicant to a civil penalty of not more than \$500): compensation, will do the work, and the structure is not intended or offered for sale (Sec. 7044, Business of property who builds or improves thereon, and who does such work himself or through his own employees, wer, the building or improvement is sold within one year of completion, the owner-builder will have the bove due to: (1) I am improving my principal place of residence or appurtenances thereto, (2) the work will as prior to completion of the work, and (4) I have not claimed exemption on this subdivision on more than two and Professions Code). Sectors to construct the project, (Sec. 7044, Business and Professions Code).
O Testify that in the performance of the work for which this permit is issued, I shall not employ any person in any manner so as to become subject to the Worker's Compensation Laws of California (not required for work valued at one handred dollars (\$100) or less). NOTICE TO APPLICANT: If, after making this Certificate of Exemption, you should become subject to the Worker's Compensation provisions of the Labor Code, you must forthwith compty with such provisions or this permit shall be deemed revoked. This permit is issued pursuant to all provisions of Tile 12 Claster 12.12 of the Oakland Musician Code. It is granted upon the express condition that the permittee shall be responsible for all claims and labilities arising out of work performed under the permit or arising out of work performed under the permit upon the obligations with respect to street maintenance. The permittee shall, and by secreptance of the permit agrees to defend, indomnify, save and bold harmiess the City, its officers and employees, from and against any and all selfs, claims, or actions brought by any person for or on account of any bodity injuries, disease or illness or damage to persons and/or property mustained or arising in the tronstruction of the work performed under the permit or in consequence of permittee's failure to perform the obligations with respect to street maintenance. This permit is void 90 days from the date of insuance unless an extension is granted by the Director of the Office of Planning and Building. Thereby affirm that I am licensed under provisions of Chapter 9 of Division 3 of the Business and Professions Code and my license is in full force and effect (if contractor), that I have read this permit and agree to its requirements, and that the above information is true and correct under penalty of law. DATE STREET LAST SPECIAL PAVING DETAIL HOLDAY RESTRICTION LIMITED OPERATION AREA! REQUIRED? GYES ONO (NOVI-JANI)	The state of the s	leats of Worker's Compensation Insurance, or a certified copy thereof (Sec. 2700, Labor Code).
comply with such provisions or this permit shall be deemed revoked. This permit is issued pursuant to all provisions of Tale 12 Chapter 12.12 of the Oakland Municipal Code. It is granted upon the express condition that the permittee shall be responsible for all claims and isabilities arising out of work performed under the permit or arising out of work performed under the permit or arising out of work performed under the permittee is fallure to perform the obligations with respect to street maintenance. The permittee shall, and by acceptance of the permit agrees to defend, inducedily, save and bold harmless the City, its officers and employees, from and against any and all swits, claims, or actions brought by any person for or on account of any bodily, injuries, disease or illness or damage to persona and/or property nustained or arising in the construction of the work performed under the permit or in consequence of permittee's failure to perform the obligations with respect to street maintenance. This permit is void 90 days from the date of issuance unless an extension is grasted by the Director of the Office of Planning and Building. Thereby affirm that I am licensed under provisions of Chapter 9 of Division 3 of the Business and Professions Code and my license is in full force and effect (if contractor), that I have read this permit and agree to its requirements, and that the above information is true and correct under penalty of law. DATE STREET LAST SPECIAL PAVING DETAIL HOLDAY RESTRICTIONT LIMITED OPERATION AREAN LIMITED OPERATION AREAN RESURFACED REQUIRED TO YES TO NO (NOV 1-JAN 1) DATES O NO (7AM-9AM & 4PM-6PM) DATES O NO	D I certify that in the performance of the work for which this permit is issued	I, I shall not employ any person in any manner so as to become subject to the Worker's Compensation Laws
Signature of Permittee Agent for D Contractor - Owner Date 17 Agent for D Contractor - Owner DATE STREET LAST: SPECIAL PAVING DETAIL HOLDAY RESTRICTION? RESURFACED REQUIRED? G YES - D NO (NOV 1-JAN 1) - D YES G NO (7AM-9AM & 4PM-6PM) - D YES G NO	comply with such provisions or this permit shall be deemed revoked. This per granted upon the express condition that the permittee shall be responsible for a perform the obligations with respect to street maintenance. The permittee shall and employees, from and against any and all suits, claims, or actions brought mustained or arising in the construction of the work performed under the permi	rmit is issued pursuant to all provisions of Title 12 Chapter 12.12 of the Oakland Municipal Code. It is ill claims and liabilities arising out of work performed under the permit or arising out of permittee's failure to il, and by acceptance of the permit agrees to defend, indepenity, save and hold harmless the City, its officers by any person for or on account of any bodily injuries, disease or illness or damage to persons and/or property it or in consequence of permittee's failure to perform the obligations with respect to street maintenance. This
DATE STREET LAST SPECIAL PAVING DETAIL HOLIDAY RESTRICTION? LIMITED OPERATION AREA! RESURFACED REQUIRED? G.YES G.NO (NOV.1-UAN.1) G.YES G.NO (7AM-9AM & 4PM-6PM) G.YES G.NO	this permit and agree to its requirements, and that the above information is true Polyth A Hum & R.T.	a and correct under populty of law.
一个一个大学的一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个	DATE STREET LAST SPECIAL PAVING DETAIL RESURFACED REQUIRED O YES ONO	HOLIDAY RESTRICTION? LIMITED OPERATION AREA! (NOV 1 JAN 1) - D YES O NO (7AM-9AM & 4PM-6PM) - D YES O NO

ATTACHMENT C FIELD PROTOCOL

FIELD PROTOCOL

Site Safety Plan

Field work is performed by ERI personnel in accordance with a site safety plan (SSP) developed for the site. The SSP describes the basic safety requirements for the subsurface investigation and the drilling of soil borings at the work site. The SSP is applicable to personnel and subcontractors of ERI. Personnel at the site are informed of the contents of the SSP before work begins. A copy of the SSP is kept at the work site and is available for reference by appropriate parties during the work. The ERI geologist acts as the Site Safety Officer.

Soil Borings and Sampling

Prior to drilling of borings and construction of wells, ERI acquires necessary permits from the appropriate agency(ies). ERI also contacts Underground Service Alert (USA) and a private utility locator before drilling to help locate public utility lines at the site. ERI observes the driller hand-probe and hand-auger boring locations to a depth of approximately 5 feet bgs and a diameter greater than the soil boring diameter before drilling to reduce the risk of damaging underground structures.

Soil borings are drilled with a B-57 (or similar) drill rig equipped with 8-inch diameter, hollow-stem augers. Auger flights and sampling equipment are steam-cleaned before use to minimize the possibility of crosshole contamination. The rinsate is containerized and stored on site. ERI will coordinate with Tosco for appropriate recycling or disposal of the rinsate.

Drilling is performed under the observation of a field geologist, and the earth materials in the borings are identified using visual and manual methods, and classified as drilling progresses using the Unified Soil Classification System. Soil borings are drilled to approximately 10 to 15 feet below the uppermost zone of saturation or 5 feet into any competent clay layer (aquitard) encountered beneath the waterbearing zone. If an aquitard is encountered, the boring is terminated and backfilled with bentonite before installing a groundwater monitoring well.

During drilling, soil samples are collected at 5-foot intervals, obvious changes in lithology, and just above the groundwater surface. Samples are collected with a California-modified, split-spoon sampler equipped with laboratory-cleaned brass sleeves. Samples are collected by advancing the auger to a point just above the sampling depth and driving the sampler into the soil. The sampler is driven 18 inches with a standard 140-pound hammer repeatedly dropped 30 inches. The number of blows required to drive the sampler each successive 6-inch interval is counted and recorded to give an indication of soil consistency.

Soil samples are monitored with a photoionization detector (PID), which measures hydrocarbon concentrations in the ambient air or headspace above the soil sample. Field instruments such as the PID are useful for indicating relative levels of hydrocarbon vapors, but do not detect concentrations of hydrocarbons with the same precision as laboratory analyses. Soil samples selected for possible chemical analyses are sealed promptly with Teflon® tape, and plastic caps. The samples are labeled and placed in iced storage for transport to the laboratory. Chain-of-Custody Records are initiated by the geologist in the field, updated throughout handling of the samples, and sent with the samples to the laboratory. Copies of these records are in our report. Cuttings generated during drilling are placed on

plastic sheeting and covered and left at the site. ERI coordinates with Tosco for the soil to either be treated on site or removed to an appropriate recycling or disposal facility.

Monitoring Well Construction

Monitoring wells are constructed in borings using thread-jointed, 2-inch inner diameter, Schedule 40 polyvinyl chloride (PVC) casing. No chemical cements, glues, or solvents are used in well construction. The screened portion of each well consists of factory-perforated casing with 0.020-inch wide slots. If unconfined aquifer conditions exist, the well screen is installed from the total depth of each well to approximately 10 feet above the uppermost water-bearing unit. If confined conditions exist, the uppermost water-bearing unit is screened exclusively. Unperforated casing is installed from the top of each screen to the ground surface. The annular space in the well is packed with number 3 sand to approximately 1 to 2 feet above the slotted interval. A bentonite plug is added above the sand pack to prevent cement from entering the well pack. The remaining annulus is backfilled to grade with a slurry of Portland cement.

The monitoring wells are protected with a traffic-rated steel utility box equipped with a galvanized sheet steel skirt. The box has a watertight seal to protect against surface-water infiltration. The design of this box discourages vandalism and reduces the possibility of accidental disturbance of the well.

ATTACHMENT D

UNIFIED SOIL CLASSIFICATION SYSTEM, SYMBOL KEY, AND BORING LOGS

UNIFIED SOIL CLASSIFICATION SYSTEM

MAJOR D	ENOISIVI	LTR	DESCRIPTION	MAJOR D	IVISIONS	LTR	DESCRIPTION
		GW	Well-graded gravels or gravel sand mixtures, little or no fines			ML	Inorganic silts and very fine- grained sands, rock flour, silty
		Poorly-graded gravels or gravel sand mixture, little or no fines		SILTS		or clayey fine sands or clayey silts with slight plasticity	
	GRAVELLY SOILS	GM	Silty gravels, gravel-sand-clay mixtures		CLAYS LL<50	CL	Inorganic clays of low to medium plasticity, gravelly clays, sandy clays, silty clays, lean clays
COARSE		GC	Clayey gravels, gravel—sand—clay mixtures	FINE		OL	Organic silts and organic silt— clays of low plasticity
GRAINED SOILS		SW	Well-graded sands or gravelly sands, little or no fines	GRAINED		мн	Inorganic silts, micaceous or diatomaceous fine—grained sandy or silty soils, elastic silts
	SAND AND	SP	Poorly-graded sands or gravelly sands, little or no fines		SILTS AND CLAYS	СН	Inorganic clays of high plast—icity, fat clays
	SANDY	SM	Silty sands, sand-silt mixtures		LL>50	ОН	Organic clays of medium to high plasticity
	SC Clayey sands, sand-clay mixture		Clayey sands, sand-clay mixtures		ORGANIC	Pt	Peat and other highly organic soils

			WELL DESIGN
I	DEPTH THROUGH WHICH SAMPLER IS DRIVEN		SAND PACK
I	RELATIVELY UNDISTURBED SAMPLE		BENTONITE ANNULAR SEAL
$\not \bot$	MISSED SAMPLE		NEAT CEMENT ANNULAR SEAL
$\frac{\bar{z}}{\Delta}$	GROUNDWATER LEVEL OBSERVED FROM FIRST WET SOIL SAMPLE IN BORING		BLANK PVC
<u>▼</u>	STATIC GROUNDWATER LEVEL		MACHINE-SLOTTED PVC
OVM	ORGANIC VAPOR METER READING IN PARTS PER MILLION	S-10	SAMPLE LOCATION
		NR	NOT RECORDED
PID	PHOTO-IONIZATION DETECTOR READING IN PARTS PER MILLION	NA	NOT ANALYZED

BLOW/FT. REPRESENTS THE NUMBER OF BLOWS OF A 140-POUND HAMMER FALLING 30 INCHES TO DRIVE THE SAMPLER THROUGH THE LAST 12 INCHES OF AN 18-INCH OR 24-INCH PENETRATION. DASHED LINES SEPARATING UNITS ON THE LOG REPRESENT APPROXIMATE BOUNDARIES ONLY. ACTUAL BOUNDARIES MAY BE GRADUAL. LOGS REPRESENT SUBSURFACE CONDITIONS AT THE BORING LOCATION AT THE TIME OF DRILLING ONLY.


WITH DESIGN




UNIFIED SOIL CLASSIFICATION SYSTEM AND LOG OF BORINGS SYMBOL KEY

ATTACHMENT

TOSCO 76 SERVICE STATION 1156 4276 MacArthur Boulevard Oakland, California





Site: Tosco 76 Service Station 1156 Date: 7/16/99 Drill Contractor: Woodward Drilling Sample Method: Split Spoon Geologist: MADN S. DOCKEN Location: 2 Feet Rast of Southernmost Driveway Registration: R.G. 4412 Along MacArthur Boulevard Logged by: Dylan Crouse GEOLOGIC DESCRIPTION 4 asphalt Clay, dark greenish grey, motiled, redish orange, size of split plasticity, (35% sand, 65% clay) 5 11 20 CH 15% fine gravels up to 0.5", 20% sand, medium—grained, damp Silty clay orange brown, motiled green gray (35% silt, 65% clay), moist, medium plasticity, very moist, black stiding 20 29 20 Gravelly clay, light vellowish brown wet, meaning plasticity, very moist, medium plasticity, very moist, medium plasticity, very moist, medium plasticity, very moist, medium plasticity, very meaning plast		Project No.: 2235 Boring: B2/MW2 Plate: AP	PENDIX
Sample Method: Split Spoon Drill Rig: B57 Bore Hole Diameter: 8' Signature Location: 2 Feet East of Southernmost Driveway Along MacArthur Boulevard Logged by: Dylan Cronse GEOLOGIC DESCRIPTION 4 asphalt Clay, dark greenish gray, mottled redish orange, singh plasticity, (35% sand, 65% clay) 5-11 20 GH 15% fine gravels up to 0.5', 20% sand, medium-grained, damp 15% fine gravels up to 0.5', 20% sand, medium-grained, damp Silty clay, orange brown, mottled green gray (35% said, 65% clay), moist, medium plasticity GEOLOGIC DESCRIPTION 4 asphalt Clay, dark greenish gray, mottled redish orange, singh plasticity, (35% sand, 65% clay) 5-11 20 GH 15% fine gravels up to 0.5', 20% sand, medium-grained, damp Silty clay, orange brown, mottled green gray (35% said, 65% clay), moist, medium plasticity GEOLOGIC DESCRIPTION 4 asphalt Clay, dark greenish gray, mottled green gray (35% sand, 65% clay), moist, medium plasticity GEOLOGIC DESCRIPTION 4 asphalt Clay, dark greenish gray, mottled green gray (35% sand, 65% clay), moist, medium plasticity GEOLOGIC DESCRIPTION 4 asphalt Clay, dark greenish gray, mottled green gray (35% sand, 65% clay) GEOLOGIC DESCRIPTION 4 asphalt Clay, dark greenish gray, mottled green gray (35% sand, 65% clay) GEOLOGIC DESCRIPTION 4 asphalt Clay, dark greenish gray, mottled green gray (35% sand, 65% clay) GEOLOGIC DESCRIPTION 4 asphalt Clay, dark greenish gray, mottled green gray (35% sand, 65% clay) GEOLOGIC DESCRIPTION 4 asphalt Clay, dark greenish gray, mottled green gray (35% sand, 65% clay) GEOLOGIC DESCRIPTION 4 asphalt Clay, dark greenish gray, mottled green gray (35% sand, 65% clay) GEOLOGIC DESCRIPTION 4 asphalt Clay, dark greenish gray, mottled green gray (35% sand, 65% clay) GEOLOGIC DESCRIPTION 4 asphalt GEOLOGIC DESCRIPTION 5 and dark greenish gray, mottled green gray (40% sand, 65% clay) GEOLOGIC DESCRIPTION 5 and dark greenish gray, mottled green gray (40% sand, 65% clay) GEOLOGIC DESCRIPTION 5 and dark gray 6 and dark gray 6 and dark gray 6 and dark gray	EN FRANCISCOTAL		7/16/99
Drill Rig: B87	RESOLUTIONS, INC.	Drill Contractor: Woodward Drilling	
Location: 2 Feet East of Southernmost Driveway Registration: R.G. 4412 Along MacArthur Roulevard Logged by: Dylan Crobse GEOLOGIC DESCRIPTION 4 asphalt Claymer's greenish gray, motiled redish orange, high plasticity, (35% sand, 65% clay) 15% fine gravels up to 0.5°, 20% sand, medium—grained, damp 15% fine gravels up to 0.5°, 20% sand, medium—grained, damp 15% silt, 65% clay), moist, medium plasticity 20 29 20 Gravelly clay, light yellowish brown, (40% fine moist, black stations) Sandy clay, trace of silt, yellowish brown, wet, medium plasticity, (35% sand, 15% silt, 50% clay) MI. Sandy clay, trace of silt, yellowish brown, wet, medium plasticity, (35% sand, 15% silt, 50% clay) Total depth at 26.5 feet, Groundwater encountered at 23' 6".	: 선생, 경기 없는 1시 (특) 급하기 전, 경기를 하고 있다. 사람이 있는 전에 보고 하고 있다. 그리고 있다.		PEKHM
Along MacArthur Roulevard Logged by: Dylan Crobse GEOLOGIC DESCRIPTION 4 asphalt Clay, dark greenish gray, nottled redish orange, sight plasticity, (35% sand, 31ghtly damp, sight plasticity, (35% sand, 65% clay) 10 18 0 15% fine gravels up to 0.5", 20% sand, medium—grained, damp Silty clay orange brown, mottled green gray (35% silf, 65% clay), moist, medium plasticity 20 29 20 GROLOGIC DESCRIPTION 4 asphalt Clay, dark greenish gray, nottled redish orange, silf plasticity, (35% sand, 65% clay) Silty clay orange brown, mottled green gray (35% silf, 65% clay), moist, medium plasticity, were gravely clay, light yellowish brown, (40% fine gravely clay, light medium plasticity, very medium plasticity medium plasticity medium plasticity m		9/1	/ /
GEOLOGIC DESCRIPTION 4" asphalt Clay, dark greenish gray, mottled redish orange, some coarse-grained sand, slightly damp, high plasticity, (35% sand, 65% clay) 10 18 0 15% fine gravels up to 0.5", 20% sand, medium-grained, damp 15% fine gravels up to 0.5", 20% sand, medium-grained, damp Silty clay, orange brown, mottled green gray, with the same of		t of Southernmost Driveway Registration: R.G.	4412
4. asphale. Clay, dark greenish gray, mottled redish orange, some coarse grained sand, slightly damp, high plasticity, (35% sand, 65% clay) 10- 18 0	Along_MacA	rthur Houlevard Logged by: Dylan Cro	/
4. asphale. Clay, dark greenish gray, motiled redish orange, some coarse grained sand, slightly damp, high plasticity, (35% sand, 65% clay) 10- 18 0	10 p 30 10 0	//	131 13
4. asphale. Clay, dark greenish gray, mottled redish orange, some coarse grained sand, slightly damp, high plasticity, (35% sand, 65% clay) 10- 18 0		GEOLOGIC DESCRIPTION	A SA
Clay, dark greenish gray, mottlet redish orange, some coarse-grained sand, slightly damp, high plasticity, (35% sand, 65% clay) 10 18 0	13/39 3 79 3/	A" aenhalt	100 VII
10- 18 0 15% fine gravels up to 0.5", 20% sand, medium—grained, damp Silty clay, orange brown, mottled green gray (35% silt, 65% clay), moist, medium plasticity 20- 29 20		Clay, dark greenish gray, mottled redish orange,	
10- 18 0 15% fine gravels up to 0.5°, 20% sand, medium—grained, damp Silty clay, orange brown, mottled green gravity (35% silt, 65% clay), moist, medium plasticity CL 20- 29 20		high plasticity, (35% sand, 65% clay)	
15% fine gravels up to 0.5°, 20% sand, medium—grained, damp 150 21 130 CL CL 20 29 20 ML Silty clay, orange brown, mottled green gray; (35% silt, 65% clay), moist, medium plasticity gravelly clay, light yellowish brown, (40% fine gravel) clay, light yellowish brown, wet, moist, black staining moist, black staining medium plasticity, very medium plasticity, (35% sand, 15% silt, 50% gravelly clay, trace of silt yellowish brown, wet, medium plasticity, (35% sand, 15% silt, 50% gravelly clay, trace of silt yellowish brown, wet, medium plasticity, (35% sand, 15% silt, 50% gravelly clay, trace of silt yellowish brown, wet, medium plasticity, clay is a silt of the control			7.2.2 4.2.2.2
15% fine gravels up to 0.5°, 20% sand, medium—grained, damp 150 21 130 CL CL 20 29 20 ML Silty clay, orange brown, mottled green gray; (35% silt, 65% clay), moist, medium plasticity gravelly clay, light yellowish brown, (40% fine gravel) clay, light yellowish brown, wet, moist, black staining moist, black staining medium plasticity, very medium plasticity, (35% sand, 15% silt, 50% gravelly clay, trace of silt yellowish brown, wet, medium plasticity, (35% sand, 15% silt, 50% gravelly clay, trace of silt yellowish brown, wet, medium plasticity, (35% sand, 15% silt, 50% gravelly clay, trace of silt yellowish brown, wet, medium plasticity, clay is a silt of the control	- 4 00		### #### 5
15% fine gravels up to 0.5", 20% sand, 15	-5-11 20 II CE	I	·····
15% fine gravels up to 0.5", 20% sand, 15	The Property		E
15% fine gravels up to 0.5", 20% sand, 15			# # #
Sility clay, orange brown, mottled green grayly (35% silt, 65% clay), moist, medium plasticity CI. 20 29 20 gravelly clay, light yellowish brown, (40% fine gravel, 60% clay), medium plasticity, very moist, black staining Sandy clay, trace of silt, yellowish brown, wet, medium plasticity, (35% sand, 15% silt, 50% of the gravel, 60% clay). Total depth at 26.5 feet. Groundwater encountered at 23' 6".			ρ
Sility clay, orange brown, mottled green grayly (35% silt, 65% clay), moist, medium plasticity CI. 20 29 20 gravelly clay, light yellowish brown, (40% fine gravel, 60% clay), medium plasticity, very moist, black staining Sandy clay, trace of silt, yellowish brown, wet, medium plasticity, (35% sand, 15% silt, 50% of the gravel, 60% clay). Total depth at 26.5 feet. Groundwater encountered at 23' 6".	10-18 0	15% fine gravels up to 0.5", 20% sand,	
Silty clay, orange brown, mottled green gray (35% silt, 65% clay), moist, medium plasticity CL gravelly clay, light yellowish brown (40% fine braye), 60% clay) medium plasticity, very moist, black staining Sandy clay, trace of silt yellowish brown, wet, medium plasticity, very medium plasticity, very medium plasticity, very medium plasticity, (35% sand, 15% silt, 50% clay) medium plasticity, very moist, brown, wet, medium plasticity, very moist, brown, wet, medium plasticity, very moist, brown, wet, medium plasticity, very moist, medium plasticity Total clay, trace of silt yellowish brown, wet, medium plasticity, very moist, medium plasticity Total depth at 28.5 feet. Groundwater encountered at 23' 6".		medium-gramed, damp	# # # # # # # # # # # # # # # # # # #
Silty clay, orange brown, mottled green gray (35% silt, 65% clay), moist, medium plasticity CL gravelly clay, light yellowish brown (40% fine braye), 60% clay) medium plasticity, very moist, black staining Sandy clay, trace of silt yellowish brown, wet, medium plasticity, very medium plasticity, very medium plasticity, very medium plasticity, (35% sand, 15% silt, 50% clay) medium plasticity, very moist, brown, wet, medium plasticity, very moist, brown, wet, medium plasticity, very moist, brown, wet, medium plasticity, very moist, medium plasticity Total clay, trace of silt yellowish brown, wet, medium plasticity, very moist, medium plasticity Total depth at 28.5 feet. Groundwater encountered at 23' 6".			iro e
20 29 20 gravelly clay, light yellowish brown, (40% fine bravel, 60% clay), medium plasticity, very moist, black staining Sandy clay, trace of silt yellowish brown, wet, medium plasticity, (35% sand, 15% silt, 50% Total depth at 26.5 feet. Groundwater encountered at 23' 6".	 		
20 29 20 gravelly clay, light yellowish brown, (40% fine bravel, 60% clay), medium plasticity, very moist, black staining Sandy clay, trace of silt yellowish brown, wet, medium plasticity, (35% sand, 15% silt, 50% Total depth at 26.5 feet. Groundwater encountered at 23' 6".		(35% silt, 65% clay), moist, medium plasticity	N
20 29 20 gravelly clay, light yellowish brown, (40% fine gravel, 60% clay), medium plasticity, very moist, black staining Sandy clay, trace of silt yellowish brown wet, medium plasticity, (35% sand, 15% silt, 50% Total depth at 26.5 feet. Groundwater encountered at 23' 6".	15 21 130	PARTICLE ACCORDANCE AND	
20 29 20 Sandy clay, trace of silt, yellowish brown, wet, medium plasticity, (35% sand, 15% silt, 50% Sandy clay, trace of silt, yellowish brown, wet, medium plasticity, (35% sand, 15% silt, 50% Total depth at 28.5 feet. Groundwater encountered at 23' 6".	CI		
20 29 20 Sandy clay, trace of silt, yellowish brown, wet, medium plasticity, (35% sand, 15% silt, 50% Clay) Sandy clay, trace of silt, yellowish brown, wet, medium plasticity, (35% sand, 15% silt, 50% Clay) Total depth at 26.5 feet. Groundwater encountered at 23' 6".			
20 29 20 Sandy clay, trace of silt, yellowish brown, wet, medium plasticity, (35% sand, 15% silt, 50% Clay) Sandy clay, trace of silt, yellowish brown, wet, medium plasticity, (35% sand, 15% silt, 50% Clay) Total depth at 26.5 feet. Groundwater encountered at 23' 6".		· ·	Siz
Sandy clay, trace of silt yellowish brown, wet, medium plasticity, (35% sand, 15% silt, 50% Total depth at 26.5 feet. Groundwater encountered at 23' 6".		gravelly clay, light yellowish brown, (40% fine	
Sandy clay, trace of silt yellowish brown, wet, medium plasticity, (35% sand, 15% silt, 50% Total depth at 26.5 feet. Groundwater encountered at 23' 6".	20 29 20	moist, black staining	
Total depth at 26.5 feet. Groundwater encountered at 23' 6".			E
Total depth at 26.5 feet. Groundwater encountered at 23' 6".	_ - - - - - - - - - - 	Sandy clay trace of silt vellowish brown wet	- E
Total depth at 26.5 feet. Groundwater encountered at 23' 6".	¥ //MI	medium plasticity, (35% sand, 15% silt, 50%	ā
Total depth at 26.5 feet. Groundwater encountered at 23' 6".		Catay	
Groundwater encountered at 23' 6".			98
Casing Diameter: Slo		Total depth at 26.5 feet.	
Casing Diameter: 2"		Groundwater encountered at 23 6.	lot
Casing Diameter: 2		A	w
Casing Diameter: 2	Fare III		1 4
Casing Diameter:	\vdash		1
			"
		€	je j
		(*	l i
		=	Dia
			ps
			lisi
FM: 2235B002			ပြီ
	PN: 2235B002		




		Project No.: 2235 Boring: B4/MW4 Plate: AP	
ENV	ROMMENTAL ESOLUTIONS, MC.		7/16/99
Sample M	fethod: Split S	Bore Hole Diameter: 8" Signature R.G.	CKUM /
Drill Rig:	B57	Bore Hole Diameter: 8" Signature fanh	Marle
Location:	18 Feet North	of Southernmost Dispenser Registration: R.G./ High Street Logged by: Dylan Cro	4412
18/	/ //	// Logged by. Dyian ora	
	AN CONTROL OF COUNTY	GEOLOGIC DESCRIPTION	AL ALICE
		4 1/2'" asphalt	
		Clay, greenish gray, mottled, orange slightly damp, high plasticity	
-5-17 30	。 	<u>.</u>	E
[3]17]30			Portland
H	T		
	1		B. B.
10-22 25	3		
	CH	trace of medium-grained sand, slightly moist	Grout:
			
	-[-]-[;
15-19 4	H	moist	2/12
	1	and the second s	######################################
	<u> </u>		Size

20 28 4	T	brownish yellow, black staining, 20% gravel, 20% medium-grained sand, moist	T E
		medium-grained sand, moist	oy oy
	<u> </u>		
□		brown, mottled, olive yellow, moist, black staining	9
25 36 0			e e
\square	111	Total depth at 26.5 feet. Groundwater encountered at 23.6 feet.	Size
H		Groundwater encountered at 23.6 feet.	Slot
			"
		_ ~	
H			čv
			etel
		= "	lam
			ĮQ 2
			Casing Diameter:
			Ca
PW: 2235R004			








ATTACHMENT E

CUMULATIVE GROUNDWATER MONITORING AND SAMPLING DATA





Tosco 76 Service Station #1156 4276 MacArthur Boulevard Oakland, California


REVISED DATE

PROJECT NUMBER 180225

REVIEWED BY

October 3, 2001

DATE



6747 Sierra Ct., Suite J Dublin, CA 94568 (925) 551-7555

4276 MacArthur Boulevard Oakland, California

REVISED DATE

PROJECT NUMBER 180225

REVIEWED BY

DATE

October 3, 2001

FILE NAME: P:\Enviro\Toxco\1156\Q01-1156.DWG | Layout Tob: Con4

Table 1 Groundwater Monitoring Data and Analytical Results

WELL ID/	DATE	DTW	S.I.	GWE	Product Thickness	TPH-D	TPH-G	В	æ		¥	
TOC*	DAIL	(f1.)	(fl. bgs)	(msl)	(ft.)	(ppb)	(ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)
3.4777.4							٠					
MW-1 174.86	07/20/99 ⁵	7.50	5.0-25.0	167.36		16,000 ²	150.000	11.000	****			
177.00	09/28/99	8.75	3.0-23.0		-0.01	2,410 ²	120,000 6,020 ⁶	11,000	27,000	3,300	18,000	ND ¹
	09/28/99			166.11	<0.01			1,030	1,040	68.5	412	321/333 ³
•		9.05		165.83**	0.02	7,870 ^{2,4}	72,700 ⁶	7,410	13,900	2,070	9,620	ND ¹
	03/31/00	7.18		167.68	0.00	3,600 ²	92,000 ⁶	10,000	23,000	3,200	14,000	ND ¹
	07/14/00	7.68		167.18	0.00	8,580 ²	108,000 ⁶	8,250	18,700	3,750	17,800	ND ¹
	10/03/00	7.99		166.87	0.00	9,260 ²	96,000 ⁶	8,760	20,000	3,350	15,600	ND1
	01/03/01	9.18		165.68	0.00	11,0008	. 37,000 ⁶	5,800	13,000	1,700	8,100	2,200
	04/04/01	8.05		166.81	0.00	1 4,000 ⁸	86,900 ⁶	7,780	18,500	2,470	11,800	¹ ND/481 ³
	07/17/01	7.01		167.85	0.00	2,200 ⁸	79,000 ⁶	5,600	11,000	2,800	12,000	¹ ND/230 ³
177.54	10/03/01	7.89		169.65	0.00		99,000 ⁶	8,200	18,000	3,000	16,000	<2,500
	10/05/01	7.91		169.63	0.00	13,000 ²		**				, Ф.Я.
MW-2					•			٠				
173.01	07/20/99	5.40	5.0-25.0	167.61			ND!	ND	ND	ND^1	ND^1	4,500/11,000 ^{3,4}
	09/28/99	5.60		167.41	0.00	_	1,390 ⁶	124	NDI	62.9	43.1	5,280/6,150 ³
	01/07/00	5.92		167.09	0.00		1,450 ⁶	99.0	ND	23.8	16.0	33,100
	03/31/00	5.23		167.78	0.00		ND	42	ימא	ND ¹	ND ¹	17,000
	07/14/00	5.52		167.49	0.00		ND ¹	44.7	NDI	ND ¹	ND ¹	66,500
	10/03/00	6.04		166.97	0.00	••	ND ¹	56.7	ND ¹	ND ¹	ND ^I	57,500
	01/03/01	6.42		166.59	0.00		ND ¹	ND ¹	ND ¹	ND ¹	^ו מא	49,000
	04/04/01	6.14		166.87	0.00		ND ¹	ND ¹	ND ¹	ND ¹	ND ¹	49,000 38,700/37,800 ³
	07/17/01	5.30		167.71	0.00		ND ¹	ND ¹	ND ¹	ND ^t	ND ^t	
173.50	10/03/01	7.38		167.71	0.00		<250	2.7	ND <2.5	<2.5	<2.5	65,000/56,000 ³ 14,000/18,000 ³

Table 1 Groundwater Monitoring Data and Analytical Results

					Product							
WELL ID/	DATE	DTW	S.L.	GWE	Thickness	TPH-D	TPH-G	В	T	E	X	MTBE
TOC*		(fL)	(ft. bgs)	(msl)	(ft.)	(ррб)	(ppb)	(ppb)	(ppb)	(ppb)	(ppb)	(ppb)
MW-3												
178.44	07/20/99	8.50	5.0-25.0	169.94			1,000	76	52	79	76	330
	09/28/99	8.31		170.13	0.00		1,860 ⁶	174	95.4	71.8	135	443/288 ³
	01/07/00	8.56		169.88	0.00		28,400 ⁶	2,450	3,090	1,560	3,910	1,940
	03/31/00	8.42		170.02	0.00	••	26,000 ⁶	1,300	2,900	2,600	3,500	2,800
	.07/14/00	8.61		169.83	0.00		24,500 ⁶	1,850	2,630	2,750	3,900	548
	10/03/00	9.14	4	169.30	0.00		22,000 ⁶	1,910	2,020	2,400	2,680	965
	01/03/01	9.06		169.38	0.00	-	14,000 ⁶	1,600	1,100	2,300	1,400	3,300
	04/04/01	8.98		169.46	0.00		19,600 ⁶	1,150	1,470	2,100	1,820	1,050/450 ³
	07/17/01	7.46		170.98	0.00	- -	26,000 ⁶	1,500	2,100	2,100	3,400	¹ ND/350 ³
178.13	10/03/01	9.81		168.32	0.00		22,000 ⁶	830	1,900	1,700	3,000	<1,000
3.4337 4												
MW-4 179.10	07/20/99	7.40	5.0-25.0	171.70			69	2.7	A 77	ND		
.,,,,,,	09/28/99	7.19	3.0-23.0	171.70	0.00		4,050 ⁶		0.77	ND	7.1	100
	01/07/00	8.98		170.12	0.00		7,010 ⁶	1,250	72.0	51.3	133	416/4593
	03/31/00	7.26					7,010 5,500 ⁶	2,260	167	271	276	764
•	07/14/00	7.20 7.67		171.84 171.43	0.00 0.00	-	3,300 7,940 ⁶	1,800	230	330	400	1,000
	10/03/00	8.12		171.43	0.00		7,940 11,400 ⁶	2,810	332	450	247	1,530
	01/03/01 ⁷	9.10		•	0.00	**	8,600 ⁶	3,110	437	519	816	1,040
	04/04/01	9.10 8.63		170.00			9,950 ⁶	2,500	340	480	960	850
	04/04/01	6.49		170.47	0.00		·	2,380	126	416	725	1,140/819 ³
178.96	10/03/01	7.01		172.61	0.00	••	10,000 ⁶	2,300	110	410	800	1,200/9003
170,70	TO/CO/OT	1.01		171.95	0.00	***	7,800 ⁶	2,100	85	380	390	580/820 ³
								•				
MW-5												
169.18	10/03/01 ¹⁰	2.81		166.37	0.00		<50	<0.50	<0.50	<0.50	< 0.50	1,800/2,100 ³

Table 1 Groundwater Monitoring Data and Analytical Results

WELL ID/	DATE	DTW	S.I.	GWE	Product Thickness	TPH-D	TPH-G	В	T	E	x	MTBE
TOC*		(ft.)	(fL bgs)	(msl)	(ft.)	(ppb)	(ppb)	(ppb)	(ppb)	(ppb)	(ppb)	(ppb)
MW-6 169.04	10/03/01 ¹⁰	2.87		166.17	0.00		<50	<0.50	<0.50	<0.50	<0.50	200/270 ³
MW-7 171.64	10/03/01 ¹⁰	7.62	**	164.02	0.00	**	10,000°	210	<50	<50	800	35,000/40,000 ³
Trip Blank					·*					-		
TB-LB	07/20/99	· 		••						<u>:</u> _		
	09/28/99				. ••		ND	ND	NĎ	ND	ND	ND
	01/07/00						ND	ND	ND	ND	ND	ND .
-	03/31/00	-					ND	ND	ND	ND	ND	ND
	07/14/00						ND	ND	ND	ND	ND	ND
	10/03/00				••	· ·	ND	ND	ND	ND	ND	ND
	01/03/01						ND	ND	ND	ND	ND	ND
	04/04/01					••	ND	ND	ND	ND	ND	ND
	07/17/01			 .			ND	ND	ND	ND	ND	ND
	10/03/01	••				••	<50	<0.50	<0.50	<0.50	<0.50	<5.0
	10/05/01	**				••	<50	< 0.50	< 0.50	< 0.50	<0.50	<5.0

Table I

Groundwater Monitoring Data and Analytical Results

Tosco 76 Service Station #1156 4276 MacArthur Boulevard Oakland, California

EXPLANATIONS:

Groundwater monitoring data and laboratory analytical results prior to September 28, 1999, were compiled from reports prepared by Environmental Resolutions, Inc.

TOC = Top of Casing

TPH-D = Total Petroleum Hydrocarbons as Diesel

(ppb) = Parts per billion

DTW = Depth to Water

TPH-G = Total Petroleum Hydrocarbons as Gasoline

ND = Not Detected

(ft.) = Feet

B = Benzene

-- = Not Measured/Not Analyzed

S.J. = Screen Interval

T = Toluene

(ft. bgs) = Feet Below Ground Surface

E = Ethylbenzene

GWE = Groundwater Elevation

X = Xylenes

(msl) = Mean sea level

MTBE = Methyl tertiary butyl ether

- * TOC elevations were resurveyed in September 2001, by Morrow Surveying. TOC elevations are based on City of Oakland Benchmark No. 3967, (Elevation = 174.40 feet, msl).
- ** GWE has been corrected due to the presence of free product; correction factor: [(TOC DTW) + (Product Thickness x 0.77)].
- Detection limit raised. Refer to analytical reports.
- ² Laboratory report indicates unidentified hydrocarbons C9-C24.
- 3 MTBE by EPA Method 8260.
- Laboratory analyzed sample past EPA recommended holding time.
- 5 Total Recoverable Petroleum Oil was ND.
- 6 Laboratory report indicates gasoline C6-C12.
- This sample was originally analyzed within holding time. Re-analysis for confirmation or dilution was performed past the recommended holding time.
- B Laboratory report indicates unidentified hydrocarbons <C16.</p>
- ⁹ Laboratory report indicates weathered gasoline C6-C12.
- Well development performed.

Table 2 Groundwater Analytical Results

WELL ID	DATE	ETHANOL	TBA	MTBE	DIPE	ETBE	TAME	1,2-DCA	EDB	HVOCs	SVOCs
		(ppb)	(ppb)	(ppb)	(ppb)	(ppb)	(ppb)	(ppb)	(ppb)	(руб)	(рув)
MW-1	07/20/99			11,000 ³			<u></u> .			ND	ND ²
	09/28/99		ND ⁶	333	ND^6	ND^6	ND ⁶			ND ⁴	ND ⁵
	01/07/00							**	· 	ND ^{7,8}	ND ⁹
	03/31/00									"	ND ¹⁰
	07/14/00		••					 :	44	ND ¹²	ND^{13}
	10/03/00								••	ND ¹⁵	ND ¹⁴
	01/03/01									ND ¹⁵	ND ¹⁶
	04/04/01	ND^6	ND ⁶	481	ND ⁶	ND ⁶	ND ⁶	ND ⁶	ND^6	ND ¹⁷	ND ¹⁸
	07/17/01	ND ⁶	ND^6	230	ND6	ND ⁶	ND ⁶	ND ⁶	ND ⁶	ND^{20}	ND ¹⁹
				·							
MW-2	09/28/99		ND ⁶	6,150	ND^6	ND6	ND ⁶			. **	
	04/04/01	ND^6	ND^6	37,800	ND ⁶	ND^6	ND ⁶	ND^6	ND6	·	
	07/17/01	ND ⁶	ND ⁶	56,000	ND ⁶	ND^6	ND ⁶	ND ⁶	ND^6	<u>.</u>	
	10/03/01			18,000		••	••		••		••
		·									
MW-3	09/28/99	-	ND ⁶	288	ND ⁶	ND ⁶	8.80				
	04/04/01	ND ⁶	ND ⁶	450	ND ⁶	ND ⁶	ND ⁶	ND6	ND ⁶		
	07/17/01	ND ⁶	ND ⁶	350	ND ⁶						
MW-4	09/28/99		ND ⁶	459	ND ⁶	ND ⁶	ND ⁶				
TAT AA =+4	09/28/99	ND ⁶	ND ⁶	819	ND ⁶						
	07/17/01	ND ⁶	ND ⁶	900	ND ⁶						
	10/03/01	.1D	11D	820			P#				
	10/05/01	 .		U#V		·	· · .	4 •			
MW-5	10/03/01	••	**	2,100	46	-			**	••	
	•			-							

Table 2 Groundwater Analytical Results

WELL ID	DATE	ETHANOL (ppb)	TBA (ppb)	MTBE (ppb)	DIPE (pph)	ETBE (ppb)	TAME (<i>ppb</i>)	1,2-DCA (pph)	EDB (ppb)	HVOCs (ppb)	SVOCs (ppb)
MW-6	10/03/01		-	270					· 		
MW-7	10/03/01	**		40,000	••	••		B.o.	**		

Table 2

Groundwater Analytical Results

Tosco 76 Service Station #1156 4276 MacArthur Boulevard Oakland, California

EXPLANATIONS:

Groundwater laboratory analytical results prior to September 28, 1999, were compiled from reports prepared by Environmental Resolutions, Inc.

TBA = Tertiary butyl alcohol

TAME = Tertiary amyl methyl ether

(ppb) = Parts per billion

MTBE = Methyl tertiary butyl ether

EDB = 1.2-Dibromoethane

ND = Not Detected

DIPE = Di-isopropyl ether

HVOCs = Halogenated Volatile Organic Compounds

-- = Not Analyzed

ETBE = Ethyl tertiary butyl ether

SVOCs = Semi-Volatile Organic Compounds

- All HVOCs were ND except for Chlorobenzene at 12 ppb; 1,2-Dichlorobenzene (1,2-DCB) at 3.9 ppb; 1,1-Dichloroethane (1,1-DCA) at 2.0 ppb; 1,2-Dichloroethane (1,2-DCA) at 20 ppb; cis-1,2-Dichloroethene (cis-1,2-DCE) at 3.6 ppb and 1,2-Dichloropropane (1,2-DCP) at 0.92 ppb.
- All SVOCs were ND except for Benzyl alcohol at 37 ppb; 2,4-Dimethylphenol at 140 ppb; 2-Methylnaphthalene at 240 ppb; 4-Methylphenol at 27 ppb and Naphthalene at 600 ppb.
- Laboratory analyzed sample past EPA recommended holding time.
- All HVOCs were ND except for Benzene at 6,130 ppb; Ethylbenzene at 1,590 ppb; Naphthalene at 534 ppb; Toluene at 11,900 ppb; 1,2,4-Trimethylbenzene at 1,240 ppb; 1,3,5-Trimethylbenzene at 318 ppb and Total Xylenes at 7,360 ppb.
- All SVOCs were ND (with a raised detection limit) except for 2,4-Dimethylphenol at 13.6 ppb; 2-Methylphenol at 87.4 ppb; 2-Methylphenol at 26.4; 4-Methylphenol at 35.6 and Naphthalene at 292 ppb.
- 6 Detection limit raised. Refer to analytical reports.
- All HVOCs were ND (with a raised detection limit) except for Benzene at 8,380 ppb; Ethylbenzene at 2,380 ppb; Naphthalene at 1,050 ppb; n-Propylbenzene at 371 ppb; Toluene at 17,600 ppb; 1,2,4-Trimethylbenzene at 2,210 ppb; 1,3,5-Trimethylbenzene at 597 ppb and Total Xylenes at 10,800 ppb.
- EPA Method 8260 for HVOCs.
- All SVOCs were ND (with a raised detection limit) except for 2-Methylnaphthalene at 315 ppb and Naphthalene at 615 ppb.
- All SVOCs were ND except for Bis(2-ethylhexyl)phthalate at 10 ppb; 1,2-DCB at 6.2 ppb; 2-Methylnaphthalene at 73 ppb; 2-Methylphenol at 31 ppb; 4-Methylphenol at 18 ppb and Naphthalene at 140 ppb. Laboratory report indicates all SVOCs were analyzed outside the EPA recommended holding time.
- 11 Laboratory did not analyze for HVOCs.
- All HVOCs were ND (with a raised detection limit) except for Tetrachloroethene at 334 ppb.
- All SVOCs were ND (with a raised detection limit) except for 2-Methylnaphthalene at 300 ppb and Naphthalene at 690 ppb.
- All SVOCs were ND (with a raised detection limit) except for Benzoic acid at 362 ppb; Bis(2-ethylhexyl)phthalate at 51.6 ppb; 2-Methylnaphthalene at 98.1 ppb; 4-Methylphenol at 28.9 ppb and Naphthalene at 361 ppb.
- ¹⁵ All HVOCs were ND (with a raised detection limit).
- All SVOCs were ND (with a raised detection limit) except for 2-Methylnaphthalene at 180 ppb and Naphthalene at 400 ppb.
- All HVOCs were ND except for cis-1,2-DCA at 3.4 ppb; 1,2-DCA at 5.7 ppb; Chlorobenzene at 5.6 ppb and 1,2-DCB at 4.6 ppb.
- All SVOCs were ND except for Benzoic acid at 28 ppb; Bis(2-ethylhexyl)phthalate at 55 ppb; 2-Methylnaphthalene at 78 ppb and Naphthalene at 490 ppb.

Table 2

Groundwater Analytical Results

Tosco 76 Service Station #1156 4276 MacArthur Boulevard Oakland, California

EXPLANATIONS: (cont)


- All SVOCs were ND except for Bis(2-ethylhexyl)phthalate at 400 ppb; 1,2-DCB at 18 ppb; 2,4-Dimethylphenol at 16 ppb; 2-Methylphenol at 290 ppb; 2-Methylphenol at 47 ppb; 4-Methylphenol at 25 ppb; Naphthalene at 740 ppb and N-Nitrosodimethylamine at 7.7 ppb.
- Volatile Organic Compounds (VOCs) by EPA Method 8021B were ND with a raised detection limit.

ANALYTICAL METHODS:

EPA Method 8260 for Oxygenate Compounds EPA Method 8010 for HVOCs EPA Method 8270 for SVOCs

ATTACHMENT F

LABORATORY ANALYSIS REPORTS AND CHAIN-OF-CUSTODY RECORDS





19 September, 2001

Paul Blank ERI 73 Digital Dr. Suite 100 Novato, CA 94949

RE: TOSCO

Sequoia Report: P109015

Enclosed are the results of analyses for samples received by the laboratory on 09/04/01 15:50. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Angelee Cari

Client Services Representative

Angelee Care

CA ELAP Certificate #2374



73 Digital Dr. Suite 100

Novato CA, 94949

1455 McDowell Blvd, North Ste D Petaluma, CA 94954 (707) 792-1865 FAX (707) 792-0342 www.scquoialabs.com

FRI

Project: TOSCO

Project Number: 1156, Oakland

Project Manager: Paul Blank

Reported:

09/19/01 14:04

ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory ID	Matrix	Date Sampled	Date Received
S-5-MW5	P109015-01	Soil	08/29/01 09:30	09/04/01 15:50
S-5-MW6	P109015-05	Soil	08/29/01 12:05	09/04/01 15:50
S-5-MW7	P109015-10	Soil	08/29/01 14:45	09/04/01 15:50
S-10-MW7	P109015-11	Soil	08/29/01 14:50	09/04/01 15:50
S-SP1-(1-4)	P109015-15	Soil	08/29/01 16:00	09/04/01 15:50

Sequoia Analytical - Petaluma
Anyelue Carie

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.



ERI

73 Digital Dr. Suite 100 Novato CA, 94949 Project: TOSCO

Project Number: 1156, Oakland Project Manager: Paul Blank Reported: 09/19/01 14:04

Total Petroleum Hydrocarbons as Gasoline and BTEX by EPA 8015M/8020M Sequoia Analytical - Petaluma

		- ·		1 1000			•		
Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
S-5-MW5 (P109015-01) Soil	Sampled: 08/29/01 09:30	Received:	09/04/01	15:50					
Gasoline (C6-C12)	ND	. 1.0	mg/kg	1	1090037	09/05/01	09/05/01	EPA 8015M/8020M	
Benzene	ND	0.0050		н	#	н	•	H	
Toluene	ND	0.0050		#	n	#	•	n	
Ethylbenzene	ND	0.0050	*	#	10	*	n .	H	
Xylenes (total)	ND	0.0050	Ħ	#	H	н	*	Ħ	
Methyl tert-butyl ether	ND	0.050	#	#	n	n		11	
Surrogate: a, a, a-Trifluorotoluen	e	102 %	65-	135	н	,,	ff	ч	
Surrogate: 4-Bromofluorobenze		101 %	65-	135	*	**	"	n	
S-5-MW6 (P109015-05) Soil	Sampled: 08/29/01 12:05	Received:	09/04/01	15:50					•
Gasoline (C6-C12)	ND	1.0	mg/kg	1	1090037	09/05/01	09/05/01	EPA -8015M/8020M	
Benzene	ND	0.0050	"	и		11	n	н	
Toluene	ND	0.0050	"	11	tt	41	n	11	
Ethylbenzene	ND	0.0050	*		Ħ	**	н	4	
Xylenes (total)	ND	0.0050	н		ti	H	n	•	
Methyl tert-butyl ether	ND	0.050	н	**	11		11	#	
Surrogate: a,a,a-Trifluorotoluen	e	106 %	65	135	"	"	#	*	
Surrogate: 4-Bromofluorobenzei		96.5 %	65-	135	tf.	"	н	"	
S-5-MW7 (P109015-10) Soil	Sampled: 08/29/01 14:45	Received:	09/04/01	15:50				•	
Gasoline (C6-C12)	ND	1.0	mg/kg	1	1090037	09/05/01	09/05/01	EPA 8015M/8020M	
Benzene	ND	0.0050	"	11	и	II	1P	н	
Toluene	ND	0.0050	н	н	*	п	m	11	
Ethylbenzene	ND	0.0050		н		Ħ	n	н	
Xylenes (total)	ND	0.0050	n	11		16		11	
Methyl tert-butyl ether	ND	0.050		"	H	11	11	#	
Surrogate: a,a,a-Trifluorotoluen	e	105 %	65-	135	"	#	11	"	
Surrogate: 4-Bromofluorobenzer		96.8 %	65-	135	,,	"	**	"	



73 Digital Dr. Suite 100

Novato CA, 94949

Project: TOSCO Project Number: 1156, Oakland Project Manager: Paul Blank

Reported: 09/19/01 14:04

Total Petroleum Hydrocarbons as Gasoline and BTEX by EPA 8015M/8020M Sequoia Analytical - Petaluma

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
S-10-MW7 (P109015-11) Soil S	ampled: 08/29/01 14:50	Received	: 09/04/01	15:50					· · · · · · · · · · · · · · · · · · ·
Gasoline (C6-C12)	ND	5.0	mg/kg	5	1090037	09/05/01	09/05/01	EPA 8015M/8020M	
Benzene	0.18	0.025	41	**	•	n	*	•	
Toluene	ND	0.025	Ħ	#		#	я	•	
Ethylbenzene	0.085	0.025	Ħ	н	**	H	•		
Xylenes (total)	0.34	0.025	н	-	-	II .	*	þ	
Methyl tert-butyl ether	ND	0.25	н	-	n	*	н	n	
Surrogate: a.a.a-Trifluorotoluene		102 %	65-	135	"	a	*	м	
Surrogate: 4-Bromofluorobenzene		102 %	65-	135	, .	et	*	*	
S-SP1-(1-4) (P109015-15) Soil S	Sampled: 08/29/01 16:00	Receive	d: 09/04/0	1 15:50					
Gasoline (C6-C12)	ND	1.0	mg/kg	1	1090037	09/05/01	09/05/01	EPA 8015M/8020M	
Benzene	0.0051	0.0050	"	**	Ħ	11		n	
Toluene	ND	0.0050		н	H		•	j u	
Ethylbenzene	0.0075	0.0050		Ħ	Ħ	#1	Ħ	n	
Xylenes (total)	0.031	0.0050		Ħ	H	*	n	. 4	
Methyl tert-butyl ether	0.062	0.050	"	н	н		n	11	
Surrogate: a,a,a-Trifluorotoluene		104 %	65-1	135	"	,	"	H	
Surrogate: 4-Bromofluorobenzene		97.7 %	65-1	35	tt	"	"	*	



1455 McDowell Blvd, North Ste D Petaluma, CA 94954 (707) 792-1865 FAX (707) 792-0342 www.sequoialabs.com

ERI

73 Digital Dr. Suite 100 Novato CA, 94949 Project: TOSCO

Project Number: 1156, Oakland

Reported: 09/19/01 14:04

Project Manager: Paul Blank

Total Metals by EPA 6000/7000 Series Methods

Sequoia Analytical - Petaluma

Analyte	R Result	Leporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
S-SP1-(1-4) (P109015-15) Soil	Sampled: 08/29/01 16:00	Receive	d: 09/04/	1 15:50					
Lead	ND	5.5	mg/kg	1	1090090	09/06/01	09/12/01	EPA 6010B	



1455 McDowell Blvd, North Ste D Petaluma, CA 94954 (707) 792-1865 FAX (707) 792-0342 www.sequoialabs.com

ERI

73 Digital Dr. Suite 100 Novato CA, 94949 Project: TOSCO

Project Number: 1156, Oakland Project Manager: Paul Blank Reported:

09/19/01 14:04

Volatile Organic Compounds by EPA Method 8260B

Sequoia Analytical - Petaluma

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
S-SP1-(1-4) (P109015-15) Soil Sam	pled: 08/29/01 16:0	0 Receive	d: 09/04/01	15:50					<u>. </u>
Methyl tert-butyl ether	0.025	0.0050	mg/kg	. 1	1090167	09/12/01	09/12/01	EPA 8260B	
Surrogate: Dibromofluoromethane	_	88.0 %	80-12	20	ir		н	*	



ERI

Project: TOSCO

73 Digital Dr. Suite 100 Novato CA, 94949 Project Number: 1156, Oakland Project Manager: Paul Blank

Reported: 09/19/01 14:04

Total Petroleum Hydrocarbons as Gasoline and BTEX by EPA 8015M/8020M - Quality Control Sequoia Analytical - Petaluma

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch 1090037 - EPA 5030, soils			,							
Blank (1090037-BLK1)				Prepared a	& Analyz	ed: 09/05/	01			
Gasoline (C6-C12)	ND	1.0	mg/kg				•		· · · · · · · · · · · · · · · · · · ·	
Benzene	ND	0.0050	*							
Toluene	ND	0.0050								
Ethylbenzene	ND	0.0050	*							
Xylenes (total)	ND	0.0050	*							
Methyl tert-butyl ether	ND	0.050								
Surrogate: a,a,a-Trifluorotoluene	0.620		"	0.600		103	65-135	<u>-</u>	-	
Surrogate: 4-Bromofluorobenzene	0.608		n	0.600		101	65-135			
LCS (1090037-BS1)				Prepared &	& Analyze	ed: 09/05/0	01			
Gasoline (C6-C12)	5.15	1.0	mg/kg	5.50		93.6	65-135			
Benzene	0.0846	0.0050	п	0.0660		128	65-135			
Toluene	0.406	0.0050	**	0.397		102	65-135			
Ethylbenzene	0.0895	0.0050	#	0.0920		97.3	65-135			
Xylenes (total)	0.493	0.0050	H	0.461		107	65-135			
Methyl tert-butyl ether	0.141	0.050	π	0.105		134	65-135			
Surrogate: a,a,a-Trifluorotoluene	0.625		"	0.600		104	65-135			
Surrogate: 4-Bromofluorobenzene	0.626		"	0.600		104	65-135			
Matrix Spike (1090037-MS1)	So	urce: P10901	15-05	Prepared &	& Analyze	d: 09/05/0)1			
Gasoline (C6-C12)	5.16	1.0	mg/kg	5.50	ND	92.8	65-135			
Benzene	0.0728	0.0050	41	0.0660	ND	110	65-135			
Toluene	0.433	0.0050	Ħ	0.397	ND	109	65-135		•	
Ethylbenzene	0.0952	0.0050	н	0.0920	ND	103	65-135			
Xylenes (total)	0.521	0.0050	н	0.461	ND	113	65-135			
Methyl tert-butyl ether	0.131	0.050	н	0.105	ND	125	65-135			
Surrogate: a,a,a-Trifluorotoluene	0.629		H	0.600		105	65-135			
Surrogate: 4-Bromofluorobenzene	0.594		,,,	0.600		99.0	65-135			



EDI

73 Digital Dr. Suite 100 Novato CA, 94949 Project: TOSCO

Project Number: 1156, Oakland Project Manager: Paul Blank Reported:

09/19/01 14:04

RPD

%REC

Total Petroleum Hydrocarbons as Gasoline and BTEX by EPA 8015M/8020M - Quality Control Sequoia Analytical - Petaluma

Reporting

Spike

Source

Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes
Batch 1090037 - EPA 5030, soils										
Matrix Spike Dup (1090037-MSD1)	Sou	rce: P10901	15-05	Prepared d	& Analyz	ed: 09/05/	01			
Gasoline (C6-C12)	5.10	1.0	mg/kg	5.50	ND	91.7	65-135	1.17	20	
Benzene	0.0747	0.0050	•	0.0660	ND	113	65-135	2.58	20	
Toluene	0.449	0.0050		0.397	ND	113	65-135	3.63	20	
Ethylbenzene	0.0979	0.0050	н	0.0920	ND	106	65-135	2.80	20	
Xylenes (total)	0.532	0.0050	н	0.461	ND	115	65-135	2.09	20	
Methyl tert-butyl ether	0.122	0.050	н	0.105	ND	116	65-135	7.11	20	
Surrogate: a,a,a-Trifluorotoluene	0.640		**	0.600		107	65-135			
Surrogate: 4-Bromofluorobenzene	0.596		n	0.600		99.3	65-135			



1455 McDowell Bivd, North Ste D Petaluma, CA 94954 (707) 792-1865 FAX (707) 792-0342 www.sequoialabs.com

ERI

73 Digital Dr. Suite 100 Novato CA, 94949 Project: TOSCO

Project Number: 1156, Oakland Project Manager: Paul Blank

Reported:

09/19/01 14:04

Total Metals by EPA 6000/7000 Series Methods - Quality Control Sequoia Analytical - Petaluma

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch 1090090 - EPA 3050B										
Blank (1090090-BLK1)				Prepared:	09/06/01	Analyzed	: 09/12/01		•	
Lead	ND	7.5	mg/kg							
LCS (1090090-BS1)				Prepared:	09/06/01	Analyzed	: 09/12/01			
Lead	45.6	7.5	mg/kg	50.0		91.2	80-120			
Matrix Spike (1090090-MS1)	Sou	rce: P10900	6-01RE1	Prepared:	09/06/01	Analyzed	: 09/12/01	÷		
Lead	55,0	6.9	mg/kg	46.3	11	95.0	75-125			
Matrix Spike Dup (1090090-MSD1)	Sou	rce: P10900	6-01RE1	Prepared:	09/06/01	Analyzed	. 09/12/01			
Lead	49.6	6.1	mg/kg	41.0	11	94.1	75-125	10.3	35	



PDI

73 Digital Dr. Suite 100 Novato CA, 94949 Project: TOSCO

Project Number: 1156, Oakland Project Manager: Paul Blank Reported: 09/19/01 14:04

ounds by FDA Mathod 9260B Quality Cantral

Volatile Organic Compounds by EPA Method 8260B - Quality Control Sequoia Analytical - Petaluma

**		D		Cariles	Source	•	%REC		RPD	
Analyte	Result	Reporting Limit	Units	Spike Level	Result	%REC	Limits	RPD	Limit	Notes
Batch 1090167 - EPA 5030 soils										
Blank (1090167-BLK1)				Prepared &	k Analyz	ed: 09/12/	01			
Methyl tert-butyl ether	ND	0.0050	mg/kg							
Surrogate: Dibromofluoromethane	0.0440		#	0.0500		88.0	80-120			
Blank (1090167-BLK2)				Prepared &	& Analyz	ed: 09/17/	01			
Methyl tert-butyl ether	ND	0.0050	mg/kg							
Surrogate: Dibromofluoromethane	0,0436		ħ	0.0500		87.2	80-120			
LCS (1090167-BS1)				Prepared d	& Analyz	ed: 09/12/	01			
Methyl tert-butyl ether	0.0525	0.0050	mg/kg	0.0500		105	76-124			
Surrogate: Dibromofluoromethane	0.0440	<u> </u>	*	0.0500		88.0	80-120			
LCS (1090167-BS2)				Prepared &	& Analyz	ed: 09/17/	01			
Methyl tert-butyl ether	0.0528	0.0050	mg/kg	0.0500		106	76-124			
Surrogate: Dibromofluoromethane	0.0436		"	0.0500		87.2	80-120			
Matrix Spike (1090167-MS1)	Sc	ource: P1090	91-03	Prepared &	k Analyz	ed: 09/17/	01		-	
Methyl tert-butyl ether	0.126	0.0050	mg/kg	0.125	ND	101	76-124			
Surrogate: Dibromofluoromethane	0.112		,,	0.125		89.6	80-120			
Matrix Spike Dup (1090167-MSD1)	Sc	ource: P1090	91-03	Prepared &	k Analyz	ed: 09/17/	01			
Methyl tert-butyl ether	0.126	0.0050	mg/kg	0.125	ND	101	76-124	0.00	35	
Surrogate: Dibromofluoromethane	0.113		"	0.125		90.4	80-120			



1455 McDowell Blvd, North Ste D Petaluma, CA 94954 (707) 792-1865 FAX (707) 792-0342 www.sequoialabs.com

ERI

73 Digital Dr. Suite 100 Novato CA, 94949 Project: TOSCO

Project Number: 1156, Oakland

Project Manager: Paul Blank

Reported:

09/19/01 14:04

Notes and Definitions

DET

Analyte DETECTED

ND

Analyte NOT DETECTED at or above the reporting limit

NR

Not Reported

dry

Sample results reported on a dry weight basis

RPD

Relative Percent Difference

TOSCO

☐ 819 Striker Ave., Suite 8 • Sacramento, CA 95834 • (916) 921-9600 FAX (916) 921-0100 ☐ 404 N. Wiget Lane • Walnut Creek, CA 94598 • (925) 988-9600 FAX (925) 988-9673 ☐ 1455 McDowell Blvd. North, Suite D • Petaluma, CA 94954 • (707) 792-1865 FAX (707) 792-0342 ☐ 1551 Industrial Road • San Carlos, CA 94070 • (650) 232-9600 FAX (650) 232-9612

Consultant Company:	ERT					Project	Name	: 22	350	03 T	5		The second se	, and the same	
	isital Or	Ste	100)		TOSCO) Engir	neer (re	equired) Da	ve Do	. Wit			
City: Novato	State:	CA			14949										-
Telephone: 415 -		5 F/	x #:41	5-38	2-1856	Site #,	City, S	táte: (表	115	6 Oal	Vard, LA	Client
Report To: Paul	Blank	Sampler:	Rob S	rus		QC Da					Level (J Level A	<u>.</u>
Turnaround (X 10 Work		Work Days Work Day		3 Work Da 2-8 Hours		nking Wa			//		Analyses	Reque	ested		Pink - (
CODE: • Misc. •	Detect. 🚨 Eval.	☐ Remed.	□ Demol.	□ Clos	ure 🗆 Oth	er	T S He	Sa Maria		JE Wed. Co	Sales IS.	in g.	//	/	
Client Sample I.D.	Date/Time Sampled	1	# of Cont.	Cont. Type	Sequoia's Sample #	Ŕ	HER BITS HE	LEP ROOM	E REPRESENT	EP BUS HELD	on the country of the			Comments	3
1.5-5-MW5	8/29/01930	Sil		aso leave	Polices		\propto	\times			\times			•	<u>ā</u>
2.5-10-MW5	1 935		1	1		1							1	told	Secuoia
3.5-15-MWS	940				o	= ∵							J.	Held	
4.5 24 - MW5	950				•	Ľ.								told	Yellow
6.5.5. MW6	1205					<u>5</u>	\searrow	\geq			\times			,	۶ ا
6.5-10-MWG	1310				0	ERC		W GE	ISIN	TACT	3				
4.5-15-MW6		-			CO(7	USIOL		TYPIN	TACT					
8.5-20-MW6	1230			1/	Ö										
9.5-24-WW6	V 1225	V	V	V	cő	TER T	EMPE	RATU	RE			ļ		told	<u></u> .g
10.								<u> </u>		\searrow					
Relinquished By:	Politan		Date: 8	1/5/101	Time: ()60	Re	celved	By				Däle: 🦸	74.4	Time:////	
Relinquished By:			Date:		arimer	Re	ceived	By:	mm. vagasamna m		,	Date:		Time:	<u> </u>
Relinquished By:	er tig		Dafe:	B. C.	Time:	Ŕe	ceived	В у:	*******	manufact. Man		Date:	BIRTH Booklean combined at	Time:	
Were Samples Received	In Good Condition	? □Yes 0	3 No	San	ples on ice?	☐ Yes	□ No	Meth	od of Si	hipment				Page of _	
To be completed upor 1) Were the analy 2) Was the repor	yses requested o	n the Chair	of Custo	ody repor	ted? 🗅 Yes	es 🗀 i					tre still ne				
Annoved by	Cloaned Ailthi II	o i adrinate.		opature:	162	- 140	ii iiQ		was m mnany:		iound am	o:		Date:	

MY UUZAYS

TOSCO

□ 819 Striker Ave., Suite 8 • Sacramento, CA 95834 • (916) 921-9600 FAX (916) 921-0100 2 404 N. Wiget Lane • Walnut Creek, CA 94598 • (925) 988-9600 FAX (925) 988-9673 □ 1455 McDowell Blvd. North, Suite D • Petaluma, CA 94954 • (707) 792-1865 FAX (707) 792-0342 □ 1551 Industrial Road • San Carlos, CA 94070 • (650) 232-9600 FAX (650) 232-9612

Consultant Company: ERI			Project Name: 227	350375		
Address: 73 Digital I	dr. Ste 100	aire -	TOSCO Engineer (re	quired) Dave 1	De Witt	
	e: Ž Zip Cod	ie: 94949				
Telephone: 415-382-9105		382-1856	Site #, City, State:	113, Oakland	LA	
Report To: Paul Blank	Sampler: Rol		QC Data: Level i			IB 🗆 Level A
	D 5 Work Days □ 3 World Day □ 2-8 H		inking Water	Analyse	s Requested	7 7
CODE: Misc. Detect. Deval	. 🗆 Remed. 🗅 Demol. 🗅 🤆	Closure 🗅 Oth	her Sund See 1	Shed the shift feet	CHANGE TO THE CHANGE T	
Client Date/Time Sample LD. Sampled	Matrix # of Cont Desc. Cont. Type	Sample #	her RH EP BILL REP BEE	Brace Price and Departs of the	and the second	Comments
1.5-5-MWJ 8/29/01/74	5 Soil 1 Brass	ve Planous-11				
2.5-10-MW7 1757		4				
3.5-15-MW7 175	5		2			Hold
4.5-20 MW7 150	0	**				Hold
5.5-24-14W7 150			4			Hold
6.5-5P1-(11-4) V 160	10 V 4 V	- 12 0				Composite
7.	COOLER CUSTODY SI	EALS ENTACT				
8.		NOT INTACT				
9.	COOLER TEMPERATA	/				
10.			TC /			
Relinquished By: Relinquished By:	Date: 3/34	6) Time: 000	Received By		Date 4	Time: //20
Relinquished By:	Date	Time:	Received By:		Date:	Time:
Relinquished By:	Dete	Time:	Received By:	· · · · · · · · · · · · · · · · · · ·	Date:	Time:
Were Samples Received in Good Conditi	on? □ Yes □ No	Samples on Ice?	☐ Yes ☐ No Metho	d of Shipment		Page of
To be completed upon receipt of rep 1) Were the analyses requested 2) Was the report issued within	d on the Chain of Custody re			at analyses are still ne		
Approved by:	Signati		•	pany:	···	Defe-

ATTACHMENT G SOIL SAMPLE LOCATIONS AND ANALYTICAL RESULTS

TABLE 1
SAMPLE ANALYSIS RESULTS OF SOIL AND GROUNDWATER

Tosco (Union) 76 Service Station 1156 4276 MacArthur Boulevard Oakland, California (Page 1 of 2)

Sample #	Depth	Date	ТЕРНа	ТРРН	В	Ť	E	х	TRPH	TTLC Lead	SVOC's	HVOC's
FUEL USTS - S	OIL				··			·		LANG		
S-6-T1N	6.0	3/23/98	NA	1,200	0.90	NĎ	14	100	NA	6.8	NA	NA
S-9.5-T1S	9.5	3/23/98	NA	590	1.5	ND	5.6	33	NA	NA	NA	NA
S-7-T2S	7.0	3/23/98	NA	670	1.0	0.74	6.8	51	NA	NA	NA	NA
S-6-T2N	6.0	3/23/98	NA	83	ND	ND	0.15	0.41	NA	NA	NA	NA
DISPENSERS -	SOIL											
S-2-D1	2.0	4/9/98	NA	ND	ND	ND	ND	ND	NA	NA	NA	NA
.S-3-D2	3.0	4/9/98	NA	16	ND	ND	ND	0.13	NA	NA .	NA	NA
S-3-D3	3.0	4/9/98	NA	590	1.6	15	18	99	NA	110*	NA	NA
S-3-D4	3.0	4/9/98	NA	ND	ND	ND	ND	0.070	NA	NA	NA	NA
PRODUCT LIN	ES - SOIL			4		•						
S-3-PL1	3.0	4/9/98	NA	160	ND	ND	ND	8.4	NA	NA	NA	NA
S-3.5-PL2	3.5	4/9/98	NA	63	ND	ND	ND	0.45	NA	NA	NA	NA
USED - OIL US	T - SOIL											
S-6.5-T35	6.5	3/23/98	78,000	130	0.55	1.3	1.2	11	8,400	7.2	ND	ND**
S-4.5-T3W	4.5	4/9/98	2.3	5.0	ND	0.066	ND	0.011	ND	ND	ND	ND
S-3-T3S	3.0	4/9/98	ND	1.6	0.043	ND	0.0091	ND	ND	ND	ND	ND
S-6-T3S	6.0	4/9/98	560	81	0.64	1.4	1.1	5.9	360	ND	ND***	ND
FUEL UST CA	VITY- WATE	R										
W-7.5-T2	7.5	3/23/98	NA	41,000	ND	400	770	8,900	NA	NA	NA	NA
STOCKPILE												
SP-1-(1-4)	NA	4/3/98	NA	15	0.024	0.034	0.024	0.069	NA	16	NA	NA
SP-1-(5-8)	NA	4/3/98	NA	3.2	0.013	ND	ND	0.014	NA	12	NA	NA
SP-2-(1-4)	NA	4/3/98	ŊA	13	0.076	ND	0.019	0.060	NA	5.0	NA	NA
SP-2-(5-8)	NA	4/3/98	ŇA	42	0.19	ND	0.11	0.60	NA	5.4	NA.	NA.
SP-2-(9-12)	NA	4/3/98	NA	15	0.19	ND	0.034	0.092	NA	ND	NA.	NA.
SP-2-(13-16)	NA	4/3/98	NA	41	0.66	16.0	0.42	2.2	NA	ND	NA.	NA.
SP-2-(17-20)	NA	4/3/98	NA	10	0.036	0.027	0.013	0.058	NA	ND	NA.	NA.
SP-3-(1-4)	NA	4/9/98	290	12	0.13	0.027	0.094	0.53	570	30	ND	ND
SP-4-(A-10)	NA	4/9/98	NA	19	0.0076	0.058	0.068	0.40	NA	10	NA	NA

TABLE I SAMPLE ANALYSIS RESULTS OF SOIL AND GROUNDWATER

Tosco (Union) 76 Service Station 1156 4276 MacArthur Boulevard Oakland, California (Page 2 of 2)

					· · · · · · · · · · · · · · · · · · ·							
Sample #	Depth	Date	TEPHd	TPPHg	В	Ť	E	x	TRPH	TTLC	SVOC's	HVOC's
										Lead		

Notes:

Soil results (S) in milligrams per kilogram (mg/kg) unless otherwise noted.

Water results (W) in micrograms per liter (ug/L).

ug/kg	-	rograms per liter
TEPHd	-	s as diesel analyzed using modified EPA method 8015.
TPPHg	-	s gasoline analyzed using modified EPA method 8015.
BTEX	-	Total Xylenes analyzed using EPA method 8020.
TRPH	-	carbons analyzed using EPA method 5520 E&F.
TTLC Lead	*	on of lead analyzed using EPA method 6010.
STLC Lead	=	tion of lead analyzed using EPA method 6010.
SVOC's	-	ounds analyzed using EPA method 8270.
HVOC's	=	mpounds analyzed using EPA method 8010.
NA	=	lyzed/Not Applicable
ND	=	Not detected
*	200	sis: STLC Lead = 8.0 mg/L
**	-	cis-1,2-Dichloroethene = 56 ug/kg
***	-	thalene = 580 ug/kg; Naphthalene = 500 ug/kg

Additional Analyses:

Sample S-6.5-T3S analyzed for TTLC Cadmium = ND; Chromium = 50 mg/kg; Nickel = 64 mg/kg; Zinc = 52 mg/kg using EPA method 6010.


Sample S-4.5-T3W analyzed for TTLC Cadmium = ND; Chromium = 22 mg/kg; Nickel = 70 mg/kg; Zinc = 22 mg/kg using EPA method 6010.

Sample S-3-T3S analyzed for TTLC Cadmium = ND; Chromium = 37 mg/kg; Nickel = 34 mg/kg; Zinc = 34 mg/kg using EPA method 6010.

Sample S-6-T3S analyzed for TTLC Cadmium = ND; Chromium = 27 mg/kg; Nickel = 25 mg/kg; Zinc = 27 mg/kg using EPA method 6010.

Sample SP-3-(1-4) analyzed for TTLC Cadmium = ND; Chromium = 35 mg/kg; Nickel = 40 mg/kg; Zinc = 42 mg/kg using EPA method 6010.

Sample W-7.5-T2 analyzed for methyl tertiary butyl ether = 1,800 ug/L using EPA method 8020.



ERI ENVIRONMENTAL RESOLUTIONS, INC.

GENERALIZED SITE PLAN

TOSCO (UNION) 76 SERVICE STATION 1156 4276 MacArthur Boulevard Oakland, California PROJECT NO.

2235 PLATE

2 October 22, 1997

TABLE 1 ANALYTICAL RESULTS of SOIL SAMPLES (TEPHd, TPPHg, TRPH, MTBE, 5-CAM Metals) Tosco 76 Service Station 1156


Tosco 76 Service Station 1156 4276 MacArthur Boulevard Oakland, California

		Date	TEPHd	TRPH	TPPHg	MTBE	В	т	E	x		5-	CAM METAL	S	
Sample Number	Plate Call-out	Sampled	11,1111			WIIDE		•	<i>L</i>	Α	Pb	Cd	Cr	Ni	Zr
		- Campino	≺					ppm			*****************		*********		>
Soft - Borings															
S-10.5-B1	MWi	7/16/99	140	73	6,800	ND*	2.6	25	110	470	NA	NA	NA	NA	NA
S-10.5-B2	MW2	7/16/99	NA	NA	ND	ND	ND	ND	ND	ND	NA	NA	NA	NA	N/
S-10.5-B3	MW3	7/16/99	NA	NA	16	0.36	0.32	0.43	0.28	1.8	NA	NA	NA	NA	N.A
S-10.5-B4	MW4	7/16/99	NA	NA	22	0.71	1.1	0.32	0.46	1.3	NA	NA	NA	NA	NA
S-20.5-B4	MW4	7/16/99	ND	ND	ND	ND	ND	ND	0.0069	NA	NA	NA	NA	NA	NA
Soil-Stockpiles															
Comp SP1-(1-4)		7/16/99	19	NA	58	ND*	0.074	0.20	0.52	3.7	26	ND	23	28	41
es:								- -							
TPPHg	-	Total purges	ble petroleun	hydrocarbon	s as gasoline an	alyzed using EPA	Method 8015/8	020 modified.							
TEPHd	#	Total extrac	able petroleu	m hydrocarbo	ns as diesel anal	yzed using EPA	Method 3550/80	15 modified.							
TRPH	-	Total recove	rable petroiet	m hydrocarbo	ons as oil analyz	ed using EPA M	ethod 5520 E&F	ì.							
ppm	=	Parts per mi	llion.			-									
S-10.5-B1	-	Soil Sample	depth in feet-	Boring 1.					•						
Comp SP1-(1-4)	=	Stock Pile 1	, 1 through 4	composite sar	nples.										
ND	-	Not detected	l at or above l	aboratory rep	orting limit.							•			
		Not Analyze	ed.										•		
NA	-	INOU WITHING													
	-	•		r analyzed usi	ng EPA Method	18015/8020 mod	lfied .								
NA		Methyl terti	ary butyl ethe			1 8015/8020 mod /zed using EPA 1		20 modified.							
NA MTBE	-	Methyl terti Benzene, to	ary butyl ethe hene, ethylbe	nzene, and to	tai xylenes analy		viethod 8015/80	20 modified.							

TABLE 2 ANALYTICAL RESULTS OF SOIL SAMPLES (HVOCs and SVOCs)

Tosco 76 Service Station 1156 4276 MacArthur Boulevard Oakland, California

				HVOCS		SVOCs	· _ · _		
Sample Number	Plate Call-out	Date Sampled	Chlorobenzene	1,2-Dichlorobenzene	1,4-Dichlorobenzene	2-Methylnaphthalene	Naphthalene		
	<u></u>		<>						
Soil - Borings									
S-10.5-B1	MW1	7/16/99	0.70	0.87	0.38	12	6.4		
S-10.5-B2	MW2	7/16/99	NA	NA	NA	NA	NA		
S-10.5-B3	MW3	7/16/99	NA	NA	NA	NA	NA		
S-10.5-B4	MW4	7/16/99	NA	NA	NA	NA	NA		
S-20.5-B4	MW4	7/16/99	NA	NA	NA	NA	NA		
Soil-Stockpiles									
Comp SP1-(1-4)		7/16/99	ND	0.077	ND	ND	ND		
Notes:									
ppm	=	Parts per millio	m.						
S-10.5-B4	-	Soil Sample-de	pth in feet-Boring	4.	•				
Comp SP1-(1-4)	=	Stock Pile 1, 1	through 4 compos	site samples.					
HVOCs	•	Halogenated vo	olatile organic com	pounds analyzed using E	PA Method 8010.				
SVOCs	-	Semi-volatile o	rganics compound	s analyzed using EPA M	ethod 8270.				
ND	**	Not detected at	or above laborate	ry reporting limit.					
Plate call out	-	MW1 (Monitor	ring Well 1).						
_	=	Not applicable							
NA	=	Not Analyzed.							



ASOOCESS NT

EXPLANATION

MW4

�

Groundwater Monitoring Well

Groundwater Elevation Relative to Mean Sea Level 171.70

i = Interpreted Groundwater Gradient

Analytical results for Toluene, Ethylbenzene, and Total Xylenes are presented in Table 2.

Groundwater Concentrations in ppb.

Sampled July 20, 1999

Total Purgeable Petroleum Hydrocarbons 120,000

as Gasoline

11,000 Benzene
NO Methyl Tertiary Butyl Ether (MTBE)
16,000 Total Extractable Petroleum Hydrocarbons

as Diesel Not Detected At or Above the Laboratory

Method Detection Limit NA Not Analyzed

MTHE confirmed using EPA Method 8260
Total Recoverable Petroleum Hydrocarbons,
Haiogenated Volatile Organic Compounds, and
Semivolatile Organic Compounds Analytical
Results are presented in Table 2
Parts Per Billion

GENERALIZED SITE PLAN

ND

ENVIRONMENTAL RESOLUTIONS, INC.

TOSCO 76 SERVICE STATION 1156 4276 MacArthur Boulevard Oakland, California

PROJECT NO.

2235

PLATE

2

September 9.

ATTACHMENT H SOIL DISPOSAL CONFIRMATION



Hazardous Wasie Hauler (Registration #2843)

8896 Elder Creek Rd. - Sacramenio, CA 95828 - FAX (916) 381-1573


Disposal Confirmation

Request for Transportation	on Received:		10/5/01
·	Consult	ant Information	
Company: Contact;	ERI Rob Saur		· · · · · · · · · · · · · · · · · · ·
Phone:	415-382-3591		
Fax:	415-382-1856		
	Site	Information	-
Station #:	Tosco #1156		
Street Address:	4276 MacArthur	Blvd	
City, State, ZIP:	Oakland, CA		
Customer:	Tos	300	
Environmental Engineer: Fax:			
Material Description:	Soil		
Estimated Quantity:	5 Tons	· · · · · · · · · · · · · · · · · · ·	
Service Requested Date:	10/5/01		
Disposal Facility:	Forward Landfill	•	
Contact:	Brad Bonner		
Phone:	209-982-4298		***************************************
Approval #:	1202		
Date of Disposal:	10/8/01	- <u> </u>	
Actual Tonnage	1.45 Tons		
Transporter:	Manley & Sons	Trucking Inc	
Contact:	Glenell Forbes	110011119, 1110.	
Phone:	916 381-6864		
Fax:	916 381-1573	<u> </u>	
Invoice:	50005	· · · · · · · · · · · · · · · · · · ·	
Date of Invoice:	10/11/01		
Fax To: Consult	ant	Engineer	Unocal

Engineer

Unocal

ATTACHMENT I RESULTS OF GROUNDWATER RECEPTOR SURVEY



Contact Site Administrator | Road Maps by ETAK
Well and LUFT site positions are approximate. Locational accuracy will improve as state agencies and responsible parties obtain
and report new information.

TOSCO UNION 76 (OAKLAND 4276 MACARTHUR BLVD OAKLAND , CA 94602 (Show this Site on Map)	SAN	I Agency (lead agen	RWOCB (REGION 2) - (CTH)	
Water System Name	Water System ID	Well Name	Common Well Name	Dist To LUFT
PANY RANG MENTANGEN WE I WAS A	npoyasiji	(1/12-1911) (1/12)	TERATRIPORUPE PRIMINEY	The same
EAST BAY REGIONAL PARK DISTRCT	0707642	0707642-001GEN	LPA REPORTED PRIMARY SOURCE	1615 Feet
() 1507 超高压物器 PARK	ONO OSEK	uzura annus inst	THE BUILDING PRINCESS OF STREET	用。
EASY BAY REGIONAL PARK DISTRCT	0707644	0707644-001GEN	LPA REPORTED PRIMARY SOURCE	1615 Fee

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

Job #1607. Mills College, Oakland. Well

LOG OF WELLS

Yellow cementy clay 20	feet	
Loose gravel, some water 20 to 24	u	
Yellow comenty gravel 24 " 36	**	
Blue cementy gravel 36 " 44	99	
Yellow cementy gravel 44 " 52		
Yellow gravel 58 " 72	17	
Cementy gravel, yellow 78 " 84		
Yellow clay with cwarel bearing of a soc		
Nellow clay with gravel 84 " 120 Blue clay 120 " 138		2
Volley along with annual		
Yellow clay with gravel 138 " 140 Sticky yellow clay 140 " 180 Red clay with gravel, (Dry) 180 " 188		
priory Action cray 180 180		
med clay with gravel, (Dry) 180 " 188	- 11	
iellow samy clay 188 " 215	11	
Yellow cement gravel 213 " 224	17 ,	
Hard cement gravel, dry 224 " 232	_π Π	3
Yellow sandy clay 232 " 288	11	
Yollaw sandy clay with gravel, dry 288 " 330	TT	
Brown sticky clay 330 " 347	17	
Brown sticky clay 330 " 347 Brown cement gravel 347 " 358	11	
	547	

352 feet of 12" No. 12 Red Hard Double Steel Casing including Starter 20 feet long with No. 10 Shoe. 30 feet of machine perforations.

Extra Perforations 24° to 42° 70° 70° 70° 100°

Kiva Well, Mills College. Bored by H. W. Norman, Foreman, John Reiber.


LOG OF WELL.

Dark soil8	
Cement gravel 8 to25	feet
Loose rock & many	77
Loose rock & gravel 25 " 50	34
Yellow clay 50 * 80	99
Gray clay 80 " 98	10
Cement gravel	
10110F () 8A 00000000000000000000000000000000000	
Cement gravel	- 7
Water gravel 135 *145	11.0
MAN AAMANA AMANA?	7
70 11 OW A1 OW	
Cement crave 1	
Cement gravel 175 "200	19
Yellow olay 200 "214	10
Water gravel 214 *220	31
Sandy clay 220 man	79
Fine sand 240 M250	19
lellow sandy clay PEO HPRO	17
Cement gravel 280 306	₩
Fine sand & water gravel 306 w319	11 37
V-11	7 11
Con at the second of	
Vallim at an	11
10110W C18y 351 *354	₩

237 ft. 12" No. 12 R. H. Double casing, including starter and shoe. 126 ft. 10" No. 14 R. H. Dbl. Casing inc. Shoe 42 feet of machine perforations, 10" Casing.

Perforated 25" to 51" - 12" Casing.

Work done by H. W. Norman, Cut-Rate Well Borer,
I WILL SAVE YOU MONEY.



coupty		DEPARTMENT OF WATER RESC	DWN No.	25	13w-
NEAR			ОТНЕЯ Н	00_/	-5- 10 100
		WELL LOG			
LOCATION	MILLS CO	OLLEGS JOB on 64th Avenue			
DWNER		ADDRESS			
DRILLED BY		ADDRESS			
PRILLING METHO	D0				X
		GRAVEL PACKED DATE COM			
TE OF CABING	DEPTH	STRUCK WAT	ER AY.		
ERFORATIONS_		SIZE			Wo
VATER LEVEL DE	FORE PERFORAT	TINGAFTER			
KOT DATA: DISC	HARGE G. P. N.				
			HOUR	RUN	
		LEYEL RECORD			
URFACE ELEY		DATUMSOURCE OF INFORMATION			
DEPTH	ELEV. OF BOTTOM OF STRATUM		THICK	SP.	i -
0 - 6		Black adobe	NESS	YIELD	
0 - 9	+	Sam Sram clay	_		
2 - 21		TOW Clay			
23 - 50	-	harr vellow clay emall most -th	1 -		
	-		Olay		
The state of the s	-	The same and the s		\vdash	
53 -66		101 6121		\vdash	
		and mayel and mid with a		-	
65 - 32					
82 - 97		Sort direty Pine charact			
82 - 97 87 - 91		1 no charta			
82 = 97 87 = 91 91 = 98		ined conert clay and anamal			
82 = 97 67 - 91 91 = 98 98 = 101		Hard brown clay and gravel			
82 = 97 87 - 91 91 = 98 98 = 101 101 = 117		Hard brown clay			
82 = 97 87 - 91 91 - 98 98 - 101 101 - 117 117 - 127		Hard brown clay Soft brown sandy sediment			
87 - 97 87 - 91 91 - 98 98 - 101 101 - 117 117 - 127 127 - 136		Hard brown clay Soft brown sandy sediment Hard Gravel mix with clay no water in			
82 = 97 87 - 91 91 - 98 98 - 101 101 - 117 117 - 127		Hard brown clay Soft brown sandy sediment Hard Gravel mix with elay no water in Hard brown elay			
82 = 97 87 - 91 91 = 98 98 = 101 101 = 117 117 = 127 127 = 136 136 - 161		Hard brown clay Soft brown sandy sediment Hard Gravel mix with clay no water in Hard brown clay Hard coment gravel mix with clay Hard coment gravel mix with clay			
82 = 97 67 - 91 91 = 98 98 = 101 101 = 117 117 = 127 127 = 136 136 = 161		Hard brown clay Soft brown sandy sediment Hard Cravel mix with clay no water in Hard brown clay Hard coment gravel mix with clay Hard yellow clay incl coment gravel mix with clay			
82 - 97 87 - 91 91 - 98 98 - 101 101 - 117 117 - 127 127 - 136 136 - 161 161 - 164 164 - 169		Hard brown clay Soft brown sandy sediment Hard Cravel mix with clay no water in Hard brown clay Hard coment gravel mix with clay Hard yellow clay Hard yellow clay Hard yellow clay			
82 - 97 87 - 91 91 - 98 98 - 101 101 - 117 117 - 127 127 - 136 136 - 161 161 - 164 164 - 169		Hard brown clay Soft brown sandy sediment Hard Cravel mix with clay no water in Hard brown clay Hard coment gravel mix with clay Hard yellow clay Hard yellow clay Hard yellow clay Hard yellow clay			
82 = 97 87 - 91 91 - 98 98 - 101 101 - 117 117 - 127 127 - 136 136 - 1h1 117 - 164 164 - 169 169 - 187 187 - 190		Hard brown clay Soft brown sandy sediment Hard Crawel with with clay no water in Hard brown clay Hard coment gravel mix with clay Hard yellow clay Hard blue clay			
82 - 97 67 - 91 91 - 98 98 - 101 101 - 117 117 - 127 127 - 136 136 - 161 161 - 169 169 - 187 187 - 190 190 - 207		Hard brown clay Soft brown sandy sediment Hard Gravel mix with clay no water in Hard brown clay Hard coment gravel mix with clay Hard vellow clay Hard yellow clay Hard yellow clay Hard blue clay Hard blue clay			
82 - 97 67 - 91 91 - 98 98 - 101 101 - 117 117 - 127 127 - 136 136 - 111 111 - 164 164 - 169 169 - 187 187 - 190 190 - 207 207 - 208		Hard brown clay Soft brown sandy sediment Hard Gravel mix with clay no water in Hard Cravel mix with clay no water in Hard coment gravel mix with clay Hard yellow clay Hard yellow clay Hard yellow clay Hard blue clay Hard blue clay Hard yellow clay Hard blue clay Hard yellow clay Hard yellow clay Hard blue clay			
82 - 97 87 - 91 91 - 98 98 - 101 101 - 117 117 - 127 127 - 136 136 - 161 161 - 169 169 - 187 187 - 190 190 - 207 207 - 208 203 - 225		Hard brown clay Soft brown sandy sediment Hard Cravel mix with clay no water in Hard brown clay Hard coment gravel mix with clay Hard yellow clay Hard yellow clay Hard yellow clay Hard blue clay Hard blue clay Hard yellow clay Hard blue clay Hard yellow clay Hard blue clay Hard yellow clay			
82 - 97 87 - 91 91 - 98 98 - 101 101 - 117 117 - 127 127 - 136 136 - 161 161 - 169 169 - 187 187 - 190 190 - 207 207 - 208 203 - 225 225 - 236		Hard brown clay Soft brown sandy sediment Hard Cravel mix with clay no water in Hard brown clay Hard coment gravel mix with clay Hard coment gravel mix with clay Hard yellow clay Hard yellow clay Hard blue clay Hard blue clay Hard yellow sand Hard yellow clay Hard blue clay			
82 - 97 87 - 91 91 - 98 98 - 101 101 - 117 117 - 127 127 - 136 136 - 161 161 - 169 169 - 187 187 - 190 190 - 207 207 - 208 203 - 225 225 - 236 236 - 243		Hard brown clay Soft brown sandy sediment Hard Gravel mix with clay no water in Hard brown clay Hard coment gravel mix with clay Hard yellow clay Hard yellow clay Hard blue clay Hard blue clay Hard yellow clay Hard blue clay Hard yellow clay Hard blue clay			
82 - 97 87 - 91 91 - 98 98 - 101 101 - 117 117 - 127 127 - 136 136 - 161 161 - 169 169 - 187 187 - 190 190 - 207 207 - 208 203 - 225 225 - 236 236 - 263 263 - 261		Hard brown clay Soft brown sandy sediment Hard Gravel mix with clay no water in Hard brown clay Hard coment gravel mix with clay Hard yellow clay Hard yellow clay Hard blue clay Hard blue clay Hard yellow clay Hard blue clay Hard yellow clay Hard blue clay			
87 - 97 87 - 91 91 - 98 98 - 101 101 - 117 117 - 127 127 - 136 136 - 161 161 - 169 169 - 187 187 - 190 190 - 207 207 - 208 203 - 225 225 - 236 236 - 213 213 - 261 261 - 277		Hard brown clay Soft brown sandy sediment Hard Gravel mix with clay no water in Hard coment gravel mix with clay Hard coment gravel mix with clay Hard yellow clay Hard yellow clay Hard vallow clay Hard vallow clay Hard vallow clay Hard yellow clay Hard yellow clay Hard yellow clay Hard yellow clay Hard policy clay Hard rown clay			
82 - 97 87 - 91 91 - 98 98 - 101 101 - 117 117 - 127 127 - 136 136 - 161 161 - 169 169 - 187 187 - 190 190 - 207 207 - 208 203 - 225 225 - 236 236 - 263 263 - 261		Hard brown clay Soft brown sandy sediment Hard Cravel mix with clay no water in Hard brown clay Hard coment gravel mix with clay Hard coment gravel mix with clay Hard yellow clay Hard yellow clay Hard blue clay Hard blue clay Hard yellow sand Hard yellow clay Hard blue clay			