




PROPOSED BORING LOCATIONS

FORMER CHEVRON ALAMEDA BULK PLANT 2001 VERSAILLES AVENUE ALAMEDA, CALIFORNIA **FIGURE**

3

 PROJECT NO.
 DRAWN BY:
 DATE
 BASE MAP:

 chev-1
 AMD
 1/95
 KLEINFELDER





SITE PLAN FORMER CHEVRON ALAMEDA BULK PLANT 2001 VERSAILLES AVENUE ALAMEDA, CALIFORNIA

FIGURE

1

PROJECT NO.

DRAWN BY:

DATE


KLEINFELDER


BASE MAP:


chev-1


AMD

1/95









Jun 9/25/89 metries

INSPECTION OF CURRENT SITE CONDITIONS

The site was inspected by Earth Metrics staff in August and again in September, 1989. Salient observations are described as follows:

- <u>Drums</u>. There are several 55-gallon drums of product stored in an unpaved unbermed area (see Figure 2). These drums are pending disposal according to Mr. King.
- <u>Sump</u>. There is a concrete lined sump near the end of one of the two existing buildings.
- <u>Waste Oil Receptacle</u>. There is another waste oil receptacle located above-ground in the back of the above-mentioned building on the north side of the building.
- Product Lines. There are subsurface product lines traversing southnorth beneath the above-mentioned building. The lines were once connected to former above-ground tanks on the northeast corner of the site and the dispensing area in the center of the site.
- Potential Asbestos Containing Building Materials. These potential materials have been sampled by Earth Metrics and tested by Forensics Analytical Laboratory. Test results from the laboratory are provided in Appendix A.

All previous historic underground tasks have been pulled and removed from the site, according to the property owner (King, 1989). Drums were stated to be in preparation for off-site disposal or recycling (King, 1989).

ASBESTOS INSPECTION


Two main buildings and miscellaneous out-structures were inspected on September 22, 1989 for potential asbestos containing building materials (ACBM). Such building materials (ceiling tiles, floor tiles, ductwork, and others), if found to contain asbestos, are subject to special handling in removal and disposal prior to building demolition. The inspection was performed by a registered Asbestos Health Emergency Response Act (AHERA) inspector.


In the main building, the heating system, main duct, flume, and several of the above-ceiling ducts were found to contain asbestos insulation (greater than one percent asbestos content). This material requires removal by a licensed asbestos removal contractor and disposal by a licensed waste hauler prior to routine demolition.


There are approximately 110 linear feet of the subject asbestos-containing ductwork. Removal and disposal will cost \$18 - \$20 per linear foot. The other building is unheated and has no ductwork.


Floor tile in the office was sampled and tested to contain asbestos (five to ten percent chrysotile). Removal and disposal of the floor tile will cost \$4 to \$6 per square foot of tile area. A precise estimate of the square footage is not available because access into the second unheated building was limited to visual inspection through windows on September 22. The best estimate is
















FORMER ALAMEDA BULK PLANT 2001 VERSAILLES AVENUE ALAMEDA, CALIFORNIA

FIGURE

ROJECT NO.

ev-1

DRAWN BY:

DATE

AMD

1/95

BASE MAP:

KLEINFELDER

