HEALTH CARE SERVICES

AGENCY



DAVID J. KEARS, Agency Director

R0#807

July 31, 1998

STID #3663

Mr. William Gomban 409 13th Street, Oakland, CA 94612 ENVIRONMENTAL HEALTH SERVICES 1131 Harbor Bay Parkway. Suite 250 Alameda, CA 94502-6577 (510) 567-6700

(510) 337-9335 (FAX)

Chad Schwartz PO Box 41841 Sacramento, CA 95841

Re: Fuel Leak Site Case Closure at Oakland Tribune Building, 2302 Valdez St., Oakland, CA 94612

Dear Mr. Gomban & Mr. Schwartz:

This letter transmits the enclosed underground storage tank (UST) case closure letter in accordance with Chapter 6.75 (Article 4, Section 25299.37[h]). The State Water Resources Control Board adopted this letter on February 20, 1997. As of March 1, 1997, the Alameda County Environmental Protection Division is required to use this case closure letter for all UST leak sites. We are also transmitting to you the enclosed case closure summary. These documents confirm the completion of the investigation and cleanup of the reported release at the subject site. The subject fuel leak case is closed.

SITE INVESTIGATION AND CLEANUP SUMMARY

Please be advised that the following condition(s) exist at the site:

- 1) The final level(s) of contamination consists of 655 parts per Billion of TPH(g) and 630, 49, 21 130 parts per billion (ppb) respectively, of BTEX.
- 2) If a change in land use is proposed or excavation of soils is planned at this site, the an evaluation of risk from exposure to contaminated soil and groundwater must be made.

If you have any questions, please contact this office at (510) 567-6737.

Sincerely,

Brian P. Oliva, REHS, REA, Hazardous Materials Specialist

Bus Pal

enclosures: Case Closure Letter, Case Closure Summary

ALAMEDA COUNTY

HEALTH CARE SERVICES





DAVID J. KEARS, Agency Director

July 31, 1998

STID #3663

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700

REMEDIAL ACTION COMPLETION CERTIFICATION

William Gomban 409 13th Street, Oakland, CA 94612

Chad Schwartz PO Box 418172, Sacramento, CA 95841

Subject: Oakland Tribune, 2302 Valdez Street, Oakland, CA, removal of one (1) 8,000 gallon gasoline and one (1) 750 gallon waste oil underground fuel storage tank

Dear Mr. Gomban & Mr. Schwartz:

This letter confirms the completion of a site investigation and remedial action for the underground storage tank formerly located at the above described location. Thank you for your cooperation throughout this investigation. Your willingness and promptness in responding to our inquiries concerning the former underground storage tank are greatly appreciated.

Based upon the available information in the above-referenced file and with the provision that the information provided to this agency was accurate and representative of site conditions, no further action related to the underground storage tank release is required.

This notice is issued pursuant to a regulation contained in Section 2721(e) of Title 23 of the California Code of Regulations.

Please contact Brian P. Oliva, at (510) 567-6737 if you have any questions regarding this matter.

Sincerely,

Mee Ling Tung

Director of Environmental Health Services

Chief, Hazardous Materials Division - files Brian P. Oliva, ACDEH Chuck Headlee, RWOCB Lori Casias, SWRCB Cheryl Gordon, State Cleanup Fund Leroy Griffin Fire Department enclosure

CASE CLOSURE SUMMARY LEAKING UNDERGROUND FUEL STORAGE TANK PROGRAM

I. AGENCY INFORMATION

DATE: July 8, 1998

Agency Name; Alameda County Haz-Mat

City/State/Zip: Alameda, CA 94502

Responsible Staff Person: Brian P. Oliva

Address: 1131 Harbor Bay Pkwy

Phone: (510) 567-6737

Title: Hazardous Materials Specialist

of Mark

ΙÖ

CASE INFORMATION

Site Facility Name: Oakland Tribune 2302 Valder St.

Site Facility Address: 2300 Valdez Street, Oakland, CA 94612

RB LUSTIS Case No. N/A

Local Case No./LOP Cases No. 3663

Résponsible Parties:

Addresses

Phone Numbers:

William Gomban

409 13th Street, Oakland, CA 94612

Oakland Tribune

Chad Schwartz, Attorney, PO Box 418172, Sacramento, CA 959+1 (916) 972-8300 Oakland Tribune

Tank No: Closed in-place Size in gallons Contents: Date: or removed: 02/23/88 8.000 gasoline removed 1 2 750 waste oil 02/23/88 removed

Ш. RELEASE AND CHARAACTERIZATION INFORMATION

Cause and type of release:

Unknown

Site Characterization completed?

Yes

Date Approved by oversight agency:

03/31/98

Monitoring wells installed?

Yes

Number: 9

Proper screen interval?

Yes

Highest GW depth below ground surface? 6.53' Lowest depth: 8.43'

Flow direction: Westerly/Southwestly Most sensitive current use: Commercial

Are drinking wells affected?

Unknown Aquifer name: N/A

Are surface waters affected?

Nearest affected SW name: Unknown No

Off-site beneficial use impacts (address/location):

Reports on file? Yes Where is report filed?

Alameda County

1131 Harbor Bay Pkwy, Alameda, CA 94502

Page 1

CASE CLOSURE SUMMARY Leaking Underground Fuel Storage Tank Program

Treatment and disposal of Affected Materials

<u>Material</u>	Amount (include units)	Action (Trea or disposal wi	tment ith destination)	<u>Date</u>
Tank & Piping Free Product	1-8,000 gallon gasoline 1-750 gallon waste oil	removed removed	H&H, San Francisco H& H San Francisco	
Soil	60cy	aerated o	n site	
Groundwater Maximum Docu	mented Contaminant Co	ncentrations—B	efore and After Clean	ıup
Contaminant	Soil		Water	r
	Before ¹	After ²	Before ³	<u>After</u>
TPH (gas)	5,500	655	6,300	3,500
TPH(diesel)	N/A	N/A	990	<50
TPH (motor oil)			2,500	<100
Oil & Grease	12,000	3,600	10,200	N/A
Benzene	2.3	0.74	630	630
Toluene	17	0.40	300	49
Ethylbenzene	5.6	4.1	400	21
Xylene	67	2.34	600	130
MTBE	N/A	N/A	<5	<10
CARBONTET.	N/A	N/A	20	64
CHLOROFORM	I N/A	N/A	4.6	16

¹ "Before" results were revealed in soil samples collected in 02/89 during removal of USTs and the subsequent sampling.

² "After" results were revealed in soil samples collected on 08/88 and 08/89 during soil borings and monitoring well installation.

³ "Before" results were revealed in groundwater samples collected in 08/89 from MW-5 and on 01/18/96, from MW-1

^{4 &}quot;After" results were revealed in the final sampling of well MW-1 on 02/11/98

CASE CLOSURE SUMMARY Leaking Underground Fuel Storage Tank Program

Comments (Depth of Remediation Etc.,)

The Oakland Tribune utilized the site for a maintenance garage beginning in 1943 and remained there until about 1986. The USTs, both gasoline and the waste oil tanks were apparently present prior to 1943 (See figure 1).

The two USTs were removed by Clayton Environmental Services in February 1988. Soils samples collected beneath removed USTs showed elevated levels of gasoline and heavy hydrocarbons. Based on these results (see attached figures) the UST excavation cavity was over-excavated down to about 18 feet bgs.

In August, 1988, three monitoring wells were installed by Clayton Environmental, indicating groundwater impact from the site. One year later, in September, 1989, eight soil borings were advanced as well as four additional monitoring wells (MW-4 through MW-7). In August 1990, two more monitoring wells were installed (MW-8 & MW-9) Soils samples from each boring to 11 feet bgs, did not reveal significant levels of TPH-G or BTEX.

In January of 1996, the nine previously installed wells were purged and sampled annually for the next three years (see attached tables).

In light of the levels of contamination encountered in the groundwater, a *Risk-Base Corrective Action* was undertaken for the site. The possible complex exposure pathways for the site include (1) inhalation of hydrocarbons vapors via subsurface soil and groundwater volatilization to both outdoor air and enclosed buildings; and (2) Ingestion of hydrocarbons in groundwater resulting from dissolved plume migration and from hydrocarbons in subsurface soil leaching to groundwater. Calculations show that representative constituent concentrations in subsurface soils and groundwater are below calculated site specific target cleanup levels calculated for the site, therefore, residual contamination does not pose a risk to human health.

See section VII, additional comments...

IV. Closure

Does completed corrective action protect existing beneficial uses per the Regional Board Basin Plan? Undetermined Does the completed corrective action protect potential beneficial uses per the Regional Board Basin Plan? Undetermined Does corrective action protect public health for current land use? Yes

Site management requirements: Site health and safety plan requires if excavation/trenching is proposed in the vicinity of the former USTs.

Should corrective action be reviewed if land use changes? Yes
Monitoring wells on site? Nine (9) Monitoring well decommissioned? None
List enforcement actions taken: None
List enforcement actions rescinded: N/A

CASE CLOSURE SUMMARY Leaking Underground Fuel Tank Program

V. LOCAL AGENCY REPRESENTATIVE DATA

Name: Brian P. Oliva, REHS, REA	Title: Hazardous Materials Specialist
Signature: Buw P. Oll	Date: 4/8/98
Reviewed by Eva UW	Title: Hazardous Materials Specialist
Name: Orulu	Date: 7/10/98
Name: Thomas Peacock Signature:	Title: Supervising Hazardous Materials Specialist 7 - 10 - 9 F Date:
VI. RWQCB NOTIFICATION	
Date Submitted to RB:	RB Response:
RWQCB Staff Name: Chuck Headlee	Title: AWRCE EG
Signature: Cluck Headlle	Date: 7/14/98

VI. ADDITIONAL COMMENTS, DATA, ETC.

Case closure is warranted for the site as a "Low-Risk Groundwater Case" for the following reasons.

a) The source has been sufficiently removed or has been remediated.

Laboratory analysis of verification soil samples collected from the site indicate sufficiently low numbers in the area of the former gasoline and waste oil tanks. A "Risked Based Site Assessment" indicated the site is in all probability, safe, regarding public health.

CASE CLSOURE SUMMARY Leaking Underground Fuel Storage Tank Program

VII. Additional Comments Continued...

b) The site has been adequately characterized.

Laboratory analysis of soil and groundwater samples collected during site investigations document that the previous release is small in extent and appears to be limited to soils which have come in contact with ground water in the vicinity of MW-1.

c) The dissolve hydrocarbon plume appears to be stable and has is not migrating.

Petroleum hydrocarbons were detected in the groundwater samples collected in MW-1, during the sampling events from 1996-1998. Laboratory analysis of groundwater samples collected from the down-gradient wells MW-8 and MW-9, revealed non-detectable concentrations of TPH-G and BTEX. The petroleum hydrocarbon contamination should continue to naturally degrade over time.

- d) No water wells, deeper water wells, surface water or other sensitive receptors are likely to be impacted.
- e) The site presents no significant risk to human health or the environment.

Laboratory analysis of soil and groundwater samples collected during the groundwater monitoring well installation and subsequent UST removals, and the subsequent investigations revealed non-detectable concentrations of benzene (with the exception of MW-1, and MW-4).

Figure 1. Adjacent Asphalt Paved Lot Soil Pile from Drain Excavation Aerated Soil from Tank Excavation (leveled 6-12" high) Sidewalk Drain Area Excavation **MW-3** Gas Pump MW-1 Restroom Adjacent Above Stairway Ground Parking Ф Structure The Oakland Office Tribune Garage and Hydraulic Lifts Storage Space Car Repair Area 🕁 Sidewalk 23rd Street Residential Area **Existing Groundwater Monitoring Well** Proposed Groundwater Monitoring Well Feet Oakland Tribune

Valdez Street

Former 750

Former 8,000

Tank

Adjacent

Parking

Adjacent Parking

Proposed Soil Boring

OAKLAND TRIBUNE GARAGE

Oakland, California

Source: Clayton Environmental

8735-043

Dames & Moore

Consultants, Inc.

Lot


KEY


Lot

Gallon Gasoline

Oil Tank

Gallon Waste








Table 3 SUMMARY OF GROUNDWATER ANALYTICAL RESULTS FOR PETROLEUM HYDROCARBONS

			Former Oa	OLEUM E	IYDROCA ine Mainten	RBONS ance Garage			
Sample ID	Sampling Date				Concentr	ation (mg/l)			
		TPH-D	TPH-MO	TPH-G	B	T	E	X	MTBI
MW-6	08/15/89			_	< 0.0005	< 0.0005	< 0.0005	< 0.0005	
	05/14/90				< 0.0005	< 0.0005	< 0.0005		
 <u>-</u> -	01/18/96	< 0.05	< 0.5					< 0.0005	
MW-7	08/15/89			~-	< 0.0005	< 0.0005	< 0.0005	10.0005	
	05/14/90				< 0.0005	< 0.0005		< 0.0005	
	01/18/96				< 0.0005	< 0.0005	< 0.0005	< 0.0005	
MW-8	05/18/90				< 0.0005		< 0.0005	< 0.0005	
	01/18/96	< 0.05	< 0.5	< 0.05	< 0.0005	< 0.0005	< 0.0005	< 0.0005	
MW-9	05/18/90					< 0.0005	< 0.0005	< 0.0005	
	01/18/96	0.704	-05		0.0085	0.0081	0.0044	0.0054	
		0.70 \-	< 0.5	2.4	0.028	0.020	0.028	0.028	
	12/30/97	< 0.106	< 0.10	4 7	0.056	0.020	0.030	0.027	< 0.025
	02/11/98	< 0.05	< 0.10	5.2	0.050	0.033	0.096	0.074	< 0.025

- Not analyzed for this analyte.
- 2 -Not detected above the expressed value.
- 3 -4 -
- Not detected above the expressed value.

 West Laboratory report states "Increased reporting limit due to gas and oil range interference."

 NET laboratory report states: "The positive result appears to be a lighter hydrocarbon than Diesel.

 West Laboratory report states "Not typical diesel."

 West Laboratory report states "Increased reporting limit due to gasoline range interference." 5 -
- 6 -

	SUMMARY OF GROU	Tal	ble 4 ER ANALYTICAL RESULTS FOR
~ · · · · · · · · · · · · · · · · · · ·	HALUGEN	NATED VO	DLATILE ORGANICS ne Maintenance Garage
Sample Sampling ID Date	CARB. CHL.	1,2-DCB	Concentration (ug/I)

Sample 115	Sampling		. v./ V. V. V. V		15600 18500	tion (ug/I)			
	Date	CARB.	CHL.	1,2-DCB	1,3-DCB	1,4 DCB	I,1-DCA	I,2-DCA	
MW-1	07/27/89	0.7	2.6	0 5	<0.5	<0.5	1.2	1.9	1.4
	05/14/90	<0.5	<05	4.0	<0.5	<0.5	2.9	1.0	
MW-2	07/27/89	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	1.6 <0.5
	05/14/90	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	
MW-3	07/27/89	0.7	0 5	11.0	2.7	31.0	<0.5	<0.5	<u><0.5</u> <0.5
	05/14/90	<0.5	<0.5	<0.5	<05	<0.5	<0.5		
MW-4	08/15/89	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5 2.2	<0.5 <0.5
	05/14/90	<0.5	<0.5	<0.5	<0.5	<0.5	0.6	<0.5	
MW-5	08/15/89	0 9	0.5	<0.5	<0 5	<0.5	<0.5	<0.5	<0.5 <0.5
	05/14/90	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5		
MW-6	08/15/89	1 8	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5 <0.5	<u><0.5</u> <0.5
	05/14/90	<u><0.5</u>	<u><0.5</u>	<u><0.5</u>	<u>_<0_5</u>	<u><0.5</u>	1.5	<0.5	<0.5 <0.5

Groundwater analytical results from previous investigations are summarized in Tables 3 and 4 (see Figure 5). Table 3 summarizes groundwater analytical results for TPH as Diesel (TPH-D), TPH as Motor Oil (TPH-MO), TPH-G, BTEX, and Methyl-t-butyl Ether (MTBE). Note that Table 3 also contains groundwater analytical results for groundwater samples collected from MW-1, MW-2, MW-4, and MW-9 on February 11, 1998. These samples were collected with a clean disposable bailer, without prior purging of the wells. The laboratory data report for this sampling is contained in Appendix B. Table 4 summarizes detected halogenated volatile organic compounds in groundwater.

		SUMMAR	LUIK	JNDWAT OLEUM I	HYDROCA	YTICAL RE ARBONS		PR	
Sample	Sampling				Concent	ation (mg/l)		ار میری کیک	, , , , , , , , , , , , , , , , , , ,
ID.	Date	TPH-D	ТРН-МО	TPH-G	\boldsymbol{B}	T	Ē	X	MTBE
MW-1	08/16/88	1			1.0	0.30	0.40	0.60	er ion beneautes
	07/27/89				0.10	0.0051	< 0.0012	0.26	
	5/14/90	~~			0.37	0.13	0.17	0.11	
	01/18/96	0.99	< 0.5	3.3	(0.330×	0.039	0.10	0.085	
	12/30/97	$< 0.100^3$	0.190	6.3	1.10	0.073	0.35	0.20	< 0.050
	02/11/98	< 0.05	< 0.10	3.5	0.63	(0.049)	0.21	0.13	< 0.100
MW-2	08/16/88				< 0.0004	€0.0003	< 0.0003	< 0.0004	<u> </u>
	07/27/89				0.024	< 0.001	< 0.001	0.08	
	5/14/90				< 0 03	0.012	0.12	0.02	
	01/18/96			0.20	< 0.0005	0.0008	0.0034	0.0025	
	12/30/97	$< 0.100^3$	0.150	0.32	< 0.0005	< 0.0005	0.0035	0.00083	< 0.005
	02/11/98	< 0.05	< 0.10	< 0.05	< 0.0005	< 0.0005	< 0.0005	< 0.0005	
MW-3	08/16/88				0.052	0.001	0.0049	0.017	< 0.005
	07/27/89	-~			< 0.001	< 0.001	< 0.001	0.017	
	05/14/90				< 0.0005	< 0.0005	< 0.0005	< 0.0005	
	01/18/96	1.24	2.5						
MW-4	08/15/89				< 0.0005	< 0.0005	< 0.0005	10.0005	
	05/14/90				0.22	0.02	0.12	< 0.0005	
	01/18/96	0.474	< 0.5	0.42	0.005	0.0008	0.12	0.18	
	12/30/97	0.0795	0.21	0.19	0.0045	0.00093		0.0071	
	02/11/98	< 0.05	< 0.10	< 0.05	< 0.0095	< 0.00093	0.0037	0.0031	< 0.005
MW-5	08/15/89	-			< 0.0005		<0.0005	< 0.0005	< 0.005
	05/14/90				0.043	< 0.0005	< 0.0005	< 0.0005	
	01/18/96	< 0.05	<0.5		0.045	0.001	0.0094	0.011	

Table 4 SUMMARY OF GROUNDWATER ANALYTICAL RESULTS FOR HALOGENATED VOLATILE ORGANICS

Former Oakland Tribune Maintenance Garage

MW-7 08/15/89 20.0 4.6 <0.5	Sample	Sampling			46 S S S S S S S S S S S S S S S S S S S	Concenti	ration (ug/l)			· Arrigad
MW-7 08/15/89 20.0 4.6 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	ID .	Date	<u>CARB</u>	CHI.	1,2-DCB	1,3-DCB	1,4 DCB	1,1-DCA	I.2-DCA	TCE
MW-8 05/18/90 <0.5 <0.5 <0.5 <0.5 <0.5	MW-7	08/15/89	20.0	4.6	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
MW-8 05/18/90 \<0.5 \ <0.5 \ <0.5 \ <0.5		05/14/90	64 /	16	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	MW-8	05/18/90	<0.5	√ <0.5	<u>/ \ <0.5</u>	<0.5	<0.5	<0.5	<0.5	<0.5
MW-9 05/18/90 <0.5 <0.5 <0.5 <0.5	MW-9	05/18/90	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5		<0.5

CARB. - Carbon Tetrachloride 1,3-DCB - 1,3-Dichlorobenzene 1,2-DCA - 1,2-Dichloroethane

CDIDI

CHL - Chloroform 1,4-DCB - 1,4-Dichlorobenzene TCE - Trichloroethene

1,2-DCB - 1,2-Dichlorobenzene 1,1-DCA - 1,1-Dichloroethane

Based on our review and interpretation of available site data, we draw the following conclusions about the project site:

- Subsurface soils consist of a low permeability clay layer, underlain by more permeable sands and gravels below about 16 feet in depth. Well borings and investigative soil borings encountered clays, silty clays, sandy clays, and gravely clays down to about 16 feet below grade. Soils beneath about 16 feet in depth consist primarily of clayey sands and gravels. Dames & Moore conducted single well slug tests on wells MW-4 through MW-7 in August 1989 using the Bower and Rice method. Calculated hydraulic conductivities in the four wells, which are all screened from about ten feet to 25 feet in depth, ranged from 2.41 x 10⁻⁵ to 2.68 x 10⁻⁴, with an average hydraulic conductivity of 1.08 x 10⁻⁴.
- Waste oil range hydrocarbons have been encountered in three areas of the site: (1) Adjacent to a former floor sump located in the northeast corner of the site building; (2) Adjacent to the assumed inlet to the former waste oil UST, located adjacent to MW-1; and (3) In soil samples from MW-2, located on the south side of the project site building. However, soil analytical results from borings located downgradient (south) from these locations indicates that these waste oil-impacted soils are very localized and do not represent a significant soil impact.
- Subsurface soils are gasoline impacted at approximate groundwater depth (10 to 15 feet in depth), extending south away from the former USTs. Soil analytical results from samples at approximate groundwater depth show TPH-G results ranging between nondetect to 560 milligrams per kilogram. Benzene concentrations in these soil samples tend to be nondetectable at increased distance away from the UST and floor sump source areas.
- Groundwater is not significantly impacted by waste oil range hydrocarbons or identified solvents. Groundwater analytical results show low levels of diesel and motor oil range hydrocarbons immediately adjacent to source areas, but not extending

BORING SB-1 SAMPLING DEPTH IN FEET DATE DRILLED: 8/3/89 SAMPLER TYPE OVA READING (PPM) SAMPLING RESISTANCE SAMPLES **SYMBOLS** DESCRIPTION **CONCRETE FLOOR** SC 3 U 0 DARK BROWN CLAYEY SAND, fine (slightly moist) (very loose) [FILL] CL BROWN SANDY CLAY with some small gravel, 2-5 mm in diamater (slightly moist) (medium stiff) 5 0 U 20 Grades with brownish yellow mottling and large amount of subangular to subrounded gravel, 2-35 mm in diameter (slightly moist) (very stiff) 10 0 U 68 Decreasing gravel, increasing moisture 15 0 U 17 20 0 U 70 Grades with gray mottling; gravel 2-15 mm in diameter (moist) (very stiff to hard) 25 0 U Gravel increasing in diameter up to 7 cm, mostly jasper and chert (wet) 46 NOTES: Boring completed at a depth of 26.5 feet on 8/3/89. 2. Sampling resistance is measured in blows per foot required to drive the sampler 12 inches with a 140 lb. hammer falling 30 inches after sampler 30 has been seated 6 inches. 3. Boring log indicates interpreted subsurface conditions only at the location and the time the boring was drilled. 4. For an explanation of terms used see the Soils Classification Chart and Key to Test Data, Plate B-13. 35

LOG OF BORING

BORING SB-2 SAMPLING DATE DRILLED: 8/3/89 DEPTH IN FEET SAMPLER TYPE OVA READING (PPM) SAMPLING RESISTANCE SYMBOLS DESCRIPTION **CONCRETE FLOOR** SM DARK BROWN SILTY SAND, fine (slightly moist) (loose to very loose) 6 U 0 [FILL] BROWN TO BROWNISH YELLOW SANDY GRAVELLY CLAY with minor CL black mottling, gravels up to 5mm in diameter (very stiff to hard) 5 U 72 0 BROWN TO BROWNISH YELLOW CLAYEY SAND with some gravel SC (slightly moist) (very dense) 10 U 50 Grades with some clay pockets and gravel up to 30mm in diameter 15 U 57 0 BROWN AND BROWNISH YELLOW GRAVELLY SAND (very moist) SP (very dense) 20 U 91 0 BROWN SANDY CLAY with some gravel (hard) CL 68 U 0 25 NOTES: 1. Boring completed at a depth of 24.5 feet on 8/3/89. 2. Sampling resistance is measured in blows per foot required to drive the sampler 12 inches with a 140 lb. hammer falling 30 inches after sampler has been seated 6 inches. 3. Boring log indicates interpreted subsurface conditions only at the location and the time the boring was drilled. 30 4. For an explanation of terms used see the Soils Classification Chart and Key to Test Data, Plate B-13. 35


LOG OF BORING


_	S	SAMPLI	NG]		BORING SB-3
O DEPTH IN FEET	OVA READING (PPM)	SAMPLER TYPE	SAMPLING RESISTANCE	SAMPLES	SYMBOLS	DATE DRILLED: 8/3/89 DESCRIPTION
U					77/	CONCRETE FLOOR
5	0	U	35		CL	BROWN GRAVELLY SANDY CLAY with rootlets (slightly moist) (stiff to very stiff)
_	0	U	29			Grades with decreasing organics, less gravel
10	0	U	36			Grades light brown with some iron oxide staining
15					SP	BROWN GRAVELLY SAND with some clay and strong gasoline odor; gravels angular to subrounded 5-10mm in diameter (moist) (stiff to hard)
	>1000	U	76		7/2 00	Grades with sand and angular to subrounded gravel up to 30mm in diameter
20	10	U	95		GC	CLAYEY SANDY GRAVEL with slight gasoline odor, gravels up to 20mm in diameter (wet) (dense)
25		U	90	4	2. Sa sa ha 3. Bo an 4. Fo	ES: pring completed at a depth of 21.5 feet on 8/3/89. campling resistance is measured in blows per foot required to drive the tampler 12 inches with a 140 lb. hammer falling 30 inches after sampler as been seated 6 inches. pring log indicates interpreted subsurface conditions only at the location and the time the boring was drilled. per an explanation of terms used see the Soils Classification Chart and any to Test Data, Plate B-13.
30						
35		į				


9101 001 015


LOG OF BORING

BORING SB-4 / MW-4 SAMPLING DATE DRILLED: 8/8/89 SAMPLER TYPE OVA READING (PPM) SAMPLING RESISTANCE SAMPLES DESCRIPTION SYMBOLS CEMENT GROUT CONCRETE FLOOR BROWN SANDY SILTY CLAY with small pockets of CL light brown silty clay; trace iron oxide staining; U 36 0 (slightly moist) (stiff) Grades with black mottling (moist) 35 U 0 Grades light brown with silty clayey sand lenses and trace gravel up to 1cm in diameter; iron oxide **SENTONITE SEAL** nodules (slightly moist) 39 ٥ U BROWNISH AND GREENISH GRAY MOTTLED SP SAND with slight odor (moist) (medium dense) SCREENED INTERVAL SAND 40 U 8 BROWN TO LIGHT BROWN SANDY CLAY with CL orange mottling; some gravel up to 7cm in diameter (moist) (stiff to medium stiff) 23 U 0 Grades with large amount of angular gravel 76 U 0 NOTES: 1. Boring completed at a depth of 26.5 feet on 8/8/89. 2. 4-inch PVC observation well installed to a depth of 25.5 feet; screened interval 3. Sampling resistance is measured in blows per foot required to drive the sampler from 10.0 to 25.0 feet. 12 inches with a 140 lb, hammer falling 30 inches after sampler has been seated 4. Boring log indicates interpreted subsurface conditions only at the location and the time the boring was drilled. 5. For an explanation of terms used see the Soils Classification Chart and Key to Test Data, Plate B-13. LOG OF BORING Dames & Moore









SAMPLER TYPE		BORING SB-9
MPLE	SAMPLING RESISTANCE	DATE DRILLED: 8/7/89
SA S	SAN	SYMBOLS DESCRIPTION
U	26	CL BROWNISH YELLOW SILTY SANDY CLAY with dark brown and orange mottling (slightly moist) (stiff)
U	46	Grades brown with iron oxide staining (hard)
U	32	Grades lighter brown with less sand
U	31	CL GREENISH GRAY SANDY GRAVELLY CLAY with slight odor (slightly moist) (stiff to very stiff)
U	80	GW BROWN SILTY SANDY GRAVEL with trace clay (very moist to wet)
		NOTES: 1. Boring completed at a depth of 21.5 feet on 8/7/89. 2. Sampling resistance is measured in blows per foot required to drive the sampler 12 inches with a 140 lb. hammer falling 30 inches after sampler has been seated 6 inches.
		 Boring log indicates interpreted subsurface conditions only at the location and the time the boring was drilled. For an explanation of terms used see the Soils Classification Chart and Key to Test Data, Plate B-13.
		·
	U	U 46 U 32 U 31

			,
	S	AMPLIN	IG
O DEPTH IN FEET	OVA READING (PPM)	SAMPLER TYPE	SAMPLING RESISTANCE
5	0	U	14
	0	U	58
10	0	υ	41
15	2	U	25
	0	U	57
75	0	U	37
S. S			
The second secon			

BORING SB-10

DATE DRILLED: 8/7/89

ഗ

SAMPLES			
SA	SYMB	OLS	DESCRIPTION
			CONCRETE FLOOR
3		ML.	DARK BROWN CLAYEY SILT with some sand (dry to slightly moist) (loose) [FILL]
		CL	BROWN TO BROWNISH YELLOW SILTY SANDY CLAY with gravel, black mottling (stiff to hard)
			Grades to brown to light brown with less sand, iron oxide or manganese nodules (slightly moist) (very stiff)
			Grades brown to brownish yellow with more sand
		sc	LIGHT BROWN CLAYEY SAND, medium to fine, with black mottling and gravel (moist) (medium dense)
		GC	BROWN CLAYEY SANDY GRAVEL, fine (very moist)

NOTES:

- 1. Boring completed at a depth of 24.0 feet on 8/7/89.
- 2. Sampling resistance is measured in blows per foot required to drive the sampler 12 inches with a 140 lb. hammer falling 30 inches after sampler has been seated 6 inches.
- 3. Boring log indicates interpreted subsurface conditions only at the location and the time the boring was drilled.
- 4. For an explanation of terms used see the Soils Classification Chart and Key to Test Data, Plate B-13.

Market on the								
0.35			SAMPLING					
The second secon	O DEPTH IN FEET	OVA READING	(101)	SAMPLER TYPE		SAMPLING		
	5	0		ប		21		
		0	0 U			53		
	10 15	5		U		32		
	20	0		U		76 26		
2		0.5						
3(
35								

BORING SB-11

DATE DRILLED: 8/7/89

SAI	SYMBOLS		DESCRIPTION				
1	777	1	CONCRETE FLOOR				
		CL	BROWN SANDY CLAY with some fine gravel up to 4mm (slightly moist) (stiff)				
			Grades with increasing sand				
			Grades with black and tan mottling, some silt, decreasing sand				
		SC	BROWN-ORANGE TO BROWN CLAYEY GRAVELLY SAND with gravel lenses, gravel primarily chert, up to 2cm in diameter (slightly moist)				
		CL	BROWN TO LIGHT BROWN SANDY GRAVELLY CLAY with orange and black mottling (moist) (stiff)				

NOTES:

- 1. Boring completed at a depth of 24.0 feet on 8/7/89.
- Sampling resistance is measured in blows per foot required to drive the sampler 12 inches with a 140 lb. hammer falling 30 inches after sampler has been seated 6 inches.
- Boring log indicates interpreted subsurface conditions only at the location and the time the boring was drilled.
- For an explanation of terms used see the Soils Classification Chart and Key to Test Data, Plate B-13.


LOG OF BORING

	SAMPLING		VG	BORING SB-12	
DEPTH IN FEET	OVA READING (PPM)	SAMPLER TYPE	SAMPLING RESISTANCE	DATE DRILLED: 8/8/89 SYMBOLS DESCRIPTION	
0	0	U		32	CL PROMINTO LICUTE PROMINI CANON OF AN ANTI-
5	U	· · · ·	32	BROWN TO LIGHT BROWN SANDY CLAY with iron oxide staining (slightly moist) (stiff)	
	0	U	26	Grades brown with minor black mottling and some very fine gravel 1-3mm in diameter	
10	0	U	27	Grades lighter brown with increasing sand, Iron oxide staining and black mottling	
15				GW BROWN AND GREENISH GRAY SANDY CLAYEY GRAVEL, angular to subrounded up to 4cm, gasoline odor (very moist)	
	20	U	94		
20				SC LIGHT BROWN CLAYEY SAND with some brownish yellow mottling and gravel, rounded to subangular up to 5cm, mostly chert, jasper and quartz	
	20	U	59		
25				 NOTES: 1. Boring completed at a depth of 21.5 feet on 8/7/89. 2. Sampling resistance is measured in blows per foot required to drive the sampler 12 inches with a 140 lb. hammer falling 30 inches after sampler 	
				 has been seated 6 inches. 3. Boring log indicates interpreted subsurface conditions only at the location and the time the boring was drilled. 4. For an explanation of terms used see the Soils Classification Chart and 	
30				Key to Test Data, Plate B-13.	
₃₅ l					

UNIFIED SOIL CLASSIFICATION CHART

豆	览							
SYMBOL	LETTER	DESCRIPTION	MAJOR DIVISIONS					
0 0	GW	WELL-GRADED GRAVELS OR GRAVEL-SAND MIXTURES, LITTLE OR NO FINES	CLEAN GRAVELS	ਜੂਨ ਨ: 4:	N, THE 1/4" SIZE MAY BE THE NO.4 SIEVE SIZE			
	GP	POORLY-GRADED GRAVELS OR GRAVEL-SAND MIXTURES, LITTLE OR NO FINES	(LITTLE OR NO FINES)	ELS HALF ACTION HAN NO SIZE		o sin		
	GM	SILTY GRAVELS, GRAVEL-SAND-SILT MIXTURES	GRAVELS WITH FINES	GRAVELS MORE THAN HALF OF COARSE FRACTION IS LARGER THAN NO.4 SIEVE SIZE		SOIL TERIAL EVE SIZ		
	GC	CLAYEY GRAVELS, GRAVEL-SAND-CLAY MIXTURES	(APPRECIABLE AMOUNT OF FINES)			COARSE-GRAINED SOILS MORE THAN HALF OF MATERIAL IS LARGER THAN NO.200 SIEVE SIZE		
	sw	WELL-GRADED SAND OR GRAVELLY SANDS, LITTLE OR NO FINES	CLEAN SANDS	SANDS MORE THAN HALF OF COARSE FRACTION IS SMALLER THAN NO.4 SIEVE SIZE	FOR VISUAL CLASSIFICATION, THE 1/4" SIZE MAY BE USED AS EQUIVALENT TO THE NO.4 SIEVE SIZE	NHALE TAN NO	THE EYE	
	SP	POORLY-GRADED SANDS OR GRAVELLY SANDS, LITTLE OR NO FINES	(LITTLE OR NO FINES)			ARSE IE THAN GER TH	THE NO.200 U.S. STANDARD SIEVE IS ABOUT TI SMALLEST PARTICLE VISIBLE TO THE NAKED E	
	SM	SILTY SANDS, SAND-SILT MIXTURES	SANDS WITH FINES			8 2		
	sc	CLAYEY SANDS, SAND-CLAY MIXTURES	(APPRECIABLE AMOUNT OF FINES)					
	ML	INORGANIC SILTS, VERY FINE SANDS, ROCK FLOUR. SILTY OR CLAYEY FINE SANDS OR CLAYEY SILTS WITH SLIGHT PLASTICITY	7			AL 1S SIZE	ANDAF E VISIE	
	CL	INORGANIC CLAYS OF LOW TO MEDIUM PLASTICITY, GRAVELLY CLAYS, SANDY CLAYS, SILTY CLAYS, LEAN CLAYS	SILTS & CLAYS LIQUID LIMIT LESS THAN 50		SOILS AATERIAL SIEVE SI	U.S. ST ARTICL		
	OL	ORGANIC SILTS AND ORGANIC SILT-CLAYS OF LOW PLASTICITY	ED SOOF MAT			VO.200 LEST P		
	МН	ORGANIC SILTS AND ORGANIC SILT-CLAYS OF LOW PLASTICITY	SAVIS SALTIS SAVIS SAVI		SMAL			
	СН	INORGANIC CLAYS OF HIGH PLASTICITY, FAT CLAYS			NE-G E THAN LER TI			
	ОН	ORGANIC CLAYS OF MEDIUM TO HIGH PLASTICITY, ORGANIC SILTS			MOR			
錣	PT	PEAT AND OTHER HIGHLY ORGANIC SOILS	HIGHLY ORGANIC SOILS					

PLASTICITY CHART



TYPES OF SOIL SAMPLERS

U - DAMES & MOORE TYPE "U" SAMPLER

KEY TO SAMPLES

INDICATES UNDISTURBED SAMPLES
INDICATES DISTURBED SAMPLE
INDICATES NO RECOVERY IN SAMPLE

KEY TO TEST DATA

LV - LABORATORY VANE SHEAR TEST

TV - TORVANE (PERFORMED IN FIELD)

PP - POCKET PENETROMETER

TXUU - TRIAXIAL COMPRESSION-UNCONSOLIDATED UNDRAINED

DSCU - DIRECT SHEAR-CONSOLIDATED UNDRAINED

AL - ATTERBERG LIMITS

GSA - GRAIN SIZE ANALYSES

C - CONSOLIDATION TEST

SOIL CLASSIFICATION CHART AND KEY TO TEST DATA