

## R02838

(510) 567-6700

**RAFAT A. SHAHID, DIRECTOR** 

Division of Clean Water Programs

UST Local Oversight Program 1131 Harbor Bay Parkway Alameda, CA 94502-6577

State Water Resources Control Board

DEPARTMENT OF ENVIRONMENTAL HEALTH

October 27, 1995 Dep Ref STID 5563

Russ Catanho 16019 Via Toledo San Lorenzo, CA 945.80

RE: Oakland Automatic Sales, 719 Alice St., Oakland, CA 94607

Dear Russ Catanho,

This office has received and reviewed documents concerning an oil/water separator at the above facility. The latest document is a Report of Soil and Groundwater Investigation dated October 10, 1995 by Century West Engineering Corporation.

The latest soil borings showed no contamination in SB2, 3, and 4. SB5 had significant contamination up to 21,000 ppm of motor oil, but this was concentrated at the 2 ½ foot depth and was very limited in aerial extent. There was no significant contamination below 5 ft. SB2, 3, and 4 surround SB5, except on the west, which is the property line. It would seem that source removal would be proper except that the area is inaccessible and now the separator has been filled with 2 feet of concrete. Groundwater was not significantly impacted, as positive results in the ppm range were heavier than diesel with no BTEX. Remaining levels of contamination will be passively remediated. There also is no way to monitor the site because of the cap and the small area to be monitored. This site is only 4 blocks from the Oakland estuary, which is to the southwest.

This letter confirms the completion of site investigation at the above site. With the provision that the information provided to this agency was accurate and representative of existing conditions, this office has determined that no further action is required at this time.

Sincerely,

Thomas Peacock Manager

 c: James Gribi, Century West Engineering Corp., 7950 Dublin Blvd., Suite 203, Dublin, CA 94568
Gordon Coleman-file
Sum Arigala, RWQCB

tp.dep-ref/5563clos.ltr