12/531

: , :

March 8, 1999

PHASE I ENVIRONMENTAL SITE ASSESSMENT

1285 66th Street Emeryville, California

Project No. 3102

Prepared For

Heller Financial
50 Beale Street, Suite 1600
San Francisco, CA 94105

Prepared By

All Environmental, Inc. 901 Moraga Road, Suite C Lafayette, CA 94549 (800) 801-3224

EXECUTIVE SUMMARY

All Environmental, Inc. (AEI) was retained by Heller Financial to conduct a Phase I Environmental Site Assessment (ESA), in conformance with the scope and limitations of ASTM Practice E 1527, for the property located at 1285 66th Street in the City of Emeryville, Alameda County, California.

The subject property is located on the south side of 66th Street, approximately 100 feet south of the intersection between Hollis Street and 66th Street. The rectangular shaped parcel is approximately 15,000 square feet in size and is developed with a 18,000 square foot concrete block building. Offices comprise the western portion of the building. The western portion of the building is improved with a second story. A single story dry storage warehouse is located on the eastern portion of the building. According to historical sources the subject property building was constructed in two stages. The western portion of the subject property was constructed between 1959 and 1966. The eastern warehouse portion of the building was added on circa 1970. The offices of Liquid Sugars, Inc. (LSI) currently occupy the building. An asphalt parking area is located north of the building.

The subject property was not identified on a search of electronically compiled federal, state, county, and city databases. These databases include regulatory agency lists of known or potential hazardous waste sites, landfills, hazardous waste generators, and disposal facilities in addition to sites under investigation.

AEI's investigation has revealed the following recognized environmental concerns associated with the subject property:

- Due to the age of the subject property building, there is a potential that ACMs are present. All suspect ACMs were observed in good condition with the exception of acoustical ceiling spray and do not pose a health and safety concern to the occupants of the subject property at this time. Samples of acoustical ceiling spray were collected and analyzed. No asbestos was detected within the samples. The remaining identified suspect ACMs would need to be sampled to confirm the presence or absence of asbestos prior to any renovation or demolition activities to prevent potential exposure to workers and/or building occupants.
- Due to the construction date of the subject property building, there is a potential that leadbased paint is present. All observed painted surfaces were in good condition and do not pose a health and safety concern to the occupants of the subject property at this time. However, actual material samples would need to be collected in order to determine whether or not leadbased paint is present.

AEI's investigation has revealed the following recognized environmental concerns at nearby properties:

ΔEI

- Liquid Sugars, Inc. (LSI), located adjacent to the east of the subject property was identified as a leaking underground storage tank site (LUST). According to reports provided in the Gribi Associates Phase I Environmental Site Assessment report, two 1,000 gallon gasoline and one 10,000 gallon diesel USTs were removed from the site in November 1990. Significant concentrations of petroleum hydrocarbons were detected in soil samples collected from the tank excavation. Groundwater monitoring wells were installed near the former tank hold. Groundwater samples were collected and analyzed on a quarterly basis on seven occasions. Moderate concentrations of petroleum hydrocarbons were detected in the groundwater beneath the site. Based on the close proximity, there is a potential that the unauthorized release could impact the subject property.
- The Mohawk Petroleum Corporation distribution plant was formerly located adjacent to the east of the subject property during the 1950s and 1960s. Significant quantities of petroleum hydrocarbons were stored at the site. There is a potential that the former petroleum distribution facility impacted the soil or groundwater beneath the site. Due to the close proximity of the former petroleum storage areas, there is a potential that the subject property would be impacted by a historical unauthorized release.

AEI's investigation has revealed no evidence of recognized environmental concerns associated with the subject property or adjacent properties. AEI recommends further investigation to determine if the historical storage of petroleum hydrocarbons and the unauthorized release at the eastern adjacent site has impacted the subject property.

AEI

TABLE OF CONTENTS

1.0	INTRODUCTION]
1.1	Scope of Work	
1.2	Limitations	
1.3	Limiting Conditions	
2.0	SITE AND VICINITY DESCRIPTION	÷
	Site Location and Description	
2.2	Site and Vicinity Characteristics	
	Geology and Hydrogeology	
	HISTORICAL REVIEW OF SITE AND VICINITY	
	Aerial Photograph Review	•
3.2	Local Agencies	
	3.2.1 Health Department.	
	3.2.2 Fire Department.	
	3.2.3 Building Department	
3.3	Sanborn Fire Insurance Maps.	6
	City Directories	
3.5	Interviews	7
4.0	REVIEW OF REGULATORY AGENCY RECORDS	8
4.1	Records Summary	8
4.2	Record Details	9
5.0	SITE INSPECTION AND RECONNAISSANCE	13
5.1	On-Site Observations	13
	5.1.1 Presence of Hazardous Materials	
	5.1.2 Underground and Aboveground Hazardous Storage Containers	
	5.1.3 Indication of Polychlorinated Biphenyl's (PCB's)	
	5.1.4 Presence of Asbestos Containing Materials (ACM)	
	5.1.5 Presence of Lead-Based Paint	
	5.1.6 Surface Staining and Stressed Vegetation	
50	5.1.7 Other Observations	
	Off-site Observations	
6.0	FINDINGS AND CONCLUSIONS	16
7.0	SIGNATURE OF ENVIRONMENTAL PROFESSIONALS	17



FIGURES

- 1 SITE LOCATION MAP
- 2 SITE PLAN

APPENDICES

- A PROPERTY PHOTOGRAPHS
- **B** AERIAL PHOTOGRAPHS
- C REGULATORY DATABASE
- D SANBORN FIRE INSURANCE MAPS
- E OTHER RELEVANT DATA

1.0 INTRODUCTION

This report documents the methods and findings of the Phase I Environmental Site Assessment of the property located at 1285 66th Street in the City of Emeryville, California (Figure 1: Site Location Map, Figure 2: Site Map, and Appendix A: Property Photographs).

1.1 Scope of Work

The purpose of the Phase I Environmental Site Assessment is to identify potential environmental liabilities associated with the presence of hazardous materials, its use, storage, and disposal at and in the vicinity of the subject property, as well as regulatory non-compliance that may have occurred at the subject property. Property assessment activities focused on: 1) a review of federal, state, and local lists which identify and describe underground fuel tank sites, leaking underground fuel tank sites, hazardous waste generation sites, and hazardous waste storage and disposal facility sites within a one mile radius of the property; 2) a property and surrounding site reconnaissance with personal interviews to identify environmental contamination; and 3) a review of historical sources to help ascertain previous land use at the site and in the surrounding area.

The goal of All Environmental, Inc. in conducting the environmental site assessment was to identify the presence or likely presence of any hazardous substances or petroleum products on the property that may indicate an existing release, a past release, or a potential release of an environmental contaminant into the soil, groundwater, or surface water of the property.

1.2 Limitations

Property conditions, as well as local, state, and federal regulations can change significantly over time. Therefore, the recommendations and conclusions presented as a result of this study apply strictly to the environmental regulations and property conditions existing at the time the study was performed. Available information has been analyzed using currently accepted assessment techniques and it is believed that the inferences made are reasonably representative of the property. All Environmental, Inc. makes no warranty, expressed or implied, except that the services have been performed in accordance with generally accepted environmental property assessment practices applicable at the time and location of the study.

The Phase I Environmental Site Assessment is not, and should not be construed as, a warranty or guarantee about the presence or absence of environmental contaminants that may affect the property. Neither is the assessment intended to assure clear title to the property in question. The sole purpose of investigation into property title records is to ascertain a historical basis of prior land use. This investigation was prepared for the sole use and benefit of Heller Financial. Neither this report, nor any of the information contained herein shall be used or relied upon for any purpose by any person or entity other than Heller Financial.



1.3 Limiting Conditions The performance of this Phase I Environmental Site Assessment was not limited in any way. AEI was granted full and complete access to the subject property.

ΔEI

2.0 SITE AND VICINITY DESCRIPTION

2.1 Site Location and Description

The subject property is located on the south side of 66th Street, approximately 100 feet south of the intersection between Hollis Street and 66th Street. The rectangular shaped parcel is approximately 15,000 square feet in size and is developed with a 18,000 square foot concrete block building. Offices comprise the western portion of the building. The western portion of the building is improved with a second story. A single story dry storage warehouse is located on the eastern portion of the building. According to historical sources, the subject property building was constructed in two stages: the western portion of the subject property was constructed between 1959 and 1966, and the eastern warehouse portion of the building was added on circa 1970. The offices of Liquid Sugars, Inc. (LSI) currently occupy the building. An asphalt parking area is located north of the building.

Refer to Figure 1: Site Location Map, Figure 2: Site Map, and Appendix A: Property Photographs for site location.

2.2 Site and Vicinity Characteristics

The subject property is located in a historically industrial area of Emeryville. The subject property parcel is a part of the Liquid Sugars, Inc. plant that consists of three additional parcels located adjacent to the east of the subject property. Light industrial buildings are located to the north, south and west of the subject property building. Adjacent properties to the north, east and west of the subject property were identified as unauthorized hazardous materials release sites or hazardous materials storage sites (refer to section 4.0).

2.3 Geology and Hydrogeology

Decisions affecting the mode, occurrence, quality and use of groundwater within the area must be based on knowledge of the geologic and hydrogeologic aspects of the study area and surrounding region.

The subject property is located at 27 feet above mean sea level and the local topography is relatively flat. The nearest surface water is San Francisco Bay, located approximately one half mile to the west. According to borehole logs from a subsurface investigation performed at the subject property on February 25, 1999, the site is underlain by silty clay and sandy clay to a depth of approximately 15 feet below ground surface. Based on information obtained from the subsurface investigation and groundwater monitoring well data from sites near the subject property, depth to groundwater is approximately 10 feet below ground surface. Groundwater flow direction is predominantly to the west, however due to the close proximity of the Bay and the shallow groundwater gradient in the area, it is likely that the groundwater is tidally influenced.



3.0 HISTORICAL REVIEW OF SITE AND VICINITY

The subject property was used for residential purposes prior to the construction of the current building. The current building was constructed in two stages. According to aerial photographs, the western portion of the building was constructed between 1959 and 1966. City directories indicate that the building was occupied by Waukesha Pacific Equipment Company for wholesale diesel engine parts. Aerial photographs indicate that the eastern portion of the building was developed circa 1970. Building department records indicate that the subject property building was occupied by Pacific Electronics in 1973 for light assembly of electronic parts. In 1982 the property tenant is listed as Liquid Sugars, Inc., the current tenant of the property.

3.1 Aerial Photograph Review

On February 8, 1999, All Environmental, Inc. reviewed aerial photographs of the subject property and surrounding area. Aerial photographs were reviewed for the following years (also refer to Appendix B: Aerial Photographs Reviewed).

Date: 1996 Date: 1969
Scale: 1:12,000 Scale: 1:12,000

Date: 1990 Date: 1966 Scale: 1:12,000 Scale: 1:36,000

Date: 1985 Date: 1959
Scale: 1:12,000 Scale: 1:9,600

 Date:
 1981
 Date:
 1953

 Scale:
 1:12,000
 Scale:
 1:10,000

Date: 1975 Date: 1949 Scale: 1:12,000 Scale: 1:7,200

In the 1949, 1953 and 1959 aerial photographs, the subject property building is not present. A small building is located in the northeast corner of the property and appears to be a residence with a backyard stretching the full length of the eastern property boundary. Two additional buildings are present on the property along the southern property boundary.

In the 1966 aerial photograph, the western portion of the subject property building is constructed. The residential dwelling and associated yard are present.

In the 1969 aerial photograph, the subject property building is developed as it is today. The residential dwelling is present.



In the remaining aerial photographs reviewed, the subject property is developed as it is today.

3.2 Local Agencies

Local agencies, such as environmental health departments, fire prevention bureaus, and building departments are contacted in order to identify any current or previous reports of hazardous materials use, storage, and release that may have occurred at the subject property which would indicate the potential of soil and/or groundwater contamination.

3.2.1 Health Department

Files at the local health department may contain information regarding hazardous materials at the subject property, as well as information regarding unauthorized releases of petroleum hydrocarbons or other contaminants that may affect the soil or groundwater in the area.

A file search was not performed at the local health department. Information regarding unauthorized releases of hazardous materials was obtained from a previous Phase I Environmental Site Assessment (ESA) performed by Gribi Associates and issued on November 9, 1998 (refer to Appendix E). Refer to Section 4.2 for specific information pertaining to nearby sites.

3.2.2 Fire Department

On February 8, 1999, the Emeryville Fire Department (EFD) was contacted for information on the subject property in order to identify any previous or current tenants that may have used or stored hazardous materials at the subject property.

No information was on file with the EFD for the subject property address.

3.2.3 Building Department

On February 8, 1999, the Emeryville Building Department (EBD) was visited for information on the subject property in order to identify historical tenants and use.

According to the EBD files, a permit to construct the second floor mezzanine was issued in February, 1973. Pacific Electronics, Inc. was indicated as the tenant of the building and reportedly used the building for light assembly of electronic parts. CBS Retail was listed as the tenant of the property in 1975 and the first record of Liquid Sugars, Inc. as the tenant of the property was a 1982 permit.

AEI

3.3 Sanborn Fire Insurance Maps

Sanborn Fire Insurance maps were developed in the late 1800s and early 1900s for use as an assessment tool for fire insurance rates in urbanized areas. A search was made of the University of California, Berkeley Map Room's collection of Sanborn Fire Insurance maps on February 9, 1999. Sanborn maps were available and reviewed for the years 1911, 1950, 1952 and 1969.

The subject property is developed with two dwellings in the 1911 Sanborn map. The surrounding properties are developed with similar dwellings.

In the 1950 Sanborn map, the subject property is developed with two dwellings located along the eastern property boundary. The Mohawk Petroleum Corporation distribution plant is located adjacent to the east of the subject property. Above ground storage tanks are shown located adjacent to the subject property.

No significant changes were noted in the 1952 Sanborn map.

In the 1969 Sanborn map, one of the dwellings is present in the northeast corner of the property. The southwest corner of the property is developed with light industrial building used for a wholesale engine parts warehouse.

3.4 City Directories

A search of historic city directories was conducted for the subject property at the Oakland Public Library on February 17, 1999. Directories were available and reviewed for the years 1969, 1974, 1979, 1981, 1984, 1989, 1998. The following table summarizes the results of the city directory search.

City Directory Search Results

Year	Occupant Eisted
1969	Waukesha Pacific Equipment Co
	Diesel Engines
1974	No Listing
1979	No Listing
1981	No Listing
1984	CA Omega Foods
	CA Syrup & Extract Co
	Emeryville Transportation Co
	LSI
1989	CA Omega Foods
	CA Syrup & Extract Co
	Emeryville Transportation Co
	LSI
1998	CA Omega Foods
ļ	CA Syrup & Extract Co
	Emeryville Transportation Co
<u> </u>	LSI



3.5 Interviews

Mr. Ron Mooney of Liquid Sugars, Inc. (LSI) was contacted on March 2, 1999 for information regarding disclosure of former hazardous materials storage and generation at the subject property. Mr. Mooney indicated that small quantities (<55 gallons) of waste oil, chlorine and acid were previously stored in the warehouse portion of the building prior to off-site disposal. The oil, chlorine and acid were used for running tests at the eastern adjacent LSI property. No unauthorized releases were associated with the stored hazardous materials.

ΔEI

4.0 REVIEW OF REGULATORY AGENCY RECORDS

The following information was obtained through a search of electronically compiled federal, state, county, and city databases provided by Vista Information Solutions, Inc. The database search includes regulatory agency lists of known or potential hazardous waste sites, landfills, hazardous waste generators, and disposal facilities in addition to sites under investigation. The information provided in this report was obtained from publicly available sources. The locations of the sites listed in this report are plotted with a geographic information system utilizing geocoding of site addresses. The accuracy of these locations is generally +/- 300 feet. AEI's field representative has attempted to confirm the locations of listings on or adjacent to the subject property. Refer to the radius map (Appendix C: Regulatory Database Review Report) for a location of the sites in relation to the subject property.

4.1 Records Summary

× .

DATABASE REVIEWED	SUBJECT	ADJACENT. PROPERTY
Identification as National Priorities List (NPL) "Superfund" site	No	No
Identification as RCRA CORRACTS site	No	No
Identification as State (CalSites SPL/SCL) site	No	No
Identification as CERCLIS/NFRAP site	No	No
Reported as leaking underground storage tanks (LUST) site	No	Yes
Identification as solid waste landfill (SWLF)	No	No
Registered underground/aboveground storage tanks (UST/AST)	No	Yes
Incidents of ERNS List Spill Reporting	No	No
Identification as hazardous waste handler and/or generator (RCRA-TSD, LG-GEN and/or SM-GEN)	No	Yes
Identification on SPILLS List	No	No

The subject property was not identified during the regulatory database search.



4.2 Record Details

National Priorities List (NPL) is EPA's national listing of contaminated sites targeted for cleanup because they pose a threat to human health and the environment. The Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA or Superfund) authorizes and requires the EPA to investigate, categorize, and enforce the cleanup of hazardous waste sites on the NPL. An NPL site on or near a particular property may threaten the environmental integrity of the property or affect its marketability.

No sites within a 1-mile radius of the subject property were identified during the NPL database search.

<u>CORRACTS</u> is an EPA-maintained database of Resource Conservation and Recovery Act (RCRA) facilities undergoing "corrective action". A "corrective action order" is issued when there has been a release of hazardous waste or constituents into the environment from a RCRA facility. Corrective actions may be required beyond the facility's boundary and can be required regardless of when the release occurred, even if it predates RCRA.

One site within a 1-mile radius of the subject property was identified during the CORRACTS database search. The site is located one mile south of the subject property. Based on relative distance from the subject property this site is not a significant environmental concerns.

<u>California Sites (CalSites)</u> are provided by the California Environmental Protection Agency, Department of Toxic Substances Control (DTSC) and include state equivalent NPL (SPL) and CERCLIS (SCL) sites.

Two sites within a 1-mile radius of the subject property were identified during the CalSites SPL database search. Myers Container Corporation, located at 6549 San Pablo Avenue, was identified as an SPL, CERCLIS/NFRAP, LUST, UST and Large Generator site (see below for definitions). According to the Gribi Associates Phase I ESA, extensive subsurface investigations were performed at the site after a Remedial Action Order was issued by the DTSC in 1991. There is no indication that contamination originating from the Myers Drum site has extended beyond the West Vallejo Street property boundary. The site is currently listed as no further remedial action planned, (NFRAP). Based on relative distance from the subject property, regulatory status and the defined extent of contamination, this site is not a significant environmental concern.

The second identified SPL site is also a Myers Container Corporation site located at 4500 Shellmound Avenue. The site is located one mile south of the subject property. Based on relative distance from the subject property, regulatory status and/or hydrologically downgradient location, this site is not a significant environmental concern.



Nine sites within a ½-mile radius of the subject property were identified during the CalSites SCL database search. Based on relative distance from the subject property, regulatory status and/or hydrologically downgradient location, these sites are not significant environmental concerns.

<u>CERCLIS/NFRAP</u> is a list of sites that the EPA has investigated or is presently investigating for release or threatened release of hazardous substances, which may be subject to review in accordance with the terms and conditions of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA, also known as Superfund). Sites listed on the "No Further Remedial Action Planned" (NFRAP) database are sites where, following an initial investigation, no contamination was found, contamination was removed quickly, or the contamination was not serious enough to require federal Superfund or NPL consideration.

Nine sites within a ½-mile radius of the subject property were identified during the CERCLIS/NFRAP database search. Based on relative distance from the subject property, regulatory status and/or hydrologically downgradient location, these sites are not significant environmental concerns.

<u>Leaking Underground Storage Tanks (LUST) List</u> is a list produced by the Regional Water Quality Control Board (RWQCB) of known sites with current or former leaking underground storage tanks on the premises.

Seventy two sites within a ½-mile radius of the subject property were identified during the LUST database search.

Two adjacent properties were identified as LUST sites. Liquid Sugars, Inc. (LSI), located adjacent to the east of the subject property was identified. According to reports provided in the Gribi Associates Phase I ESA report, two 1,000 gallon gasoline and one 10,000 gallon diesel USTs were removed from the site in November, 1990. Significant concentrations of petroleum hydrocarbons were detected in soil samples collected from the tank excavation. Groundwater monitoring wells were installed near the former tank hold. Groundwater samples were collected and analyzed on a quarterly basis on seven occasions. Moderate concentrations of petroleum hydrocarbons were detected in the groundwater beneath the site. Based on the close proximity, there is a potential that the unauthorized release could impact the subject property.

The second adjacent LUST site is located across 66th Street at 1295 67th Street. Copper and Brass Sales, Inc. was identified on the database, however, the site is currently occupied by New Logic International. The unauthorized release impacted the soil only and the case has received closure. Based on regulatory status this site is not a significant environmental concern.

The remaining seventy sites are not considered significant environmental concerns based on relative distance from the subject property, regulatory status and/or hydrologically downgradient location.



<u>Solid Waste Landfills (SWLF)</u> is a database generated by the State of California Solid Waste Information System (SWIS), which includes active and inactive landfills and transfer stations within the state maintained by the California Integrated Waste Management Board.

One site within a ½-mile radius of the subject property was identified during the SWLF database search. The site is located greater than 0.3 miles west of the subject property. Based on relative distance from the subject property, regulatory status and hydrologically downgradient location, this site is not a significant environmental concern.

<u>Underground/Aboveground Storage Tanks (UST/AST) List</u> is a comprehensive listing of registered underground and aboveground storage tanks located within the State of California.

Thirty seven (37) sites within a ¼-mile radius of the subject property were identified during the UST/AST database search. Due to the lack of a documented release or factors discussed in the LUST segment of Section 4.2, the storage of hazardous materials within registered tanks is not a significant environmental concern. The storage of hazardous materials within registered tanks is a potential environmental concern if the UST/AST is located in close proximity of the property and an unauthorized release occurs.

<u>Emergency Response Notification System (ERNS)</u> is a national database used to collect information on reported releases of oil and hazardous substances. The database contains information from spill reports made to federal authorities including the EPA, the U.S. Coast Guard, the National Response Center and the Department of Transportation.

Two sites within a 1/8-mile radius of the subject property were identified during the ERNS database search. Based on relative distance from the subject property and the fact that ERNS releases are one time events, the unauthorized release at these sites is not a significant environmental concern.

Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous waste from the point of generation to the point of disposal. Information from the RCRA database is divided into three categories: TSD, LG GEN and SM GEN. The TSD category is searched to a ½-mile radius and tracks facilities which treat, store and/or dispose of hazardous waste. LG GEN, or large generators, are facilities that generate more than 1000 kg of hazardous waste per month. SM GEN, or small generators, are facilities that generate between 100 and 1000 kg of hazardous waste per month. The LG-GEN and SM-GEN databases are searched up to a ½-mile radius from the subject property.

No sites within a ½-mile radius of the subject property were identified during the RCRA-TSD database search.

Four sites within a ¹/₈-mile radius of the subject property were identified during the RCRA (LG-GEN) database search.



Seven sites within a 1/3-mile radius of the subject property were identified during the RCRA (SM-GEN) database search.

The storage, treatment, disposal and/or generation of hazardous materials at these sites is not a significant environmental concern based on the lack of a documented release or factors discussed in prior segments of Section 4.2.

<u>SPILLS</u> is a database generated by the Regional Water Quality Control Board and local Office of Emergency Services. This database lists hazardous materials incidents that required an emergency response.

No sites within a ¼-mile radius of the subject property were identified during the SPILLS database search.

AEI

5.0 SITE INSPECTION AND RECONNAISSANCE

5.1 On-Site Observations

On February 8, 1999, a site reconnaissance of the subject property, adjoining properties, and immediately surrounding areas was conducted by Jennifer Pucci of AEI in order to obtain information indicating the likelihood of recognized environmental conditions in connection with the subject property.

5.1.1 Presence of Hazardous Materials

The use, storage, generation and/or disposal of hazardous materials were not observed at the subject property during the site inspection.

5.1.2 Underground and Aboveground Hazardous Storage Containers

No above ground storage tanks were observed during the site inspection. No fill pipes or access ways indicating the possibility of any underground storage tanks were identified at the subject property during the site inspection.

5.1.3 Indication of Polychlorinated Biphenyl's (PCB's)

Electrical transformers can potentially contain toxic polychlorinated biphenyl's (PCB's). Transformers that contain 50 to 500 parts per million (ppm) PCB's are classified as PCB contaminated. The management of potential PCB-containing transformers is the responsibility of the local utility or the transformer owner. Actual material samples need to be collected to determine if transformers are PCB-containing.

One pole-mounted transformer was observed on the subject property during the site inspection.

No spills, staining or leaks were observed on or around the transformer.

5.1.4 Presence of Asbestos Containing Materials (ACM)

The production of asbestos-containing materials (ACMs) was banned in 1978 by the passage of the EPA's National Emission Standards for Hazardous Air Pollutants (NESHAP). Due to warehouse inventories, there is a potential that ACMs are present in buildings constructed as late as 1980. During the site inspection suspect ACMs were observed within the building. The condition and friability of the identified suspect ACMs is noted in the following table:



Suspect Asbestos Containing Materials (ACMs)

Material	Location	Friable	Condition
Acoustical Ceiling Spray	First Floor Office	yes	Damaged
9x9 Floor tile	First Floor Mens Restroom	no	Good
Wallboard, taping, compound	Throughout	no	Good
Roofing Materials	Roof	no	Not observed

All suspect ACMs were observed in good condition with the exception of the acoustical ceiling spray and do not pose a health and safety concern to the occupants of the subject property at this time. The identified suspect ACMs would need to be sampled to confirm the presence or absence of asbestos prior to any renovation or demolition activities to prevent potential exposure to workers and/or building occupants.

Three samples of acoustical ceiling spray were collected and analyzed at Forensic Analytical Laboratories. No asbestos was detected in any of the samples collected. Refer to Appendix E for copies of the analytical results.

5.1.5 Presence of Lead-Based Paint

Lead-based paint is any paint, varnish, stain, or other applied coating that has 1 mg/cm² (or 5,000 ug/g by dry weight) or more of lead. In Section 1017 of the Housing and Urban Development Guidelines, Residential Lead-Based Paint Hazard Reduction Act of 1992, otherwise known as "Title X", states that a lead-based paint hazard is "any condition that causes exposure to lead that would result in adverse human health effects" resulting from lead-contaminated dust, bare, lead-contaminated soil, and/or lead-contaminated paint that is deteriorated or present on accessible, friction, or impact surfaces. Therefore, under Title X, intact lead-based paint on most walls and ceilings would not be considered a "hazard", although the paint should be maintained and its condition monitored to ensure that it does not deteriorate and become a hazard. In buildings constructed after 1978, it is very unlikely that lead-based paint is present.

Due to the construction date of the subject property building there is a potential that lead-based paint is present. Both interior and exterior painted surfaces were observed to be in good condition and do not pose a health and safety concern to the occupants of the subject property at this time. However, actual material samples would need to be collected in order to determine if lead-based paint is present.

5.1.6 Surface Staining and Stressed Vegetation

No evidence of surface staining and stressed vegetation was observed on the subject property during the site inspection.



5.1.7 Other Observations

No other concerns were noted during the site inspection.

5.2 Off-site Observations

The Liquid Sugars, Inc. plant operation is located adjacent to the west of the subject property. Refer to section 4.2 for additional information regarding the adjacent site.

In addition, a railroad spur is located adjacent to the south of the subject property. The railroad spur is not currently in use and was historically used to access the southern adjacent property (1280 65th Street). The adjacent property to the south is occupied by Autumn Press, a printing operation. Various drums and smaller containers were outside near the railroad tracks. The contents of the drums could not be determined, but there is a potential that the drums contain inks, paints, solvents or oils for the printing operation. The drums were not in secondary containment. No leaks or spills were observed on or around the drums. This site was not identified during the database search.

ΔEI

6.0 FINDINGS AND CONCLUSIONS

AEI's investigation has revealed the following recognized environmental concerns associated with the subject property:

- Due to the age of the subject property building, there is a potential that ACMs are present. All suspect ACMs were observed in good condition with the exception of acoustical ceiling spray and do not pose a health and safety concern to the occupants of the subject property at this time. Samples of acoustical ceiling spray were collected and analyzed. No asbestos was detected within the samples. The remaining identified suspect ACMs would need to be sampled to confirm the presence or absence of asbestos prior to any renovation or demolition activities to prevent potential exposure to workers and/or building occupants.
- Due to the construction date of the subject property building, there is a potential that leadbased paint is present. All observed painted surfaces were in good condition and do not pose a health and safety concern to the occupants of the subject property at this time. However, actual material samples would need to be collected in order to determine if lead-based paint is present.

AEI's investigation has revealed the following recognized environmental concerns at nearby properties:

- Liquid Sugars, Inc. (LSI), located adjacent to the east of the subject property was identified as a leaking underground storage tank site (LUST). According to reports provided in the Gribi Associates Phase I Environmental Site Assessment report, two 1,000 gallon gasoline and one 10,000 gallon diesel USTs were removed from the site in November 1990. Significant concentrations of petroleum hydrocarbons were detected in soil samples collected from the tank excavation. Groundwater monitoring wells were installed near the former tank hold. Groundwater samples were collected and analyzed on a quarterly basis on seven occasions. Moderate concentrations of petroleum hydrocarbons were detected in the groundwater beneath the site. Based on the close proximity, there is a potential that the unauthorized release could impact the subject property.
- The Mohawk Petroleum Corporation distribution plant was formerly located adjacent to the east of the subject property during the 1950s and 1960s. Significant quantities of petroleum hydrocarbons were stored at the site. There is a potential that the former petroleum distribution facility impacted the soil or groundwater beneath the site. Due to the close proximity of the former petroleum storage areas, there is a potential that the subject property would be impacted by a historical unauthorized release.



7.0 SIGNATURE OF ENVIRONMENTAL PROFESSIONALS

All Environmental, Inc. has performed a Phase I Environmental Site Assessment for the property located at 1285 66th Street in the City of Emeryville, Alameda County, California, in conformance with the scope and limitations of ASTM Standard 1527.


Prepared by:

Jennifer Pucci, REA Senior Project Manager Reviewed by:

Craig Hertz, REA Senior Author

AEI

FIGURES





ALL ENVIRONMENTAL, INC.

901 MORAGA ROAD, SUITE C, LAFAYETTE, CA

SITE LOCATION MAP

1285 66th STREET EMERYVILLE. CALIFORNIA

FIGURE 1

:30

APPENDIX A PROPERTY PHOTOGRAPHS

...



PHOTO 1 VIEW OF SUBJECT PROPERTY BUILDING FROM 66^{TH} STREET




PHOTO 2
REAR VIEW OF SUBJECT PROPERTY BUILDING

ALL ENVIRONMENTAL, INC. 901 MORAGA ROAD, SUITE C, LAFAYETTE, CA




PHOTO 3

REAR VIEW OF SUBJECT PROPERTY BUILDING

ADJACENT LSI ABOVEGROUND STORAGE TANKS VISIBLE




PHOTO 4 POLE-MOUNTED TRANSFORMERS LOCATED ALONG 66^{TH} STREET

ALL ENVIRONMENTAL, INC. 901 MORAGA ROAD, SUITE C, LAFAYETTE, CA

APPENDIX B AERIAL PHOTOGRAPHS

:, .





SOURCE: PACIFIC AERIAL SURVEYS PHOTO ID: AV 337 7 22 1959, 1:12,000

ALL ENVIRONMENTAL, INC.

901 MORAGA ROAD, SUITE C. LAFAYETTE. CA

AERIAL PHOTOGRAPH

1285 66th STREET EMERYVILLE. CALIFORNIA

AERIAL PHOTOGRAPH I





PACIFIC AERIAL SURVEYS PHOTO ID: AV 3845 7 20 1990, 1:12,000

ALL ENVIRONMENTAL, INC. 901 MORAGA ROAD, SUITE C. LAFAYETTE. CA

AERIAL PHOTOGRAPH

1285 66th STREET EMERYVILLE, CALIFORNIA

AERIAL PHOTOGRAPH 3





SOURCE: PACIFIC AERIAL SURVEYS PHOTO ID: AV 902 6 16 1966, 1:12.000

ALL ENVIRONMENTAL, INC. 901 MORAGA ROAD, SUITE C, LAFAYETTE. CA

AERIAL PHOTOGRAPH

1285 66th STREET EMERYVILLE, CALIFORNIA

AERIAL PHOTOGRAPH 2

APPENDIX C REGULATORY DATABASE

ā,

SITE ASSESSMENT REPORT

PROPERTY	CLIENT
INFORMATION	INFORMATION
Project Name/Ref #: Not Provided Project #3102 1285 66th St Emeryville, CA 94608 Latitude/Longitude: (37.848274, 122.289266)	-

	Site Dist	ribution Summary	within 1/8 mile	1/8 to . 1/4 mile	1/4 to 1/2 mile	1/2 to 1 mile.
Agency / D	atabase:-Type	e of Records		•		
A) Databas	es searched to	o 1 mile:				
US EPA	NPL	National Priority List	o	O _	0	0
US EPA	CORRACTS	RCRA Corrective Actions and associated				
	(TSD)	TSD	0	0	0	1
STATE	SPL	State equivalent priority list	0	1	0	1
B) Databas	es searched to	o 1/2 mile:				
STATE	SCL	State equivalent CERCLIS list	0	4	5	-
US EPA	CERCLIS / NFRAP	Sites currently or formerly under review by US EPA	0	2	6	•
US EPA	TSD	RCRA permitted treatment, storage, disposal facilities	0	0	0	•
STATE	LUST	Leaking Underground Storage Tanks	15	30	27	-
STATE	SWLF	Permitted as solid waste landfills, incinerators, or transfer stations	0	0	1	•
C) Databas	ses searched to	o 1/4 mile:				
STATE	UST	Registered underground storage tanks	17	20		_
STATE	AST	Registered aboveground storage tanks	11	0	-	-
D) Databas	ses searched to	o 1/8 mile:				<u> </u>
US EPA	ERNS	Emergency Response Notification System of spills	2	<u>. </u>	•	•
US EPA	LG GEN	RCRA registered large generators of hazardous waste	4	•	•	•
US EPA	SM GEN	RCRA registered small generators of hazardous waste	7	•	•	•
STATE	SPILLS	State spills list	0		-	-



For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.


Report ID: 990003102

Date of Report: February 4, 1999

Page #1

This report meets the ASTM standard E-1527 for standard federal and state government database research in a
Phase I environmental site assessment. A (-) indicates a distance not searched because it exceeds these ASTM
search parameters.
search parameters.
LIMITATION OF LIABILITY
Customer proceeds at its own risk in choosing to rely on VISTA services, in whole or in part, prior to proceeding with any transaction. VISTA cannot be an insurer of the accuracy of the information, errors occurring in conversion of data, or for
customer's use of data. VISTA and its affiliated companies, officers, agents, employees and independent contractors cannot be
held liable for accuracy, storage, delivery, loss or expense suffered by customer resulting directly or indirectly from any
Information provided by VISTA.
NOTES
NOTES








For More Information Call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403 Report ID: 990003102

Date of Report: February 4, 1999

APPENDIX D SANBORN FIRE INSURANCE MAPS







APPENDIX E OTHER RELEVANT INFORMATION

Ċ,



Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

All Environmental Ms. Jennifer Pucci 901 Moraga Road Suite #C Lafayette, CA 94549

Client ID: 3122 Report Number: B007973 Date Received: 02/05/99

 Date Received:
 02/05/99

 Date Analyzed:
 02/08/99

 Date Reported:
 02/08/99

Job ID / Site: Job #3102, 1285 66th Street, Emeryville

FASI Job ID: 3122-30

Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
ACS-1	19907091		· · · · · · · · · · · · · · · · · · ·				
Layer: Off-White S	emi-Fibrous Material		ND				
Layer: Paint			ND				
SECOND CONTRACTOR CONT	A Mila Bandalas ina Karang a nanci.	and of the community		nde en albadeia		ela il illa discrisi Ze	15 . For 6 . P. P
Total Composite Values : Comment: €ollected on 2.	of Fibrous Components: /3/99	Asbestos:(ND		se (Trace%): -]	ibrous Glass (ND)	

ND

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (Trace%) Fibrous Glass (ND) Comment:Collected on 2/3/99

ACS-3
19907093

Layer: Off-White Semi-Fibrous Material
ND
Layer: Paint
ND

Igial Composite Values of Fibraus Components: Asbestos: (ND) Celhilose (Trace%) Fibrous Glass (ND)

Comment: Collected on 2/3/99

Layer. Paint

Dave Sandusky, CIH, Laboratory Director, Hayward Laboratory

Note: Limit of Quantification ("LOQ") = 1%. Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (dient) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.



BULK SAMPLE REQUEST FORM

				HEROES! FURIM			
CLIENT NAME & ADI	DAESS:	٠	PHONE: 925 2836 000	DATE: 2/3/99			
		MENTAL, INC.	Circle the Method and Turn Around Time	Results Needed:			
	-	, Lafayette, CA 94549	hr/12hr/24hr/48hr/Ext 48hr				
			PLM: Standard) Point Count Gravimetry Prep				
CONTACT: Jenr	uler Pi	<u>vei</u>	TEM: QUAL / QUANT. / WATE	R .			
P.O.#	J	<u>vei</u> JOB # 3102	AA/Fiame AA/Furnace (C)	-			
SITE: 1285 6	6th Stree	t. Emeryville	METALS:				
SAMPLE NUMBER	DATE COLLECTED		AMPLE LOCATION/DESCRIPTION				
ACS-1	2/3/99	aconstral Ceele	ng Spray, Ground Albor				
ACS-2							
ACS-3	1						
			·				
				·			
			·	·			
		•					
	•		,				
Sampled by: Jenn	for Pu	eri 1	Date: 2/3/99 / Time: //	bus			
Relinquished by: Date/Time: 2/3/99	1 Puc	n I	Date/Time: /) / Q / NO				
Relinquished by:			Received By:				
Date/Time:			Date/Time: Sealed Condition (circle one) YES	NO			

02/22/99 16:50 FAX 5108344119

CUSHMAN & WAKEFIELD

Ø002/004

Feb-22-99 03:21P George Lamberth

P.08

02/22/99 11:43 24158419388

EANSON BRIDGETT

@008/010



potential buyer/leases with important information about the Property/Ph required by law to disclose.	in of the Property/Premises. The purpose is, intriend, to provide this brokers and the series which is ourselfly in the schiol browledge of the Owner and which the Owner is leveraged through the averages of a faci, or the averages of sufficient information.
and circumstances 50 as to coupe one to believe that a certain allugio	n or condition probably exists.
TO WHOM IT MAY CONCERN:	
tionid Sucare. Inc.	("Gwner"),
mans the property/premises constrointy known by the street address of	1295 65th Street
located in the City of Ringryy 111e	County
of, Alameda	, State of California
	or property) See contract with buyer dated 1/35/99.
(herein after "Property"), and certifies that:	
thereon, including, but not limited to the roof, except (if there are no e	e of any meterial physical defects in the Property or any improvements and structures mappings write "NONE"; The roof may have minor leaks:
these are old seructures and should be im	imendantly sassesed.
He govern greatering and machinized agriculture addition on the Process	g, ventuating, air considering, plumbing, loading doors, electrical and lighting systems, by us of the data hersot, if any, are not in good-operating order and condition, except (if constlading of anything not in commuting order.
3. Soil Conditions. Owner has no actual immedge that the drainage or soil problems, except (if there are no exceptions write "No	e Property has any slipping, skilling, sattling, flooding, pontang or any other grading, DNST Months
4. Utilities. Owner represents and werrants that the Property and the cost of installation thereof has been fully paid III private sept	is zerved by the following utilities (check the appropriate boxes) of public zewer System is system. If electricity, II natural gree, II dominate Water, II telephone, and II other.
5. Natural Huserd Zone. Owner has no actual knowledge the zone, accept of there are no exceptions write "NONE"; Property actus.	et the Property is incessed within a definested found, earthquaids, or other natural fezzard test in a located within earthquaids zone and flood
requisions, codes, or severents, conditions of restrictions, or of import of any unfulfilled order of directive of any applicable government a reper, maintainence or improvement is to be performed on the Proper improvement a may have been done without place been involved with quithing any crows, which may or may not have performed to the performed of the performed of the performed of the performance of the pe	ice of any aspect or condition of the Property which visites applicable laws, quies, novements of alterations made to the Property Willout a permit where one was required opinion or of any casualty insurance company that any work of investigation, remandation by, except (if there are no exceptions write TVONET POVET Plot years extrained. Last employed its own maintenances that years to applicable codes, or obtained naturally office invitating pulldout. He are still monitoring throughly never to this building.

P.09

Feb-22-99 03:21P George Lamberth

02/22/99 11:43 \$4158419386

::

•

÷

HANSON BRIDGETT

₫009/010

	7. Hanardonn Subalances.
A. Owner has no sessel imp	Mostge of the Property ever having been used as a west dump, of the past of possent existence of any states of
telow ground alongs butte on the Pro	party, or of the current existence on the Property of sableton, transformers containing PCS's or any hexarous, toxi-
entites supplie continue tiloipelii v	and/or quantity of adolptics, use, manufacture or effect, render it subject to Federal, state or local regulation
nyestigation, remediation or removal a	is potentially interious to public feasiti or welfare, except (if there are no exceptions unde "NONE"); He do not
have dry knowledge	of any hazardous substances on the property.
	The state of the s
S. Owner represents and w	devente that it is not currently, and never has been engaged in the business of liabling waste, and never store.
the same addition with 1	except (If there are no exceptions with "NCNE"): We have account verticus chemicals on
	considered hexardous substances. We store some quantities of
	action with heire a very small generator.
ecospilors write "NCNE": We do	not have any knowledge of any structure on the Property having suffered nestodes fire derings, except (if there are no not have any knowledge of any fire demage on the property
1. Addons, Suite or Proceeding	s. Comer has no actual knowledge that any endone, suits or proceedings are pending or streamened before any count
	treent, commencer, board, bureau, against or instrumentally that would affect the Property or the right or ability of a
America tendent to convey, codupy or u	Size the Property, except (if there are no exceptions write "NONE"); He do not have any
10. Governmental Proces edovelopment agency plan or other la	ilings. Owner has he actual kinominings of any existing or contemplated contempedan, environmental, zoning, at use regulation proceedings which could detrimentally affect the value, use and operation of the Property, except (
10. Governmental Process scovelopment agency plan or other is fiere are no exceptions write 'NONE'; lesignations for the pro- is they are i the account must transit! Lity intends to nur levelopments (ex. Clive esticions, sessments, Homese, Henry scorder where the Property is located	dings. Owner has no actual knowledge of any existing or contemptated condensation, environmental, rosing at use regulation proceedings which could determinely affect the value, use and operation of the Property, except to the City of Environmental is reviewing the General Plan and Scraine rearries adjacent to the site, as well as all of the adjacent eiter negligible in the "Morth of Bowell" area. The direction seems to the bowell is area. The direction seems to the boweld light industrial and mixed use including some housing. The area through the wail drill brank area. There are proposed time. Haven't in the area, which may affect the properties. 11. Unrecented This Matters. Owner has no column knowledge of any anomalouses, coverants, conditions of other matters which affect the Property that we not recorded in the official records of my country of these see no complete with TNONET; the did not have any knowledge of any country of these see no complete with TNONET; the did not have any knowledge of any country.
10. Governments Process White are no exceptions with "NCNE"; Issignations for the property intends to put It intends to put Invelopments (cx. Clive; catifors, securents, Homese, Henry mander where the Property is local contractorded title matters.	dings. Owner has he exist knowledge of any existing or contemplated condemnation, environmental, zoning of user regulation proceedings which could desimantally affect the value, user and operation of the Property, except to the office of Emergerial extension and Zoning reportions adjacents to the site, as well as all of the adjacent eiters recluded in the "Morth of Bowell" area. The direction assemble to the adjacent eiters are included in the "Morth of Bowell" area. The direction assemble to the transfer and mixed use including some housing. The transfer the transfer the proposed the through the rail drill brank area. There are proposed the Mayeral in the area, which may affect the properties. 11. Unrecented This Matters. Owner has no educat knowledge of any anomales conduct records of the count of enemy of there are no except the for not have any knowledge of any anomales.
10. Governmental Process scievelopment agency plan or other is fire are no exceptions write 'NONE'; lesignations for the pro- is they are in the accurate to are in the intende to run levelopments (cx. Clive; estictors, sessements, Hospess, Herts, scorder where the Property is local mark-corded with a matter.	dings. Owner has he admit knowledge of any existing or contemplated condemnation, environmental, zoning at use regulation proceedings which could destinantially affect the value, use and operation of the Property, encept if the City of Emeryville is reviewing the General Plan and Sching reparties adjacent to the site. As well as all of the adjacent eiter necluded in the "Morth of Powell" area. The direction seems to be browned light industrial and mixed use including some housing. The area proposed that the real drill track area. There are proposed that the real drill track area. There are proposed that the value area, which may reflect the properties. 11. Unrecorded This Matters. Owner has no solut knowledge of any encamberous, coverence, continued, except of five see no complete the Property Unit we not recorded in the official records of the count of these see no complete with NONE"; for do not have any knowledge of any leases, subjects or other tensory agreements are no complete with NONE"; for do not have any knowledge of any leases on the
10. Governmental Process sciences against against plan or other in these are no exceptions with 'NONE'; less ignations. For the process they are in the process that it intends to nur investigate the purific intends to nur investigate (ex. Clive) confidents (ex. Clive) confidents the Property is located where the Property is located to the Property accept (if there is lifeting the Property, except (if there is lifeting the Property).	dings. Owner has he actual knowledge of any existing or contemplated condemnsation, environmental, zoning at use requision proceedings which could detrimentally effect the value, use and operation of the Property, encept if The City of Enterville is reviewing the General Plan and Scrains required and advances to the site, as well as all of the advances eiter recluded in the "Morth of Powell" area. The direction seems to the thought industrial and mixed use. Including some housing. The transfer through the rail drill brack area. There are proposed Title. Mayoral in the area, which may affect the properties. 11. Unrecorded This Matters. Owner has no solute knowledge of any encumentage, coverents, conditions charges or other matters which effect the Property that we not recorded in the official records of the count of, except if there are no exceptions with TNONEY: Mr. do not have any knowledge of any leases or other bracky agreements are no assessions with TNONEY: Mr. do not have any leases or other bracky agreements are no assessions with TNONEY: Mr. do not have any knowledge of any leases on the large and the strength of the property. 12. Leases. Owner has no actual knowledge of any leases, sublement of any leases on the large of any leases. (It will be presumed that there are no additional lights which warrant disclosure unless they
10. Governmental Process sciences against against plan or other in them are no exceptions write 'NONE'; less ignations. For the process they are in the process in they are in a continued transition of the process in the process in the process is a continued to the process in	dings. Owner has he actual thresholds of any existing or contemplated condensession, environmental, zoning at the requisition proceedings which could desimentally affect the value, use and operation of the Property, encept to The City of Emeryville is reviewing the General Dian and Soming marries adjacent to the site, as well as all of the adjacent sites. The City of Emeryville is reviewing the General Dian and Soming marries adjacent to the site, as well as all of the adjacent sites. The director to the site, as well as all of the adjacent sites. The should in the should of Bowell's area, the including some housing. The road through the sail drill brack area. There are proposed the former's in the area, which may affect the properties. 11. Unrecorded This Matters, Owner has no solust knowledge of any anosamenous, coverents, conditions charges or other matters which affect the file of the Property that we not recorded in the official moords or me count of, except if there are no ecosphere with NONEY; in fig. not have any knowledge of any leases or other brancy agreements are no acceptions with TRANEY; He do not have any knowledge of any leases on the buyers have read the Phase I report. The typical phase is they because I have any knowledge of any leases they because have read the Phase I report. The typical phase is they because I have any knowledge of any leases.

The externants herein will be relied upon by brokens, buyers, immeds, lenders and others. Therefore, Carner ansilor the Owner's Property Manager has terrieved and modified this printed distantent as hecessery to accurately and completely state of the incommental facts concerning the Property. To the extent such modifications are not made, this abstract away be relied upon as printed. This abstract, however, shall not relieve a buyer or leases of responsibility for transportant investigation of the Property. Owner agrees to promptly holly, it writing, all appropriate parties of any material changes which may occur to the sindaments contained harein from the date this statement is signed until title to the Property is transferred, or the lease is executed.

01967 - American Industrial Real Estate Association

Page 2 of 2 REVISED

Form Plante

UST Local Oversight Program
Alameda County Health Care Services
August 25, 1995
Page 2

- Each well was purged of approximately three well volumes. During purging, temperature, pH, conductivity, and turbidity of the well water were periodically monitored and recorded until they stabilized. All purged water was stored onsite in sealed 55-gallon metal drums. Ground water sampling data sheets for each well are contained in Appendix A.
- After purging the required volume, ground water was poured directly from the bailer into two one-liter amber jars and four 40-ml VOA vials. Each container was then tightly sealed with teflon lined septums, making sure that no air bubbles were present in the containers. Each container was then labeled and placed in cold storage for transport to the analytical laboratory under formal chain-of-custody.

RESULTS OF QUARTERLY MONITORING

Hydrologic Conditions

Purged water from both monitoring wells exhibited moderate to strong hydrocarbon odors and hydrocarbon sheen during sampling.

Analytical Results

Ground water samples from the two wells were analyzed for total petroleum hydrocarbons as gasoline (TPH-gas by EPA Method 5030/8015 Modified); total petroleum hydrocarbons as diesel (TPH-diesel by EPA Method 8015 Modified); and benzene, toluene, ethylbenzene and xylenes (BTEX by EPA Method 602/8020). Table 1 summarizes these analytical results. Laboratory data reports and chain-of-custody records are contained in Appendix B.



Table I SUMMARY OF GROUND WATER ANALYTICAL RESULTS Liquid Sugars, Inc. 66th Street Site

IVall	Sample	Water .		3, 110. 0011	Constituer	it (ppm)		
Number	Date	Depth!	TPH-gas	TP [I-diesel		7	E	X
MW-I	04/23/93	6.72 ft	0.64	0.99	0.0063	ND(.0005) ²	0.0056	0 0025
(West)	07/13/93	8.00 ft	0.70	1.50	0.0320	0.0012	0.0033	0.0110
	11/02/93	8.95 A	0.87	1.70	0.0190	ND(.0005)	0.0066	0.0044
	02/15/94	7.91 A	1.20	2.00	0.0220	0.0018	0.0100	0.0064
	, 05/18/94	7.65 ft	1.70	2.60^{1}	0.0570	0.0210	0.3000	0.1300
	.08/17/94	8.51 ft	1.20	2.20^{1}	0.0130	0.0019	0.0008	0.0082
	12/22/94	6.58 ft	1.10	2.40 ^{4,5}	0.0270	0.0069	0.0014	0.0059
	05/09/95	6.73 ft	1.20	2.004.5	0.0140	0.0082	0.0120	0.0062
MW-2	04/23/93	6.73 ft	1.10	2.10	0.3200	0.0065	0.0082	0.0130
(East)	07/13/93	8.38 ft	0.48	0.21	0.0330	0.0025	0.0052	0.0047
	11/02/93	9.05 ft	0.43	1.80	0.0160	0.0009	0.0019	0.0021
	02/15/94	6.82 ſt	1.40	2.80	0.0560	0.0029	0.0075	0.0071
	05/18/94	7.56 ft	0.54	3.00	0.0240	0.0013	0.0026	0.0034
	08/17/94	8.50 ft	0.88	2.203	0.0250	0.0030	0.0028	0.0086
:	12/22/94	6.23 ft]	0.616	3.10 ^{4,5}	0.0036	0.0033	0.0054	0.0016
	05/09/95	6.71 ft	2.30	5.20	0.0150	0.0060	0.0110	0.0130

- Depth to ground water from top of casing.


 Not detected above the concentration expressed in the parentheses.

 Lab results state: "The positive result has an atypical pattern for Diesel analysis."

 Lab results state: "The positive result appears to be a heavier hydrocarbon than Diesel."
- Lab results state: "The positive result appears to be a lighter hydrocarbon than Diesel."

 Lab results state: "The positive result appears to be a heavier hydrocarbon than Gasoline."





Michick 2001 (11)

DESIGNED BY .	DATE :		FIGURE 2	ON DNIWARD
DITAWNIT	BICALIC .	CENTURY WEST ZZ PROINFFRING	SITE PLAN	
144 144 144 144 144 144 144 144 144 144	ta ci	V., 2		SHEET NO
DHAWING .	,		CAYEC: 20516-001-07	



GROUNDWATER SAMPLING RECORD

AMPLE	NO.			MEIL NO	- IM-	- <i>f</i>
ROJECI	NAME /	5I		PROJECT	NO	
EIL DI	AMETER	WE	T DESIE		SCREEN IN	TERVAL
•						
TALC. F	TURGE H20 CC	E	_FT. (X)	** =	(X) 3	=GALS.
	TAZIZ					_
LABORAT	ORY		טק	rge/sampl	E METHOD_	
Weather	R CONDITIONS	<u> </u>	<u> </u>			
*****	VOLUME	27.02 50.43	かせいつ			************
TIME	(GALS.)	(GPM)	<u>(0)</u> (1) 7	COND.	<u>عة</u> مرحو	(TURBIDITY) SL COOK -/43~ \$ 5/1
		7	107	/ /-	1.77	
		4			272	1 . 3 . 5 pm 2 s
			775		′,	- •
<u></u>	•	<u> </u>				
						-
<u></u>						
	•					
Sample				<u> </u>		_
REMARI	\ <u></u>					



GROUNEWATER SAMPLING RECORD

					-	**************************************	
MPLE :		!		WELL NO.	1111	٠	<u> </u>
							 .
ELL DI	AMETER	wei	T DELLE	S	CREEN IN	TERVAL	
		PEAST INE				•	_
ALC. P	URGE H20 CO	ol.	FT, (X)	** = <u> </u>	(X) 3	=GA	LS.
AMA ÈA	LYSIS					•	
AEORAT	ORY		PU	rge/sampli	E METHOD_		
<i>i</i> eather	CONDITION	s					
*****			*****	****	****	*******	***
	AOTOWE AOTOWE	PUMP RATE	TEYP.	CONT	- -	REMARKS (TURBICITY)	3-
<u>TME</u>	(GALS.)	(GFM)	<u> </u>	191	حب <u>ح</u> ر	ره ومرد الادران	, - 5/
	, ,		100	1,25	- 	77.7	(<,
_			(2.5		<i>=d</i> 3	•	
	<u>!^</u>			337		li	
	<u> </u>					ч	
	· 23					•	
		ne can de la lace de lace de la lace de	62.7	7.00	7.20		· · ·
		-	·				
							
				201 L			
Sample	CZEH	MC2		MULI			No. 2 2 2



Client Name: Century West Engineering

Client Acet: 75300 NET Job No: 95.02081 Date: 06/02/1995

ELAP Cart: 1386 Page: 2

Ref: LSI (Oakland) Proj. No. 20515-901-13

SAMPLE DESCRIPTION: MW-1

Cace Taken: 05/13/1995

Time Taken:

NET Sample No: - 242569								Run
1122		-	Reportin	5	-	Cacs	Cace	Bacon
Parameter	Results	Flacs	<u> </u>	Units	Yechod	Exergenced	Analyzed	Уc
TPS (Gas/STXE, Liquid)								
METROD S030/M801S							05/31/1995	2983
OLLUTION, FACTOR-	<u>.</u>			-			05/31/1995	2383
as Gasoline	1.2		20.05	mg/L	5030		05/31/1995	2883
METHOD 3020 (GC.Liquid)							05/31/1995	2983
Senzene	14		0.5	ug/L	8020		05/31/1995	2981 -
Toluene	8.2		0.5	ug/L	3020		05/31/1995	2983
Sthylbenzene	. 12		0.5	ug/L	3020		05/31/1995	2983
Xylenes (Total)	6.2		0.5	ug/t.	3020		05/31/1995	2383
SURROGATE RESULTS	1						05/31/1995	2981
Bromofluorobenzene (SURR)	- 115			t Rec.	5030		05/31/1995	2983
MSTROD MSO15 (EXT., Liquid)	.·.	-				05/13/1395		
DILUTION FACTOR*	:						05/15/1995	1300
as Diesel	2.3	3L,3%	3.35	mg/L	3513		05/25/1995	1000

ON: The positive result appears to be a heavier hydrocarbon than Diesel. OL : The positive result appears to be a lighter hydrocarbon than Diesel.

÷ į

NOTE: Results apply only to the samples analyzed. Reproduction of this report is permitted only in its entirety.



Client Name:

Century West Engineering

Clienc Acct: 75300

NET Job No: 95.02983

Dace: 06/02/1995

Ref: LSI (Cakland) Proj. No. 20515-001-12

CONTINUING CALIBRATION VERIFICATION STANDARD REPORT

		CT!	CCT				
	cer	Standard	Standard				तथक
	Standard `	Amount	Amouns		t Cate	Analysc	Sacch Number
	f Recovery	Found	<u>Except ed</u>	<u> ೮೩೩೩೩</u>	Adalyzed		
PH (Gas/BTXE, Liquid)				•			
as Gasoline	95.0	0.43	a. 5a	mg/L	05/31/1995	aal	2883
Bensene	106.9	5.34	5.00	ಗಡೆ\ <u>೯</u>	05/31/1995	aai	2983
Toluene	97.2	4.35	5.00	ug/L	05/31/1995	<u> 441</u>	2883
Ethylbenzene	93.0	4.69	5.00	ug/L -	05/31/1995	aa!	2983
Xylenes (Total)	- 100.0	15.0	15.0	- ug/1 -	09/31/1999	a a i	2883
romofluorosenzene (SURR)	87.0	87	198	% Rec.	05/11/1995	aai	2993
STROD M861S (EXT., Liquid)	103.0	1030	1900	<u>π</u> φ/1	05/25/1995	:: s	1000

31 45



Client Name: Century West Engineering

Client Acc: 75300 NET Joo No: 95,0208

Dace: 06/02/199

Page: 5

Ref: LSI (Caxland) Proj. No. 20515-001-12

METHOD BLANK REPORT

	Mechod					
	31ack					₹धन
	Amount	yetozzrud	ebozzrud		Amalysc	Bacsa
Parameter	Found	Limit	Janes	Analyzed	Initials	Yumper
TPH (Gas/BTXE, Liquid)						
as Gasoline	ND.	0.05	` ~ mg/L [']	T05/31/1995	aa.	2385
3enzene '	NC	Q.5	45/1	QS/31/1995	aai	2883
Toluene	NC	0.5	ug/L	05/11/1995	aal	2283
Ethylbenzene	SID	0.5	ug/L	05/31/1995	aal	2993
Xylenes (Total)	МĎ	0.5	ug/1	05/31/1995	aal	2883
Sromofluorobensene (SURR)	35		Y Rec.	05/31/1995	aa.	2883
-METHOD M801S (EXT., Liquid)						
as Diesel	ND.	0.05	ag/L	05/26/1995	===	1000



KEY TO ABBREVIATIONS and METHOD REFERENCES

:	Less than;	When ag	pearing	; in results	column	india	ates analyte
	not detected				This	datum	anbercedes
	the listed	Reportin	ig Limit	Ξ.			•

: Reporting Limits are a function of the dilution factor for any given sample. To obtain the actual reporting limits for this sample, multiply the stated Reporting Limits by the dilution factor (but do not multiply reported values).

ICVS : Initial Calibration Verification Standard (External Standard).

mean : Average; sum of measurements divided by number of measurements.

mg/Kg (ppm) : Concentration in units of milligrams of analyte per kilogram of sample,

wet-weight basis (parts per million).

mg/L : Concentration in units of milligrams of analyte per liter of sample.

mL/L/hr : Milliliters per liter per hour.

MPN/100 mL : Most probable number of bacteria per one hundred milliliters of sample.

N/A : Not applicable.

NA : Not analyzed.

NO : Not detected; the analyte concentration is less than applicable listed

reporting limit.

NTU : Nephelometric turbidity units.

RPD : Relative percent difference, 100 (Value 1 - Value 2)/mean value.

SNA : Standard not available.

ug/Kg (ppb) : Concentration in units of micrograms of analyte per kilogram of sample,

wet-weight basis (parts per billion).

ug/L : Concentration in units of micrograms of analyte per liter of sample.

'umhos/cm : Hicromhos per centimeter.

Method References

¥.

Methods 100 through 491: see "Methods for Chemical Analysis of Water & Wastes", U.S. EPA, 600/4-79-020, rev. 1983.

Methods 601 through 625: see "Guidelines Establishing Test Procedures for the Analysis of Pollutants" U.S. EPA, 40 CFR, Part 136, rev. 1988.

Methods 1000 through 9999: see "Test Methods for Evaluating Solid Waste", U.S. EPA SW-846, 3rd edition, 1986.

 \underline{SM} : see "Standard Methods for the Examination of Water & Wastawater, 17th Edition, APHA, 1989.

SOIL BORING LOG TB-3Century West Engineering										
Site Location: LIQUID SUGARS, INC., EMERYVILLE CA							Boring ID: TB-3 Total Cepth: 11.5'			
Boring Location: S side of UST pit							on: Unknown	Initial GW Depth: 10'		
Purpose: Investigative							1 By: Jim Gribi	Final GW Depth:		
Date: November 7, 1991							Casing:	From:	To:	
Consulti	ng Film	: Century	West Engir	eering		Perfora	dons:	From:	To:	
Project I	lumber	20516-00	1-03			Filter S	and:	From:	To:	
Drilling (Contract	tor: Kvilhau	ıg Well Drill	ing		Benton	ite:	From:	To:	
Onlling	Method:	Hollow Ste	m Auger			Grout:	Cement/sand	From: 0	.0° To: 11.5°	
Depth	PID	Sample	Blow Counts	Profile	,	Soil Desc	aiption		Remarks & USCS Classification	
01 02 03	,				0.0 - 1.0 1.0 - 3.0	*** ·	Concrete and baseron Light gray SILT, clayer HC odor.		USCS: ML	
04 05					3.0 - 5.0		Dark gray silty CLAY, moist, faint HC odor.	firm, hard,	USCS: CL	
<u>06</u> <u>07</u> <u>08</u>	490	TB-3.1	12 24 50		5.0 - 11.5		Grav green clavev GR	AVEL clasts -	USCS: GC-GM	
<u>09</u> 10		,	` .	, ^ -	. # . 	·-	Gray green clayey GR 1/4" to 1+" subrounder moist to saturated, fair HC odor.	id, very sandy, nt to moderate	Ground water = 10'	
11 12 13 14 15	180	TB-3.2	2149 22		Total Dept	<u>h - 11.5'</u>	in the second se			
v	,		-							

· n

· Wash

modern of which is the processing of the contraction of the contractio

SOIL BORING LOG TB-5 Century West Engineering									
Site Location: LIQUID SUGARS, INC., EMERYVILLE, CA						Baring ID: TB-5	Total Deoth: 11.5		
Boring L	ocation	: SE side of	UST oit			Elevation: Unknown	Initial GW Depth: 10.5		
Purcose	: Invest	igative				Logged By: Jim Gribi Final GW Depth:			
Date: N	ovembe	r 7, 1991				Blank Casing:	From:	Ta:	
Consulti	ng Firm	: Century	West Engin	eering		Perforations:	From:	To:	
Project i	Number	20516-00	1-03			Filter Sand:	From:	Ta:	
Drilling (Contract	or: Kvilha	ug Weil Drill	ing	سينا الريا	Bentonite:	From:	To:	
Orilling I	vethod:	Hollow St	em Auger			Grout: Cement/sand	From: 0	.0' To: 11.5'	
Depth	PID	Sample ID	Blow Counts	Profile	٠	Soil Description	-	Remarks & USCS Classification	
01 02 03 04 05 05 07 08 09	280	TB-5.1	8 20 42		0.0 - 1.0 1.0 - 8.0 8.0 - 11.5	Dark gray green CLAY, sim, slightly gravely, mois moderate HC odor.	E_ clasts - verv sandv.	USCS: CL	
11 12 13 14 15	180	T8-5.2	25 42 20		Total Dec	th <u>- 11.5°</u>		Ground water = 10.5*	

~~~

-,4-1

\*

| SOIL BORING LOG TB-7Century West Engineering       |                |              |                |         |                                      |                                                                                                                                                                                                     |            |                                  |  |
|----------------------------------------------------|----------------|--------------|----------------|---------|--------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|----------------------------------|--|
| Site Location: LIQUID SUGARS, INC., EMERYVILLE, CA |                |              |                |         |                                      |                                                                                                                                                                                                     |            | ooth: 11.5'                      |  |
| Boring Location: W of UST oit, step out            |                |              |                |         |                                      |                                                                                                                                                                                                     |            | il GW Deoth: 10°                 |  |
| Purpose                                            | Invest         | igative      |                |         |                                      | Logged By: Jim Gribi                                                                                                                                                                                | W Deoth:   |                                  |  |
| Date: N                                            | ovembe         | r 7. 1991    |                |         |                                      | Blank Casing:                                                                                                                                                                                       | From:      | Ta:                              |  |
| Consulti                                           | ng Fim         | n: Century   | West Engir     | eering  |                                      | Perforations:                                                                                                                                                                                       | From:      | Ta:                              |  |
| Project N                                          | łumber         | 20516-00     | 1-03           |         |                                      | Filter Sand:                                                                                                                                                                                        | From:      | To:                              |  |
| Drilling (                                         | Contract       | or: Kvilha   | ug Well Driil  | ing     |                                      | Bentonite:                                                                                                                                                                                          | From:      | To:                              |  |
| Orilling I                                         | Method:        | Hollow St    | em Auger       |         |                                      | Grout: Cement/sand                                                                                                                                                                                  | From: 0    | ).0' To: 11.5'                   |  |
| Depth                                              | 윈              | Sample<br>ID | Blow<br>Counts | Profile |                                      | Soil Description                                                                                                                                                                                    |            | Remarks & USCS<br>Classification |  |
| 01<br>82<br>84<br>85<br>86<br>87<br>88<br>88       | 175            | TB-7.1       | 12<br>25<br>50 |         | 0.0 - 1.0<br>1.0 - 7.0<br>8.0 - 11.5 | Concrete and baserock.  Dark gray CLAY, slightly slith slightly gravely, moist, faint fodor.  Olive gray to Gray green Sit. some large gravel clasts - 1/1+" subrounded, moist to sa faint HC odor. | T, sandy,  | USCS: CL                         |  |
| 10                                                 | 140            | TB-7.2       | 12             | -       |                                      | faint HC odor.                                                                                                                                                                                      | <u> </u>   | Ground water * 10*               |  |
| 11<br>12<br>13<br>14<br>15                         |                | · ~ · `      | 12<br>25<br>30 |         | Total Dept                           | h - 11.5°                                                                                                                                                                                           |            | -                                |  |
| ·                                                  | and the second | ·            |                |         |                                      |                                                                                                                                                                                                     | - سىسى سام |                                  |  |

المراد مراق و عليه را

e de la companya del companya de la companya del companya de la co

المائير المائوي المستعرف بالمائيس البالي المعسد