

PHOTOS TAKEN BY RON OWCARZ
AT UGT MODIFICATION AT VICKY
SHELL, 2120 MONTANA ST. IN OAK,
ON 7/6, 7/19 + 7/20/93



7/20/93-Photo taken by Ron Owcasz at Bangal shell, 2120 Montana Ave. in Oak. Red caps indicate soil sample locations in side wall of pit overexcavation for UGT pipe work. ©



7/20/93 Photo taken by Ron Owcasz at shell station @ 2120 Montana Ave. in Oak for piping of UGT work where soil contamination was found at pit overexcavation. ©



7/20/93-Photo taken by Ron Owcasz at Bangal shell, 2120 Montana Ave. Oak. Shown is soil cont. at side wall of pit overexcavation for UGT pipe work. ©



7/19/93-Photo taken by Ron Oweasz at Banzal
Shell, 2120 Montana Ave, Oak. Shown is Allison
Watts taking soil samples at pit overexcavation. ©



7/19/93-Photo taken by Ron Oweasz at Banzal
Shell, 2120 Montana Ave, Oak. Shown is Allison
Watts taking soil samples after pit reexcavation. ©



7/6/93-Photo taken by Ron O'Carroll at Bansal shell, 2120 Montana Ave, Oak. Shown is Allison Watts taking soil sample in side wall of pit where cont. was found at UGT piping mod. @



7/6/93-Photo taken by Ron O'Carroll at Bansal shell, 2120 Montana Ave, Oak. Shown is Allison Watts taking soil sample at end of old piping where some soil cont. was observed. @



7/6/93-Photo taken by Ron O'Carroll at Bansal shell, 2120 Montana Ave, Oak. Shown is new sump that failed sump test twice. Also note oil cont. of side wall adjacent to it. @



7/6/93-Photo taken by Ron Owcasz at Banzal shell, 2120 Montana Ave. Oak. Shown is soil sample location at end of old pipe line for UAT mud. 12215117976-B



7/6/93-Photo taken by Ron Owcasz at Banzal shell, 2120 Montana Ave. Oak. Shown is Allison Watts taking soil sample under middle of old piping where some soil cont. was observed. 12215117976-B