



R0253
76 Broadway
Sacramento, CA 95818
phone 916.558.7876
fax 916.558.7699

August 2, 2005

Mr. Don Hwang
Alameda County Health Agency
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502

Re: **Document Transmittal**
Fuel Leak Case
76 Station #5781
3535 Pierson Street
Oakland, CA

Dear Mr. Hwang:

Please find attached TRC's *Quarterly Status Report, dated 7/29/05* for the above referenced site. I declare, under penalty of perjury, that to the best of my knowledge the information and/or recommendations contained in the attached proposal or report are true and correct.

If you have any questions or need additional information, please call me at (916) 558-7666.

Sincerely,

A handwritten signature in cursive script, appearing to read "Thomas H. Kosel".

Thomas H. Kosel
Site Manger, Risk Management and Remediation
ConocoPhillips
76 Broadway, Sacramento, CA 95818

Attachment

cc: Roger Batra, TRC



Customer-Focused Solutions

July 29, 2005

TRC Project No. 42010205

Mr. Don Hwang
Alameda County Health Services
1131 Harbor Bay Parkway
Alameda, CA 94502-6577

**RE: Quarterly Status Report - Second Quarter 2005
76 Service Station #5781, 3535 Pierson Street, Oakland, California
Alameda County**

Dear Mr. Hwang:

On behalf of ConocoPhillips Company (ConocoPhillips), TRC is submitting the Second Quarter 2005 Quarterly Status Report for the subject site.

PREVIOUS ASSESSMENTS

The subject site is currently an operating service station located on the northwest corner of the intersection of Pierson Street and the Highway 580 off ramp in Oakland California. Station facilities include two 12,000-gallon double-wall fiberglass clad steel gasoline underground storage tanks (USTs), one 520-gallon fiberglass clad steel waste oil UST, two dispenser islands and associated double-walled fiberglass piping, and a station building.

December 1989: Two 10,000 gallon steel fuel USTs and one 280-gallon steel waste oil UST and associated product piping were removed. No holes or cracks were observed in the gasoline USTs, however a hole was observed in the waste oil UST. Confirmation soil sampling was conducted. Petroleum hydrocarbon levels were non-detect or low beneath the fuel USTs and piping. Total oil and grease (TOG) levels were elevated beneath the waste oil tank. The waste oil UST pit was over-excavated to the extent permitted by the station building and buried utilities. Four sidewall samples were collected at depths ranging from 9 to 10 feet below ground surface (bgs) following the over-excavation. Maximum residual TOG levels were elevated.

April 1990: Three exploratory soil borings were advanced to depths ranging from approximately 40 to 50 feet bgs, and soil samples were collected. Petroleum hydrocarbon levels were non-detect in the soil samples. Since groundwater was not encountered, monitoring wells were not installed.

July 1990: Two soil borings were advanced adjacent to the former waste oil tank cavity to determine if waste oil impacted soil was limited to the immediate area surrounding the former waste oil UST. Groundwater was encountered at depths from approximately 33.5 to 36.7 feet bgs and a grab groundwater sample was collected from each boring. Maximum levels of petroleum hydrocarbons and volatile organic compounds in soil and grab groundwater samples were non-detect to low.

December 1991: One monitoring well was installed to a depth of 45 feet bgs.

October 2003: Site environmental consulting responsibilities were transferred to TRC.

SENSITIVE RECEPTORS

According to information in Geotracker, four active wells owned by East Bay Regional Park District are located 2,193 feet northeast of site.

MONITORING AND SAMPLING

One well is currently monitored annually. The next monitoring and sampling event is scheduled for the first quarter of 2006.

CHARACTERIZATION STATUS

The site is monitored and sampled annually.

REMEDIATION STATUS

December 1989: The waste oil UST pit was over-excavated to 16 feet bgs, approximately 35 feet to the east, 10 feet to the west, 15 feet to the south, and 2 feet to the north. The station building and buried utilities prevented further excavation except to the east.

Remediation is not currently being conducted at the site.

RECENT CORRESPONDENCE

No correspondence this quarter.

CURRENT QUARTER ACTIVITIES

No gauging or sampling was performed this quarter.

NEXT QUARTER ACTIVITIES


Continue annual monitoring and sampling until case closure is granted.

QSR – Second Quarter 2005
76 Service Station #5781, Oakland, California
July 29, 2005
Page 3

If you have any questions regarding this report, please call me at (925) 688-2466.

Sincerely,

TRC



Roger Batra
Senior Project Manager

cc: Thomas Kosel, ConocoPhillips (hard copy and electronic upload)