

4057 Port Chicago Highway, Concord, CA 94520 (415) 671-2387

FAX: (415) 685-9148

February 1, 1993

Project No. 020501659

Ms. Anne Lunt Safety-Kleen Corporation P.O. Box 1429 San Pedro, CA 90733-1421

RE:

Product Recovery Volume-January 1993 Safety-Kleen Facility 400 Market Street Oakland, California

Dear Ms. Lunt:

The purpose of this letter is to report the volume of product recovered during the first two weeks of January 1993 for the site referenced above. The recovery well (RW) and monitoring well MW-9 have been monitored for product thickness and the product has been removed from the wells by hand bailing on a weekly basis.

Table 1 (attached) provides a tabulation of product thickness measurements for the two wells and the approximate product volumes removed from the wells. Please note that the installation of the product recovery system was initiated on January 15, 1993. On that day, product was not bailed from RW to allow for startup testing of the product recovery system.

Please contact me if you have any questions or require additional information, it can be reached in our Concord office at (510) 671-2387.

Sincerely,

Groundwater Technology, Inc.

MICHAEL J. WRAY Project Manager

Attachments

TABLE 1
WEEKLY PRODUCT RECOVERY VOLUME
SAFETY-KLEEN CORPORATION FACILITY
400 MARKET STREET, OAKLAND, CALIFORNIA

	RW			MW-9		
	Depth-to Product (ft)	Product Thickness (ft)	Approx. Product Volume Bailed (gals)	Depth-to Product (ft)	Product Thickness (ft)	Approx. Product Volume Bailed (gals)
01/05/93	6.58	0.41	.5	7.47	0.53	<.5
01/15/93	6.12	0.42	0	7.0	0.3	<.5



^{*} Note: Product was not removed from RW to allow for testing of the product recovery system being installed.