



B3-652  
NEW  
DB

ONE OF THE NPCI  
COMPANIES

B C C

BENEFIT  
CAPITAL  
CORPORATION

1330 BROADWAY  
SUITE 500  
OAKLAND, CA 94612  
415 834-1337

CALIFORNIA REGIONAL WATER

MAY 13 1987

QUALITY CONTROL

April 29, 1987

Mr. Peter Johnson  
California Regional Water Quality Board  
for the San Francisco Bay Region  
111 Jackson Street, Room 6000  
Oakland, CA 94607

B3-652  
5/23/87

Re: 1650 - 65th Street, Emeryville, CA

1 ALAMEDA

Dear Mr. Johnson:

Please accept this letter as written notice of possible excessive hydrocarbon content in the soil at the above location. This letter is to confirm the verbal notice given to your department on April 27, 1987, in accordance with the requirements of proposition 65. Attempts were made to contact you by telephone directly on April 27, 28, and 29, but we have not received any return calls.

Only one test on a sample from one borehole shows excess hydrocarbons at this early stage, but obviously we are concerned, and wish to investigate this matter thoroughly. To do this we have employed Mr. Trevor Pitts of Zero Waste Systems, Inc. to do further studies. Mr. Pitts can be reached at (415) 893-8257.

Please contact me or Mr. Pitts directly if you require further information. I look forward to cooperating with your department to fully resolve this matter should further investigation confirm the preliminary results.

Sincerely,

Ronald V. Schwartz  
President

RVS/ajd

cc: Trevor Pitts  
Kenneth W. Ruthenburg, Jr.  
Mark Scher

"because you've earned it"

**ES**

*S&B GSZ*

*117 652 11/16/87*

**TRANSMITTAL**

**ENGINEERING — SCIENCE, INC.  
600 BANCROFT WAY  
BERKELEY, CALIFORNIA 94710  
(415) 548-7970**

Date: 17 September 1987  
ES Project No. NC049.03

IF MATERIAL NOT AS LISTED,  
PLEASE NOTIFY US AT ONCE

To: REGIONAL WATER QUALITY CONTROL BOARD  
1111 JACKSON STREET, ROOM 6040  
OAKLAND, CA 94607

**CALIFORNIA REGIONAL WATER**

**SEP 28 1987**

Attn: GREG ZENTNER

Re: \_\_\_\_\_

**QUALITY CONTROL BOARD**

**WE ARE SENDING YOU**

- ATTACHED       UNDER SEPARATE COVER VIA \_\_\_\_\_
- SHOP DRAWINGS       TRACINGS
- PRINTS       CATALOGS
- DOCUMENTS       COPY OF LETTER
- SPECIFICATIONS       \_\_\_\_\_

COPIES	DATE	ITEM
1	9/17	FINAL REPORT FOR THE UNDERGROUND STORAGE TANK CLOSURE INVESTIGATION, (650 65TH STREET), PROPERTY, (EMERYVILLE, CA)
		<i>(Benefit Capital Corp)</i>
		<i>Emeryville Bayfront Limited Partnership</i>

REMARKS \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**COPY TO**

- File
- Author
- Reading File
- \_\_\_\_\_

SIGNED *[Signature]*  
RICHARD S. MAKDISI

# ES ENGINEERING-SCIENCE

600 BANCROFT WAY • BERKELEY, CALIFORNIA 94710 • 415/548-7970

18 September 1987

Ref: NC049.03

CALIFORNIA REGIONAL WATER

SEP 28 1987

QUALITY CONTROL BOARD

Emeryville Bay Front Limited Partnership  
c/o Ronald V. Schwartz, President  
Benefit Capital Corporation  
1330 Broadway, Suite 500  
Oakland, California 94612

Subject: Underground Fuel Storage Tank Site Investigation near the  
Southeast Corner of the Warehouse Building, 1650 65th Street  
Property, Emeryville, California

## INTRODUCTION


This report describes the implementation of the underground fuel storage tank site characterization plan submitted to Benefit Capital Corporation (BCC) by Engineering-Science (ES) in a letter proposal dated 25 June 1987. The scope of this work included observation of removal of the abandoned Underground Storage Tank (UST) by Cleveland Wrecking Company (CWC), soil sampling beneath the UST, and installation of a groundwater monitoring well if warranted by evidence of soil contamination.

## SITE LOCATION AND HISTORY


The property, approximately 5.5 acres, is located in western Emeryville two blocks south of the Emeryville/Berkeley city boundary. Figure 1 is a site location map. Originally below sea level, the property was used as a municipal disposal site from the early 1940's to the late 1950's. Following construction of the existing warehouse in the mid-1950's, the property was leased to the supermarket company, Louis Stores, which used the warehouse as a distribution center. From 1973 to the present, the United States Post Office has occupied the warehouse, using it for storage and distribution of postal service equipment. Figure 2 is a site plan of the 1650 65th Street property.

The abandoned UST is located near the southeast corner of the warehouse building. It has an estimated 2,000 gallon capacity and was probably installed over 20 years ago. The tank initially contained gasoline and later stored waste oil.

FIGURE 1




# SITE PLAN



## LEGEND


- MW-1 ○ MONITORING WELL INSTALLED BY ENGINEERING-SCIENCE
- EB-6 ● APPROXIMATE LOCATION OF EXPLORATORY BORINGS, PETER KALDVEER AND ASSOCIATES 1987
- EXCAVATED TANK

BASE: PETER KALDVEER AND ASSOCIATES, INC. 1987, FROM 'TOPO MAP', BY TRONOFF ASSOCIATES, DATED FEBRUARY 3, 1983



ENGINEERING-SCIENCE

FIGURE 2



Emeryville Bay Front Limited Partnership

18 September 1987

Page 4

#### TANK CLOSURE ACTIVITIES

CWC excavated the UST on 2 July 1987 and hauled it off-site. Figure 3 shows the excavation boundaries, tank and piping layout and soil sampling locations. A small volume of residual oily sludge was pumped from the tank prior to tank removal. Excavation began with removal of the vent and product line pipes; strong hydrocarbon odors emanated from soil removed from this area. A small amount of gasoline spilled from the product line piping during its removal. Excavation of the tank itself revealed no indication of contamination; the clayey soil and sandy fill excavated from around the tank exhibited no odor. Following completion of each excavation section, CWC immediately backfilled each excavated area with soil removed from that area. Documentation of the excavation in the form of copies of permits and shipping manifests has already been provided to BCC by Cleveland Wrecking Company. Photographic documentation of the excavation is presented in Appendix A.

The tank, vent pipe, product line and fittings were examined by ES personnel for signs of corrosion and holes. The tank, vent lines and product lines were in good condition and showed no signs of corrosion. The product line fittings were rusty, however.

ES personnel collected three soil samples during the tank excavation: one from beneath the product line (FP-1) and one from beneath both the northern (N-1) and the southern (S-1) end of the tank. The samples, collected in 2-inch brass tubes, were analyzed for total fuel hydrocarbons (EPA Method 8015), aromatic volatile organics (EPA Method 8020) and for lead. Only sample FP-1, with 490 mg/kg total petroleum hydrocarbons, had a significant level of contamination. Analytical results are summarized in Table 1. Complete analytical results are presented in Appendix B. Chain of custody records are included in Appendix C.

#### GROUNDWATER MONITORING WELL INSTALLATION

Because the contaminant level in soil sample FP-1 exceeded the 100 ppm limit established by the Regional Water Quality Control Board (RWQCB), a groundwater monitoring well was installed to determine the effect of soil contamination on ground water quality. The well site, selected to be downgradient of the UST contaminant source, was located west of the UST excavation and north of the product line trench. This was near the area where Sample FP-1 was collected.

Well installation occurred on 27 July and began with drilling of a borehole roughly 3 feet west of the excavation. Metal scraps encountered 15 feet below ground surface caused drilling refusal and required abandonment of the initial borehole. A second borehole was drilled roughly three feet west of the initial borehole. This borehole was completed as the 30-foot deep monitoring well MW-1. Figure 3 shows the locations of the abandoned borehole and Monitoring Well MW-1.

TABLE 1  
SUMMARY OF SOIL AND GROUNDWATER ANALYTICAL RESULTS

Sample I.D.	Matrix	Total Fuel Hydrocarbons	Analysis		Lead (mg/kg, dry)
			EPA Method 8020		
			Toluene (ppm)	Xylene (ppm)	
N-1	Soil	<.01 ppm	<.03	<.04	5
S-1	Soil	<.01 ppm	<.03	<.04	4.8
FP-1	Soil	490 ppm	0.90	23	36
MW-5	Soil	170 mg/kg	NA	NA	NA
MW-10	Soil	6,600 mg/kg	NA	NA	NA
MW-1	Water	33 mg/l	NA	NA	NA

NA - not analyzed.



Emeryville Bay Front Limited Partnership

18 September 1987

Page 7

Hydrocarbon odors were detected in both borings. The strongest hydrocarbon odors detected during drilling of Monitoring Well MW-1 were in soil cuttings from 13 to 16 feet below ground surface; a mild gasoline odor was detected in cuttings from 17 to 23 feet below ground surface. In the abandoned borehole, a strong gasoline odor was observed in saturated, sandy cuttings originating from 12 to 15 feet below ground surface. Geologic logs for both the abandoned borehole and Monitoring Well MW-1, along with construction details for MW-1, are presented in Appendix D.

During drilling of the initial borehole, two soil samples were collected by California modified split spoon sampler: one at a depth of 5 feet (MW-5) and one at a depth of 10 feet (MW-10). These samples were analyzed for total fuel hydrocarbons by EPA Method 8015. Results are summarized in Table 1. Complete analytical results are presented in Appendix B. Appendix C contains chain of custody records. No additional samples were collected during drilling of the borehole completed as the monitoring well, MW-1.

Monitoring Well MW-1 was sampled on 28 July 1987. The sample, MW-1, was collected with a quartz teflon bailer and analyzed by EPA Method 8015 for total fuel hydrocarbons. No free product was found floating on the groundwater surface on 28 July or on 17 August, when the site was visited again. However, both times the groundwater was yellow and had a strong gasoline odor. Groundwater level, measured on 17 August following a period of equilibration, was 12.27 feet below ground surface. The groundwater sample analytical results are summarized in Table 1 and presented in full in Appendix B. Sampling notes and chain of custody records are presented in Appendix C.

#### SOIL AND GROUNDWATER SAMPLING RESULTS

Analytical results of soil and water samples revealed moderate (>100 - <1,000 ppm) to high (>1,000 ppm) soil contamination west of the UST and low level (<100 ppm) contamination of ground water. The highest contamination in the soil, 6,600 ppm total petroleum hydrocarbons, was found 10 feet below ground surface (MW-10) while shallower samples ranged from 170 ppm (MW-5) to 490 (FP-1) ppm total fuel hydrocarbons. Analysis revealed 33 mg/l total fuel hydrocarbons in the groundwater. Conversations with laboratory chemists indicated that, for samples MW-5 and MW-10, gasoline was the major fuel hydrocarbon detected. Some long chain hydrocarbons, indicative of petroleum hydrocarbons such as oil, were also noted by the laboratory chemists; these were not included in the soil analysis results.

Because gasoline was the major hydrocarbon detected in the soil samples, contamination probably occurred as a result of gasoline leaking from the UST or as a result of gasoline spills. The lower concentration of MW-5 compared to MW-10 indicates that if spills rather than leaks caused contamination, the spills did not occur in the vicinity of the abandoned borehole where samples MW-5 and MW-10 were collected. If leaks were responsible for the contamination, they probably were in the product line

Emeryville Bay Front Limited Partnership

18 September 1987

Page 8

fittings since no corrosion or holes were observed on the tank itself. It is unlikely that an UST other than the one excavated could be responsible for the hydrocarbon contamination. The closest known UST is north of the site, near EB-7 (Figure 2); this UST is too far away to explain the high levels of contamination in the soil relative to those in the groundwater. If the UST near EB-7 were the origin of contaminants detected in monitoring well MW-1, high contaminant concentrations in the water relative to the soil would be expected.

The remediation for the site depends upon the extent of contamination. The RWQCB guidelines require excavation of soil containing greater than 1000 ppm total petroleum hydrocarbons and quarterly sampling of UST monitoring wells. In addition, a site having greater than 1000 ppm hydrocarbons must be ranked to determine the need for additional remediation procedures. An Unauthorized Release Contamination Report detailing contaminant concentrations, sent to the County of Alameda Environmental Health Services Hazardous Materials Management Program and to the RWQCB, is included in Appendix D.

The extent of the soil containing greater than 1000 ppm cannot be determined from contamination characterization done to date. High levels of contamination extend west of the UST at least as far as the abandoned borehole from which the samples were collected. Previous site investigations (Reference 1) detected total petroleum hydrocarbons at a level of 200 ppm east of the excavation (soil boring EB-5, Figure 2). This suggests that moderate levels of contamination originating from the UST have migrated eastward despite the absence of petroleum hydrocarbons in the samples collected from below the UST or that gasoline spills may have occurred east of the excavation.

#### CONCLUSIONS

- ° One underground storage tank and associated vent and product pipes were removed from the vicinity of the southeast corner of the warehouse building. The tank and piping were in good shape; the product line fittings were rusty.
- ° Hydrocarbon odors were detected in soils excavated from around the product line. A soil sample from this area had 490 ppm total petroleum hydrocarbons. Soil and samples from the main excavation were clean.
- ° Soil samples were collected from a 15 foot borehole situated west of the tank excavation. The soil sample taken at a depth of 5 feet revealed moderate levels of hydrocarbon contamination. The soil sample collected at 10 feet contained hydrocarbons at 6,600 mg/kg; this exceeds the 1,000 ppm total petroleum hydrocarbons limit established in the Regional Water Quality Control Board UST guidelines and the Alameda County Environmental Health Department. Soil with contamination exceeding this limit requires excavation for treatment or disposal to a Class 1 landfill.

Emeryville Bay Front Limited Partnership

18 September 1987

Page 9

- A 30-foot monitoring well, MW-1, was installed west of the tank excavation. A groundwater sample from this well contained 33 mg/l hydrocarbons.

Previous site investigations indicate that moderate level hydrocarbon contamination, probably originating from the removed tank, exists east of the excavation area.

#### RECOMMENDATIONS


- Soil sampling to define extent of soil containing greater than 1000 ppm total petroleum hydrocarbons
- Excavation and disposal of the contaminated soil to a Class I hazardous waste landfill by a State of California Certified Hazardous Waste Hauler and/or treatment of the contaminated soil by aeration/ bacterial degradation enhancement.
- Ranking of site to determine additional remedial actions required by the RWQCB
- Quarterly sampling of the groundwater monitoring well for a period of one year (three more quarterly samplings) to determine seasonal fluctuation of groundwater contamination, if any.

It has been a pleasure to provide Benefit Capital Corporation with the requested services. Should you have any questions, please call.


Very truly yours,



Katherine A. Chesick  
Project Geohydrologist



Dan B. McCullar  
Senior Geohydrologist



Richard S. Makdisi  
Project Manager

dkm/337.23

cc: Mark Sher/Dan Norse, Wareham Development  
Lee Eisner, Wareham Development  
Ted Gerow, Alameda County Environmental  
Health Department  
Greg Zentner, RWQCB

REFERENCES

1. Peter Kaldveer and Associates, Inc., 1987, Site Characterization and Preliminary Soil Testing 1650 65th Street Warehouse Emeryville, California.

APPENDIX A  
PHOTOGRAPHIC DOCUMENTATION  
OF THE UST EXCAVATION

Client BCC  
Subject UST DEMOLITION/  
SITE CHARACTERIZATION

Job No. NC049.00  
By RSM  
Checked \_\_\_\_\_

Sheet 1 of 3  
Date 8/13/87  
Rev. \_\_\_\_\_



PHOTO 1: General view of UST Intake and preparation of dry Ice Installation.



PHOTO 2: Dry Ice Installation Into UST.

Client BCC  
Subject UST DEMOLITION/  
SITE CHARACTERIZATION

Job No. N1049.00  
By RSM  
Checked \_\_\_\_\_

Sheet 2 of 3  
Date 8/13/87  
Rev. \_\_\_\_\_



PHOTO 3: Upending of tank in excavation:  
Some breakage of tank occurred during removal.



PHOTO 4: Close-up of rupture created during removal.

ENGINEERING-SCIENCE

Client BCC  
Subject UST DEMOLITION/  
SITE CHARACTERIZATION

Job No. NCO49.00  
By RSM  
Checked \_\_\_\_\_

Sheet 3 of 3  
Date 8/13/87  
Rev. \_\_\_\_\_




PHOTO 5: Excavation after UST removal.





PHOTO 6: UST showing area of rupture near vent pipes created during UST removal.



**TMA**  
Thermo Analytical Inc.



TMA/Norcal  
2030 Wright Avenue  
Richmond, CA 94804-0040  
(415) 235-2633

July 20, 1987

Engineering Science  
600 Bancroft Way  
Berkeley, CA 94710

Attention: Mr. Wang

Dear Mr. Wang:

Please find enclosed the analytical report for fuel analysis from our Los Angeles based laboratory, TMA/ARLI. TMA/ARLI is certified by the State of California for hazardous waste testing by Gas Chromatography. TMA/Norcal is certified in many of the other categories including inorganics, GC/MS and pesticides. Completion of our certification for fuel and general GC should be quite soon.

The results for lead analysis and percent moisture are as follows:


---

<u>Sample Identification</u>		<u>Lead</u>	<u>Moisture</u>
<u>Client</u>	<u>TMA/Norcal</u>	<u>mg/kg dry</u>	<u>%</u>
N-1	2226-40-2	5.0	11.0
S-1	2226-40-4	4.8	1.7
FP-1	2226-40-6	36	7.53

---

Please contact me if you have any questions regarding this report.

Sincerely,



Mary Janney  
Program Manager


MJ/dss

Enclosure

07/15/87 11:43:33

REPORT TMA/NORCAL  
TO 2030 Wright Ave  
Richmond, CA 94804

PREPARED Thermo Analytical, Inc.  
BY 160 Taylor Street  
Monrovia, CA 91016

  
CERTIFIED BY

ATTEN Sample Control

ATTEN \_\_\_\_\_  
PHONE 818-357-3247

CONTACT JSC

CLIENT TMA NORCAL      SAMPLES 3  
COMPANY TMA/NORCAL  
FACILITY \_\_\_\_\_

This report is for the sole and exclusive use of the client to whom it is addressed. Samples not destroyed in testing are retained a maximum of thirty (30) days unless otherwise requested.

WORK ID Project No. 2226-40  
TAKEN By Unknown  
TRANS By Federal Express  
TYPE Soils  
P. O. # 6463  
INVOICE under separate cover

Data Reported by Telecon 7/9/87

SAMPLE IDENTIFICATION

- 01 N-1
- 02 S-1
- 03 FP-1

TEST CODES and NAMES used on this report

- 8015M Fuels-Total Hydrocarbons
- 8020 Aromatic Volatile Organics



Results by Sample

SAMPLE ID N-1

FRACTION Q1A TEST CODE 8015M NAME Fuels-Total Hydrocarbons  
Date & Time Collected not specified Category

MODIFIED 8015 - FUEL HYDROCARBONS

COMPOUND	RESULT	DET	LIMIT	ANALYST
C5 - C12 Hydrocarbons	<u>ND</u>		0.1	<u>YY</u>
C10 - C16 Hydrocarbons	<u>ND</u>		0.1	DATE INJECTED <u>07/07/87</u>
C9 - C22 Hydrocarbons	<u>ND</u>		0.1	DILUTION FACTOR <u>1.00</u>
C9 - C14 Hydrocarbons	<u>ND</u>		0.1	VERIFIED <u>JSC</u>

NOTE: All results reported in ppm unless otherwise specified  
ND = Not detected at the specified limits

SAMPLE ID N-1 FRACTION 01A TEST CODE 8020 NAME Aromatic Volatile Organics  
Date & Time Collected not specified Category \_\_\_\_\_

8020 AROMATIC VOLATILE ORGANICS

COMPOUND	RESULT	DET	LIMIT	ANALYST	MLH
Benzene	ND		0.03	DATE INJECTD	07/07/87
Chlorobenzene	ND		0.03	DILUTION FACTOR	1.00
1,2-Dichlorobenzene	ND		0.04	VERIFIED	JSC
1,3-Dichlorobenzene	ND		0.04		
1,4-Dichlorobenzene	ND		0.04		
Ethylbenzene	ND		0.04		
Toluene	ND		0.03		
Xylenes (Dimethylbenzenes)	ND		0.04		

NOTE: All results reported in ppm unless otherwise specified  
ND = Not detected at the specified limits

Results by Sample

SAMPLE ID S-1 FRACTION 02A TEST CODE 8015M NAME Fuels-Total Hydrocarbons  
Date & Time Collected not specified Category \_\_\_\_\_

MODIFIED 8015 - FUEL HYDROCARBONS

COMPOUND	RESULT	DET	LIMIT	
C5 - C12 Hydrocarbons	<u>ND</u>		0.1	ANALYST <u>YY</u>
C10 - C16 Hydrocarbons	<u>ND</u>		0.1	DATE INJECTED <u>07/07/87</u>
C9 - C22 Hydrocarbons	<u>ND</u>		0.1	DILUTION FACTOR <u>1.00</u>
C9 - C14 Hydrocarbons	<u>ND</u>		0.1	VERIFIED <u>JSC</u>

NOTE: All results reported in ppm unless otherwise specified  
ND = Not detected at the specified limits

SAMPLE ID S-1 FRACTION 02A TEST CODE 8020 NAME Aromatic Volatile Organics  
Date & Time Collected not specified Category \_\_\_\_\_

8020 AROMATIC VOLATILE ORGANICS

COMPOUND	RESULT	DET	LIMIT
Benzene	ND		0.03
Chlorobenzene	ND		0.03
1,2-Dichlorobenzene	ND		0.04
1,3-Dichlorobenzene	ND		0.04
1,4-Dichlorobenzene	ND		0.04
Ethylbenzene	ND		0.04
Toluene	ND		0.03
Xylenes (Dimethylbenzenes)	ND		0.04

ANALYST MLH  
DATE INJECTD 07/07/87  
DILUTION FACTOR 1.00  
VERIFIED JSC

NOTE: All results reported in ppm unless otherwise specified  
ND = Not detected at the specified limits

Results by Sample

SAMPLE ID FP-1 FRACTION Q3A TEST CODE 8015M NAME Fuels-Total Hydrocarbons  
Date & Time Collected not specified Category \_\_\_\_\_

MODIFIED 8015 - FUEL HYDROCARBONS

COMPOUND	RESULT	DET	LIMIT	ANALYST	YY
C5 - C12 Hydrocarbons	<u>ND</u>		0.1		
C10 - C16 Hydrocarbons	<u>ND</u>		0.1	DATE INJECTED	<u>07/07/87</u>
C9 - C22 Hydrocarbons	<u>ND</u>		0.1	DILUTION FACTOR	<u>1.00</u>
C9 - C14 Hydrocarbons	<u>490.</u>		0.1	VERIFIED	<u>JSC</u>

NOTE: All results reported in ppm unless otherwise specified  
ND = Not detected at the specified limits

Received: 07/06/87

## Results by Sample

SAMPLE ID FP-1FRACTION 03ATEST CODE 8020NAME Aromatic Volatile OrganicsDate & Time Collected not specifiedCategory 

## 8020 AROMATIC VOLATILE ORGANICS

COMPOUND	RESULT	DET	LIMIT
Benzene	<u>ND</u>		1.0
Chlorobenzene	<u>ND</u>		1.0
1,2-Dichlorobenzene	<u>ND</u>		1.1
1,3-Dichlorobenzene	<u>ND</u>		1.1
1,4-Dichlorobenzene	<u>ND</u>		1.1
Ethylbenzene	<u>ND</u>		1.1
Toluene	<u>0.90</u>		0.90
Xylenes (Dimethylbenzenes)	<u>23.</u>		1.1

ANALYST	<u>MLH</u>
DATE INJECTD	<u>07/07/87</u>
DILUTION FACTOR	<u>1.00</u>
VERIFIED	<u>JSC</u>

NOTE: All results reported in ppm unless otherwise specified  
 ND = Not detected at the specified limits



Received: 07/06/87

07/15/87 11:43:33

TMA/NORCAL

Three soil samples from project 2226-40 were submitted for analysis on a rush basis. The soils were extracted and analyzed for fuel hydrocarbons by the modified 8015 method, and also for aromatic 8020 compounds. The sample labeled "FP-1" was found to contain approximately 490 ppm of a C9 - C14 petroleum hydrocarbon - possibly Stoddard's Solvent. This solvent was used for the quantitation. The sample was also found to contain xylene isomers, which was confirmed by GC/MS. The results are attached.



1255 POWELL STREET EMERYVILLE, CA 94608 • (415) 428-2300

LOG NO: E87-07-508

Received: 27 JUL 87

Reported: 30 JUL 87

Ms. Katherine Chesick  
Engineering Science  
600 Bancroft Way  
Berkeley, California 94710

Project: NG049

REPORT OF ANALYTICAL RESULTS

Page 1

LOG NO	SAMPLE DESCRIPTION, SOIL SAMPLES	DATE SAMPLED	
07-508-1	MW-5', 1650 65th Street	27 JUL 87	
07-508-2	MW-10', 1650 65th Street	27 JUL 87	
PARAMETER		07-508-1	07-508-2
Total Fuel Hydrocarbons, mg/kg		170	6600

D. A. McLean, Laboratory Director



LOG NO: E87-07-520

Received: 28 JUL 87

Reported: 30 JUL 87

Ms. Kathleen Chesick  
Engineering Science  
600 Bancroft Way  
Berkeley, California 94710

Project: N0049.02

REPORT OF ANALYTICAL RESULTS

Page 1

LOG NO	SAMPLE DESCRIPTION, WATER SAMPLES	DATE SAMPLED
07-520-1	MW-1	28 JUL 87
PARAMETER	07-520-1	
Total Fuel Hydrocarbons, mg/L	33	

D. A. McLean, Laboratory Director

# GROUNDWATER SAMPLING FIELD NOTES

Benefit Capital Corp.  
1650 65th Street  
Emeryville, CA

PROJECT/LOCATION \_\_\_\_\_

PROJ. NO. NC049 DATE 28 July 1987

WELL ID	SAMPLE DATE, TIME AND SAMPLER	WATER LEVEL BEFORE *, WELL DIAMETER AND DEPTH	WATER LEVEL AFTER *	GALLONS PER CASING PER WELL PURGING METHOD **	PUMP ON	PUMP OFF	FLOW RATE / GALLONS PURGED	TEMPERATURE °C	SPECIFIC CONDUCTIVITY (UMHOS / CM )	PH	TOTAL WATER PURGED (GALLONS)	SAMPLE COLLECTION METHOD **	ANALYSIS AND PRESERVATIVE NO. AND TYPE OF CONTAINERS	COMMENTS (SAMPLE TURBIDITY, SAMPLE ODOR, WEATHER CONDITIONS, ETC.)
MW-1	28 July 87 10:54 W. Hauck	12.09 2" diam 30 ft.	13.04	2.9	B						10.0	B	GC/ FID 2 Total 40 ml Pet. VOA Hydro.	No free product observed on water surface; purged water initially yellow. Sample very turbid w/ strong gas odor.

\* WATER LEVEL FROM GROUND SURFACE, IN FEET  
\*\*WW-WELL WIZARD; G-GRUNDFOS PUMP; B-BAILER

## WATER LEVEL DATA

PERSONNEL K. Chesick

PROJECT/LOCATION 1650 65<sup>th</sup> Street

PROJ. NO. NC049 DATE 8/17/87

WELL NO.	DEPTH TO T. O. C. <sup>1</sup>	WATER LEVEL FROM T.O.C.	WATER LEVEL FROM GROUND SURFACE	MEASURED WELL DEPTH	GALLONS/ LINEAR <sup>2</sup> CASING FT.	GALLONS/ CASING <sup>3</sup> VOLUME	WELL ELEVATION (USGS)	WATER LEVEL ELEVATION (USGS)
MW-1	0.19	12.08	12.27	27.97	0.16	2.51		

1. RELATIVE TO GROUND SURFACE; BY CONVENTION, T.O.C. ABOVE GROUND SURFACE HAVE NEGATIVE DEPTHS, THOSE BELOW HAVE POSITIVE DEPTHS
2. TO DETERMINE NUMBER OF GALLONS PER CASING VOLUME, ASSUME: FOR 2' ID CASING, 0.16 GALLONS PER LINEAR CASING FOOT; FOR 4' ID CASING, 0.65 GALLONS PER LINEAR CASING FOOT; FOR 6' ID CASING, 1.47 GALLONS PER LINEAR CASING FOOT.
3. GALLONS PER CASING VOLUME = [(MEASURED WELL DEPTH) - (WATER LEVEL FROM GROUND SURFACE)] x [GALLONS PER LINEAR CASING FT.]

CHAIN OF CUSTODY RECORD

Proj. No. **NE 049.02**  
 Project Name **Emerysville Bay Front Partnership**

SAMPLERS (Signature)  
*JSP Wang*

NO. OF CONTAINERS

*Asst. Dir. EPA 8020  
 Total Petroleum Hydrocarbons w/o Metal → Lead (Pb)*

REMARKS

STA. NO.	DATE	TIME	STATION LOCATION	NO. OF CONTAINERS	AROMATIC	BTX	LEAD	OTHER	REMARKS
<i>74</i> N-1/2	7/2	12:35	N-bed	2	X	X	X		<i>10K turnaround 270                  REP HOWE (EPA 8020) 1510                  ↓                  verbal results to                  Richard Makdisi                  415-548-7970</i>
S-01	7/2	12:35	S-bed	1	X	X	X		
FP-1/2	7/2	10:40	REP Fill pipe/product line	2	X	X	X		

Relinquished by: (Signature) <i>JSP Wang</i>	Date/Time 7/2/87 1610	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature)	Date/Time	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature)	Date/Time	Received for Laboratory by: (Signature) <i>Debbie Fisher</i>	Date/Time 7/2/87 16:10	Remarks	

**ENGINEERING - SCIENCE, INC.  
CHAIN OF CUSTODY RECORD**

CLIENT: ENGINEERING-SCIENCE, INC. BERKELEY		PROJECT MANAGER: <i>K. Chesick</i>		PROJ. NO.: <i>NC049.02</i>		NO. OF CONTAINERS	ANALYSES REQUIRED							PRESERVED TO BE COMPOSITED BY LAB	REMARKS	
PROJECT NAME / LOCATION: <i>1650 65<sup>th</sup> St. Emeryville</i>							GC/FID 90% Petroleum Hydrocarbons									
SAMPLER(S): (SIGNATURE)																
SAMPLE ID	DATE	TIME	MATRIX	SAMPLE LOCATION												
<i>MW-1</i>	<i>7/28/87</i>	<i>10:54</i>	<i>H<sub>2</sub>O</i>			<i>2</i>	<input checked="" type="checkbox"/>						<i>24 hr turnaround</i>			
RELINQUISHED BY: (SIGNATURE) <i>Wayne Bauer</i>		DATE/TIME <i>7-28-87 11:20</i>		RECEIVED BY: (SIGNATURE) <i>E. Kusny</i>		RELINQUISHED BY: (SIGNATURE)		DATE/TIME		RECEIVED BY: (SIGNATURE)						
RELINQUISHED BY: (SIGNATURE)		DATE/TIME		RECEIVED FOR LABORATORY BY: (SIGNATURE)		DATE/TIME		REMARKS <i>24 hr turnaround</i>								

**ENGINEERING - SCIENCE, INC.  
CHAIN OF CUSTODY RECORD**

CLIENT: ENGINEERING-SCIENCE, INC. BERKELEY		PROJECT MANAGER: <i>K. Chesick</i>		PROJ. NO.: <i>NG049.02</i>		NO. OF CONTAINERS	ANALYSES REQUIRED							REMARKS
PROJECT NAME / LOCATION: <i>B.C.C. 1650 65<sup>th</sup> St.</i>							GC/FID Total Petroleum Hydrocarbons	PRESERVED	TO BE COMPOSITED BY LAB					
SAMPLER(S): (SIGNATURE) <i>K. Chesick</i>														
SAMPLE ID	DATE	TIME	MATRIX	SAMPLE LOCATION										
<i>HW-5'</i>	<i>7/27/87</i>	<i>9:50</i>	<i>Soil</i>	<i>1650 65<sup>th</sup> St.</i>		1	✓						<i>Brass tubes } 24 hr</i>	
<i>HW-10'</i>	<i>7/27/87</i>	<i>10:20</i>	<i>Soil</i>	<i>"</i>		1	✓						<i>Brass tubes } turnaround</i>	
RELINQUISHED BY: (SIGNATURE) <i>Katherine Chesick</i>		DATE/TIME <i>7/27/87 15:04</i>		RECEIVED BY: (SIGNATURE) <i>Edward Kwong</i>		RELINQUISHED BY: (SIGNATURE)		DATE/TIME		RECEIVED BY: (SIGNATURE)				
RELINQUISHED BY: (SIGNATURE)		DATE/TIME		RECEIVED FOR LABORATORY BY: (SIGNATURE)		DATE/TIME		REMARKS <u><i>24 hr turnaround</i></u>						