Prepared For: Chevron U.S.A., Inc.

Groundwater Monitoring Well Installation Report Chevron USA Livermore, California

March 11, 1985

J. H. KLEINFELDER & ASSOCIATES

GEOTECHNICAL CONSULTANTS • MATERIALS TESTING LAND & WATER RESOURCES

1901 OLYMPIC BOULEVARD, SUITE 300 WALNUT CREEK, CA 94596-5063

(415) 938-5610

March 1, 1985 File: B-1458-1

Mr. John Randall Chevron U.S.A., Inc. 2 Annabel Lane Suite 200 San Ramon, CA 94583

Dear Mr. Randall:

Enclosed is a report summarizing the installation of two groundwater monitoring wells at Chevron U.S.A.'s service station at 4904 South Front Street in Livermore, California.

Please contact us if you have any questions.

Very truly yours,

J. H. KLEIMPELDER & ASSOCIATES

Michael S. Bonkowski Project Geologist

Edward E. Rinne

Engineering Manager

Ellimoi & Rome

MSB: EER: tms

Enclosure

GROUNDWATER MONITORING WELL INSTALLATION REPORT CHEVRON USA

LIVERMORE, CALIFORNIA

I. INTRODUCTION

The following report summarizes the geotechnical services performed at Chevron USA's Service Station at 4904 South Front Street in Livermore, California. Chevron USA contracted J. H. Kleinfelder & Associates to install two groundwater monitoring wells for a water quality site investigation. On January 9, 1985, J. H. Kleinfelder & Associates completed two soil borings and installed two monitoring wells under this contract. This report describes the work elements associated with the monitoring well installation, and discusses the results of our field observations.

II. SITE LOCATION

Chevron's service station is located at 4909 South Front Street in Livermore, California, as shown on Plate 1. The station is situated at the northeast corner of the intersection of South Front Street and Highway 84, and across the street from Mobil Oil Company's Service Station located at 4707 First Street.

III. SCOPE OF WORK

Two monitoring wells (K-10 and K-11) were installed offsite of Chevron's service station. The well locations and depths were specified by Chevron U.S.A. Monitoring well K-11 was placed in the backfill along the east edge of a drainage culvert which runs along the western perimeter of Chevron Service Station's and under Mobil Oil Company's Service Station. Monitoring well K-12 was placed in South

Front Street just north of Mobil Oil Company's Service Station. Both monitoring wells are situated downgradient of Chevron's Service Station. The locations of these wells are shown on Plate 2.

IV. FIELD ACTIVITIES/OBSERVATIONS

A. Soil Borings

The location of the two soil borings in which the monitoring wells were installed is shown on Plate 2. The borings were drilled using a truck-mounted CME 75 drill rig equipped with 10-inch hollow stem augers. A description of the soils encountered is presented on Plate 4 and 5, with a copy of the Unified Soils Classification System (used to identify the soils) included as Plate 3. The soils encountered during drilling consisted of thin interbeds of clay, silty clay, gravelly clay, silt, clayey silt, and sand. In monitoring well K-ll, groundwater was encountered 20.6 feet below grade in a 5 foot thick unit of clay. In monitoring well K-l2, groundwater was encountered 17.5 feet below grade in a 14 foot thick unit of clay.

B. Monitoring Wells

Both groundwater monitoring wells were constructed in the soil borings at the completion of drilling and logging. Monitoring well K-II was completed with a 3-inch inside diameter PVC pipe, with well screen sections perforated with 0.020-inch slots from 5 to 35 feet below the ground surface. The annular space between the pipe and the wall of the boring was backfilled with #3 Monterey sand to approximately one foot above the top of the perforated section. A one-foot bentonite plug was placed above the sand pack to provide a seal against surface water infiltration. Monitoring well K-I2 was completed with a 3-inch inside diameter PVC pipe, with well screen sections perforated with 0.020-inch slots from 4 to 30 feet below the ground surface. The annular space between the pipe and the wall of the boring was backfilled with #3 Monterey sand to approximately one foot above the top of the perforated section. A one-foot bentonite plug was placed

above the sand pack to provide a seal against surface water infiltration.

Concrete was placed in the annular space of both monitoring wells from the bentonite plug to the surface. Both monitoring wells were completed with locking screw caps inside a Christy Box.

C. Sampling Procedure


Soil samples were collected and logged with a standard penetration split spoon sampler. Samples were collected every 2.5 feet until water was encountered, and every 5 feet thereafter. Sampling started at a depth of 7.5 feet in well K-10 and at a depth of 5 feet in well K-11.

IV. DISCUSSION

No odor of gasoline was detected in monitoring well K-10 at Mobil Oil Company's Service Station. A slight odor of gasoline was detected in the samples collected at 12.5 feet and 15 feet in monitoring well K-11.

V. LIMITATIONS

This report was prepared in general accordance with the accepted standard of practice which exists in Northern California at the time the investigation was performed. It should be recognized that definition and evaluation of geologic conditions is a difficult and inexact art. Judgements leading to conclusions and recommendations are generally made with an incomplete knowledge of the subsurface conditions present. More extensive studies including additional subsurface investigation can tend to reduce the inherent uncertainties associated with subsurface modeling. If the client wishes to reduce the uncertainty beyond the level associated with this study, Kleinfelder and Associates should be notified for additional consultation.



SCALE: $1^n = 1/2$ mile


J.H. KLEINFELDER & ASSOCIATES CHOTECHNICAL CONSULTANTS + MATERIALS TESTING



CHEVRON USA 4904 S. FRONT STREET LIVERMOORE, CA SITE LOCATION MAP

PLATE

1



UNIFIED SOIL CLASSIFICATION SYSTEM

MAJOR DI	VISTONS	LTA	DESCRIPTION	PAJOR DIVISIONS		LTR	DESCRIPT (ON	
ł	GRAVEL AND GRAVELLY SOILS	SH.	Well-graded gravels or gravel sand mixtures, little or no fines.	FINE	SILTS AND CLAYS LL<50	HL	inorganic silts and very fine sands, rock flour, slity or clayey fine sands or clayey silt with slight plasticity.	
		GP	Poorly-graded gravels or gravel sand mixture, little or no fines					
		GH	Silty gravels, gravel-sand-clay mixtures.			CL	Inorganic clays of low to medium plasticity, gravelly clays, sandy clays, silty clays, lean clays.	
COARSE GRAINED		ĢC	Clayey gravels, gravel-sand-clay mixtures.			DL	Organic silts and organic silt- clays of low plasticity	
SOILS		SW	Well-graded sands or gravelly sands, little or no fines.	GRAINED SOILS	SILTS	МН	Inorganic silts, micaceous or diatomaceous fine sandy or silty soils, elastic silts	
	SAND SANDY SOILS	SP	Poorly-graded sands or gravelly sands, little or no fines.		AND CLAYS	СН	Inorganic clays of high plasticity fat clays.	
		SH	Silty sands, sand-silt mimtures,		LL>50	ОН	Organic clays of medium to high plasticity.	
		sc	Clayey sands, sand-clay mixtures.	MIGHLY ORGANIC SOILS		Pt	Peet and other highly organic soils.	

7	Standard penetration split spoon sample		Blank casing
Į	Modified California Sampler		
<u> </u>	Shelby tube sample Water level observed in boring		Screened casing
=	No recovery	5 1	Cement grout
NFWE	No free water encountered	6	cometre group
NOSC	No odor, scent, or fluid cut		Bentonite
NOTE:	Blow count represents the number of blows of a 140-pound hammer falling 30 inches per blow required to drive a sampler through the last 12 inches of an 18-inch penetration.		Sand pack
NOTE:	The line separating strata on the logs		

represent approximate boundaries only. The actual transition may be gradual. No warranty is provided as to the continuity of soil strata between borings. Logs represent the soil section observed at the boring location on the date of drilling only.

J.H. KLEINFELDER & ASSOCIATES GEOTECHNICAL CONSULTANTS . MATERIALS TESTING



CHEVRON USA 4904 S. FRONT STREET LIVERMOORE, CA BORING LOG LEGEND

PLATE

	0 -	Blow/ FL	Sample No.	USCS	DESCRIPTION	CONS
	0 -				Asphalt 4"	61 8
	1 - 2 - 3 -			ML	SILT - brown, little clay, little gravel, l" rounded, stiff, low plasticity, moist, NOSC	0 0.0000000000000000000000000000000000
	4 - 5 -					
	6 -	¥		СН	CLAY - brown, little silt, soft, high plasticity moist, NOSC	
	7 -					囯
Ĩ	8 -	2 2 3		СН	CLAY - brown, trace fine gravel, 1/4" angular, soft, high plasticity, moist, NOSC	
	0 -	1 0 2		СН	CLAY - dark brown, trace fine gravel, 1/4" rounded, poorly sorted, soft, high plasticity,	
1	1 -				moist, NOSC	
1	2 -					
1.	3 -	5 6 9		CL	SILTY CLAY - tan, little fine gravel, 1/2" subrounded, poorly sorted, trace black organics, stiff, low plasticity, moist, NOSC	
1	4 -			1		
1	5 -	9 10		CL	GRAVELLY CLAY - tan with light grey mottling, fine gravel, 1/4" rounded, poorly sorted	

J.H KLEINFELDER & ASSOCIATES GEOTECHNICAL CONSULTANTS + MATERIALS TESTING

PROJECT NO. B-1458-1



CHEVRON USA 4904 S. FRONT STREET LIVERMOORE, CA LOG OF BORING NO. K-II

PLATE

16-	Blow/ Fl.	Sample No.	USCS	DESCRIPTION	c
7-	16			Little silt, very stiff, low plasticity, NOSC	
8-	4 6 9		CL	SILTY CLAY - tan, rust staining, stiff, medium plasticity, moist NOSC	
9-					
1-	4 6 12	포	ML	CLAYEY SILT - tan, rust staining, trace fine gravel, 1/8" subangular, very stiff, medium plasticity, slightly wet, NOSC	-
2-	8				
3-					
4-					
5-	6		ML	SANDY SILT - tan, fine sand, stiff, medium plasticity	-
5-	9				
7-	23		SP	SAND - tan, trace fine gravel, ½" poorly sorted, fine to medium sand, some silt, medium dense, wet, NOSC	
3-					
9-					
)-			СН	CLAY - tan, trace black organics, stiff, high	
-	4 6 9		on	plasticity, work, NOSC	


J.H. KLEINFELDER & ASSOCIATES CEOTECHNICAL CONSULTANTS . MATERIALS TESTING

PROJECT NO. B-1458-1



CHEVRON USA 4904 S. FRONT STREET LIVERMOORE, CA LOG OF BORING NO. K-II

PLATE



J.H. KLEINFELDER & ASSOCIATES CECTECHNICAL CONSULTANTS . MATERIALS TESTING

PROJECT NO. B-1458-1



CHEVRON USA 4904 S. FRONT STREET LIVERMOORE, CA LOG OF BORING NO. K-II

PLATE

4

0 -	Blow/ Ft.	Sample No.	uscs	DESCRIPTION
				Asphalt 1'
i es				
2				
=				
-				
-	2		СН	SILTY CLAY - black, trace root fragments, stiff,
-	2 5 6			high plasticity, moist, NOSC
-				
545	5 6 8	1	СН	CLAY - tan with light gray mottling, rust staining, little silt, trace black organics, very stiff, high plasticity, moist, NOSC
-	o	1		
	7	,	6	SILTY CLAY - tan with light gray mottling, rust
-	13		CL	staining, trace fine gravel, 1/8", very stiff, medium plasticity, moist, NOSC
-				
-	7 10		CL	CLAY - tan and rust, little silt, trace black organics, very stiff, medium plasticity, moist,
-	13	_		Gas Odor
	4		CL	CLAY - tan, trace black organics in fissures, stiff

J. H. KLEINFELDER & ASSOCIATES
GEOTECHNICAL CONSULTANTS . MATERIALS TESTING

CHEVRON USA 4904 S. FRONT STREET LIVERMOORE, CA LOG OF BORING NO. K-12

PLATE

5