ALCO HAZMAT

# **SEMCO**

94 MAY -4 PM 2: 48 ENVIRONMENTAL & GENERAL ENGINEERING CONTRACTOR HAZARDOUS SUBSTANCES REMOVAL AND REMEDIAL ACTIONS CERTIFICATION LICENSE # 449864 A, B, C61/D40

1217 So. 7th STREET, MODESTO, CALIFORNIA 95351 (209) 524-9653 1741 LESLIE STREET, SAN MATEO, CALIFORNIA 94402 (415) 572-8033

April 29, 1994

Juliet Shin Alameda County Department of Environmental Health 80 Swan Way, #200 Oakland, California 94621

Re: Encinal Terminals, 1521 Buena Vista Avenue, Alameda, California

Subject: Proposed Work Plan for Site Remediation

Dear Juliet,

Attached please find the proposed Work Plan for continued work at the referenced site. Also attached are the tank removal analytical results from which the Work Plan is based. If you should have any questions or need further information please contact me at (209) 524-9653.

Sincerely,

Semco

Doug Flaming

Operations Manager

Enclosure

## WORK PLAN FOR OVER-EXCAVATION AT 1521 BUENA VISTA AVENUE, ALAMEDA APRIL 29, 1994

#### 1.0 BACKGROUND

Semco was contracted by Alameda Terminals, located at 1521 Buena Vista Avenue, to remove one (1) 2,000 gallon, and one (1) 1,000 gallon underground storage tank at the same address (See site map for location)

#### 2.0 SITE HISTORY

The site is an industrial property. Semco has contracted with Alameda Terminals for the remediation work.

- 2.1 The underground storage tanks were removed on Tuesday, April 5, 1994. The tanks were transported to Erickson, Inc. by Richard Hamilton Trucking under manifest #92863895. Samples were collected from the 2,000 gallon tank site at the north, and south end of the excavation, above the water interface, at minus 6'. Samples were collected from the 1,000 gallon site at the north, and south end of the excavation, at minus 8'. Water was not encountered at the 1,000 gallon tank site. One (1) composite soil sample was taken from each of the two sites. All samples were taken under the direction of Juliet Shin, Alameda County Environmental Health Department. (See sample location map).
- 2.2 The condition of the tanks were noted by Semco and Juliet Shin as follows:
  - 2,000 gallon tank North end of tank, seam weld eroded, (screw driver/probe was able to slip through the seam. Some corrosion present, but no other holes apparent.
  - 1,000 gallon tank Tank was in tact, with double tar wrap (most of wrap still in place). No apparent holes in tank.

### 3.0 ANALYTICAL PROTOCOLS AND RESULTS

All samples were taken by Semco under the direction of Juliet Shin, Alameda County Environmental Health Department, using clean 2" x 6" brass tubes. They were sealed with teflon tape, capped with pre-formed end caps, and sealed with masking tape at each end. The samples were placed in an iced cooler for transportation under a Chain of Custody to North State Environmental for analysis. The soil six (6) soil samples, and one (1) water sample were analyzed for TPH as Diesel, and BTXE. (See analytical results with Chain of Custody).

#### 4. CONCLUSIONS AND RECOMMENDATIONS

Based on the relatively low levels of contamination Semco proposes to perform minor over-excavation at both former tank sites. During excavation, field screening will be performed by use of a Photo Ionization Detector (PID). Semco will perform de-watering during excavation if ground water is encountered. Following excavation, confirmation samples will be obtained under the direction of Alameda County Environmental Health Department. The excavation will then be backfilled to grade with an approved material. Excavated soil, and pumped ground water will be stored on-site pending characterization for disposal.



SEMCO APR 15 1994 Heceivel

#### CERTIFICATE OF ANALYSIS

Benzene, Toluene, Ethylbenzene and Xylenes by Method 8020/5030 Diesel by Method 8015 M

Job No: 94-357 Date Sampled: 04/05/94 Client: Semco Date Received: 04/05/94 Project: 93-3504 Alameda Treminals Date Analysed: 04/06/94

Sample No.	Client ID	Analyte	Result				
94-357-01	#1 South Wall Interface 6'	Benzene Toluene Ethylbenzene Xylenes Diesel	ND 0.011 mg/Kg ND 0.094 mg/Kg 38 mg/Kg				
94-357-02	#2 North Wall Interface 6'	Benzene Toluene Ethylbenzene Xylenes Diesel	ND ND ND 0.018 mg/Kg 160 mg/Kg				
94-357-03	#3 Pit Water 6' # 1 Tank	Benzene Toluene Ethylbenzene Xylenes Diesel	ND 3 ug/L 0.6 ug/L 3 ug/L 26 mg/L				
94-357-04	#4 Comp Soils # 1 Tank	Benzene Toluene Ethylbenzene Xylenes Diesel	ND 0.027 mg/Kg 0.017 mg/Kg 0.1 mg/Kg 3 mg/Kg				
94-357-05	#5 South End # 2 Tank 8'	Benzene Toluene Ethylbenzene Xylenes Diesel	ND ND 0.025 mg/Kg 0.033 mg/Kg 4 mg/Kg				





94-357-06	#6 North End # 2 Tank 8'	Benzene Toluene Ethylbenzene Xylenes Diesel	ND ND ND ND 380	mg/Kg
94-357-07	#7 Comp Spoils # 2 Tank	Benzene Toluene Ethylbenzene Xylenes Diesel	ND 0.053 0.012 0.063 47	mg/Kg mg/Kg mg/Kg mg/Kg

Control/Quality Assurance Summary: Soil

Analyte	Method	Reporting Limit	( Blank	MS/MSD Recovery	RPD
BTXE	8020/5030	0.005 mg	g/Kg ND	99%	6
Diesel	8015 M	1 mg	I/Kg ND	95%	4
Control/Q	uality Assurar	nce Summary	: Water		
Analyte	Method	Reporting	l Blank	MS/MSD Recovery	RPD


Analyte	Method	Limit	Blank	Recovery	RPD
BTXE	8020/5030	0.5 ug/L	ND	99%	6
Diesel	8015 M	0.05 mg/L	ND	95%	4


DOHS Certificate No: 1753

Reviewed and Approved

John Murphy Laboratory Director

Section I	CH	All	V	OF	(	U	ST	ГО	D١	1	A	ND		AN	۱ <u>۸</u> ۱	LYS	515	R	EQUE	EST	<b>,</b> L	AB N	)		
Project Manager — Phone (415)	1741 572-97 仁月UC 672 80	34 K	K <sub>1</sub>	per								S	ame 24 48	(Circ De Hrs Hrs	cie C	72 5	Hr Day	8	415/	<b>Aarti</b> i	nez		San	CAL, Franc 647-	isco
Send Coolers to Project No. / P.O.	: Mo	des	to [	√, <b>₹</b>	San Al	ΔΛ	late //F	<b>09</b>	罕	FD	M	) N //	8 ∧/16	amı	oler Leto			I_V	Alas	non.	<u> </u>	~	~~~~		
Section II					<u> </u>				- · .	Requ	15							ection						nation	
			۵				7			2		`		2//	7//	////	<u> </u>			]		-		merks	
	A=Air	Q 4	w Level							Subject	racting							Cont	ainers		_		nediat		
Sample Identification	Watrix W=Water	TPH - G	TPH - LOW	TPH - G	втхЕ	040	8010	8240	Metals	Others *	Subcontracting					Date	Time	Quantity	Pres.		c	onte	mineti	on [	
1 #1-SOUTH WILL INTERFACE	5		1		V											4/5.91					90	4-3	57	0 /	
2 #2- NorTH Wall INTERFACE	5	ļ		ļ					<u> </u>		_					9/3.94	11:23	1 2082					e	» ک	
3 73 - P.T H20 6 771	1 W	ļ	14		14			<u> </u>		ļ						244	11:30	24000			······································				
474-Compspoils TANK	5	<del> </del>	1/		1			-	<del> </del>	┼	$\dashv$			-		4.5.94				<del>                                     </del>		******	~		
5 HS - SOUTH END TONK	15	<del> </del>	1	-	\\ \. \					-	$\dashv$			-		41.5.94 41.5.94					<del></del> -	<del></del>		<del>~~~~</del>	
7+7- Comp Spoils TANK	5	<del> </del>	17	1.	1			<del> </del>	<del> </del>	1	$\dashv$					4.5.99			<del> </del>	<del> </del>	A	· · · · · · ·	<u>ن ۔</u> نا۔		
8		<del>                                     </del>	<del>                                     </del>						<del> </del>								ديد کړد ۱۰			#	-0	(I)	-1	<del></del>	
9																	·····			e e		E S			<del></del>
10																				Ç		ე ე			
14				ļ <u>.</u>	<u> </u>				<u> </u>	<u> </u>											94				
12		دها								<u> </u>										<u></u>				in Venezia	
Relinquished by	AL I	*\//	igs X		Date		_		711/				ved				<del></del>			1	ees i				
Organization Relinquished by Organization				Date/Time					Re	Organization  Received by  Organization								Samples Stored in los Appropriate Containers Samples Preserved VOA's without Headspace							
Relinquished by Organization				4	Date	/Ti	me_				Re	cei	ved	by	1/2	I SE	1	1 18							





#4-COMP SPOILS-#1 TANK

1521 BUENAVISTA AVE ALAMEDA

NOT TO SCALE