ALAMEDA COUNTY

HEALTH CARE SERVICES

AGENCY



DAVID J. KEARS, Agency Director

January 22, 1997 StID # 3803 ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION (LOP) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

REMEDIAL ACTION COMPLETION CERTIFICATION

Ms. Gladys Cheney c/o Mr. Dennis Welch Melfort Properties 30593 Union City Blvd. Union City, CA 94587

Re: Former Chip Steak Company, 958 77th Ave., Oakland 94621

Dear Ms. Cheney:

This letter confirms the completion of site investigation and remedial action for the one underground 1,000 gallon gasoline tank at the above described location. Thank you for your cooperation throughout this investigation. Your willingness and promptness in responding to our inquiries concerning the former underground storage tank is greatly appreciated.

Based upon the available information and with provision that the information provided to this agency was accurate and representative of site conditions, no further action related to the underground tank release is required.

This notice is issued pursuant to the regulation contained in Title 23, Division 3, Chapter 16, Section 2721 (e) of the California Code of Regulations.

Please contact Barney Chan at (510) 567-6765 if you have any questions regarding this matter.

Sincerely,

Mee Ling Tung, Director

c: B. Chan, Hazardous Materials Division-files

Kevin Graves, RWQCB

L. Casias, SWRCB (with attachment)

Mr. J. Walton Cheney, 3282 Chablis Court, Pleasanton, CA 94566 RACC958-77

CASE CLOSURE SUMMARY Leaking Underground Fuel Storage Tank Program

I. AGENCY INFORMATION

Date: 12/29/95

Agency name: Alameda County-HazMat Address: 1131 Harbor Bay Parkway

Rm 250, Alameda CA 94502

City/State/Zip: Alameda Phone: (510) 567-6700

Responsible staff person: Barney Chan Title: Hazardous Materials Spec.

II. CASE INFORMATION

Site facility name: Chip Steak Company

Site facility address: 958 77th Ave., Oakland CA 94621

RB LUSTIS Case No: N/A Local Case No./LOP Case No.: 3803

ULR filing date: 10/31/88 SWEEPS No: N/A

Responsible Parties: Addresses: Phone Numbers:

Ms. Gladys H. Cheney 30593 Union City Blvd. c/o Mr. Dennis Welch Union City, CA 94587 Melfort Properties S.F, CA 94119-3575

Tank
No:Size in
qal.:Contents:
or removed?:Closed in-place
or removed?:Date:
0r removed?:11,000gasolineRemoved10/05/88

III RELEASE AND SITE CHARACTERIZATION INFORMATION

Cause and type of release: unknown

Site characterization complete? Yes

Date approved by oversight agency: 4/20/95 work plan approved

Monitoring Wells installed? YES Number: 3

Proper screened interval? Yes, from 7-24' bgs

Page 1 of 3

Leaking Underground Fuel Storage Program

Highest GW depth: 5.22'BGS Lowest depth: 8.25' BGS

Flow direction: northwesterly

Most sensitive current use: unknown

Are drinking water wells affected? No Aquifer name: NA

Is surface water affected? No Nearest affected SW name: NA

Off-site beneficial use impacts (addresses/locations): None

Report(s) on file? Yes Where is report(s)? Alameda County

1131 Harbor Bay Parkway, Room 250, Alameda CA 94502-6577

Treatment and Disposal of Affected Material:

<u>Material</u>	Amount (include units)	Action (Treatment or Disposal w/destination)	<u>Date</u>
Tank	1-1000 gallon gas	Disposed @ H& H, 220 China Basin, San Francisco	10/5/88
Soil	35 cy	Disposed, Redwood Landfill Novato	9/13/89
Liquid	100 gallon	Disposed, @ H&H, SF	10/5/88
Groundwater	1500 gallon	Evergreen Oil, Inc, Newark, CA 94560	5/23/95

Maximum Documented Contaminant Concentrations - - Before and After Cleanup Contaminant Soil (npm) * Water (nph)

CONCAMILMANC	SOIT (ББш)	* water	(ppp)
	<u>Before</u>	After	Before	After
TPH (Gas)	1400	130 ¹		170
Benzene	3.1	<0.04		8
Toluene	59	<0.02		0.63
Ethylbenzene	26	0.04		1.6
Xylenes	150	0.11		0.57
Other Lead			80	
Chlorobenzene	<0.03			44
cis 1,2-DCE, TCE, Vinyl	Chloride		100, 8.8	, 8.9

Comments (Depth of Remediation, etc.):

* from initial groundwater sample

IV. CLOSURE

Does completed corrective action protect existing beneficial uses per the Regional Board Basin Plan? YES

Page 2 of 3

¹ from overexcavation floor sample

Leaking Underground Fuel Storage Tank Program

Does completed corrective action protect potential beneficial uses per the Regional Board Basin Plan? YES

Does corrective action protect public health for current land use? YES

Site management requirements: NA

Should corrective action be reviewed if land use changes? No

Monitoring wells Decommissioned: NO, pending closure

Number Decommissioned: 0 Number Retained: 3

List enforcement actions taken: NOV 2/3/89

List enforcement actions rescinded: Received wp on August 24, 1989

V. LOCAL AGENCY REPRESENTATIVE DATA

Name: Barney M. Chan Title: Hazardous Materials Specialist

Signature: famey at the Date: 1/2/96

Reviewed by

Name: Susan Hugo Title: Sen. Haz. Materials Specialist

Signature: June 2/Hugo Date: 1/2/96

Name: Eva Chu Title: Haz. Mat. Specialist

Signature: Walker Date: 1/2/96

VI. RWOCB NOTIFICATION

Date Submitted to RB: RB Response:

RWQCB Staff Name: K. Graves Title: AWRCE Date:

VII. ADDITIONAL COMMENTS, DATA, ETC.

Page 3 of 3

A 1000 gallon gasoline tank located just north of the main building, lying between the building and the street, was removed on October 5, 1988. Running parallel to the tank and street is a 12" clay sanitary sewer line. Two soil samples taken from the base of the tank detected 1400 and 730 mg/kg TPHg. Since an original tank closure plan was never submitted it is unclear exactly where the original soil samples were taken.

On March 8, 1989, overexcavation was performed. Approximately 35 cy of soil was removed, during which rainfall prevented any more excavation. Only one soil sample was taken from the center of the floor bottom after the over-excavation at a depth of 13.5'. This sample exhibited 130 ppm TPHg and 0.11 ppm and 0.04 ppm xylene and ethylbenzene respectively.

On August 9, 1989 three monitoring wells were installed around the former tank pit, with MW3 being the downgradient well and lying closest to the sanitary sewer. Soil samples from these wells were rather unremarkable with levels of TEX just-above above detection limits and TPHg at 20 mg/kg in MW1 (8-8.5')

Groundwater monitoring was performed only once in 1990, twice in 1991 and discontinued in 1992. It was resumed in 1993 and performed more regularly in 1993-1994. Based on the monitoring results, it appeared that petroleum contamination had attenuated, however, chlorobenzene at concentrations above the CA MCL of 30 ppb continued to be detected in MW3, the downgradient well.

Based on the presence of the majority of contaminants being detected in MW3, a work plan was proposed and accepted for the removal of groundwater from this well. Also, it was believed that the sanitary sewer line may be acting as a conduit and source of contamination being detected in MW3. The work plan therefore included the installation of hydropunch borings up- and downgradient along the sewer line along with borings next to MW3. A total of 1500 gallons of water was removed from MW3. Five hydropunch borings were advanced and grab groundwater samples collected. Only three of the five samples were analyzed, (HP-1, HP-2 and HP-5). With the exception of HP-3, all borings encountered gravel and sandy clay which are common to trench backfill material. MW-3 was also sampled after the removal of the 1500 gallons of water.


The results of this investigation are as follows:

Site Summary for Chip Steak Co., 958 77th Ave., #3803 Page 2.

Rationale for no further work:

It has been demonstrated that there is definitely communication with the water in MW3 and the water around the sanitary sewer The shallow groundwater table (approx. 5-6') makes this a very likely and probable condition. The extraction of groundwater from MW-3 drew water and contamination from around the sewer line. This is evidenced in the elevated contaminant levels detected in the May 95 MW-3 water sample taken just after groundwater removal compared to the more typical contaminant levels found in the recent 9/26/95 sample. If we assume that contamination migrates along the sewer line and that the contaminant flows also along the sewer line (not unusual) the high levels of chlorinated solvents detected in HP-5 could account for the contamination found in MW-3. It would be pointless to continue to monitor MW-3 which is in communication with contaminants found in the sanitary sewer.

The source of chlorobenzene in groundwater has not been determined. Chlorobenzene was not detected in any soil sampleS from beneath the former tank or from any soil from the monitoring well borings. The concentration of chlorobenzene has equilibrated to approx. 40-50 ppb. Yet, the grab groundwater sample from HP-1, closest to MW-3 did not detect chlorobenzene. It appears residual chlorobenzene in groundwater is limited in extent. Chlorobenzene does not significantly impact groundwater quality as the California MCL is 30 ppb and the EPA MCL is 100 ppb.







TABLE 1	
SUMMARY OF GROUND WATER ANALYTICAL	TEST DATA

SUMMAR	Y OF (<u>GROUNI</u>) WATER A	ANALYTICAL	TEST DATA	7
Date	TPH			Ethyl-	Total	Chloro-
Sampled .		Benzene	Toluene	benzene	X vlenes	benzene
Monitoring Well My	<u>W-1</u>					
9-89 (1) 10-90 (1) 1-91 (1) 4-91 (1) 3-16-93 (1) 6-16-93 (1) -10-14-93 (1) -1-3-94 (1) -4-26-94 (1) -8-12-94 (1)	560 350 80 170 90 60 63 < 50 < 50	5.4 0.8 0.6 17 <0.5 <1 <1 <1 <1	<0.3 <0.3 <0.3 7.3 <0.5 <1 <1 <1 <1	15 0.5 <0.4 <0.4 <0.5 <1 <1 <1 <1	1.2 4.1 0.3 <0.3 <0.5 <1 <1 <1 <1	<0.3 <0.3 <0.3 <0.3 <1 <1 <1 <1
Monitoring Well MV	<u>W-2</u>				_	_
9-89 (1) 10-90 (1) 1-91 (1) 4-91 (1) 3-16-93 (1) 6-16-93 (1) 10-14-93 (1) 1-3-94 (1) 4-26-94 (1) 8-12-94 (1)	<50 <50 <50 <50 <50 <50 <50 <50 <50	<0.4 <0.4 <0.4 <0.5 <1 <1 <1	<0.3 <0.3 <0.3 <0.5 <1 <1 <1 <1	<0.5 <0.4 <0.4 <0.4 <0.5 <1 <1 <1 <1	<0.3 <0.3 <0.3 <0.3 <0.3 2.3 <1 <1 <1 <1 <1	16 11 3.9 10 3 <1 2 <1 <1
Monitoring Well MV	<u>V-3</u>					
9-89 (1) 10-90 (1) 1-91 (1) 4-91 (1) 3-16-93 (1) 6-16-93 (1) 10-14-93 (1) 1-3-94 (1) 4-26-94 (1) 8-12-94 (1) Following Extraction	120 230 220 300 170 180 140 130 210	16 13 5 16 28 24 3 4 4	<0.3 1.5 3 5.5 <0.5 <1 <1 <1 <1	9 19 18 41 <0.5 <1 1 <1 2	<0.3 8.5 5 14 1.6 <1 <1 <1 <1 <1	<0.3 95 75 79 62 90 42 34 52
5-15 - 95 ⁽²⁾	1300	50	8.1	53	140	42
Current Sample 9-26-95 (2)	170	8	0.63	1.6	0.57	44

Note: (1) Concentrations reported by Subsurface Consultants, Inc.

(2) Samples obtained and reported by Geo Plexus, Inc. concentrations reported as parts per billion (ppb)

Geo Plexus, Incorporated



• INDICATES LOCATIONS OF HYDROPUNCH BORINGS

Source: Ron Archer Survey Plan prepared for Clayton Environmental, dated 9/22/89

MELFORT PROPERTIES

DATE 5/25/95 SCALE 1"=30' dcg

BORING LOCATION PLAN

Figure 3

Geo Plexus, I	'nC.
	~ ~ ·

Hydroghena

McCAMPBELL ANALYTICAL INC.

110 2nd Avenue South, #D7, Pacheco, CA 94553 Tele: 510-798-1620 Fax: 510-798-1622

Geo Plexus, I	inc.	Client Project ID: # C95015; Decon Date Sampled: 05/15/95 Environmental, Melfort Properties					_		
1900 Wyatt D	rive, # 1	Date Received: 05/16/95				d: 05/16/95			
Santa Clara,	Ca. 95054	Client (Contact: Da	vid Glick		Date	e Extract	ed: 05/17/95	
		Client I	P.O:			Date	e Analyze	d: 05/17/95	
Gaso	line Range (C6-C	12) Volat	tile Hydroca	rbons as	Gasoline*	, with BT	EX and C	hlorobenzen ⁽⁰⁾	ie*
Lab ID	Client ID	Matrix		Benzene		Ethylben- zene	[0111	% Rec. Surrogate
52499	HP1-WS1A	w	100,f	1.0	ND	ND	ND	ND	108
52500	HP2-WS1A	w	140,f,j	32	ND	3.2	3.0	ND	100
52503	HP5-WS1A	W.	1200f,i	0.92	0.79	ND	0.93	, MD	#
	MW-3		1300	So	8.1	53	140	42	105
Reporting	Limit unless oth-	w	50 ug/L	0.5	0.5	0.5	0.5	0.5	
erwise sta	ated; ND means ted above the re- rting limit	s	1.0 mg/kg	0.005	0.005	0.005	0.005	0.005	

^{*} water and vapor samples are reported in ug/L, soil samples in mg/kg, and all TCLP extracts in mg/L

[#] cluttered chromatogram; sample peak coelutes with surrogate peak

⁺ The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation: a) unmodified or weakly modified gasoline is significant; b) heavier gasoline range compounds are significant (aged gasoline?); c) lighter gasoline range compounds (the most mobile fraction) are significant; d) gasoline range compounds having broad chromatographic peaks are significant; biologically altered gasoline?; e) TPH pattern that does not appear to be derived from gasoline (?); f) one to a few isolated peaks present; g) strongly aged gasoline or diesel range compounds are significant; h) lighter than water immiscible sheen is present; i) liquid sample that contains greater than ~ 5 vol. % sediment; j) no recognizable pattern.

110 2nd Avenue South, #D7, Pacheco, CA 94553 Tele: 510-798-1620 Fax: 510-798-1622

Geo Plexus, Inc.	Client Project ID: # C95015; Decon Date Sampled: 05/15/95				
1900 Wyatt Drive, # 1	Environmental, Melfort Properties Date Received: 05/16/95			: 05/16/95	
Santa Clara, Ca. 95054	Client Contact: Day	vid Glick	Date Extracted	acted: 05/16-05/17/95	
	Client P.O:		Date Analyzed	I: 05/16-05/17/95	
**************************************	Volati	le Halocarbons			
EPA method 601 or 8010	···				
Lab ID	52498	<u></u>	<u> </u>	100	
Client ID	MW3-WS1B	UP-1	1 AP-5	10-0	
<u>Matrix</u>	W-	<u> </u>			
Compound		Conce	ntration*		
Bromodichloromethane	ND< 5				
Bromoform ^(b)	ND< 5				
Bromomethane	ND< 5			<u> </u>	
Carbon Tetrachloride ^(c)	ND<5				
Chlorobenzene	(45)	NO	<50	\ \mathcal{V} \mathcal{V} \ \mathcal{V} \ \mathcal{V} \ \mathcal{V} \mathcal{V} \ \mathcal{V} \mathc	
Chloroethane	ND≪5		<u> </u>		
2-Chloroethyl Viny l Ether (d)	ND< 5				
Chloroform (e)	ND< 5				
Chloromethane	ND< 5				
Dibromochloromethane	ND< 5				
1,2-Dichlorobenzene	ND< 5				
1,3-Dichlorobenzene	ND< 5				
1,4-Dichlorobenzene	ND< 5				
Dichlorodifluoromethane	ND< 5				
1,1-Dichloroethane	ND< 5			0.63	
1,2-Dichloroethane	ND< 5			0.56	
1,1-Dichloroethene	ND< 5				
cis 1,2-Dichloroethene	(200)	190	360	24	
trans 1,2-Dichloroethene	ND< 5				
1,2-Dichloropropane	ND< 5				
cis 1,3-Dichloropropene	ND< 5				
trans 1,3-Dichloropropene	ND< 5				
Methylene Chloride ^(f)	ND< 5				
1,1,2,2-Tetrachloroethane	ND< 5				
Tetrachloroethene	ND< 5			3	
1,1,1-Trichloroethane	ND< 5				
1,1,2-Trichloroethane	ND< 5				
Trichloroethene	(20)	24	3000	3	
Trichlorofluoromethane	ND<5 ·				
Vinyl Chloride ^(g)	(20)	7.8	250	2.1	
% Recovery Surrogate	89				
Comments					

Reporting limit unless otherwise stated: water/TCLP extracts, ND < 0.5ug/L; soil, ND < 5úg/kg

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis

⁽b) tribromomethane; (c) tetrachloromethane; (d) (2-chloroethoxy) ethene; (e) trichloromethane; (f) dichloromethane; (g) chloroethene; (h) a lighter than water immiscible sheen is present; (i) liquid sample that contains greater than ~ 5 vol. % sediment.

DHS Certification No. 1644

110 2nd Avenue South, #D7, Pacheco, CA 94553 Tele: 510-798-1620 Fax: 510-798-1622

Geo Plexus, Inc.	Client Project I	D: # C95015; Dece	on Date Sampled: 0	Date Sampled: 05/15/95		
1900 Wyatt Drive, #1	Environmental, Mo	elfort Properties		Date Received: 05/16/95		
Santa Clara, Ca. 95054	Client Contact: Da	vid Glick	Date Extracted:			
	Client P.O:		Date Analyzed:	05/16-05/22/95		
	Volat	ile Halocarbons				
EPA method 601 or 8010	50.400					
Lab ID	52499	52500	52503			
Client ID	HP1-WS1B	HP2-WS1A.B	HP5-WS1B			
<u>Matrix</u> Compound	W	<u> </u>				
Bromodichloromethane	\	Concentr				
Bromoform ^(b)	ND < 5	ND	ND< 50			
Bromomethane	ND< 5	ND ND	ND< 50			
Carbon Tetrachloride (c)	ND< 5 ND< 5	ND ND	ND < 50	lugher		
Chlorobenzene	ND< 5	ND ND	ND< 50	wyn,		
Chloroethane	ND< 5	ND ND	ND < 50			
2-Chloroethyl Viny l Ether (d)	ND< 5	ND ND	ND< 50			
Chloroform (e)	ND< 5	ND	ND< 50			
Chloromethane	ND< 5	ND	ND< 50			
Dibromochloromethane	ND< 5	ND	ND< 50			
,2-Dichlorobenzene	ND< 5	ND	ND< 50			
,3-Dichlorobenzene	ND< 5	ND ND	ND< 50	···		
l,4-Dichlorobenzene	ND< 5	ND	ND< 50			
Dichlorodifluoromethane	ND < 5	ND	ND< 50			
,1-Dichloroethane	ND< 5	ND	ND< 50	Begr		
,2-Dichloroethane	ND< 5	0.63	_ND<-50	•		
1,1-Dichloroethene	ND<3	0.56	ND< 50			
cis 1,2-Dichloroethene	(190)	WD	ND< 50			
rans 1,2-Dichloroethene	ND< 5	(24_) ND	(360)	. <u></u>		
1,2-Dichloropropane	ND< 5	ND	ND< 50			
cis 1,3-Dichloropropene	ND< 5	ND ND	ND< 50			
rans 1,3-Dichloropropene	ND< 5	ND	ND< 50			
Methylene Chloride (f)	ND< 5	ND	ND< 50			
,1,2,2-Tetrachloroethane	ND< 5	ND ND	ND < 50			
etrachloroethene	ND< 5	3.0	ND < 50			
,1,1-Trichloroethane	ND< 5	ND	ND< 50			
1,2-Trichloroethane	_ ND< 5	ND ND	ND< 50			
richloroethene	24	3.0	ND < 50			
richlorofluoromethane	ND<5		3000			
/inyl Chloride ^(g)	7.8	(2.1)	ND<50			
6 Recovery Surrogate	87	89	ND< 50	degradati		
Comments		07	86	-		
water and vapor samples are reported	in 119/1 soil samples in 1	and all TOLD and all	<u>1</u>			

Edward Hamilton, Lab Director

Reporting limit unless otherwise stated: water/TCLP extracts, ND < 0.5ug/L; soil, ND < 5ug/kg

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis

⁽b) tribromomethane; (c) tetrachloromethane; (d) (2-chloroethoxy) ethene; (e) trichloromethane; (f) dichloromethane; (g) chloroethene; (h) a lighter than water immiscible sheen is present; (i) liquid sample that contains greater than ~ 5 vol. % sediment.

DHS Certification No. 1644