

meeting Fred Devine, John Horn, Scott Hugenberger

Hertlein Electric - 19051 Lk Chabot 6-29-89

1960 - fall

- storm drain pipe installed where old creek once existed - work done by Flood Control
- tank hit by excavation equipment - punctured
- tank eventually replaced in late 1960 or early 1961


1975-'86

- tank removed
- odor detected in soil
- no visible holes observed in tank
- dug up noticeably cont. soil and aerated it
- had samples analyzed by _____ labs to verify aeration
- wells (3) drilled + one domestic

- 1) how deep?
- 2) where H₂O needed?
- 3) type of material

1989 Jan-Feb

- took upper soils to "clean" stockpile
- "dirty" soils pile created from deep sections



Request site assessment proposal + money # (333)
w/m 30 days