




997 Grant Ave., San Lorenzo. 12-18-90.  
6k premium unleaded fuel tank.




997 Grant Av., San Lorenzo. 12-18-90.  
6k unleaded premium fuel tank.




997 Grant Av., San Lorenzo. 12-18-90,  
middle tank 10k. Far left rib had  
pin hole to right. Note puddled water.



997 Grant Av., San Lorenzo. 12-18-90,  
middle 10k fuel tank. Crack noted  
next to rib in center of photo.




997 Grant Av., San Lorenzo. 12-18-90,  
Middle 10k tank.



997 Grant Av., San Lorenzo. 12-18-90,  
Middle 10k tank.



997 Grant Av., San Lorenzo. 12-18-90.  
3 fuel tanks before removal.



997 Grant Av., San Lorenzo. 12-18-90.  
North 10 K tank. Apparently in good  
condition.



997 Grant Av., San Lorenzo. 12-18-90.  
Pooled water, w. side of fuel tank pit.



997 Grant Av., San Lorenzo. 12-18-90.  
Pooled water - w. side of fuel tank pit.  
Oily sheen present - ~ 11 feet deep.



997 Grant Av. San Lorenzo. 12-18-90.  
Waste oil tank - bottom. No noticeable  
breaches.



997 Grant Av., San Lorenzo. 12-18-90  
Waste oil tank pit bottom immediately after  
tank removal. 9-10' depth.



997 Grant Av., San Lorenzo. 12-18-90  
Waste oil pit NW wall - surface to ~ 7'.



997 Grant Av., San Lorenzo. 12-18-90,  
Waste oil tank.