

October 22, 1993

Chevron U.S.A. Products Company 2410 Camino Ramon San Ramon, CA 94583 P.O. Box 5004 San Ramon, CA 94583-0804

Marketing Department Phone 510 842 9500

Ms. Juliet Shin Alameda County Health Care Services Agency 80 Swan Way, Room 200 Oakland, CA 94621

Re: Former Chevron Service Station #9-5630 997 Grant Avenue, San Lorenzo

Dear Ms. Shin:

Enclosed we are forwarding the Petition for Case Closure Report dated December 1, 1993, prepared by our consultant Geraghty & Miller, Inc. (GM) for the above referenced site. This report addresses in detail each item outlined in the Regional Water Quality Control Board's (RWQCB) memorandum dated February 26, 1992, titled "Format of Letter of Recommendations for UST Case Closure".

As per our conversation of October 21, 1993, the site meets all the criterion outlined by the RWQCB for case closure. We would appreciate your review and formal concurrence to the RWQCB of this closure recommendation. No further work is planned for this site. If you have any questions or comments, please do not hesitate to contact me at (510) 842-9581. Chevron appreciates all your efforts in bringing this site to closure.

Sincerely,

CHEVRON U.S.A. PRODUCTS COMPANY

Nancy Vukelich

Site Assessment and Remediation Engineer

Enclosure

cc: Mr. Rich Hiett, RWQCB-Bay Area Ms. B.C. Owen File (9-5630-1)

Mr. Lawrence E. Cogan Ware & Freidenrich 400 Hamilton Avenue Palo Alto, CA 94301 93 DEC -9 MM ID: 06



December 1, 1993 Project No. RC0256.001

Ms. Nancy Vukelich Chevron U.S.A. Products Company 2410 Camino Ramon San Ramon, California 94583

SUBJECT: Site Data Summary in Association with Petition for Case Closure, Former Chevron Service Station #9-5630, 997 Grant Avenue, San Lorenzo, California 94580.

Dear Ms. Vukelich:

This letter provides a summary of background information regarding the Chevron U.S.A. Products Company (Chevron) site referenced above. The purpose of this letter is to provide the Alameda County Health Care Services Agency with information so that they can make a recommendation for case closure to the San Francisco Bay Regional Water Quality Control Board (RWQCB).

#### EXECUTIVE SUMMARY

- Three gasoline underground storage tanks (USTs), one waste-oil tank, and associated product piping and fuel islands were excavated and removed from the site during December 1990.
- The highest concentrations of total petroleum hydrocarbons as gasoline (TPH-G) detected were 6,000 milligrams per kilogram (mg/kg) in the soil beneath the fuel service islands and product piping, and 4,500 mg/kg in the soil collected from the UST excavation.
- Petroleum hydrocarbons were not detected in the soil collected from the wasteoil tank excavation. Only one volatile organic compound (VOC) (4-methyl-2-pentanone) was detected, at a concentration of 0.077 mg/kg.

- Additional soil excavation was performed in the areas where petroleum hydrocarbons were detected during the UST, product piping, and fuel island removal. Soil was excavated vertically to groundwater and horizontally to the extent physically possible without undermining the public sidewalk at the site boundary. Excavation was continued until organic vapor meter photoionization detector (OVM) readings were less than 100 parts per million (ppm). Ten verification samples were collected from the sidewalls of the excavation. Concentrations of TPH-G exceeding 100 mg/kg were detected in only two samples (170 mg/kg and 270 mg/kg).
- Excavated soils were aerated until the concentration of TPH-G in all soils to be used for backfill material was less than 10 mg/kg. In all, 5,204 cubic yards (yd<sup>3</sup>) of soil were excavated and aerated. Of that, 220 yd<sup>3</sup> were transported offsite for disposal. The remaining 4,984 yd<sup>3</sup> of excavated soil were used for only 1380 yds 3 documented backfill material.

- Five groundwater monitor wells have been installed. The depth to water ranges from 7 to 13 feet below ground surface (bgs). The direction of groundwater flow ranges from west to northwest.
- Historically, petroleum hydrocarbons have been detected intermittently in the on-site monitor wells. Since March 1993, petroleum hydrocarbons have not been detected in any of the monitor wells. Further, petroleum hydrocarbons have never been detected in the one off-site monitor well situated immediately downgradient of the site.

### **BACKGROUND**

The site is a former Chevron service station at 997 Grant Avenue in southwestern Alameda County in the city of San Lorenzo on the northeast corner of the Grant and Washington Avenues intersection (Figure 1). The site is located in an area comprising residences and small businesses, and is currently an unpaved vacant lot. The former UST complex was located south of the service station building and consisted of two 10,000-gallon and one 6,000-gallon fiberglass USTs. The two 10,000-gallon tanks contained regular leaded and regular unleaded gasoline, and the 6,000-gallon tank contained supreme unleaded gasoline. A 1,000-gallon fiberglass waste-oil tank was located north of the northwest corner of the service station (Figure 2).



In September 1986, the USTs failed a pressure test due to leaks found in the vent lines. After the lines were replaced, the system was retested and the system tested tight. A tank pressure test performed in November 1989 indicated that the tanks tested tight (GeoStrategies, Inc. [GSI], February 8, 1991).

The four USTs were removed during December 1990. The leaded gasoline and waste oil USTs and fiberglass product lines had no visible holes or leaks. The regular unleaded gasoline UST had three large cracks and one pinhole on the bottom; the supreme unleaded gasoline UST had one small crack on the bottom. It is not known what damage might have occurred during tank removal (GSI, September 13, 1991).

## PREVIOUS WORK AND INVESTIGATIVE METHODS

#### SITE ASSESSMENTS/TANK REMOVAL

In September 1986, the product tanks failed a pressure test due to leaks found in the vent lines. After the lines were replaced, the system was retested and results showed that the system tested tight. The most recent tank test performed in November 1989 indicated that the tanks tested tight (GSI, February 8, 1991). In November 1990, four 2-inch diameter on-site groundwater monitoring wells (C-1 through C-4) (Figure 2) were installed to assess the soil and groundwater conditions beneath the site. Monitor Well C-1 was installed in the area of the former waste-oil tank, Monitor Wells C-2 and C-3 were installed in the area of the former pump islands, and Monitor Well C-4 was installed in the area of the former USTs.

Soil and groundwater samples from Wells C-1 through C-4 were analyzed for TPH-G (United States Environmental Protection Agency [USEPA] Method 8015, modified) and benzene, toluene, ethylbenzene, and xylenes (BTEX) (USEPA Method 8022). Soil and groundwater samples from Well C-1 (adjacent to the waste-oil tank) were also analyzed for VOCs (USEPA Method 8240) and total oil and grease (TOG) (USEPA Method 503E). Laboratory results for TPH-G, BTEX, total oil and grease, and VOC analyses performed on soil samples from Well C-1 were all below method detection limits. The highest concentrations of TPH-G were reported in the soil samples collected from 10 feet bgs from Wells C-2, C-3, and C-4, at concentrations of 99 mg/kg, 140 mg/kg, and 890 mg/kg, respectively. Benzene was identified in soil samples collected at a depth of 10



feet bgs from Wells C-2, C-3, and C-4, at concentrations of 0.18 mg/kg, 0.20 mg/kg, and 2.8 mg/kg, respectively (GSI, February 8, 1991).

In December 1990, groundwater samples were collected from Monitor Wells C-1 through C-4. At that time, liquid-phase hydrocarbons (LPH) or sheens were not observed in any of the wells, and laboratory analytical results from that sampling event reported no detectable concentrations of TPH-G. Benzene was detected in Monitor Wells C-2, C-3, and C-4, at concentrations of 0.7 micrograms per liter (µg/L), 1 µg/L, and 4 µg/L, respectively. Benzene was not detected in the groundwater sample collected from Monitor Well C-1. Additionally, concentrations of VOCs and TOG were not detected in groundwater samples collected from Monitor Well C-1. The depth to groundwater was approximately 11 feet bgs and the direction of groundwater flow was towards the west (GSI, February 8, 1991).

In December 1990, all USTs and piping were removed. During the excavation, approximately 504 yd<sup>3</sup> were removed to a depth of approximately 11.5 feet bgs, which was the level of encountered groundwater. The excavated soil was stockpiled onsite. Tank removal and soil excavation activities were witnessed by representatives from the Eden Consolidated Fire Protection District and the Alameda County Health Services Agency. Five soil samples (CW-1B and CW-2 through CW-5) were collected from the waste-oil tank excavation (Figure 3). The soil samples were analyzed for TPH-G (USEPA Method 8015, modified), BTEX (USEPA Method 8020), TOG (USEPA Method 503E), and VOCs (USEPA Method 8240). TPH-G, BTEX, and TOG were not detected in these soil samples. The VOC 4-methyl-2-pentanone was detected in Soil Sample CW-2 at a concentration of 77 micrograms per kilogram (μg/kg) (GSI, September 13, 1991).

Trenches were excavated to expose and remove the underground product piping between the UST complex and the service islands. Soil samples CT-1 through CT-11 were collected from the piping trenches at a depth of approximately 3.5 feet below grade. Soil Sample CT-12 was collected under the location of Soil Sample CT-2 at a depth of 5.5 feet below grade. These soil samples were analyzed for TPH-G (USEPA Method 8015, modified) and BTEX (USEPA Method 8020). Concentrations of TPH-G in Soil Samples CT-1 through CT-12 ranged from 6,000 mg/kg to below laboratory method detection limits (GSI, September 13, 1991). Laboratory analytical results are presented in Table 3.



Soil Samples CX-1B, CX-4B, CX-5B, CX-7B, CX-9B, and CX-10B were collected approximately 11.5 feet bgs at the bottom of the UST excavation. Soil samples CX-2S, CX-3S, CX-6S, CX-8S, CX-11S, CX-12S, CX-13S, and CX-14S were collected along the sidewalls of the excavation at depths varying from 8 to 9.5 feet bgs (Figure 3). These soil samples were analyzed for TPH-G (USEPA Method 8015, modified) and BTEX (USEPA Method 8020). Concentrations of TPH-G in these soil samples ranged from 4,500 mg/kg to below laboratory method detection limits (GSI, September 13, 1991). Laboratory analytical results are presented in Table 3.

In February 1993, one additional groundwater monitor well (C-5) was installed to the northwest of the site to further delineate the lateral extent of dissolved hydrocarbons (Figure 2). Both soil and groundwater samples were collected and analyzed for TPH-G (USEPA Method 8015, modified) and BTEX (USEPA Method 8020). Concentrations of TPH-G and BTEX were not detected in the soil and groundwater samples collected from Well C-5 (Groundwater Technology, Inc. [GTI], March 19, 1993).

# **HYDROGEOLOGIC SETTING**

#### REGIONAL HYDROGEOLOGY

The site lies on the west sloping surface of the San Francisco Bay Plain. The San Francisco Bay is approximately 1.6 miles southwest of the site. The nearest body of surface water, San Lorenzo Creek, is approximately 1,800 feet hydraulically crossgradient of the site and is a concrete-lined channel (Environmental Geosciences Engineering [EGE], May 12, 1992). No other surface streams are mapped in the vicinity of the site. The principal water-bearing unit is a sandy silt. The saturated thickness of the shallow semiconfined water-bearing unit is generally less than 10 feet thick (EGE, May 12, 1992). Historic groundwater depths have ranged between approximately 7 feet and 13 feet bgs.

## SITE HYDROGEOLOGY

Attachment 1 presents the exploratory boring logs of Soil Borings C-1 through C-5 (GSI, February 8, 1991 and GTI, March 19, 1993). The site is underlain predominantly by clay, with interbedded silts, sandy silts, and silty sands to a total explored depth of 33.5 feet bgs. Depth to groundwater ranges from approximately 7 feet to 13 feet bgs.



Groundwater monitoring data are presented in Table 1. Wells C-1 through C-3 have been monitored and sampled since December 1990, and have been monitored and sampled quarterly since September 1991. Monitor Well C-4 was monitored in December 1990 and again in September 1991, and was destroyed during initial excavation activities in December 1991. Monitor Well C-5 has been monitored and sampled quarterly since February 1993. Laboratory analytical results are presented in Table 2. Groundwater elevation contours as measured on September 7, 1993, are presented in Figure 5. The most recent gradient calculated from depth-to-groundwater measurements collected on September 7, 1993, was 0.0056. The regional groundwater flow direction has generally been reported ranging from west-southwest to west-northwest, towards the San Francisco Bay. The direction of groundwater flow as measured on September 7, 1993, was towards the northwest (Sierra Environmental Services [SES], October 13, 1993).

## BENEFICIAL USES OF WATER

To assess the existing beneficial uses of groundwater in the vicinity, a well survey was conducted on November 4, 1993, to identify wells located within a  $^{1}/_{2}$ -mile radius of the site. The well survey consisted producing a list of all active and inactive wells within a  $^{1}/_{2}$ -mile radius of the subject site that are on file at the Alameda County Flood Control District, Zone 7 (Zone 7). Additionally, Zone 7 produced a map of the locations of those wells (Figure 6). According to information provided by Zone 7, there are approximately 72 registered active wells located within a  $^{1}/_{2}$ -mile radius of the subject site. Of these, 35 are monitoring wells, 29 irrigation wells, 2 cathodic protection wells, 3 domestic wells, 1 is a test well, 1 an observation well, and 1 a pieziometer well.

## REMEDIATION ACTIVITIES AND EFFECTIVENESS

In soil samples collected during the UST excavation, elevated concentrations of petroleum hydrocarbons were detected beneath the former tank complex and beneath one of the former pump islands located immediately west of the tank complex. An additional 4,700 yd<sup>3</sup> were excavated in February 1991 to remove soils containing these elevated concentrations (EGE, May 12, 1992). Soil excavation was limited vertically to groundwater and horizontally so as not to jeopardize existing sidewalk structures. Overexcavation of the soil was conducted at the site based on field observations and the results of screening the soil for organic vapor using an OVM. Overexcavation was continued until OVM readings were less than 100 parts per million (ppm). Verification soil



samples were then collected. Soil Samples CX-15S through CX-24S were collected from the sidewalls of the overexcavation (Figure 4). Concentrations of TPH-G in those soil samples ranged from 270 mg/kg to below laboratory method detection limits. Laboratory analytical results are presented in Table 3.

Following excavation, the soil was stockpiled and composite soil samples were collected and analyzed for TPH-G and BTEX. Upon receipt of the initial laboratory analytical results for the stockpiled soils, all soils with a TPH-G concentration of greater than 9 mg/kg (approximately 1,600 yd³) were aerated onsite in compliance with Bay Area Air Quality Management District (BAAQMD) guidelines. Upon completion of the aeration process, soil samples were collected from each approximately 20 yd³ of aerated soil. The samples were analyzed for TPH-G and BTEX. If the TPH-G concentration in the stockpiled soil was less than 10 mg/kg, then those soils were retained for use as backfill material. All other soils were reaerated to further reduce TPH-G concentrations, and then resampled. Approximately 220 yd³ of soil were transported to the Browning Ferris Industries North Vasco Road Disposal Facility in Livermore, California. All remaining stockpiled soils with TPH-G concentrations less than 10 mg/kg (approximately 4,984 yd³) were retained onsite for use as backfill material (GSI, September 13, 1991).

int mentioned in cited

The excavation was initially backfilled with one foot of 1<sup>1</sup>/<sub>2</sub>-inch drain rock. Filter fabric was placed on top of the drain rock. The stockpiled excavated and aerated soil (gravels, sands, and clays) were used to backfill the excavation. The backfill and compaction were performed by Golden West Environmental Services. In November 1991, Construction Material Testing, Inc. (CMT) personnel visited the site and performed soil density tests. Final testing found the soil to meet or exceed the specified density (CMT, December 18, 1991).

Geraghty & Miller appreciates the opportunity to be of service to Chevron. If you have any questions, please do not hesitate to contact the undersigned at (510) 233-3200.

Sincerely,

GERAGHTY & MILLER, INC.

Darryl B. Snow

Staff Geologist/Project Manager

Gary W. Keyes

Principal Engineer/Associate

Richmond, California Office Manager

Enclosures: Table 1 Summary of Depth-to-Water Measurements

Table 2 Summary of Groundwater Analytical ResultsTable 3 Soil Sample Laboratory Analytical Results

Figure 1 Site Location Map

Figure 2 Site Plan

Figure 3 First Phase Excavation Second Phase Excavation

Figure 5 Groundwater Elevation Contour Map September 7, 1993

Figure 6 Well Survey Map

Attachment 1 Copies of GSI and GTI Exploratory Boring Logs

#### REFERENCES

- Construction Materials Testing. December 18, 1991. Results of Soil Compaction Testing, Former Chevron U.S.A. Products Company Service Station #9-5630, 997 Grant Avenue, San Lorenzo, California.
- Environmental Geosciences Engineering. May 12, 1992. Results of Corrective Action and Feasibility Assessment, Former Chevron U.S.A. Products Company Service Station #9-5630, 997 Grant Avenue, San Lorenzo, California.
- GeoStrategies Inc. February 8, 1991. Preliminary Site Assessment/Well Installation Report, Former Chevron U.S.A. Products Company Service Station #9-5630, 997 Grant Avenue, San Lorenzo, California.
- U.S.A. Products Company Service Station #9-5630, 997 Grant Avenue, San Lorenzo, California.
- Groundwater Technology, Inc. March 19, 1993. Additional Environmental Assessment Report, Former Chevron U.S.A. Products Company Service Station #9-5630, 997 Grant Avenue, San Lorenzo, California.
- Sierra Environmental Services. October 13, 1993. Quarterly Groundwater Sampling Report, Former Chevron U.S.A. Products Company Service Station #9-5630, 997 Grant Avenue, San Lorenzo, California.

Table 1: Summary of Depth-to-Water Measurements
Former Chevron Service Station #9-5630
997 Grant Avenue, San Lorenzo, California

		Depth to	Product		
		Water (a)	Thickness (b)	Top of Casing	_
Well	Date	(feet)	(feet)	Elevation (c)	Elevation
C-1	5-Dec-90	12.44	0	24.08 (d)	11.64
~ .	6-Sep-91	13.20	o	23.88 (e)	10.68
	4-Dec-91	11.71	Ö	25.00 (0)	12.17
	2-Apr-92	9.43	Ö		14.45
	3-Jun-92	10.14	Ö		13.74
	2-Sep-92	11.79	ő		12.09
	1-Dec-92	11.78	ő		12.10
	23-Mar-93	7.94	o		15.94
	15-Jun-93	9.39	ő		14.49
	7-Sep-93	10.72	ő		13.16
	7-uvp-75	10,72	Ū		15.10
C-2	5-Dec-90	11.30	0	22.69 (d)	11.39
	6-Sep-91	11.00	0	21.54 (e)	10.54
	4-Dec-91	9.38	0		12.16
	2-Apr-92	7.33	0		14,21
	3-Jun-92	8.99	0		12.55
	2-Sep-92	9.59	0		11.95
	1-Dec-92	9.58	0		11.96
	23-Mar-93	6.30	0		15.24
	15-Jun-93	7.27	0		14.27
	7-Sep-93	8.55	0		12.99
C-3	5-Dec-90	11.75	0	23.45 (d)	11.70
	6-Sep-91	11.62	Ö	22.40 (e)	10.78
	4-Dec-91	10.14	0	` '	12.26
	2-Apr-92	8.07	o		14.33
	3-Jun-92	8.63	0		13.77
	2-Sep-92	10.30	o		12.10
	1-Dec-92	10.24	0		12.16
	23-Mar-93	6.83	Ö		15.57
	15-Jun-93	7.95	o		14.45
	7-Sep-93 (h)	NM	NM		NM
C-4	5-Dec-90	11.85	0	23.32 (d)	11.47
	6-Sep-91 (f)	NM	NM	, ,	NM

Table 1: Summary of Depth-to-Water Measurements
Former Chevron Service Station #9-5630
997 Grant Avenue, San Lorenzo, California

Well	Date	Depth to Water (a)  (feet)	Product Thickness (b) (feet)	Top of Casing Elevation (c)	Top of Water Elevation
C-5	16-Feb-93	6.64	0	22.01 (g)	15.37
	23-Mar-93	6.60	0	_	15.41
	15-Jun-93	8.10	0		13.91
	7-Sep-93	9.40	0		12.61

- (a) Measured from top of PVC casing.
- (b) Sierra Environmental Services product thicknesses were measured with an MMC flexi-dip interface probe.
- (c) Top-of-casing elevations and well locations surveyed by KCA Engineers, Inc., San Francisco, California. Well elevations surveyed relative to City of San Francisco survey datum, which is 8.62 feet above U.S. Coastal Geodetic survey mean sea-level datum.
- (d) Wellhead elevations taken from the Preliminary Site Assessment/Well Installation Report prepared by GeoStrategies, Inc., dated February 8, 1991.
- (e) Top-of-casing elevations surveyed by Ron Miller, P.E. #15816, on April 2, 1992. Groundwater elevations prior to this date have been corrected using these survey data.
- (f) Well was destroyed during tank removal and soil excavation operations.
- (g) Top-of-casing elevation compiled from the Groundwater Technology Inc., report prepared for Chevron. Well construction details for C-5 not available for inclusion in this report.
- (h) Well not located by SES personnel.

#### NM Not measured.

The Top of Water Elevation in the presence of liquid-phase hydrocarbons is calculated by (TOC-DTW)+((DTW-DTP) X 0.8).



Table 2: Summary of Groundwater Analytical Results
Former Chevron Service Station #9-5630
997 Grant Avenue, San Lorenzo, California.

		TPH (a)	Benzene (b)	Toluene (b)	Ethylbenzene (b)	Xylenes (b)	Total Oil & Gas (c)
Well	Date	(μg/L)	(µg/L)	(µg/L)	(µg/L)	(μg/L)	(μg/L.)
C-1	5-Dec-90 (d)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	<5,000
	6-Sep-91 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	NA
	4-Dec-91 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	NA
	2-Apr-92 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	<5,000
	3-Jun-92 (e)	ND(<50)	(1.4)	(1.5)	$\bigcirc 0.6 \bigcirc$	(3.0)	NA
	2-Sep-92 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	NA
	1-Dec-92 (e)	ND(<50)	$\bigcirc 0.6$	(3.5)	(0.7)	$\langle 3.4 \rangle$	NA
	23-Mar-93 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	NA
	15-Jun-93 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<1.5)	NA
	7-Sep-93 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<1.5)	NA
			2. E. S.				
C-2	5-Dec-90 (d)	ND(<50)	(0.7)	ND(<0.5)	ND(<0.5)	0.5	NA.
	6-Sep-91 (e)	ND(<50)	1.3	(0.6.)	(0.7)	1.5	NA
	4-Dec-91 (g)	NA	NA	NA	NA	NA	NA
	2-Apr-92 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	NA
	3-Jun-92 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	NA
	2-Sep-92 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	NA
	1-Dec-92 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	NA
	23-Mar-93 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	NA
	15-Jun-93 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<1.5)	NA
	7-Sep-93 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<1.5)	NA
G 2	£ 73 00 (4)	NID( -60)	15	( O 7 )	NTD( AN E)	NTD( =0.5)	DT A
C-3	5-Dec-90 (d)	ND(<50)	150	(0.7	ND(<0.5)	ND(<0.5)	NA NA
	6-Scp-91 (e)	1,100	\150 \rightarrow \150 \	\_0.6 \ \_\(0.6)	51	1.9	NA NA
	4-Dec-91 (e)	89	ND(<0.5)	ND(<0.5)	0.7	0.6	NA NA
	2-Apr-92 (e)	60	2.1	1.3	1.1	3.2	NA NA
	3-Jun-92 (e)	180 (	3.0	1.4	0.6	1.5	NA
	2-Sep-92 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	(0.9)	NA
	1-Dec-92 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	NA NA
	23-Mar-93 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	NA
	15-Jun-93 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<1.5)	NA
	7-Sep-93 (i)	NA	NA	NA	NA	NA	NA
C 4	5 Dag 00 (4)	ND(-EN	~~ <b>A</b>	2	^ 7	2	N) A
C-4	5-Dec-90 (d)	ND(<50)	4	2_	0.7	3	NA NA
	6-Sep-91 (f)	NA	NA	NA	NA	NA	NA
C-5	16-Feb-93 (h)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	NA
	23-Mar-93 (c)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	NA
	15-Jun-93 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<1.5)	NA
	7-Sep-93 (e)	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<1.5)	NA
	, dob 22 (c)	112(400)	(10.0)	112(10.0)	112 (40.0)	110 ( 71.0)	- 14 B

Project No. RC0256.001

Table 2: Summary of Groundwater Analytical Results
Former Chevron Service Station #9-5630
997 Grant Avenue, San Lorenzo, California.

TB 5-Dec-90 (d) ND(<50) ND(<0.5) ND(<0.	otal Oil & Gas (c) (µg/L)	Xylenes (b) (μg/L)	Ethylbenzene (b) (µg/L)	Toluene (b) (µg/L)	Benzene (b) (μg/L)	TPH (a) (μg/L)	Date	Well
6-Sep-91 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) A-Dec-91 (e) ND(<50) ND(<0.5) ND(<0.	NA	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<50)	5-Dec-90 (d)	тв
4-Dec-91 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  2-Apr-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  3-Jun-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  2-Sep-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  1-Dec-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  23-Mar-93 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  15-Jun-93 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  7-Sep-93 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  4-Dec-91 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  2-Apr-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  3-Jun-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  2-Sep-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  2-Sep-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  1-Dec-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  ND(<0.5) ND(<0.5)	NA	• •	, ,	- '		, ,	• •	
2-Apr-92 (e) ND(<50) ND(<0.5)	NA		• •	- ,	•		•	
3-Jun-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) 2-Sep-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) 1-Dec-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) 23-Mar-93 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) 15-Jun-93 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) 7-Sep-93 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<1.5)  BB 6-Sep-91 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) 4-Dec-91 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) 2-Apr-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) 3-Jun-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) 2-Sep-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) 1-Dec-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)	NA		, ,	• •			• •	
1-Dec-92 (e) ND(<50) ND(<0.5) ND(<1.5)	NA	, .	• •	, ,	• •			
23-Mar-93 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<1.5)	NA	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<50)	2-Sep-92 (e)	
15-Jun-93 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<1.5) 7-Sep-93 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  BB 6-Sep-91 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) 4-Dec-91 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) 2-Apr-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) 3-Jun-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) 2-Sep-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) 1-Dec-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)	ÑΑ	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<50)	1-Dec-92 (e)	
7-Sep-93 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<1.5)  BB 6-Sep-91 (e) ND(<50) ND(<0.5) ND	NA	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<50)	23-Mar-93 (e)	
BB 6-Sep-91 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) A-Dec-91 (e) ND(<50) ND(<0.5) ND(	NA	ND(<1.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<50)	15-Jun-93 (e)	
4-Dec-91 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  2-Apr-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  3-Jun-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  2-Sep-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  1-Dec-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)  ND(<0.5) ND(<0.5)	NA	ND(<1.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<50)	7-Sep-93 (e)	
2-Apr-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) S-Jun-92 (e) ND(<50) ND(<0.5) ND(<0.	NA	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0,5)	ND(<50)	6-Sep-91 (e)	вв
3-Jun-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5) 2-Sep-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5)	NA	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<50)	4-Dec-91 (e)	
2-Sep-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) 0.4 1-Dec-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)	NA	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<50)	2-Apr-92 (e)	
1-Dec-92 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5)	NA	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<50)	3-Jun-92 (e)	
	NA	0.4	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<50)	2-Sep-92 (e)	
23-Mar-93 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<0.5)	NA	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<50)	1-Dec-92 (e)	
	NA	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<50)	23-Mar-93 (e)	
15-Jun-93 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<1.5)	NA	ND(<1.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<50)	15-Jun-93 (e)	
7-Sep-93 (e) ND(<50) ND(<0.5) ND(<0.5) ND(<0.5) ND(<1.5)	NA	ND(<1.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<50)	7-Sep-93 (e)	

<sup>(</sup>a) TPH = Total petroleum hydrocarbons as gasoline. Analyzed by USEPA Method 8015/5030, modified.

<sup>(</sup>i) Well was not located by SES personnel.

NA	Not analyzed
TB	Trip blank
μg/L	Micrograms per liter
ND	Not detected (laboratory method detection limit)
ТВ	Trip Blank
BB	Bailer Blank

<sup>(</sup>b) Analyzed by USEPA Method 8020.

<sup>(</sup>c) Analyzed by USEPA Method 503E.

<sup>(</sup>d) Samples analyzed by Superior Analytical Laboratory of San Francisco, California.

<sup>(</sup>c) Samples analyzed by Superior Precision Analytical, Inc. of Martinez, California.

<sup>(</sup>f) Well was destroyed during tank removal and soil excavation operations.

<sup>(</sup>g) Well was obstructed and could not be sampled.


<sup>(</sup>h) Analytic laboratory information for this event not available for inclusion in this report.


Table 3: Soil Sample Analytical Results
Former Chevron Service Station #9-5630
997 Grant Avenue, San Lorenzo, California.


Sample Number	Sample Depth (feet)	Sample Date	Analysis Date	TPH-G (mg/kg)	Benzene (mg/kg)	Toluene (mg/kg)	Ethyl- benzene (mg/kg)	Xylenes (mg/kg)	Oil and Grease (mg/kg)
Product Pi	ping Tre	nches/Pump	Islands Samp	oles					
CT-1	3.5	18-Dec-90	28-Dec-90	<1	<.005	<.005	<.005	0.009	
CT-2	3.5	18-Dec-90	28-Dec-90	3,400	<0.5	1.7	12	80	
CT-3	3.5	18-Dec-90	2-Jan-91	8	0.12	0.10	0.35	0.30	
CT-4	3.5	18-Dec-90	28-Dec-90	8	0.11	0.069	0.26	0.15	
CT-5	3.5	18-Dec-90	2-Jan-91	<1	0.010	<.005	<.005	0.017	
CT-6	3.5	18-Dec-90	28-Dec-90	5	0.031	0.010	<.005	0.15	
CT-7	3.5	18-Dec-90	28-Dec-90	2	<.005	0.006	0.007	0.030	
CT-8	3.5	18-Dec-90	28-Dec-90	<1	<.005	<.005	<.005	0.005	
CT-9	3.5	18-Dec-90	28-Dec-90	3	<.005	0.012	<.005	0.030	
CT-10	3.5	18-Dec-90	28-Dec-90	13	0.029	0.010	0.29	0.61	
<b>C</b> T-11	3.5	18-Dec-90	28-Dec-90	4	0.45	<.005	0.11	0.062	
CT-12	5.5	15-Jan-91	24-Jan-91	6,000	0.500	17	56	400	
Gasoline Ta	ank Exca	vation Samp	les						
CX-1B	11.5	18-Dec-90	28-Dec-90	1,500	1.2	50	29	160	
CX-2S	9.5	18-Dec-90	28-Dec-90	12	0.014	0.100	0.096	0.38	
CX-3S	8.5	18-Dec-90	28-Dec-90	6	0.009	0.014	0.100	0.075	
CX-4B	11.5	18-Dec-90	28-Dec-90	1,700	0.40	31	25	150	
CX-5B	11.5	18-Dec-90	28-Dec-90	1,600	0.39	32	24	140	
CX-6S	8.5	18-Dec-90	28-Dec-90	6	0.005	0.013	0.040	0.12	
CX-7B	11.5	18-Dec-90	28-Dec-90	730	0.89	19	11	62	
CX-8S	8.0	18-Dec-90	28-Dec-90	4,500	0.70	10	39	210	


Table 3: Soil Sample Analytical Results
Former Chevron Service Station #9-5630
997 Grant Avenue, San Lorenzo, California.


Sample Number	Sample Depth (feet)	Sample Date	Analysis Date	TPH-G (mg/kg)	Benzene (mg/kg)	Toluene (mg/kg)	Ethyl- benzene (mg/kg)	Xylenes (mg/kg)	Oil and Grease (mg/kg)
CX-9B	11.5	18-Dec-90	28-Dec-90	1,100	<0.3	9.9	15	80	
CX-10B	11.5	18-Dec-90	28-Dec-90	54	0.026	0.23	0.38	1.6	
CX-11S	8.0	18-Dec-90	28-Dec-90	780	0.35	11	11	65	
CX-12S	8.5	18-Dec-90	28-Dec-90	220	0.17	0.070	7	0.30	
CX-13S	8.5	18-Dec-90	28-Dec-90	1,900	0.45	16	28	160	
CX-14S	9.0	18-Dec-90	29-Dec-90	680	<0.3	6	9.6	57	
CX-15S	9.5	15-Feb-91	25-Feb-91	3	<.005	<.005	0.014	0.008	
CX-16S	9.5	15-Feb-91	25-Feb-91	2	<.005	<.005	0.011	0.013	
CX-17S	9.5	15-Feb-91	25-Feb-91	<1	0.056	<.005	<.005	0.011	
CX-18S	9.5	15-Feb-91	25-Feb-91	2	800.0	<.005	0.019	0.006	
CX-19S	9.5	15-Feb-91	25-Feb-91	46	< 0.30	0.046	0.18	0.41	
CX-20S	9.5	15-Feb-91	25-Feb-91	<1	<.005	<.005	<.005	<.005	
CX-21S	9.5	15-Feb-91	25-Feb-91	170	0.037	0.075	2	4	
CX-22S	9.5	15-Feb-91	25-Feb-91	54	0.024	0.038	0.25	0.83	
CX-23S	9.5	15-Feb-91	25-Feb-91	270	0.011	0.093	3	9	
CX-24S	8.5	26-Aug-91	30-Aug-91	5	<.005	0.049	0.012	0.015	
TPH-G CX CW B	Excavat		ocarbons as g excavation san		mg/kg CT S	Milligrams per Trench sample Sidewall			











EXPLANATION

C-5 Monitoring wellC-4 Destroyed well

12.61 Ground water elevation, in feet

NM Not measured

Ground water elevation contour, dashed where inferred, queried where uncertain

Approximate ground water flow direction

0 30 60 ft.



Reference: SIERRA

Project No. RC0256.000


13.00



GROUNDWATER ELEVATION CONTOUR MAP SEPTEMBER 7, 1993

Former Chevron Service Station #9-5630 997 Grant Avenue San Lorenzo, California FIGURE

5



Reference: Alameda County Flood Control District - Zone 7



Project No. RC0256.000

## **WELL SURVEY MAP**

.5 MILE RADIUS NOVEMBER 4, 1993
Former Chevron Service Station #9-5630
997 Grant Avenue
San Lorenzo, California

**FIGURE** 

6

# ATTACHMENT 1

# COPIES OF GSI AND GTI EXPLORATORY BORING LOGS

	MAJOR DIVIS	SIONS		TYPICAL NAMES
VE VE		CLEAN GRAVELS WITH LITTLE	GW	WELL GRADED GRAVELS WITH OR WITHOUT SAND, LITTLE OR NO FINES
). 200 SIE	GRAVELS MORE THAN HALF	OR NO FINES	GP	POORLY GRADED GRAVELS WITH OR WITHOUT SAND, LITTLE OR NO FINES
D SOILS THAN NO	COARSE FRACTION IS LARGER THAN NO. 4 SIEVE SIZE	GRAVELS WITH	GM	SILTY GRAVELS, SILTY GRAVELS WITH SAND
COARSE-GRAINED SOILS MORE THAN HALF IS COARSER THAN NO. 200 SIEVE		OVER 15% FINES	GC	CLAYEY GRAVELS, CLAYEY GRAVELS WITH SAND
OARSE-		CLEAN SANDS WITH LITTLE	sw	WELL GRADED SANDS WITH OR WITHOUT GRAVEL, LITTLE OR NO FINES
ETHAN	SANDS MORE THAN HALF	OR NO FINES	SP	POORLY GRADED SANDS WITH OR WITHOUT GRAVEL, LITTLE OR NO FINES
MOR	COARSE FRACTION IS SMALLER THAN NO. 4 SIEVE SIZE	SANDS WITH	SM	SILTY SANDS WITH OR WITHOUT GRAVEL
		OVER 15% FINES	sc	CLAYEY SANDS WITH OR WITHOUT GRAVEL
SIEVE			ML	INORGANIC SILTS AND VERY FINE SANDS, ROCK FLOUR, SILTS WITH SANDS AND GRAVELS
ILS 1 NO. 200		ID CLAYS 50% OR LESS	CL	INORGANIC CLAYS OF LOW TO MEDIUM PLASTICITY CLAYS WITH SANDS AND GRAVELS, LEAN CLAYS
FINE-GRAINED SOILS HALF IS FINER THAN NO			OL.	ORGANIC SILTS OR CLAYS OF LOW PLASTICITY
IE-GRAI			МН	INORGANIC SILTS, MICACEOUS OR DIATOMACIOUS, FINE SANDY OR SILTY SOILS, ELASTIC SILTS
FINE-GRAINED SOILS MORE THAN HALF IS FINER THAN NO. 200 SIEVE		ND-CLAYS EATER THAN 50%	СН	INOPGANIC CLAYS OF HIGH PLASTICITY, FAT CLAYS
MORE			ОН	TRISANIC SILTS OR CLAYS OF MEDIUM TO HIGH PLASTICITY
-	HIGHLY ORG	GANIC SOILS	PT	C. A.* AND OTHER OF YORGANIC SOILS

- Permeability Perm - Consolidation Consol - Liquid Limit (%) LL PI - Plastic Index (%) - Specific Gravity G۶ - Particle Size Analysis MA 2.5 YR 6/2

Soil Color according to Munsell Soil Color Charts (1975 Edition)

5 GY 5/2 - GSA Rock Color Chart - No Soil Sample Recoverd

- "Undisturbed" Sample

- Bulk or Classification Sample

· First Encountered Ground Water Level

· Piezometric Ground Water Level

 Sample drive hammer weight - 140 pounds failing 30 inches. Blows required to drive sampler 1 foot are indicated on the logs



GeoStrategies Inc.

Unified Soil Classification - ASTM D 2488-85 and Key to Test Data

Casi	San Lorenzo, California  Sheet 1  od by: KDM   Dniller: Bayland   of 2  ig installation data:  of Box Elevation: 24.08   Datum: MSL  or Level   17.5'   12.44'    ime   15:45   17:32    oate   11/13/90   12/5/90    Description
City   Logs   Casi   Cost	San Lorenzo, California  Sheet 1  of 2  grant part of 2  grant part of 2  grant part of 2  grant part of 3  grant part of 3
Casi	Solution   Description   Des
Top   Gold diameter:   B-Inches   Top   Gold diameter:   B-Inches   Top   Gold diameter:   B-Inches   Gold diameter:   Gold	pg installation data:  of Box Elevation: 24.08   Datum: MSL  or Level   17.5'   12.44'    ime   15:45   17:32    Date   11/13/90   12/5/90    Description  PAVEMENT SECTION - 1.3 ft.
Cole diameter: 8-Inches	or Level 17.5' 12.44*
Columbia   Columbia	or Level 17.5' 12.44*
0	ime 15:45 17:32 Date 11/13/90 12/5/90  Description  PAVEMENT SECTION - 1.3 ft.
0 1 1 2 3 3 4 4 5 5 6 5 6 6 7 7 8 8 9 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Description 12/5/90  Description  PAVEMENT SECTION - 1.3 ft.
0 1 1 2 3 3 4 4 5 5 6 5 6 6 7 7 8 8 9 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Description PAVEMENT SECTION - 1,3 ft.
0 1 1 2 3 3 4 4 5 5 6 5 6 6 7 7 8 8 9 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	PAVEMENT SECTION - 1,3 ft.
1 2 3 3 3 4 4 5 5 5 5 6 5 7 7 7 7 7 7 7 7 7 7 7 7 7 7	
1 2 3 3 3 4 4 5 5 5 5 6 5 7 7 7 7 7 7 7 7 7 7 7 7 7 7	
1 2 300 C-1- 6.8 400 S&H 5.0 5 refusal 6 8 9 9 11.5 18 S&H 10.5 11 12 12 12 13 13 14 14 14 15 15 15 15 15 15 15 15 15 15 15 15 15	
300 C-1- 6.8 400 S&H 5.0 5 refusal 6 7 8 9 1.5 18 S&H 10.5 11 12 12 13 14	W 77/ OLAY (OL) Sleet (40) (70 0/4)
300 C-1- 6.8 400 S&H 5.0 5 refusal 6 7 8 9 1.5 18 S&H 10.5 11 12 12 13 14	SILTY CLAY (CL) - black (10YR 2/1), very stiff, damp,
300 C-1- 6.8 400 S&H 5.0 5 refusal 6 7 8 9 9 1.5 18 S&H 10.5 11 12 12 14 14 14	nedium plasticity; 50% clay; 35% silt; 15% fine sand;
300 C-1- 6.8 400 S&H 5.0 5 refusal 6 7 8 9 9 1.5 18 S&H 10.5 11 12 12 14 14 14 14	race fine gravel in cuttings.
300   C-1- 6.8   400   S&H   5.0   5	
300   C-1- 6.8   400   S&H   5.0   5	DU TO COAND COAD III I I I I I I I I I I I I I I I I I
6.8 400 S&H 5.0 5 refusal 6 7 8 9 1.5 18 S&H 10.5 11 12 13 14 14	SILTY SAND (SM) - dark grayish brown (10YR 4/2),
refusal 6 7 7 8 8 9 9 1 11 12 12 13 14 14 14 15 15 15 15 15 15 15 15 15 15 15 15 15	nedium dense, damp; 70% fine sand; 30% silt; trace
6 7 8 8 9 9 1 1.5 18 S&H 10.5 11 12 12 13 14 14 14 15 15 15 15 15 15 15 15 15 15 15 15 15	vorm burrows.
7 8 9 9 1.5 18 S&H 10.5 11 12 12 13 14 14 14 15 15 15 15 15 15 15 15 15 15 15 15 15	
8 9 9 1 1.5 18 S&H 10.5 11 12 12 13 14 14 14 15 15 15 15 15 15 15 15 15 15 15 15 15	
8 9 9 1 1.5 18 S&H 10.5 11 12 12 13 14 14 14 15 15 15 15 15 15 15 15 15 15 15 15 15	
1.5 18 S&H 10.5 11 12 12 13 14 14 14 15 15 15 15 15 15 15 15 15 15 15 15 15	
1.5   18   S&H   10.5   11   12   13   14   14   15   15   15   15   15   15	
1.5   18   S&H   10.5   11   12   13   14   14   15   15   15   15   15   15	SILTY CLAY (CL/ML) - black (10YR 2/1), very stiff, da-
1.5   18   S&H   10.5   11   12	ow plasticity; 60% clay; 45% silt; 5% fine sand; roots
1.5   18   S&H   10.5   11   12	ootholes; small white caliche concretions.
11 12 13 14 14 15	
12 13 14 14 C-1- 15	
13 ¥ 14 C-1- 15	
13 ¥ 14 C-1- 15	
14 C-1- 15	CLAY (CL) - light alive brown (2.5YR 5/4), stiff, mais:
C-1- 15	medium to high plasticity; 80% clay; 15% silt; 5% fine
C-1- 15	sand.
C-1- 15	
	ocasional small (<1 mm) black and red-brown rock
	ragments.
1.5   10   S&H   15.5	
16	
	(
17	
18 7	
18 -	easier drilling at 17 feet.
	easier drilling at 17 feet. Water on sample rods at 17.5 feet.
Remarks: * Converted to equivalent Standard Penetration blow	

REVIEWED BY RGICEG MCC: CE6 1351 JOB NUMBER 727801

DATE 11/90

REVISED DATE

Field loca	tion of be	onng:						Project No		, Date.	11/12/90	Bonng No:	٦
		•							Chevron Ser		n No. 5630	C-1	
		(S	ee Plate	2)					997 Grant Av			<b>\</b>	
		-							San Lorenzo			Sheet 2	_
									KDM	Driller:	Bayland	of 2	┙
								Casing installs	ation data:				
Drilling n		Hollow S		ger					<del></del>				_
Hole dia	neter:	8-Inches					<del></del>	Top of Box Ei	evation:		Datum:		4
ı	( <del>)</del>			<b>-</b>			2 S	Water Level		<u> </u>			
PiO (pp·m)	Blows/ft * or ressure (ps	Type of Semple	Sample Number	٠ <del>ق</del>	Sample	Well Detar	8 5	Time	-	<u> </u>			-1
<u>"                                    </u>	Blows/ft * or Pressure (psi)	l r⊵og	& ₹	8	8	~ -	Sort Group Symbol (USCS)	Date	<u> </u>	December	_ <del>_\</del>		$\dashv$
-	1 1						i i i i	SANDY	CILT (MIL)	Description	(2.5Y 7/4), k	noce moiet	$\dashv$
		ļ	C-1-	20							e sand; 10%		-1
1.5	4	S&H	20.5	20					ed fine sand			1000.00	┨
1.5	<u> </u>	- Our i	20.0	21				- Julian	, <u>, , , , , , , , , , , , , , , , , , </u>				-
<u> </u>		-		-				······································	······································	·			
		ļ <u>-</u>		22				grades	to:	_ <del></del>			
				1									
				23									
				<u>į</u> į							cattered sma		_
				24	<u> </u>			nodules	; rare harde	r fragments	(1/4 inch dia	imeter).	_
	ļ <u>.</u>			<u> </u>									_
			C-1-	25									
1.5	8	S&H	25.5									<del></del>	-
	<del> </del>	ļ	<del></del>	26	<u> </u>								
ļ				27								<del></del>	$\dashv$
		<del> </del>	<u> </u>	27				Stiffer	t 28 feet.				
				28	$\vdash$		11///	1 Cunera	201001.				$\dashv$
<u> </u>	<del> </del>				-	:		CLAY (	CL) - pale ve	llow brown	(2.5Y 7/4), v	ery stiff,	~
	ļ	<del> </del>		29		1					clay; 25% sih		
<del>-</del>		1	C-1-	1				sand.					
1.5	15	S&H	30.0	30			Y///					<del></del>	
								1					
		<u> </u>		31	<u></u>							<del></del>	
		<u> </u>	ļ	<u>.</u>				CLAYE	Y SILT (ML/	CL) - pale y	ellow brown	(2.5Y 7/4),	
	<del>                                     </del>	-	<del>                                     </del>	: 32			Y//				dium plastic	ity; 50% Silt;	
<u></u>	<del> </del>		-	1 00			1///	40% CIS	ay; 10% fine	Saliu.		<del></del>	
NI/A	8	SPT	33.5	<u> </u> 33			11/	<b></b>					
N/A	1 0	1 371	33.5	34			111/	Rottom	of sample a	t 33.5 feet			
<del></del>		+	<del>                                     </del>	1	-				of boring at				
	<del> </del>	<del>                                     </del>	-	35	-		1	11/12/9				····	
	<u> </u>	<del> </del>	<del>                                     </del>	7				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				··········	
		<del> </del>	1	<sup>  </sup> 36		1				<del>,</del>		······································	
			1	1									
				37		]							
				]		Į				,			
				] 38		]							
			<u> </u>		<u></u>								
	1	<u> </u>	1	39		<u> </u>				<del></del>			
Hemark	s: N/A =	Not Ava	ulable										
			<u>.</u>										
							Log of	Boring				BORING	ON E

GSI

GeoStrategies Inc.

C-1

 JOB NUMBER
 REVIEWED BY PRICEG
 DATE
 REVISED DATE

 727801
 MCC: CE6 /35/
 11/90

Field loca	tion of b	onng:					~	Project No 727801 Date: 11/12/90 Boring No
								Chent: Chevron Service Station No. 5630
		(S	ee Plate	2)				Location: 997 Grant Avenue
								City: San Lorenzo, California Sheet 1
								Logged by: KDM Dniler: Bayland of 2
								Casing installation data:
Drilling r			Stem Aug	jer				The differential colors
Hole dia	meter:	8-inches	3				T	Top of Box Elevation: 22.69 Datum: MSL
	ક્રિ		φ×.	<b>-</b>		_	SCS	Water Level 18.7'   11.0'   11.30'
PiO (mgd)	Blows/ft.* or ressure (ps	Type of Sample	Sample Number	Depth (ft.)	Sample	Wett	0. P. O. P.	Time         16:00         15:50         17:00           Date         11/12/90         11/13/90         12/5/90
- <u>y</u>	Blows/ft.* or Pressure (ps)	⊬w	ぴヹ	å	Ø		Soll Group Symbol (USCS)	Description 12/3/30
	-	<del> </del>			<u>}</u>	1	65	PAVEMENT SECTION - 1.3 ft. thick
	-	<del> </del>		1				PAVENDENT OPENION - 1.0 II. UIION
	<del>                                     </del>	<del> </del>	1	•	-	1		
	<del>                                     </del>	<del>                                     </del>		2		1		
			†	_	<del></del>	1		SANDY CLAY (CL) - black (2.5YR/), medium stiff, damp,
	1			3		1	V///	medium plasticity; 50 % clay; 40% fine sand; 10% silt;
	150					1	Y///	trace worm burrows.
62	150	S&H	C-2-4.0	4		]	1///	1
	150	<u> </u>						
				5		_		
	<u> </u>	ļ	<u> </u>	_		4	V//	
	ļ	ļ	<del>;</del>	6	<u> </u>	_	Y///	
		<del>                                     </del>		! _		4	1//	1
	<u> </u>	<del> </del>		7		4		
			<del> </del>			4		CLAYEY SAND (SC) - olive yellow (2.5YR 6/6), medium
<del></del>	250	1	·	8		┥	1//	dense, damp; 50% medium sand; 30% clay; 10% coarse
1274	250	S&H	C-2-9.0	9		-		sand; 10% silt.
16.7	250	0001	10-2-0.0	٦		1	1///	Survey, 70 70 Oils.
		<del> </del>	<u> </u>	10	_	1		
		<del> </del>		1		1	1///	
	- <del></del>	<del></del>		11		<b>_</b>	1//	
	1			•		7=	1/1/	
			1	12			11//	1
	1		· · · · · · · · · · · · · · · · · · ·			_		1
	<u> </u>	<u> </u>		13		_}		
		0.51	0011			_		01 AV (01) (0.5 VD (2)
7.9	9	I S&H	C-2-14.0	14		4	Y//	CLAY (CL) - gray (2.5 YR/4), stiff, damp, medium
	<del> </del>	<del> </del>	<del> </del>	45		-	Y///	plasticity; 70% clay; 25% silt; 5% diseminated caliche
	<u>:</u>	<del> </del>	1	15	-	4	1///	(white to gray color), small rootholes; dark staining along vertical soil pores or burrows.
	<del>                                     </del>		<del> </del>	16		-		Vertical soil pores of ourtows.
	+		<del> </del>	10	$\vdash$	-	1///	.)
<i>-</i>	<del>                                     </del>	+	<del> </del>	17		-	VI	CLAYEY SILT (ML/CL) - olive yellow (2.5Y 6/6), medium
	<del>†                                      </del>	<del> </del>	<del></del>			ာ်	111/	stiff, moist; 60% silt; 10% fine sand; 25% clay; 5% rock
	1	1	<del> </del>	18	-	-(		fragments; very small rootholes.
	<del> </del>			1		1		4
	<del>†</del>	1	Ī	19		Ϋ́		
N/A	7	S&H	C-2-19.5			٦ ·		
				20		1		
Remarks	5: *Conv	erted to	equivaler	nt Si	anc	lard Pe	netration	blow/ft.
E8 [38]	[EE]						Log of	Boring BORING N

GeoStrategies Inc.

JOB NUMBER 727801

REVIEWED BY RICCEG

MCC: CEG 1351

DATE 11/90

REVISED DATE

Field loca	ation of t	oring:					7.11		27801	Date: 11/12/90	Boring No:
		<b>'</b> 0	<b>51</b> -4	~						rvice Station No. 5630	C-2
		(S	ee Plate	2)				<u> </u>	97 Grant A		
								City: S		o, California Driller: Bayland	Sheet 2 of 2
								Casing installat		i Driller: Bayland	1 01 2
Ordling r	nathod:	Hollow S	Stom Aug	-				Casing installat	ion daw.		
Hole dia		8-inches		101				Top of Box Ele	vation:	Datum:	
	<del></del>	1	<u> </u>	<u></u>	Ī		୍ର	Water Level	······································		
a ê	Blows/ft.* or Pressure (psi)	2 8	ple	Depth (ft.)	Sample	76 FE	Soil Group Symbol (USCS)	Time			
O G	Se of se	Type of Semple	Sample	Эері	Ser	Weli Detail	5 pg	Date			
	. E		1 !				, , , , , , , , , , , , , , , , , , ,			Description	
		ļ	ļ					041/04/	3U T (MAL)	ali ia i all'air (0 m) (0(0)	1
	<u> </u>	<del> </del>	<u> </u>	21	<del>                                     </del>					olive yellow (2.5Y 6/6),	
	<del> </del>		· · · · · · · · · · · · · · · · · · ·	22						tlets, trace caliche; 40% I; 10% - 30% clay. Alter	
	<del> </del>	<del></del>	! 		$\vdash$					2 inches thick.	riate sariey
	}	<del></del>		23							
	<u> </u>	<del>                                     </del>									
50.3	7	S&H	C-2-24.0	24			1111				
	<u> </u>	ļ		25			-				
<del></del>	<del> </del>	<del>- </del> -	ļ <u>-</u>								
			<u> </u>	26	<u> </u>	ł			<u></u>		
	<del>}</del>	<del>-</del>	<u> </u>	27	<del> </del>	]					
			-							,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
		<del> </del>		28	-	<u> </u>		harder d	rılling at 27.	.5 ft.	
	İ			j		]	Y///				
1.5	9	S&H	C-2-29.0	29		]	Y///	CLAY (C	L) - olive ye	ellow (2.5Y 6/6), stiff, m	oist, trace
			ļ			1		disemen	ated caliche	e; 60% clay; 30% silt; 1	0% fine sand.
	ļ <u>.</u>	<del></del>	<del> </del>	30	<u> </u>	{	-	Pottom	of Boring at	20.5.4	
	<u> </u>	<del></del>	<del> </del>	31	<u> </u>	-		Bottom	of Boring at of Sample a	29.5 ft	
		<del></del>	<del></del>	1	-	1		11/12/90		1. 2.3.0 it.	
<del></del>	<del>}</del>	<del>- </del>	<del>\</del>	32	}	1					
	<del>                                     </del>	_				1					
	Ī		1	33		]					
				34							
	<u> </u>		<u> </u>	į	<u> </u>	-					
		1	1	35 	-	{		<del> </del> -	<del></del>		
<b> </b>	<del> </del>		<del> </del>	36	-	1					
<del> </del>	<del> </del>	<del></del>	<del> </del>	130		1		<del> -</del>			
		-	<del></del>	37		1		-			
-		<del>                                     </del>		1		1					
				] 38		]	1				
						]					
				39		1		_			
			<del></del>	٠. ا		-					
Domasi	1		1	140	!	1					·
Remark	<b>&gt;</b> .										
L								Boring			ACDING
1::3 3	311						L.OG 01	- DOTING			SORING N

GeoStrategies Inc.

JOB NUMBER 727801

REMEWED BY ROACEG MCC: CEG 1351

DATE 11/90

REVISED DATE

(See Plate 2)  ing method: Hollow Stem Auger a diameter: 8-Inches	Client: Chevron Service Station No. 5630  Location: 997 Grant Avenue  City: San Lorenzo, California  Logged by: KDM   Driller: Bayland   of 2  Casing installation data:
ing method: Hallow Stem Auger	City: San Lorenzo, California Sheet 1  Logged by: KDM Driller: Bayland of 2  Casing installation data:
ing method: Hallow Stem Auger	Logged by: KDM Driller: Bayland of 2  Casing installation data:
diameter: 8-inches	Casing installation data:
diameter: 8-inches	
diameter: 8-inches	Datum ACI
diameter: 3-Inches	Top of Box Elevation: 23.45 Datum: MSL
	11.75'
e e e e e e e e e e e e e e e e e e e	Time 15:40 16:00 15.55
Pressure of Type of Sample Number Oropin (ft)  Sample Sample Sample Sample Sample Sample Sample Sample Detail Detail it is a sample Sam	Date 11/12/90 11/13/90 12/5/90 Description
0	PAVEMENT SECTION 1.0 ft.
1	PAVEMENT SCOTION 1.0 II.
	SANDY CLAY (CL) - black (10YR 2/1), medium stiff,
2	damp, low to medium plasticity.
3	
4	(f)
150	
200 5	40.
78 200 S&H C-3-5.5	SANDY SILT (ML) - black (10YR 2/1), medium stiff,
78 200 0411 0 0 00	damp, low to medium plasticity; 70% silt; 20% sand; 10
	clay; discoloration from product.
7	
8	
	2 5YB
9	COLOR CHANGE to very dark grayish brown (2.5YR 3/2), damp, low plasticity; 70% silt; 25% sand; 5% clay
	3/2), damp, low plasticity, 70% slit, 25% sand, 5% oldy
10	
750 13 S&H C-3-10.5	
11	
<u> </u>	
12 =	y"/
	easy drilling at 12.5 ft.
13	Casy drining at 1215 in
14	(40VP 4/2) ctiff
	CLAY (CL) - dark grayish brown (10YR 4/2), stiff,
15	saturated, medium to high plasticity; rootholes; 75%
29 10 S&H C-3-15.5	clay; 15% silt; 10% sand;
16	//
	///
17	//}
18 💆	Water on rods at 18.0 ft.
19	
Remarks: * Converted to equivalent Standard Peneti	ration blow/ft.
Hellimys: * Councilied to edulation organization of outside	

GSI

GeoStrategies Inc.

**C-3** 

JOB NUMBER REVIEWED BY PIGCES DATE REVISED DATE REVISED DATE

727801 MCC: CE6 /35/

11/90

-1610 1008	ation of be	oring.							727801		11/12/90	T BOUND M
								Client:		ervice Station	No. 5630	- С-3
		(S	ee Plate	2)			Location:	997 Grant A			ŀ	
								City:		o, California		Sheet
								Logged by:		Driller:	Bayland	of 2
								Casing instal	lation data:			
		Hollow S	Stem Au	ger								
lole dia	meter:	8-inches	3					Top of Box E	levation:	<del>- , , ,</del>	Datum:	
_	8	Ī		-			2 (S)	V, ater Level				
ob (wood)	\$ 2	Type of Semple	Sample Number	Depth (ft.)	Semple	Well	So.	Time				
ድ ጅ	Blows/ft.* or Pressure (psi)	\$ <del>`</del> \$	S Z	8	ð	<b>≯</b> ∆	Soil Group Synibol (USCS)	Date		<u> </u>	<u> </u>	<u> </u>
	_ &					<u> </u>	ð.			Description		<del></del>
				1						o dark brown		
							V//			lay; 10% silt;	10% tine sa	and; open
6	6	S&H	C-3-20.5	20	<b></b>			burrow	s; rootholes.	<del></del>		
	ļ	ļ	<u> </u>	١	<b>}</b>		V///					
	ļ <u>.</u>			21	<b> </b>			1				
	<del></del>	<del></del>	<del> </del>	~	<b>  </b>		Y///	<del> </del> -				
·———	-		<del> </del>	22	ļ <u>-</u>			<del></del>			<del></del>	
	ļ	<del> </del>		23				Hardor	drilling at 23	2 5 4		
	<del> </del>	<u> </u>		23	<del> </del>			naiuei	uning at Z	), S II.		
	<del> </del>	<u> </u>	<del> </del>	24				<del> </del>				
	<del>                                     </del>	<del> </del>	C-3-	24			V///	COLO	CHANGE	to light olive t	10wn (2 5VI	D 5/A) at
2 5	9	S&H	25.5	25			Y///	<u> </u>	; damp.	to light olive t	2.511	7 3/4) at
3.5	9	San	25.5	25			Y///	24.0 11.	, uamp.			
	<del> </del>	<u> </u>	-	26				·				
				20	-			_ <del></del>				
	+			27	-		7//	1				
	<del> </del>	<del>                                     </del>	<del></del>	·	-			Bottom	of Boring a	27.0 ft.		
			<del> </del>	28		}	1		of Sample			
· <del></del>	<del>                                     </del>	<del>                                     </del>	<del> </del>	-				1/12/9			· · · · · · · · · · · · · · · · · · ·	'
	<del> </del>	<del> </del>	<del>                                     </del>	29			Į					
	<del> </del>	<u> </u>		7		1		1				
	T			30		1						
			1	-,		1						
		1	1	31		1						
	1		1	7		1	ļ				-	
	1			32		]						
				]								
				្ន 33		]						
						]						
				34		1						
				_		ļ						
	<del></del>	<u> </u>	<u> </u>	<u> </u>	<u></u>	1						
	<u> </u>	ļ	<u> </u>			4						
	<u> </u>	<u> </u>	<u> </u>	36		1						
		<del> </del>	<b></b>	1 .	<u></u>	Ţ			<del></del>			
	ļ	<u> </u>	<del> </del>	37	<u> </u>	1		<u></u>				
	<del> </del>	<b></b>	<del>-</del>	1	<u></u>	4	}					
	<u> </u>	<u> </u>		38		1						
	<u></u>	<u> </u>	1		1	<u> </u>		<u> </u>				
Remarks												

GeoStrategies Inc.

JOB NUMBER 727801

REVIEWED BY PROJECT MCL: CE6 1351

DATE 11/90

REVISED DATE

								City: Logged by:	San Lorenzo		Bayland	Sheet 1
								Casing installa		1	Daylaria	<u> </u>
illing n	nethod:	Hollow S	Stem Aug	ger								
ole dia	meter:	8-inches						Top of Box El			Datum: MS	
	ু জ			-	_		₽§	Water Level	19.0'	14.0	12.0'	11.85
ΣΕ <u>φ</u>	) es	Type of Sample	Sample	Depth (ft.)	Sample	Weif	9.50	Time Date	14:30	15:00 11/13/90	16:05 11/13/90	16:36 12/5/90
- &	Blows/ft.* or Pressure (ps/)	F. W	ು ಚಿಕ	8	ιħ		Soil Group Symbol (USCS)	Date	11/13/90	Description	1 11/13/30	1 123/50
	)	<u> </u>	1	$\overline{}$		]	\ <u> </u>		,			
				0								
	<u> </u>	<u> </u>				-		PAVEM	ENT SECTION	JN 1.0 ft.		
	<u> </u>	-	!	· <b>1</b>		]	door doors, 100	FILL - G	RAVELLY S	AND, dense	slightly dan	מר
				2		1						<u> </u>
						]	- 100 30 may 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
	ļ			3			***************************************		<del></del>			
	<u> </u>	<del> </del>	 	4		-		<b>}</b>	<del></del>			
	200	<del> </del>	1	7		1	Y///	SANDY	CLAY (CL)	- black (10YF	R 2/1), media	um stiff,
· · · · · ·	200			5		]				m plasticity;		
0	200	S&H	C-4-5.5	(			V//	sand.				·
		<u> </u>	<u> </u>	6		4	Y///	<del> </del>				
<del></del>		<del> </del> -		7		-{		1				····
	<u> </u>	<del></del>	<del>                                     </del>			1		<del>}</del>				
				8		]	1///					
						]						
	ļ	<u> </u>	ļ	9		4	V//	<del> </del>				
		<del> </del>	<u> </u>	10		4		<del> </del>				
1994	14	S&H	C-4-10.5			]		/		o olive brown		
	1		ì	111		]	Y//	` <b></b>		% silt; 25% s	sand; trace s	shell
	<u> </u>	ļ	<u> </u>	10		_		fragme	nts.			
<i>-</i>	<del> </del>	<u> </u>	<u>;                                    </u>	12		¥.		J		<del></del>		
<del></del>		<del> </del>	1	]   13	 	-	1//	<del> </del> -				
		<u> </u>				]						
				14		¥	1///	<del></del>		<del></del>		
	<u> </u>	<u> </u>	! <del> </del>	15	<b>-</b>	<b>│</b> <del>-</del>	Y//	十一,	CI) gravie	h brown (2.5)	V 4/2) modi	um etiff
0	8	S&H	C-4-15.5			┪				igh plasticity		
·	<del>                                     </del>	1 00.1	1 100	16		7		Sand 2	ray oxidatio	n staining alo	ong small ro	otholes ar
						]	Y///	L so sor				
		-		17		4		1_			<del></del>	<del>-</del>
	-		<del>                                     </del>	18	-	-	1//1					
	<del> </del>	+	-	10	L 	1		-				
	<del> </del>	<del> </del>		19	<u>                                     </u>							
emark	: * Con	verted to	equivale	nt S	tan	dard Pe	netration	blows/ft				
· · · · · · · · · · · · · · · · · · ·												·
		oStrate					Log of	Boring				BORII

JOB NUMBER 727801 REMEWED BY ROCEG

MCC: CE6 1351

DATE 11/90

REVISED CATE

Field localist of Soring.								72700		11/13/90	- Boring 140,			
									on Service Static	on No. 5630	- C-4 1			
		(S	ee Plate	2)				Location. 997 Grant Avenue						
								City: San Lo	orenzo, Californi		Sheet 2			
]								Logged by: KDM	Driller	Bayland	여 2			
								Casing installation dat	A:					
Drilling r	nethod:	Hollow S	Stem Au	ger										
Hole dia	neter:	8-inches						Top of Box Elevation:   Datum:						
— <del>—</del>		T		1			ଜ	Water Level		<del>-  </del>	<del>                                     </del>			
_	ف نے	₩ <u>₽</u>	<b>ē ē</b>	Depth (ft.)		_ =	\$ S	Time		<del></del>				
Opd)	\$ 5 g	Type of Sample	Semple	뒿	Semple	Weil	& £	Date		<del></del>	<del></del>			
٦	Blows/ft.* or Pressure (psi)	F-0	υž	යී	Ø	_	Soil Group Symbol (USCS)	Date	1	i	<u> </u>			
		<u> </u>	<u> </u>	ļ			0	5. 1.VEV.6.V.=	Descriptio					
		1						CLAYEY SILT	(ML) - light olive	brown (2.5YF	(5/4),			
			<u></u>	20				medium stiff, d	amp, medium pl	asticity; 60%	silt; 35%			
15.5	6	S&H	C-4-20.5					clay; 5% fine s	and.					
	!			21			1111							
		<u> </u>		]										
				22			] [ ] [ ]							
				[			$\{ \{ \} \} \}$							
				23							-			
			İ	24					,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		· · · · · · · · · · · · · · · · · · ·			
			<u> </u>	1						<del></del>				
		<u> </u>		25										
7.9	7	S&H	C-4-25.5											
	<u> </u>		, 20.0	26			1111	} <del></del>	<del></del> -					
	<u> </u>	<del> </del>	ļ	-										
			<del> </del>	27										
		<del>}</del>	}	4.1	}—-}			} <del></del>			<del></del>			
<u> </u>			<u> </u>	28			]   ]   [	<del></del>			<del></del>			
<del></del>	<u> </u>	<del> </del>		40			1   1				l			
		<del> </del> -	ļ	-	}					<del></del>				
<u> </u>		<del> </del>	1	29							<del></del>			
			l				1     1							
				30			] ] ] ] ]							
N/A	6	S&H	C-4-30.5											
ļ			<u> </u>	31	<b></b>			Bottom of Bori	ng at 30.5 ft.	······································				
<u> </u>	<u> </u>	<u> </u>	1	j			1	Bottom of San	ple at 30.5 ft.					
		<u> </u>		32				11/13/90						
	<u>.</u>			33			1				<del></del> -			
				]										
				34										
		1	]	1						<del></del>				
				35						····	-			
				j -					***		<del></del> -			
		<del> </del>	<del> </del>	36	<del>  </del>			<u> </u>			<del></del>			
				1				<del></del>						
<u> </u>		<del> </del>	ļ	37				ļ			<del></del> _			
	<u></u>		<del>}</del>	٠,	}}			<del></del>		······································	-			
		ļ	ļ	20	├┤			ļ <del></del>			-			
		<del> </del>	!	38			1	ļ			<del></del>			
<del></del>		1	<del> </del>	200	}}		)				<del></del>			
Comen		<u> </u>	<u> </u>	39	<u> </u>		1	L						
Remarks	i								•					
time in	*****						1	B =		<del></del>				



GeoStrategies Inc.

Log of Boring

JOB NUMBER 727801

REVIEWED BY RICCEG
MCC: CE6 /35/

DATE 11/90

REVISED DATE

# Drilling Log



# Monitoring Well C-5

						wner <u>Chevron U.S.A. Products Co.</u> . <u>02020 3451</u>	See Site Map For Boring Location					
Surface	Elev. 22.2	2 <i>7 ft.</i> To	otal Hole C	Depth 3	20.5	ft.         Diameter 8 in.           ft.         Static         02/16/93 15.37 ft.	COMMENTS:					
Screen:	Ola <u><i>2 in.</i></u> Ola <u><i>2 in.</i></u>	Le										
Filter Pa	ck Materia	<u>Lapis Lu</u>										
Driller Re	od Furlow			· <del></del>	L	og By Chip Hurley						
Checked	Checked By David Kleesattel License No. RG# 5136 Constant Checked By David Kleesattel License No. RG# 5136											
Depth (ft.)	Well Completion	PIO (ppm)	Sample ID Blow Count/ # Recovery	Graphic Log	Class.	Description (Cales Taylors S						
ے م	S E	L 5	N B B B B B B B B B B B B B B B B B B B	259	nscs	(Color, Texture, S Trace < 10%, Little 10% to 20%, Some	tructure) 20% to 35%, And 35% to 50%					
-2-												
} ~												
- 0						Asphalt over 6 inches of siltstone						
- 2 -												
<b>-</b>						,						
4 -			ا ا			Brown silty CLAY (maist, stiff, about 7	75% clay 25% eilt)					
- 6 -		8.6	10 7 6			Diomi sity of the most, still, cooter	on clay, zon siit,					
} -												
- 8 -	JI - I - I - I					Encountered groundwater at 9:30AM	02/02/93					
- 10 -		4.9	8		CL		,					
} -			6 7			Same as above (saturated)						
- 12 -												
14 -												
-		4.9	22 [			Same as at + urated)						
- 16 -		[	22 F 22 F 17									
- 18 -												
-												
- 20 -						- No recovery (saturated)						
} †			50			End of boring at 20.5 feet. Installed	groundwater monitoring well.					
- 22 -												
- 24 -												