HEALTH CARE SERVICES

AGENCY



DAVID J. KEARS, Agency Director

June 23, 1998 StID # 5495 ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION (LOP) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

REMEDIAL ACTION COMPLETION CERTIFICATION

Mr. Alex Gulyas Golden Gate Facility Sector 5125 Central Ave. Fremont CA 94536

Mr. Dale Klettke Port of Oakland 530 Water St. Oakland CA 94607

RE: FAA, Building M104, MOIA, Oakland 94621

Dear Mssrs. Gulyas and Klettke:

This letter confirms the completion of site investigation and remedial action for the one (1) approximately 1000 gallon diesel fuel underground tank removed from the above described location. Thank you for your cooperation throughout this investigation. Your willingness and promptness in responding to our inquiries concerning the former underground tank is greatly appreciated.

Based upon the available information and with provision that the information provided to this agency was accurate and representative of site conditions, no further action related to the underground tank releases is required.

This notice is issued pursuant to a regulation contained in Title 23, Division 3, Chapter 16, Section 2721 (e) of the California Code of Regulations.

Please contact Barney Chan at (510) 567-6765 if you have any questions regarding this matter.

Sincerely,

Mee Ling Tung

Director, Environmental Health

C: B. Chan, Hazardous Materials Division-files Chuck Headlee, RWQCB

Mr. Dave Deaner, SWRCB Cleanup Fund

Mr. Leroy Griffin, City of Oakland OES, 505 14th St., Suite 702, Oakland CA 94612

RACCMI.04

ALAMEDA COUNTY

HEALTH CARE SERVICES





DAVID J. KEARS, Agency Director

June 24, 1998 StID# 5495

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION (LOP) 1131 Harbor Bay Parkway, Suite 250

Mr. Alex Gulvas Golden Gate Facility Sector 5125 Central Ave. Fremont, CA 94536

Mr. Dale Klameda CA 94502-6577 Port of Oak (20) 337-9335 530 Water St. Oakland CA 94607

RE: Fuel Leak Site Case Closure- FAA, Building M104, MOIA Oakland CA 94621

Dear Mssrs. Gulyas and Klettke:

This letter transmits the enclosed underground storage tank (UST) case closure letter in accordance with the Health and Safety Code, Chapter 6.75 (Article 4, Section 25299.37 h). The State Water Resources Control Board adopted this letter on February 20, 1997. As of March 1, 1997, the Alameda County Health Services, Local Oversight Program (LOP) is required to use this case closure letter. We are also enclosing the case closure summary. These documents confirm the completion of the investigation and cleanup of the reported release at the subject site.

Site Investigation and Cleanup Summary:

Please be advised that the following conditions exist at the site:

* 169 parts per million (ppm) Total Petroleum Hydrocarbons as diesel (TPHd), remain in the soil at the site.

* 130 parts per billion (ppb) TPHd remain in groundwater at the

This site should be included in the City's permit tracking system. Please contact me at (510) 567-6765 if you have any questions.

Sincerely,

painer M

Barney M. Chan


Hazardous Materials Specialist

enclosures: Case Closure Letter, Case Closure Summary

c: Mr. L. Griffin, City of Oakland OES, 505 14th St., Suite 702, Oakland CA 94612

B. Chan, files (letter only)

JUN 1 6 1998



QUALITY CONTROL BOARD CASE CLOSURE SUMMERT 2: 40 Leaking Underground Fuel Storage Tank Program

AGENCY INFORMATION I.

Date: June 9, 1998

Agency name:

Ļ

Alameda County-HazMat Address: 1131 Harbor Bay Parkway

Rm 250, Alameda CA 94502

City/State/Zip: Alameda

Phone:

(510) 567-6700

Responsible staff person: Barney Chan

Title: Hazardous Materials Spec.

II. CASE INFORMATION

Site facility name: FAA, Building M104, MOIA

Site facility address: 51 John Glenn Drive, Oakland CA 94614

RB LUSTIS Case No: N/A

Local Case No./LOP Case No.: 5495

ULR filing date: 1/19/98

SWEEPS No: N/A

Responsible Parties:	Addresses:	Phone Numbers:
Golden Gate Facility Sector c/o Mr. Alex Gulyas	5125 Central Ave. Fremont, CA 94536	510-745-3473
Port of Oakland c/o Mr. Dale Klettke	530 Water St. Oakland CA 94607	510/272-1118

Tank No:	Size in gal.:	Contents:	<pre>Closed in-place or removed?:</pre>	<u>Date:</u>
1	1,000	diesel	Removed	1/8/98

RELEASE AND SITE CHARACTERIZATION INFORMATION III

Cause and type of release: possible leak in piping run

Site characterization complete? Yes

Date approved by oversight agency:

Number: used MW-9, 1 of the 9 Monitoring Wells installed? Yes wells installed by neighboring site (1 Airport Drive)

Proper screened interval? Yes, 3-13' bgs

Page 1 of 5

Leaking Underground Fuel Storage Program

Highest GW depth: 4.2' bgs Lowest depth: 5.5' bgs (from MW-9)

Flow direction: southwesterly

Most sensitive current use: site is located at the Metropolitan Oakland

International Airport

Are drinking water wells affected? No Aquifer name: NA

Is surface water affected? No Nearest affected SW name: NA

Off-site beneficial use impacts (addresses/locations): NA

Report(s) on file? Yes Where is report(s)? Alameda County
1131 Harbor Bay Parkway,

Room 250, Alameda CA 94502-6577

Treatment and Disposal of Affected Material:

<u>Material</u>	Amount (include units)		n (Treatment sal w/destination)	<u>Date</u>
Tanks & Piping	1-1,000 gallon	Disposed,	Erickson, Richmond	1/8/98
Sludge Soil	1- 55 gallon drum ~24 cubic yards	Disposed, Disposed,	Demeno Kerdoon Altamont Landfill	1/12/98 1/29/98

Maximum Documented Contaminant Concentrations - - Before and After Cleanup

Contaminant	Soil (ppm)	Water (ppb)
•	1Before After 2	3Before After4
TPH (Diesel)	160 160	2600 130
Benzene	ND ND	0.54 ND
Toluene	ND ND	2.3 ND
Ethylbenzene	ND ND	0.71 ND
Xvlenes	ND ND	4.6 ND

Comments (Depth of Remediation, etc.):

- 1 soil sample beneath piping run
- 2 no over-excavation performed
- 3 grab groundwater sample from tank pit
- 4 groundwater monitoring results, 2/14/97, MW-9

Leaking Underground Fuel Storage Tank Program

IV. CLOSURE

Does completed corrective action protect existing beneficial uses per the Regional Board Basin Plan? Undetermined

Does corrective action protect public health for current land use? YES

Site management requirements: site should be included in the City of Oakland Permit Tracking System.

Should corrective action be reviewed if land use changes? Yes

Monitoring wells Decommisioned: No

Number Decommissioned: 0, well belongs to neighboring site

Number Retained: N/A

List enforcement actions taken: none

List enforcement actions rescinded: NA

V. LOCAL AGENCY REPRESENTATIVE DATA

Name: Barney M. Chan Title: Hazardous Materials Specialist

Signature: Bawey M. Cham Date: 6/9/98

Reviewed by

Signature: 1 m. Date: 6-5-9

Name: Eva Chu Title: Hazardous Materials Specialist

Signature: Date: 4298

VI. RWQCB NOTIFICATION

Date Submitted to RB: RB Response:

RWQCB Staff Name: C. Headlee Title: EG Date: 6/15/28

Page 3 of 5

Leaking Underground Fuel Storage Tank Program

VII. ADDITIONAL COMMENTS, DATA, ETC.

The 1000 gallon underground diesel tank, owned by the FAA and used to fuel a generator at the south Air Traffic Control Tower (ATCT) was located just south of Building M104. This location is approximately 50' southwest and down gradient of the Hertz Rental Car facility, located at 1 Airport Drive. The address of the Port of Oakland's Building M104, 51 John Glenn Drive, is used for this site. See Figure 1 for the location of this site.

On January 8, 1998, in the presence of employees from the FAA, their contractor Kvaerner Aronson, the subcontractor, Army Corp of Engineers, the Port of Oakland, the City of Oakland Fire Services and Alameda County Environmental Health, the 1000 gallon diesel UST was removed. The Port of Oakland is the property owner and also maintains a 8000 gallon diesel tank approximately 20' north of this tank. See Figure 2 for a site plan indicating the tank, tank samples and neighboring site with wells.

Shoring was placed around the tank to prevent caving of the sidewalls. Groundwater, as anticipated, was encountered during the removal. The neighboring site, Hertz Rental, has an ongoing investigation and has installed nine monitoring wells. Groundwater gradient at that site is southwesterly and encountered at 3-5' bgs. Beneath the UST, at approximately 6' depth, was a concrete deadman. The UST had an approximately 30' piping run leading to the generator inside Building M104. Four soil sample were taken from the sidewalls at a depth of 6', just above groundwater. These samples were identified as Pit Wall N, Pit Wall S, Pit Wall E and Pit Wall W. These samples were sandy soil, typical of the native soils. A grab groundwater sample from the tank pit and a piping run sample, midway below the shallow piping run, were also taken.


All sidewall samples were ND for TPHd and BTEX. The piping run sample exhibited 160 ppm TPHd (characterized as aged diesel) and ND for BTEX. The groundwater sample exhibited 2.6 mg/l TPHd and 0.54,2.2,0.68 and 4.6 ppb BTEX, respectively. See Tables 1 and 2 for a summary of analytical results. It appears that the TPHd release from the piping run impacted groundwater. The TPHg release from the nearby Hertz site has likely impacted this site because BTEX was found in the grab groundwater sample. This is reasonable since there is a significant release near MW-4 on the Hertz site, which is up-gradient to this former tank pit. Enclosed are the recent groundwater monitoring results and gradient map for the Hertz facility. The historical monitoring of MW-9 for the Hertz site demonstrates that TPHd is not a significant problem in groundwater. The grab groundwater sample result is not representative of actual groundwater conditions.


Leaking Underground Fuel Storage Tank Program

This site is recommended for closure as a low risk soil and groundwater case. The following supports this decision:

- · The underground tank has been removed.
- · Soil contamination seems to have been confined to the piping run.
- Based upon long term monitoring, the levels of TPHd and BTEX are not of human health or environmental concern and the plume is not moving.
- The site has been adequately characterized.

Page 5 of 5





Sample ID	ВЕТХ	TPH as Diesel	Fuel Fingerprint	Fuel Fingerprint
Sample 1D	(ug/l)	(mg/l)	(% weight)	(mg/l)
Pit Water	B=0.54			
VOA I	T=2.2		NA I	NA
	E= 0.68	NA	NA	IVA.
	X=4.6			
Pit Water	·B=0.52	1		
VOA 2	T=2.3	214	NA	NA
	E=0.71	NA	IVA.	^ \^ ^
l	X=4.6			
Pit Water			<c10=nd< td=""><td><c10=nd< td=""></c10=nd<></td></c10=nd<>	<c10=nd< td=""></c10=nd<>
1 Liter			C10-C12=0.8	C10-C12=0.02
			C13-C15=10.7	C13-C15=0.28
,	NA	2.6	C16-C22=64.1	C16-C22=1.68
			C23-C32=22.2	C23-C32=0.58
			>C32=2.2	>C32=0.06
Detection				<c10=1.0< td=""></c10=1.0<>
Limit				C10-C12=0.05
2111110				C13-C15=0.05
	0.5	0.2	Not Applicable	C16-C22=0.2
				C23-C32=0.2
				>C32=0.2

ND = Not detected

NA = Not analyzed

Table 1
GROUNDWATER ELEVATIONS AND ANALYTICAL RESULTS

Hertz Service Center 1 Airport Drive Oakland, California

		•	_							•	
MW-No.	 Date	TOC DTW GWE	GWE	VE TPHg B	В	T	E	X	MTBE	TPHd	
MIAA-140.	Dute	(feet)	(feet)	(feet)	(ppb)	(ppb)	(ppb)	(ppb)	(ppb)	(ppb)	(ppb)
	- /- /00	7.77	2.62	4.03	ND	ND	ND	ND	ND		_
MW-3	2/3/93	7.66	3.63	4.03 3.84	ND	ND	ND	ND	ND		55
	5/27/93	7.66	3.82	3.60	ND	ND	ND	ND	ND		ND
	12/2/93	7.66	4.06		ND 		-	-		·	
	9/17/96	7.66	3.76	3.90	-					_	
	11/27/96	7.66	3.58	4.08			_		<u></u>		
	2/14/97	7.66	3.01	4.65				-		_	_
	12/3/97	7.66	3.31	4.35		_	_				
MW-4	2/18/92	7.11	3.68	3.43	6,600	910	1,900	280	1,700		ND
TAT A A*	5/13/92	7.11	3.54	3.57	62,000	3,400	5,200	990	5,200		_
	9/1/92	7.11	3.97	3.14	120,000	8,800	14,000	2,100	11,000	_	_
	11/5/92	7.11	5.23	1.88	24,000	2,600	3,300	510	2,100	_	
	2/3/93	7.11	4.22	2.89	50,000	4,7 00	5,000	1,500	6,600		***
	5/27/93	7.11	4.33	2.78	48,000	6,300	7,200	1,600	6,800	_	4,900
	12/2/93	7.11	4.72	2.39	21,000	3,500	3,800	640	2,000	_	770
	9/17/96	7.11	4.38	2.73	16,000	4,300	1,900	<i>7</i> 50	1,900	100	220
	11/27/96	7.11	4.20	2.91	14,000	5,100	2,600	1,300	2,500	ND<300	ND<20
	2/14/97 (b,c)	7.11	3.58	3.53	19,000	3,300	3,100	980	2,600	150	210
	12/3/97	7.11	3.92	3.19	6,400	1,500	0,640	520	0,890	160	_
	(= 100	7.7/	4.76	3.00	ND	ND	ND	ND	ND	_	170
MW-5	11/5/92	7.76			- ND	-	-	_	_		-
	2/3/93	7.76	200	3.88	ND	ND	ND	ND	ND		<i>7</i> 5
	5/27/93	7.76	3.88	3.40	ND	ND	ND	ND	ND		60
	12/2/93	7.76	4.36	3. 4 0 3.77	-	-	_		_		~-
	9/17/96	7.76	3.99	3.77 3.96				_		-	_
	11/27/96	7.76	3.80	<i>3.9</i> 0 4.60	100	1.2	ND<0.5	0.8	ND<2	95	860
	2/14/97 (b)	7.76	3.16		100 		-	-			_
	12/3/97	7.76	_	_							
MW-6	11/5/92	7.17	5.28	1.89	820	250	ND	5.9	ND		-
1,2,1	2/3/93	7.17	4.27	2.90	330	120	2.8	19	5.3	-	~
	5/27/93	7.17	4.35	2.82	1,300	370	ND	87	19	****	960
	12/2/93	7.17	4.81	2.36	280	11	1.0	65	3.0		700
	9/17/96	7.17	4.39	2.78	ND<50	1.0	0.5	ND<0.5	ND<2.0	ND<5	270


Page 2 of 4


Table 1
GROUNDWATER ELEVATIONS AND ANALYTICAL RESULTS

Hertz Service Center
1 Airport Drive
Oakland, California

				. · Oaklaild, Camorian				• • •			
MW-No.	Date	TOC (feet)	DTW (feet)	GWE (feet)	`TPHg (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)	TPHd (ppb)
MW-6	11/27/96 2/14/97 (b) 12/3/97	7.17 7.17 7.17	4.23 3.57 3.92	2.94 3.60 3.25	ND<50 50 ND<50	ND<0.5 0.9 0.6	ND<0.5 ND<0.5 ND<0.5	ND<0.5 ND<0.5 ND<0.5	ND<2.0 ND<2.0 ND<2.0	7 9 ND<5	ND<50 600
MW-7	5/27/93 12/2/93 9/17/96 11/27/96 2/14/97 (b) 12/3/97	6.93 6.93 6.93 6.93 6.93 6.93	4.58 4.78 4.52 4.35 3.70 4.04	2.35 2.15 2.41 2.58 3.23 2.89	ND ND - ND<50	ND ND - ND<0.5	ND ND - - ND<0.5 -	ND ND - - ND<0.5	ND ND - - ND√2 -	 ND<5	76 ND 140
MW-8	5/27/93 12/2/93 9/17/96 (a) 11/27/96 (a) 2/14/97 (a) Not Located	6.75 6.75 6.75 6.75 6.75	4.84 5.44 	1.91 1.31 	ND ND - - -	ND ND - - -	ND ND - - -	ND ND - - -	ND ND 	- - - -	91 54 - - 72
MW-9	5/27/93 12/2/93 9/17/96 11/27/96 2/14/97 (b) 12/3/97	6.55 6.55 6.55 6.55 6.55 6.55	4.97 5.53 4.95 4.16 4.40	1.58 1.02 1.60 2.39 2.15	ND ND . - - ND<50 ND<50	ND ND - - ND<0.5 ND<0.5	ND ND ND<0.5 ND<0.5	ND ND ND<0.5 ND<0.5	ND ND - ND<2 ND<2	- - - - ND<5 ND<5	72 130

Notes: TOC DTW GWE TPHg TPHd BTEX MTBE	Elevation at the north side of the top of the well casing referenced to mean sea level (wells were surveyed by others) Depth to water Groundwater elevation Total petroleum hydrocarbons as gasoline using EPA Method 8015 (modified) Total petroleum hydrocarbons as diesel fuel using EPA Method 8015 (modified) Benzene, toluene, ethylbenzene and total xylenes using EPA Method 8020 (modified) Methyl tert butyl ether using EPA Method 8020 (modified)
ppb	Parts per billion (micrograms per liter)





3.0 DATA PRESENTATION

3.1 SOIL SAMPLES

The soil samples were submitted to Advanced Technology Laboratories for analysis by EPA Test Method 8015 Modified for diesel and by EPA Test Method 8020 for benzene, toluene, ethylbenzene, and xylenes (BTEX). Selected samples were analyzed for a fuel fingerprint in the carbon range C6 through C36. The analytical results are summarized below in Table 1.

Table 1 - Analytical Results
Soil Samples

Sample ID	BETX (ug/kg)	TPH as Diesel (mg/kg)	Fuel Fingerprint (mg/kg)
Pit Wall N	ND	ND	ND
Pit Wall S	ND	ND	ND
Pit Wall E	ND	ND	ND
Pit Wall W	ND	ND	ND
Pipe Run	ND	160*	. NA
Roll Off Composite	ND	ND	NA
Detection Limit	5	10	<c10-c15=1.0 C16->C32=10</c10-c15=1.0

ND = Not detected NA = Not analyzed

^{*}Sample contains hydrocarbons heavier than diesel