## ALAMEDA COUNTY HEALTH CARE SERVICES

AGENCY



ALEX BRISCOE, Director

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

February 27, 2013

Mr. Peter Puckett Berkeley Farms P.O. Box 4616 Hayward, CA 94540-4616

Ms. Karen Bellini Harmon Management Co. 199 First Street, Suite 212 Los Altos, CA 94022

Subject: Case Closure for Fuel Leak Case No. RO0002452 and GeoTracker Global ID T0600190380. Berkeley Farms Truck Repair Southern Site, 4501 San Pablo Avenue, Emeryville, CA 94608

#### Dear Responsible Parties:

This letter transmits the enclosed underground storage tank (UST) case closure letter in accordance with Chapter 6.75 (Article 4, Section 25299.37[h]). The State Water Resources Control Board adopted this letter on February 20, 1997. As of March 1, 1997, the Alameda County Environmental Health (ACEH) is required to use this case closure letter for all UST leak sites. We are also transmitting to you the enclosed case closure summary. These documents confirm the completion of the investigation and cleanup of the reported release at the subject site. The subject fuel leak case is closed. This case closure letter and the case closure summary can also be viewed on the State Water Resources Control Board's Geotracker website (http://geotracker.swrcb.ca.gov) and the Alameda County Environmental Health website (http://www.acgov.org/aceh/index.htm).

#### SITE INVESTIGATION AND CLEANUP SUMMARY

Please be advised that the following conditions exist at the site:

- Total petroleum hydrocarbons as gasoline remains in soil at concentrations up to 980 ppm.
- Benzene remains in soil at concentrations up to 13 ppm.
- As described in section IV of the attached Case Closure Summary, the case was closed with Site Management Requirements that limit future land use to commercial land use only.

If you have any questions, please call Jerry Wickham at (510) 567-6791. Thank you.

Sincerely.

Donna L. Drogos, Division Chief

**Division Chief** 

#### Enclosures:

- 1. Remedial Action Completion Certification
- 2. Case Closure Summary

CC:

Markus Niebanck
Emeryville Redevelopment Agency
1333 Park Ave.
Emeryville, CA 94608 (Sent via electronic mail to mniebanck@ci.emeryville.ca.us)

Andrew Lojo
Antea Group
1350 Treat Blvd., Suite 250
Walnut Creek, CA 94597 (Sent via E-mail to:
Andy.Lojo@anteagroup.com)

Nicole Persaud
Antea Group
1350 Treat Blvd., Suite 250
Walnut Creek, CA 94597 (Sent via E-mail to:
Nicole.Persaud@anteagroup.com)

Closure Unit State Water Resources Control Board UST Cleanup Fund P.O. Box 944212 Sacramento, CA 94244-2120 (uploaded to GeoTracker)

Norman Stone
Dean Foods
1415 E. 5050 S
Ogden, UT 88403 (Sent via electronic mail to
Norm Stone@deanfoods.com

Donna Drogos, ACEH (Sent via E-mail to: <a href="mailto:donna.drogos@acgov.org">donna.drogos@acgov.org</a>)
Jerry Wickham, ACEH (Sent via E-mail to: <a href="mailto:jerry.wickham@acgov.org">jerry.wickham@acgov.org</a>)

GeoTracker (w/enc) eFile (w/orig enc)

# ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY

ALEX BRISCOE, Director



DEPARTMENT OF ENVIRONMENTAL HEALTH
OFFICE OF THE DIRECTOR
1131 HARBOR BAY PARKWAY
ALAMEDA, CA 94502
(510) 567-6777
FAX (510) 337-9135

#### REMEDIAL ACTION COMPLETION CERTIFICATION

February 27, 2013

Mr. Peter Puckett Berkeley Farms P.O. Box 4616 Hayward, CA 94540-4616

Ms. Karen Bellini Harmon Management Co. 199 First Street, Suite 212 Los Altos, CA 94022

Subject: Case Closure for Fuel Leak Case No. RO0002452 and GeoTracker Global ID T0600190380, Berkeley Farms Truck Repair Southern Site, 4501 San Pablo Avenue, Emeryville, CA 94608

#### Dear Responsible Parties:

This letter confirms the completion of a site investigation and remedial action for the underground storage tanks formerly located at the above-described location. Thank you for your cooperation throughout this investigation. Your willingness and promptness in responding to our inquiries concerning the former underground storage tank(s) are greatly appreciated.

Based on information in the above-referenced file and with the provision that the information provided to this agency was accurate and representative of site conditions, this agency finds that the site investigation and corrective action carried out at your underground storage tank(s) site is in compliance with the requirements of subdivisions (a) and (b) of Section 25299.37 of the Health and Safety Code and with corrective action regulations adopted pursuant to Section 25299.77 of the Health and Safety Code and that no further action related to the petroleum release(s) at the site is required.

Claims for reimbursement of corrective action costs submitted to the Underground Storage Tank Cleanup Fund more than 365 days after the date of this letter or issuance or activation of the Fund's Letter of Commitment, whichever occurs later, will not be reimbursed unless one of the following exceptions applies:

- · Claims are submitted pursuant to Section 25299.57, subdivision (k) (reopened UST case); or
- Submission within the timeframe was beyond the claimant's reasonable control, ongoing work is
  required for closure that will result in the submission of claims beyond that time period, or that under the
  circumstances of the case, it would be unreasonable or inequitable to impose the 365-day time period.

This notice is issued pursuant to subdivision (h) of Section 25299.37 of the Health and Safety Code. Please contact our office if you have any questions regarding this matter.

Sincerely:

Ariu Levi Director

# CASE CLOSURE SUMMARY LEAKING UNDERGROUND FUEL STORAGE TANK - LOCAL OVERSIGHT PROGRAM

#### I. AGENCY INFORMATION

Agency Name: Alameda County Environmental Health	Address: 1131 Harbor Bay Parkway
City/State/Zip: Alameda, CA 94502-6577	Phone: (510) 567-6791
Responsible Staff Person: Jerry Wickham	Title: Hazardous Materials Specialist

#### II. CASE INFORMATION

Site Facility Name: Berkeley Farn	ns Truck Repair Southern Site		
Site Facility Address: 4501 San P	ablo Avenue, Emeryville, CA 94608		
RB Case No.: 01-3548	Local Case No.:	LOP	Case No.: RO0002452
URF Filing Date: 11/24/1997	SWEEPS No.: APN: 049-1178-4		
Responsible Parties	Addresses		Phone Numbers
Peter Puckett Berkeley Farms	P.O. Box 4616, Hayward, CA 94540-46	510-265-8600	
Karen Bellini	199 First Street, Suite 212, Los Altos CA		
Harmon Management Co.	94022		

Tank I.D. No	Size in Gallons	Contents	Closed In Place/Removed?	Date	
1-3	Unknown	Petroleum Fuel	Reported Removed	Reported removed approximately 1985	
			The state of the s		
	Piping		Reported Removed	Unknown	

#### **III. RELEASE AND SITE CHARACTERIZATION INFORMATION**

Cause and Type of Release: Unknown, report	s on U	ST removal not submit	red			
Site characterization complete? Yes Date Approved By Oversight Agency:						
Monitoring wells installed? Yes		Number: 1	Proper screened interval?			
Highest GW Depth Below Ground Surface: 4 feet Lowest Depth: 11 feet Flow Direction: West						
Most Sensitive Current Use: Potential Drinking water source.						

Date: September 14, 2006

Summary of Production Wells in Vicinity: B Avenue, no water supply wells are within ½ n	ased on well survey information from adjacent site at 4343 San Pablo nile of the site.				
Are drinking water wells affected? No	Aquifer Name: East Bay Plain				
Is surface water affected? No Nearest SW Name: San Francisco Bay 3,200 feet to west					
Off-Site Beneficial Use Impacts (Addresses/L	Locations): None				
Reports on file? Yes	Where are reports filed? Alameda County Environmental Health and City of Oakland Fire Department				

	TREATMENT	AND DISPOSAL OF AFFECTED MATERIAL	
Material	Amount (Include Units)	Action (Treatment or Disposal w/Destination)	Date
Tank	Three USTs	Not reported	Reported approximately 1985
Piping	Not reported	Not reported	Not reported
Free Product	Not reported		
Soil	1,102 tons	Transported to Allied Waste Landfill in Manteca, CA for disposal	04/1998 to 12/1998
Groundwater	15,000 gallons	Transported to Seaport Environmental, Inc. in Redwood City, CA for disposal	04/1998

# MAXIMUM DOCUMENTED CONTAMINANT CONCENTRATIONS BEFORE AND AFTER CLEANUP (Please see Attachments 1 through 6 for additional information on contaminant locations and concentrations)

Contaminant	Soil (	(ppm)	Water (ppb)		
Contaminant	Before	After	Before	After	
TPH (Gas)	5,300	980	38,000(1)	61(1)	
TPH (Diesel)	3,900	320	105,000(2)	85(2)	
Oil and Grease	NA	NA .	NA	NA	
Benzene	33	13	2,300	980	
Toluene	200	30	3,000	9.5	
Ethylbenzene	110	18	3,600	640	
Xylenes	600	77	3,100	1,200	
Heavy Metals	140	13	<5(3)	<5(3)	
MTBE	21(4)	21(4)	320(5)	320(5)	
Other (8240/8270)	NA	NA	<0.03(6)	<0.03(6)	

- (1) The maximum concentration before cleanup of 38,000 ppb of TPHg was detected in groundwater from well MW1 during the August 21, 1998 sampling event immediately following overexcavation of the former tank pit. The maximum concentration of 61 ppb after cleanup is from the most recent groundwater sampling event on September 7, 2002.
- (2) The maximum concentration before cleanup of 105,000 ppb of TPHd was detected in groundwater from well MW1 during the June 2, 1998 sampling event, which occurred immediately after overexcavation but prior to backfilling of the former tank pit. The maximum concentration of 85 ppb after cleanup is from the most recent groundwater sampling event on September 7, 2002.
- (3) Total lead; cadmium, chromium, lead, nickel and zinc were not detected or within the range of ambient concentrations.
- (4) Maximum MTBE concentration in soil was detected using EPA Method 8020 and was not confirmed by EPA Method 8260. No other fuel oxygenates analyzed. 1,2-dichloroethane was <0.03 ppb.</p>
- (5) Maximum MTBE concentration in soil was detected using EPA Method 8020 and was not confirmed by EPA Method 8260. No other fuel oxygenates analyzed; 1,2-dichloroethane was <0.03 ppb.
- (6) 1,2-dichloroethane; no other VOCs detected in groundwater.

Site History and Description of Corrective Actions:

The site is located at 4501 San Pablo Avenue in Emeryville and is currently the site of a Kentucky Fried Chicken restaurant. The site operated as a truck repair shop and yard for the Berkeley dairy facility until approximately 1998. The property directly north of this site, which has an address of 4575 San Pablo Avenue, was also part of the former Berkeley Farms truck repair shop, but the property was subdivided into a separate fuel leak case (RO245) in 2002 since the sources of contamination, site history, and ownership were different for the northern and southern portions of the property. A service station is reported to have operated at the site from approximately 1966 through 1979 after which the site was used as an auto repair facility until 1985. An AC Transit maintenance yard is west (downgradient) of the site (fuel leak case RO

The former service station was demolished in approximately 1985 and three former fuel underground storage tanks (USTs) were reportedly removed from the site. No tank closure report or analytical data are available from the tank removal. Three soil borings were advanced at the site in during an October 1997 soil and groundwater investigation to investigate the former fuel tanks and dispensers. Boring SB2 was located in the former fuel tank pit and boring SB3 was located adjacent to the former dispensers. A third boring, boring SB1, was located near the eastern edge of the former tank pit. Total petroleum hydrocarbons as gasoline (TPHg) were detected in soil from each of the borings at maximum concentrations of 140 ppm (SB1), 25 ppm (SB2), and 210 ppm (SB3). TPHg were detected in grab groundwater samples from the three borings at concentrations of 5,300 ppb (SB1), 48,000 ppb (SB2), and 9,900 ppb (SB3).

On February 20, 1998 one monitoring well was installed at the site. An additional two monitoring wells were installed on the property to the north (fuel leak case RO245). Quarterly monitoring was conducted at the sites from February 1998 to September 2002.

Due to the elevated concentrations of fuel hydrocarbons detected in the borings and monitoring wells, the former fuel tank pit was re-excavated between April 30, 1998 and June 1, 1998. Based on the observations of piping and debris in the tank pit, it appeared that some or all of the tankpit backfill material had been replaced in the tank pit following tank removal. Three phases of overexcavation and confirmation sampling were conducted to remove petroleum-hydrocarbon impacted soil. A total of approximately 400 cubic yards of soil and 15,000 gallons of water were removed. Confirmation samples collected from the sidewalls and bottom of the excavation contained relatively low concentrations of TPH as diesel (60 ppm) and no detectable concentrations of TPH as gasoline and BTEX.

In order to delineate the downgradient plume, soil and groundwater samples were collected from three soil borings (B-4 through B-6) that were advanced downgradient of the former tank pit on the AC Transit site to the west. One soil sample and one grab groundwater sample was collected from each boring. TPH as gasoline, TPH as motor oil, BTEX, and MTBE were not detected in the soil and groundwater samples from all borings. TPH as diesel was detected in groundwater from boring B-5 at a concentration of 66 ppb but was not detected in soil or groundwater from the other borings. These data indicated the extent of the hydrocarbon plume from the site was generally limited to the site.

During construction of the foundation for the Kentucky Fried Chicken restaurant in December 1998, additional hydrocarbon-impacted soils were encountered in the area of a pump island and product piping. An area beneath the building footprint approximately 45 feet wide by 90 feet long was excavated to a depth of approximately 3.75 feet. A total of 703 tons of soil was excavated and disposed offsite at the Allied Waste Landfill in Manteca.

Based on the results of a risk assessment (Waterstone Environmental 1999), a vapor barrier consisting of a 20 mil thick layer of Paraseal GM liner material was laid down at approximately 42 inches below grade over the excavated area. This area included the building footprint and additional areas north of the building. The vapor barrier overlaps were sealed and layers of 10 mil visqueen were laid over the Paraseal. Vapor collection piping was reportedly installed along the inside of the foundation walls and then routed inside the wall and outside to the rooftop.

Well MW1, which was damaged during construction, was decommissioned and replacement well MW-1A was installed on July 30, 1999. On September 7, 2002, five soil vapor samples were collected above the vapor barrier (approximately two feet below grade) at various points on the perimeter of the restaurant building. TPHg and BTEX were not detected in the five vapor samples. Well MW1 and replacement well MW1A were sampled quarterly from February 1998 to December 2001 in conjunction with sampling the two monitoring wells on the parcel to the north. Fuel hydrocarbon concentrations in groundwater have generally attenuated following the overexcavation of the tank pit and soil removal in the area of the fast food restaurant. During the last groundwater monitoring event conducted at the site, TPHg was detected at 61 ppb, TPHd was detected at 85 ppb, and benzene was detected at 0.72 ppb.

#### IV. CLOSURE

Does completed corrective action protect existing beneficial uses per the Regional Board Basin Plan? (Yes) No.

Does completed corrective action protect potential beneficial uses per the Regional Board Basin Plan? (Yes) No

Does corrective action protect public health for current land use? Alameda County Environmental Health staff does not make specific determinations concerning public health risk. However, based upon the information available in our files to date, it does not appear that the release would present a risk to human health based upon current land use and conditions.

Site Management Requirements: Case closure for the fuel leak site is granted for commercial land use only. If a change in land use to residential or other conservative scenario occurs at this property, Alameda County Environmental Health must be notified and the case needs to be re-evaluated. These site management requirements are to be entered into the City of Emeryville's OSIRIS (One Stop Interactive Resource Information System) Map Server due to the residual contamination posing a nuisance for subsurface utility work.

Should corrective action be reviewed if land use changes? Yes

Was a deed restriction or deed notification filed? No

Date Recorded: --

Monitoring Wells Decommissioned: No

Number Decommissioned: 0

Number Retained: 1

List Enforcement Actions Taken: None

List Enforcement Actions Rescinded: --

#### V. ADDITIONAL COMMENTS, DATA, ETC.

Considerations and/or Variances:

Tank removal activities for the former fuel USTs were not documented. Soils in the area of the former tank pit were re-excavated and disposed off-site between April 30, 1998 and June 1, 1998. In addition, approximately 702 tons of soil were excavated and removed from the footprint of a fast food restaurant constructed on the site. MTBE was detected in the on-site well at a maximum concentration of 320 ppb in groundwater. However, the MTBE detection resulted from EPA Method 8020 analysis and was not confirmed by EPA Method 8260. If MTBE is present, it is likely from an off-site upgradient source.

#### Conclusion:

Alameda County Environmental Health staff believe that the levels of residual contamination do not pose a significant threat to water resources, public health and safety, and the environment under the current land use based upon the information available in our files to date. No further investigation or cleanup is necessary. ACEH staff recommend case closure for this site.

#### VI. LOCAL AGENCY REPRESENTATIVE DATA

Prepared by: Jerry Wickham	Title: Hazardous Materials Specialist
Signature: William	Date: 05/10/06
Approved by: Donna L. Drogos, P.E.	Title: Supervising Hazardous Materials Specialist
Signature:	Date: 05/10/06

This closure approval is based upon the available information and with the provision that the information provided to this agency was accurate and representative of site conditions.

#### VII. REGIONAL BOARD NOTIFICATION

Regional Board Staff Name: Cherte McCaulou	Title: Engineering Geologist			
RB Response: Concur, based sofely upon information contained in this case closure summary.	Date Submitted to RB:			
Signature: Mui McCanlon	Date: 9 8 06			

#### VIII, MONITORING WELL DECOMMISSIONING

Date Requested by ACEH; 64/14/66	Date of Well Decommissioning Report: 02/05/13				
All Monitoring Wells Decommissioned Ves No	Number Decommissioned: 1	Number Retained: 🂢			
Reason Wells Retained:					
Additional requirements for submittal of groundwa	iter data from retained wells: N	` '			
ACEH Concurrence - Signature:	Wieldram	Date; 02/27/13			
		3.0.0			

#### Attachments:


Site Vicinity Map

Potentiometric Surface Map -- September 8, 1999


- 2. Site Plan – January 23, 1998; Site Plan – June 3, 1998; Sampling Locations Map; Locations of Sampling and Soil Excavation Areas; Site Plan Showing Soil Vapor Sample Points; Petroleum Hydrocarbons in Groundwater – October 30, 1998; Petroleum Hydrocarbons in Groundwater – September 9, 1999,
- Soil and Soil Vapor Analytical Data
- Groundwater Analytical Data
- Boring Logs 6.


This document and the related CASE CLOSURE LETTER & REMEDIAL ACTION COMPLETION CERTIFICATE shall be retained by the lead agency as part of the official site file.


Site Location and Hospital Route Map
Berkeley Farms Truck Repair Shop & Yard, 4575 San Pablo Avenue, Emeryville, CA





Copyright © 1988-1987, Microsoft Corporation and/or its suppliers. All rights reserved. Please visit our even ples at impulmaps expedia, com.
















Waterstone Environmental, LLC 2712 Rawson Street Oakland, CA 94619 (510) 533-6710 FIGURE 1
LOCATIONS OF SAMPLING AND
SOIL EXCAVATION AREAS
FORMER BERKELEY FARMS TRUCK
PARKING AND REPAIR FACILITY
EMERYVILLE, CALIFORNIA





Petroleum Hydrocarbons in Groundwater

Geo-Logic Report dates



GE0-LOGIC GL-97-110.R4 June 9, 1998

TABLE 1
SUMMARY OF LABORATORY ANALYSES
SOIL

Sample/depth	TPH as <u>Diesel</u>	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	Ethyl- <u>benzene</u>	<u>Xylenes</u>
	(Collecte	d on April	30, 1998	).		
KS (8.5')	NA	<0.1	5.0	4.1	5.8	90
	(Collecte	d on May 8	, 1998)			•
KN (7.5')	<0.1	<0.1	<0.005	<0.005	<0.005	<0.005
KS (7, 5 )	<0.1	<0.1	<0.005	<0.005	<0.005	<0.005
KE (7.5')	<0.1	<0.1	<0.005	<0.005	<0.005	<0.005
KW (7.5')	<0.1	<0.1	<0.005	<0.005	<0.005	<0.005
KB1 (7.5')	3,900	<0.1	<0.005	30	<0.005	<0.005
	(Collected	d on May 1	5, 1998)			
KE2 (7.0')	60	<0.1	<0.005	<0.005	<0.005	<0.005
Method Blank/ Detection Limit	<0.1	<0.1	<0.005	<0.005	<0.005	<0.005

Results are in milligrams per kilogram (mg/kg).

Georlagic report dated 6-9-98

GEO-LOGIC GL-97-110.R3 March 7, 1998

TABLE 3
SUMMARY OF LABORATORY ANALYSES
SOIL

*,	•					•	
<u>Date</u>	Sample No./Depth	TPH as <u>Diesel</u>	TPH as <u>Gasoline</u>	<u>Benzene</u>	Toluene	Ethyl- benzene	<u>Xylenes</u>
2/20/98	MW1 (4.5' MW1 (7.5' MW2 (4.5' MW2 (7.5' MW3 (6.0' MW3 (8.0'	<pre>(0.1) &lt; 0.1 (0.1) &lt; 0.1 (</pre>	160 2,800  20 11	<0.005 8.0  <0.005 <0.005	<0.005 9.0  <0.005 <0.005	<0.005 37  <0.005 <0.005	6.3 220  <0.005 <0.005
Detectio	n Limit	0.1	0.1	0.005	0.005	0.005	0.005
<u>Date</u>	Sample No./Depth	TRP	H MTBI	<b>3</b>			
2/20/98	MW1 (4.5' MW1 (7.5' MW2 (4.5' MW2 (7.5' MW3 (6.0' MW3 (8.0'	) ) 26 ) 17 )		)5			

<sup>--</sup> analyses not performed.

Detection Limit

Results are in milligrams per kilogram (mg/kg), unless otherwise indicated.

0.005

5.0

Geologic Report dates 3.7-98

Geo-Logic GL-97-110.R6 October 30, 1998

### TABLE 1

# SUMMARY OF LABORATORY ANALYSES SOIL

(Samples collected on October 8, 1998)

Sample No./Depth	TPH as <u>Diesel</u>	TPH <u>Gas</u>	<u>Benzene</u>	<u>Toluene</u>	Ethyl- <u>benzene</u>	Xylenes	MTBE	TPH as <u>Motor Oil</u>	
B1 (5.5')	<0.1	<0.1	<0.005	<0.005	<0.005	<0.005	<0.1	<0.1	
B2 (9†)	<0.1	<0.1	<0.005	<0.005	<0.005	<0.005	<0.1	<0.1	
B3 (10.5')	<0.1	<0.1	<0.005	<0.005	<0.005	<0.005	<0.1	<0.1	
B4 (10.51)	<0.1	<0.1	<0.005	<0.005	<0.005	<0.005	<0.1	<b></b>	
B5 (5.5 <sup>1</sup> )	<0.1	<0.1	<0.005	<0.005	<0.005	<0.005	<0.1	·	
B5 (10.5')	<0.1	<0.1	<0.005	<0.005	<0.005	<0.005	<0.1		
B6 (10.5!)	<0.1	<0.1	<0.005	<0.005	<0.005	<0.005	<0.1		
Det. Limit		<0.1	<0.005	<0.005	<0.005	<0.005	<0.1	<0.1	
Method Bla	ınk							•	

-- analyses not performed.

Results are in milligrams per kilogram (mg/kg), unless otherwise indicated.

Geologic Report dated

TABLE 3
SUMMARY OF LABORATORY ANALYSES - SOIL

(Collected on July 30, 1999)

Sample No./Depth	TPH as <u>Diesel</u>	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	Ethyl- benzene	Xylenes	MTBE.
MW1A (4.5'	) 53	2.7	0.019	<0.005	0.046	0.041	<0.005
MW1A (9.5'	) 570	.35	0.23	0.14	0.29	0.38	<0.005
Comp S1*	2.7	160	0.020	<0.005	0.039	0.027	<0.005
Det. Limit	0.10	0.10	0.005	0.005	0.005	0.005	<0.005

<sup>\*</sup> Total Lead was detected at a concentration of 33 ppm. Results are in parts per million (ppm).

TABLE 1: SOIL SAMPLE RESULTS - SITE INVESTIGATION Berkaley Farms Truck Maintenance Facility 4575 San Pablo Avenue Emeryville, California

Sample Location	Sample Depth (Feet)	TPH-g. mg/Kg	TPH-d mg/Kg	TPH-mo mg/Kg	VOC mg/Kg	Antifreeze mg/Kg	Metals mg/Kg
. Pagillaria		1000 E	fund frage			3.0.35	T MOVING
SB1	2.5	21	ND	10.0	I	F	Ţ~
743 BF	7.5	140	7 <u>4</u> 7 5 1	1			
	13.5	0.2	27 27	***	-	_	***************************************
SB2	25	ND	La lating		-		-75
	6.0	0.6	- <del>-</del>		3. 1. 1. A. A.	4 <sup>th</sup> = 2	
A COL	13.0	25.0	and the same of	40 Y 21 199		Part Contra	-
SB3	1.0	11.0		; <del>,</del>	7	_	-
	4.5	17	•	_	-		
	12.5	210	_	-	-12		-
SB4	1.5	ND	ND	8.0	ND	ND	
	8.0	ND	ND	ND	ND	ND	
	12.5	ND.	ИD	ND.	ND	ND	
SB5	4.0	ND	ND	34(0	ЙĎ	ND	
	8.5	ND	ND	24.0	ND ·	ND	-
	14.0	1.2	5.0	ND	ND	ND	_
SB6	2.0	ND	5.0	8		ND	
	7.0	ИD	ND	ND		ND	
	13.0	ND	ND	ND	•	ND	-
SB7	4.0	210	8,200	25,000	ND	in the	-
	ু 7.0	340	1,600	9,400	11(1 2 DCB	)	
- 1,	(1,0	13	690	2,400	QZ.	-	-
SB8	2,0		1300.0	2000.0		-	
	10.5	-	МD	85,0	-	•	-
	15.0	7	ДN	ND	_		7 7 7 m
SBO	4.9			-			*As 5/ Be 0.
<b>"我就要说。"</b>	<b>5.</b> 0		••(	3	-		7/s 5/ Be 0

NOTÉS:

TPH-g

Total Petroleum Hydrocarbons as gasoline mg/Kg micrograms per kilogram (ppm)
Total Petroleum Hydrocarbons as diesel
Total Petroleum Hydrocarbons as motor oil
Volatile Organic Compounds

\* Metals above Residential PRGs not TPH-d TPH mo

VOC:

\* Metals above Residential PRGs not listed

Not Detected (above Method reporting lim 1.2-Dichlorobenzene NA Not Analyzed

# TABLE 1 SOIL SAMPLING RESULTS (mg/kg)

Pre-Foundation Excavation Former Berkeley Farms Property 4575 San Pablo Ave., Emeryville

SAMPLE .	DEPTH	TPH/G	TPH/D	BENZENE	TOLUENE	ETHYL	XYLENES	MTBE	LEAD
ID NO	(bgs)					BENZENE			
SW-1-2 <sup>1</sup>	2	5300	1400	33	200	110	600	<5	15
SW-7-5	<sup>7</sup> 5	490	320	3.8	3.2	4.6	12	<3	9.5
NE-2-3 <sup>1</sup>	3	6.3	ND	0.99	0.1	0.12	0.21	ND	8.7
MW-3-2 <sup>1</sup>	2	360	55	10	22	6.7	32	5.7	12
MW-5-5	5	800	190	13	30	16	66	21	8.6
MW-6-9	9	540	110	6.3	16	11	47	<7	7.1
Mid-4-3 <sup>1</sup>	3	560	300	5.9	14	7.9	37	<4	140
Mid-10-5	5	980	250	13	27	18	77	<10	13
g-L²	4-pt Profile	13	170	0.41	0.19	0.6	0.63	NA	41

<sup>1-</sup> Soils removed and disposed of at Forward Landfill

NA Not Analyzed

<sup>2-</sup> Profile sample collected by geo-Logic and delivered to Calcoast Analytical

# TABLE 3 SOIL VAPOR ANALYTICAL RESULTS

#### Former Berkeley Farms Truck Shop 4575 San Pablo Avenue, Emeryville, CA

(samples collected 9/7/02)

Sample/ Depth (feet)	TPH-g (ppb)	Benzene (ppb)	Ethylbenzene (ppb)	Toluene (ppb)	Xylenes (ppb)	MTBE (ppb)
SVP1 (2')	ND	ND	ND	ND	ND	ND
SVP2 (2')	ND	ND	ND	ND	ND	ND
SVP3 (2')	ND	ND	ND	ND	ND.	ND
SVP4 (2')	ND	ND	ND	ND	ND	ND
SVP5 (2')	. ND	ND	ND	ND	ND	ND
Det, Limit	25	0.25	0.25	0.25	0.25	2.5

### EXPLANATION:

ppb = parts per billion

#### ANALYTICAL METHODS:

TPHg =Total Petroleum Hydrocarbons as gasoline by EPA Method 8015-Modified.

BTEX = Benzene, Toluene, Ethylbenzene, and Xylenes according to EPA Method 8021B.

MTBE according to EPA Method 8021B.

TABLE 2
SUMMARY OF LABORATORY ANALYSES-WATER

	ample umber	TPH as Diesel	TPH as Gasoline	Benzene	Toluene	Ethyl	Virlanaa
9/7/02	MW1A	85	61	0.72	1.1	$\frac{\text{benzene}}{< 0.25}$	$\frac{\text{Xylenes}}{<0.25}$
12/7/01	MW1A	180	820	84	7.7	8.4	26
9/17/01	MW1A	180	820	84	7.7	8.4	.26
6/15/01	MW1A	94	350	15	3.5	<0.5	<0.5
3/13/01	MW1A	1,600	15,000	980	37	820	2,100
12/13/00		250	1,400	96	12	<2.0	10
9/19/00	MW1A	< 50	<50	<0.5	<0.5	<0.5	<0.5
6/6/00	MW1A	630	2,400	270	9.5	79	27
3/6/00	MW1A	2,100	13,000	560	<20	640	1,200
12/8/99	MW1A	310	1,200	93	1.8	48	53
9/6/99	MW1A	< 5.0	<5.0	<0.5	<0.5	<0.5	<0.5
8/6/99	MW1A	<5.0	<5.0	<0.5	<0.5	<0.5	<0.5
6/7/99	MW1		(Well	inaccessib.	le, damaged	) •	
3/4/99	MW1		(Well	inaccessib:	le, damaged	)	
11/17/98	MW1	88,000	29,000	2,300	3,000	3,600	3,100
8/21/98	MW1+	96,000	38,000	1,700	1,000	2,400	3,300
6/2/98	MW1	105,000	34,000	1,900	1,600	2,400	3,500
2/27/98	MW1	81,000	27,000	2,200	910	1,700	2,700
12/7/01	MW2	<50	<50	<0.5	<0.5	<0.5	<0.5
9/17/01	MW2	< 50	<50	<0.5	<0.5	<0.5	<0.5
6/15/01	MW2	< 50	< 50	<0.5	<0.5	<0.5	<0.5
3/13/01	MW2	· <50	< 50	<0.5	<0.5	<0.5	<0.5
12/13/00	MW2	< 50	< 50	<0.5	<0.5	<0.5	<0.5
9/19/00	MW2	330	2,000	210	8.7	5,5	6.0
6/6/00	MW2	<50	<50	<0.5	<0.5	<0.5	<0.5
3/6/00	MW2	< 50	<5.0	<0.5	<0.5	<0.5	<0.5
12/8/99	MW2	<50	<5.0	<0.5	<0.5	<0.5	<0.5
9/6/99	MW2	<5.0	<5.0	<0.5	<0.5	<0.5	<0.5
6/7/99	MW2	<5.0	<5.0	<0.5	<0.5	<0.5	<0.5
3/4/99	MW2	<5.0	<5.0	<0.5	<0.5	<0.5	<0.5
11/17/98	MW2	4,300	260	190	420	470	600
8/21/98	MW2+	1,900	<5.0	<0.5	<0.5	220	400
6/2/98	MW2	7,600	60	220	510	800	1,100
2/27/98	MW2	14,000	<5.0	<0.5	120	460	730

TABLE 2
SUMMARY OF LABORATORY ANALYSES-WATER (continued)

	Sample	TPH as		
Date	Number	Motor Oil	MTBE	TOTAL LEAD
9/7/02	MW1A		43	
12/7/01	MW1A	· Mar tree	120	
9/17/01	MW1A	·, ——	120	<b></b>
6/15/01	MW1A		84	
3/13/01	MW1A		320	<del></del>
12/13/00	MW1A		170	
9/19/00	MW1A		13	
6/6/00	MW1A		210	
3/6/00	MW1A	320	<400	<del></del>
12/8/99	MW1A		140	
9/6/99	MW1A		<0.5	
8/6/99	MW1A		<0.5	
6/7/99	MW1	(Well in	accessib	ole, damaged)
3/4/99	MW1		accessib	
11/17/98	MW1	· <b></b>	<0.5	
6/2/98	MW1*	80,000	<0.5	<5.0
2/27/98	MW1		<0.5	
12/7/01	MW2	<250	<5.0	
9/17/01	MW2	<250	<5.0	
6/15/01	MW2	<250	<5.0	
3/13/01	MW2	<250	<5.0	
12/13/00	MW2	<250	<5.0	· <del>-</del> -
9/19/00	MW2	<250	180	
6/6/00	MW2	<250	<5.0	<del></del>
3/6/00	MW2	<250	<5.0	
12/8/99	MW2	<250	<5.0	
9/6/99	MW2	47	<0.5	
6/7/99	MW2	<0.5	<0.5	
3/4/99	MW2	<0.5	<0.5	
11/17/98	MW2	<0.5	<0.5	
6/2/98	MW2*	3,800	<0.5	<5.0
2/27/98	MW2	20,000**	<0.5	

TABLE 2
SUMMARY OF LABORATORY ANALYSES-WATER (continued)

Sample Date Number	TPH as Diesel	TPH as Gasoline	Benzene	Toluene	Ethyl benzene	Xylenes
12/7/01 MW3 9/17/01 MW3 6/15/01 MW3 3/13/01 MW3 12/13/00 MW3 9/19/00 MW3 6/6/00 MW3 3/6/00 MW3 12/8/99 MW3 9/6/99 MW3 6/7/99 MW3 3/4/99 MW3 11/17/98 MW3	3	<50 <50 <50 <50 <50 <5.0 <5.0 <5.0 <5.0	<pre>&lt;0.5 &lt;0.5 &lt;0.5 &lt;0.5 &lt;0.5 &lt;0.5 &lt;0.5 &lt;0.5</pre>	<pre></pre>	<pre></pre>	Xylenes  <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.
8/21/98 MW3 6/2/98 MW3 2/27/98 MW3	<5.0	<5.0 <5.0 <5.0	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.

TABLE 2
SUMMARY OF LABORATORY ANALYSES-WATER(continued)

Sample <u>Date</u>	Number	TPH as Motor Oil	MTBE	TOTAL LEAD
12/7/01	ЕММ		8.4	——
9/17/01	MW3		8.4	
6/15/01	EWM		6.7	
3/13/01	EWM.		11	
12/13/00	EWM.		9.3	<b></b> .
9/19/00	MW3		<5.0	·
6/6/00	MW3	<b></b> .	21	<b></b>
3/6/00	MW3	<250	24/21++	
12/8/99	MM3		18	
9/6/99	MW3	. <u>-</u> -	<0.5	
6/7/99	MW3		<0.5	
3/4/99	EWM		<0.5	· · · · ·
11/17/98	EWM.	·	<0.5	
6/2/98	*EWM	<5.0	<0.5	<5.0
2/27/98	EWM.			

- -- Analyses not performed.
- + Cadmium, chromium, lead, nickel, and zinc were nondetectable, except for 0.078 mg/l of nickel detected in MWl.
- ++ 21 ppb by EPA Method 8260.
- All EPA Method 8010 constituents were nondetectable.
- \*\* 20,000 ppb of Total Recoverable Petroleum Hydrocarbons by EPA Method 418.1. Results are in micrograms per liter ( $\Phi g/L$ ), unless otherwise indicated.

Geo-Logic GL-97-110.R6 October 30, 1998

TABLE 2
SUMMARY OF LABORATORY ANALYSES
WATER

(Samples collected on October 8, 1998)

Sample <u>No./Depth</u>	TPH as <u>Diesel</u>		<u>Benzene</u>	<u>Toluene</u>	Ethyl- <u>benzene</u>	Xylenes	MTBE	TPH as Motor Oil
B1 (10.5')	<5.0	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
B2 (14.4')	<5.0	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
B3 (10.8')	<5.0	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
B4 (18.8')	<5.0	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	
B5 (11.1')	66	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	<del></del>
B6 (10.7')	<5.0	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	
Det. Limit/ Method Blan		<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5

-- analyses not performed

Results are in micrograms per liter (mcg/L), unless otherwise indicated.

Geologic raport dated 1030-98

TABLE 2

GROUNDWATER SAMPLE RESULTS - SITE INVESTIGATION Berkeley Farms Truck Maintenance Facility 4575 San Pablo Avenue

Emeryville, California

P. P.B.

		1 1 24			
Sample Location	TPH-g µg/L	TPH-d µg/L	TPH-ma	VOC µg/L	Antifresze ug/L
SB1	5300.0		<u> </u>		
SB2	48000.0				
SB3	9900.0	-	,,		
SB4	ND	ND	ND	ND	
SB5	ND	ND	ND		ND
SB6	ND	120.0	ND	***************************************	MD
SB7	4200,0	10000.0	21000.0	43 12-DCB;	
•	1			0.6 1.4-DCB;	
				7.0 1.1 DCA:	-
SB8		***************************************		1.8 1.2 DCA	<u>-</u>
SB9**	50.0	ND	DN	-	
5B10	50.0		***************************************	-	
	<u> </u>		<del>,</del>	- 1	-

W.b.
Tank

TPH-g TPH-d TPH-ms VOC 1,2-DCB 1,4-DCB	Total Petroleum Hydrocarbons as gasoline Total Petroleum Hydrocarbons as diesel Total Petroleum Hydrocarbons as motor oil Volatile Organic Compounds 1.2-Dichlorobenzene 1.4-Dichlorobenzene	1.1-DCA 1.2-DCA µg/L ND	1.1-Dichloroethane 1,2-Dichloroethane micrograms per liter (ppb) Not Detected Not Analyzed MTBE observed at 69 up/
---	--	----------------------------------	--

BTEX Range, 8020

Davenport & ASSOC. 10-24-97

### **DATA SHEET**

### **PURGEABLE HALOCARBONS**

SAMPLE:

GEO-LOGIC; BERKELEY FARMS; MW1

Compound	Compound	Method Blank	Method
Compound	Detected (µg/L)	(µg/L)	Detection Limit
	Detected (page)	(hair)	(µg/L)
Chloromethane	< MDL (ND)	< MDL (ND)	0.08
Bromomethane	< MDL (ND)	< MDL (ND)	1.18
Dichlorodifluoromethane	< MDL (ND)	< MDL (ND)	1.81
Vinyl chloride	< MDL (ND)	< MDL (ND)	0.18
Chloroethane	< MDL (ND)	< MDL (ND)	0.52
Methylene chloride	< MDL (ND)	< MDL (ND)	0.25
Trichlorofluoromethane	< MDL (ND)	< MDL (ND)	ND
1, 1-Dichloroethene	< MDL (ND)	< MDL (ND)	0.13
1, 1-Dichloroethane	< MDL (ND)	< MDL (ND)	0.17
trans-1, 2-Dichloroethene	< MDL (ND)	< MDL (ND)	0.10
Chloroform	< MDL (ND)	< MDL (ND)	0.05
1, 2-Dichloroethane	< MDL (ND)	< MDL (ND)	0.03
1, 1, 1-Trichloroethane	< MDL (ND)	< MDL (ND)	0.03
Carbon tetrachloride	< MDL (ND)	< MDL (ND)	0.12
Bromodichloromethane	< MDL (ND)	< MDL (ND)	0.10
1, 2-Dichloropropane	< MDL (ND)	< MDL (ND)	0.04
trans-1, 3-Dichloropropene	< MDL (ND)	< MDL (ND)	0.34
Trichloroethene	< MDL (ND)	< MDL (ND)	0.12
Dibromochloromethane	< MDL (ND)	< MDL (ND)	0.09
1, 1, 2-Trichloroethane	< MDL (ND)	< MDL (ND)	0.02
cis-1, 3-Dichloropropene	< MDL (ND)	< MDL (ND)	0.20
2-Chloroethylvinyl ether	< MDL (ND)	< MDL (ND)	0.13
Bromoform	< MDL (ND)	< MDL (ND)	0.20
1, 1, 2, 2-Tetrachloroethane	< MDL (ND)	< MDL (ND)	0.03
Tetrachloroethene	< MDL (ND)	< MDL (ND)	0.03
Chlorobenzene	< MDL (ND)	< MDL (ND)	0.25
1, 3-Dichlorobenzene	< MDL (ND)	< MDL (ND)	0.32
1, 2-Dichlorobenzene	< MDL (ND)	< MDL (ND)	0.15
1, 4-Dichlorobenzene	< MDL (ND)	< MDL (ND)	0.24

			-	ВО	RING LOG		
Project No. GL-97-110.R3 Boring					casing diameter. 8", 2" Logged By: Joel Greger		
Project: Berk		W	ell Cov	er Elevation: 42.	5 Date drilled: 2/2	20/98	
Boring No. M			Drilling	Metho	d: Hollow Stem A	ger Drilling Company:	Woodward Drilling
Penetration Blows/6" PID	G.W. level	Sample Depth (ft)	Stratig	atigraphy Description USCS)			
		-0 -			8" of concrete p	avement over 4" of sand an	d gravel base
7/10/11 PID-0	$\subseteq$	_ _ _ 5 -	ML		@ 4': brownisl no odor	green clayey silt, very stiff,	wet,
5/6/11 PID-0	PID-0	-  -  - 10 -	ML-CL			ayey silt/silty clay, stiff, satu lor of hydrocarbons	rated,
		_ _ _ _ _ 15 -					
·		- - - - 20 -			Sandpack: #	0 slot from 7-17 feet 2/12 sand from 5-17 feet	
		- - 25 - - -			Seal: Bento	ite 4-5 feet, neat cement gr	out U-4 feet.
		- 30 · - - -					
Berkeley Farms Truck Shop & Yard				Date: February 21, 1998			
4575 San Pablo Avenue Emeryville, California					MW1	Drawn By: JG/Geo-Logic	
		Borii	ng Lo	g an	d Well Com	letion Details — ATTACHMEI	NT 6

		<del></del>		ВО	RING LOG	· · · · · · · · · · · · · · · · · · ·	
Project No. GL-97-110.R6  Project: Berkeley Farms Truck Shop & Yard			Boring diameter: 8"				Logged By: Joel Greger  Date drilled: 10/8/98
			Drilling Company: Woodward Drilling				
Boring No.	B-4		Drillin	g Metho	od: Hollow Stem	Auger	Date backfilled: 10/8/98
Penetration Blows/6" (Mod. Cal)	PID reading	Sample Depth (ft)	Soil Class (USCS)				Description
A-12 tomo.		 			9" of concrete	e over sar	nd, silt, and gravel base (fill).
6/12/18	PID-0	5 7	ML				ark reddish brown (5YR 2.5/2), stiff, mottled iron oxide
6/8/11	PID-0	10		$ \ge   $	CLAYEY SILT along fissures diameter.	「 (ML), gra s, stiff, trac	ay (5Y 5/1), wet to saturated ce angular gravels to 1/4" in
		- 15 <del>-</del> - 1				to 18 fee	partially retracted augers, no et, no water. Drilled to 20 come in.)
		- 20 <del>-</del>					
		 - 25 <del>-</del>			Total Depth: Ground water Backfilled with	measured	at 18.8'. and neat cement grout.
		- 30 — - 30 —					
Berkeley Farms Truck Shop & Yard 4575 San Pablo Avenue			B-4 Date	e: October 27, 1998			
	Emeryville, California				1 1	Dra	wn By: JG/Geo-Logic

Boring Log

		<sub>1</sub> .		ВО	RING LOG	<del></del>	
Project No. GL-97-110.R6  Project: Berkeley Farms Truck Shop & Yard		).Ř6	Boring diameter: 8"  Drilling Company: Woodward Drilling				Logged By: Joel Greger  Date drilled: 10/8/98
						Drilling	
Boring `No.	B-5		Drilling Method: Hollow Stem Auger			Auger	Date backfilled: 10/8/98
Blows/6" reading Dept		Sampl Depth (ft)			Description		
		- 0 -			9" of concrete	over sand	l, silt, and gravel base (fill).
7/9/14	PID -19.1	- 5 · - 5 · -	ML		SANDY SILT 3.1), slightly n hydrocarbons.	(ML), very noist to mo	dark gray (stained?) ((10YR ist, stiff, odor of
5/8/14	PID-13.3	- 10 · - - -	      - 	$\geq$	CLAYEY SILT mottled bluish hydrocarbons.	(ML), brov gray and i	vn (10YR 5/3), v. moist, stiff, ron oxidestaining, odor of
		- 15 - 			(Drilled to 20 came in quick	feet and re ly).	tracted augers, ground water
		- - 20 -	_				
·		- - - 25 - -	-		Total Depth: 2 Ground water Backfilled with	measured a	at 11.1'. and neat cement grout.
		- 30 - - -	-				
Berkeley Farms Truck Shop & Yard 4575 San Pablo Avenue Emeryville, California				October 27, 1998			
				B-5 Drav	Draw	n By: JG/Geo-Logic	

			ВО	RING LOG	
Project No. GL-97-1	0.R6	Boring diameter: 8"  Drilling Company: Woodward Drilling			Logged By: Joel Greger
Project: Berkeley Fa Truck Shop &					Date drilled: 10/8/98
Boring No. B-6		Drilling Method: Hollow Stem Auger			Date backfilled: 10/8/98
Penetration Blows/6" (Mod. Cal) PID PID Dep reading (ft)			G.W. level		Description
	-			9" of concrete over sa	nd, silt, and gravel base (fill).
5/10/14 PID-0	- 5 -	ML.		CLAYEY SILT (ML), be moist, stiff, mottled blu staining.	rown (10YR 5/3), moist to very ish gray and iron oxide
6/11/12 PID-0	- 10 ·	<b>X</b>	<u> </u>	CLAYEY SILT (ML), lig stiff, 2" zone of very w 11 feet.	ght olive gray (5Y 6/2), v. moist, reathered decomposed gravels a
	- 15 - - - -			(Drilled to 20 feet and came in quickly).	retracted augers, ground water
	20 -	-			
	- - - 25 -			Total Depth: 20 feet Ground water measured Backfilled with bentonite	d at 10.7'. and neat cement grout.
	30 -	-			
	-  -	-			
Berkeley Farms Truck Shop & Yard 4575 San Pablo Avenue			ard	B-6	te: October 27, 1998
Emeryville, California				1 1	ıwn By: JG/Geo-Logic