## QUARTERLY GROUNDWATER REPORT

#### 5800 CHRISTIE AVENUE, EMERYVILLE, CALIFORNIA

FEBRUARY 22, 1993

**SUBMITTED TO:** 

MR. BRIAN OLIVA

ALAMEDA COUNTY HEALTH CARE SERVICES

HAZARDOUS MATERIALS DIVISION

80 SWAN WAY, ROOM 200

OAKLAND, CALIFORNIA 94621

MR. RICHARD HIETT

BAY AREA REGIONAL WATER QUALITY

**CONTROL BOARD** 

2101 WEBSTER STREET, SUITE 500

OAKLAND, CALIFORNIA 94612

PREPARED FOR:

CROLEY & HERRING INVESTMENT COMPANY

448 THARP DRIVE,

MORAGA, CALIFORNIA 94556

PREPARED BY: ETS ENVIRONMENT & TECHNOLOGY SERVICES

2081 15TH STREET.

SAN FRANCISCO, CALIFORNIA 94114

TELEPHONE: 415-861-0810

FACIMILE:

415-861-3269

## ETS ENVIRONMENT & TECHNOLOGY SERVICES

## 2081 15TH STREET, SAN FRANCISCO, CALIFORNIA 94114 PHONE 415-861-0810 FAX 415-861-3269

February 22, 1993

Mr. Dick Herring President Croley & Herring Investment Company 448 Tharp Avenue, Moraga, California 94556

Subject:

Quarterly Groundwater Report

5800 Christie Avenue, Emeryville, California

Dear Mr. Herring:

Enclosed please find a copy of the quarterly groundwater report for the January, 1993 water sampling period at the subject facility.

ALTER W. LOO No. 1207

Please contact me if you have any question about this report.

Sincerely,

Walter W. Loo, RG CEG

President

#### TABLE OF CONTENT

- 1.0 INTRODUCTION
- 2.0 GROUNDWATER MOVEMENT ANALYSIS
- 3.0 GROUNDWATER QUALITY
- 4.0 SUMMARY OF FINDINGS

## APPENDIX A GROUNDWATER LABORATORY ANALYSIS REPORT

#### LIST OF FIGURES

FIGURE 1 LOCATION MAP

### LIST OF TABLES

| TABLE 1 | SUMMARY OF GROUNDWATER LEVEL<br>SURVEYS |  |  |  |  |
|---------|---|--|--|--|--|
| TABLE 2 | GROUNDWATER MOVEMENT ANALYSIS           |  |  |  |  |
| TABLE 3 | SUMMARY OF QUARTERLY GROUNDWATER        |  |  |  |  |

#### 1.0 INTRODUCTION

Environmental & Technology Services(ETS) was retained by Croley & Herring Investment Company to perform the 14th quarterly groundwater monitoring for the facility located at 5800 Christie Street in Emeryville, California. The subject facility is currently leased to an electronic merchandise retailer. Prior to leasing, soil contamination was identified at the subject facility. The contaminated soil was removed with the exception of that which was underlying the building because of safety concerns. The removed soil was remediated on-site and properly disposed of with the approval of the regulatory agencies.

A vapor extraction system(VES) was installed immediately adjacent to the northeastern side of the building to mitigate the residual volatile hydrocarbons contained in the soil. The residual volatile organic chemicals(VOCs) were remediated from an average VOCs concentration of about 660 ppm to a satisfactory level at an average of 0.82 ppm in soil. A soil closure plan was submitted(11/15/91) and approval of closure was received on 1/21/92 after submittal of confirmation soil sampling results. The soil vapor extraction system was decommissioned and the Bay Area Air Quality Management District was notified on 12/16/91. The final VES closure report was completed on August 29, 1992.

As part of the site activities, a quarterly groundwater monitoring program has been implemented. Previous quarterly monitoring events were conducted on November 6, 1989, February 20, 1990, May 31, 1990, September 7, 1990, December 4, 1990, April 16, 1991, July 3,1991, October 12, 1991, January 26, 1992, April 8, 1992, July 15,1992, and October 19, 1992 respectively. This quarterly monitoring event was conducted on January 11, 1993. Water samples were taken from the monitoring wells and sent to a State-certified laboratory for analysis under proper chain-of-custody procedures.

This report presents the results of this quarterly groundwater monitoring event on well EW-lincluding laboratory analytical results, groundwater movement analysis, summary of findings, and conclusions and discussions.

## 2.0 GROUNDWATER MOVEMENT ANALYSIS

Prior to sample collection of this quarterly sampling, depth-to-water table in each of the three existing monitoring wells at the facility was measured for the analysis of groundwater movement. Table 1 presents a summary of the water levels in the three wells (EW-1, MW-2, and MW-3) from the groundwater monitoring events prepared by ETS.

From the result of the water level measurements on January 11, 1993, elevation of water levels were increased in the three wells, as compared to the data collected in November 1992. Nevertheless, the groundwater flow direction remained in the same direction, flowing towards south (Figure 1). The hydraulic gradient was 0.011 feet per horizontal foot.

Groundwater movement across the facility remains in a similar pattern, as compared to the result from the previous sampling event. Data of flow direction and hydraulic gradient are summarized in Table 1.




TABLE 1
SUMMARY OF WATER LEVEL DATA

| WELL<br>Name | TOC I                           | TW SWL   | DTW SWL                     | 5/31/90<br>DTW SWL<br>Ft. Ft.  | DTW SWL    |
|--------------|---------------------------------|--|-----------------------------|--------------------------------|------------|
| EW-1         | 8.62                            | 6.15 2.47  | 5.93 2.69                   | 5.86 2.76                      | 6.30 2.32  |
| MW-2         | 7.42                            | 4.37 3.05  | 4.26 3.16                   | 4.26 3.16                      | 4.60 2.82  |
| MW-3         | 6.42                            | 5.10 1.32  | 5.42 1.00                   | 4.93 1.49                      | 5.15 1.17  |
| WELL<br>Name | 12/4/90<br>DTW SWL I<br>Ft. Ft. | DTW SWL  | DTW SWL                     | 10/14/91<br>DTW SWL<br>Ft. Ft. | DTW SWL    |
| EW-1         | 7.39 2.23                       | 6.02 2.60  | 6.20 2.42                   | 6.5 2.12                       | 6.20 2.42  |
| MW-2         | 4.67 2.75                       | 4.31 3.11  | 4.52 2.9                    | 3.92 3.5                       | 4.43 3.10  |
| MW-3         | 5.96 1.35                       | 5.25 1.17  | 5.33 1.09                   | 4.63 1.79                      | 6.50 -0.08 |
| WELL<br>Name |                                 |  | _ DTW                       | SWL                            |            |
| EW-1         | 6.10 2.52                       | 6.1 2.52   | 5.5                         | 3.12                           |            |
| MW-2         | 4,42 3.00                       | 4.77 2.65  | 2.9                         | 4.92                           |            |
| MW-3         | 5.23 1.19                       | 5.37 1.05  | 3.6                         | 2.82                           |            |
| Note:        | TOC<br>DTW<br>SWL<br>MSL        | top of casin<br>depth to was<br>static wate<br>mean sea le | ater table<br>r level above | MSL                            |            |

TABLE 2
GROUNDWATER MOVEMENT ANALYSIS

| Date            | 4/25/89 | 11/6/89 | 2/20/90 | 5/31/90  | 9/7/90 | 12/4/90 |          |
|-----------------|---------|---------|---------|----------|--------|---------|----------|
| Flow<br>Towards | SW      | S       | s       | S        | S      | S       |          |
| Gradient        | 0.001   | 0.012   | 0.016   | 0.0125   | 0.0115 | 0.045   |          |
| Date            | 4/16/91 | 7/3/9   | 1       | 10/14/91 | 1/9/92 | 7/15/92 | 10/19/92 |
| Flow<br>Towards | S       | s       |         | S        | SW     | S       | S        |
| Gradient        | 0.014   | 0.01    | 3       | 0.011    | 0.0238 | 0.013   | 0.0127   |
| Date            | 1/11/93 |         |         |          |        |         |          |
| Flow<br>Towards | S       |         |         |          |        |         |          |
| Gradient        | 0.011   |         |         |          |        |         |          |

## 3.0 GROUNDWATER QUALITY

On January 11, 1993, ETS field personnel visited the facility and collected water samples from monitoring well EW-1 for laboratory analysis. These groundwater samples were sent to a state-certified laoratory for analyses of halocarbons using EPA method 601, total petroleum hydrocarbons (TPH) as gasoline and gasoline constituents benzene, toluene, ethylbenzene, and total xylenes (BTEX) using EPA method 602.

From the results of the laboratory analysis (Appendix A), water sample taken from well EW-1 contained some volatile organic compounds. The VOCs detected in well EW-1 from the January 11, 1993 sampling episode are presented in Table 3.

TABLE 3

# SUMMARY OF QUARTERLY GROUNDWATER QUALITY RESULTS OF WELL EW-1 5800 CHRISTIE AVENUE, EMERYVILLE, CALIFORNIA

## **CONCENTRATIONS IN MG/L**

| COMPOUNDS   | 5/8/89  | 11/6/89   | 2/20/90  | 5/31/90  | 9/7/90   | 12/4/90   | 4/6/91  | 7/3/91  | 10/12/91  | 1/8/92   | 4/8/92  |
|---|---|---|--|--|--|---|---|---|---|--|---|
| TPH as GASOLINE   | NA  | 0.74  | 12.0   | 24.0   | 25.0   | 7.4   | 51.0  | 23.0  | 39.0  | <5.0   | 12.0  |
| BENZENE<br>TOLUENE<br>XYLENES<br>ETHYLBENZENE   | ND<br>0.19<br>0.17<br>ND                                | 0.18<br>0.039<br>0.067<br>0.0008  | 1.3<br>3.6<br>0.047<br>0.0071  | 0.056<br>6.1<br>0.14<br>0.017  | 1.1<br>0.8<br>0.042<br>ND  | 0.18<br>3.2<br>ND<br>ND                                     | 3.0<br>12.0<br>ND<br>ND                                 | 0.65<br>8.7<br>ND<br>ND                                     | ND<br>1.3<br>ND<br>ND   | ND<br>0.58<br>ND<br>ND   | 4.0<br>ND<br>ND<br>ND                           |
| HALOCARBONS   | 0.718   | 1.1861  | 4.701  | 6.876  | 6.661  | 3.762   | 10.6  | 6.49  | 2.794   | 4.459  | 6.8   |
| TCE 1,1 DCE 1,2 DCE 1,1,1 TCA 1,1 DCA 1,2 DCA VINYL CHLORIDE CHLOROETHANE MET. CHLORIDE | 0.64<br>0.078<br>ND<br>ND<br>ND<br>ND<br>ND<br>ND<br>ND | 0.74<br>0.0023<br>0.35<br>0.026<br>0.034<br>0.0048<br>0.029<br>ND<br>ND | 1.1<br>0.014<br>2.5<br>0.55<br>0.46<br>0.034<br>ND<br>0.029<br>0.014 | 0.83<br>0.069<br>0.11<br>1.2<br>1.9<br>0.033<br>2.6<br>0.094<br>0.04 | 0.49<br>0.036<br>2.4<br>0.51<br>1.3<br>0.053<br>1.7<br>0.15<br>0.022 | 1.5<br>ND<br>1.5<br>0.072<br>0.46<br>ND<br>0.23<br>ND<br>ND | 1.3<br>ND<br>3.7<br>2.9<br>1.8<br>ND<br>0.9<br>ND<br>ND | 0.13<br>ND<br>2.0<br>0.2<br>2.0<br>ND<br>1.99<br>0.17<br>ND | 0.73<br>ND<br>0.62<br>0.47<br>0.63<br>0.12<br>0.17<br>0.054<br>ND | 1.7<br>ND<br>1.52<br>0.089<br>0.42<br>0.25<br>0.48<br>ND<br>ND | 2.8<br>ND<br>ND<br>ND<br>1.3<br>2.7<br>ND<br>ND |
| TOTAL VOCs  | 1.078   | 1.9261  | 16.701   | 30.876   | 31.661   | 11.162  | 61.6  | 29.49   | 41.794  | <9.459   | 18.8  |

NA NOT ANALYSED

ND NOT DETECTED OR BELOW DETECTION LIMITS

VOCs VOLATILE ORGANIC COMPOUNDS (TPH PLUS TOX)

#### **3(CONTINUE) TABLE**

## SUMMARY OF QUARTERLY GROUNDWATER QUALITY RESULTS OF WELL EW-1 5800 CHRISTIE AVENUE, **EMERYVILLE, CALIFORNIA**

## **CONCENTRATIONS IN MG/L**

| COMPOUNDS   | 7/15/92  | 10/19/92  | 1/11/93  |
|---|--|---|--|
| TPH as GASOLINE   | 100.0  | 26.0  | 20.0   |
| BENZENE<br>TOLUENE<br>XYLENES<br>ETHYLBENZENE   | ND<br>4.7<br>ND<br>ND  | ND<br>12.5<br>ND<br>ND                                      | ND<br>7.5<br>ND<br>0.075                                 |
| HALOCARBONS   | 2.461  | 5.07  | 0.065  |
| PCE TCE 1,1 DCE 1,2 DCE 1,1,1 TCA 1,1 DCA 1,2 DCA VINYL CHLORIDE CHLOROETHANE MET. CHLORIDE | ND<br>0.68<br>ND<br>0.6<br>0.42<br>0.6<br>0.11<br>0.15<br>ND<br>ND | ND<br>0.27<br>4.8<br>ND<br>ND<br>ND<br>ND<br>ND<br>ND<br>ND | 0.042<br>0.023<br>ND<br>ND<br>ND<br>ND<br>ND<br>ND<br>ND |
| TOTAL VOCs  | 102.461  | 31.07   | 20.065   |

NOT ANALYSED NA

ND NOT DETECTED OR BELOW DETECTION LIMITS VOCs VOLATILE ORGANIC COMPOUNDS (TPH PLUS TOX)

#### 4.0 SUMMARY OF FINDINGS

Table 3 presents a summary of analystical results of well EW-1 in time series. There are several factors that affect the changes in the hydrocarbon concentration. These factors are variations in water table, chemical breakdown due to biodegradation, and unidentified off-site sources.

An experiment was tried to desorb the organic chemicals from the clayey material and oxidize them in places near well EW-1 by the application of direct electrical current flow in the subsurface without pumping the groundwater. The experiment showed successful control of the flow of groundwater in the area and the total volatile organic compounds(VOCs) at one time reached below 4 ppm due to the induced electrochemical reactions between electrodes. The degree of the effectiveness and success cannot be assessed at this time because the readings were interfered with by the spreading of the upgradient gasoline plume.

Also, there are indications that strong biodegradation activities are taking place in the subsurface. Prescribed amounts of glucose was added to the groundwater underlying the area to stimulate cometabolic biodegradation of the chlorinated solvents. The results of groundwater analysis showed reduction of the chlorinated solvents since the addition of the glucose.

## APPENDIX A

GROUNDWATER LABORATORY ANALYSIS REPORT