

Wickham, Jerry, Env. Health

Subject: RO3075_PHONE_LOG_2012-04-18
Entry Type: Phone call
Start: Wed 4/18/2012 3:12 PM
End: Wed 4/18/2012 3:12 PM
Duration: 0 hours

Phone call with Mark Trevor and Mohammad Bazargani of Strategic Engineering & Science. When the elevator shaft was removed, oil was observed dripping from the casing. The casing, which is roughly 30 to 40 feet long had holes in it (holes appeared to be cut not corrosion. Soil samples were collected from the stockpile from shaft removal. No PCBs were detected. Four posts were installed for new elevator construction. Groundwater samples were previously collected but not downgradient from elevator shaft. I indicated that they will need to collect discrete, multiple-depth groundwater samples. They will put together a Work Plan to collect groundwater samples using Hydropunch likely in sidewalk area. They want to do the work during construction. I indicated that I could review a Work Plan within a few days.

Jerry Wickham