UNDERGROUND STORAGE TANK (UST) SITE - UNAUTHORIZED RELEASE / CONTAMINATION REPORT

EMERGENCY: ☐ Yes ☒ No

HAS STATE OFFICE OF EMERGENCY SERVICES REPORT BEEN FILED? ☐ Yes ☒ No

REPORT DATE: July 31, 2015

CASE #: RO0003171

FOR LOCAL AGENCY USE ONLY

I HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE REPORTED THIS INFORMATION TO LOCAL OFFICIALS PURSUANT TO SECTION 25180.7 OF THE HEALTH AND SAFETY CODE.

SIGNED _____ DATE _____

REPORTED BY

NAME OF INDIVIDUAL FILING REPORT: Ryan Wood

PHONE: (925) 296-8015

SIGNATURE

REPRESENTING: ☐ LOCAL AGENCY ☐ REGIONAL BOARD ☒ OWNER/OPERATOR ☐ OTHER

COMPANY OR AGENCY NAME: CDM Smith

ADDRESS: 100 Pringle Ave, Ste 300 (STREET) Walnut Creek, (CITY) CA (STATE) 94596 (ZIP)

RESPONSIBLE PARTY

NAME: Bay Area Rapid Transit (BART) ☐ Unknown

CONTACT PERSON: Gary Jensen

PHONE: (510) 464-7659

ADDRESS: PO BOX 12688, Mailstop LKS-18 (STREET) Oakland, (CITY) CA (STATE) 94604-2688 (ZIP)

SITE LOCATION

FACILITY NAME (IF APPLICABLE): BART Oakland Maintenance Shop

OPERATOR: BART

PHONE: (510) 464-6654

ADDRESS: 601 East 8th Street (STREET) Oakland (CITY) Alameda (COUNTY) (ZIP)

CROSS STREET: 5th Ave

IMPLEMENTING AGENCIES

LOCAL AGENCY / AGENCY NAME: Alameda County Environmental Health

PHONE: (510) 567-6708

REGIONAL BOARD

PHONE: ( )

SUBSTANCES INVOLVED

(1) NAME: Waste Oil

QUANTITY LOST (GALLONS): ☒ Unknown

(2) ☐ Unknown

DISCOVERY/ABATEMENT

DATE DISCOVERED: February 2015

HOW DISCOVERED: ☒ Tank Test ☐ Tank Removal ☐ Nuisance Conditions ☐ Inventory Control ☐ Subsurface Monitoring ☐ Other

DATE DISCHARGE BEGAN: ☒ Unknown

HAS DISCHARGE BEEN STOPPED? ☒ Yes ☐ No IF YES, DATE: February 2015

METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY): ☐ Remove Contents ☐ Close Tank ☐ Repair Tank ☐ Change Procedure ☐ Replace Tank ☐ Other ☒ Repair Piping

SOURCE/CAUSE

SOURCE OF DISCHARGE: ☐ Tank ☒ Piping ☐ Dispenser ☐ Delivery Problem ☐ Submersible Turbine Pump (STP) ☐ Other

CAUSE(S): ☐ Spill ☐ Overfill ☒ Physical/Mechanical Damage ☐ Corrosion ☒ Installation Problem ☐ Unknown ☐ Other

CASE TYPE

CHECK ONE ONLY: ☐ Undetermined ☒ Soil Only ☐ Groundwater ☐ Drinking Water – (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)

CURRENT STATUS

CHECK ONE ONLY: ☒ Open - Site Assessment ☐ Open - Assessment & Interim Remedial Action ☐ Open - Remediation ☐ Open - Verification Monitoring ☐ Open - Inactive ☐ Closed – No Further Action Required

REMEDIAL ACTION

CHECK APPROPRIATE ACTION(S)

Human health exposure control? ☐ Yes ☐ No ☒ Unknown

Groundwater migration control? ☐ Yes ☐ No ☒ Unknown

☒ No Action Required (NAR) ☐ Excavate & Treat (ET) ☐ Treatment at Hookup (TH) ☐ Other ☐ Excavate & Dispose (ED) ☐ Free Product Removal (FPR) ☐ Replace Supply (RS)

COMMENTS

Piping sump was full of oil as a result of overfill alarm/shutoff failure. Piping runs were replaced due to supply line being manifolded with the vent line. Contamination was found along the piping area only. No work was completed on the tank. The tank interstice is liquid filled and no alarms have been triggered on the tank. Tank remains operational. Soil samples were collected and analyzed on February 13th, 2015.