ALEX BRISCOE, Agency Director



ENVIRONMENTAL HEALTH DEPARTMENT OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Certified Mail #: 7009 2820 0001 4359 7986

February 25, 2014

#### NOTICE OF RESPONSIBILITY

Site Name & Address:

CHEVRON #9-1583

5509 MARTIN LUTHER KING JR WAY

OAKLAND, CA 94609

RO0000002

Local ID: Related ID:

2047

RWQCB ID:

01-0379

Global ID:

T0600100348

Responsible Party:

PETER T GRASSI TRUST 1804 N SHORELINE BLVD #140 MOUNTAIN VIEW CA 94043 Date First Reported:

1/25/1990

Substance:

8,8006619 Multiple Releases

Funding for Oversight:

LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified CHEVRON CORPORATION as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about

Date:

02/25/14

ARIU LEVI, Director Contract Project Director Action: Add Reason: NEW

## ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

February 25, 2014

Site Name & Address:

**CHEVRON #9-1583** 

5509 MARTIN LUTHER KING JR WAY

**OAKLAND, CA 94609** 

Local ID: RO0000002

Related ID: 2047
RWQCB ID: 01-0379

Global ID: T0600100348

#### **All Responsible Parties**

RP has been named a Primary RP - BRIAN WAITE CHEVRON ENVIRONMENTAL MANANGEMENT COMPANY

6101 BOLLINGER ROAD | SAN RAMON, CA 94583 | No Phone Number Listed

#### RP has been named a Primary RP - EVELYN SCHLICHTING

1475 2<sup>ND</sup> STREET | SAN RAFAEL, CA 94901 | No Phone Number Listed

#### RP has been named a Primary RP - BEN & PATRICIA SHIMEK

PO BOX 681 | ROSS, CA 94957 | No Phone Number Listed

## RP has been named a Primary RP -

PETER T GRASSI TRUST

1804 N SHORELINE BLVD #140 | MOUNTAIN VIEW, CA 94043 | No Phone Number Listed

### Responsible Party Identification Background

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

February 25, 2014

#### **Responsible Party Identification**

#### **Existence of Unauthorized Release**

Seven shallow soil samples (A through F and SS-1) were collected from the site on December 14, 1989 during the removal and replacement of product piping. Contamination was detected in two soil samples (B and SS-1) up to 1,700 parts per million (ppm) Total Petroleum Hydrocarbons as gasoline (TPHg) and 0.14 ppm benzene. These data indicate than an unauthorized release had occurred.

Three groundwater monitoring wells (MW-1 through 3) were installed at the site in response to a suspected leak. Soil samples were not collected from the well borings, nor was there any groundwater samples collected. On March 13, 1990 groundwater samples were collected from the three wells and up to 50,000 parts per billion (ppb) TPHg (MW-1) and 9,900 ppb benzene (MW-3) were detected. These data indicate than an unauthorized release had occurred.

### Responsible Party Identification

Evelyn Schlichting (et al, trust of Evelyn Schlichting) purchased or received the property in October 1972. She is a responsible party for the site because she owned the property where an unauthorized release has occurred (Definition 3).

Chevron Corporation (Chevron) owned and / or operated the USTs at this site. Chevron is a responsible party for site because it owned or operated the USTs used for the storage of a hazardous substance (Definition 1), owned or operated the USTs immediately before the discontinuation of its use (Definition 2), and had control over an UST at the time of or following an unauthorized release of a hazardous substance (Definition 4).

Peter Grassi Trust purchased or received the property in January 2011 and is therefore a former property owner of the site. He is a responsible party for the site because he owned the property where an unauthorized release has occurred (Definition 3).

ALEX BRISCOE, Agency Director



ENVIRONMENTAL HEALTH DEPARTMENT OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Certified Mail #: 7009 2820 0001 4359 7979

February 25, 2014

## NOTICE OF RESPONSIBILITY

Site Name & Address:

CHEVRON #9-1583

5509 MARTIN LUTHER KING JR WAY

OAKLAND, CA 94609

Local ID:

RO0000002

Related ID:

2047

RWQCB ID:

01-0379

Global ID:

T0600100348

Responsible Party:

EVELYN SCHLICHTING c/o BEN SCIMEK; PETROLEUM SALES, INC. 1475 2<sup>ND</sup> STREET SAN RAFAEL CA 94901 Date First Reported:

1/25/1990

Substance:

8,8006619 Multiple Releases

Funding for Oversight:

LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified CHEVRON CORPORATION as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about

ARIU LEVI, Director

Contract Project Director

Date

02 75 14

Action: Add

Reason: NEW

## ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

February 25, 2014

Site Name & Address:

**CHEVRON #9-1583** 

5509 MARTIN LUTHER KING JR WAY

**OAKLAND, CA 94609** 

Local ID: RO0000002

Related ID: 2047
RWQCB ID: 01-0379

Global ID: T0600100348

#### **All Responsible Parties**

RP has been named a Primary RP - BRIAN WAITE CHEVRON ENVIRONMENTAL MANANGEMENT COMPANY

6101 BOLLINGER ROAD | SAN RAMON, CA 94583 | No Phone Number Listed

#### RP has been named a Primary RP - EVELYN SCHLICHTING

1475 2<sup>ND</sup> STREET | SAN RAFAEL, CA 94901 | No Phone Number Listed

#### RP has been named a Primary RP - BEN & PATRICIA SHIMEK

PO BOX 681 | ROSS, CA 94957 | No Phone Number Listed

## RP has been named a Primary RP -

PETER T GRASSI TRUST

1804 N SHORELINE BLVD #140 | MOUNTAIN VIEW, CA 94043 | No Phone Number Listed

### Responsible Party Identification Background

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

February 25, 2014

#### **Responsible Party Identification**

#### **Existence of Unauthorized Release**

Seven shallow soil samples (A through F and SS-1) were collected from the site on December 14, 1989 during the removal and replacement of product piping. Contamination was detected in two soil samples (B and SS-1) up to 1,700 parts per million (ppm) Total Petroleum Hydrocarbons as gasoline (TPHg) and 0.14 ppm benzene. These data indicate than an unauthorized release had occurred.

Three groundwater monitoring wells (MW-1 through 3) were installed at the site in response to a suspected leak. Soil samples were not collected from the well borings, nor was there any groundwater samples collected. On March 13, 1990 groundwater samples were collected from the three wells and up to 50,000 parts per billion (ppb) TPHg (MW-1) and 9,900 ppb benzene (MW-3) were detected. These data indicate than an unauthorized release had occurred.

### Responsible Party Identification

Evelyn Schlichting (et al, trust of Evelyn Schlichting) purchased or received the property in October 1972. She is a responsible party for the site because she owned the property where an unauthorized release has occurred (Definition 3).

Chevron Corporation (Chevron) owned and / or operated the USTs at this site. Chevron is a responsible party for site because it owned or operated the USTs used for the storage of a hazardous substance (Definition 1), owned or operated the USTs immediately before the discontinuation of its use (Definition 2), and had control over an UST at the time of or following an unauthorized release of a hazardous substance (Definition 4).

Peter Grassi Trust purchased or received the property in January 2011 and is therefore a former property owner of the site. He is a responsible party for the site because he owned the property where an unauthorized release has occurred (Definition 3).

ALEX BRISCOE, Agency Director



ENVIRONMENTAL HEALTH DEPARTMENT OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Certified Mail #: 7009 2820 0001 4359 7962

February 25, 2014

## NOTICE OF RESPONSIBILITY

Site Name & Address:

CHEVRON #9-1583

5509 MARTIN LUTHER KING JR WAY

OAKLAND, CA 94609

Local 1D:

RO0000002

Related ID:

2047

RWQCB ID:

01-0379

Global ID:

T0600100348

Responsible Party:

BEN & PATRICIA SHIMEK PO BOX 681 ROSS CA 94957 Date First Reported:

1/25/1990

Substance:

8,8006619 Multiple Releases

Funding for Oversight:

LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified CHEVRON CORPORATION as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about

1660

Date

02 25 14

Action: Add

Reason: NEW

Contract Project Director

ARIU LEVI, Director

## ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

February 25, 2014

Site Name & Address:

**CHEVRON #9-1583** 

5509 MARTIN LUTHER KING JR WAY

**OAKLAND, CA 94609** 

Local ID: RO0000002

Related ID: 2047
RWQCB ID: 01-0379

Global ID: T0600100348

#### **All Responsible Parties**

RP has been named a Primary RP - BRIAN WAITE CHEVRON ENVIRONMENTAL MANANGEMENT COMPANY

6101 BOLLINGER ROAD | SAN RAMON, CA 94583 | No Phone Number Listed

#### RP has been named a Primary RP - EVELYN SCHLICHTING

1475 2<sup>ND</sup> STREET | SAN RAFAEL, CA 94901 | No Phone Number Listed

#### RP has been named a Primary RP - BEN & PATRICIA SHIMEK

PO BOX 681 | ROSS, CA 94957 | No Phone Number Listed

## RP has been named a Primary RP -

PETER T GRASSI TRUST

1804 N SHORELINE BLVD #140 | MOUNTAIN VIEW, CA 94043 | No Phone Number Listed

### Responsible Party Identification Background

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

February 25, 2014

#### **Responsible Party Identification**

#### **Existence of Unauthorized Release**

Seven shallow soil samples (A through F and SS-1) were collected from the site on December 14, 1989 during the removal and replacement of product piping. Contamination was detected in two soil samples (B and SS-1) up to 1,700 parts per million (ppm) Total Petroleum Hydrocarbons as gasoline (TPHg) and 0.14 ppm benzene. These data indicate than an unauthorized release had occurred.

Three groundwater monitoring wells (MW-1 through 3) were installed at the site in response to a suspected leak. Soil samples were not collected from the well borings, nor was there any groundwater samples collected. On March 13, 1990 groundwater samples were collected from the three wells and up to 50,000 parts per billion (ppb) TPHg (MW-1) and 9,900 ppb benzene (MW-3) were detected. These data indicate than an unauthorized release had occurred.

### Responsible Party Identification

Evelyn Schlichting (et al, trust of Evelyn Schlichting) purchased or received the property in October 1972. She is a responsible party for the site because she owned the property where an unauthorized release has occurred (Definition 3).

Chevron Corporation (Chevron) owned and / or operated the USTs at this site. Chevron is a responsible party for site because it owned or operated the USTs used for the storage of a hazardous substance (Definition 1), owned or operated the USTs immediately before the discontinuation of its use (Definition 2), and had control over an UST at the time of or following an unauthorized release of a hazardous substance (Definition 4).

Peter Grassi Trust purchased or received the property in January 2011 and is therefore a former property owner of the site. He is a responsible party for the site because he owned the property where an unauthorized release has occurred (Definition 3).

ALEX BRISCOE, Agency Director



ENVIRONMENTAL HEALTH DEPARTMENT OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

February 25, 2014

#### **NOTICE OF RESPONSIBILITY**

Site Name & Address:

CHEVRON #9-1583

5509 MARTIN LUTHER KING JR WAY

OAKLAND, CA 94609

Local ID:

RO0000002

Related ID:

2047

RWQCB ID:

01-0379

Global ID:

T0600100348

Responsible Party:

BRIAN WAITE CHEVRON ENVIRONMENTAL MANAGEMENT COMPANY 6101 BOLLINGER ROAD SAN RAMON CA 94583 Date First Reported:

1/25/1990

Substance:

8,8006619 Multiple Releases

**Funding for Oversight:** 

LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(les) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified CHEVRON CORPORATION as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about

ARIU LEVI, Director Contract Project Director Date:

62/25/14

Action: Add

Reason: NEW

## ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

February 25, 2014

Site Name & Address:

**CHEVRON #9-1583** 

5509 MARTIN LUTHER KING JR WAY

**OAKLAND, CA 94609** 

Local ID: RO0000002

Related ID: 2047
RWQCB ID: 01-0379

Global ID: T0600100348

#### **All Responsible Parties**

RP has been named a Primary RP - BRIAN WAITE CHEVRON ENVIRONMENTAL MANANGEMENT COMPANY

6101 BOLLINGER ROAD | SAN RAMON, CA 94583 | No Phone Number Listed

#### RP has been named a Primary RP - EVELYN SCHLICHTING

1475 2<sup>ND</sup> STREET | SAN RAFAEL, CA 94901 | No Phone Number Listed

#### RP has been named a Primary RP - BEN & PATRICIA SHIMEK

PO BOX 681 | ROSS, CA 94957 | No Phone Number Listed

## RP has been named a Primary RP -

PETER T GRASSI TRUST

1804 N SHORELINE BLVD #140 | MOUNTAIN VIEW, CA 94043 | No Phone Number Listed

### Responsible Party Identification Background

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

February 25, 2014

#### **Responsible Party Identification**

#### **Existence of Unauthorized Release**

Seven shallow soil samples (A through F and SS-1) were collected from the site on December 14, 1989 during the removal and replacement of product piping. Contamination was detected in two soil samples (B and SS-1) up to 1,700 parts per million (ppm) Total Petroleum Hydrocarbons as gasoline (TPHg) and 0.14 ppm benzene. These data indicate than an unauthorized release had occurred.

Three groundwater monitoring wells (MW-1 through 3) were installed at the site in response to a suspected leak. Soil samples were not collected from the well borings, nor was there any groundwater samples collected. On March 13, 1990 groundwater samples were collected from the three wells and up to 50,000 parts per billion (ppb) TPHg (MW-1) and 9,900 ppb benzene (MW-3) were detected. These data indicate than an unauthorized release had occurred.

### Responsible Party Identification

Evelyn Schlichting (et al, trust of Evelyn Schlichting) purchased or received the property in October 1972. She is a responsible party for the site because she owned the property where an unauthorized release has occurred (Definition 3).

Chevron Corporation (Chevron) owned and / or operated the USTs at this site. Chevron is a responsible party for site because it owned or operated the USTs used for the storage of a hazardous substance (Definition 1), owned or operated the USTs immediately before the discontinuation of its use (Definition 2), and had control over an UST at the time of or following an unauthorized release of a hazardous substance (Definition 4).

Peter Grassi Trust purchased or received the property in January 2011 and is therefore a former property owner of the site. He is a responsible party for the site because he owned the property where an unauthorized release has occurred (Definition 3).