



gettler — ryan inc.

general contractors

January 9, 1984

Mr. W. R. Smith
Chevron U.S.A. Inc.
Two Annabel Lane, Suite 200
San Ramon, California 94583



Reference: Service Station 0504
15900 Hesperian Boulevard
San Lorenzo, California

Gentlemen:

Enclosed are our reports covering installation of observation wells for the referenced location. Five wells were drilled using a Failing 6" continuous flight auger to the depth indicated on the boring logs. All wells were installed per your "Typical Well Profile" dated February 1, 1983.

Please contact us if any further information is required.

Very truly yours,

Jeffrey M. Ryan

jmr/ml

Attachments: Plot Plan
Well Section
Soil Boring Logs
Observation Well Daily Reports
Well Elevation Survey


Post Office Rd.

DN 4

CHEVRON
SERVICE
STATION

DN 5

DN 3



TANK
SLAB



DN 2

HESPERIAN BLVD

CHEVRON U.S.A. # 504
15900 HESPERIAN BLVD
SAN LORENZO, CA M.T.S.