

STID 3618 - 5755 Broadway - Shell  
9/6/18

1/4/93

Talked to Don Kirk - update  
at site: tanks & piping tightness test  
today on all systems: will repair the  
sewer line (cracked / clay pipe)  
need to submit work plan for investigation  
to include report on activities regarding the  
initial statement must adhere to Title 23  
2650, 2651, 2652, 2653, 2654, 2655

1/4/93

10:00 AM. Lisa Watson called - will not  
be able to test the integrity of the tanks & piping  
due to contractor (sick) but schedule to  
test tomorrow on 1/5/93. Advised it's  
ok but need to monitor the sewer line &  
the operation wells 2 thru - →

\* Kyrroffo, Lisa

STID 3618 Shell Oil Company  
5955 Broadway Street Oakland 94618

1/11/93

Called a meeting for 11/13/93 with Larry SLO  
& Shell's representative Don Kirk, Scott McCleod,  
Kay Newsome, Jeff Bauer, Denny Jan  
to discuss status of site

11/13/93

needed to discuss the following items: Don  
Kirk, Jeff Bauer, Scott McCleod, Jeffrey Kay, Dennis  
1) Red jacket replacement of piston & diaphragm  
positive line leak detector - electronic  
leak & product discharge off  
pressure loss?

2) Sample water sample - NO reduced vapor  
monitor 2x daily until sewer line  
replaced

3) Permit to replace sewer 8in w/ new <sup>Hydro</sup> lines  
Engineering Dept Public Works - (1-4 PM)  
Lourdes Khratzo <sup>supervisor</sup> 238-2110

(A) MTBE found - new release

5) Pitrod traps in the observation wells  
by today 11/13/93

6) By Wednesday WP - 1  
WP before 10:45 days