



RECEIVED

2:12 pm, Apr 15, 2009

Alameda County
Environmental Health

5052 COMMERCIAL CIRCLE
CONCORD, CALIFORNIA 94520
TELEPHONE (925) 688-1200
FACSIMILE (925) 688-0388

FORM #	253737	SS	X	BP	
REF	QM	TRANSMITTAL			
1	2	3	4	5	6 X

DATE: 7-25-02

FAX

MESSAGE TO: Dave DeWitt

COMPANY: _____

CC: _____

NO. OF PAGES, INCLUDING COVER SHEET: 4

TELEPHONE NO.: _____ FAX NO.: 277-2361

MESSAGE FROM: Tracy Walker

DESCRIPTION:

Is this what you were looking for with regard to # 3737 in Emeryville?

If not, I will have pull boxes from off site storage, so it will take a little longer.

7.

FIGURE 1 - Vicinity Map



© 1997 DeLorme, Street Atlas USA

Mag 16.00
Fri Nov 05 17:12 1999

Scale 1:3,906 (at center)

200 Feet

100 Meters






-  Local Road
-  Interstate/Limited Access
-  Major Connector
-  Railroad

Table 1
Potential Off-Site Sources

Former Tosco 76 Service Station 3737, Emeryville, California

Map ID	Site	Street Address	Environmental Database Listing(s)
1	Schwabacker Frey	5733 Pelledeau	LUST (gasoline; soil affected) CORTESE
2	Michel Pelton Co. (Animal Care Products)	5743 Landregan/Horton	LUST (leak reported 2/23/87; inactive status; not on priority list) NORTH BAY TOXICS LIST
2	Hogland, Bogart, etc.	5743 Landregan/Horton	UST (tank removed)
3	Chevron Emeryville Terminal	Southwest corner of Landregan and Powell	LUST (leak reported 2/23/87; inactive status; not on priority list) NORTH BAY TOXICS LIST
4	Bay Airgas (formerly Airco Supply Co.)	1350 Powell	UST (unleaded gas; closed; removed)
5	Construction Services	1300 Powell	LUST (oily sheen found 6/97)
6	American Bituminous Asphalt	1520 Powell	CERCLIS/NFRAP (further remedial action planned)
6	Chevron Asphalt Plant & Terminal	1520 Powell	SCL LUST NORTH BAY TOXICS LIST
7	Westinghouse Electric Corporation	5899 Peladeau	SCL (preliminary assessment, no further remedial action planned) CERCLIS/NFRAP LUST (transformer oil spill; remediation started 9/21/85) NORTH BAY TOXICS LIST
8	Hydraulic Electro Service Corporation	5812 Hollis	LUST (diesel; groundwater affected; post remedial action underway) CORTESE



SITE DETAIL DIAGRAM
Former Tosco Station No. 3737
1400 Powell Street
Emeryville, California

FIGURE 2