ENVIRONMENTAL HEALTH DEPARTMENT

ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250

Alameda, CA 94502-6577

(510) 567-6700 FAX (510) 337-9335

May 2, 2016

Ms. Carryl MacLeod
Chevron Environmental Management Co.
6101 Bollinger Canyon Road
Neil & Diane Goodhue
300 Hillside Avenue
Piedmont, CA 94611

San Ramon, CA 94583 (Sent via electronic mail to: goodhueproperty@aol.com) (Sent via electronic mail to: dcgoodhue@aol.com)

CMacleod@chevron.com)

Neil & Diane Goodhue Ms. Leslie Riasanovsky and Edward Plant 3rd, and Edward Plant 3rd, Homestead Savings

300 Hillside Avenue Trust and Trustees c/o FDIC

Piedmont, CA 94611 19 Mallorca Way Unknown Address

San Francisco, CA 94123 (Sent via electronic mail to:

tplant@edwardplantcompany.com)

San Francisco Foundation State Savings & Loan Association

Unknown Address Unknown Address

Subject: Notice of Responsibility, Fuel Leak Case RO0000138; Global ID # T0600102248; Chevron

#9-0517 / Homestead Federal Savings, 3900 Piedmont Avenue, Oakland CA 94610

Dear Ladies and Gentlemen:

In a *Notice of Requirement to Reimburse* dated October 2 1996, the Chevron USA Products Company (Chevron USA, Inc. / Chevron Environmental Management Company) and Homestead Federal Savings (Homestead Savings) were notified that the above referenced site had been placed in the Local Oversight Program and that they had been named as a Responsible Party for the fuel leak case. Additional parties have been named as Responsible Parties for the fuel leak case in the attached updated NOR as defined under 23 C.C.R Sec. 2720. Please see Attachment A – Responsible Parties Data Sheet, which identifies all Responsible Parties and provides background on the unauthorized release and Responsible Party Identification.

Should you have any questions, please contact me at (510) 567--6876 or send me an electronic mail message at mark.detterman@acgov.org.

Sincerely,

Mark E. Detterman, PG, CEG

Senior Hazardous Materials Specialist

Enclosures: Attachment 1 – Responsible Party (ies) Legal Requirements / Obligations

Electronic Report Upload (ftp) Instructions

Attachment A – Responsible Parties Data Sheet-Notice of Responsibility (NOR)

Ladies and Gentlemen RO00000138 May 2, 2016, Page 2

cc: Dilan Roe, ACDEH, (sent via electronic mail to dilan.roe@acgov.org)

Mark Detterman, ACDEH, (sent via electronic mail to mark.detterman@acgov.org)

Electronic File, GeoTracker



ENVIRONMENTAL HEALTH DEPARTMENT OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

AGENCY

REBECCA GEBHART, Acting Director

Certified Mail #: 7009 2820 0001 4359 9638

April 29, 2016

NOTICE OF RESPONSIBILITY

Site Name & Address:

CHEVRON #9-0517 / HOMESTEAD FEDERAL SAVINGS 3900 PIEDMONT AVENUE OAKLAND, CA 94610

Local ID:

RO0000138

Related ID:

NA

RWQCB ID:

NA

Global ID:

T0600102248

Responsible Party:

NEIL AND DIANE GOODHUE, EDWARD PLANT 3RD **TRUST AND TRUSTEES** 19 MALLORCA WAY SAN FRANCISCO, CA 94123

Date First Reported:

11/15/1993

Substance:

- 8006619 Gasoline-Automotive (motor gasoline and additives), leaded & unleaded
- 12034 Diesel fuel oil & additives (Nos. 1-D,
 - 2-D, 2-4)
- 12035 Waste Oil/Used Oil

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified NEIL AND DIANE GOODHUE AND EDWARD PLANT 3RD TRUST AND TRUSTEES as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your caseworker MARK DETTERMAN at this office at (510) 567-6876 If you have questions regarding your site.

RONALD BROWDER, Acting Director

Contract Project Director

Action: Update

Reason: ADD

Date:

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

April 29, 2016

Site Name & Address:

CHEVRON #9-0517 / HOMESTEAD FEDERAL SAVINGS 3900 PIEDMONT AVENUE OAKLAND, CA 94610 Local ID: RO0000138

Related ID: NA RWQCB ID: NA

Global ID: T0600102248

All Responsible Parties

RP has been named a Primary RP – CHEVRON USA, INC. C/O CHEVRON ENVIRONMENTAL MANAGEMENT CO. ATTN: MS. CARRYL MACLEOD

6101 BOLLINGER CANYON ROAD | SAN RAMON, CA 94583 | No Phone Number Listed

RP has been named a Primary RP - STATE SAVINGS & LOAN ASSOCIATION

ADDRESS UNKNOWN | No Phone Number Listed

RP has been named a Primary RP - SAN FRANCISCO FOUNDATION

ADDRESS UNKNOWN | | No Phone Number Listed

RP has been named a Primary RP – HOMESTEAD SAVINGS C/O FDIC

ATTN: LESLIE RIASANOVSKY

ADDRESS UNKOWN | | No Phone Number Listed

RP has been named a Primary RP - NEIL AND DIANE GOODHUE

300 HILLSIDE AVENUE | PIEDMONT, CA 94611 | No Phone Number Listed

RP has been named a Primary RP - NEIL AND DIANE GOODHUE, EDWARD PLANT 3RD

300 HILLSIDE AVENUE | PIEDMONT, CA 94611 | No Phone Number Listed

RP has been named a Primary RP - NEIL AND DIANE GOODHUE, EDWARD PLANT 3RD, TRUST AND TRUSTEES

ATTEN: EDWARD PLANT 3RD

19 MALLORCA WAY | SAN FRANCISCO, CA 94123 | No Phone Number Listed

April 29, 2016

Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

Existence of Unauthorized Release

In May 1993 a Phase I ESA was conducted and found that the site had been a former service station between at least 1940 and 1978. Upon station demolition and redevelopment as a banking institution in 1978 the Phase I reported that remaining USTs were removed.

In October 1993 eight soil bores (FNBO-1 to FNBO-8) were installed at the site to investigate the former service station and the former UST locations. Concentrations up to 350 milligrams per kilogram (mg/kg) Total Recoverable Petroleum Hydrocarbons (TRPH), 3,400 mg/kg Total Petroleum Hydrocarbons as gasoline (TPHg), <500 mg/kg TPH as diesel (TPHd), 1.0 mg/kg benzene, 5.0 mg/kg ethylbenzene, and other petroleum constituents were detected. These concentrations indicate than an unauthorized release had occurred at the site.

Responsible Party Identification

Chevron USA, Inc. purchased or received the site on March 1, 1976 from the previous owner, the Standard Oil of California. Chevron USA, Inc. is a responsible party for the site because it owned a UST used for the storage of a hazardous substance (Definition 1), owned or operated a UST immediately before the discontinuation of its use (Definition 2), owned the property associated with an unauthorized release (Definition 3), and had control over a UST at the time of or following an unauthorized release of a hazardous substance (Definition 4).

The State Savings & Loan Association purchased the property on February 20, 1979. The State Savings & Loan Association is a responsible party for the site because it owns the property associated with an unauthorized release (Definition 3).

The San Francisco Foundation purchased or received the property on February 20, 1979. The San Francisco Foundation is a responsible party for the site because it owns the property associated with an unauthorized release (Definition 3).

The Homestead Savings (c/o FDIC / Leslie Riasanovsky) purchased or received the property on March 26, 1982. The Homestead Savings c/o FDIC is a responsible party for the site because it owns the property associated with an unauthorized release (Definition 3).

Neil and Diane Goodhue purchased or received the property on March 28, 1997. Neil and Diane Goodhue are responsible parties for the site because it owns the property associated with an unauthorized release (Definition 3).



REBECCA GEBHART, Acting Director



ENVIRONMENTAL HEALTH DEPARTMENT OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Certified Mail #: 7009 2820 0001 4359 9645

April 29, 2016

NOTICE OF RESPONSIBILITY

Site Name & Address:

CHEVRON #9-0517 / HOMESTEAD FEDERAL SAVINGS 3900 PIEDMONT AVENUE OAKLAND, CA 94610

Local ID:

RO0000138

Related ID:

NA NA

RWQCB ID: Global ID:

T0600102248

Responsible Party:

NEIL AND DIANE GOODHUE, EDWARD PLANT 3RD 300 HILLSIDE AVENUE PIEDMONT, CA 94611

Date First Reported:

11/15/1993

Substance:

- 8006619 Gasoline-Automotive (motor gasoline and additives), leaded & unleaded
- 12034 Diesel fuel oil & additives (Nos. 1-D,
 - 2-D, 2-4)
- 12035 Waste Oil/Used Oil

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified NEIL AND DIANE GOODHUE AND EDWARD PLANT 3RD as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your caseworker MARK DETTERMAN at this office at (510) 567-6876 If you have questions regarding your site.

RONALD BROWDER, Acting Director Contract Project Director

C Date: 0429-7016

Action: Reason:

ADD

Update

Attachment A: Responsible Parties Data Sheet

cc: Cindy Davis, SWRCB (email: cindy.davis@waterboards.ca.gov) | Dilan Roe (email: dilan.roe@acgov.org), File

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

April 29, 2016

Site Name & Address:

CHEVRON #9-0517 / HOMESTEAD FEDERAL SAVINGS 3900 PIEDMONT AVENUE OAKLAND, CA 94610 Local ID:

RO0000138

Related ID:

: NA : NA

RWQCB ID: Global ID:

T0600102248

All Responsible Parties

RP has been named a Primary RP – CHEVRON USA, INC. C/O CHEVRON ENVIRONMENTAL MANAGEMENT CO. ATTN: MS. CARRYL MACLEOD

6101 BOLLINGER CANYON ROAD | SAN RAMON, CA 94583 | No Phone Number Listed

RP has been named a Primary RP - STATE SAVINGS & LOAN ASSOCIATION

ADDRESS UNKNOWN | | No Phone Number Listed

RP has been named a Primary RP - SAN FRANCISCO FOUNDATION

ADDRESS UNKNOWN| | No Phone Number Listed

RP has been named a Primary RP - HOMESTEAD SAVINGS C/O FDIC

ATTN: LESLIE RIASANOVSKY

ADDRESS UNKOWN | | No Phone Number Listed

RP has been named a Primary RP - NEIL AND DIANE GOODHUE

300 HILLSIDE AVENUE | PIEDMONT, CA 94611 | No Phone Number Listed

RP has been named a Primary RP - NEIL AND DIANE GOODHUE, EDWARD PLANT 3RD

300 HILLSIDE AVENUE | PIEDMONT, CA 94611 | No Phone Number Listed

RP has been named a Primary RP - NEIL AND DIANE GOODHUE, EDWARD PLANT 3RD, TRUST AND TRUSTEES

ATTEN: EDWARD PLANT 3RD

19 MALLORCA WAY | SAN FRANCISCO, CA 94123 | No Phone Number Listed

April 29, 2016

Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

Existence of Unauthorized Release

In May 1993 a Phase I ESA was conducted and found that the site had been a former service station between at least 1940 and 1978. Upon station demolition and redevelopment as a banking institution in 1978 the Phase I reported that remaining USTs were removed.

In October 1993 eight soil bores (FNBO-1 to FNBO-8) were installed at the site to investigate the former service station and the former UST locations. Concentrations up to 350 milligrams per kilogram (mg/kg) Total Recoverable Petroleum Hydrocarbons (TRPH), 3,400 mg/kg Total Petroleum Hydrocarbons as gasoline (TPHg), <500 mg/kg TPH as diesel (TPHd), 1.0 mg/kg benzene, 5.0 mg/kg ethylbenzene, and other petroleum constituents were detected. These concentrations indicate than an unauthorized release had occurred at the site.

Responsible Party Identification

Chevron USA, Inc. purchased or received the site on March 1, 1976 from the previous owner, the Standard Oil of California. Chevron USA, Inc. is a responsible party for the site because it owned a UST used for the storage of a hazardous substance (Definition 1), owned or operated a UST immediately before the discontinuation of its use (Definition 2), owned the property associated with an unauthorized release (Definition 3), and had control over a UST at the time of or following an unauthorized release of a hazardous substance (Definition 4).

The State Savings & Loan Association purchased the property on February 20, 1979. The State Savings & Loan Association is a responsible party for the site because it owns the property associated with an unauthorized release (Definition 3).

The San Francisco Foundation purchased or received the property on February 20, 1979. The San Francisco Foundation is a responsible party for the site because it owns the property associated with an unauthorized release (Definition 3).

The Homestead Savings (c/o FDIC / Leslie Riasanovsky) purchased or received the property on March 26, 1982. The Homestead Savings c/o FDIC is a responsible party for the site because it owns the property associated with an unauthorized release (Definition 3).

Neil and Diane Goodhue purchased or received the property on March 28, 1997. Neil and Diane Goodhue are responsible parties for the site because it owns the property associated with an unauthorized release (Definition 3).



REBECCA GEBHART, Acting Director



ENVIRONMENTAL HEALTH DEPARTMENT OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Certified Mail #: 7009 2820 0001 4359 9621

April 29, 2016

NOTICE OF RESPONSIBILITY

Site Name & Address:

CHEVRON #9-0517 / HOMESTEAD FEDERAL SAVINGS 3900 PIEDMONT AVENUE OAKLAND, CA 94610

RO0000138

Local ID: Related ID:

NA NA

RWQCB ID: Global ID:

T0600102248

Responsible Party:

NEIL AND DIANE GOODHUE 300 HILLSIDE AVENUE PIEDMONT, CA 94611

Date First Reported:

11/15/1993

Substance:

- 8006619 Gasoline-Automotive (motor gasoline and additives), leaded & unleaded
- 12034 Diesel fuel oil & additives (Nos. 1-D, 2-D, 2-4)
 - 12035 Waste Oil/Used Oil

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified NEIL AND DIANE GOODHUE as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your caseworker MARK DETTERMAN at this office at (510) 567-6876 If you have questions regarding your site.

RONALD BROWDER, Acting Director Contract Project Director

, Date: 04-29-7016

Action:

Update ADD

Reason:

Attachment A: Responsible Parties Data Sheet

cc: Cindy Davis, SWRCB (email: cindy.davis@waterboards.ca.gov) | Dilan Roe (email: dilan.roe@acgov.org), File

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

April 29, 2016

Site Name & Address:

CHEVRON #9-0517 / HOMESTEAD FEDERAL SAVINGS **3900 PIEDMONT AVENUE** OAKLAND, CA 94610

Local ID:

RO0000138

Related ID:

NA

RWQCB ID:

NA

Global ID:

T0600102248

All Responsible Pa	rties
--------------------	-------

RP has been named a Primary RP - CHEVRON USA, INC. C/O CHEVRON ENVIRONMENTAL MANAGEMENT CO. ATTN: MS. CARRYL MACLEOD 6101 BOLLINGER CANYON ROAD | SAN RAMON, CA 94583 | No Phone Number Listed RP has been named a Primary RP - STATE SAVINGS & LOAN ASSOCIATION ADDRESS UNKNOWN | No Phone Number Listed RP has been named a Primary RP - SAN FRANCISCO FOUNDATION ADDRESS UNKNOWN | No Phone Number Listed RP has been named a Primary RP - HOMESTEAD SAVINGS C/O FDIC ATTN: LESLIE RIASANOVSKY ADDRESS UNKOWN | | No Phone Number Listed RP has been named a Primary RP - NEIL AND DIANE GOODHUE 300 HILLSIDE AVENUE | PIEDMONT, CA 94611 | No Phone Number Listed RP has been named a Primary RP - NEIL AND DIANE GOODHUE, EDWARD PLANT 3RD 300 HILLSIDE AVENUE | PIEDMONT, CA 94611 | No Phone Number Listed RP has been named a Primary RP - NEIL AND DIANE GOODHUE, EDWARD PLANT 3RD, TRUST AND TRUSTEES ATTEN: EDWARD PLANT 3RD 19 MALLORCA WAY | SAN FRANCISCO, CA 94123 | No Phone Number Listed

April 29, 2016

Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

Existence of Unauthorized Release

In May 1993 a Phase I ESA was conducted and found that the site had been a former service station between at least 1940 and 1978. Upon station demolition and redevelopment as a banking institution in 1978 the Phase I reported that remaining USTs were removed.

In October 1993 eight soil bores (FNBO-1 to FNBO-8) were installed at the site to investigate the former service station and the former UST locations. Concentrations up to 350 milligrams per kilogram (mg/kg) Total Recoverable Petroleum Hydrocarbons (TRPH), 3,400 mg/kg Total Petroleum Hydrocarbons as gasoline (TPHg), <500 mg/kg TPH as diesel (TPHd), 1.0 mg/kg benzene, 5.0 mg/kg ethylbenzene, and other petroleum constituents were detected. These concentrations indicate than an unauthorized release had occurred at the site.

Responsible Party Identification

Chevron USA, Inc. purchased or received the site on March 1, 1976 from the previous owner, the Standard Oil of California. Chevron USA, Inc. is a responsible party for the site because it owned a UST used for the storage of a hazardous substance (Definition 1), owned or operated a UST immediately before the discontinuation of its use (Definition 2), owned the property associated with an unauthorized release (Definition 3), and had control over a UST at the time of or following an unauthorized release of a hazardous substance (Definition 4).

The State Savings & Loan Association purchased the property on February 20, 1979. The State Savings & Loan Association is a responsible party for the site because it owns the property associated with an unauthorized release (Definition 3).

The San Francisco Foundation purchased or received the property on February 20, 1979. The San Francisco Foundation is a responsible party for the site because it owns the property associated with an unauthorized release (Definition 3).

The Homestead Savings (c/o FDIC / Leslie Riasanovsky) purchased or received the property on March 26, 1982. The Homestead Savings c/o FDIC is a responsible party for the site because it owns the property associated with an unauthorized release (Definition 3).

Neil and Diane Goodhue purchased or received the property on March 28, 1997. Neil and Diane Goodhue are responsible parties for the site because it owns the property associated with an unauthorized release (Definition 3).



REBECCA GEBHART, Acting Director



ENVIRONMENTAL HEALTH DEPARTMENT OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Certified Mail #:

April 29, 2016

NOTICE OF RESPONSIBILITY

Site Name & Address:

CHEVRON #9-0517 / HOMESTEAD FEDERAL SAVINGS **3900 PIEDMONT AVENUE** OAKLAND, CA 94610

Local ID:

RO0000138

Related ID: **RWQCB ID:** NΑ NA

Global ID:

T0600102248

Responsible Party:

SAN FRANCISCO FOUNDATION **ADDRESS UNKNOWN**

Date First Reported:

11/15/1993

Substance:

- 8006619 Gasoline-Automotive (motor gasoline and additives), leaded & unleaded
- 12034 Diesel fuel oil & additives (Nos. 1-D,
 - 2-D, 2-4)
- 12035 Waste Oil/Used Oil

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified STATE SAVINGS & LOAN ASSOCIATION as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your caseworker MARK DETTERMAN at this office at (510) 567-6876 If you have questions regarding your site.

Date: 04-29-2016 RONALD BROWDER, Acting Director Contract Project Director

Action:

Reason:

ADD

Update

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

April 29, 2016

Site Name & Address:

CHEVRON #9-0517 / HOMESTEAD FEDERAL SAVINGS 3900 PIEDMONT AVENUE OAKLAND, CA 94610 Local ID: RO0000138

Related ID: NA RWQCB ID: NA

Global ID: T0600102248

All Responsible Parties

RP has been named a Primary RP – CHEVRON USA, INC. C/O CHEVRON ENVIRONMENTAL MANAGEMENT CO.

ATTN: MS. CARRYL MACLEOD

6101 BOLLINGER CANYON ROAD | SAN RAMON, CA 94583 | No Phone Number Listed

RP has been named a Primary RP - STATE SAVINGS & LOAN ASSOCIATION

ADDRESS UNKNOWN | No Phone Number Listed

RP has been named a Primary RP - SAN FRANCISCO FOUNDATION

ADDRESS UNKNOWN | No Phone Number Listed

RP has been named a Primary RP – HOMESTEAD SAVINGS C/O FDIC

ATTN: LESLIE RIASANOVSKY

ADDRESS UNKOWN | | No Phone Number Listed

RP has been named a Primary RP - NEIL AND DIANE GOODHUE

300 HILLSIDE AVENUE | PIEDMONT, CA 94611 | No Phone Number Listed

RP has been named a Primary RP – NEIL AND DIANE GOODHUE, EDWARD PLANT 3RD

300 HILLSIDE AVENUE | PIEDMONT, CA 94611 | No Phone Number Listed

RP has been named a Primary RP - NEIL AND DIANE GOODHUE, EDWARD PLANT 3^{RO}, TRUST AND TRUSTEES

ATTEN: EDWARD PLANT 3RD

19 MALLORCA WAY | SAN FRANCISCO, CA 94123 | No Phone Number Listed

April 29, 2016

Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

Existence of Unauthorized Release

In May 1993 a Phase I ESA was conducted and found that the site had been a former service station between at least 1940 and 1978. Upon station demolition and redevelopment as a banking institution in 1978 the Phase I reported that remaining USTs were removed.

In October 1993 eight soil bores (FNBO-1 to FNBO-8) were installed at the site to investigate the former service station and the former UST locations. Concentrations up to 350 milligrams per kilogram (mg/kg) Total Recoverable Petroleum Hydrocarbons (TRPH), 3,400 mg/kg Total Petroleum Hydrocarbons as gasoline (TPHg), <500 mg/kg TPH as diesel (TPHd), 1.0 mg/kg benzene, 5.0 mg/kg ethylbenzene, and other petroleum constituents were detected. These concentrations indicate than an unauthorized release had occurred at the site.

Responsible Party Identification

Chevron USA, Inc. purchased or received the site on March 1, 1976 from the previous owner, the Standard Oil of California. Chevron USA, Inc. is a responsible party for the site because it owned a UST used for the storage of a hazardous substance (Definition 1), owned or operated a UST immediately before the discontinuation of its use (Definition 2), owned the property associated with an unauthorized release (Definition 3), and had control over a UST at the time of or following an unauthorized release of a hazardous substance (Definition 4).

The State Savings & Loan Association purchased the property on February 20, 1979. The State Savings & Loan Association is a responsible party for the site because it owns the property associated with an unauthorized release (Definition 3).

The San Francisco Foundation purchased or received the property on February 20, 1979. The San Francisco Foundation is a responsible party for the site because it owns the property associated with an unauthorized release (Definition 3).

The Homestead Savings (c/o FDIC / Leslie Riasanovsky) purchased or received the property on March 26, 1982. The Homestead Savings c/o FDIC is a responsible party for the site because it owns the property associated with an unauthorized release (Definition 3).

Neil and Diane Goodhue purchased or received the property on March 28, 1997. Neil and Diane Goodhue are responsible parties for the site because it owns the property associated with an unauthorized release (Definition 3).



REBECCA GEBHART, Acting Director



ENVIRONMENTAL HEALTH DEPARTMENT OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Certified Mail #:

AGENCY

April 29, 2016

NOTICE OF RESPONSIBILITY

Site Name & Address:

CHEVRON #9-0517 / HOMESTEAD FEDERAL SAVINGS **3900 PIEDMONT AVENUE** OAKLAND, CA 94610

Local ID:

RO0000138

Related ID:

NA NA

RWQCB ID: Global ID:

T0600102248

Responsible Party:

STATE SAVINGS & LOAN ASSOCIATION ADDRESS UNKNOWN

Date First Reported:

11/15/1993

Substance:

- 8006619 Gasoline-Automotive (motor gasoline and additives), leaded & unleaded
- 12034 Diesel fuel oil & additives (Nos. 1-D,
 - 2-D, 2-4)
- 12035 Waste Oil/Used Oil

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified STATE SAVINGS & LOAN ASSOCIATION as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your caseworker MARK DETTERMAN at this office at (510) 567-6876 If you have questions regarding your site.

RONALD BROWDER, Acting Director Contract Project Director

Action:

Update

Reason:

ADD

Webate: 04-79-2016

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

April 29, 2016

Site Name & Address:

CHEVRON #9-0517 / HOMESTEAD FEDERAL SAVINGS 3900 PIEDMONT AVENUE OAKLAND, CA 94610

19 MALLORCA WAY | SAN FRANCISCO, CA 94123 | No Phone Number Listed

Local ID:

RO0000138

Related ID:

NA NA

RWQCB ID:

Global ID:

T0600102248

ΔII	Doc	nor	cibl	lo 0	arti	00
AII	Kes	nor	ISIDI	10 6	arti	29

RP has been named a Primary RP - CHEVRON USA, INC. C/O CHEVRON ENVIRONMENTAL MANAGEMENT CO. ATTN: MS. CARRYL MACLEOD 6101 BOLLINGER CANYON ROAD | SAN RAMON, CA 94583 | No Phone Number Listed RP has been named a Primary RP - STATE SAVINGS & LOAN ASSOCIATION ADDRESS UNKNOWN | No Phone Number Listed RP has been named a Primary RP - SAN FRANCISCO FOUNDATION ADDRESS UNKNOWN | No Phone Number Listed RP has been named a Primary RP - HOMESTEAD SAVINGS C/O FDIC ATTN: LESLIE RIASANOVSKY ADDRESS UNKOWN | | No Phone Number Listed RP has been named a Primary RP - NEIL AND DIANE GOODHUE 300 HILLSIDE AVENUE | PIEDMONT, CA 94611 | No Phone Number Listed RP has been named a Primary RP - NEIL AND DIANE GOODHUE, EDWARD PLANT 3RD 300 HILLSIDE AVENUE | PIEDMONT, CA 94611 | No Phone Number Listed RP has been named a Primary RP - NEIL AND DIANE GOODHUE, EDWARD PLANT 3RD, TRUST AND TRUSTEES ATTEN: EDWARD PLANT 3RD

April 29, 2016

Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

Existence of Unauthorized Release

In May 1993 a Phase I ESA was conducted and found that the site had been a former service station between at least 1940 and 1978. Upon station demolition and redevelopment as a banking institution in 1978 the Phase I reported that remaining USTs were removed.

In October 1993 eight soil bores (FNBO-1 to FNBO-8) were installed at the site to investigate the former service station and the former UST locations. Concentrations up to 350 milligrams per kilogram (mg/kg) Total Recoverable Petroleum Hydrocarbons (TRPH), 3,400 mg/kg Total Petroleum Hydrocarbons as gasoline (TPHg), <500 mg/kg TPH as diesel (TPHd), 1.0 mg/kg benzene, 5.0 mg/kg ethylbenzene, and other petroleum constituents were detected. These concentrations indicate than an unauthorized release had occurred at the site.

Responsible Party Identification

Chevron USA, Inc. purchased or received the site on March 1, 1976 from the previous owner, the Standard Oil of California. Chevron USA, Inc. is a responsible party for the site because it owned a UST used for the storage of a hazardous substance (Definition 1), owned or operated a UST immediately before the discontinuation of its use (Definition 2), owned the property associated with an unauthorized release (Definition 3), and had control over a UST at the time of or following an unauthorized release of a hazardous substance (Definition 4).

The State Savings & Loan Association purchased the property on February 20, 1979. The State Savings & Loan Association is a responsible party for the site because it owns the property associated with an unauthorized release (Definition 3).

The San Francisco Foundation purchased or received the property on February 20, 1979. The San Francisco Foundation is a responsible party for the site because it owns the property associated with an unauthorized release (Definition 3).

The Homestead Savings (c/o FDIC / Leslie Riasanovsky) purchased or received the property on March 26, 1982. The Homestead Savings c/o FDIC is a responsible party for the site because it owns the property associated with an unauthorized release (Definition 3).

Neil and Diane Goodhue purchased or received the property on March 28, 1997. Neil and Diane Goodhue are responsible parties for the site because it owns the property associated with an unauthorized release (Definition 3).