\$285 / Who!

FOURTH QUARTER GROUNDWATER SAMPLING
FOR THE PROPERTY
LOCATED AT 5175 BROADWAY STREET
OAKLAND, CALIFORNIA
JUNE 12, 1992


PREPARED FOR:
MR. MOHAMMAD MEHDIZADEH
150 RANDOM WAY
PLEASANT HILL, CALIFORNIA 94523

BY:

SOIL TECH ENGINEERING, INC.
298 BROKAW ROAD
SANTA CLARA, CALIFORNIA 95050

SOIL TECH ENGINEERING, INC.

TABLE OF CONTENTS	Page No.
LETTER OF TRANSMITTAL SITE DESCRIPTION AND BACKGROUND Tank Removal and Sampling CURRENT FIELD WORK LABORATORY ANALYSIS LABORATORY RESULTS	1-2 2 2-4 4-5 5
SUMMARY RECOMMENDATION SCHEDULE LIMITATIONS TABLE 1 - GROUNDWATER MONITORING DATA TABLE 2 - GROUNDWATER ANALYTICAL RESULTS APPENDIX "A"	6 6 7 7 8-9 10-11
Figure 1 - Vicinity Map Figure 2 - Site Plan	12 13
APPENDIX "B"	
Groundwater Sampling	SOP1
APPENDIX "C"	
Priority Environmental Labs Report and Chain-of-Custody	



SOIL TECH ENGINEERING

Soil, Foundation and Geological Engineers

298 BROKAW ROAD, SANTA CLARA, CA 95050 ■ (408) 496-0265 OR (408) 496-0266

June 12, 1992

File No. 8-90-420-GI

Mr. Mohammad Mehdizadeh 150 Random Way Pleasant Hill, California 94523

SUBJECT: FOURTH QUARTER GROUNDWATER SAMPLING FOR THE SITE

Located at 5175 Broadway Street, in

Oakland, California

Dear Mr. Mehdizadeh:

This report presents the results of the fourth quarterly groundwater sampling performed during June 2, 1992, by Soil Tech Engineering, Inc. (STE), at the subject site located at 5175 Broadway Street, in Oakland, California (Figure 1).

The scope of work for this sampling was to:

- 1) Measured depth-to-groundwater and liquid-hydrocarbon thickness (if present) in the five on-site wells.
- 2) Collect groundwater samples from the on-site wells for analyses of Total Petroleum Hydrocarbons as gasoline (TPHg) and Hydrocarbon constituents, Benzene, Toluene, Ethylbenzene and Total Xylenes (BTEX).

- 3) Updated the database for water level/liquid-hydrocarbon level measurements and groundwater data.
- 4) Review results and prepare a report of the investigation.

SITE DESCRIPTION AND BACKGROUND:

The site is located at 5175 Broadway Street, in Oakland, California. The area in the vicinity of the site consist of mainly a residential and light commercial (Figure 1).

TANK REMOVAL AND SAMPLING:

In January 1990, Tank Protect Engineering, Inc. (TPE), was retained to supervise the removal of underground fuel tanks and to conduct soil sampling, soil excavation, soil treatment and disposal. In addition, TPE installed three monitoring wells onsite.

Initial analytical results of soil samples taken after the tank removal showed moderate levels of Total Petroleum Hydrocarbons as Gasoline (TPHg) in two locations. The rest of the samples showed TPHg ranging from non-detected to less than 120 parts per million (ppm). Due to the presence of elevated levels of TPHg detected in the excavation, TPE installed three on-site monitoring wells (MW-1 to MW-3), as required by state and local regulatory

agencies (Figure 2). TPE's preliminary groundwater assessment also indicated that the shallow groundwater had been impacted.

The Alameda County Health Department (ACHD) requested the property owner to conduct further investigation in order to define the extent of dissolved hydrocarbon contamination in the groundwater.

Soil Tech Engineering, Inc. (STE), was retained in September 1990 to conduct monitoring and sampling of the on-site monitoring wells. The objective of the quarterly groundwater sampling program was to monitor seasonal and long-term variations in the conditions of the shallow aquifer beneath the site and to assess the direction of the groundwater flow for further investigation.

STE sampled the three on-site groundwater monitoring wells (MW-1 to MW-3) on September 26, 1990, and January 14, 1991. The sampling was conducted in accordance with ACHD and California Regional Water Quality Control Board (CRWQCB) guidelines and STE's Standard Operating Procedures (SOP) included in Appendix "B".

The three on-site wells contained moderate to high levels of dissolved hydrocarbons. A comparison of the September 1990 sampling with TPE's analytical results of April 1990 showed an increase in dissolved hydrocarbons in wells MW-1 and MW-2. In well MW-3 (the down-gradient well), TPHg and Toluene levels decreased, whereas Benzene, Ethylbenzene and Total Xylenes increased slightly.

The analytical results for groundwater samples collected on January 14, 1991, showed an increase in TPH and BTEX levels in well MW-2 from those reported in September 1990. Well MW-1 also showed a slight increase in TPH and Benzene, but showed a decrease in Toluene, Ethylbenzene and Xylene levels. Well MW-3 showed a substantial decrease in TPH and BTEX.

Per the request of the Alameda County Health Department (ACHD) in a letter dated March 29, 1991, STE installed two additional monitoring wells STMW-1 (STMW-4) and STMW-2 (STMW-5) on June 21, 1991. The July 3, 1991, water sampling results showed low levels of dissolved Total Petroleum Hydrocarbons as gasoline (TPHg) and Benzene, Toluene, Ethylbenzene and Xylenes (BTEX) in all five wells. The presence of low levels of TPHg and BTEX in the upgradient well, STMW-1 (STMW-4), (located in the east corner of the property) indicated a potential off-site source. Based on the water level data, the groundwater direction was west to southwest on July 3, 1991. The detail of this investigation is summarized in STE's report dated July 23, 1991.

The second quarterly sampling was conducted in November 1991. The detail of the sampling is described in STE's report dated November 22, 1991.

CURRENT FIELD WORK:

On June 2, 1992, the five on-site wells were monitored, purged and sampled in accordance with STE's Standard Operating Procedures

(SOP) (Appendix "B"), which follows state and local guidelines. During field observation, STE staff detected mild petroleum odors in wells MW-1, MW-2 and STMW-5. They also found very light petroleum sheen and very light to mild petroleum odors in wells MW-3 and STMW-4. After appropriate purging, no sheen was detected in the wells MW-3 and STMW-4. Table 1 summarizes the groundwater monitoring data.

Based on water elevation data, the groundwater flow direction was in southwest direction on June 2, 1992.

LABORATORY ANALYSIS:

The water samples were placed in a cool ice chest and submitted to GeoChem Labs, a state-certified laboratory, with a chain-of-custody record.

The samples were analyzed for Total Petroleum Hydrocarbons as gasoline (TPHg) per EPA Method 5030/8015 and for Benzene, Toluene, Ethylbenzene, and Total Xylenes (BTEX) per EPA Method 602.

LABORATORY RESULTS:

Table 2 summarizes the water samples results taken since May 17, 1990. Low to moderate levels of TPHg were detected in all five wells sampled during this quarter. The TPHg levels ranging from 1.8 parts per million (ppm) to 50 ppm. Low levels of BTEX were also found in all five wells.

SUMMARY:

The analytical results of groundwater samples collected in June 2, 1992 showed a slight increase in TPHg levels in wells MW-1, MW-2, STMW-4 and STMW-5 and decrease in TPHg and BTEX levels in well MW-3 compared to March 4, 1992. BTEX concentrations slightly increase in wells MW-1, MW-2, STMW-4 and STMW-5.

TPHg and BTEX levels appears to be increased due to residual soil contamination left in the ground. Recent results continue to detect dissolved hydrocarbon contamination on-site. It appears that the fluctuation of dissolved hydrocarbons in the wells may be due to seasonal effects, except the up-gradient well STMW-4 may be due to the possible off-site source.

RECOMMENDATIONS:

Since dissolved hydrocarbons continue to be present in the wells and some of the hydrocarbons constituent decreased and some have increased in the wells, STE recommends the continuation of the monitoring and sampling of the five wells for one more year. The proposed monitoring and sampling program should then be reevaluated following the fourth quarterly sampling.

A copy of this report should be sent to the Alameda County Health Department and the California Regional Water Quality Control Board.

File No. 8-90-420-GI

SCHEDULE:

The next monitoring and sampling of the wells will be scheduled in September 1992.

LIMITATIONS:

This report is issued with the understanding that it is the responsibility of the owner or his representative to ensure that the information and recommendations contained herein are called to the attention of the Local Environmental Agencies.

The findings of this report are based on the results of the independent laboratory analyses and are valid at the present date and conditions. However, changes in the conditions of a property can occur with the passage of time, whether they are due to natural processes or the works of man, on this property or adjacent properties.

If you have any questions or require additional information, please feel free to contact our office at your convenience.

Sincerely,

SOIL TECH ENGINEERING, INC.

LAWRENCE KOO, P. E.

C. E. #34928

NOORODDIN AMELI PROJECT ENGINEER

FRANK HAMEDI-FARD GENERAL MANAGER

TABLE 1 GROUNDWATER MONITORING DATA IN FEET

	Well Number	Water Depth*	Product Thickness	Petroleum Odor		
5/17/90**	MW-1	9.26	Not Available	Not Available		
	MW-2	10.00	Not Available	Not Available		
	MW-3	12.42	Not Available	Not Available		
9/26/90	MW-1	9.92	Not Present	Mild		
	MW-2	10.83	Not Present	Mild		
	MW-3	13.50	Not Present	Mild		
1/14/91	MW-1	9.54	Not Present	Mild		
	MW-2	10.63	Not Present	None		
	MW-3	12.58	Light Sheen	None		
7/03/91	MW-1	9.417	Not Present	Light		
	MW-2	10.083	Not Present	Light		
	MW-3	12.083	Sheen	Strong		
	STMW-1	11.00	Sheen	Mild		
	STMW-2	13.917	Not Present	None		
11/11/91	MW-1	9.45	Not Present	Mild		
	MW-2	10.21	Not Present	Mild		
	MW-3	12.29	Light Sheen	Mild		
	STMW-4***	11.08	Light Sheen	Strong		
	STMW-5***	14.00	Not Present	Light		

TABLE 1 CONT'D GROUNDWATER MONITORING DATA IN FEET

Date	Well Number	Water Depth*	Product Thickness	Petroleum Odor
3/04/92	MW-1	7.93	Not Present	Light
	MW-2	8.70	Not Present	Light
	MW-3	10.26	Dark Brown Sheen	Strong
	STMW-4	9.44	Brown Sheen	Mild
	STMW-5	11.80	Not Present	Very Light
6/02/92	MW-1	8.98	Not Present	Mild
	MW-2	9.52	Not Present	Mild
	MW-3	11.40	Light Sheen	Moderate
	STMW-4	10.32	Not Present	Very Light
-	STMW-5	13.06	Not Present	Mild

^{* =} Below Ground Surface

^{** =} Measured by TPE

*** = STMW-4 is the same well as STMW-1.

^{**** =} STMW-5 is the same well as STMW-2.

TABLE 2 GROUNDWATER ANALYTICAL RESULTS IN PARTS PER MILLION (ppm)

Date	Well Number	ТРНд	В	Т	E	x
4/30/89*	MW-1	0.2	0.018	0.005	0.002	0.012
	MW-2	0.23	0.039	0.018	0.005	0.023
	MW-3	56	3.6	8.6	1.3	7.2
9/26/90	MW-1	1.3	0.055	0.031	0.12	0.1
	MW-2	0.85	0.94	0.005	0.025	0.047
	MW-3	54	5.1	0.42	1.6	8.0
1/14/91	MW-1	1.7	0.057	0.028	0.042	0.053
	MW-2	3.1	0.35	0.083	0.086	0.13
	MW-3	35	2.6	6.6	1.5	5.7
7/03/91	MW-1	0.58	0.032	0.041	0.04	0.055
	MW-2	1.5	0.3	0.052	0.024	0.034
	MW-3	33	4.1	4.3	1.4	4.8
	STMW-1**	3.1	0.61	0.062	0.039	0.15
	STMW-2**	0.69	0.099	0.081	0.019	0.098
11/11/91	MW-1	0.33	0.02	0.002	0.002	0.011
<u> </u>	MW-2	0.96	0.32	0.015	0.004	0.029
	MW-3	57	3.9	8.4	2.1	14
	STMW-4***	3.6	0.99	0.025	0.003	0.18
	STMW-5****	0.41	0.061	0.002	0.001	0.02

TABLE 2 CONT'D GROUNDWATER ANALYTICAL RESULTS IN PARTS PER MILLION (PPM)


Date	Well Number	ТРНд	В	T	E	х
3/04/92	MW-1	0.81	0.011	0.0051	0.0097	0.023
	MW-2	1.5	0.0095	0.0084	0.0098	0.022
	MW-3	57	0.72	0.87	0.81	3.1
	STMW-4***	5.0	0.035	0.02	0.022	0.071
	STMW-5****	0.46	0.013	0.0065	0.011	0.018
6/02/92	MW-1	2.2	0.093	0.032	0.04	0.12
	MW-2	2.8	0.084	0.041	0.059	0.095
	MW-3	50	0.24	0.24	0.22	0.74
	STMW-4***	13	0.14	0.045	0.063	0.21
	STMW-5***	1.86	0.027	0.02	0.021	0.043

TPHg = Total Petroleum Hydrocarbons as gasoline

BTEX = Benzene, Toluene, Ethylbenzene, Xylenes
* = Analytical Results from TPE Site Assessment

** = Soil Tech Engineering, Inc., Monitoring Wells


*** = STMW-4 is the same well as STMW-1.
**** = STMW-5 is the same well as STMW-2.





Thomas Brothers Map 1982 Edition Alameda - Contra Costa Counties

Page 4 D6



LEGEND

C. EL. Casing Elevation

W. EL. Water Elevation

• Monitoring Well

5175)	BROADWAY STREET, OAKLAND, CALI	FORNIA
SCALE: 1"=20'		FIGURE 2
DRAWN BY N.A.	PROJECT NO. 8-90-420-GI	6/01/92

GROUNDWATER SAMPLING

Prior to collection of groundwater samples, all of the sampling equipment (i.e. bailer, cables, bladder pump, discharge lines and etc...) was cleaned by pumping TSP water solution followed by distilled water.

Prior to purging, the well "Water Sampling Field Survey Forms" were filled out (depth to water and total depth of water column were measured and recorded). The well was then bailed or pumped to remove four to ten well volumes or until the discharged water temperature, conductivity and pH stabilized. "Stabilized" is defined as three consecutive readings within 15% of one another.

The groundwater sample was collected when the water level in the well recovered to 80% of its static level.

Forty milliliter (ml.), glass volatile organic analysis (VOA) vials with Teflon septa were used as sample containers. The groundwater sample was decanted into each VOA vial in such a manner that there was a meniscus at the top. The cap was quickly placed over the top of the vial and securely tightened. The VOA vial was then inverted and tapped to see if air bubbles were present. If none were present, the sample was labeled and refrigerated for delivery under chain-of-custody to the laboratory. The label information would include a sample identification number, job identification number, date, time, type of analysis requested, and the sampler's name.



PRIORITY ENVIRONMENTAL LABS

Precision Environmental Analytical Laboratory

June 04, 1992

PEL # 920604

SOIL TECH ENGINEERING

Noori Ameli

Re: Five water samples for Gasoline/BTEX analysis.

Project name: 5175 Broadway St.-Oakland

Project number: 8-90-420-GI

Date sampled: June 02, 1992 Date extracted: June 03,1992

Date submitted: June 02, 1992

Date analyzed: June 03,1992

RESULTS:

SAMPLE I.D.	Gasoline (ug/L)	Benzene (ug/L)	Toluene (ug/L)	Ethyl Benzene (ug/L)	Total Xylenes (ug/L)
	(3	(/	(-9/-/	(-9/~/	(-5/~/
MW-1 MW-2	2200	93	32	40	120
MW-3	2800 50000	84 240	41 240	59 220	95 740
STMW-4	13000	140	45	220 63	210
STMW-5	1800	27	20	21	43
511111 5	1000	41	20	21	4.5
Blank	N.D.	N.D.	N.D.	N.D.	N.D.
Spiked Recovery	92.2%	89.8%	87.4%	83.2%	90.5%
Duplicate Spiked Recovery	94.1%	95.3%	100.6%	97.8%	103.1%
Detection limit	50	0.5	0.5	0.5	0.5
Method of Analysis	5030 / 8015	602	602	602	602

David Duong Laboratory Director

1764 Houret Court Milpitas, CA. 95035

Tel: 408-946-9636

Fax: 408-946-9663

								CHAI	N OF CU	STO	DYR	ECO	RD			PRO.EN					
L	0-G[2 2	V CO	adwi	ay S	3t.	OAKLAND			A A CONTRACTOR OF THE SECOND S			T./	//	//./	/				
SAMPLER				,							5 3	% \$	γ,	/.	/ /	///					
<i>N</i>	·Am	سيان		α .					CON-	(2)		6/				//			REA	MARKS	
NO.	DATE	TIME	So!L	Warek			LO	CATION	TAINER		72/			/.							,
j	42/92	1330		/	-,		<u>un -</u>	-1	2	V						·					
		141		/			WW -	-2	2	٢	1										
_3	42/92	14		1	·		MW-	-3	2	<u> </u> -	1										
	4492	13 -				<u>57</u>	NW.	-4	2			_		L							
5 \$	12/92	13 ²		-/		ST	MW-	- 5	2	1		<u></u>									
			_		<u> </u>																
			\downarrow		 .					_									<u> </u>		-
				_														. <u>.</u>			
— - -			\dashv																		
								 .		<u> </u>											
			-							<u> </u>				$-\downarrow$	_				 		
	-			-				···		ļ				_					·		·
												\dashv									_
elinquished	by: (Sia)	natural I		- 	Date	/ Time	Receid	ed by (Signature)	-	D-U						 					
NA		_		6/2	,	5 <u>5</u> 14	116	Today		i veili	nquish	α ογ:	(รเฐก	eture)		Da	ite ,	/Time	Receive	by: (Signatu	re)
elinquished	by: (Sign	nature)			Date /	Time	Receive	ed by: (Signature)	JE-	Relin	quishe	d by:	(Signa	turej		Da	te /	Time	Received	i by: (Signatur	·e)
elinquished	by: (Sign	ature)			Date /	Time	ļ	d for Laboratory	1	6/2	10ate 2/92	Time	14	Ren	narks			<u> </u>	1		
	-			-						•	•			[·			



SOIL TECH ENGINEERING

Soil, Foundation and Geological Engineers

								CHAIN	OF CUS			_	_					TY		9	
PROJ. 1	NO.	5175	NA C	ME	adwa	<u></u> у S	t.	OAKLAND		A May	4	(2) G/		/./	/ /					920604	
						J			· .		26	1/	7			//	1	IN	IV #	22840	
SAMPLER	RS: (Signa	ture)								1 8	* 51/		/	/· /	/ /		/:				
1	An	<u>eli</u>							CON-	6	9	9/					•		REM.	ARKS	
NO.	DATE	TIME	Soll.	Water			LO	CATION	TAINER	1		_	_	<u>/</u>	_	_					·
í	42/92	اد <u>3</u> 13		/		Λ	- W	-1	2	1											
	42/92		-	1			w -		2	1											
2	1476	45		/					2		-	-			_						
	42/92	14-		-	<u> </u>	-	<u> </u>			/	-										
4	4492	13					WV -		2	1											
5	12/92	132		'رز		STI	<u> </u>	- 5	2												
										<u> </u>											
																					
	-																				
					<u>.</u>			· · · · · · · · · · · · · · · · · · ·				_					 				<u></u>
											_										
İ													_	_							
																			·		
Relinquishe	d by: (Si	gnatures		6/	Date /	Time 5 <u>5</u> 14	116	Ped py: 15ignaturel		Relin	quish	d by:	(Sigi	isture.) 		Date / 1	îme -	Receive	by: (Signatura)	
Relinquishe	d bγ: <i>(s)</i>	gnature)			Date /		Receiv	red by: (Signature)	J&	Relino	puistie	đ by:	(Sign	ature)			Date / T	ime	Received	by: (Signature)	
Relinquishe	d by: (Sig	gnature)			Date /	Time		red for Laboratory investory L		6/2	Date /92	/Time		Ret	marks						



SOIL TECH ENGINEERING Soil, Foundation and Geological Engineers

								CHAI	N OF CU	STO	DYR	ECO	RD			PRO.EN					
L	0-G[2 2	V CO	adwi	ay S	3t.	OAKLAND			A A CONTRACTOR OF THE SECOND S			T./	//	//./	/				
SAMPLER				,							5 3	% \$	γ,	/.	/ /	///					
<i>N</i>	·Am	سيان		α .					CON-	(2)		6/				//			REA	MARKS	
NO.	DATE	TIME	So!L	Warek			LO	CATION	TAINER		72/			/.							,
j	42/92	1330		/	-,		<u>un -</u>	-1	2	V						·					
		141		/			WW -	-2	2	٢	1										
_3	42/92	14		1	·		MW-	-3	2	<u> </u> -	1										
	4492	13 -				<u>57</u>	NW.	-4	2			_		L							
5 \$	12/92	13 ²		-/		ST	MW-	- 5	2	1		<u></u>									
			_		<u> </u>																
			\downarrow		 .					_									<u> </u>		-
				_														. <u>.</u>			
— - -			\dashv																		
								 .		<u> </u>											
			-							<u> </u>				$-\downarrow$	_				 		
	-			-				···		ļ				_					·		·
												\dashv									_
elinquished	by: (Sia)	natural I		- 	Date	/ Time	Receid	ed by (Signature)	-	D-U						 					
NA		_		6/2	,	5 <u>5</u> 14	116	Today		i veili	nquish	α ογ:	(รเฐก	eture)		Da	ite ,	/Time	Receive	by: (Signatu	re)
elinquished	by: (Sign	nature)			Date /	Time	Receive	ed by: (Signature)	JE-	Relin	quishe	d by:	(Signa	turej		Da	te /	Time	Received	i by: (Signatur	·e)
elinquished	by: (Sign	ature)			Date /	Time	ļ	d for Laboratory	1	6/2	10ate 2/92	Time	15	Ren	narks			<u> </u>	1		
	-			-						•	•			[·			



SOIL TECH ENGINEERING

Soil, Foundation and Geological Engineers

								CHAIN	OF CUS			_	_					TY		9	
PROJ. 1	NO.	5175	NA C	ME	adwa	<u></u> у S	t.	OAKLAND		A May	4	(2) G/		/./	/ /					920604	
						J			· .		26	1/	7			//	1	IN	IV #	22840	
SAMPLER	RS: (Signa	ture)								1 8	* 51/		/	/· /	/ /		/:				
1	An	<u>eli</u>							CON-	6	\mathscr{Y}_{ζ}	9/					•		REM.	ARKS	
NO.	DATE	TIME	Soll.	Water			LO	CATION	TAINER	1		_	_	<u>/</u>	_	_					·
í	42/92	اد <u>3</u> 13		/		Λ	- W	-1	2	1											
	42/92		-	1			w -		2	1											
2	1476	45		/					2		-	-			_						
	42/92	14-		-	<u> </u>	-	<u> </u>			/	-										
4	4492	13					WV -		2	1											
5	12/92	132		'رز		STI	<u> </u>	- 5	2												
										<u> </u>											
																					
	-																				
					<u>.</u>			· · · · · · · · · · · · · · · · · · ·				_					 				<u></u>
											_										
İ													_	_							
																			·		
Relinquishe	d by: (Si	gnatures		6/	Date /	Time 5 <u>5</u> 14	116	Ped py: 15ignaturel		Relin	quish	d by:	(Sigi	isture.	,		Date / 1	îme -	Receive	by: (Signatura)	
Relinquishe	d bγ: <i>(s)</i>	gnature)			Date /		Receiv	red by: (Signature)	J&	Relino	puistie	đ by:	(Sign	ature)			Date / T	ime	Received	by: (Signature)	
Relinquishe	d by: (Sig	gnature)			Date /	Time		red for Laboratory investory L		6/2	Date /92	/Time		Ret	marks						



SOIL TECH ENGINEERING Soil, Foundation and Geological Engineers