ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY



DAVID J. KEARS, Agency Director

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

July 24, 2009

BILL COX
BILL COX CADILLAC
UNKNOWN
UNKNOWN

H W SHEPARD JR WELLS FARGO BANK TRUST 230 BAY PL OAKLAND CA 94612-3805 R B D L SHEPARD TRUSTS GREATER BAY TRUST COMPANY TRUSTEE 333 MARRKET ST #2300 San Francisco CA 94105

ROBERT BOND BOND CC OAKLAND LLC 350 WEST HUBBARD ST STE #450 CHICAGO IL 60610 ARNOLD BROWN KESTREL PARTNERS LLC 4457 WILLOW RD STE #102 PLEASANTON CA 94588-8554 STEPHEN WILSON 230 BAY PLACE LP 400 RACE ST STE #200 SAN JOSE CA 95126

Subject: Fuel Leak Case No. RO0000148 and Geotracker Global ID T0600100193, BILL COX CADILLAC & BUICK, 230 BAY PL, Oakland CA 94612 – Groundwater Monitoring Requirements

Dear Responsible Party(ies):

The purpose of this correspondence is to inform you of changes to groundwater monitoring requirements for all fuel leak cases in California. The California State Water Resources Control Board (State Water Board) has approved Resolution No. 2009-0042 (Actions to Improve Administration of the UST Cleanup Fund and UST Cleanup Program). Resolution No. 2009-0042 states that, "Regional Water Board and LOP agencies shall reduce quarterly groundwater monitoring requirements to semiannual or less frequent monitoring at all site unless site-specific needs warrant otherwise and shall notify all responsible parties of the new requirements no later than August 1, 2009. If more than semiannual monitoring is required for a case, the responsible party and State Water board shall be notified of the rationale and the notice shall be posted on Geotracker."

In accordance with Resolution No. 2009-0042, groundwater monitoring for your site is to be reduced from quarterly to semiannual monitoring unless site-specific needs warrant otherwise. The semiannual monitoring is to be conducted during either the first and third quarters or during the second and fourth quarters. Please review historic groundwater monitoring results and identify the quarter during which the highest chemical concentrations typically occur in order to select the appropriate semiannual monitoring schedule. As an example, if the highest chemical concentrations in groundwater are typically reported during the first quarter, the wells should be sampled on a first and third quarter monitoring schedule.

A semiannual groundwater monitoring should be used only for wells that have been sampled over a minimum of one hydrologic cycle (four consecutive quarters). New monitoring wells should be sampled quarterly for one year before a semiannual monitoring schedule is implemented for new wells.

Any groundwater monitoring wells that are currently sampled on a less frequent schedule than semiannual (annual or longer) may continue to be sampled on the less frequent schedule. Please present results from the semiannual groundwater monitoring in groundwater monitoring reports no later than 60 days following the groundwater sampling event.

Responsible Party(ies) RO0000148, July 24, 2009, Page 2

If you have any questions, please call me at (510) 777-2478 or send me an electronic mail message at paresh.khatri@acgov.org.

Sincerely,

Paresh C. Khatri

Hazardous Materials Specialist

Enclosure: ACEH Electronic Report Upload (ftp) Instructions

cc: Charles Pardini, LFR, 1800 Powell Street, 12th Floor, Emeryville, CA 94608-1814 Leroy Griffin, Oakland Fire Department, 250 Frank H. Ogawa Plaza, Ste. 3341, Oakland, CA 94612-2032 (Sent via E-mail to: <u>lgriffin@oaklandnet.com</u>)

Donna Drogos, ACEH (Sent via E-mail to: donna.drogos@acgov.org)
Paresh Khatri, ACEH (Sent via E-mail to: paresh.khatri@acgov.org)
Geotracker, File

RESPONSIBLE PARTY OF RECORD AS OF 07/22/2009

RO0000148, BILL COX CADILLAC & BUICK, 230 BAY PL , Oakland, CA, 94612

Alameda County Environmental Health (ACEH) has the following information on record regarding the Responsible Party(ies) for the above referenced site. Please update the following information for our records. Should you have contact information regarding additional Responsible Parties, please correct the information accordingly. Also, please check the "e-mail preferred" box to receive all future correspondences and notifications by e-mail.

Current Information	Corrections or Additions	
BILL COX	Name:	
ILL COX CADILLAC	Company:	
INE ST	Address:	
SAN FRANCISCO CA 94111	City:State:Zip:	
	E-mail:	
	Home Phone: ()	
	Office Phone: ()	
	Cell Phone: ()	
I W SHEPARD JR	Name:	
WELLS FARGO BANK TRUST	Name: Company:	
230 BAY PL	Address:	
30 BAI FL DAKLAND CA 946123805	Address: State: Zip:	
MILENIO CA STOLESCOS	F-mail:	
	Home Phone: ()	
	Office Phone: ()	
	Cell Phone: ()	
R B D L SHEPARD TRUSTS	Name:	
GREATER BAY TRUST COMPANY TRUSTEE	Company:	
333 MARRKET ST #2300	Address:	
San Francisco CA 94105	City:State:Zip	:
	E-mail:	
	Home Phone: ()	
	Omce Phone: ()	
	Cell Phone: ()	
ROBERT BOND	Name:	
BOND CC OAKLAND LLC	Company:	
350 WEST HUBBARD ST STE #450	Address:	
CHICAGO IL 60610	City: State: Zip):
	E-mail:	
	Home Phone: ()	
	Office Phone: ()	
	Cell Phone: ()	

RESPONSIBLE PARTY OF RECORD AS OF 07/22/2009

ARNOLD BROWN	Name:
KESTREL PARTNERS LLC	Company:
4457 WILLOW RD STE #102	Address:
PLEASANTON CA 945888554	City: State: Zip:
	E-mail:
	Home Phone: ()
	Office Phone: ()
	Cell Phone: ()
STEPHEN WILSON	Name:
230 BAY PLACE LP	Company:
400 RACE ST STE #200	Address:
SAN JOSE CA 95126	City: State: Zip:
	E-mail:
	Home Phone: ()
	Office Phone: ()
	Cell Phone: ()