


5812 HOLLYS ST
EMERVILLE UST REMOVAL

8/4/2010
SP

UST being removed



UST REMOVAL



SPT Contaminated soil ~ 10ft bgs

UST Removal Preparation

Corrossion Hole 1ft x 1ft



5812 WOLLS ST
EMERYVILLE UST REMOVAL

8/4/2010
SP



Golden Gate Tank Removal Soil Sampling ↑



Corrossion Hole in UST 2ft by 1ft



UST exterior cleaning

Soil Removal \approx 10ft bys



5812 WOLLIS ST
EMERYVILLE USE REMOVAL

8/4/2010



Soil Removal \uparrow \approx 11ft bys



Over-excavation Soil Stockpile



GGT Soil Sampling