Shell Oil Company



EAST BAY MARKETING DISTRICT

P.O. Box 4023 Concord, CA 94524 (415) 676-1414

February 28, 1989

Mr. Ariu Levi Alameda County Department of Environmental Health Hazardous Materials Division 80 Swan Way, Suite #200 Oakland, CA 94621

Dear Mr. Levi:

RE: SOIL SAMPLING RESULTS SHELL STATION 630 HIGH STREET OAKLAND, CA

This letter is in response to your requirements regarding soil sampling at the above Shell station.

Attached find copies of soil sampling reports prepared by Blaine Tech Services Inc. dated February 10, 1989, February 13, 1989 and February 16, 1989 and analytical results by Mobile Chem Labs Inc.

Shell has contracted with a geological firm to prepare a complete environmental assessment report for site remediation.

A copy of the report will be submitted for your review.

If you have any questions or require additional information, call me on (415) 676-1414, Ext. 128.

Very truly yours,


R. G. Newsome

Sr. District Engineer

Attachments

cc: Kurt Feazel
Larry Adams
Darrell Robinson
Stan Roller
Environmental Files

cc + Attach: Water Quality Control Board, San Francisco Bay Region



BLAINE TECH SERVICES INC.

1370 TULLY RD., SUITE 505 SAN JOSE, CA 95122 (408) 995-5535

February 10, 1989

Shell Oil Company P.O. Box 4023 Concord, CA 94524

Attention: Ray Newsome

SITE: Shell Oil 630 High Street Oakland, California

PROJECT:
Sampling of product line and dispenser pump islands

SAMPLED ON: January 26, 1989

SAMPLING REPORT 89026-C-1

OBJECTIVE SERVICES

Blaine Tech Services, Inc. performs specialized environmental sampling and documentation as an independent third party. In order to avoid compromising the objectivity necessary for the proper and disinterested performance of this work, Blaine Tech Services, Inc. does not participate in the interpretation of analytical results or become involved with the marketing or installation of remedial systems. The interpretation of results should be performed by representatives of interested regulatory agencies and/or those professionals who are engaged as paid consultants in the business of providing opinions and proposals for further investigation or clean-up activities.

This report describes the initial environmental sampling and documentation performed by our firm on this project. In addition to the text of the Sampling Report, supporting documents are provided as attachments. These include the chain of custody and the certified analytical laboratory report. All of these documents should be kept together and preserved as a file of interrelated records which, together, comprise the documentation of the work performed at the site.

Scope of Requested Services

In accordance with your request, field personnel would be dispatched to the site to collect soil samples from beneath a product line trench and three product dispensing pump islands. In addition, we were to arrange for the proper analyses of the samples, and maintain adequate documentation resulting in the issuance of a formal Sampling Report. The collection of environmental samples was to be performed in accordance with the requirements of the State Water Resources Control Board and the specific directions of the Local Implementing Agency (LIA) inspector present at the site at the time of sampling.

Execution of the Work

The subject site is located within the overall jurisdiction of the Regional Water Quality Control Board -- San Francisco Bay Region. Initial inspection and evaluation of the site is customarily conducted by the local implementing agency (LIA), which was the Alameda County Health Department. The local implementing agency was represented by Mr. Ariu Levi, who was present to observe the sampling.

Personnel were dispatched from our office and arrived at the subject site on Thursday, January 26, 1989. Our field personnel found that, prior to our arrival, Armer/Norman and Associates had dismantled and removed all fuel dispensing facilities, and had excavated three locations on the site from which samples were to be taken: Area 1 consisting of the three product dispener pump islands, and the product line connecting these islands to the underground gasoline storage tanks; Area 2, which consisted of two product dispensing pump islands which had been used by a service station that occupied the eastern portion of the property prior to the present Shell Oil facility; and Area 3, which was not directly connected with any known product lines or fuel dispensing facilities, but smelled of gasoline.

In Area 1, three samples (Samples #9, #10, and #11) were obtained from the main product line trench adjacent to the ends of each of the three dispenser pump islands. These samples were obtained from depths ranging between one and a half to two and three quarters feet (1.5'-2.75') below grade level. Two samples (Samples #5 and #6) were obtained from beneath the eastern island at one to one and one-quarter feet (1'-1.25') below grade, beneath the middle pump island (Sample #4) at two feet (2') below grade and beneath the western pump island (Samples #2 and #3) at two feet (2') below grade. One sample (Sample #1) was taken at a depth of two feet (2') below grade from an area to the west of the western pump island that smelled of gasoline.

Area 2 consists of two dispenser pump islands that had previously been associated with another gasoline service station that occupied the eastern portion of the site prior to the present Shell Oil facility. At some time in the past, these islands had been abandoned and paved over. One sample (Sample #7) was obtained from beneath the western island at one and a half feet (1.5') below grade, and one sample (Sample #8) from beneath the eastern island at one foot (1.0') below grade.

Area 3 consisted of a small patch of ground that smelled of gasoline. One sample (Sample #12) from this area was obtained at two and three quarters feet (2.75') below grade.

The three sampling areas were located in a portion of the property between Oakport Street and the underground storage tanks where approximately one foot (1') of asphalt paving and underlying base rock material had been removed. The sampling depths given in this Sampling Report were measured from the surface of the soil in this exposed area.

The sample locations were chosen by Mr. Ariu Levi of the Alameda County Health Department. The samples were obtained through the use of a hand driven soil core sampler. The location of individual sampling points is shown on the diagram on page four. Additional information on the exact method of sample collection will be found in the Sampling Methodology section of this report.

After completion of the field work, the sample containers were delivered to Sequoia Analytical Laboratory in Redwood City, California. Sequoia Analytical Laboratory is a California Department of Health Services certified Hazardous Materials Testing Laboratory and is listed as DOHS HMTL #145.

It was requested that the analytical procedures used for these analyses be those specified by the Regional Water Quality Control Board -- San Francisco Bay Region. The methods are defined in attachments to the San Francisco RWQCB (Region 2) publication, <u>Guidelines For Addressing Fuel Leaks</u> and in documents issued to clarify the Board's interpretation of the <u>California LUFT Manual</u>.

PAGE 4

The certified analytical report should also be reviewed when samples are taken from below waste oil tanks as <u>any</u> detection of the EPA halogenated and purgeable aromatic compounds may be grounds for requiring further action. Also the TABLE OF SAMPLING LOCATIONS AND ANALYTICAL RESULTS is insufficiently spacious to allow anything more that a simple listing of the detected compounds. The TABLE does not include such information as the detection limits at which other compounds were not detected. The full text of the laboratory report will be found in Section Four of this report.

REPORTAGE

Submission to the Regional Water Quality Control Board and the local implementing agency should include copies of the sampling report, the chain of custody, and the certified analytical report issued by the Hazardous Materials Testing Laboratory. The property owner should attach a cover letter and submit all documents together in a package.

The following addresses have been listed here for your convenience:

Water Quality Control Board San Francisco Bay Region 1111 Jackson Street Room 6040 Oakland, CA 94607 ATTN: Greg Zentner

Alameda County Health Hazardous Materials Management 420 27th Street Oakland, CA 94612 ATTN: Ariu Levi

Please call if we can be of any further assistance.

-Richard C. Blaine

RCB/dmp

attachments: supporting documents

BLAINE TECH SERVICES INC.

1370 TU SAN JO

-	CHAIN OF 89026cl
-	SITE SPECIFICATION Shell Oil
	1.20 11 1 Cl +

JLLY ROAD, SUITE 505 ISE, CA 95122	630 High Street
95-5535	Oakland, CA

nor ccor				·	<u> </u>		
(408) 995-5535			<u>Oa</u>	Klan:	1, CA		
Bill BLA	INE TECH	SERVICES,	Inc. SP		•	TRUC L lead	TIONS
SAMPLE I.D.	QUANTITY	турв ок	ANALYSIS TO	DETECT	STATUS	RESULTS	LAB NUMBER
<u>i</u>	1	50,1	TPH(qua),	BTYE	48 m.		
2	1	M	4	(f		_	
3	ı	ft	4	14			
4	1		ч	12			
5	1		ц	ч			
6	1	11	11	4			
7	1	<u>u</u>	TPH(yes)	BIXE MAG	underd		
8	i	11	· · · · · · · · · · · · · · · · · · ·	4	τ.		
9		Lt .	TRH jas)	BIXE			
1Û		15	- d	h			
{1i		lı.	"	14			
17_			1	ħ			
Field sampli	ng A	tephony	! Carta	Same	oling was	: <u>30</u> am/74	
		OM (namy, ti	me,date)	>>>> INI	THE CHET	OV OF (na	ame, time, date
from	<u> </u>	:AM/FP	,				-8: -1/PH8:
from		:AM/I*	88 -	> to		A:AI	4/FH8

The laboratory designated to perform these analyses is: Significance. DIS HATE # 145 NOTE: Procedures and detection limits must confrom to RACE/Region Z. specifications. Please include chain of custody number and site specification on reports and invoices.

Blaine Tech Services 1370 Tully Rd., Suite 505 San Jose, CA 95122

Client Project ID: Matrix Descript: BTS #89026C1, Shell, Oakland Soil Sampled: Received: Jan 26, 1989 Jan 27, 1989

San Jose, CA 95122 Analy Attention: Richard Blaine First

Analysis Method: First Sample #:

EPA 5030 or 3810/8015/8020 901-2762 Analyzed: Reported:

Jan 31, 1989 Feb 2, 1989

TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)	
901-2762	1	70	2.5	0.2	0.25	0.33	
901-2763	2	690	N.D.	0.34	16	31	
901-2764	3	2,400	2.8	4.4	17	140	
901-2765	4	2.9	N.D.	N.D.	N.D.	0.18	
901-2766	5	620	7.0	22	9.4	38	
901-2767	6	5.8	N.D.	N.D.	0.17	0.11	
901-2768	7	24	0.21	0.17	0.37	1.1	
901-2769	8	3.3	0.2	N.D.	N.D.	0.17	
901-2770	9	38	0.088	N.D.	0.74	1.2	
901-2771	10	1.7	N.D.	N.D.	N.D.	0.1	
Detection Limits	s:	1.0	0.05	0.1	0.1	0.1	

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Arthur G. Burton Laboratory Director

9012762.BLA <1>

Blaine Tech Services 1370 Tully Rd., Suite 505 San Jose, CA 95122

Client Project ID: Matrix Descript:

BTS #89026C1, Shell, Oakland Soil

Sampled: Received: Jan 26, 1989 Jan 27, 1989

Attention: Richard Blaine

Analysis Method: First Sample #:

EPA 5030 or 3810/8015/8020 901-2772

Analyzed: Reported: Jan 31, 1989 Feb 2, 1989

TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)
901-2772	11	1.2	N.D.	N.D.	N.D.	0.11
901-2773	12	460	N.D.	0.63	0.69	2.5

Detection Limits:	1.0	0.05	0.1	0.1	0.1	

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Arthur G. Burton **Laboratory Director** Blaine Tech Services 1370 Tully Rd., Suite 505 San Jose, CA 95122 Attention: Richard Blaine Client Project ID: Sample Descript: Analysis Method:

First Sample #:

BTS #89026C1, Shell, Oakland Soil

California LUFT Manual, 12/87 901-2768 Sampled: Jan 26, 1989 Received: Jan 27, 1989

Received: Jan 27, 1989 Analyzed: Jan 31, 1989 Reported: Feb 2, 1989

ORGANIC LEAD

Sample Number	Sample Description	Sample Results mg/kg (ppm)
901-2768	7	0.3
901-2769	8	0.4

Detection Limits:

0.05

Analytes reported as N.D. were not present above the stated limit of detection.


SEQUOIA ANALYTICAL

Arthur G. Burton Laboratory Director



. . ,














BLAINE TECH SERVICES INC.

1370 TULLY RD., SUITE 505 SAN JOSE, CA 95122 (408) 995-5535

February 13, 1989

Shell Oil Company P.O. Box 4023 Concord, CA 94524

Attention: Ray Newsome

SITE: Shell Oil 630 High Street Oakland, California

PROJECT:
Confirmation samples
following additional excavation

SAMPLED ON: February 3, 1989

SAMPLING REPORT 89034-C-1

OBJECTIVE SERVICES

Blaine Tech Services, Inc. performs specialized environmental sampling and documentation as an independent third party. In order to avoid compromising the objectivity necessary for the proper and disinterested performance of this work, Blaine Tech Services, Inc. does not participate in interpretation of analytical results or become involved with the marketing or installation of remedial systems. The interpretation of results should be performed by representatives of interested regulatory agencies and/or those professionals who are engaged as paid consultants in the business of providing opinions and proposals for further investigation or clean-up activities.

This report describes the environmental sampling and documentation performed by our firm on this project. In addition to the text of the Sampling Report, supporting documents are provided as attachments. These include the chain of custody and the certified analytical laboratory report. All of these documents should be kept together and preserved as a file of interrelated records which, together, comprise the documentation of the work performed at the site.

Background

Our field personnel first visited the subject site on Thursday, January 26, 1989, to obtain soil samples from beneath the product lines and the product dispensing islands. A total of nine sample were collected from the product line trench and the three western dispenser pump islands. Two soil samples were collected from the eastern dispenser island area, where two dispenser pump islands had been located at some point in the past. Finally, a soil sample was collected from an area that smelled of gasoline, but was not closely associated with either the product dispensing pump islands or the product line trench. Discussion of this sampling activity can be found in Blaine Tech Services, Inc. Sampling Report No. 89026-C-1.

Scope of Requested Services

In accordance with your request, field personnel would be dispatched to the site to obtain additional soil samples from the area of the product line trench and the product dispensing pump islands. In addition, our personnel would arrange for the proper analyses of the samples, and maintain adequate documentation resulting in the issuance of a formal Sampling Report. The collection of environmental samples was to be performed in accordance with the requirements of the State Water Resources Control Board.

Execution of the Work

Field personnel were dispatched from our office and arrived at the subject site on Friday, February 3, 1989, to perform the requested sampling. Our personnel found that several of the areas sampled during our previous site visit had been more extensively excavated. While our field personnel were present at the site, the gasoline and waste oil tank pits associated with the service station previouly located on the eastern portion of the property were excavated and soil samples obtained.

Sampling began in the area of the product line trench and the dispenser pump islands. This product line trench runs eastward connecting the current gasoline tank pit with three dispensing pump islands. The area of the dispenser pump island closest to the tank pit had been excavated and a three foot (3') deep slot trench excavated from the island area westward for approximately twenty five feet (25'). Soil from the floor (Sample #1) and from the northern wall (Sample #2) of the excavated island area were taken at a depth of three feet (3') below grade level. Four samples (Samples #3, #4, #5, and #6) were obtained from the western wall of the slot trench, also at a depth of three feet (3') below grade level. These samples were obtained with a hand driven soil core sampler.

In its eastward run, the product line trench connects with two other dispenser pump island areas. The first of these island areas, the middle of the three dispenser pump islands, was not sampled during this site visit. The area of the third, or easternmost, dispenser pump island had been excavated to a depth of approximately two feet (2') below grade level. Soil from the floor of this excavated area was collected as Sample #10. This sample was obtained with a hand driven soil core sampler.

In the southeastern corner of the site, in the area thought to have previously been occupied by a gasoline tank pit associated with the earlier service station, a slot trench approximately four feet (4') wide and thirty eight feet (38') in length was dug to a depth between eleven and thirteen feet (11' - 13') below grade level. Three samples were obtained from the floor of the trench. Sample #7 was taken near the southeast end of the trench at eleven feet (11') below grade. Sample #9 was taken near the middle of the trench run at eleven feet (11') below grade. Sample #11 was taken from the northwest end of the trench at a depth of thirteen feet (13') below grade level. These samples were obtained with a hand driven soil core sampler.


One sample of soil material (Sample #8) was obtained from the spoils pile generated by the excavation of this trench. This sample was believed to be representative of the material being excavated from the trench. The sample was taken because, after the completion of the sampling activity, the material of the spoils pile was returned to the trench.

A waste oil tank was also believed to have been associated with the former service station. The area where this tank was believed to have been located was excavated to a depth of six feet (6') below grade, and one sample (Sample #12) was obtained from the floor of the excavation. This sample was obtained with a hand driven soil core sampler.

The location of individual sampling points is shown on diagram two on page five. Additional information on the exact method of sample collection will be found in the Sampling Methodology section of this report.


Analysis of the soil samples was conducted on the site at the time of the sampling. The analytical procedures were performed by Mobile Chem Labs, Inc., of San Carlos, California. Mobile Chem Labs, Inc. is a California Department of Health Services certified Hazardous Materials Testing Laboratory and is listed as DOHS HMTL #289.

It was requested that the analytical procedures used for these analyses be those specified by the Regional Water Quality Control Board -- San Francisco Bay Region. The methods are defined in attachments to the San Francisco RWQCB (Region 2) publication, Guidelines For Addressing Fuel Leaks and in documents issued to clarify the Board's interpretation of the California LUFT Manual.









ENLARGEMENT OF PRODUCT LINE TRENCH SAMPLING

SAMPLING PERFORMED BY STEVE CARTER DIAGRAM PREPARED BY BRENT ADAMS

MAP REF: THOMAS BROS. ALAMEDA CO. P.12 A-4

- #1 SOIL SAMPLE FROM 3 PETROLEUM ANALYSIS FOR TOTAL PETROLEUM HYDROCARBONS(TPH) AS GASOLINE BENZENF TOLUENE XYLENES AND ETHYLBENZENE (BTXE) AT MOBIL CHEM LAB
- #2 SOIL SAMPLE FROM 3'
 ANALYSIS FOR TPH AS GASOLINE
 AND BIXE
- #3 SOIL SAMPLE FROM 3. ANALYSIS FOR TPH AS GASOLINE AND BIXE
- #4 SOIL SAMPLE FROM 3' ANALYSIS FOR TPH AS GASOLINE
- #5 SOIL SAMPLE FROM 3' ANALYSIS FOR TPH AS GASOLINE
- #6 SOIL SAMPLE FROM 3' ANALYSIS FOR TPH AS GASOLINE AND BIXE
- #7 SOIL SAMPLE FROM 11'
 ANALYSIS FOR TPH AS GASOLINE
 AND BIXE
- *#8 SOIL SAMPLE FROM THE SOUTHEASTERN TRENCH ANALYSIS FOR TPH AS GASOLINE AND BIXE
- #9 SOIL SAMPLE FROM 11' ANALYSIS FOR THE AS GASOLINE AND BIXE
- #10 SOIL SAMPLE FROM 2' ANALYSIS FOR TPH AS GASOLINE AND BIXE
- #11 SOIL SAMPLE FROM 13' ANALYSIS FOR TPH AS GASOLINE AND BIXE
- #12 SOIL SAMPLE FROM 6' ANALYSIS FOR TOTAL OIL AND GREASE, TPH AS DIESEL, AND EPA 8240

*NOTE:

SAMPLE #8 WAS FROM A PILE OF MATERIAL REMOVED WHILE DIGGING THE TRENCH IN THE SOUTHEAST CORNER OF THE LOT BOULD REPRESENT ABOUT THE HIGHEST THE LEVELS OF THE MATERIA REMOVED. THIS MATERIAL HOWEVER, WAS PUT BACK IN THE TRENCH AT THE COMPLETION OF THE SAMPLING.

SAMPLING METHODOLOGIES USED ON THIS PROJECT

Hand Driven Core Sampling: This is another term for the sampling methodology that is often called undisturbed soil sampling. This is the generally preferred sampling method for both geotechnical and environmental investigations because the method captures a relatively undisturbed cylinder of soil which can be retained in its sealed brass liner during transport to a laboratory for very precise examination. Whether driven by a drill rig or a much smaller hand operated slide hammer, the principle attributes of the methodology remain the same.

Because of the tons of force which can be exerted by a drill rig, the samplers, drill rod and hammers are, necessarily, quite massive. Apparatus used in hand augered borings is usually much lighter and more subject to wear and breakage. Specialized hand tools that enable a person to drive samples consist of a sampling shoe (which contains the brass liners), light weight drill rod, and a small slide hammer. These hand operated drive samplers collect samples in the same two inch diameter brass liners used in many drill rig samplers, but collect only a four or six inch long core rather than twelve to twenty four inches of soil commonly obtained by drilling apparatus.

Common uses for hand operated drive samplers include all those applications where an undisturbed soil sample is desired. Typical applications include the collection of soil samples from the bottom of a hand augered boring, capillary zone sampling where a drill rod is used to extend the sampler across an open pit to a selected location on the wall of the excavation, and when sampling soil from the backhoe bucket that is too hard to allow a brass sample liner to be pushed into the soil by hand.

In practice, the sampler is usually overdriven and then retracted. Then the sampler is removed from the drill rods and hammer, opened, and the sample contained in the brass sample liners removed. Samples to be analyzed for environmental hazards are treated according to the same sample handling protocol as all other environmental samples.

SAMPLE CONTAINERS

Our firm uses new sample containers of the type specified by either EPA or the RWQCB for the collection of samples at sites where underground storage tanks are involved. Soil samples for volatile, semivolatile and nonvolatile analyses are all collected in properly prepared new brass liners which are 2 inches in diameter by 4 inches in length. Closure is accomplished with press fit plastic end caps which are fitted to the open ends of brass tube liners after a sheet of aluminum foil is wrapped over the exposed sample material. A non-contributing/nonsubtractive tape is wrapped completely around the joint areas where the plastic caps meet the outer wall of the brass tube. No preservative other than cold storage is used on samples captured in sample containers of this type.

SAMPLE HANDLING PROCEDURES

Solid sample material is captured by advancing the liner into the soil. This may be done by pushing the liner into soft soils or by containing the liner in a drive shoe which can be advanced and then retracted by means of a slide hammer. The open ends of the sample

liner are covered with aluminum foil and plastic end caps. Excess aluminum foil is removed and the edge of the plastic end caps is tightly sealed against the outer surface of the brass liner with an unbroken wrap made with a tape which has been tested to confirm that it does not contribute compounds that would be detected in the type of analyses intended for the sample contained inside of the brass liner. The brass liner is then labeled with the appropriate identification numbers which specify the sampling activity designation number, sample collection area, depth etc. that apply to that particular sample. Because the analyses were being performed on-site at the time of the sampling, the sample liner is then immediately turned over to the mobile laboratory personnel.

SAMPLE DESIGNATIONS

All sample containers are identified with both an activity number and a discrete sample identification number. Please note that the activity number is the number that appears on our chain of custody. It is roughly equivalent to a job number, but applies only to work done on a particular day of the year rather than spanning several days as an actual activity often does. This is followed by the sample I.D. number which is usually a simple number such as #1, #2, #3.

CHAIN OF CUSTODY

In general, samples are continuously maintained in either a chilled ice chest, refrigerator, or freezer from the time of collection until acceptance by the State certified Hazardous Materials Testing Laboratory selected to perform the analytical procedures. If the samples are taken charge of by a different party (such as another person from our office, a courier, etc.) prior to being delivered to the laboratory, appropriate release and acceptance records are made on the chain of custody (time, date, and signature of person releasing the samples followed by the time, date and signature of the person accepting custody of the samples).

In this case, a mobile laboratory was present at the site and the analytical procedures were being performed immediately following the collection of the samples. The samples were turned over to the mobile laboratory capped, and sealed. The time the sample was turned over to the laboratory was noted on the left side of the chain of custody adjacent to the sample number. Acceptance of the samples by the mobile laboratory personnel was testified to by the signature at the bottom of the chain of custody which was affixed at the completion of the sample collection activity.

LABORATORY IDENTIFICATION NUMBERS

Following receipt of the samples and completion of the Chain of Custody form, the laboratory then assigns their own identification numbers to the samples. Different laboratories use different numbering systems and, according to their own internal conventions, may or may not assign sequential numbers to samples which are placed on temporary "hold", pending the results of other analyses. Laboratory identification numbers (if assigned and available) are included on the DIAGRAM, and will be found on the certified analytical report by the analytical laboratory.

CERTIFIED ANALYTICAL REPORT

The certified analytical report (CAR) generated by the laboratory is the official document in which they issue their findings. The Results of Analyses section of the TABLE OF SAMPLING LOCATIONS AND ANALYTICAL RESULTS should correspond exactly with the laboratory's CAR. Any discrepancy between analytical values should be decided in favor of the CAR, for while it may, itself, be in error with regard to a particular number, the CAR remains the recognized document until such time as it is amended with a corrected report.

The certified analytical report should also be reviewed when samples are taken from below waste oil tanks as <u>any</u> detection of the EPA halogenated and purgeable aromatic compounds may be grounds for requiring further action. Also the TABLE OF SAMPLING LOCATIONS AND ANALYTICAL RESULTS is insufficiently spacious to allow anything more that a simple listing of the detected compounds. The TABLE does not include such information as the detection limits at which other compounds were not detected. The full text of the laboratory report will be found in Section Four of this report.

REPORTAGE

Submission to the Regional Water Quality Control Board and the local implementing agency should include copies of the sampling report, the chain of custody, and the certified analytical report issued by the Hazardous Materials Testing Laboratory. The property owner should attach a cover letter and submit all documents together in a package.

The following addresses have been listed here for your convenience:

Water Quality Control Board San Francisco Bay Region 1111 Jackson Street Room 6040 Oakland, CA 94607 ATTN: Greg Zentner

Alameda County Health Hazardous Materials Management 420 27th Street Oakland, CA 94612 ATTN: Ariu Levi Please call if we can be of any further assistance.

Richard C. Blaine

RCB/dmp

attachments: supporting documents

BLAINE TECH SERVICES INC.

1370 TULLY ROAD, SUITE 505 SAN JOSE, CA 95122 (408) 995-5535

CHAIN OF CUSTODY # _	8103	40		
SITE SPECIPICATION	on She	il O	1 50	chon
630 1		Sh, Ye	<u> </u>	
Caklan				

()	Bill	BLAINE TEC	H.	SERVICES.	Inc.		P	R	C	ī	A	E.	ĭ	N	S	T	ĸ	11	C	т	Ŧ	0	N	S
						'— <u></u> -	- <u>-</u> -				 -	<u>~</u> _	 *	••				<u> </u>		-	-	<u>~</u>	<u></u>	
M	Dill	Stant d	- 1	T .		1																		
174	Dill	Shell	4			•																		
,		O																						

ZIMÉ MITTE	g)(c)			 	
3001	SAMPLE 1.D.	QUANTITY TYPE OK	ANALYSIS TO DETECT STATUS	RESULTS L	AB NUMBER
12.25		<u> Soil</u>	Tith Gas), Boxe	 -	
15.36	2_		TER CAD BOXE		
17:59	3	<u>t 5,4 </u>	TPH (co), BTXE		
18016	<u>-</u>	1 501/	TORIGIST STXE		
13:32	5	<u>1 5.1</u>	7PH 1321 13TXT		
13:49		1 50.7	180 (25) BTAT		
14:24	-7	<u>l</u>	TPH (921) 15-45		
14:32	<u> </u>	<u> </u>	TPHGLA BIXE		
14:44	9	1 81	THE STREET		
15:54	10	1 50,1	TPH(qu) BTXE		
16:20	!	1 50:1	714 (gas), BTKE		
16:30	12	1 Soil	Toy, TPH (diesel) 8240		
<u> </u> 					

Field sampling						Sampling was completed at					
From J. Luter	fikt # b	1 (nai	de, tim M/PM_	e,date) 24389	->>>> -> tu <u>k</u>	TINTO THE CU	STODY	OF 15:40	(name,¶ ⊘AM/PM	.ime,d 2/3	late) 88
from	<u> </u>	:	VM/PM_	88	-> to.			_;	_am/}?m		88
from	A	_:/	M/IM_	88 -	-> to_		<u> </u>	_ :	_AM/PM		88

The laboratory designated to perform these analyses is: Math. (2007) THIS HMIL # 12.1 NOTE: Proxedures and detection limits, must confrom to RACE Region ____ specifications. Please include chain of custody number and site specification on reports and invoices.

Shell Oil Company P.O. BOX 4023 Concord, CA 94524 Attn: Ray Newsome

Date Sampled: 02-03-89 Date Received: 02-03-89 Date Reported: 02-03-89

Sample Number -----V029001

Sample Description
----89034C1-Oakland
630 High St.
#1 SOIL

ANALYSIS

	Detection Limit	Sample Results
	ppm	ppm
Total Petroleum Hydrocarbons as Gasoline	1.0	8.0
Benzene	0.1	0.6
Toluene	0.1	<0.1
Xylenes	0.1	<0.1
Ethylbenzene	0.1	1.5

Note: Analysis was performed using EPA methods 5020 and 8015 with method 8020 used for BTX distinction.

MOBILE CHEM LABS

Shell Oil Company P.O. BOX 4023 Concord, CA 94524

Attn: Ray Newsome

Date Sampled: 02-03-89 Date Received: 02-03-89 Date Reported: 02-03-89

Sample Number -----V029002 Sample Description
-----89034C1-Oakland
630 High St.
#2 SOIL

ANALYSIS

	Detection Limit	Sample Results	
	ppm	ppm	
Total Petroleum Hydrocarbons as Gasoline	1.0	2.0	
Benzene	0.1	<0.1	
Toluene	0.1	<0.1	
Xylenes	0.1	<0.1	
Ethylbenzene	0.1	<0.1	

Note: Analysis was performed using EPA methods 5020 and 8015 with method 8020 used for BTX distinction.

MOBILE CHEM LABS

Shell Oil Company P.O. BOX 4023 Concord, CA 94524 Attn: Ray Newsome

Date Sampled: 02-03-89 Date Received: 02-03-89 Date Reported: 02-03-89

Sample Number -----V029003 Sample Description
-----89034C1-Oakland
630 High St.
#3 SOIL

ANALYSIS

	Detection Limit	Sample Results
	ppm	ppm
Total Petroleum Hydrocarbons as Gasoline	1.0	4.5
Benzene	0.1	0.2
Toluene	0.1	<0.1
Xylenes	0.1	<0.1
Ethylbenzene	0.1	<0.1

Note: Analysis was performed using EPA methods 5020 and 8015 with method 8020 used for BTX distinction.

MOBILE CHEM LABS

Shell Oil Company P.O. BOX 4023 Concord, CA 94524

Attn: Ray Newsome

Date Sampled: 02-03-89 Date Received: 02-03-89 Date Reported: 02-03-89

Sample Description
-----89034C1-Oakland
630 High St.
#4 SOIL

ANALYSIS

	Detection Limit	Sample Results
	ppm	ppm
Total Petroleum Hydrocarbons as Gasoline	1.0	3.0
Benzene	0.1	0.2
Toluene	0.1	<0.1
Xylenes	0.1	<0.1
Ethylbenzene	0.1	<0.1

Note: Analysis was performed using EPA methods 5020 and 8015 with method 8020 used for BTX distinction.

MOBILE CHEM LABS

Shell Oil Company P.O. BOX 4023 Concord, CA 94524

Concord, CA 94524 Attn: Ray Newsome Date Sampled: 02-03-89 Date Received: 02-03-89 Date Reported: 02-03-89

Sample Number -----V029005

ANALYSIS

	Detection Limit	Sample Results
	ppm	ppm
Total Petroleum Hydrocarbons as Gasoline	1.0	3.6
Benzene	0.1	0.2
Toluene	0.1	<0.1
Xylenes	0.1	<0.1
Ethylbenzene	0.1	<0.1

Note: Analysis was performed using EPA methods 5020 and 8015 with method 8020 used for BTX distinction.

MOBILE CHEM LABS

Shell Oil Company P.O. BOX 4023 Concord, CA 94524 Attn: Ray Newsome

Date Sampled: 02-03-89 Date Received: 02-03-89 Date Reported: 02-03-89

Sample Number -----V029006 Sample Description
-----89034C1-Oakland
630 High St.
#6 SOIL

ANALYSIS

	Detection Limit	Sample Results
	ppm	ppm
Total Petroleum Hydrocarbons as Gasoline	1.0	<1.0
Benzene	0.1	<0.1
Toluene	0.1	<0.1
Xylenes	0.1	<0.1
Ethylbenzene	0.1	<0.1

Note: Analysis was performed using EPA methods 5020 and 8015 with method 8020 used for BTX distinction.

MOBILE CHEM LABS

Shell Oil Company P.O. BOX 4023

Concord, CA 94524 Attn: Ray Newsome Date Sampled: 02-03-89 Date Received: 02-03-89 Date Reported: 02-03-89

Sample Number -----V029007 Sample Description
-----89034C1-Oakland
630 High St.
#7 SOIL

ANALYSIS

	Detection Limit	Sample Results
	ppm	ppm
Total Petroleum Hydrocarbons as Gasoline	1.0	37
Benzene	0.1	<0.1
Toluene	0.1	<0.1
Xylenes	0.1	0.5
Ethylbenzene	0.1	<0.1

Note: Analysis was performed using EPA methods 5020 and 8015 with method 8020 used for BTX distinction.

MOBILE CHEM LABS

733 Dartmouth Avenue San Carlos, CA 94070 • (415) 591-5820

Shell Oil Company P.O. BOX 4023 Concord, CA 94524

Attn: Ray Newsome

Date Sampled: 02-03-89 Date Received: 02-03-89 Date Reported:02-03-89

Sample Number V029008

Sample Description 89034C1-Oakland 630 High St. #8 SOIL

ANALYSIS

	Detection Limit	Sample Results
	ppm	ppm
Total Petroleum Hydrocarbons as Gasoline	1.0	19
Benzene	0.1	0.1
Toluene	0.1	<0.1
Xylenes	0.1	1.3
Ethylbenzene	0.1	0.4

Analysis was performed using EPA methods 5020 and 8015 with Note: method 8020 used for BTX distinction.

MOBILE CHEM LABS

Shell Oil Company P.O. BOX 4023 Concord, CA 94524 Attn: Ray Newsome

Date Sampled: 02-03-89 Date Received: 02-03-89 Date Reported: 02-03-89

Sample Number -----V029009 Sample Description
----89034C1-Oakland
630 High St.
#9 SOIL

ANALYSIS

Detection Limit	Sample Results
ppm	ppm
1.0	25
0.1	0.1
0.1	<0.1
0.1	1.0
0.1	0.5
	Limit ppm 1.0 0.1 0.1

Note: Analysis was performed using EPA methods 5020 and 8015 with method 8020 used for BTX distinction.

MOBILE CHEM LABS

Shell Oil Company P.O. BOX 4023 Concord, CA 94524 Attn: Ray Newsome

Date Sampled: 02-03-89 Date Received: 02-03-89 Date Reported: 02-03-89

Sample Number ------V029010 Sample Description
----89034C1-Oakland
630 High St.
#10 SOIL

ANALYSIS

	Detection Limit	Sample Results	
	ppm	ppm	
Total Petroleum Hydrocarbons as Gasoline	1.0	75	
Benzene	0.1	3.6	
Toluene	0.1	1.5	
Xylenes	0.1	13	
Ethylbenzene	0.1	7.1	

Note: Analysis was performed using EPA methods 5020 and 8015 with method 8020 used for BTX distinction.

MOBILE CHEM LABS

Shell Oil Company P.O. BOX 4023 Concord, CA 94524

Attn: Ray Newsome

Date Sampled: 02-03-89 Date Received:02-03-89 Date Reported:02-03-89

Sample Number V029011

Sample Description 89034C1-Oakland 630 High St. #11 SOIL

ANALYSIS

	Detection Limit	Sample Results
	ppm	ppm
Total Petroleum Hydrocarbons as Gasoline	1.0	42
Benzene	0.1	<0.1
Toluene	0.1	<0.1
Xylenes	0.1	1.2
Ethylbenzene	0.1	0.1

Analysis was performed using EPA methods 5020 and 8015 with Note: method 8020 used for BTX distinction.

MOBILE CHEM LABS

Shell Oil Company P.O. BOX 4023

Concord, CA 94524

Attn: Ray Newsome

Date Sampled: 01-03-89 Date Received: 01-03-89 Date Reported: 01-04-89

Sample Number	Sample Description	Detection Limit	Gravimetric Waste Oil as Petroleum Oil
	89034C1-Oakland 630 High St.	ppm	ppm
V029012	#12	50	600

Note: Analysis was performed using EPA extraction method 3510 with Trichlorotrifluoroethane as solvent, and gravimetric determination by standard methods 503e

MOBILE CHEM LABS



Shell Oil Co. P.O. BOX 4023

Concord, CA 94524 Attn: Ray Newsome Date Sampled: 02-03-89 Date Received: 02-03-89 Date Reported: 02-04-89

Sample Number	Sample Description	Detection Limit	Gravimetric Waste Oil as Petroleum Oil
	89034C1-Oakland 630 High St.	ppm	ppm
V029012	#12	50	600

Note: Analysis was performed using EPA extraction method 3510 with Trichlorotrifluoroethane as solvent, and gravimetric determination by standard methods 503e

MOBILE CHEM LABS

Mobile Chem Labs, Inc. 733 Dartmouth Avenue San Carlos, CA 94070 Attention: Joy Client Project ID: Sample Descript:

Analysis Method:

Lab Number:

89034CI, S.O.S. - Oakland

Soil, V029012 EPA 8240

EPA 8240 902-0449 Sampled:

Feb 3, 1989

Received: Feb 6, 1989 Analyzed: Feb 6, 1989 Reported: Feb 6, 1989

VOLATILE ORGANICS by GC/MS (EPA 8240)

Analyte	Detection Limit ug/kg		Sample Results ug/kg
Acetone	500.0	***************************************	N.D.
Benzene	100.0	********************************	N.D.
Bromodichloromethane	100.0	***************************************	N.D.
Bromoform	100.0	*************	N.D.
Bromomethane	100.0		N.D.
2-Butanone	500.0	***************************************	N.D.
Carbon disulfide	100.0	***************************************	N.D.
Carbon tetrachloride	100.0	***************************************	N.D.
Chlorobenzene	100.0	**************************	N.D.
Chlorodibromomethane	100.0	*************************	N.D.
Chloroethane	100.0	***********************	N.D.
2-Chloroethyl vinyl ether	500.0	*****************************	N.D.
Chloroform	100.0		N.D.
Chloromethane	100.0		N.D.
1,1-Dichloroethane	100.0		N.D.
1,2-Dichloroethane	100.0	<pre><pre></pre></pre>	N.D.
1,1-Dichloroethene	100.0	******************************	N.D.
Total 1,2-Dichloroethene	100.0	******************************	N.D.
1,2-Dichloropropane	100.0	*************************	N.D.
cis 1,3-Dichloropropene	100.0	************	N.D.
trans 1,3-Dichloropropene	100.0		N.D.
Ethylbenzene	100.0	*************	N.D.
2-Hexanone	500.0	*****************************	N.D.
Methylene chloride	100.0	***************************************	N.D.
4-Methyl-2-pentanone	500.0	***************************************	N.D.
Styrene	100.0	***************************************	N.D.
1,1,2,2-Tetrachloroethane	100.0		N.D.
Tetrachloroethene	100.0	•	N.D.
Toluene	100.0	***************************************	N.D.
1,1,1-Trichloroethane	100.0	***************************************	N.D.
1,1,2-Trichloroethane	100.0	***************************************	N.D.
Trichloroethene	100.0	***************************************	N.D.
Trichlorofluoromethane	100.0	***************************************	N.D.
Vinyl acetate	100.0	***************************************	N.D.
Vinyl chloride	100.0	***************************************	N.D.
Total Xylenes	100.0	***************************************	N.D.

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Arthur G. Burton Laboratory Director