

MEETING NOTES

CASE NO.: RO0361

ADDRESS: 4191 First Street, Pleasanton

DATE: February 11, 2009

PARTICIPANTS:

Jerry Wickham, ACEH

Terry Grayson, representing ConocoPhillips

John Reay, Delta

There was no formal agenda for the meeting. The topic of the meeting was future actions for the site.

- Jerry Wickham indicated that highest concern for site was the MTBE from USTs at site.
- The heavier hydrocarbons in subsurface, which may be from a former Bunker oil tank near property boundary, are not as significant a problem as the MTBE for groundwater.
- The former Bunker C tank may be on a triangular piece of property adjacent to the ConocoPhillips (COP) site.
- John Reay infers that a fault is present between monitoring well MW-9 and MW-5.
- The hydraulic gradient for the site is uncertain because long-screen wells connect different water-bearing zones. Cannot compare water levels from long-screen wells due to vertical gradients.
- COP is considering ozone sparging for site remediation.

ACTION ITEMS:

- COP will prepare a work plan for decommissioning long-screen monitoring wells and installing wells within discrete intervals. Work plan will be prepared in place of CAP requested in ACEH correspondence. Work plan to be submitted by March 1, 2009.
- COP will research whether ConocoPhillips owned the triangular property strip immediately north of station.