

3-4-93

Chevron
3369 Castro Valley Bl
Castro Valley

demolition of site / removal of
waste water from sumps





Chevron
3369 Castro Valley Blvd
Castro Valley

3-15-93

Closeup of stained soil
on east side of Sump.
Note also vertical seam
in Sump; water was seen
leaking from this seam
when soil was removed.

Chevron
3369 Castro Valley Bl
Castro Valley
3-15-93

View to west. Note 2nd
smaller sump north of main
sump.





Chevron
3369 Castro Valley Bl
Castro Valley
3-15-93

• oil/water sump
excavation

Note heavily-stained soil
on left (east) side of
sump.

Chewron
3369 Castro Valley Bl
Castro Valley
3-15-93

Removing main sump in sections.
Note stained soil.





Chevron
3369 Castro Valley Bl
Castro Valley
3-15-93

Removing main sump in sections

055 052 12 21 260 556



Chesron
3369 Castro Valley B1
Castro Valley
3-15-93

View to east, at west flank
of main sump; smaller sump all
depicted here. Note soil staining
at excavation base.

055 052 01
055 056

3-4-93

Chevron
3369 Castro Valley Bl

Castro Valley

demolition of site /
removal of waste water
from tanks



































C.V. Blvd (E) → utility box



High voltage line

CU Blvd



2nd/3rd generation piping trench



Chevron



3369 Castro Valley Blvd. 1/26/93
Chevron



Three (3) 2" FRP product lines heading east beneath utility box (PG+E)



1/26/93
3369 Castro Valley Blvd.
Chevron