

Questions: left message for AL Martiney. #4610

- 1) Why have D.O. ares increased so little, even after ORC injection?
 - 2) Explain / define how exponential trend line is determined.
-

11/16/99

SBW/ A Martiney:

- 1) D.O. is low - thinks that G. Rogers may be measuring it ex situ & introducing O₂, need to resolve so the same (correct method) is used.
- 2) Will provide program results used to generate the exponential plot.

5/28/97

Spw / Wm Theyskins of ATC.

- I changed a Tier 1 or 2 RBCA prior to any attempt to remove soil or GW
- Agreed to add bio-indicator parameters to wells
- informed him of options for 1" well
- discussed problems w/ having 2 consultants proposing similar things, who'll be ~~the~~ actual one?

oral No. of

\$ 483⁰⁰ Rec'd 7-21-93

New Genico
Address 3027 E 14th St

Oakland 94411 Phone

Contractor John P Cummings

Address PO Box 2874

Fremont Ca Phone

OTHER (Specify)

Address

Phone

CONTACT FOR INVESTIGATION

No.	Plans Rec'd.
Plans Approved	
Layout Made	
Rejected	
Applicant Notified	
Plans Returned	
Permit Issued	

CONSTRUCTION PROGRESS ACCEPTANCE	
Pre-Plaster/drywall	
Pre-Final	
Final	

POOL	Pre-Concrete/Gunite				
	Pre-Plaster				
EXCAVATION	Final				
	Septic Tank				
	Absorption Field				
FINAL	Absorption Bed				
	House Sewer				
	Septic Tank				
OTHER	Absorption Field				
	Absorption Bed				

U.G. TANKS

Final

STID 4610

REMARKS	
Date	By
7-26-93	BC
Tank R plan review, need a refund receipt from field out, left message w/ Mr Cummings 8:55 am	

REMARKS	
Date	By

LOCATION

Vicinity Map
STID 4610
704474
\$483⁰⁰
7-21-93