

Jerry Ray - meeting
Alan Whitman


9/13/89

26TH SO. contamination - oil tested - turned out to be motor oil. Sulprizio wanted samples to be in personal custody of Jerry Ray, who refused.

source of oil: unknown, but possibly oil-change service for Custom Alloy, which operated on 26TH SO.

name: Tony's Ford-A-Sale 829-1625

Custom Alloy Map



boiler contains oil
from leaking ~~hydraulic~~ hydraulics

1 foot deep; 200' x 50'

oil from ITP was removed around the time of my initial inspection on 2/15, probably after; Eddie told this to ~~Jerry~~ Jerry, and Jerry knew nothing about this beforehand.